

Eaton® 9395/9395P System Bypass Module (SBM)

Production Firmware History (Since Version 2.26)



p/n: P-164001200
Revision 01

NOTICE OF PROPRIETARY INFORMATION

The equipment discussed herein is capable of causing great harm to life, limb, and/or property. Installation, maintenance, and/or repair of the equipment referenced herein must be performed by Eaton duly authorized and trained, certified personnel.

Notwithstanding the foregoing, Eaton assumes NO responsibility for any damage or injury to any persons or property which may be caused to any extent by reliance on the information provided herein except to the extent such damage or injury results solely and directly from the willful negligence of Eaton, its agents, or employees. Additionally, Eaton shall not be liable for any indirect, special incidental, or consequential damages, such as, but not limited to, loss of anticipated profits, good will, or other economic loss in connection with or arising out of the existence of, the furnishing of, or the use of the information provided for in this agreement, whether or not the possibility of damage was disclosed to or could have been reasonably foreseen by Eaton.

The information contained herein is proprietary to Eaton. It is unlawful to copy or reproduce this document or any part thereof in any media or to use or reference same except for those purposes in the means and quantities specified by written agreement with Eaton. Periodically, changes are made to the contents herein. Please contact Eaton or your original source for any modification, updates, or new additions. Due to the possibility of such changes, RELIABILITY ON THE CONTENTS HEREIN IS AT RECIPIENT'S/USER'S OWN RISK.

No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without the prior written permission of the publisher, Service Documentation Department, Eaton.

Eaton reserves the right to change specifications without prior notice. Eaton is a registered trademark of Eaton. PDI, JCOMM, Quad-Wye, ToughRail Technology, and WaveStar are registered trademarks of Power Distribution Inc. All other trademarks are held by their respective owners. All other trademarks are property of their respective companies.

©Copyright 2024 Eaton, Raleigh, NC, USA. All rights reserved. No part of this document may be reproduced in any way without the express written approval of Eaton.

Eaton 9395/9395P SBM Production Firmware History

Description

This document is intended for end-user informational purposes. It describes the changes between revision levels of the primary control board firmware used in the Eaton 9395/9395P System Bypass Module (SBM) product line. This document will be changing periodically and reposted on www.Eaton.com to reflect new production level firmware changes. In all cases, the changes, enhancements, fixes, and new features listed under a given production release are automatically transferred into the next production release.

DSP / Control Version 2.30.7000 (DSP1) / December 2023

Fixes

- Corrects a customer issue where the SBM manual transfers to and from bypass result in a differential current during the time the inverter and bypass are tied together. This can result in a ground fault breaker trip. The resolution provides a parameter-based solution that significantly reduces transfer times (to prevent a breaker trip) by reducing the number of debounce cycles required to detect CBP and CBS breaker states during manual transfers.

This release does not eliminate differential current.

DSP / Control Version 2.30.2267 (DSP1) and .2268 (DSP2) / July 2019

Fixes

- 2.30.2267 / .2268 was specifically created to address issues with the slowness of Square D breakers for one specific customer. The timing of the breakers was allowing considerable back feed current to flow into the bypass source during manual transfers.

It was initially intended that use of the 2.30.2267 / .2268 firmware would be limited only to that customer but then a parameter selection was added to turn the fix on if needed.

DSP / Control Version 2.28 / August 2014

Fixes

- Inconsistent fault clearing while in ESS:
During a Factory Witness Test a load loss in about 25% of the applied upstream faults was observed. This issue was addressed by forcing more time to requalify sources after going on-line. Abnormal cases were mitigated by using voltage sensing and breaker state changes.
- Incorrect metering values when used with derated UPSs
When used with derated UPSs the HMI would display incorrect meter values. This was addressed by adding a parameter to select which UPS is derated and associated parameters which updated the kVA and kW values.
- Flashing of the previous 2.26 firmware caused the RMP (Remote Monitor Panel) to stop working.

DSP / Control Version 2.26 / April 2013

Fixes

- The SBM entered ESS mode before the UPMs were ready.
- The system would go in, then out, and then back into ESS mode when Bypass voltage is removed.
- 9395 SBM System Frequency Range; When Bypass Frequency increases beyond the 3Hz window the History Log fills up with nuisance "Notice" messages.



P-164001200 01