

Production Firmware History

NOTICE OF PROPRIETARY INFORMATION

The equipment discussed herein is capable of causing great harm to life, limb, and/or property. Installation, maintenance, and/or repair of the equipment referenced herein must be performed by Eaton duly authorized and trained, certified personnel.

Notwithstanding the foregoing, Eaton assumes NO responsibility for any damage or injury to any persons or property which may be caused to any extent by reliance on the information provided herein except to the extent such damage or injury results solely and directly from the willful negligence of Eaton, its agents, or employees. Additionally, Eaton shall not be liable for any indirect, special incidental, or consequential damages, such as, but not limited to, loss of anticipated profits, good will, or other economic loss in connection with or arising out of the existence of, the furnishing of, or the use of the information provided for in this agreement, whether or not the possibility of damage was disclosed to or could have been reasonably foreseen by Eaton.

The information contained herein is proprietary to Eaton. It is unlawful to copy or reproduce this document or any part thereof in any media or to use or reference same except for those purposes in the means and quantities specified by written agreement with Eaton. Periodically, changes are made to the contents herein. Please contact Eaton or your original source for any modification, updates, or new additions. Due to the possibility of such changes, RELIABILITY ON THE CONTENTS HEREIN IS AT RECIPIENT'S/USER'S OWN RISK.

No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without the prior written permission of the publisher, Service Documentation Department, Eaton.

Eaton reserves the right to change specifications without prior notice. Eaton is a registered trademark of Eaton. PDI, JCOMM, Quad-Wye, ToughRail Technology, and WaveStar are registered trademarks of Power Distribution Inc. All other trademarks are held by their respective owners. All other trademarks are property of their respective companies.

©Copyright 2023 Eaton, Raleigh, NC, USA. All rights reserved. No part of this document may be reproduced in any way without the express written approval of Eaton.

Eaton 9395XC UPS Production Firmware History

Description

This document is intended for end-user informational purposes. It describes the changes between revision levels of the primary control board firmware used in the Eaton 9395XC product line. This document will be changing periodically and reposted on www.Eaton.com to reflect new production level firmware changes. In all cases, the changes, enhancements, fixes, and new features listed under a given production release are automatically transferred into the next production release.

Revision 1.14.00

Released: Oct 18, 2023

Notes

- Compatible with all existing 9395XC UPS Hardware

New Features

- None

Fixes

- Resolved the issue of the HMI not always booting up correctly.
- Resolved Charger Failed issue that occurred when the battery breaker was not closed in immediately after going online.
- Resolved Clock / time issue on HMI.

Revision 1.08.00

Fixes

- [HMI] Native Relay Outputs showing non-stop blue spinner
- [HMI] Screen shows text of file and directory info after power cycle
- [HMI] Screen stuck with Eaton logo during booting
- [HMI] Corrects the unable to set date and time on front panel issue
- [Control] Inverter instability
- [Control] Input THD Exceeds 3% specification
- [Control] Large (~3.8kHz) oscillation on Input Voltage/Current when input currents are large.
- [Control] N-station no-load drop on battery dumps load with DC link OV

Table 1. Software Builds within v1.08.00

CPU	Software/Firmware Version
MCU App	v1.08.0000
UPM App	v1.08.0001
MCU FPGA	v1.00.0000
UPM FPGA	v1.02.0000
ARM App	v1.08.0000

Table 1. Software Builds within v1.08.00 (Continued)

CPU	Software/Firmware Version
ARM Bootloader	v1.00.0000
SHARC Bootloader	v1.06.0000
U-Boot	v1.00.0000
IO Expansion App	v1.02.0000
IO Expansion Bootloader	v1.06.0000
Bypass PIC	v0.14
HMI Bootloader	v2020.04.1.1
HMI OS	v3.0.0.4
HMI App	v1.0.6
Service Tool Software Version Required	v1.10.84

Revision 1.06.00**Fixes**

- MCU Battery Breaker Trip With Load Off Not Working
- [HMI] Estimated Runtime does not display correctly
- Meters screen on the HMI is not working correctly- HMI Test
- Battery voltage displays as 6553.5volts when batteries are not connected
- Top bar voltage not displayed
- HMI/REST MCU input meters always near zero
- Active alarm timeline is blank while alarms are active
- HMI Charger ON/OFF status should be based on UPM ChargeDcCommand nodebit

Table 2. Software Builds within v1.06.00

CPU	Software/Firmware Version
MCU App	v1.06.0001
UPM App	v1.06.0000
MCU FPGA	v1.00.0000
UPM FPGA	v1.02.0000
ARM App	v1.06.0001
ARM Bootloader	v1.00.0000
SHARC Bootloader	v1.06.0000
U-Boot	v1.00.0000
IO Expansion App	v1.02.0000

Table 2. Software Builds within v1.06.00 (Continued)

CPU	Software/Firmware Version
IO Expansion Bootloader	v1.06.0000
Bypass PIC	v0.14
HMI Bootloader	v2020.04.1.1
HMI App	v1.0.4
Service Tool Software Version Required	v1.10.74

Revision 1.04.00***New***

- Commissioning release of 9395XC UPS Production Firmware for Americas 1500kW monolithic.

Table 3. Software Builds within v1.04.00

CPU	Software/Firmware Version
MCU App	v1.04.0000
UPM App	v1.04.0000
MCU FPGA	v1.00.0000
UPM FPGA	v1.02.0000
ARM App	v1.04.0000
ARM Bootloader	v1.00.0000
SHARC Bootloader	v1.02.0000
U-Boot	v1.00.0000
IO Expansion App	v1.02.0000
IO Expansion Bootloader	v1.00.0000
Bypass PIC	v0.14
HMI Bootloader	v2020.04.1.1
HMI App	v1.0.4
Service Tool Software Version Required	v1.10.62



P-164001174 02