

Visual Capacity

Release Notes

Release 6.2.1





Eaton

www.eaton.com/powerquality

LEGAL NOTICE

Copyright © 2020. Eaton. All rights reserved. The contents of this document constitute valuable proprietary and confidential property of Eaton Corporation and are provided subject to specific obligations of confidentiality set forth in one or more binding legal agreements. Any use of this material is limited strictly to the uses specifically authorized in the applicable license agreement(s) pursuant to which such material has been furnished. Any use or disclosure of all or any part of this material not specifically authorized in writing by Eaton Corporation is strictly prohibited.

Contact Eaton Support

For your convenience, Eaton provides support to assist you with questions on installation, operation and troubleshooting. Please contact us at:

softwareconnectivityts@eaton.com

800-356-5737 option 2, option 5, option 1





Contents

Con	ntent	S	3
1	1 Ir	ntroduction	4
1	1	About This Guide	4
1	2	Audience	4
2	Rel	ease Details	5
2	.1	Upgrade Patch	5
2.1.	.1. Uj	ograde Patch Details	5
2.1.	.2.	Upgrade Patch Prerequisites	5
2.1.	.3.	Upgrade Patch Installation Instructions	6
3	6.2	.1 Enhancements	8
3	5.1	Enhancements Table	8





1 1 Introduction

1.1 About This Guide

This guide provides detailed information related to the features and enhancements provided in

1.2 Audience

This guide is intended for administrators who are responsible for installing, licensing, and configuring the application.





2 Release Details

This version of the product is available as an upgrade patch to the previous release.

2.1 Upgrade Patch

The following details apply to the upgrade patch version of the installation which is applied to an existing instance of the application only.

2.1.1. Upgrade Patch Details

Item	Description
Name of Install File	VCOMPatch-200118-C-6.02.00001-20012201-
	6b6ce3c1d4266835c8aae6a94dcbf4da.tar
Type of Install File	Upgrade
MD5 Checksum	6b6ce3c1d4266835c8aae6a94dcbf4da
Release Date	January 2020
Version Affected	6.2.0
Version of 3D Client Required	6.2.0

2.1.2. Upgrade Patch Prerequisites

The following items are required to complete a successful installation of this release.

Please ensure all pre-requisites are met prior to starting any installations of the application.

- WARNING: Before installing this patch, please ensure that ALL VCOM servers have at least one known-good and recent backup and/or VM snapshot to rollback to if necessary.
- All VCOM servers must have version affected (as noted above) installed
 - \circ Version number is visible on the Web Interface link ribbon bar on the upper left or
 - On the server run: cat /opt/VDC/VERSION
- WARNING: If the VCOM system consists of multiple servers, it is vital to install this patch in the following order:
 - Master Database Server first
 - Then the Master Server
 - Finally, all the Probe Servers
 - If the Master Database Server and Master Server reside on the same server, apply this patch on that server first
- Must have SSH access via a tool like PuTTY to gain command line access on the server
- Must have access to the systems using the root user account
- Root user must use BASH shell
- Must have the ability to transfer the patch file to the server (example: WinSCP)





- Confirm the integrity of the patch transfer by comparing the MD5 checksum located in the Patch Details above:
 - After moving the file from your local system to the application server run: md5sum PATCH NAME.tar.bz2

2.1.3. Upgrade Patch Installation Instructions

Follow the instructions below to successfully apply this version of the product to your existing application servers.

WARNING you will be presented with a similar message at the beginning of the installation. Please ensure that the conditions are met before starting the install.



- Upload PATCH_NAME.tar.bz2 onto all application servers under /tmp/
- Login to all application servers as root user
- Extract the patch installer by running:
 - o tar -C /opt/VDC -xvf /tmp/PATCH NAME.tar.bz2
- Apply the patch by running:
 - o /opt/VDC/patch/PATCH_NAME/install -u {certified |
 customized | locked}

The -u option is **NOT** required for this patch. It will control how updates to the model library will be processed. Most upgrade packages include updates to existing models and creation of new models in the model database. Select one of the three options for managing this model update like in the example below:

/opt/VDC/patch/PATCH NAME/install -u certified

- Certified The application will receive the most up to date model information for models included in the upgrade file. For existing models, changes to the model will be overwritten with the configurations included in the patch. If the model does not exist, then it will be created.
- Customized If the model exists in the application it will NOT be updated with the information contained in the upgrade file. If the model does not exist, then it will be created.





- Locked The model information will NOT be processed into the application as part of the upgrade process.
- Monitoring Templates If you have modified any of the system monitoring templates, by adding OIDs, etc. those changes will be kept by default during the upgrade.
 - To RESET the system monitoring templates back to the original system settings you must use the -P option. For example: /opt/VDC/patch/PATCH NAME/install -P -u certified
- Clear browser history after installation before launching a web session to log into the new version of the application.





3 6.2.1 Enhancements

3.1 Enhancements Table

ID	Description
3618	Bug 11105,11104 Fixed the Location calculate issue
3619	Manage upload library change default the option to All Files.
3620	UPS Firmware Version
3621	[!BVG-242-75886]: VPM version 6.2.0 APC product line mispelled
3622	Set wall height
3623	RPDU and ATS Dashboard Power Path link
3624	Clearmon9.sh script overwritten issue
3625	UPS MS Card discovery add Serial Number

• 3618 Bug 11105,11104 Fixed the Location calculate issue

When the Location have Actual Power doesn't have data in area level, the Estimated Yearly Cost should also no data. Fixed the issue that the Estimated Yearly Cost value unit transfer error.

Before:

Visual Data Center	(A CONTRACTOR
• • •	< ≡	Location - Floor1				
Group By None v	View	Deploy	Ste Data Attributes	Graphs Alarms	Calendar Devices	Parts
Search		* =	- Mar - E	· •		
Υ & World [3] Ψ ■ Afghanistan [1]	Design Rat	k Space				
₩ @ Budghis (1)	Ante	Designed Rack Number	Designed Rack Space (H ²)	Designed Rack Variable	Total Designed Rack Space (R ¹)	Used Rack Space (R ²)
T 🚵 Gula 1 Naw [1]	Area1		0.00		0.00	0.00
> III 16building [2]	Area2		0.00		0.00	0.00
▼ ■Australia [1]	Area1		0.00		0.00	0.00
T Clueensland	Arrest		0.00		0.00	425.67
■ BOR Building (1)	70.004		0.00		4.00	422.07
F MChina [2]	Au	billute			Value	
V∉Hunan [1]	the Ac	tual Power				
₹_dungsha [t]	- Co	eling - Tons Capacity			44.5 to	n:
7 m0723 Building (1)	11 Co	oling Utilization			4,450 1	C
HeatHoort 4	-	Imated Yearly Cost			\$ 2,014	.8
Elensi	35 Est	timated Yearly Power Consumpt	5on		8,760 k	w
El Ares2	E FR	int U Space Remaining			2.1871	1
El Arread	and Free	ont U Space Total			2,2711	
El Persona	100					





Now:

	Attribute	Value
-	Cooling Utilization	
- ini	Estimated Yearly Cost	
55	Estimated Yearly Energy Consumption	
iter	Front U Space Remaining	42 U
-	Front U Space Reserved	00
25	Front U Space Total	42 U
	Front U Space Used	0 U

• 3619 Manage upload library change default the option to All Files

When upload the library under manage page, browse file the default option is All files.

Visual D	A Ladia	R			Table States	N.	Later Series	No.		2	0	• •	0	9
	- U. AND - 30 X 100 - 20 X 100 - 11 20 - 11 20	Statute of	Palace Arriver Baylor Analys Baylor	Non-State	Index Marina Divisional Divisional Divisional	And Branch	And			- To	Test 10%		-	2000-0100
-	-	are (]						at the int						-
Types Manufactures Manufactures Manufactures Manufactures Manufactures	iterature Types Description	*												
El Seno de l'essenties	2												100	-

• 3620 UPS Firmware Version

Change Firmware Software as Firmware version for UPS devices

	1. Select Seguri 1			\rightarrow	2 Upperd No.			- Arm	ma Pite		
sile	at this type of lingu	f practice by the complete	d.								
) Des	Weitch C Devic	at POURP hard	h (C Godeni ()	Cevia Notare	- Derite Centigere	ites - C ITTAR Mode	Westign 10.1	та Антон Мерлер			
in the second se	ri darinan ena meri	te opdate.									
4	declarer 10					- 108	00-0	alle or t			
	A187000	Derive DF	Market	Sand Rombo) ^a Johnson	Dairy Chair #	Overer	Opinia Dona	Personal Version	Rect -	Addition
	bent,	ret	Seet.	init	birth.	hints.	liest.	loch.	leint,	loan	Teern-
		alanti - Bahash Hali - Mina	38250	el: Grasseener. Mag: SP258	30.38.00.224			kerbat.	W/\ 01.14.0026		
		ni#5- Connecties Web:SHVF Conf	PW9138.7089- 8030	E Q042540044, Mgc 10000647- FFE	192,508,111,319			Palific	PP-0.13 PM-3-30	Rickl Reutle_Robert	
		1975- Falanta/1890	linicos	diments?	10.05.00.024			1111 per pet dania grace	Network Management Card V6.0018		
		1075-101-00-25 10-00-76-03	10004077-0311	8412/15006	10.16.00324			kri-bol/whi	661		





• 3621 [!BVG-242-75886]: VPM version 6.2.0 APC product line misspelled

The Model AP7802 product line is spelled "Seitched Rack PDU" and this should read "Switched Rack PDU".

< ≡ Mo	del - AP7802	
Name	 4/7902 	Product Line * Sectional Rack POW
UUID	391a7e77-000-11e9-0416-005550000010	Energy Type
Туре	PDU Madminist	Description
Manufacturer	• APC	

• 3622 Set wall height

Add the function for set wall height.



• 3623 RPDU and ATS Dashboard Power Path link

Update the PDU – Rackmount and Transfer Switch Rackmount device dashboard Power Path link from flash page to h5 page.





Dashbuard	Gaphs ÎÎÎÎ	Parts	Alarma	Calendar 201	Attributes	Monthor	Applications	images	Gniupi A	tarka.	Projects	Root Cause
impact									*	÷		
Output						Cont	guration					
Attribute			Value			Am	lbute		v	ahie		

Voltage			120.8 V	Input Voltage Rating				1.0 V
Current			0.0 A	Input Frequency Rating				60.0 Hz
Status Internal F	allure		Good	Preferred			5	durce 1
Status Output			Output Provered	Sensitivity				Normal
Status Overload			No Overload	Transfer Mode			51	tandard
Status Over Tem	perature		No Over Temperature	Last Transfer Test Result			No Test i	nitiated
Status Short Circ	uit .		No Short Circuit	-				
Status Communi	ication Low		Good	Environment				
Status Configura	tion Failure		Good	Attribute		Value		
Contact Sensors				Temperature				
Senaar	Type	Statue	Description	Humidity				
1	Normally Open	Closed With Notice	Input #1	Capacity	-			
2	Normally Open	Closed With Notice	input #2				Power Path (Connect
				Metrics Total	Used	Reserved	Available	

✓ ■ Power Path - eATS - GAD5F33062



• 3624 Clearmon9.sh script overwritten issue

Fixed the /opt/VDC/bin/clearmon9.sh overwritten issue.





• 3625 UPS MS Card discovery add Serial Number

Add the Serial Number for UPS MS card discovered device.

Device 1	Type	Manufectorer	Product Line	Model	Lifecycle Status	Acort Tag	Serial Number	IP Address
eupa	biarch	Search	Service.	Septer.	Sauritui	Jaardh	Seath.	226
wURS - Bulloch Hull - Shop	UPS-Rackmount	Eaton	50	5#750	available		(D: G128/46054, Mig) 5#750	10.10.10.22
eUPS - EatonSP1000	UP5 - Rackindunt	Eaton	52	5#1000	Available		G123/46317	10.30.10.22
eUP5 - upe-00-20-95- 69-79-63	UP5 - Rackressunt	Exton	Powerware 5110	103004257-5591	Availabie		8F12/15003	10.10.10.23