



Eaton  
Electronics Division  
5735 W. Las Positas Blvd #100  
Pleasanton, CA 94588  
www.eaton.com/electronics

## Product Change Notice

PCN#: EE-PCN16043

11/21/2016

### CLASSIFICATION OF CHANGE:

Documentation

### DESCRIPTION OF CHANGE:

Maximum surge voltage is specified incorrectly on the datasheet. Change from 3.0V to 2.8V.

### REASON FOR CHANGE:

Correct documentation

### EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices.

### PARTS NUMBERS AFFECTED:

HB0820-2R5305-R	HB1840-2R5606-R
HB1020-2R5505-R	HB1860-2R5117-R
HB1030-2R5106-R	
HB1325-2R5156-R	
HB1625-2R5256-R	
HB1635-2R5356-R	

### TIME SCHEDULE:

Start Shipment Date: N/A

Last Time Buy Date: N/A

Last Time Shipment Date: N/A

**SAMPLE AVAILABILITY:** N/A

**QUALIFICATION DATA:** N/A

### ISSUED BY:

Global Product Manager: Jason Lee

### CONTACT INFORMATION:

For questions or comments, please contact your local [Eaton sales representative](#).