

## Product Change Notice

PCN#: EE-PCN17043

09/20/2017

### CLASSIFICATION OF CHANGE:

Appearance and packaging


### DESCRIPTION OF CHANGE:

COLOR OF EPOXY ON BOTTOM CORNERS FROM GRAY TO BLACK.

CORRECT ERROR IN THE REPRESENTATION OF THE PART ORIENTATION IN THE TAPE & REEL CARRIER POCKET FROM:



TO:



### REASON FOR CHANGE:

Color change due to request from manufacturing to improve detection of epoxy near the SMT terminals. Internal documentation has had instructions to orient it as proposed, but external documentation had an error.

### EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices. Customer needs to confirm if the orientation conforms to their pick and place operation.

### PARTS FAMILIES AFFECTED:

DRAQ75-470-R

**TIME SCHEDULE:**

Start Shipment Date: N/A

Last Time Buy Date: N/A

Last Time Shipment Date: N/A

**SAMPLE AVAILABILITY:**

N/A

**QUALIFICATION DATA:**

N/A

**ISSUED BY:**

Global Product Manager: Steve Subiry

**CONTACT INFORMATION:**

For questions or comments, please contact your local [Eaton sales representative](#).