

## Product Change Notice


April 17, 2015

### CLASSIFICATION OF CHANGE:

Datasheet correction.

### DESCRIPTION OF CHANGE:

The Eaton PowerStor KR Family of supercapacitors in 0.1, 0.22, 0.33 and 0.47F capacities with an "H" configuration are shown with an incorrect polarity in the drawing on page 3 of the datasheet. The datasheet is updated to reflect the correct polarity.



### REASON FOR CHANGE:

Update datasheet to reflect actual part polarity.

### EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

No change to the part has been implemented according to actual part markings.

### PARTS NUMBERS/SERIES/FAMILIES AFFECTED:

KR-5R5H104-R

KR-5R5H224-R

KR-5R5H334-R

KR-5R5H474-R

### TIME SCHEDULE:

Datasheet updated April 2015.

Last Time Buy Date: n/a

Last Time Shipment Date: n/a

### SAMPLE AVAILABILITY:

n/a

### QUALIFICATION DATA:

n/a

### ISSUED BY:

Jason Lee, Global Product Manager - Supercapacitors

If you have any question about this product change, please contact your local Eaton representative or [CapacitorTech@eaton.com](mailto:CapacitorTech@eaton.com).