**IF LBL1510** 

R Crouse-Hinds

## **SAVE THESE INSTRUCTIONS FOR FUTURE REFERENCE**

**ACAUTION** Read carefully before installing and wiring the receptacle. Any warning or special instructions should be closely followed. Check the ratings to insure suitability for the environment & supply. Must be installed in accordance with the NEC or CEC and all other applicable codes. All receptacles must be properly grounded. These devices are not suitable for hazardous locations

These devices are not provided with cable entry holes. All holes added should be done by experienced personnel through the thickened areas of the junction box suitable for threading. Keep tightly closed when in operation. Do not attempt to install this receptacle unless you are familiar with warnings, cautions and procedures outlined in this information sheet.

## INSTALLATION & ELECTRICAL WIRING

**AWARNING** Risk of electrical shock hazard, only qualified personnel should conduct this procedure!

Do not make electrical connections with the power ON. Use cu or cu clad wire only. These units are provided with receptacles for operation on 125 vac (208,250,277,480,600 vac optional) max. 20 amps. Consideration to the number of receptacles installed on each line should be given when selecting cable size. Apply lubicant to all screws and threads during installation, failure to use can result in voiding warranty.

1. Locate and drill cable gland hole through the thickened area of the junction box (0A) per instructions furnished with cable gland

(not provided). Clean all foreign material out of junction box.

- 2. Mount the junction box (0A) in its intended location using
- 1/4" bolts (not provided). See illustration below for mounting dimensions.
- 3. Cables should be stripped back approx. 6" 10" to allow individual
- 4. Install cable glands (not provided) per instructions furnished with cable gland.
- 5. Route cable in through cable gland and secure seal on cable jacket.


## A CAUTION See cover label for voltage and current rating.

6. (2P3W) - Insert L1 (Load) lead into sleeve of receptacle (4A) and secure with set screw (9D). Insert L2 (Neutral) lead into sleeve of receptacle (4A) and secure with set screw (9E).

**6.** (3P4W) - Insert L1 lead into sleeve of receptacle (4A) and secure with set screw. Insert L2 lead into sleeve of receptacle (4A) and secure with set screw.

Insert L3 lead into sleeve of receptacle (4A) and secure with set screw.

- 7. Connect Green or earth wire to Ground sleeve on rear of receptacle
- (4A) and secure with set screw (9F). Also connect ground to green screw (9C).
- 8. Mount receptacle (4A) to the cover (1A) with two #8 screws (9A) provided, position gasket (7B) between receptacle and cover.
- 9. Slip gasket (7A) over cover (1A) so it can be installed between
- 10. Mount cover with #10 screws (9B) provided. Torque screws only



All statements, technical information and recommendations contained herein are based on information and tests we believe to be reliable. The accuracy or completness thereof are not guaranteed. In accordance with Crouse-Hinds "Terms and Conditions of Sale", and since conditions of use are outside our control, the purchaser should determine the suitability of the product for his intended use and assumes all risk and liability whatsoever in connection therewith.

