



Powering Business Worldwide

Eaton Aerospace Master Technical Publications Index List

EATON BEDHAMPTON	EATON BELTSVILLE	EATON BETHEL	EATON EUCLID	EATON GLENOLDEN	EATON GRAND RAPIDS	EATON IRVINE	EATON JACKSON	EATON JACKSON	EATON LOS ANGELES	EATON TITCHFIELD	EATON LAKESIDE
Larchwood Avenue	11642 Old Baltimore Pike	15 Durant Avenue	23555 Euclid Avenue	24 East Glenolden Avenue	3675 Patterson Avenue	9650 Jeronimo Road	5353 Highland Drive	300 South East Avenue	4690 Colorado Boulevard	Abbey Park, Southampton Road,	Fluid & Electrical Distribution
Bedhampton, Havant	Beltsville, MD 80705 USA	Bethel, CT 06801	Cleveland, OH	Glenolden, PA 19036	Grand Rapids, MI 49512	Irvine, California 92618	Jackson, Mississippi 39206	Jackson, Michigan 49203	Los Angeles CA 90039	Titchfield, Fareham, Hampshire,	Division, Broad Ground Road,
PO9 3QL		USA	USA	USA	USA	USA	USA	USA	USA	PO14 4QA	Lakeside, Redditch, Worcestershire, B98 8YS
UK	FAA Certificate: XEPR787K									UK	
FAA Certificate: VS6Y531J	EASA Certificate: 145.5437	FAA Certificate: E1TR150N	FAA Certificate: A6GR410J	FAA Certificate: ENOR612Y	FAA Certificate: VKGR687N	FAA Certificate: QCSR241K	FAA Certificate: EF4R152M		FAA Certificate: FH3R501L	FAA Certificate: G7EY819J	
CAA Certificate: UK 145.00817		EASA Certificate: 145.4401	EASA Certificate: 145.4167	EASA Certificate: 145.6285	EASA Certificate: 145.5037	EASA Certificates: 145.4057	EASA Certificates: 145.4999		EASA Certificate: 145.4998	CAA Certificates: UK 21G.2336 & UK 145.00769	
CAAC Certificate: F04400198	Cage Code: 15284		CAAC Certificate: F00100321								
Cage Code: K4413		Cage Code: 02750	Cage Code: 59875	Cage Codes: 16780 & 97484	Cage Codes: 17472, 72121 & 09145	Cage Codes: 86090 & OTD23	Cage Codes: 62983 & 90166	Cage Code: 00624	Cage Codes: 99643, 76050, 09790 & 52906	Cage Codes: K2523, U9084, U1918 & K2617	Cage Code: U2569

For all Index queries please contact Robert Lamb, Supportability Manager, Aerospace Group: techdocenquiry@eaton.com

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
194875	MF64-3906-30BC S394	AP105B-1524-3A6	CMM	Hydraulic Motor	--	Jan 01/92	2	SEA KING	Eaton Bedhampton	K4413	--
227767	MF-024-B006-GB1	29-10-022	CMM	Constant Displacement Hydraulic Motor Assembly	--	Apr 01/72	0	TRANSAAL C160	Eaton Bedhampton	K4413	--
331612	MF69-3906-30BC-S701	AP105B-1530-3A6	CMM	Hydraulic Motor	--	Feb 01/94	2	SEA KING	Eaton Bedhampton	K4413	--
384922	MPEV3-011-13 GB1	29-21-03	CMM	Variable Displacement Hydraulic Pump Assembly	--	Nov 17/00	2	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
385184	MPEV3-011-13 GB1	29-21-04	CMM	D.C. Electric Motor Subassembly	--	Apr 09/01	2	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
453627	PV3-075-9UK1B	29-10-38	CMM	Variable Displacement Hydraulic Pump Assembly	--	Mar 5/99	8	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
453665	MPEV3-011-8UK 2B	29-10-41	CMM	Hydraulic Motorpump Assembly	--	Mar 15/10	6	CASA CN 235, CASA CN 295	Eaton Bedhampton	K4413	--
933402	MPEV3-011-8UK 2C	29-10-41	CMM	Hydraulic Motorpump Assembly	--	Mar 15/10	6	CASA CN 235, CASA CN 295	Eaton Bedhampton	K4413	--
453740	HR6B9-002-EA2	27-31-01	CMM	In Line Relief Valve	--	Mar 19/91	1	BAe 125	Eaton Bedhampton	K4413	--
453897	PPEV3-011-12EA1	52-38-05	CMM	Hydraulic Power Package Assembly	--	Jan 25/91	2	LOCKHEED L1011 TRISTAR	Eaton Bedhampton	K4413	--
454166	PV3-022-21EA1A	AP105B-0146-136	CMM	Variable Delivery Hydraulic Pump	--	Mar 01/99	0	TUCANO	Eaton Bedhampton	K4413	--
454464	HR6B9-002-EA4	27-31-01	CMM	In Line Relief Valve	--	Mar 19/91	1	BAe 125	Eaton Bedhampton	K4413	--
454466	MF3-022-2GB1G	TMRC 19-11-01	CMM	Hydraulic Motor	--	May 29/87	2	TORNADO	Eaton Bedhampton	K4413	--
454481	PPEV3-008-EA1A	29-10-43	CMM	Electric Motor Driven Hydraulic Pump Package Assembly	--	Jul 12/04	12	PIAGGIO P180	Eaton Bedhampton	K4413	--
520393	PV3-032-3EA2	29-10-50	CMM	Variable Displacement Hydraulic Pump Assembly	--	Mar 17/04	1	HAL ADVANCED LIGHT HELICOPTER	Eaton Bedhampton	K4413	--
520550	PV3-115-EA1C	29-21-05	CMM	Variable Displacement Hydraulic Pump Assembly	--	Jul 30/04	8	A319, A320, A321	Eaton Bedhampton	K4413	--
520551	PV3-205-30GB3B	TMRC 21-10-02	CMM	Engine Driven Variable Delivery Pressure Controlled Hydraulic Pump	--	Mar 02/01	6	TORNADO	Eaton Bedhampton	K4413	--
520567	CMV3-022-EA3	24-24-51	CMM	Constant Speed Motor/Generator Assembly	--	Sep 21/01	10	A319, A320, A321, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
520568	CMV3-022-EA3A	24-24-51	CMM	Constant Speed Motor/Generator Assembly	--	Sep 21/01	10	A319, A320, A321, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
520696	MPHF1-037-EA1A	29-10-42	CMM	Hydraulic Power Transfer Unit	--	Mar 05/99	3	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
520800	PPEV3-008-EA3	29-10-45	CMM	Electric Motor Driven Hydraulic Pump Package Assembly	--	Mar 26/04	9	PILATUS PC12	Eaton Bedhampton	K4413	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
520805	MF3-032-EA3E	27-50-01	CMM	Fixed Displacement Hydraulic Motor Assembly	--	Sep 30/94	5	A320	Eaton Bedhampton	K4413	--
520814	PPEV3-008-EA2A	29-10-43	CMM	Electric Motor Driven Hydraulic Pump Package Assembly	--	Jul 12/04	12	PIAGGIO P180	Eaton Bedhampton	K4413	--
520827	MGC-EA2	24-24-05	CMM	Generator Control Unit Assembly	--	Aug 3/01	4	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
520829	CMV3-022-EA4	24-23-01	CMM	Constant Speed Motor/Generator Assembly	--	Feb 28/02	4	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
520848	CMV3-049-EA1	24-24-03	CMM	Constant Speed Motor/Generator Assembly	--	Nov 25/02	4	A330, A340-500, A340-600	Eaton Bedhampton	K4413	--
520850	CMV3-049-EA2	24-24-01	CMM	Hydraulic Motor Generator Assembly	--	Jul 1/04	8	B757, GULFSTREAM V	Eaton Bedhampton	K4413	--
520854	MGC-EA3	24-24-02	CMM	Generator Control Unit Assembly	--	Jun 28/02	8	GULFSTREAM V, B757	Eaton Bedhampton	K4413	--
520912	CMV3-022-EA3B	24-24-51	CMM	Constant Speed Motor/Generator Assembly	--	Sep 21/01	10	A319, A320, A321, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
520913	CMV3-022-EA3C	24-24-51	CMM	Constant Speed Motor/Generator Assembly	--	Sep 21/01	10	A319, A320, A321, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
520915	MGC-050-EA2D	24-24-34	CMM	Generator Control Unit Assembly	--	May 2/03	13	A319, A320, A321, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
521100	MGC-050-EA2E	24-24-35	CMM	Generator Control Unit Assembly	--	May 6/03	4	A319, A320, A321, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
521352	MGC-EA4A	24-35-98	CMM	Generator Control Unit Assembly	--	May 9/03	5	SUPER PUMA	Eaton Bedhampton	K4413	--
521354	CMV3-022-EA5A	49-40-99	CMM	Constant Speed Motor/Generator Assembly	--	Oct 12/99	2	SUPER PUMA	Eaton Bedhampton	K4413	--
112545	MF36-3909-30Z2	29-10-003	CMM	Hydraulic Motor	--	01-Apr-76	2	SUPER PUMA	Eaton Bedhampton	K4413	--
268570	MF36-3909-30Z2-GB2	29-10-003	CMM	Hydraulic Motor	--	01-Apr-76	2	Wessex Helicopter	Eaton Bedhampton	K4413	--
521424	MF3-075-EA1E	27-40-01	CMM	Fixed Displacement Hydraulic Motor Assembly	--	Jun 13/01	5	A330, A340	Eaton Bedhampton	K4413	--
521449	PV3-115-EA3C	29-10-44	CMM	Variable Displacement Hydraulic Pump Assembly	--	Mar 30/09	7	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
715185	MPHF1-037-GB1A	AP105B-1824-13A6	CMM	Hydraulic Power Transfer Unit	--	Apr 01/99	4	JAGUAR	Eaton Bedhampton	K4413	--
715418	HR6B9-002-GB3	29-10-28	CMM	In Line Relief Valve	--	Apr 30/97	4	A300, A310	Eaton Bedhampton	K4413	--
715439	HR6B9-310-GB1A	29-10-26	CMM	Relief Valve	--	Mar 26/04	9	A300, A310	Eaton Bedhampton	K4413	--
715445	HR6B9-002-GB1A	29-10-27	CMM	Relief Valve	--	Mar 4/02	7	A300, A310, BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
715640	PV3-011-8GB1	29-10-33	CMM	Variable Delivery Hydraulic Pump	--	Dec 02/81	2	ARIANE ROCKET	Eaton Bedhampton	K4413	--
715665	PV3-075-9GB3	29-10-35	CMM	Hydraulic Pump	--	Oct 01/80	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
715745	EA50057-GB3	29-10-010	CMM	3/4" TS In-Line Relief Valve	--	Mar 05/99	4	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
715750	MPEV3-011-13 GB1	29-21-02	CMM	Hydraulic Motorpump Assembly	--	Nov 30/94	1	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
715815	PV3-044-12AGB2	None (911029) AP105B-0130-123A 29-10-59	CMM	Variable Displacement Hydraulic Pump	--	00Jun 02Apr 1	5	HAWK, T45 GOSHAWK	Eaton Bedhampton	K4413	--
715868	PV3-205-30GB3A	TMRC 21-10-02	CMM	Engine Driven Pump	--	Mar 02/01	6	TORNADO	Eaton Bedhampton	K4413	--
715995	MF3-011-2GB1D	TMRC 19-11-01	CMM	Hydraulic Motor	--	May 29/87	2	TORNADO	Eaton Bedhampton	K4413	--
715996	MF3-022-2GB1E	TMRC 19-11-01	CMM	Hydraulic Motor	--	May 29/87	2	TORNADO	Eaton Bedhampton	K4413	--
716308	PV3-017-UK1	FAP105B-0142-1 and FAP105B-0142-3	CMM	Ram Air Turbine Driven Hydraulic Pump	--	Nov 01/83	2	TORNADO	Eaton Bedhampton	K4413	--
716331	PV3-115-1UK2	AP105B-0141-13A6	CMM	Variable Delivery Hydraulic Pump	--	Jul 01/90	7	JAGUAR	Eaton Bedhampton	K4413	--
716555	MF3-115-GB2D	TMRC 19-10-01	CMM	Hydraulic Motor	--	Nov 15/83	0	TORNADO	Eaton Bedhampton	K4413	--
716558	MF3-022-2GB1F	TMRC 19-11-01	CMM	Hydraulic Motor	--	May 29/87	2	TORNADO	Eaton Bedhampton	K4413	--
716663	MPHF1-037-UK1	29-10-36	CMM	Power Transfer Unit	--	Jan 01/81	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
716853	MPHF1-037-UK2	29-10-37	CMM	Hydraulic Power Transfer Unit	--	Feb 02/90	3	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
716879	PV3-044-UK2	29-10-40	CMM	Variable Displacement Hydraulic Pump	--	Aug 16/94	1	S.211 TRAINER	Eaton Bedhampton	K4413	--
716884	HR6B9-002-UK2	29-21-01	CMM	In Line Relief Valve	--	Mar 17/97	2	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
716942	CMF3-022-2UK1	21-20-01	CMM	Solenoid Controlled Hydraulic Motor Assembly	--	Mar 27/97	3	S.211 TRAINER	Eaton Bedhampton	K4413	--
716958	PV3-075-9UK2	29-10-38	CMM	Variable Displacement Hydraulic Pump Assembly	--	Mar 5/99	8	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
716986	MF3-011-2GB1F	TMRC 19-11-01	CMM	Hydraulic Motor	--	May 29/87	2	TORNADO	Eaton Bedhampton	K4413	--
716988	PV3-075-9UK2A	29-10-38	CMM	Variable Displacement Hydraulic Pump Assembly	--	Mar 5/99	8	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
717091	PV3-075-9UK1A	29-10-38	CMM	Variable Displacement Hydraulic Pump Assembly	--	Mar 5/99	8	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
776001	MF1-009-GB2	AP105B-1554-13A6	CMM	Fixed Stroke Hydraulic Motor	--	Jul 01/96	3	JAGUAR	Eaton Bedhampton	K4413	--
776876	HR6B9-002-GB2	29-10-28	CMM	In Line Relief Valve	--	Apr 30/97	4	A300, A310	Eaton Bedhampton	K4413	--
848354	PV3-300-13C	29-10-41	CMM	Variable Displacement Hydraulic Pump	--	Jun 02/09	15	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
849356	PPV3-011-2C	29-11-04	CMM	Pump Package Assembly	--	Apr 02/07	5	A129	Eaton Bedhampton	K4413	--
920395	MGC-EA1B	24-24-04	CMM	Generator Control Unit Assembly	--	Jun 5/01	8	A340-500, A340-600	Eaton Bedhampton	K4413	--
920422	PPEV3-008-EA3A	29-10-45	CMM	Electric Motor Driven Hydraulic Pump Package Assembly	--	Mar 26/04	9	PILATUS PC12	Eaton Bedhampton	K4413	--
920449	MF3-075-EA1F	27-40-02	CMM	Fixed Displacement Hydraulic Motor Assembly	--	Mar 11/02	5	A330, A340	Eaton Bedhampton	K4413	--
920550	MF3-032-EA3F	27-50-01	CMM	Fixed Displacement Hydraulic Motor Assembly	--	Sep 30/94	5	A320	Eaton Bedhampton	K4413	--
920582	CMV3-049-EA1A	24-24-03	CMM	Constant Speed Motor/Generator Assembly	--	Nov 25/02	4	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
920635	HR6B9-002-EA5	29-10-27	CMM	Relief Valve	--	Mar 4/02	7	A300, A310	Eaton Bedhampton	K4413	--
928005	MGC-EA1C	24-24-04	CMM	Generator Control Unit Assembly	--	Jun 5/01	8	A340-500, A340-600	Eaton Bedhampton	K4413	--
928078	CMV3-049-EA3	24-24-06	CMM	Hydraulic Motor Generator Assembly	--	-	2	GULFSTREAM V	Eaton Bedhampton	K4413	--
928080	MGC-EA6	24-24-07	CMM	Generator Control Unit Assembly	--	Feb 23/96	0	GULFSTREAM V	Eaton Bedhampton	K4413	--
928099	PPV3-056-2D	29-11-01	CMM	Variable Displacement Pump Package Assembly	--	Jul 31/00	3	A129	Eaton Bedhampton	K4413	--
928178	RRS-190-1A	29-21-08	CMM	Reservoir Assembly	--	Jul 7/03	3	EH101 MERLIN	Eaton Bedhampton	K4413	--
928179	RRS-500-EA1	29-21-07	CMM	Reservoir Assembly	--	Jul 7/03	4	EH101 MERLIN	Eaton Bedhampton	K4413	--
933196	PV3-044-UK2A	29-10-51	CMM	Variable Displacement Hydraulic Pump	--	Nov 30/98	0	S.211 TRAINER	Eaton Bedhampton	K4413	--
933197	CMF3-022-2UK1A	21-20-02	CMM	Solenoid Controlled Hydraulic Motor Assembly	--	Jun 25/01	1	S.211 TRAINER	Eaton Bedhampton	K4413	--
933239	MF3-075 EA1G	27-40-01	CMM	Fixed Displacement Hydraulic Motor Assembly	--	Jun 13/01	5	A330, A340	Eaton Bedhampton	K4413	--
933249	MF3-075-EA1H	27-40-02	CMM	Fixed Displacement Hydraulic Motor Assembly	--	Mar 11/02	5	A330, A340	Eaton Bedhampton	K4413	--
933252	MF3-075-EA1J	27-40-02	CMM	Fixed Displacement Hydraulic Motor Assembly	--	Mar 11/02	5	A330, A340	Eaton Bedhampton	K4413	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3022142-000	MF3-075-EA1K	27-40-06	CMM	Fixed Displacement Hydraulic Motor Assembly	--	Jan31/19	0	A330, A340	Eaton Bedhampton	K4413	--
933260	PV3-115-EA1D	29-21-10	CMM	Variable Displacement Hydraulic Pump Assembly	--	Nov 30/04	2	A319, A320, A321	Eaton Bedhampton	K4413	--
933270	MPEV3-008-EA3	29-21-09	CMM	DC Electric Driven Hydraulic Motorpump Assembly	--	Apr 9/01	2	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
933322	PPEV3-008-EA3B	29-10-47	CMM	Electric Motor Driven Hydraulic Pump Package Assembly	--	Mar 26/04	6	PILATUS PC12	Eaton Bedhampton	K4413	--
933340	PPEV3-008-EA3C	29-10-45	CMM	Electric Motor Driven Hydraulic Pump Package Assembly	--	Mar 26/04	9	PILATUS PC12	Eaton Bedhampton	K4413	--
933392	PPV3-056-2E	29-11-02	CMM	Variable Displacement Pump Package Assembly	--	Dec 23/03	5	EH101 MERLIN	Eaton Bedhampton	K4413	--
933476	MPEV3-008-EA3A	29-21-09	CMM	DC Electric Driven Hydraulic Motorpump Assembly	--	Apr 9/01	2	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
933578	PPEV3-008-EA3D	29-10-54	CMM	Electric Motor Driven Hydraulic Pump Package Assembly	--	Mar 26/04	2	PILATUS PC12	Eaton Bedhampton	K4413	--
971600	MPHV3-115-1C	29-10-57	CMM	Hydraulic Power Transfer Motorpump Assembly	--	Jul 31/01	1	A319, A320, A321	Eaton Bedhampton	K4413	--
971844	PV3-300-13E	29-10-41	CMM	Variable Displacement Hydraulic Pump	--	Jun 02/09	15	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
972630	PV3-300-13F	29-10-41	CMM	Variable Displacement Hydraulic Pump	--	Jun 02/09	15	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974014	MPHV3-115-1B	29-10-57	CMM	Hydraulic Power Transfer Motorpump Assembly	--	Jul 31/01	1	A319, A320, A321	Eaton Bedhampton	K4413	--
974540	MPEV3-032-15	29-10-72	CMM	Motorpump Assembly	--	Jun 03/11	7	A319, A320, A321, A330, A340, A340-500/600	Eaton Bedhampton	K4413	--
3022143-000	MPEV3-032-EA3	29-22-03	CMM	Motorpump Assembly	--	Jun 01/15	0	A320 NEO	Eaton Bedhampton	K4413	--
3022147-100	MPEV3-032-EA5	29-22-06	CMM	Motorpump Assembly	--	Jan 25/18	0	KC390	Eaton Bedhampton	K4413	--
974800	PV3-300-13L	29-10-55	CMM	Variable Displacement Hydraulic Pump	--	Jan 26/09	10	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974947	PV3-300-13H	29-10-41	CMM	Variable Displacement Hydraulic Pump	--	Jun 02/09	15	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974976	PV3-300-13K	29-10-41	CMM	Variable Displacement Hydraulic Pump	--	Jun 02/09	15	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
3022008-000	CMV3-049-EA5	24-24-08	CMM	Hydraulic Motor Generator Assembly	--	Jul 1/04	1	B757, GULFSTREAM V	Eaton Bedhampton	K4413	--
3022010-000	MF2-019-EA1	911090	CMM	Fixed Displacement Bent Axis Motor Assembly	--	Apr 05/04	0	GRIPEN	Eaton Bedhampton	K4413	--
3022016-000	HR6B9-002-EA5A	29-10-53	CMM	Manual Depressurising Relief Valve Assembly	--	Mar 6/02	1	A319, A320, A321	Eaton Bedhampton	K4413	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3022017-001	MF3-075-EA2A	27-40-03	CMM	Fixed Displacement Hydraulic Motor Assembly	--	Mar 11/02	1	A340-500, A340-600	Eaton Bedhampton	K4413	--
3022018-000	CMV3-049-EA6	24-24-09	CMM	Hydraulic Motor Generator Assembly	--	Jan 25/10	1	GULFSTREAM V	Eaton Bedhampton	K4413	--
3022024-000	PPV3-056-2F	29-11-03	CMM	Variable Displacement Pump Package Assembly	--	Dec 23/03	4	EH101 MERLIN	Eaton Bedhampton	K4413	--
3022049-000	CMV3-022-EA4B	24-23-03	CMM	Constant Speed Motor/Generator Assembly	--	Jul 16/04	1	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
3022053-000	PV3-300-EA2	29-10-56	CMM	Variable Displacement Hydraulic Pump	--	Sep 18/18	5	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
3022053-001	PV3-300-EA2A	29-10-56	CMM	Variable Displacement Hydraulic Pump	--	Sep 18/18	5	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
3022151-000	PV3-300-EA4	29-10-56	CMM	Variable Displacement Hydraulic Pump	--	Sep 18/18	5	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
3022071-006	MPEV3-035-EA1F	29-21-18	CMM	Motorpump Assembly	--	Jan 15/16	3	A380	Eaton Bedhampton	K4413	--
3022071-007	MPEV3-035-EA1G	29-21-18	CMM	Motorpump Assembly	--	Jan 15/16	3	A380	Eaton Bedhampton	K4413	--
3022071-008	MPEV3-035-EA1H	29-21-18	CMM	Motorpump Assembly	--	Jan 15/16	3	A380	Eaton Bedhampton	K4413	--
3022071-009	MPEV3-035-EA1J	29-21-18	CMM	Motorpump Assembly	--	Jan 15/16	3	A380	Eaton Bedhampton	K4413	--
3022071-010	MPEV3-035-EA1K	29-21-18	CMM	Motorpump Assembly	--	Jan 15/16	3	A380	Eaton Bedhampton	K4413	--
3022072-004	MPP-EA1D	29-21-17	CMM	Motor Control and Protection unit	--	Apr 01/07	0	A380	Eaton Bedhampton	K4413	--
3022073-002	MPS-EA1B	29-21-12	CMM	Motor Switching Unit	--	Oct 12/06	0	A380	Eaton Bedhampton	K4413	--
3022078-001	RMV3-075-EA1A	27-80-48	CMM	Servo Controlled Variable Displacement Motor	--	Oct 31/14	1	A380	Eaton Bedhampton	K4413	--
3022079-304	NA	29-20-03	CMM	Reservoir Filling Hand Pump	--	Feb15/08	0	A380	Eaton Bedhampton	K4413	--
3022079-324	NA	29-20-04	CMM	Reservoir Air Pressure Valve	--	Aug 08/16	0	A380	Eaton Bedhampton	K4413	--
3022081-000	PPV3-011-2D	29-11-04	CMM	Pump Package Assembly	--	Apr 02/07	5	A129	Eaton Bedhampton	K4413	--
3022109-000	HD1B9-026-EA1	29-31-01	CMM	Reservoir Filling Selector Valve Assembly	--	Jan 02/08	0	A380	Eaton Bedhampton	K4413	--
3031733-001	PV3-300-31G	29-10-60	CMM	Variable Displacement Hydraulic Pump	--	Mar 20/18	9	A380	Eaton Bedhampton	K4413	--
3032374-001	PV3-300-31J	29-10-60	CMM	Variable Displacement Hydraulic Pump	--	Mar 20/18	9	A380	Eaton Bedhampton	K4413	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3032782-000	PV3-300-31K	29-10-60	CMM	Variable Displacement Hydraulic Pump	--	Mar 20/18	9	A380	Eaton Bedhampton	K4413	--
3032793-000	PV3-300-31L	29-10-60	CMM	Variable Displacement Hydraulic Pump	--	Mar 20/18	9	A380	Eaton Bedhampton	K4413	--
3032793-001	PV3-300-31M	29-10-60	CMM	Variable Displacement Hydraulic Pump	--	Mar 20/18	9	A380	Eaton Bedhampton	K4413	--
3032793-002	PV3-300-31N	29-10-60	CMM	Variable Displacement Hydraulic Pump	--	Mar 20/18	9	A380	Eaton Bedhampton	K4413	--
3032793-003	PV3-300-31P	29-10-60	CMM	Variable Displacement Hydraulic Pump	--	Mar 20/18	9	A380	Eaton Bedhampton	K4413	--
71149-3	NA	24-23-02	CMM	Standby Generator Selector Valve Assembly	--	Oct 11/99	3	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
891392	HD6B9-140-EA1	29-20-05	CMM	Service Selector Valve Assembly	--	Nov 14/16	--	PILATUS PC12	Eaton Bedhampton	K4413	--
229183	AA-65674-L6	NAVWEPS 03-30CH-106	--	Handbook Overhaul Instructions	--	Dec 15/65	--	--	Eaton Bedhampton	K4413	--
453627	PV3-075-9UK1B	716958-29-02	SB	New piston and shoe subassemblies	--	Jan 16/86	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
453627	PV3-075-9UK1B	716958-29-03	SB	Improved shaft seal subassembly	--	Jan 16/86	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
453627	PV3-075-9UK1B	716958-29-04	SB	Improved drive shaft bearing	--	Aug 14/87	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
453665	MPEV3-011-8UK 2B	453665-29-01	SB	Reduced torque tightening of pump securing nuts	--	Mar 01/89	0	CASA CN 235, CASA CN 295	Eaton Bedhampton	K4413	--
453665	MPEV3-011-8UK 2B	453665-29-02	SB	Damaged electric motor armature	--	May 20/93	1	CASA CN 235, CASA CN 295	Eaton Bedhampton	K4413	--
453665	MPEV3-011-8UK 2B	453665-29-03	SB	Uneven electric motor brush wear	--	Jul 27/93	0	CASA CN 235, CASA CN 295	Eaton Bedhampton	K4413	--
453665	MPEV3-011-8UK 2B	453665-29-04	SB	Improved performance of the electric motor subassembly	--	Jul 28/93	0	CASA CN 235, CASA CN 295	Eaton Bedhampton	K4413	--
453897	PPEV3-011-12EA1	453897-52-01	SB	Improved filler and breather assemblies and start valve retainer	--	Nov 03/87	0	L-1011 Tristar	Eaton Bedhampton	K4413	--
454083	CMV3-022-EA2	520568-24-02	SB	Modified solenoid control valve	--	Aug 24/89	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
454083	CMV3-022-EA2	454083-24-01	SB	Prevent fluid entering connectors	--	Jan 16/89	0	A320	Eaton Bedhampton	K4413	--
520550	PV3-115-EA1C	520550-29-01	SB	Strengthened hold down plate retainer and retaining plate segment attaching screws	--	Mar 30/90	0	A319, A320, A321	Eaton Bedhampton	K4413	--
520550	PV3-115-EA1C	520550-29-02	SB	Improved yoke	--	Mar 30/90	0	A319, A320, A321	Eaton Bedhampton	K4413	--
520550	PV3-115-EA1C	520550-29-03	SB	Change the Hydraulic Pump Assembly Part Number 520550 (Model PV3-115-EA1C) to Hydraulic Pump Assembly Part Number 022260 (Model PV3-115-EA1C)	--	Jul 19/04	0	A319, A320, A321	Eaton Bedhampton	K4413	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
520567	CMV3-022-EA3	520568-24-01	SB	Increased qualification standard of diodes installed in drive shaft subassembly	--	Jul 31/89	1	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520567	CMV3-022-EA3	520568-24-02	SB	Modified solenoid control valve	--	Aug 24/89	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520567	CMV3-022-EA3	520568-24-03	SB	Change of seep drain unions	--	Jul 22/92	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520567	CMV3-022-EA3	520568-24-04	SB	Change of mounting flange, inserts and pins	--	Jan 06/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520567	CMV3-022-EA3	520568-24-05	SB	Change of servo control valve	--	Jan 16/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520567	CMV3-022-EA3	520568-24-06	SB	Change of housing, inserts and plug subassembly	--	Jan 16/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520567	CMV3-022-EA3	520568-24-07	SB	Change of valve plate, bearing and pins subassembly	--	Jan 16/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520568	CMV3-022-EA3A	520568-24-01	SB	Increased qualification standard of diodes installed in drive shaft subassembly	--	Jul 31/89	1	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520568	CMV3-022-EA3A	520568-24-02	SB	Modified solenoid control valve	--	Aug 24/89	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520568	CMV3-022-EA3A	520568-24-03	SB	Change of seep drain unions	--	Jul 22/92	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520568	CMV3-022-EA3A	520568-24-04	SB	Change of mounting flange, inserts and pins	--	Jan 06/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520568	CMV3-022-EA3A	520568-24-05	SB	Change of servo control valve	--	Jan 16/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520568	CMV3-022-EA3A	520568-24-06	SB	Change of housing, inserts and plug subassembly	--	Jan 16/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520568	CMV3-022-EA3A	520568-24-07	SB	Change of valve plate, bearing and pins subassembly	--	Jan 16/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520586	MGC-050-EA2A	520754-24-01	SB	Reduce operating temperature of transistor Q7	--	Aug 24/89	0	A320	Eaton Bedhampton	K4413	--
520738	MGC-050-EA2B	520754-24-01	SB	Reduce operating temperature of transistor Q7	--	Aug 24/89	0	A320	Eaton Bedhampton	K4413	--
520738	MGC-050-EA2B	520738-24-01	SB	Enhanced performance and compatibility	--	Jan 16/89	0	A320	Eaton Bedhampton	K4413	--
520754	MGC-050-EA2C	520754-24-01	SB	Reduce operating temperature of transistor Q7	--	Aug 24/89	0	A320	Eaton Bedhampton	K4413	--
520800	PPEV3-008-EA3	520800-29-01	SB	Convert PPEV3-008-EA3 to PPEV3-008-EA3D	--	Aug 31/15	0	PILATUS PC12	Eaton Bedhampton	K4413	--
520805	MF3-032-EA3E	520805-27-01	SB	Change of valve plate material	--	Sep 19/94	0	A320	Eaton Bedhampton	K4413	--
520814	PPEV3-008-EA2A	520814-29-01	SB	Install a hydraulic hose in the pressure transducer port	--	Jul 10/01	0	PIAGGIO P180	Eaton Bedhampton	K4413	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
520814	PPEV3-008-EA2A	520814-29-02	SB	Change of valve plate casting process	--	May 13/02	0	PIAGGIO P180	Eaton Bedhampton	K4413	--
520814	PPEV3-008-EA2A	520814-29-03	SB	Change of mounting flange casting process	--	May 13/02	0	PIAGGIO P180	Eaton Bedhampton	K4413	--
520814	PPEV3-008-EA2A	520814-29-04	SB	Change of actuator piston	--	May 13/02	0	PIAGGIO P180	Eaton Bedhampton	K4413	--
520814	PPEV3-008-EA2A	520814-29-05	SB	Replacement of Electric Motor Field Housing	--	Jun 01/15	2	PIAGGIO P180	Eaton Bedhampton	K4413	--
520829	CMV3-022-EA4	520829-24-01	SB	Change of servo control valve	--	Feb 16/98	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
520829	CMV3-022-EA4	520829-24-02	SB	A better hydraulic motor shaft seal subassembly	--	Sep 21/00	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
520829	CMV3-022-EA4	520829-24-03	SB	To introduce a new CSM/G, Part Number 3022049-000 (Model CMV3-022-EA4B)	--	Feb 04/02	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
520850	CMV3-049-EA2	520850-24-02	SB	Change the HMG P/N 520850 (Model CMV3-049-EA2) to HMG P/N 3022008-000 (Model CMV3-049-EA5)	--	Jun 9/04	0	B757, GULFSTREAM V	Eaton Bedhampton	K4413	--
520854	MGC-EA3	520854-24-01	SB	Bus sense PEC subassembly transistor failure	--	Nov 16/98	0	GULFSTREAM V, B757	Eaton Bedhampton	K4413	--
520912	CMV3-022-EA3B	520568-24-01	SB	Increased qualification standard of diodes installed in drive shaft subassembly	--	Jul 31/89	1	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520912	CMV3-022-EA3B	520568-24-03	SB	Change of seep drain unions	--	Jul 22/92	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520912	CMV3-022-EA3B	520568-24-04	SB	Change of mounting flange, inserts and pins	--	Jan 06/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520912	CMV3-022-EA3B	520568-24-05	SB	Change of servo control valve	--	Jan 16/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520912	CMV3-022-EA3B	520568-24-06	SB	Change of housing, inserts and plug subassembly	--	Jan 16/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520912	CMV3-022-EA3B	520568-24-07	SB	Change of valve plate, bearing and pins subassembly	--	Jan 16/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520913	CMV3-022-EA3C	520913-24-01	SB	Remove bearing retaining ring and related components	--	Aug 29/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520913	CMV3-022-EA3C	520913-24-02	SB	Change of housing, inserts and plugs subassembly	--	Aug 29/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520913	CMV3-022-EA3C	520913-24-03	SB	Change of hold down plate retainer	--	Aug 29/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520913	CMV3-022-EA3C	520913-24-04	SB	Change of mounting flange, inserts and pins subassembly	--	Aug 29/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520913	CMV3-022-EA3C	520913-24-05	SB	A better hydraulic motor shaft seal subassembly	--	Oct 27/97	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520913	CMV3-022-EA3C	520913-24-06	SB	A better generator shaft seal subassembly	--	Feb 28/00	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
520913	CMV3-022-EA3C	520913-24-07	SB	To install a modified solenoid control valve	--	Aug 20/01	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520913	CMV3-022-EA3C	520913-24-08	SB	Introduction of Improved CSMG Generator Subassembly	--	Sep 12/19	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520913	CMV3-022-EA3C	520568-24-01	SB	Increased qualification standard of diodes installed in drive shaft subassembly	--	Jul 31/89	1	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520913	CMV3-022-EA3C	520568-24-03	SB	Change of seep drain unions	--	Jul 22/92	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520913	CMV3-022-EA3C	520568-24-04	SB	Change of mounting flange, inserts and pins	--	Jan 06/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520913	CMV3-022-EA3C	520568-24-05	SB	Change of servo control valve	--	Jan 16/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520913	CMV3-022-EA3C	520568-24-06	SB	Change of housing, inserts and plug subassembly	--	Jan 16/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520913	CMV3-022-EA3C	520568-24-07	SB	Change of valve plate, bearing and pins subassembly	--	Jan 16/96	0	A319, A320, A321, A340	Eaton Bedhampton	K4413	--
520915	MGC-050-EA2D	520915-24-01	SB	To do a test on power supply board subassembly diode D56 to find any electrical deterioration	--	Jul 21/94	0	A319, A320, A321, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
520915	MGC-050-EA2D	520915-24-02	SB	Circuit changes to make the GCU completely self-testable	--	Jan 10/96	0	A319, A320, A321, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
520915	MGC-050-EA2D	520915-24-03	SB	To introduce a new GCU	--	Jan 27/98	1	A319, A320, A321, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
521100	MGC-050-EA2E	521100-24-01	SB	Power Supply PEC Additional Resistor	--	June 18/08	0	A319, A320, A321, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
521100	MGC-050-EA2E	521100-24-02	SB	Strengthened Rear End Plate	--	June 18/08	0	A319, A320, A321, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
521100	MGC-050-EA2E	521100-24-03	SB	Power Supply Board Component Support	--	June 18/08	0	A319, A320, A321, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
521100	MGC-050-EA2E	521100-24-04	SB	PEC, Subassembly, Analogue, Speed Control with Discrete MOSFETs, PNR 520402 Revision F, Replaces PEC, Subassembly, Analogue, Speed	--	Jul 03/12	0	A319, A320, A321, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
521352	MGC-EA4A	521352-24-01	SB	Revised Procurement Specifications for Wound Components	--	Dec 22/14	0	SUPER PUMA	Eaton Bedhampton	K4413	--
521354	CMV3-022-EA5A	521354-49-01	SB	Remove bearing retaining ring and related components	--	Jul 26/99	1	SUPER PUMA	Eaton Bedhampton	K4413	--
521354	CMV3-022-EA5A	521354-49-02	SB	Change of hold down plate retainer	--	Jul 26/99	1	SUPER PUMA	Eaton Bedhampton	K4413	--
521354	CMV3-022-EA5A	521354-49-03	SB	Change of valve plate, bearing and pins subassembly	--	Jul 26/99	1	SUPER PUMA	Eaton Bedhampton	K4413	--
521354	CMV3-022-EA5A	521354-49-04	SB	Change of housing, inserts and plugs subassembly	--	Jul 26/99	1	SUPER PUMA	Eaton Bedhampton	K4413	--
521354	CMV3-022-EA5A	521354-49-05	SB	Change of mounting flange, inserts and pins subassembly	--	Jul 26/99	1	SUPER PUMA	Eaton Bedhampton	K4413	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
521354	CMV3-022-EA5A	521354-49-06	SB	A better hydraulic motor shaft seal subassembly	--	Jul 26/99	1	SUPER PUMA	Eaton Bedhampton	K4413	--
521424	MF3-075-EA1E	521424-27-01	SB	To decrease hydraulic motor cylinder block wear and stop manifold subassembly hydraulic leaks	--	Mar 30/94	0	A330, A340	Eaton Bedhampton	K4413	--
521424	MF3-075-EA1E	521424-27-02	SB	Stress corrosion cracking in the manifold	--	Jan 20/97	0	A330, A340	Eaton Bedhampton	K4413	--
521449	PV3-115-EA3C	521449-29-01	SB	Loose impeller screw	--	Oct 16/97	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
521449	PV3-115-EA3C	521449-29-02	SB	Change of impeller bush retaining pin	--	Jun 08/98	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
521449	PV3-115-EA3C	521449-29-03	SB	Change of actuator piston sleeve and actuator sleeve shim	--	Jun 08/98	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
521449	PV3-115-EA3C	521449-29-04	SB	Change of valve plate subassembly anodizing process	--	Apr 10/00	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
521449	PV3-115-EA3C	521449-29-05	SB	Re-Work the valve plate actuator piston sleeve hole	--	Apr 29/02	1	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
521449	PV3-115-EA3C	521449-29-06	SB	To add a second impeller bush retaining pin	--	Apr 29/02	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
521449	PV3-115-EA3C	521449-29-07	SB	Change of valve plate	--	Apr 29/02	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
521449	PV3-115-EA3C	521449-29-08	SB	Change of housing subassembly anodizing process	--	Apr 15/02	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
521449	PV3-115-EA3C	521449-29-09	SB	Re-Work the housing subassembly pintle bearing pads	--	Apr 15/02	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
521449	PV3-115-EA3C	521449-29-10	SB	Change of Shaft Seal Subassembly	--	Dec 08/08	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
521449	PV3-115-EA3C	521449-29-11	SB	Change of Actuator Piston Sleeve Seals	--	Dec 08/08	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
521449	PV3-115-EA3C	521449-29-12	SB	Introduction of revised Actuator Piston Sleeve and Shim configuration	--	Dec 08/08	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
715439	HR6B9-310-GB1A	715439-29-01	SB	Hardened end cap and spool subassembly	--	Mar 23/92	0	A300, A310	Eaton Bedhampton	K4413	--
715439	HR6B9-310-GB1A	715439-29-02	SB	A better face seal between the valve body and end cover	--	Feb 28/94	0	A300, A310	Eaton Bedhampton	K4413	--
715445	HR6B9-002-GB1A	715445-29-01	SB	Hardened sleeve and spool subassembly with additional back up rings	--	Mar 23/92	0	A300, A310, BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
715815	PV3-044-12AGB2	715815-29-01	SB	Fracture of valve plate attaching screws	--	Nov 12/96	0	HAWK, T45 GOSHAWK	Eaton Bedhampton	K4413	--
715815	PV3-044-12AGB2	715815-29-02	SB	Valve plate to housing joint face seal damaged	--	Nov 20/96	1	HAWK, T45 GOSHAWK	Eaton Bedhampton	K4413	--
715815	PV3-044-12AGB2	715815-29-03	SB	Change of valve plate and controls subassembly	--	Feb 22/99	0	HAWK, T45 GOSHAWK	Eaton Bedhampton	K4413	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
716853	MPHF1-037-UK2	716853-29-01	SB	Improved rear and intermediate main bearings	--	Jan 07/88	1	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
716853	MPHF1-037-UK2	716853-29-02	SB	Improved shaft seal subassembly	--	Apr 29/88	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
716853	MPHF1-037-UK2	716853-29-03	SB	Enhanced performance, reliability and compatibility	--	Aug 26/88	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
716853	MPHF1-037-UK2	716853-29-04	SB	Increased length of hydraulic motor attaching bolts	--	Aug 30/88	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
716884	HR6B9-002-UK2	716884-29-01	SB	Re-Seat condition high leakage rate	--	Feb 26/97	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
716946	MPHF1-037-UK4	716853-29-01	SB	Improved rear and intermediate main bearings	--	Jan 07/88	1	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
716946	MPHF1-037-UK4	716853-29-02	SB	Improved shaft seal subassembly	--	Apr 29/88	0	--	Eaton Bedhampton	K4413	--
716946	MPHF1-037-UK4	716853-29-03	SB	Enhanced performance, reliability and compatibility	--	Aug 26/88	0	--	Eaton Bedhampton	K4413	--
716946	MPHF1-037-UK4	716853-29-04	SB	Increased length of hydraulic motor attaching bolts	--	Aug 30/88	0	--	Eaton Bedhampton	K4413	--
716958	PV3-075-9UK2	716958-29-01	SB	Replacement of pre-production pressure attenuator with production standard pressure attenuator	--	Feb 6/85	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
716958	PV3-075-9UK2	716958-29-02	SB	New piston and shoe subassemblies	--	Jan 16/86	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
716958	PV3-075-9UK2	716958-29-03	SB	Improved shaft seal subassembly	--	Jan 16/86	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
716958	PV3-075-9UK2	716958-29-04	SB	Improved drive shaft bearing	--	Aug 14/87	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
716988	PV3-075-9UK2A	716958-29-02	SB	New piston and shoe subassemblies	--	Jan 16/86	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
716988	PV3-075-9UK2A	716958-29-03	SB	Improved shaft seal subassembly	--	Jan 16/86	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
716988	PV3-075-9UK2A	716958-29-04	SB	Improved drive shaft bearing	--	Aug 14/87	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
717091	PV3-075-9UK1A	716958-29-02	SB	New piston and shoe subassemblies	--	Jan 16/86	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
717091	PV3-075-9UK1A	716958-29-03	SB	Improved shaft seal subassembly	--	Jan 16/86	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
717091	PV3-075-9UK1A	716958-29-04	SB	Improved drive shaft bearing	--	Aug 14/87	0	BAE 146, RJ85, RJ100	Eaton Bedhampton	K4413	--
776876	HR6B9-002-GB2	776876-29-01	SB	Re-Seat condition high leakage rate	--	Apr 28/97	0	A300, A310	Eaton Bedhampton	K4413	--
848354	PV3-300-13C	848354-29-01	SB	Introduction of new model PV3-300-13E	--	Aug 01/95	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
848354	PV3-300-13C	848354-29-02	SB	Introduction of new model PV3-300-13F	--	Sep 01/95	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
848354	PV3-300-13C	848354-29-04	SB	Repair of yoke subassembly	--	Oct 30/98	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
848354	PV3-300-13C	848354-29-07	SB	Introduction of new model PV3-300-13K	--	Nov 14/02	6	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
848354	PV3-300-13C	848354-29-09	SB	Service flow limits	--	Oct 30/98	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
848354	PV3-300-13C	848354-29-15	SB	Carbon shaft seal improvement	--	Jun 1/00	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
848354	PV3-300-13C	848354-29-17	SB	Adaptor block repair	--	Jun 01/00	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
848354	PV3-300-13C	848354-29-22	SB	Change the retainer hold down plate screws	--	Nov 14/02	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
848354	PV3-300-13C	848354-29-25	SB	Change the coupling shaft and lubricating grease	--	Mar 17/03	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
849356	PPV3-011-2C	849356-29-01	SB	Add a spacer to the manifold subassembly attaching parts and examine the mounting flange for cracks	--	Dec 5/02	0	A129	Eaton Bedhampton	K4413	--
849356	PPV3-011-2C	849356-29-02	SB	To install a fire protection jacket, (Introduces P/N 3022081-000, Model PPV3-011-2D)	--	Mar 19/03	1	A129	Eaton Bedhampton	K4413	--
849356	PPV3-011-2C	849356-29-03	SB	Change the mounting flange	--	Jul 21/04	0	A129	Eaton Bedhampton	K4413	--
887099	PPV3-011-2B	887099-29-01	SB	Add a spacer to the manifold subassembly attaching parts and examine the mounting flange for cracks	--	Dec 12/02	0	A-129	Eaton Bedhampton	K4413	--
920395	MGC-EA1B	920395-24-01	SB	To increase the high phase take over voltage value	--	Mar 23/94	0	A340-500, A340-600	Eaton Bedhampton	K4413	--
920422	PPEV3-008-EA3A	920422-29-01	SB	Shaft Seal seep drain and fluid collector bottle added	--	Jul 14/00	1	PILATUS PC12	Eaton Bedhampton	K4413	--
920422	PPEV3-008-EA3A	920422-29-02	SB	Change of differential pressure indicator (DPI) and filter by-pass valve	--	Jul 25/97	0	PILATUS PC12	Eaton Bedhampton	K4413	--
920422	PPEV3-008-EA3A	920422-29-03	SB	Install a locating pin in the adaptor subassembly	--	Jun 26/98	1	PILATUS PC12	Eaton Bedhampton	K4413	--
920422	PPEV3-008-EA3A	920422-29-04	SB	Optional valve plate	--	Apr 15/99	0	PILATUS PC12	Eaton Bedhampton	K4413	--
920422	PPEV3-008-EA3A	920422-29-05	SB	Introduction of Model PPEV3-008-EA3D	--	Jul 22/13	0	PILATUS PC12	Eaton Bedhampton	K4413	--
920449	MF3-075-EA1F	920449-27-01	SB	Stress corrosion cracking in the manifold	--	Jul 30/96	1	A330, A340	Eaton Bedhampton	K4413	--
928005	MGC-EA1C	928005-24-A01	SB	Broken RFI filter washers	--	Oct 30/95	0	A340-500, A340-600	Eaton Bedhampton	K4413	--
928005	MGC-EA1C	928005-24-01	SB	Optional components and component value changes on the power supply PEC subassembly	--	Jul 07/99	0	A340-500, A340-600	Eaton Bedhampton	K4413	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
928078	CMV3-049-EA3	928078-24-01	SB	To change the HVG Part Number 928078 (Model CMV3-049-EA3) to HMG Part Number 3022018-000 (Model CMV3-049-EA3)	--	Mar 3/04	0	GULFSTREAM V	Eaton Bedhampton	K4413	--
928078	CMV3-049-EA3	928078-24-02	SB	Improved Sealing Modification	--	Oct 10/06	0	GULFSTREAM V	Eaton Bedhampton	K4413	--
928099	PPV3-056-2D	928099-29-01	SB	Incorrect pilot valve spool land dimension	--	Jun 17/96	5	EH101 101	Eaton Bedhampton	K4413	--
928099	PPV3-056-2D	928099-29-02	SB	Measurement of the housing casting wall thickness	--	Apr 03/98	0	EH101 101	Eaton Bedhampton	K4413	--
928099	PPV3-056-2D	928099-29-03	SB	Defective cylinder block	--	Apr 12/00	0	EH101 101	Eaton Bedhampton	K4413	--
928178	RRS-190-1A	928178-29-01	SB	Change of diaphragm and piston	--	Dec 15/98	0	EH101 MERLIN	Eaton Bedhampton	K4413	--
928178	RRS-190-1A	928178-29-02	SB	Change of reservoir guide spacer and reservoir guide post	--	Jul 31/00	0	EH101 MERLIN	Eaton Bedhampton	K4413	--
928178	RRS-190-1A	928178-29-03	SB	A Change Of Spring To Decrease The Weight Of The Reservoir Assembly	--	Jun 30/03	0	EH101 MERLIN	Eaton Bedhampton	K4413	--
928179	RRS-500-EA1	928179-29-01	SB	Change of diaphragm and piston	--	Dec 15/00	0	EH101 MERLIN	Eaton Bedhampton	K4413	--
928179	RRS-500-EA1	928179-29-02	SB	Change of reservoir guide spacer and reservoir guide post	--	Apr 02/03	0	EH101 MERLIN	Eaton Bedhampton	K4413	--
933260	PV3-115-EA1D	933260-29-01	SB	Defective mounting flange yoke bearing lugs	--	Sep 15/99	0	A319, A320, A321	Eaton Bedhampton	K4413	--
933322	PPEV3-008-EA3B	933322-29-01	SB	Change of differential pressure indicator (DPI) and filter by-pass valve	--	Sep 23/97	0	PILATUS PC12	Eaton Bedhampton	K4413	--
933322	PPEV3-008-EA3B	933322-29-02	SB	Install a locating pin in the adaptor subassembly	--	Jun 26/98	1	PILATUS PC12	Eaton Bedhampton	K4413	--
933322	PPEV3-008-EA3B	933322-29-03	SB	Optional valve plate	--	Apr 15/99	0	PILATUS PC12	Eaton Bedhampton	K4413	--
933322	PPEV3-008-EA3B	933322-29-04	SB	Optional mounting flange	--	Apr 15/99	0	PILATUS PC12	Eaton Bedhampton	K4413	--
933322	PPEV3-008-EA3B	933322-29-05	SB	Introduction of Model PPEV3-008-EA3D	--	Aug 30/13	0	PILATUS PC12	Eaton Bedhampton	K4413	--
933340	PPEV3-008-EA3C	920422-29-02	SB	Change of differential pressure indicator (DPI) and filter by-pass valve	--	Jul 25/97	0	PILATUS PC12	Eaton Bedhampton	K4413	--
933340	PPEV3-008-EA3C	920422-29-04	SB	Install a locating pin in the adaptor subassembly	--	Jun 26/99	2	PILATUS PC12	Eaton Bedhampton	K4413	--
933340	PPEV3-008-EA3C	920422-29-04	SB	Optional valve plate	--	Apr 15/99	0	PILATUS PC12	Eaton Bedhampton	K4413	--
933392	PPV3-056-2E	933392-29-01	SB	Measurement of the housing casting wall thickness	--	Apr 06/98	0	EH101 MERLIN	Eaton Bedhampton	K4413	--
933392	PPV3-056-2E	933392-29-02	SB	Remove the auxiliary reservoir port locking wire lug	--	May 13/99	0	EH101 MERLIN	Eaton Bedhampton	K4413	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
933392	PPV3-056-2E	933392-29-03	SB	To introduce variable displacement pump package assembly, P/N 3022024-000 (Model PPV3-056-2F)	--	Oct 7/99	1	EH101 MERLIN	Eaton Bedhampton	K4413	--
933392	PPV3-056-2E	933392-29-04	SB	Change of blocking valve seal and filter screen	--	Mar 29/00	0	EH101 MERLIN	Eaton Bedhampton	K4413	--
933392	PPV3-056-2E	933392-29-05	SB	Optional solenoid valve	--	Mar 29/00	0	EH101 MERLIN	Eaton Bedhampton	K4413	--
933392	PPV3-056-2E	933392-29-06	SB	Change of housing, inserts and pins subassembly	--	Mar 29/00	0	EH101 MERLIN	Eaton Bedhampton	K4413	--
933392	PPV3-056-2E	933392-29-07	SB	Defective cylinder block	--	Apr 12/00	0	EH101 MERLIN	Eaton Bedhampton	K4413	--
933578	PPEV3-008-EA3D	933578-29-01	SB	Optional Mounting Flange and Inserts Subassembly	--	Aug 30/13	0	PILATUS PC12	Eaton Bedhampton	K4413	--
933578	PPEV3-008-EA3D	933578-29-02	SB	Modification to Rotate the Differential Pressure Indicator by 90 Degrees	--	Aug 30/13	0	PILATUS PC12	Eaton Bedhampton	K4413	--
971844	PV3-300-13E	848354-29-04	SB	Repair of yoke subassembly	--	Oct 30/98	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
971844	PV3-300-13E	848354-29-06	SB	Introduction of new model PV3-300-13H	--	Apr 30/98	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
971844	PV3-300-13E	848354-29-07	SB	Introduction of new model PV3-300-13K	--	Nov 14/02	6	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
971844	PV3-300-13E	848354-29-09	SB	Service flow limits	--	Oct 30/98	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
971844	PV3-300-13E	848354-29-10	SB	Removal of the filter screen	--	Jun 01/00	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
971844	PV3-300-13E	848354-29-15	SB	Carbon shaft seal improvement	--	Jun 1/00	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
971844	PV3-300-13E	848354-29-17	SB	Adaptor block repair	--	Jun 01/00	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
971844	PV3-300-13E	848354-29-22	SB	Change the retainer hold down plate screws	--	Nov 14/02	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
971844	PV3-300-13E	848354-29-25	SB	Change the coupling shaft and lubricating grease	--	Mar 17/03	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
972630	PV3-300-13F	848354-29-04	SB	Repair of yoke subassembly	--	Oct 30/98	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
972630	PV3-300-13F	848354-29-06	SB	Introduction of new model PV3-300-13H	--	Apr 30/98	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
972630	PV3-300-13F	848354-29-07	SB	Introduction of new model PV3-300-13K	--	Nov 14/02	6	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
972630	PV3-300-13F	848354-29-09	SB	Service flow limits	--	Oct 30/98	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
972630	PV3-300-13F	848354-29-10	SB	Removal of the filter screen	--	Jun 01/00	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
972630	PV3-300-13F	848354-29-15	SB	Carbon shaft seal improvement	--	Jun 1/00	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
972630	PV3-300-13F	848354-29-16	SB	Blocking valve piston and seat improvement	--	Oct 01/00	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
972630	PV3-300-13F	848354-29-17	SB	Adaptor block repair	--	Jun 01/00	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
972630	PV3-300-13F	848354-29-19	SB	New blocking valve seat and seals	--	Jun 1/00	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
972630	PV3-300-13F	848354-29-22	SB	Change the retainer hold down plate screws	--	Nov 14/02	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
972630	PV3-300-13F	848354-29-24	SB	Inspection and rework of the housing and insert subassembly	--	Oct 28/02	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
972630	PV3-300-13F	848354-29-25	SB	Change the coupling shaft and lubricating grease	--	Mar 17/03	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
972630	PV3-300-13F	848354-29-26	SB	Change the mounting flange subassembly	--	Feb 10/03	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974540	MPEV3-032-15	974540-29-01	SB	Product Improvement - Screw change	--	Jan 15/02	0	A319, A320, A321, A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974540	MPEV3-032-15	974540-29-02	SB	Recall - FOC change of electric motor tail bearing - Barden manufacturer	--	Jun 17/02	0	A319, A320, A321, A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974540	MPEV3-032-15	974540-29-03	SB	Drive shaft contamination - Return of specified units	--	Jun 02/04	1	A319, A320, A321, A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974540	MPEV3-032-15	974540-29-04	SB	Elimination of External Leakage	--	Sept 01/07	0	A319, A320, A321, A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974540	MPEV3-032-15	974540-29-05	SB	Replacement of Lock Washer	--	Sept 01/07	0	A319, A320, A321, A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974540	MPEV3-032-15	974540-29-06	SB	Inspection and Replacement of Pressure Compensator Sleeve	--	Oct 28/10	1	A319, A320, A321, A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974540	MPEV3-032-15	974540-29-07	SB	Introduction of Reduced Diameter Small Control Piston and Shorter Large Control Piston	--	May 25/12	0	A319, A320, A321, A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974540	MPEV3-032-15	974540-29-08	SB	Introduction of New Cooling Fan	Mar 15/17	--	0	A319, A320, A321, A330, A340, A340-500, A340-601	Eaton Bedhampton	K4413	--
974800	PV3-300-13L	848354-29-09	SB	Service flow limits	--	Oct 30/98	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974800	PV3-300-13L	848354-29-11	SB	Reduce parting line leakage	--	Jun 01/00	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974800	PV3-300-13L	848354-29-12	SB	Lapping of blocking valve seat	--	Feb 19/01	2	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974800	PV3-300-13L	848354-29-14	SB	Blocking valve improvement	--	Jun 01/00	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974800	PV3-300-13L	848354-29-15	SB	Carbon shaft seal improvement	--	Jun 1/00	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
974800	PV3-300-13L	848354-29-18	SB	Inspection of the valve block orifice set screw	--	Dec 15/00	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974800	PV3-300-13L	848354-29-19	SB	New blocking valve seat and seals	--	Jun 1/00	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974800	PV3-300-13L	848354-29-20	SB	Change of the valve block subassembly	--	Jan 25/01	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974800	PV3-300-13L	974800-29-01	SB	Change the blocking valve seat	--	Jul 03/02	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974800	PV3-300-13L	974800-29-02	SB	Change the retainer hold down plate screws	--	Aug 20/02	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974800	PV3-300-13L	974800-29-03	SB	Inspection and rework of the housing and insert subassembly	--	Oct 28/02	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974800	PV3-300-13L	974800-29-04	SB	Change the coupling shaft and lubricating grease	--	Mar 17/03	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974800	PV3-300-13L	974800-29-05	SB	Change the mounting flange subassembly	--	Mar 12/03	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974800	PV3-300-13L	974800-29-06	SB	Improved Solenoid Valve	--	May 19/10	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974947	PV3-300-13H	848354-29-07	SB	Introduction of new model PV3-300-13K	--	Nov 14/02	6	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974947	PV3-300-13H	848354-29-09	SB	Service flow limits	--	Oct 30/98	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974947	PV3-300-13H	848354-29-10	SB	Removal of the filter screen	--	Jun 01/00	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974947	PV3-300-13H	848354-29-15	SB	Carbon shaft seal improvement	--	Jun 1/00	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974947	PV3-300-13H	848354-29-16	SB	Blocking valve piston and seat improvement	--	Oct 01/00	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974947	PV3-300-13H	848354-29-17	SB	Adaptor block repair	--	Jun 01/00	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974947	PV3-300-13H	848354-29-19	SB	New blocking valve seat and seals	--	Jun 1/00	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974947	PV3-300-13H	848354-29-22	SB	Change the retainer hold down plate screws	--	Nov 14/02	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974947	PV3-300-13H	848354-29-24	SB	Inspection and rework of the housing and insert subassembly	--	Oct 28/02	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974947	PV3-300-13H	848354-29-25	SB	Change the coupling shaft and lubricating grease	--	Mar 17/03	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974947	PV3-300-13H	848354-29-26	SB	Change the mounting flange subassembly	--	Feb 10/03	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974976	PV3-300-13K	848354-29-08	SB	Introduction of new model PV3-300-13L	--	Jan 08/00	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
974976	PV3-300-13K	848354-29-09	SB	Service flow limits	--	Oct 30/98	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974976	PV3-300-13K	848354-29-10	SB	Removal of the filter screen	--	Jun 01/00	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974976	PV3-300-13K	848354-29-12	SB	Lapping of blocking valve seat	--	Feb 19/01	2	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974976	PV3-300-13K	848354-29-13	SB	Replacement of blocking valve seat, blocking valve seat seal, blocking valve piston, blocking valve piston seal and blocking valve springs	--	Jun 01/00	2	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974976	PV3-300-13K	848354-29-15	SB	Carbon shaft seal improvement	--	Jun 1/00	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974976	PV3-300-13K	848354-29-17	SB	Adaptor block repair	--	Jun 01/00	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974976	PV3-300-13K	848354-29-18	SB	Inspection of the valve block orifice set screw	--	Dec 15/00	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974976	PV3-300-13K	848354-29-19	SB	New blocking valve seat and seals	--	Jun 1/00	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974976	PV3-300-13K	848354-29-20	SB	Change of the valve block subassembly	--	Jan 25/01	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974976	PV3-300-13K	848354-29-21	SB	Change the blocking valve seat	--	Jul 03/02	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974976	PV3-300-13K	848354-29-22	SB	Change the retainer hold down plate screws	--	Nov 14/02	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974976	PV3-300-13K	848354-29-23	SB	Change the yoke, ball, insert and pin subassembly	--	Jul 03/02	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974976	PV3-300-13K	848354-29-24	SB	Inspection and rework of the housing and insert subassembly	--	Oct 28/02	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974976	PV3-300-13K	848354-29-25	SB	Change the coupling shaft and lubricating grease	--	Mar 17/03	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974976	PV3-300-13K	848354-29-26	SB	Change the mounting flange subassembly	--	Feb 10/03	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974976	PV3-300-13K	848354-29-27	SB	Improved Solenoid Valve	--	May 19/10	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
974976	PV3-300-13K	848354-29-28	SB	Improved Orifice Body	--	Sept 21/07	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
3022018-000	CMV3-049-EA6	3022018-000-24-01	SB	Rear Shaft Seal Modification	--	Jun 15/06	0	GULFSTREAM V	Eaton Bedhampton	K4413	--
3022018-000	CMV3-049-EA6	3022018-000-24-02	SB	Improved Sealing Modification	--	Jun 15/06	0	GULFSTREAM V	Eaton Bedhampton	K4413	--
3022024-000	PPV3-056-2F	3022024-000-29-01	SB	Change of blocking valve seal and filter screen	--	Mar 11/00	0	EH101 MERLIN	Eaton Bedhampton	K4413	--
3022024-000	PPV3-056-2F	3022024-000-29-02	SB	Optional solenoid valve	--	Mar 11/00	0	EH101 MERLIN	Eaton Bedhampton	K4413	--

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3022024-000	PPV3-056-2F	3022024-000-29-03	SB	Change of housing, inserts and pins subassembly	--	Mar 11/00	0	EH101 MERLIN	Eaton Bedhampton	K4413	--
3022024-000	PPV3-056-2F	3022024-000-29-04	SB	Defective cylinder block	--	Apr 12/00	0	EH101 MERLIN	Eaton Bedhampton	K4413	--
3022024-000	PPV3-056-2F	3022024-000-29-05	SB	Possible incorrect installation of the bearing on the drive shaft subassembly	--	May 15/00	0	EH101 MERLIN	Eaton Bedhampton	K4413	--
3022024-000	PPV3-056-2F	3022024-000-29-06	SB	Possible incorrect installation of the bearing on the drive shaft subassembly	--	Oct 16/01	1	EH101 MERLIN	Eaton Bedhampton	K4413	--
3022024-000	PPV3-056-2F	3022024-000-29-07	SB	Change of Boost Impeller and Impeller Shaft	--	May 25/12	1	EH101 MERLIN	Eaton Bedhampton	K4413	--
3022024-000	PPV3-056-2F	3022024-000-29-08	SB	Change of Indicator Rod Material	--	July 02/08	0	EH101 MERLIN	Eaton Bedhampton	K4413	--
3022053-000	PV3-300-EA2	3022053-000-29-01	SB	Inspection of Adaptor Block	--	Sept 13/07	1	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
3022053-000	PV3-300-EA2	3022053-000-29-02	SB	Improved Mounting Flange Seal	--	Sept 18/07	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
3022053-000	PV3-300-EA2	3022053-000-29-03	SB	Improved Solenoid Valve	--	Sept 11/07	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
3022053-000	PV3-300-EA2	3022053-000-29-04	SB	To prevent Pressure Compensator Seal Failure/Low Hydraulic System Pressure	--	Oct 09/07	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
3022053-000	PV3-300-EA2	3022053-000-29-05	SB	Introduction of PV3-300-EA2A	--	Sept 18/07	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
3022053-001	PV3-300-EA2A	3022053-001-29-01	SB	Modification of EDP Type PV3-300-EA2A to PV3-300-EA4 (New Outlet Fitting)	--	Jan 02/18	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
3022053-001	PV3-300-EA2A	3022053-001-29-02	SB	Replacement of Bearing clip	--	Feb 02/18	0	A330, A340, A340-500, A340-600	Eaton Bedhampton	K4413	--
3022071-006	MPEV3-035-EA1F	3022071-006-29-01	SB	Replacement of Lifer Component	--	Mar 25/08	0	A380	Eaton Bedhampton	K4413	--
3022071-007	MPEV3-035-EA1G	3022071-007-29-01	SB	Change the Cover Plate Subassembly and Valve Plate	--	Feb 15/12	0	A380	Eaton Bedhampton	K4413	--
3022071-008	MPEV3-035-EA1H	3022071-008-29-01	SB	Improvement of Cylinder Block	--	Apr 26/13	0	A380	Eaton Bedhampton	K4413	--
3022071-009	MPEV3-035-EA1J	3022071-009-29-01	SB	Product Improved Speed Sensor Subassembly & Introduction of MPEV3-035-EA1K	--	Jun 10/15	0	A380	Eaton Bedhampton	K4413	--
3022078-001	RMV3-075-EA1A	3022078-001-27-01	SB	Resolver Spool & Hub Improvement	--	Dec 14/12	0	A380	Eaton Bedhampton	K4413	--
3022078-001	RMV3-075-EA1A	3022078-001-27-02	SB	Improved Servo Valve	--	Jul 15/14	0	A380	Eaton Bedhampton	K4413	--
3022078-001	RMV3-075-EA1A	3022078-001-27-03	SB	Improved actuator piston and introduction of RMV3-075-EA1B	--	Mar 09/20	0	A380	Eaton Bedhampton	K4413	--
3022081-000	PPV3-011-2D	3022081-000-29-01	SB	Add a spacer to the manifold subassembly attaching parts and examine the mounting flange for cracks	--	Dec 12/02	0	A129	Eaton Bedhampton	K4413	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3022081-000	PPV3-011-2D	3022081-000-29-02	SB	Change the mounting flange	--	Jul 21/04	0	A129	Eaton Bedhampton	K4413	--
3022081-000	PPV3-011-2D	3022081-000-29-03	SB	Change of Reservoir Relief Valve	--	Jun 03/10	0	A129	Eaton Bedhampton	K4413	--
3022081-000	PPV3-011-2D	3022081-000-29-04	SB	Manifold & EDV Piston Matching	--	Jun 23/14	1	A129	Eaton Bedhampton	K4413	--
3022081-000	PPV3-011-2D	3022081-000-29-05	SB	Solenoid Valve Retroft	--	Aug 14/14	0	A129	Eaton Bedhampton	K4413	--
3022143-000	MPEV3-032-EA3	3022143-000-29-01	SB	Introduction of New Cooling Fan	--	Jan 09/18	0	A320 NEO	Eaton Bedhampton	K4413	--
3032374-001	PV3-300-31J	3032374-001-29-01	SB	Improved Lift Limiter Design	--	Aug 07/09	0	A380	Eaton Bedhampton	K4413	--
3032782-000	PV3-300-31K	3032782-000-29-01	SB	Introduction of new Shaft Seal Subassembly and Model PV3-300-31L	--	Sept 28/10	1	A380	Eaton Bedhampton	K4413	--
3032793-000	PV3-300-31L	3032793-000-29-01	SB	Introduction of Improved EDV Solenoid Valve Assembly and Model PV3-300-31M	--	Oct 01/10	0	A380	Eaton Bedhampton	K4413	--
3032793-001	PV3-300-31M	3032793-001-29-01	SB	Introduction of an Alternative Blocking Valve Piston	--	Feb 25/12	0	A380	Eaton Bedhampton	K4413	--
3032793-001	PV3-300-31M	3032793-001-29-02	SB	Introduction of Model PV3-300-31N	--	Apr 06/12	0	A380	Eaton Bedhampton	K4413	--
3032793-002	PV3-300-31N	3032793-002-29-01	SB	Improvement of Clutch Solenoid	--	Jun 24/13	0	A380	Eaton Bedhampton	K4413	--
3032793-002	PV3-300-31N	3032793-002-29-02	SB	Improvement of Attenuator	--	Apr 25/16	0	A380	Eaton Bedhampton	K4413	--
3032793-002	PV3-300-31N	3032793-002-29-03	SB	Introduction of Thermal Barrier & PV3-300-31P	--	Nov 10/16	1	A380	Eaton Bedhampton	K4413	--
3032793-002	PV3-300-31N	3032793-002-29-04	SB	Introduction of Improved Shaft Seal and Model PV3-300-31R	--	Oct 16/17	0	A380	Eaton Bedhampton	K4413	--
3032793-003	PV3-300-31P	3032793-003-29-01	SB	Introduction of Improved Shaft Seal and Model PV3-300-31T	--	Dec 19/17	0	A380	Eaton Bedhampton	K4413	--
3037293-004	PV3-300-31R	29-10-60	CMM	Variable Displacement Hydraulic Pump	--	Mar 20/18	9	A380	Eaton Bedhampton	K4413	--
3037293-005	PV3-300-31T	29-10-60	CMM	Variable Displacement Hydraulic Pump	--	Mar 20/18	9	A380	Eaton Bedhampton	K4413	--
Various	Various	K4413-29-03	SIL	Vendor Service Information Letter - Shaft Seal Grommet - Material Composition	Dec 01/21	--	0	AIRBUS A319/A320/A380/A330/340 Boeing 737/757/777 Embraer E2 E175	Eaton Bedhampton	K4413	--
--	--	71-00-50	CMM	Component Maintenance Manual With Illustrated Parts List	--	July 31/2013	3	T900	Beltsville, Tijuana	15284	--
211C117-185	--	36-11-01	ACMM	--	--	28-Feb-91	0	747	Eaton Bethel	02750	--
211C117-222	--	36-20-03	ACMM	--	--	31-Jan-97	1	747	Eaton Bethel	02750	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
211C117-223	--	36-20-03	ACMM	--	--	31-Jan-97	1	747	Eaton Bethel	02750	--
211C117-245	--	36-20-05	ACMM	--	--	15-Jul-92	1	747	Eaton Bethel	02750	--
211C223-149	--	29-32-01	CMM	--	--	01-Jul-83	5	--	Eaton Bethel	02750	--
211C223-150	--	29-32-01	CMM	--	--	01-Jul-83	5	--	Eaton Bethel	02750	--
211C223-175	--	29-09-01	CMM	--	--	22-Aug-06	3	747	Eaton Bethel	02750	--
211C223-176	--	29-09-01	CMM	--	--	22-Aug-06	3	747	Eaton Bethel	02750	--
211C223-177	--	29-09-01	CMM	--	--	22-Aug-06	3	747	Eaton Bethel	02750	--
211C223-178	--	29-09-01	CMM	--	--	22-Aug-06	3	747	Eaton Bethel	02750	--
211C223-182	--	29-32-01	CMM	--	--	01-Jul-83	5	--	Eaton Bethel	02750	Active Service Bulletins 211C223-182-27-1
211C223-182A	--	29-32-01	CMM	--	--	01-Jul-83	5	--	Eaton Bethel	02750	--
211C223-183	--	29-32-01	CMM	--	--	01-Jul-83	5	--	Eaton Bethel	02750	--
211C223-184	--	29-32-01	CMM	--	--	01-Jul-83	5	--	Eaton Bethel	02750	--
211C223-199	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-200	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-203	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-208	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-209	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-211	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-212	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-214	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-216	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
211C223-252	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-253	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-275	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-278	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-296	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-297	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-301	--	29-09-01	CMM	--	--	22-Aug-06	3	747	Eaton Bethel	02750	--
211C223-312	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-319	--	29-09-01	CMM	--	--	22-Aug-06	3	747	Eaton Bethel	02750	--
211C223-320	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-321	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-322	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-323	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-324	--	29-09-02	CMM	--	--	01-Jul-87	4	--	Eaton Bethel	02750	--
211C223-326	--	29-09-03	CMM	--	--	01-Jul-87	0	--	Eaton Bethel	02750	--
211C223-327	--	29-09-03	CMM	--	--	01-Jul-87	0	--	Eaton Bethel	02750	--
211C223-343	--	36-20-04	ACMM	--	--	30-Jun-92	1	747	Eaton Bethel	02750	--
211C223-461A	--	29-34-01	ACMM	--	--	28-Feb-94	0	--	Eaton Bethel	02750	--
211C223-516	--	29-09-04	CMM	--	--	30-Dec-16	5	747	Eaton Bethel	02750	Active Service Bulletins 29-09-04-02
211C223-517	--	29-09-05	CMM	--	--	30-Dec-16	6	--	Eaton Bethel	02750	Active Service Bulletins 29-09-05-02
211C223-518	--	29-09-05	CMM	--	--	30-Dec-16	6	--	Eaton Bethel	02750	Active Service Bulletins 29-09-05-02

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
211C223-519	--	29-09-05	CMM	--	--	30-Dec-16	6	--	Eaton Bethel	02750	Active Service Bulletins 29-09-05-02
211C223-520	--	29-09-05	CMM	--	--	30-Dec-16	6	--	Eaton Bethel	02750	Active Service Bulletins 29-09-05-02
211C223-521	--	29-09-05	CMM	--	--	30-Dec-16	6	--	Eaton Bethel	02750	Active Service Bulletins 29-09-05-02
211C223-522	--	29-09-05	CMM	--	--	30-Dec-16	6	--	Eaton Bethel	02750	Active Service Bulletins 29-09-05-02
211C223-523	--	29-09-05	CMM	--	--	30-Dec-16	6	--	Eaton Bethel	02750	Active Service Bulletins 29-09-05-02
211C223-524	--	29-09-05	CMM	--	--	30-Dec-16	6	--	Eaton Bethel	02750	Active Service Bulletins 29-09-05-02
211C223-525	--	29-09-06	CMM	--	--	30-Dec-16	5	747	Eaton Bethel	02750	Active Service Bulletins 29-09-06-02
211C223-526	--	29-09-05	CMM	--	--	30-Dec-16	6	--	Eaton Bethel	02750	Active Service Bulletins 29-09-05-02
211C223-527	--	29-09-05	CMM	--	--	30-Dec-16	6	--	Eaton Bethel	02750	Active Service Bulletins 29-09-05-02
211C223-528	--	29-09-06	CMM	--	--	30-Dec-16	5	747	Eaton Bethel	02750	Active Service Bulletins 29-09-06-02
211C223-529	--	29-09-08	ACMM	--	--	15-Jul-12	1	747	Eaton Bethel	02750	--
211C223-534	--	29-09-04	CMM	--	--	30-Dec-16	5	747	Eaton Bethel	02750	Active Service Bulletins 29-09-04-02
211C223-535	--	29-09-07	CMM	--	--	30-Dec-16	6	--	Eaton Bethel	02750	Active Service Bulletins 29-09-07-02
211C223-659	--	29-09-06	CMM	--	--	30-Dec-16	5	747	Eaton Bethel	02750	--
211C223-69	--	29-32-01	CMM	--	--	01-Jul-83	5	--	Eaton Bethel	02750	--
211C223-B43	--	29-32-01	CMM	--	--	01-Jul-83	5	--	Eaton Bethel	02750	--
212C139-1	--	29-17-01	ACMM	--	--	31-Jan-94	1	747	Eaton Bethel	02750	--
212C139-3	--	29-17-01	ACMM	--	--	31-Jan-94	1	747	Eaton Bethel	02750	--
213C50-5	--	21-26-01	CMM	--	--	01-Mar-93	1	747	Eaton Bethel	02750	--
214C40-1-113	--	34-16-01	ACMM	--	--	28-Feb-91	0	--	Eaton Bethel	02750	--
214C40-1-115	--	34-11-01	ACMM	--	--	SEPT 15/14	1	747	Eaton Bethel	02750	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
214C40-1-122	--	34-16-01	ACMM	--	--	28-Feb-91	0	--	Eaton Bethel	02750	--
214C40-1-71	--	34-11-01	ACMM	--	--	SEPT 15/14	1	747	Eaton Bethel	02750	--
214C40-1-75	--	34-11-01	ACMM	--	--	SEPT 15/14	1	747	Eaton Bethel	02750	--
214C40-1-77	--	34-11-01	ACMM	--	--	SEPT 15/14	1	747	Eaton Bethel	02750	--
214C40-1-83	--	214C40-1-83-3	SB	--	--	22-Oct-02	1	--	Eaton Bethel	02750	Active Service Bulletins 214C40-1-83-35-1 R1
214C50-2	--	31-26-01	CMM	--	--	04-Nov-08	4	747	Eaton Bethel	02750	--
214C50-68	--	31-26-01	CMM	--	--	04-Nov-08	4	747	Eaton Bethel	02750	--
21C1-1-16B	--	79-34-11	ACMM	--	--	31-Jul-95	1	--	Eaton Bethel	02750	--
21C1-1-22	--	79-33-28	ACMM	--	--	30-Jun-93	0	--	Eaton Bethel	02750	--
21C1-3-21	--	28-42-01	ACMM	--	--	03-Jan-18	3	747	Eaton Bethel	02750	Active Service Bulletins 28-42-01-02
21C1-3-21-1	--	28-42-05	CMM	--	--	30-Jan-16	0	--	Eaton Bethel	02750	Active Service Bulletins 28-42-05-01
21C1-3-22	--	28-42-01	ACMM	--	--	03-Jan-18	3	747	Eaton Bethel	02750	Active Service Bulletins 28-42-01-02
21C1-3-22-1	--	28-42-05	CMM	--	--	30-Jan-16	0	--	Eaton Bethel	02750	Active Service Bulletins 28-43-05-01
21C1-5-17A	--	79-34-16	ACMM	--	--	17-Oct-06	1	--	Eaton Bethel	02750	--
21C1-5-30	--	30-21-01	CMM	--	--	15-May-15	0	--	Eaton Bethel	02750	--
21C1-6-7	--	28-42-02	ACMM	--	--	15-Jun-96	1	--	Eaton Bethel	02750	Active Service Bulletins 28-42-02-01
21C1-6-7-1	--	28-42-05	CMM	--	--	30-Jan-16	0	--	Eaton Bethel	02750	Active Service Bulletins 28-42-05-02
21SN04-104A	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-104B	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-104D	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-104E	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
21SN04-104F	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	--
21SN04-121	--	79-09-01	CMM	--	--	01-Jul-87	4	747	Eaton Bethel	02750	--
21SN04-123	--	79-33-01	CMM	--	--	15-Jul-78	3	747	Eaton Bethel	02750	--
21SN04-124	--	79-33-01	CMM	--	--	15-Jul-78	3	747	Eaton Bethel	02750	--
21SN04-132	--	28-44-02	CMM	--	--	01-Jul-75	0	--	Eaton Bethel	02750	--
21SN04-132-1	--	28-44-02	CMM	--	--	01-Jul-75	0	--	Eaton Bethel	02750	Active Service Bulletins 28-44-02-1
21SN04-132-2	--	28-44-02	CMM	--	--	01-Jul-75	0	--	Eaton Bethel	02750	--
21SN04-148	--	79-33-01	CMM	--	--	15-Jul-78	3	747	Eaton Bethel	02750	--
21SN04-149	--	79-33-01	CMM	--	--	15-Jul-78	3	747	Eaton Bethel	02750	--
21SN04-158A	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-158B	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-158C	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	--
21SN04-158D	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	--
21SN04-159	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-159A	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-159B	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-159C	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	--
21SN04-159D	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	--
21SN04-180	--	79-09-03	CMM	--	--	15-Jun-92	4	--	Eaton Bethel	02750	Active Service Bulletins 21SN04-180-73-1
21SN04-180A	--	79-09-03	CMM	--	--	15-Jun-92	4	--	Eaton Bethel	02750	Active Service Bulletins 21SN04-180-73-1
21SN04-183	--	79-09-04	CMM	--	--	30-Sep-94	5	--	Eaton Bethel	02750	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
21SN04-183A	--	79-09-04	CMM	--	--	30-Sep-94	5	--	Eaton Bethel	02750	Active Service Bulletins 21SN04-183-79-1
21SN04-19A	--	79-33-01	CMM	--	--	15-Jul-78	3	747	Eaton Bethel	02750	--
21SN04-19B	--	79-33-01	CMM	--	--	15-Jul-78	3	747	Eaton Bethel	02750	--
21SN04-209	--	79-09-03	CMM	--	--	15-Jun-92	4	--	Eaton Bethel	02750	Active Service Bulletins 79-09-03-1
21SN04-209A	--	79-09-03	CMM	--	--	15-Jun-92	4	--	Eaton Bethel	02750	Active Service Bulletins 79-09-03-2
21SN04-20A	--	79-33-01	CMM	--	--	15-Jul-78	3	747	Eaton Bethel	02750	--
21SN04-211	--	79-09-04	CMM	--	--	30-Sep-94	5	--	Eaton Bethel	02750	Active Service Bulletins 79-09-04-2
21SN04-211A	--	79-09-04	CMM	--	--	30-Sep-94	5	--	Eaton Bethel	02750	Active Service Bulletins 79-09-04-3
21SN04-223	--	73-34-04	CMM	--	--	24-Mar-04	3	--	Eaton Bethel	02750	Active Service Bulletins 73-34-04-01
21SN04-224	--	79-34-02	CMM	--	--	30-Jul-13	7	--	Eaton Bethel	02750	Active Service Bulletins 79-34-02-01
21SN04-225	--	79-34-02	CMM	--	--	30-Jul-13	7	--	Eaton Bethel	02750	Active Service Bulletins 79-34-02-01
21SN04-226	--	79-09-04	CMM	--	--	30-Sep-94	5	--	Eaton Bethel	02750	Active Service Bulletins 79-09-04-2
21SN04-226A	--	79-09-04	CMM	--	--	30-Sep-94	5	--	Eaton Bethel	02750	Active Service Bulletins 79-09-04-3
21SN04-23F	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-23G	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-23H	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-23J	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	--
21SN04-23K	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	--
21SN04-24F	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-24G	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-24H	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
21SN04-24J	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	--
21SN04-24K	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	--
21SN04-259	--	79-09-06	CMM	--	--	15-Nov-86	0	--	Eaton Bethel	02750	--
21SN04-25F	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-25G	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-25H	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-25J	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	--
21SN04-25K	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	--
21SN04-260	--	79-09-06	CMM	--	--	15-Nov-86	0	--	Eaton Bethel	02750	--
21SN04-260A	--	79-09-06	CMM	--	--	15-Nov-86	0	--	Eaton Bethel	02750	--
21SN04-268	--	79-09-04	CMM	--	--	30-Sep-94	5	--	Eaton Bethel	02750	--
21SN04-269	--	79-09-03	CMM	--	--	15-Jun-92	4	--	Eaton Bethel	02750	--
21SN04-26E	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-26F	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-26G	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-26H	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	--
21SN04-26J	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	--
21SN04-275A	--	79-34-15	CMM	--	--	15-Oct-89	1	--	Eaton Bethel	02750	--
21SN04-298A	--	79-35-16	CMM	--	--	15-Oct-89	1	--	Eaton Bethel	02750	--
21SN04-30	--	28-44-01	CMM	--	--	01-Apr-73	2	--	Eaton Bethel	02750	--
21SN04-300B	--	73-34-15	CMM	--	--	30-Apr-92	2	--	Eaton Bethel	02750	Active Service Bulletins 28-44-01-1

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
 techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
21SN04-30-1	--	28-44-01	CMM	--	--	01-Apr-73	2	--	Eaton Bethel	02750	--
21SN04-30-2	--	28-44-01	CMM	--	--	01-Apr-73	2	--	Eaton Bethel	02750	--
21SN04-306	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	--
21SN04-306A	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	Active Service Bulletins 31-09-01-2 R3
21SN04-306B	--	31-09-01	CMM	--	--	12-May-16	12	747	Eaton Bethel	02750	--
21SN04-323A	--	73-34-04	CMM	--	--	24-Mar-04	3	--	Eaton Bethel	02750	--
21SN04-324	--	79-34-02	CMM	--	--	30-Jul-13	7	--	Eaton Bethel	02750	--
21SN04-325	--	79-34-02	CMM	--	--	30-Jul-13	7	--	Eaton Bethel	02750	--
21SN04-33	--	79-09-01	CMM	--	--	01-Jul-87	4	747	Eaton Bethel	02750	--
21SN04-333	--	73-34-04	CMM	--	--	24-Mar-04	3	--	Eaton Bethel	02750	Active Service Bulletins 73-34-04-02 R1
21SN04-334	--	79-34-02	CMM	--	--	30-Jul-13	7	--	Eaton Bethel	02750	Active Service Bulletins 79-34-02-02 R1
21SN04-335	--	79-34-02	CMM	--	--	30-Jul-13	7	--	Eaton Bethel	02750	Active Service Bulletins 79-34-02-02 R1
21SN04-337A	--	73-33-11	CMM	--	--	15-Jun-95	0	--	Eaton Bethel	02750	--
21SN04-338	--	73-33-11	CMM	--	--	15-Jun-95	0	--	Eaton Bethel	02750	--
21SN04-339C	--	73-33-11	CMM	--	--	15-Jun-95	0	--	Eaton Bethel	02750	--
21SN04-33A	--	79-09-01	CMM	--	--	01-Jul-87	4	747	Eaton Bethel	02750	--
21SN04-34	--	79-09-01	CMM	--	--	01-Jul-87	4	747	Eaton Bethel	02750	--
21SN04-340	--	73-33-11	CMM	--	--	15-Jun-95	0	--	Eaton Bethel	02750	--
21SN04-341A	--	73-33-11	CMM	--	--	15-Jun-95	0	--	Eaton Bethel	02750	--
21SN04-352	--	79-09-07	CMM	--	--	15-Jan-95	1	--	Eaton Bethel	02750	--
21SN04-353	--	79-09-07	CMM	--	--	15-Jan-95	1	--	Eaton Bethel	02750	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
21SN04-354	--	79-09-07	CMM	--	--	15-Jan-95	1	--	Eaton Bethel	02750	--
21SN04-355	--	79-09-07	CMM	--	--	15-Jan-95	1	--	Eaton Bethel	02750	--
21SN04-356D	--	79-35-11	CMM	--	--	27-Aug-04	4	--	Eaton Bethel	02750	Active Service Bulletins 79-35-11-01 R1
21SN04-370	--	79-34-12	CMM	--	--	01-Jun-97	0	--	Eaton Bethel	02750	--
21SN04-371	--	79-38-02	CMM	--	--	31-Mar-95	0	--	Eaton Bethel	02750	--
21SN04-372	--	73-34-01	CMM	--	--	15-Apr-95	0	--	Eaton Bethel	02750	--
21SN04-373	--	73-34-02	CMM	--	--	31-Jan-01	1	--	Eaton Bethel	02750	Active Service Bulletins 73-34-02-01
21SN04-374	--	79-34-01	CMM	--	--	31-Jan-01	1	--	Eaton Bethel	02750	Active Service Bulletins 79-34-01-01
21SN04-383A	--	79-21-25	CMM	--	--	14-Feb-03	3	--	Eaton Bethel	02750	Active Service Bulletins 21SN04-383-01
21SN04-389A	--	79-21-26	CMM	--	--	13-Apr-04	3	747	Eaton Bethel	02750	Active Service Bulletins 79-21-26-02 R2
21SN04-389B	--	79-21-26	CMM	--	--	13-Apr-04	3	747	Eaton Bethel	02750	Active Service Bulletins 79-21-26-02 R2
21SN04-390	--	73-33-01	CMM	--	--	31-Jan-01	2	--	Eaton Bethel	02750	Active Service Bulletins 73-33-01-01
21SN04-391	--	79-21-25	CMM	--	--	14-Feb-03	3	--	Eaton Bethel	02750	Active Service Bulletins 79-21-25-02R1
21SN04-391A	--	79-21-25	CMM	--	--	14-Feb-03	3	--	Eaton Bethel	02750	Active Service Bulletins 79-21-25-02 R1
21SN04-401	--	79-35-11	CMM	--	--	27-Aug-04	4	--	Eaton Bethel	02750	Active Service Bulletins 79-35-11-02 R1
21SN04-402	--	79-21-26	CMM	--	--	13-Apr-04	3	747	Eaton Bethel	02750	Active Service Bulletins 79-21-26-04 79-21-26-03 R2
21SN04-403	--	79-21-26	CMM	--	--	13-Apr-04	3	747	Eaton Bethel	02750	Active Service Bulletins 79-21-26-03 R2 79-21-26-04
21SN04-404	--	79-21-25	CMM	--	--	14-Feb-03	3	--	Eaton Bethel	02750	Active Service Bulletins 79-21-25-03
21SN04-405	--	79-21-25	CMM	--	--	14-Feb-03	3	--	Eaton Bethel	02750	Active Service Bulletins 79-21-25-03
21SN04-413	--	79-35-11	CMM	--	--	27-Aug-04	4	--	Eaton Bethel	02750	Active Service Bulletins 79-35-11-03
21SN04-413A	--	79-35-11	CMM	--	--	27-Aug-04	4	--	Eaton Bethel	02750	Active Service Bulletins 79-35-11-03

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
21SN04-414	--	79-21-26	CMM	--	--	13-Apr-04	3	747	Eaton Bethel	02750	Active Service Bulletins 79-21-26-04
21SN04-415	--	79-21-26	CMM	--	--	13-Apr-04	3	747	Eaton Bethel	02750	Active Service Bulletins 79-21-26-04
21SN04-416	--	79-21-25	CMM	--	--	14-Feb-03	3	--	Eaton Bethel	02750	--
21SN04-417	--	79-21-25	CMM	--	--	14-Feb-03	3	--	Eaton Bethel	02750	--
21SN04-418	--	73-34-21	ACMM	--	--	31-Jan-01	0	--	Eaton Bethel	02750	Active Service Bulletins 73-34-21-01
21SN04-419	--	79-34-51	ACMM	--	--	02-Oct-08	2	--	Eaton Bethel	02750	Active Service Bulletins 79-34-51-01 R1
21SN04-420	--	73-33-24	ACMM	--	--	31-Jan-01	0	--	Eaton Bethel	02750	Active Service Bulletins 73-33-24-01
21SN04-421	--	73-33-22	CMM	--	--	31-Jan-01	0	--	Eaton Bethel	02750	Active Service Bulletins 73-33-22-01
21SN04-422A	--	77-41-03	ACMM	--	--	15-Dec-08	3	--	Eaton Bethel	02750	--
21SN04-422B	--	77-41-03	ACMM	--	--	15-Dec-08	3	--	Eaton Bethel	02750	--
21SN04-422C	--	77-41-03	ACMM	--	--	15-Dec-08	3	--	Eaton Bethel	02750	--
21SN04-425	--	73-33-23	CMM	--	--	09-Jul-08	1	--	Eaton Bethel	02750	--
21SN04-426	--	73-34-02	CMM	--	--	31-Jan-01	1	--	Eaton Bethel	02750	--
21SN04-427	--	79-34-01	CMM	--	--	31-Jan-01	1	--	Eaton Bethel	02750	--
21SN04-428	--	73-33-01	CMM	--	--	31-Jan-01	2	--	Eaton Bethel	02750	--
21SN04-430	--	73-34-21	ACMM	--	--	31-Jan-01	0	--	Eaton Bethel	02750	--
21SN04-431	--	79-34-51	ACMM	--	--	02-Oct-08	2	--	Eaton Bethel	02750	Active Service Bulletins 79-34-51-03 79-34-51-04
21SN04-432	--	73-33-24	ACMM	--	--	31-Jan-01	0	--	Eaton Bethel	02750	--
21SN04-433	--	73-33-22	CMM	--	--	31-Jan-01	0	--	Eaton Bethel	02750	--
21SN04-434	--	73-33-23	CMM	--	--	09-Jul-08	1	--	Eaton Bethel	02750	Active Service Bulletins 73-33-23-02
21SN04-434A	--	73-33-23	CMM	--	--	09-Jul-08	1	--	Eaton Bethel	02750	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
21SN04-435-1	--	28-44-03	CMM	--	--	31-Jan-99	0	--	Eaton Bethel	02750	--
21SN04-436-1	--	28-44-03	CMM	--	--	31-Jan-99	0	--	Eaton Bethel	02750	--
21SN04-437-1	--	28-44-03	CMM	--	--	31-Jan-99	0	--	Eaton Bethel	02750	--
21SN04-458	--	79-34-51	ACMM	--	--	02-Oct-08	2	--	Eaton Bethel	02750	Active Service Bulletins 79-34-51-05
21SN04-459	--	79-35-11	CMM	--	--	27-Aug-04	4	--	Eaton Bethel	02750	--
21SN04-460	--	79-21-26	CMM	--	--	13-Apr-04	3	747	Eaton Bethel	02750	--
21SN04-461	--	79-21-26	CMM	--	--	13-Apr-04	3	747	Eaton Bethel	02750	--
21SN04-466	--	73-34-04	CMM	--	--	24-Mar-04	3	--	Eaton Bethel	02750	--
21SN04-467	--	79-34-02	CMM	--	--	30-Jul-13	7	--	Eaton Bethel	02750	--
21SN04-468	--	79-34-02	CMM	--	--	30-Jul-13	7	--	Eaton Bethel	02750	--
21SN04-47	--	28-23-01	CMM	--	--	30-Nov-81	1	--	Eaton Bethel	02750	--
21SN04-59	--	75-31-21	CMM	--	--	01-Jun-72	0	--	Eaton Bethel	02750	--
21SN04-70	--	79-09-02	CMM	--	--	01-Jan-75	1	--	Eaton Bethel	02750	--
21SN04-70A	--	79-09-02	CMM	--	--	01-Jan-75	1	--	Eaton Bethel	02750	--
21SN04-71	--	79-09-02	CMM	--	--	01-Jan-75	1	--	Eaton Bethel	02750	--
21SN04-89	--	75-31-25	CMM	--	--	31-Aug-94	3	747	Eaton Bethel	02750	--
21SN04-98	--	28-44-01	CMM	--	--	01-Apr-73	2	--	Eaton Bethel	02750	--
21SN04-98-1	--	28-44-01	CMM	--	--	01-Apr-73	2	--	Eaton Bethel	02750	Active Service Bulletins 28-44-01-2
21SN04-98-2	--	28-44-01	CMM	--	--	01-Apr-73	2	--	Eaton Bethel	02750	--
21SN41-101A	--	36-12-07	CMM	--	--	01-Mar-93	0	--	Eaton Bethel	02750	--
21SN41-109A	--	30-22-11	ACMM	--	--	15-Feb-95	1	--	Eaton Bethel	02750	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
21SN41-111	--	28-42-04	CMM	--	--	01-Apr-96	1	--	Eaton Bethel	02750	--
21SN41-112	--	28-42-04	CMM	--	--	01-Apr-96	1	--	Eaton Bethel	02750	--
21SN41-113A	--	28-42-04	CMM	--	--	01-Apr-96	1	--	Eaton Bethel	02750	--
21SN41-125	--	28-42-04	CMM	--	--	01-Apr-96	1	--	Eaton Bethel	02750	--
21SN41-13	--	80-11-01	CMM	--	--	01-Mar-81	4	747	Eaton Bethel	02750	--
21SN41-1A	--	80-11-01	CMM	--	--	01-Mar-81	4	747	Eaton Bethel	02750	--
21SN41-1B	--	80-11-01	CMM	--	--	01-Mar-81	4	747	Eaton Bethel	02750	--
21SN41-30	--	80-11-01	CMM	--	--	01-Mar-81	4	747	Eaton Bethel	02750	--
21SN41-4	--	80-11-01	CMM	--	--	01-Mar-81	4	747	Eaton Bethel	02750	--
21SN41-42	--	80-21-03	CMM	--	--	01-Sep-90	2T	747	Eaton Bethel	02750	--
21SN41-49	--	80-11-02	CMM	--	--	31-Jul-98	1	747	Eaton Bethel	02750	Active Service Bulletins 80-11-02-2 R1
21SN41-49A	--	80-11-02	CMM	--	--	31-Jul-98	1	747	Eaton Bethel	02750	--
21SN41-4A	--	80-11-01	CMM	--	--	01-Mar-81	4	747	Eaton Bethel	02750	--
21SN41-5	--	80-11-01	CMM	--	--	01-Mar-81	4	747	Eaton Bethel	02750	--
21SN41-52	--	80-21-03	CMM	--	--	01-Sep-90	2T	747	Eaton Bethel	02750	--
21SN41-5A	--	80-11-01	CMM	--	--	01-Mar-81	4	747	Eaton Bethel	02750	--
21SN41-82	--	36-20-06	ACMM	--	--	31-Jul-98	1	--	Eaton Bethel	02750	Active Service Bulletins 36-20-06-1 R2
21SN41-82A	--	36-20-06	ACMM	--	--	31-Jul-98	1	--	Eaton Bethel	02750	--
21SN41-83	--	36-20-06	ACMM	--	--	31-Jul-98	1	--	Eaton Bethel	02750	Active Service Bulletins 36-20-06-1 R2
21SN41-83A	--	36-20-06	ACMM	--	--	31-Jul-98	1	--	Eaton Bethel	02750	--
21SN41-84	--	80-21-03	CMM	--	--	01-Sep-90	2T	747	Eaton Bethel	02750	Active Service Bulletins 80-21-03-1

For all Index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
21SN41-88	--	80-11-03	CMM	--	--	15-Jan-91	0	--	Eaton Bethel	02750	--
21SN41-88A	--	80-11-03	CMM	--	--	15-Jan-91	0	--	Eaton Bethel	02750	--
25GB10-107	--	28-21-12	ACMM	--	--	15-Jun-13	4	747, 777	Eaton Bethel	02750	--
25GB10-108	--	28-21-12	ACMM	--	--	15-Jun-13	4	747, 777	Eaton Bethel	02750	--
25GB10-109	--	28-21-12	ACMM	--	--	15-Jun-13	4	747, 777	Eaton Bethel	02750	--
25GB10-121	--	28-21-12	ACMM	--	--	15-Jun-13	4	747, 777	Eaton Bethel	02750	--
25GB10-99	--	28-21-12	ACMM	--	--	15-Jun-13	4	747, 777	Eaton Bethel	02750	--
41SG107-100	--	79-10-01	ACMM	--	--	01-Nov-91	0	--	Eaton Bethel	02750	--
41SG107-150	--	79-10-01	ACMM	--	--	01-Nov-91	0	--	Eaton Bethel	02750	--
41SG118-1	--	36-11-02	ACMM	--	--	15-Jul-12	2	747	Eaton Bethel	02750	--
41SG118-2	--	36-11-02	ACMM	--	--	15-Jul-12	2	747	Eaton Bethel	02750	--
41SG240-1	--	79-33-15	ACMM	--	--	30-Jan-11	2	--	Eaton Bethel	02750	Active Service Bulletins 79-33-15-01
41SG240-3	--	79-33-02	ACMM	--	--	31-Aug-96	0	--	Eaton Bethel	02750	--
41SG240-4	--	79-33-15	ACMM	--	--	30-Jan-11	2	--	Eaton Bethel	02750	--
41SG265-1	--	36-20-01	ACMM	--	--	15-Jan-90	0	747	Eaton Bethel	02750	--
41SG272-3	--	79-33-16	ACMM	--	--	15-Oct-12	5	--	Eaton Bethel	02750	--
41SG272-5	--	79-33-16	ACMM	--	--	15-Oct-12	5	--	Eaton Bethel	02750	Active Service Bulletins 79-33-16-01
41SG272-6	--	79-33-16	ACMM	--	--	15-Oct-12	5	--	Eaton Bethel	02750	--
41SG287-1	--	36-20-02	ACMM	--	--	15-Jan-90	0	747	Eaton Bethel	02750	--
41SG381-1	--	79-30-01	ACMM	--	--	16-Apr-04	3	--	Eaton Bethel	02750	--
41SG457-2	--	29-31-01	ACMM	--	--	31-Jul-98	0	--	Eaton Bethel	02750	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
14J45-1	--	36-11-05	CMM	Flex Joint Assembly	--	AUGUST 15/2000	2	--	Eaton, Eastanolee	8W928	--
14J44-1, 22J46-2	--	36-11-06	CMM	Bleed Air Duct Assembly	--	SEPTEMBER 1/2000	3	--	Eaton, Eastanolee	8W928	--
15J01-1, 575-0007-550	--	36-11-07	CMM	Flex Joint Assembly	--	SEPTEMBER 15/2000	1	--	Eaton, Eastanolee	8W928	--
14J91-500, 14J96-500, 1	--	36-11-08	CMM	Flex Joint Assembly	--	JANUARY 1/2000	1	--	Eaton, Eastanolee	8W928	--
16J62-3, 14J89-1, 14J98	--	36-11-09	CMM	Flex Slide Joint Assembly	--	APRIL 15/2002	2	--	Eaton, Eastanolee	8W928	--
14J81-1, 14J81-2	--	36-11-10	CMM	Bleed Air Duct Assembly	--	AUGUST 1/2000	3	--	Eaton, Eastanolee	8W928	--
15J26-1, 15J26-2	--	36-11-11	CMM	Flex Joint Assembly	--	APRIL 1/2002	1	--	Eaton, Eastanolee	8W928	--
16J08-1	--	36-11-14	CMM	Flex Slide Joint Assembly	--	SEPTEMBER 1/2000	1	--	Eaton, Eastanolee	8W928	--
77E70-1	--	36-11-15	CMM	Bleed Air Duct Assembly	--	SEPTEMBER 15/2000	1	--	Eaton, Eastanolee	8W928	--
73E61-1	--	36-11-16	CMM	Flex Joint Assembly	--	APRIL 1/2002	3	--	Eaton, Eastanolee	8W928	--
40E85-1, 40E85-2, 40E8	--	36-11-17	CMM	Flex Joint Assembly	--	APRIL 1/2002	3	--	Eaton, Eastanolee	8W928	--
40E87-1, 40E87-2, 53E4	--	36-11-18	CMM	Flex Joint Assembly	--	JULY 1/2002	2	--	Eaton, Eastanolee	8W928	--
53E36-1	--	36-11-19	CMM	Flex Joint Assembly	--	JULY 1/2002	2	--	Eaton, Eastanolee	8W928	--
53E08-1, 5E08-2	--	36-11-20	CMM	Flex Joint Assembly	--	JULY 1/2002	2	--	Eaton, Eastanolee	8W928	--
--	--	757-36-0028	SB	Replace HP2 Flex Joint Duct Assembly with split duct design for B757-200	--	June 27, 2002	--	B757	Eaton, Eastanolee	8W928	--
--	--	757-36-0029	SB	Replace HP2 Flex Joint Duct Assembly with split duct design for B757-300	--	June 27, 2002	--	B757	Eaton, Eastanolee	8W928	--
TB139100-4	--	28-1-1	CMM	--	30-Dec-60	30-Dec-60	BASIC	--	Eaton Euclid	59875	--
TB102700-7	--	28-1-31	CMM	--	30-Nov-62	15-Oct-67	2	--	Eaton Euclid	59875	--
225400	--	28-1-32	CMM	--	--	30-Aug-63	BASIC	--	Eaton Euclid	59875	--
831100	--	28-20-07	CMM	--	30-Sep-97	30-Sep-05	2	--	Eaton Euclid	59875	--
249000	--	28-20-1	CMM	--	--	31-Jul-69	3	--	Eaton Euclid	59875	Plessey

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
258000	--	28-20-1	CMM	--	01-Jul-63	30-Sep-05	8	--	Eaton Euclid	59875	--
TB141100-5	--	28-20-1	CMM	--	01-Jul-66	01-Jul-66	BASIC	--	Eaton Euclid	59875	--
TF11900-11	--	28-20-1	CMM	--	20-Jun-63	15-Oct-67	1	--	Eaton Euclid	59875	--
TB127300-1	--	28-20-2	CMM	--	15-Nov-60	30-Sep-05	5	--	Eaton Euclid	59875	--
832500	--	28-20-22B	CMM	--	--	30-Jul-11	3	--	Eaton Euclid	59875	--
832600	--	28-20-22T	CMM	--	--	15-Mar-12	3	--	Eaton Euclid	59875	--
TB102200-3	--	28-20-3	CMM	--	15-Feb-63	15-Jan-79	4	--	Eaton Euclid	59875	--
TB138300	--	28-20-4	CMM	--	01-Dec-60	01-Jun-68	1	--	Eaton Euclid	59875	--
382300	--	28-20-5	CMM	--	01-Jun-72	30-Sep-05	7	--	Eaton Euclid	59875	--
398000	--	28-20-6	CMM	--	31-Aug-84	13-Sep-16	7	--	Eaton Euclid	59875	--
399300	--	28-20-6	CMM	--	31-Aug-84	13-Sep-16	7	--	Eaton Euclid	59875	--
399500	--	28-20-6	CMM	--	31-Aug-84	13-Sep-16	7	--	Eaton Euclid	59875	--
702200	--	28-20-6	CMM	--	31-Aug-84	13-Sep-16	7	--	Eaton Euclid	59875	--
702300	--	28-20-6	CMM	--	31-Aug-84	13-Sep-16	7	--	Eaton Euclid	59875	--
202400	--	28-21-1	CMM	--	--	01-Dec-61	BASIC	--	Eaton Euclid	59875	--
842800	--	28-22-52	CMM	--	30-Sep-06	30-Sep-06	0	--	Eaton Euclid	59875	--
715200	--	49-30-01	CMM	--	01-May-88	01-Dec-04	4	--	Eaton Euclid	59875	--
258800	--	49-30-1	CMM	--	15-Jun-64	01-Oct-68	2	--	Eaton Euclid	59875	--
398600	--	73-10-03	CMM	--	01-Jul-81	15-May-05	2	--	Eaton Euclid	59875	--
706600	--	73-10-04	CMM	--	01-Nov-83	15-May-05	1	--	Eaton Euclid	59875	--
399700	--	73-10-05	CMM	--	30-Jun-84	15-Jun-06	5	--	Eaton Euclid	59875	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
705600	--	73-10-06	CMM	--	20-Nov-84	15-Jul-90	1	--	Eaton Euclid	59875	--
708800	--	73-10-06	CMM	--	30-Nov-84	15-Jul-90	1	--	Eaton Euclid	59875	--
710500	--	73-10-08	CMM	--	15-Mar-85	22-Sep-06	2	--	Eaton Euclid	59875	--
845400	--	73-10-08	CMM	--	15-Mar-85	22-Sep-06	2	--	Eaton Euclid	59875	--
394400	--	73-10-09	CMM	--	29-Feb-00	29-Feb-00	BASIC	--	Eaton Euclid	59875	--
717100	--	73-10-09	CMM	--	01-Dec-04	01-Dec-04	1	--	Eaton Euclid	59875	--
386100	--	73-10-10	CMM	--	15-Jan-92	30-Jun-11	4	--	Eaton Euclid	59875	--
386500	--	73-10-10	CMM	--	01-Nov-00	01-Nov-00	BASIC	--	Eaton Euclid	59875	--
845000	--	73-10-10	CMM	--	15-Jan-92	30-Jun-11	4	--	Eaton Euclid	59875	--
702800	--	73-10-11	CMM	--	15-Jan-92	01-Oct-07	3	--	Eaton Euclid	59875	--
388100	--	73-10-12	CMM	--	01-Nov-00	01-Nov-00	BASIC	--	Eaton Euclid	59875	--
825600	--	73-10-12	CMM	--	15-Aug-84	01-Oct-07	2	--	Eaton Euclid	59875	--
845600	--	73-10-13	CMM	--	21-Sep-07	21-Sep-07	1	--	Eaton Euclid	59875	--
847900	--	73-10-13	CMM	--	21-Sep-07	21-Sep-07	1	--	Eaton Euclid	59875	--
373400	--	73-11-01	CMM	--	01-Jul-69	15-Oct-91	13	--	Eaton Euclid	59875	--
382400	--	73-11-01	CMM	--	01-Jul-69	15-Oct-91	13	--	Eaton Euclid	59875	--
389400	--	73-11-01	CMM	--	01-Jul-69	15-Oct-91	13	--	Eaton Euclid	59875	--
705300	--	73-11-01	CMM	--	01-Jul-69	15-Oct-91	13	--	Eaton Euclid	59875	--
705400	--	73-11-01	CMM	--	01-Jul-69	15-Oct-91	13	--	Eaton Euclid	59875	--
705500	--	73-11-01	CMM	--	01-Jul-69	15-Oct-91	13	--	Eaton Euclid	59875	--
706800	--	73-11-01	CMM	--	01-Jul-69	15-Oct-91	13	--	Eaton Euclid	59875	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
715000	--	73-11-01	CMM	--	01-Jul-69	15-Oct-91	13	--	Eaton Euclid	59875	--
828200	--	73-11-01	CMM	--	31-Mar-98	07-Aug-19	2	--	Eaton Euclid	59875	--
829500	--	73-11-01	CMM	--	01-Apr-04	29-Jan-20	4	--	Eaton Euclid	59875	--
831000	--	73-11-01	CMM	--	31-Mar-98	31-Oct-01	1	--	Eaton Euclid	59875	--
386900	--	73-11-02	CMM	--	01-Jun-75	15-Oct-91	9	--	Eaton Euclid	59875	--
390600	--	73-11-02	CMM	--	01-Jun-75	15-Oct-91	9	--	Eaton Euclid	59875	--
720500	--	73-11-02	CMM	--	01-Jun-75	15-Oct-91	9	--	Eaton Euclid	59875	--
720600	--	73-11-02	CMM	--	01-Jun-75	15-Oct-91	9	--	Eaton Euclid	59875	--
837600	--	73-11-02	CMM	--	31-Jan-05	31-Jan-07	1	--	Eaton Euclid	59875	--
828500	--	73-11-03	CMM	--	30-Jun-95	01-Dec-04	2	--	Eaton Euclid	59875	--
711000	--	73-11-04	CMM	--	31-Jan-87	01-Nov-08	7	--	Eaton Euclid	59875	--
718800	--	73-11-04	CMM	--	31-Jan-87	01-Nov-08	7	--	Eaton Euclid	59875	--
720100	--	73-11-04	CMM	--	31-Jan-87	01-Nov-08	7	--	Eaton Euclid	59875	--
720300	--	73-11-04	CMM	--	31-Jan-87	01-Nov-08	7	--	Eaton Euclid	59875	--
721000	--	73-11-04	CMM	--	31-Jan-87	01-Nov-08	7	--	Eaton Euclid	59875	--
722100	--	73-11-04	CMM	--	31-Jan-87	01-Dec-04	7	--	Eaton Euclid	59875	--
825500	--	73-11-04	CMM	--	31-Jan-87	01-Nov-08	7	--	Eaton Euclid	59875	--
723300	--	73-11-05	CMM	--	31-Jul-92	01-Dec-04	3	--	Eaton Euclid	59875	--
846400	--	73-11-06	CMM	--	13-Jan-12	11-Oct-17	1	--	Eaton Euclid	59875	--
243600	--	73-11-1	CMM	--	01-Aug-05	15-May-09	16	--	Eaton Euclid	59875	--
358200	--	73-11-1	CMM	--	01-Aug-05	15-May-09	16	--	Eaton Euclid	59875	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
371900	--	73-11-1	CMM	--	01-Aug-05	15-May-09	16	--	Eaton Euclid	59875	--
378200	--	73-11-1	CMM	--	01-Aug-05	15-May-09	16	--	Eaton Euclid	59875	--
835800	--	73-11-1	CMM	--	01-Aug-05	15-May-09	16	--	Eaton Euclid	59875	--
847000	--	73-11-10	CMM	--	06-Dec-16	06-Dec-16	0	--	Eaton Euclid	59875	--
704300	--	73-11-11	CMM	--	01-Sep-80	16-Oct-09	14	--	Eaton Euclid	59875	--
708300	--	73-11-11	CMM	--	01-Sep-80	16-Oct-09	14	--	Eaton Euclid	59875	--
708600	--	73-11-11	CMM	--	01-Sep-80	16-Oct-09	14	--	Eaton Euclid	59875	--
708400	--	73-11-12	CMM	--	28-Feb-85	01-Nov-00	4	--	Eaton Euclid	59875	--
832900	--	73-11-12	CMM	--	01-Mar-00	01-Mar-00	BASIC	--	Eaton Euclid	59875	--
714900	--	73-11-13	CMM	--	30-Nov-87	01-Nov-00	4	--	Eaton Euclid	59875	--
724400	--	73-11-14	CMM	--	31-Oct-94	01-Nov-00	1	--	Eaton Euclid	59875	--
828300	--	73-11-15	CMM	--	31-Mar-97	11-Oct-16	4	--	Eaton Euclid	59875	--
219700	--	73-11-16	CMM	--	15-Aug-99	31-Oct-01	1	--	Eaton Euclid	59875	--
841200	--	73-11-19	CMM	--	--	31-Dec-08	1	--	Eaton Euclid	59875	--
384300	--	73-11-2	CMM	--	01-Nov-80	15-May-09	10	--	Eaton Euclid	59875	--
835900	--	73-11-2	CMM	--	01-Nov-80	15-May-09	10	--	Eaton Euclid	59875	--
830100	--	73-11-21	CMM	--	15-Mar-97	31-Oct-01	1	--	Eaton Euclid	59875	--
843500	--	73-11-34	CMM	--	13-Dec-16	--	--	--	Eaton Euclid	59875	--
838000	--	73-11-77	CMM	--	15-Sep-02	30-May-12	1	--	Eaton Euclid	59875	--
842100	--	73-12-10	CMM	--	23-Dec-15	23-Dec-15	00	--	Eaton Euclid	59875	--
721400	--	73-12-11	CMM	--	30-Apr-95	15-Oct-08	2	--	Eaton Euclid	59875	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
850200	--	73-12-11	CMM	--	01-Aug-16	--	--	--	Eaton Euclid	59875	--
830800	--	73-12-12	CMM	--	01-Aug-01	15-Oct-08	1	--	Eaton Euclid	59875	--
716700	--	73-16-01	CMM	--	30-Sep-94	01-Nov-06	2	--	Eaton Euclid	59875	--
829100	--	73-16-02	CMM	--	01-Jul-00	01-Nov-06	1	--	Eaton Euclid	59875	--
396800	--	75-31-11	CMM	--	01-Sep-80	31-Jan-06	10	--	Eaton Euclid	59875	--
706400	--	75-31-12	CMM	--	31-Dec-83	31-Jan-06	6	--	Eaton Euclid	59875	--
723000	--	79-21-02	CMM	--	01-Apr-96	01-Apr-96	BASIC	--	Eaton Euclid	59875	--
724800	--	79-21-03	CMM	--	01-Apr-96	31-Jan-00	1	--	Eaton Euclid	59875	--
830900	--	79-21-03	CMM	--	01-Apr-96	31-Jan-00	1	--	Eaton Euclid	59875	--
102200	--	28-1	TR	To add CDCCL Warning statement to the Title Page after the part number and description	TBD	--	N/A	--	Eaton Euclid	59875	In review at Boeing
846400	--	73-01	TR	Add Gear Inlet Drain Port Check and Repair	30-Aug-19	--	N/A	--	Eaton Euclid	59875	CMM Ref. 73-11-06
724400	--	73-14	TR	New views added to existing illustration Figure 520	22-Dec-16	--	N/A	--	Eaton Euclid	59875	CMM Ref. 73-11-14
396800	--	75-11	TR	New Fluids for Test added...	13-Jan-17	--	N/A	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-2) 73-001	SB	Introduction of a Pump with a Reinforced Front Mounting Flange	26-Mar-82	17-Jun-83	2	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-012	SB	Manual Functional Check of the Fuel Pump	14-Mar-83	30-Apr-84	1	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-0123 [and 708600-73-121]	SB	Introduction of New Pump Gears	14-Mar-05	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-026	SB	Dry Film Lubricant Added to Impeller Shaft	19-Dec-83	01-Aug-85	1	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-031	SB	Introduction of Vendor Part Number for Fuel Filter Element	30-Apr-84	20-Sep-84	1	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-052	SB	Introduction of a New Vendor for Fuel Filter Element	17-Feb-86	28-Apr-87	1	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-054	SB	Increased Boost Stage End Clearance and Impeller Back Shroud Clearance	05-May-86	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-055	SB	Introduction of a New Fuel Pump to Increase LP Shaft End Clearance	29-May-86	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	(CFM56-2) 73-060	SB	Spare Parts Release for CFM56-2 IPC and Fuel Pump IPL	10-Apr-87	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-070	SB	Spare Parts Release for CFM56-2 IPC	26-Jan-89	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-071	SB	Introduction of New Vendors for Fuel Filter Element	11-Apr-89	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-078	SB	Introduction of New Fuel Pump with New Solid Bronze Bearings	18-May-90	05-Feb-92	3	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-081	SB	Introduction of Solid Bronze Bearings	10-Jan-91	24-Sep-92	2	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-082	SB	Introduction of a New Stationary Shaft Seal	15-Nov-90	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-086	SB	Introduction of a Service Bulletin Plate	06-Jun-91	28-Jan-92	1	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-089	SB	Introduction of a New Control Shaft Retainer	28-Apr-92	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-091	SB	Introduction of New Pump Gears	05-Oct-92	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-098	SB	Introduction of New Impeller Drive Shaft	23-Feb-96	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-099	SB	Introduction of New Boost Stage Drive Shaft	13-May-96	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-104 [and 708600-73-103]	SB	Conversion of Bronze Bearings to Aluminum/ Bronze Bearings	18-Sep-96	17-Dec-03	3	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-107 [and 708600-73-104]	SB	Spare Parts Release	22-Aug-97	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-114 [and 708600-73-114]	SB	Introduction of a New Bearing Seal	02-Feb-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-118 [and 708600-73-115]	SB	Introduction of New Preformed Packings in the Fuel Filter	10-May-01	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-119 [and 708600-73-118]	SB	Introduction of New Fuel Filter	06-Sep-02	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 73-A113 [and 708600-73-113]	SB	Introduction of New Fuel Pump with New Filter Cover Attachment	17-Aug-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2) 75-017	SB	Introduction of New Gear Bore Epoxy Coating	04-Mar-86	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-2) 75-020	SB	Spare Parts Release for CFM56-2 IPC and Hydraulic Gear Motor IPL	06-Apr-87	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-2) 75-029	SB	Introduction of a New Hydraulic Gear Motor	05-Mar-91	10-Jun-92	2	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-2) 75-035	SB	Introduction of a New Stationary Shaft Seal 218930-1	05-Mar-93	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	(CFM56-2A) 73-0064	SB	Replacement of the Current Defective Sixth Attachment of the Fuel Filter Cover of the Main Fuel Pump Equipped with D Head Bolt	04-Feb-03	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	(CFM56-2A) 73-0067 [and 708400-73-103]	SB	Introduction of New Pump Gears	14-Mar-05	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	(CFM56-2A) 73-0080 [and 828300-73-110]	SB	Introduction of a New Filter Bypass Valve Retaining Ring	05-Oct-17	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	(CFM56-2A) 73-016	SB	Spare Parts Release for CFM56-2A IPC and Fuel Pump IPL	23-Apr-87	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	(CFM56-2A) 73-034	SB	Introduction of a New Stationary Shaft Seal	15-Nov-90	07-May-92	1	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	(CFM56-2A) 73-038	SB	Introduction of a Service Bulletin Plate	06-Jun-91	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	(CFM56-2A) 73-041	SB	Introduction of New Pump Gears	05-Oct-92	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	(CFM56-2A) 73-045	SB	Introduction of New Impeller Drive Shaft	15-Feb-96	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	(CFM56-2A) 73-046	SB	Introduction of New Boost Stage Drive Shaft	15-Feb-96	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	(CFM56-2A) 73-054	SB	Replacement of the Attachment Parts of the Fuel Filter Cover	15-Dec-97	07-Jan-98	1	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	(CFM56-2A) 73-055	SB	Inspection of the Fuel Filter Cover Attachment Parts	06-Aug-98	29-Apr-99	1	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	(CFM56-2A) 73-059 [and 708400-73-102]	SB	Introduction of a New Bearing Seal	02-Feb-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	(CFM56-2A) 73-063 [and 708600-73-115]	SB	Introduction of New Preformed Packings in the Fuel Filter	10-May-01	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	(CFM56-2A) 73-A058 [and 708400-73-101]	SB	Introduction of New Fuel Pump with New Filter Cover Attachment	17-Aug-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	(CFM56-2A) 75-002	SB	Introduction of New Gear Bore Epoxy Coating	20-Oct-86	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-2A) 75-004	SB	Spare Parts Release for CFM56-2A IPC and Hydraulic Gear Motor IPL	06-Apr-87	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-2A) 75-014	SB	Introduction of a New Hydraulic Gear Motor	12-Feb-91	03-Jun-92	2	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-2A) 75-020	SB	Introduction of a New Stationary Shaft Seal 218930-1	05-Mar-93	14-Jun-94	1	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-2B) 73-006	SB	Dry Lubricant Film Added to Impeller Shaft	31-Oct-84	04-Mar-86	1	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-0089 [and 708600-73-122]	SB	Introduction of New Pump Gears	14-Mar-05	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-0102 [and 708600-73-124]	SB	Introduction of a New Fuel Pump with a New Filter Bowl Cover	30-Jun-17	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11 73-11-12

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	(CFM56-2B) 73-0103 [and 828300-73-110]	SB	Introduction of a New Filter Bypass Valve Retaining Ring	05-Oct-17	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11 73-11-12
--	--	(CFM56-2B) 73-017	SB	Introduction of Vendor Part Number for Fuel Filter Element	04-Feb-86	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-019	SB	Introduction of a New Vendor for Fuel Filter Element	10-Feb-86	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-020	SB	Increased Boost Stage End Clearance and Impeller Back Shroud Clearance	5/5/1986 5/31/2005	--	2	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-021	SB	Introduction of a New Fuel Pump to Increase Shaft End Clearance	29-May-86	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-026	SB	Replacement of Facet Filter with APM Filter	03-Jul-86	29-Apr-87	3	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-028	SB	Spare Parts Release for CFM56-2B IPC and Fuel Pump IPL	23-Apr-87	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-045	SB	Introduction of a New Vendor for Fuel Filter Elements	18-Oct-90	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-050	SB	Introduction of a New Stationary Shaft Seal	17-Dec-90	09-Apr-92	1	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-053	SB	Introduction of a Service Bulletin Plate	06-Jun-91	06-Dec-91	1	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-057	SB	Introduction of a New Control Drive Shaft Retainer	22-Apr-92	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-059	SB	Introduction of New Pump Gears	05-Oct-92	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-063	SB	Recall of Boost Stage Drive Shaft	25-Aug-93	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-064	SB	Introduction of New Impeller Drive Shaft	23-Feb-96	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-065	SB	Introduction of New Boost Drive Shaft	17-Jun-96	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-067 [and 708600-73-100]	SB	Inspection of Impeller Nut	16-Oct-95	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-080 [and 708600-73-109]	SB	Introduction of a New Bearing Seal	04-Feb-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-084 [and 708600-73-115]	SB	Introduction of New Preformed Packings in the Fuel Filter	10-May-01	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-086 [and 708600-73-119]	SB	Introduction of New Fuel Filter	17-Oct-02	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 73-A079 [and 708600-73-112]	SB	Introduction of New Fuel Pump with New Filter Cover Attachment	17-Aug-99	22-Oct-99	1	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-2B) 75-002	SB	Introduction New VBV Close Tube and New TC1 and TC2 Fuel Tubes with Modified Routing	27-Apr-84	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	(CFM56-2B) 75-008	SB	Introduction of a New Gear Bore Epoxy Coating	17-Feb-86	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-2B) 75-010	SB	Spare Parts Release for CFM56-2B IPC and Hydraulic Gear Motor IPL	10-Apr-87	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-2B) 75-016	SB	Introduction of a New Hydraulic Gear Motor	05-Mar-91	14-May-92	3	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-2B) 75-022	SB	Introduction of a New Stationary Shaft Seal 218930-1	05-Mar-93	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-3) 73-002	SB	Replacement of the Main Fuel Pump on CFM56-3 Engines	01-Mar-84	20-Apr-94	2	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3) 73-042	SB	Introduction of a New Main Fuel Pump Fitted with a Two-Port Special PBP Elbow	18-Jul-86	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B) 73-030	SB	Introduction of Vendor Part Number for Fuel Filter Element	24-Jan-86	29-Apr-87	1	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B) 73-032	SB	Introduction of Vendor Part Number for Fuel Filter Element	10-Feb-86	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B) 73-036	SB	Increased Boost Stage End Clearance and Impeller Back Shroud Clearance	16-Apr-86	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B) 73-046	SB	Introduction of Fuel Pump v717N 708600-1 (S/N P/N 301-778-801-0) without Special Elbow for CFM56-3/3B Engines. Times Capable as Noted	26-Aug-86	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B) 73-050	SB	Spare Parts Release for CFM56-3/3B IPC and Fuel Pump IPL	27-Apr-87	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B) 75-008	SB	Introduction of New Gear Bore Epoxy Coating	14-Mar-86	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-12
--	--	(CFM56-3/3B) 75-010	SB	Spare Parts Release for CFM56-3/3B IPL and Hydraulic Gear Motor IPL	23-Apr-87	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-12
--	--	(CFM56-3/3B/3C) 73-0144 [and 708600-73-120]	SB	Introduction of New Pump Gears	11-Jan-05	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-0158 [and 828300-73-110]	SB	Introduction of a New Filter Bypass Valve Retaining Ring	05-Oct-17	--	--	--	Eaton Euclid	59875	73-11-11
--	--	(CFM56-3/3B/3C) 73-047	SB	Fuel Pump Shaft Seal Inspection	20-Nov-86	03-Dec-87	1	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-052	SB	Removal of Fuel Pump Special Elbow	30-Mar-87	19-Apr-88	1	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-071	SB	Introduction of New Vendors for Fuel Filter Element	11-Apr-89	28-Mar-91	1	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-082	SB	Introduction of New Pump with Solid Bronze Bearings	18-May-90	01-Dec-93	4	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-085	SB	Introduction of a New Stationary Shaft Seal	29-Jun-90	06-Dec-91	2	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-087	SB	Introduction of Solid Bronze Bearings	10-Jan-91	05-Feb-92	1	--	Eaton Euclid	59875	CMM Ref. 73-11-11

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	(CFM56-3/3B/3C) 73-095	SB	Introduction of a Service Bulletin Plate	06-Jun-91	06-Dec-91	1	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-102	SB	Introduction of a New Control Shaft Retainer	29-Apr-92	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-105	SB	Introduction of New Pump Gears	05-Oct-92	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-108	SB	Recall of Boost Stage Drive Shaft	04-Mar-93	16-Jun-93	1	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-112	SB	Introduction of New Impeller Drive Shaft	27-Jul-94	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-113	SB	Introduction of New Boost Stage Drive Shaft	27-Jul-94	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-115 [and 708600-73-101]	SB	Inspection of Impeller Nut	16-Oct-95	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-120 [and 708600-73-102]	SB	Conversion of Bronze Bearings to Aluminum/ Bronze Bearings	25-Sep-96	25-Oct-06	6	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-123 [and 708600-73-104]	SB	Spare Parts Release	25-Aug-97	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-127 [and 708600-73-106]	SB	Spare Parts Release (Oversize Bearings)	12-Apr-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-132 [and 708600-73-108]	SB	Introduction of a New Bearing Seal	04-Feb-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-137 [and 708600-73-115]	SB	Introduction of New Preformed Packings in the Fuel Filter	10-May-01	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-141 [and 708600-73-117]	SB	Introduction of New Fuel Filter	06-Sep-02	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 73-A129 [and 708600-73-110]	SB	Introduction of New Fuel Pump with New Filter Cover Attachment	17-Aug-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	(CFM56-3/3B/3C) 75-022	SB	Introduction of a New Hydraulic Gear Motor	07-Mar-91	23-Mar-92	3	--	Eaton Euclid	59875	CMM Ref. 75-31-12
--	--	(CFM56-3/3B/3C) 75-035	SB	Introduction of a New Stationary Shaft Seal 218930-1	05-Mar-93	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-12
--	--	(CFM56-5) 73-0126 [and 714900-73-101]	SB	Conversion of Bronze Bearings to Aluminum/ Bronze Bearings	18-Sep-96	25-Oct-06	5	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 73-0160 [and 708600-73-115]	SB	Introduction of New Preformed Packings in the Fuel Filter	04-May-01	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 73-0174	SB	Replacement of the Current Defective Sixth Attachment of the Fuel Filter Main Fuel Pump Equipped with D-Head Bolt (714900-2 and 4)	04-Feb-03	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 Canceled?
--	--	(CFM56-5) 73-0177 [and 714900-73-113]	SB	Introduction of New Fuel Filter	22-Jul-02	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 73-0192 [and 714900-73-115]	SB	Introduction of New Pump Gears	11-Jan-05	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	(CFM56-5) 73-0224 [and 828300-73-110]	SB	Introduction of a New Filter Bypass Valve Retaining Ring	05-Oct-17	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 73-025	SB	Introduction of New Vendors for Fuel Filter	11-Apr-89	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 73-061	SB	Introduction of a New Stationary Shaft Seal	15-Nov-90	09-Jan-92	1	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 73-070	SB	Introduction of a Service Bulletin Plate	06-Jun-91	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 73-077	SB	Introduction of New Fuel Pump with Solid Bronze Bearings	10-Oct-91	30-Sep-92	2	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 73-086	SB	Introduction of a New Control Shaft Retainer	22-Apr-92	13-Nov-92	1	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 73-091	SB	Introduction of New Fuel Pump Gears	05-Oct-92	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 73-096	SB	Recall of Boost Stage Drive Shaft	04-Mar-93	16-Jun-93	1	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 73-105	SB	Introduction of New Impeller Drive Shaft	27-Jul-94	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 73-106	SB	Introduction of New Boost Stage Drive Shaft	27-Jul-94	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 73-134 [and 714900-73-102]	SB	Spare Parts Release (Relief Valve Packing)	22-Aug-97	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	(CFM56-5) 73-135	SB	Replacement of the Attachment Parts of the Fuel Filter Cover (714900-1 and 2)	15-Dec-97	07-Jan-98	1	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 73-136	SB	Inspection of the Fuel Filter Cover Attachment Parts	26-May-98	29-Apr-99	2	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 73-139 [and 714900-73-103]	SB	Spare Parts Release (Oversize Bearings)	12-Apr-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 73-147 [and 714900-73-104]	SB	Introduction of a New Bearing Seal	01-Feb-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 73-155 [and 714900-73-111]	SB	Introduction of Improved Shaft Seal	08-Mar-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 73-A143 [and 714900-73-106]	SB	Introduction of New Fuel Pump with New Filter Cover Attachment	18-Jun-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) 75-0040 [and 396800-75-100]	SB	Introduction of a New Stationary Shaft Seal 219445-1	29-Jan-96	10-May-96	1	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-5) 75-0047 [and 396800-75-102]	SB	Recall/Rework of New Stationary Shaft Seal 219445-1	25-Sep-96	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-5) 75-0055 [and 396800-75-107]	SB	Introduction of a New Hydraulic Gear Motor	24-Nov-99	23-May-00	1	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-5) 75-0063	SB	VBV System Preventative Maintenance	05-Sep-06	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	(CFM56-5) 75-011	SB	Introduction of a New Hydraulic Gear Motor	28-Mar-91	01-Sep-92	2	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-5) 75-015	SB	Inspection of Suspect Stationary Shaft Seal	02-Jul-91	18-Nov-92	2	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-5) 75-028	SB	Introduction of a New Stationary Shaft Seal 218930-1	05-Mar-93	06-May-93	1	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-5) CESM 020	SB	Main Fuel Pump	12-Oct-92	15-Jun-00	4	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5) CESM 034	SB	Main Fuel Pump HP Gear Tooth Fracture	18-Dec-03	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5B) 72-032	SB	Introduction New Fuel Pump	21-Apr-94	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-14
--	--	(CFM56-5B) 73-0067 [and 714900-73-109]	SB	Introduction of a New Bearing Seal	01-Feb-00	10-Oct-00	1	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5B) 73-0084 [and 708600-73-115]	SB	Introduction of New Preformed Packings in the Fuel Filter	15-May-01	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11 -12, -13, -14
--	--	(CFM56-5B) 73-0107 [and 714900-73-112]	SB	Introduction of New Fuel Filter	22-Jul-02	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	(CFM56-5B) 73-0111	SB	Fuel Filter System (73-11-10) - Replacement of the Current Defective Sixth Attachment of the Fuel Filter Cover of the Main Fuel Pump	04-Feb-03	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	(CFM56-5B) 73-0129 [and 714900-73-116]	SB	Introduction of New Pump Gears	11-Jan-05	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5B) 73-027 [and 724400-73-100]	SB	Inspection of Impeller Nut	07-Nov-95	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	(CFM56-5B) 73-0287 [and 828300-73-110]	SB	Introduction of a New Filter Bypass Valve Retaining Ring	05-Oct-17	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	(CFM56-5B) 73-035	SB	Introduction of a New Impeller Drive Shaft	26-Jul-96	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5B) 73-036	SB	Introduction of New Boost Stage Drive Shaft	26-Jul-96	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5B) 73-053 [and 714900-73-102]	SB	Spare Parts Release (Relief Valve Packing)	22-Aug-97	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	(CFM56-5B) 73-055	SB	Replacement of the Attachment Parts of the Fuel Filter Cover	15-Dec-97	00-Jan-98	1	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5B) 73-056	SB	Inspection of Fuel Filter Cover Attachment Parts	26-May-98	29-Apr-99	2	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	(CFM56-5B) 73-078 [and 714900-73-111]	SB	Introduction of Improved Shaft Seal	08-Mar-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	(CFM56-5B) 73-A0062 [and 714900-73-107]	SB	Introduction of New Fuel Pump with New Filter Cover Attachment	18-Jun-99	20-Apr-01	1	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	(CFM56-5B) 75-0032	SB	VBV System Preventative Maintenance	05-Sep-06	07-Nov-16	3	--	Eaton Euclid	59875	CMM Ref. 75-31-11

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	(CFM56-5B) 75-004 [and 396800-75-100]	SB	Introduction of a New Hydraulic Gear Motor	23-Feb-96	10-May-96	1	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-5B) 75-0045	SB	Inspection and Overhaul of VBV System	08-Oct-12	12-Nov-15	1	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-5B) 75-011 [and 396800-75-103]	SB	Recall/Rework of New Stationary Shaft Seal 219445-1	25-Sep-96	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-5B) 75-021 [and 396800-75-107]	SB	Introduction of a New Hydraulic Gear Motor	24-Nov-99	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-5B) CESM 015	SB	Main Fuel Pump HP Gear Tooth Fracture	18-Dec-03	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5C) 73-0084 [and 714900-73-110]	SB	Introduction of a New Bearing Seal	01-Feb-00	10-Oct-00	1	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5C) 73-009	SB	Recall of Boost Stage Drive Shaft	05-Mar-93	16-Jun-93	1	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5C) 73-0094 [and 714900-73-111]	SB	Introduction of Improved Shaft Seal	08-Mar-00	04-Apr-00	1	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	(CFM56-5C) 73-0101 [and 708600-73-115]	SB	Introduction of New Preformed Packings in the Fuel Filter	15-May-01	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	(CFM56-5C) 73-0118	SB	Fuel Filter System (73-11-10) - Replacement of the Current Defective Sixth Attachment of the Fuel Filter Cover of the Main Fuel Pump	04-Feb-03	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	(CFM56-5C) 73-0119 [and 714900-73-112]	SB	Introduction of New Fuel Filter	22-Jul-02	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	(CFM56-5C) 73-0160 [and 714900-73-114]	SB	Introduction of New Pump Gears	05-Jan-05	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5C) 73-0205 [and 828300-73-110]	SB	Introduction of a New Filter Bypass Valve Retaining Ring	05-Oct-17	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	(CFM56-5C) 73-039	SB	Introduction of Fuel Pump Model 724400	14-Jun-95	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-14
--	--	(CFM56-5C) 73-040 [and 714900-73-100]	SB	Inspection of Impeller Nut	16-Oct-95	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5C) 73-048	SB	Introduction of New Impeller Drive Shaft	26-Jul-96	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5C) 73-049	SB	Introduction of New Boost Stage Drive Shaft	26-Jul-96	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-5C) 73-061	SB	Introduction of a New Alternate Fuel Pump for CFM56-5C2/G and 5C3/G Engines Versions	10-Feb-97	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	(CFM56-5C) 73-069 [and 714900-73-102]	SB	Spare Parts Release	22-Aug-97	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	(CFM56-5C) 73-070	SB	Replacement of the Attachment Parts of the Fuel Filter Cover	15-Dec-97	07-Jan-98	1	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	(CFM56-5C) 73-073	SB	Inspection of the Fuel Filter Cover Attachment Parts	26-May-98	29-Apr-99	2	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	(CFM56-5C) 73-A0078 [and 714900-73-108]	SB	Introduction of New Fuel Pump with New Filter Cover Attachment	21-Jun-99	20-Apr-01	1	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	(CFM56-5C) 75-0051 [and 396800-75-107]	SB	Introduction of a New Stationary Shaft Seal 219876-1	24-Nov-99	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-5C) 75-020 [and 396800-75-101]	SB	Introduction of a New Stationary Shaft Seal 219445-1	22-Apr-96	27-Feb-97	1	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-5C) 75-023 396800-75-104	SB	Recall/Rework of New Stationary Shaft Seal 219445-1	25-Sep-96	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	(CFM56-5C) CESM 016	SB	Main Fuel Pump HP Gear Tooth Fracture	18-Dec-03	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	(CFM56-7) 73-003	SB	To Facilitate the HMU Removal/Installation on the Main Fuel Pump	06-Mar-97	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	(CFM56-7) 73-007	SB	Introduction of New Main Fuel Pump with a New Stationary Shaft Seal	16-Jul-97	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	(CFM56-7B) 73-0052 [and 828300-73-102]	SB	Introduction of a New Impeller Drive Shaft and Impeller Drive Shaft Preformed Packing	27-Mar-01	25-Aug-03	2	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	(CFM56-7B) 73-0078 [and 828300-73-103]	SB	Introduction of New Fuel Filter	14-Jun-02	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	(CFM56-7B) 73-0079	SB	Replacement of the Current Destructive Sixth Attachment of the Fuel Filter Main Fuel Pump Equipped with D- Head Bolt	04-Feb-03	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15 Canceled?
--	--	(CFM56-7B) 73-0107 [and 828300-73-104]	SB	Inspection of Pump Cover	08-Oct-04	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	(CFM56-7B) 73-0118 [and 828300-73-105]	SB	Introduction of New Main Fuel Pump with a New Pump Cover	14-Nov-05	23-Feb-06	1	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	(CFM56-7B) 73-0144	SB	Spare Parts Release for CFM56-7B CMM	04-Apr-08	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	(CFM56-7B) 73-0164 [and 828300-73-106]	SB	Spare Parts Release for CFM56-7B CMM	19-Feb-16	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	(CFM56-7B) 73-0209 [and 828300-73-107]	SB	Replacement of Main Fuel Pump	24-Feb-15	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	(CFM56-7B) 73-0212 [and 828300-73-108]	SB	Introduction of a New Fuel Pump with a New Shaft Seal	09-Oct-15	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	(CFM56-7B) 73-0221 [and 828300-73-110]	SB	Introduction of a new Filter Bypass Valve Retaining Ring	30-May-17	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	(CFM56-7B) 73-0224 [and 828300-73-111]	SB	Introduction of a New Fuel Pump with a New Shaft Seal	04-Aug-17	02-Apr-18	2	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	(CFM56-7B) 73-0225 [and 828300-73-109]	SB	Replacement of the Filter By-pass Retaining Ring on a Specific Batch of Pumps	30-May-17	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	(CFM56-7B) 73-A034 [and 828300-73-101]	SB	Introduction of New Fuel Pump with New Filter Cover Attachment	23-Jul-99	29-Mar-04	1	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	396800-75-100 [and (CFM56-5) 75-0040]	SB	Introduction of a New Stationary Shaft Seal 219445-1	21-Dec-95	29-Mar-96	1	--	Eaton Euclid	59875	CMM Ref. 75-31-11

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	396800-75-100 [and (CFM56-5B) 75-004]	SB	Introduction of a New Hydraulic Gear Motor	21-Dec-95	29-Mar-96	1	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	396800-75-101 [and (CFM56-5C) 75-020]	SB	Introduction of a New Stationary Shaft Seal 219445-1	01-Apr-96	31-Jan-97	1	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	396800-75-102 [and (CFM56-5) 75-0047]	SB	Recall/Rework of New Stationary Shaft Seal 219445-1	01-Sep-96	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	396800-75-103 [and (CFM56-5B) 75-011]	SB	Recall/Rework of New Stationary Shaft Seal 219445-1	01-Sep-96	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	396800-75-107 [and (CFM56-5) 75-0055]	SB	Introduction of a New Hydraulic Gear Motor	12-Nov-99	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	396800-75-107 [and (CFM56-5B) 75-021]	SB	Introduction of a New Hydraulic Gear Motor	12-Nov-99	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	396800-75-107 [and (CFM56-5C) 75-0051]	SB	Introduction of a New Stationary Shaft Seal 219876-1	12-Nov-99	--	--	--	Eaton Euclid	59875	CMM Ref. 75-31-11
--	--	708400-73-101 [and (CFM56-2A) 73-A058]	SB	Introduction of New Fuel Pump with New Filter Cover Attachment	16-Apr-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	708400-73-102 [and (CFM56-2A) 73-059]	SB	Introduction of a New Bearing Seal	20-Jan-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	708400-73-103 [and (CFM56-2A) 73-0067]	SB	Introduction of New Pump Gears	10-Mar-05	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	708600-73-100 [and (CFM56-2B) 73-067]	SB	Inspection of Impeller Nut	01-Oct-95	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-101 [and (CFM56-3/3B/3C) 73-115]	SB	Inspection of Impeller Nut	01-Oct-95	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-102 [and (CFM56-3/3B/3C) 73-120]	SB	Conversion of Bronze Bearings to Aluminum/ Bronze Bearings	15-Oct-96	25-Oct-06	2	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-103 [and (CFM56-2) 73-104]	SB	Conversion of Bronze Bearings to Aluminum/ Bronze Bearings	15-Oct-96	04-Nov-03	1	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-104 [and (CFM56-2) 73-107]	SB	Spare Parts Release	15-Aug-97	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-104 [and (CFM56-3/3B/3C) 73-123]	SB	Spare Parts Release	01-May-97	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-106 [and (CFM56-3/3B/3C) 73-127]	SB	Spare Parts Release (Oversize Bearings)	30-Oct-98	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-108 [and (CFM56-3/3B/3C) 73-132]	SB	Introduction of a New Bearing Seal	20-Jan-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-109 [and (CFM56-2B) 73-080]	SB	Introduction of a New Bearing Seal	20-Jan-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-110 [and (CFM56-3/3B/3C) 73-A129]	SB	Introduction of New Fuel Pump with New Filter Cover Attachment	14-Apr-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-112 [and (CFM56-2B) 73-A079]	SB	Introduction of New Fuel Pump with New Filter Cover Attachment	14-Apr-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	708600-73-113 [and (CFM56-2) 73-A113]	SB	Introduction of New Fuel Pump with New Filter Cover Attachment	24-May-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-114 [and (CFM56-2) 73-114]	SB	Introduction of a New Bearing Seal	20-Jan-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-115 [and (CFM56-2) 73-118]	SB	Introduction of New Preformed Packings in the Fuel Filter	03-May-01	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-115 [and (CFM56-2A) 73-063]	SB	Introduction of New Preformed Packings in the Fuel Filter	03-May-01	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	708600-73-115 [and (CFM56-2B) 73-084]	SB	Introduction of New Preformed Packings in the Fuel Filter	03-May-01	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-115 [and (CFM56-3/3B/3C) 73-137]	SB	Introduction of New Preformed Packings in the Fuel Filter	03-May-01	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-115 [and (CFM56-5) 73-0160]	SB	Introduction of New Preformed Packings in the Fuel Filter	03-May-01	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	708600-73-115 [and (CFM56-5B) 73-0084]	SB	Introduction of New Preformed Packings in the Fuel Filter	03-May-01	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11 -12, -13, -14
--	--	708600-73-115 [and (CFM56-5C) 73-0101]	SB	Introduction of New Preformed Packings in the Fuel Filter	03-May-01	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	708600-73-117 [and (CFM56-3/3B/3C) 73-141]	SB	Introduction of New Fuel Filter	28-May-02	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-118 [and (CFM56-2) 73-119]	SB	Introduction of New Fuel Filter	28-May-02	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-119 [and (CFM56-2B) 73-086]	SB	Introduction of New Fuel Filter	28-May-02	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-120 [and (CFM56-3/3B/3C) 73-0144]	SB	Introduction of New Pump Gears	13-Dec-05	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-121 [and (CFM56-2) 73-0123]	SB	Introduction of New Pump Gears	10-Mar-05	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-122 [and (CFM56-2B) 73-0089]	SB	Introduction of New Pump Gears	10-Mar-05	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	708600-73-124 [and (CFM56-2B) 73-0102]	SB	Introduction of a New Fuel Pump with a New Filter Bowl Cover	04-Jul-17	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11 73-11-12
--	--	714900-73-100 [and (CFM56-5C) 73-040]	SB	Inspection of Impeller Nut	01-Oct-95	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	714900-73-101 [and (CFM56-5) 73-0126]	SB	Conversion of Bronze Bearings to Aluminum/ Bronze Bearings	15-Oct-96	25-Oct-06	2	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	714900-73-102 [and (CFM56-5) 73-134]	SB	Spare Parts Release (Relief Valve Packing)	15-Aug-97	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	714900-73-102 [and (CFM56-5B) 73-053]	SB	Spare Parts Release (Relief Valve Packing)	15-Aug-97	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	714900-73-102 [and (CFM56-5C) 73-069]	SB	Spare Parts Release	15-Aug-97	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	714900-73-103 [and (CFM56-5) 73-139]	SB	Spare Parts Release (Oversize Bearings)	30-Oct-98	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	714900-73-104 [and (CFM56-5) 73-147]	SB	Introduction of a New Bearing Seal	20-Jan-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	714900-73-106 [and (CFM56-5) 73-A143]	SB	Introduction of New Fuel Pump with New Filter Cover Attachment	09-Apr-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	714900-73-107 [and (CFM56-5B) 73-A0062]	SB	Introduction of New Fuel Pump with New Filter Cover Attachment	13-Apr-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	714900-73-108 [and (CFM56-5C) 73-A0078]	SB	Introduction of New Fuel Pump with New Filter Cover Attachment	13-Apr-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	714900-73-109 [and (CFM56-5B) 73-0067]	SB	Introduction of a New Bearing Seal	20-Jan-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	714900-73-110 [and (CFM56-5C) 73-0084]	SB	Introduction of a New Bearing Seal	20-Jan-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	714900-73-111 [and (CFM56-5) 73-155]	SB	Introduction of Improved Shaft Seal	22-Feb-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	714900-73-111 [and (CFM56-5B) 73-078]	SB	Introduction of Improved Shaft Seal	22-Feb-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	714900-73-111 [and (CFM56-5C) 73-0094]	SB	Introduction of Improved Shaft Seal	22-Feb-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	714900-73-112 [and (CFM56-5B) 73-0107]	SB	Introduction of New Fuel Filter	28-May-02	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	714900-73-112 [and (CFM56-5C) 73-0119]	SB	Introduction of New Fuel Filter	28-May-02	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	714900-73-113 [and (CFM56-5) 73-0177]	SB	Introduction of New Fuel Filter	28-May-02	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	714900-73-114 [and (CFM56-5C) 73-0160]	SB	Introduction of New Pump Gears	13-Dec-04	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	714900-73-115 [and (CFM56-5) 73-0192]	SB	Introduction of New Pump Gears	13-Dec-04	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	714900-73-116 [and (CFM56-5B) 73-0129]	SB	Introduction of New Pump Gears	13-Dec-04	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	724400-73-100 [and (CFM56-5B) 73-027]	SB	Inspection of Impeller Nut	01-Oct-95	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	724800-79-002	SB	Upgrade of Pump Assembly Configuration	15-Jan-02	--	--	--	Eaton Euclid	59875	CMM Ref. 79-21-03
--	--	828300-73-101 [and (CFM56-7B) 73-A034]	SB	Introduction of New Fuel Pump with New Filter Cover Attachment	15-Apr-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	828300-73-102 [and (CFM56-7B) 73-0052]	SB	Introduction of a New Impeller Drive Shaft and Impeller Drive Shaft Preformed Packing	30-Oct-00	20-Aug-03	1	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	828300-73-103 [and (CFM56-7B) 73-0078]	SB	Introduction of New Fuel Filter	28-May-02	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	828300-73-104 [and (CFM56-7B) 73-0107]	SB	Inspection of Pump Cover	20-Sep-04	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	828300-73-105 [and (CFM56-7B) 73-0118]	SB	Introduction of New Main Fuel Pump with a New Pump Cover	14-Nov-05	23-Feb-06	1	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	828300-73-106 [and (CFM56-7B) 73-0164]	SB	Spare Parts Release for CFM56-7B CMM	19-Feb-16	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	828300-73-107 [and (CFM56-7B) 73-0209]	SB	Replacement of Main Fuel Pump	18-Feb-15	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	828300-73-108 [and (CFM56-7B) 73-0212]	SB	Introduction of a New Fuel Pump with a New Shaft Seal	25-Aug-15	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	828300-73-109 [and (CFM56-7B) 73-0225]	SB	Replacement of the Filter By-pass Retaining Ring on a Specific Batch of Pumps	30-May-17	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	828300-73-110 [and (CFM56-2A) 73-0080]	SB	Introduction of a New Filter Bypass Valve Retaining Ring	26-May-17	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-12
--	--	828300-73-110 [and (CFM56-2B) 73-0103]	SB	Introduction of a New Filter Bypass Valve Retaining Ring	26-May-17	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11 73-11-12
--	--	828300-73-110 [and (CFM56-3/3B/3C) 73-0158]	SB	Introduction of a New Filter Bypass Valve Retaining Ring	26-May-17	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-11
--	--	828300-73-110 [and (CFM56-5) 73-0224]	SB	Introduction of a New Filter Bypass Valve Retaining Ring	26-May-17	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13
--	--	828300-73-110 [and (CFM56-5B) 73-0287]	SB	Introduction of a New Filter Bypass Valve Retaining Ring	26-May-17	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	828300-73-110 [and (CFM56-5C) 73-0205]	SB	Introduction of a New Filter Bypass Valve Retaining Ring	26-May-13	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-13 73-11-14
--	--	828300-73-110 [and (CFM56-7B) 73-0221]	SB	Introduction of a new Filter Bypass Valve Retaining Ring	26-May-17	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	828300-73-111 [and (CFM56-7B) 73-0224]	SB	Introduction of a New Fuel Pump with a New Shaft Seal	02-Apr-18	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-15
--	--	82933-73-0002 [and GEnX-1B SB 73-0067]	SB	Introduction of a New or Reworked Main Fuel Pump	07-Dec-17	31-Jan-18	1	--	Eaton Euclid	59875	CMM Ref. 73-11-06
--	--	82933-73-0002 [and GEnX-2B SB 73-0071]	SB	Introduction of a New or Reworked Main Fuel Pump	07-Dec-17	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-06
--	--	82933-73-0003 [and GEnX-2B SB 73-0073]	SB	Introduction of New Main Fuel Pump Strainer	30-Jan-18	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-06
--	--	829500-73-001	SB	Introduction of a New Fuel Pump Model	01-Apr-04	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	829500-73-003 [and CF34-8C-AL SB 73-0043]	SB	Special Fuel Pump Inspection Following Engine Thrust Roll-Back	21-Oct-16	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	829500-73-003 [and CF34-8E-AL SB 73-0032]	SB	Special Fuel Pump Inspection Following Engine Thrust Roll-Back	21-Oct-16	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	830900-79-003	SB	Upgrade of Pump Assembly Configuration	05-Jun-14	--	--	--	Eaton Euclid	59875	CMM Ref. 79-21-03

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	837600-73-001 [and CF34-10E SB 73-0032]	SB	Spare Parts Release, introduction of replacement bearings and housing for repair	06-Feb-15	26-May-15	--	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	837600-73-002 [and CF34-10E SB 73-0028]	SB	Introduction of new fuel pump VIN 837600-6 (2043M12P06) with new relief valve and new shaft seal	12-Feb-16	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	AE2100D3 SB 79-015 724800-79-001	SB	Remove/Replace Pressure Regulator Valves 219032	11/13/1996 11/13/1996	--	--	--	Eaton Euclid	59875	CMM Ref. 79-21-03
--	--	Alison 250 C18 CEB 256 C20 CEB 1261	SB	Machine Fuel Pump Gear Housing	01-Jul-88	--	--	--	Eaton Euclid	59875	CMM Ref. 73-10-10
--	--	Alison 250 C28 CEB 73-2035 C30 CEB 73-3043	SB	Machine Fuel Pump Gear Housing and Pump Cover Assembly	01-Jun-89	--	--	--	Eaton Euclid	59875	CMM Ref. 73-10-09 73-10-12
--	--	CF34-10E SB 73-0013	SB	Introduction of new fuel pump VIN 837600-5 (2043M12P05) with improved inlet strainer	15-Dec-06	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	CF34-10E SB 73-0028 [and 837600-73-002]	SB	Introduction of new fuel pump VIN 837600-6 (2043M12P06) with new relief valve and new shaft seal	12-Feb-16	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	CF34-10E SB 73-0032 [and 837600-73-001]	SB	Spare Parts Release, introduction of replacement bearings and housing for repair	06-Feb-15	26-May-15	1	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	CF34-10E SB 73-A0011	SB	Removal of Strainer from Main Fuel Pump	15-Sep-06	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	CF34-10E SB 73-A0012	SB	Inspection of Main Inlet Strainer Tripod	15-Sep-06	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	CF34-8C SB 73-0023	SB	Introduction of N2 Speed Sensor PN 829549	17-Feb-06	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	CF34-8C SB 73-A0012	SB	Inspection / Replacement of Speed Sensor PN 829599	10-Jul-03	20-Dec-05	1	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	CF34-8C-AL S/B 73-0047 [and 829500-73-004]	SB	Introduction of New Fuel Pump, 829500-9 and -10	28-Jan-19	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	CF34-8C-AL SB 73-0019	SB	Recurring Inspection of the N2 Sensor PN 829599	28-Apr-05	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	CF34-8C-AL SB 73-0043 [and 829500-73-003]	SB	Special Fuel Pump Inspection Following Engine Thrust Roll-Back	25-Oct-16	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	CF34-8E SB 73-0008	SB	Introduction of N2 Speed Sensor PN 829549	10-Feb-06	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	CF34-8E-AL S/B 73-0036 [and 829500-73-004]	SB	Introduction of New Fuel Pump, 829500-9 and -10	28-Jan-19	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	CF34-8E-AL SB 73-0005	SB	Recurring Inspection of the N2 Sensor PN 829599	28-Apr-05	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	CF34-8E-AL SB 73-0032 [and 829500-73-003]	SB	Special Fuel Pump Inspection Following Engine Thrust Roll-Back	25-Oct-16	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 228	SB	TB102200, Installation of New Diffuser	22-Jan-58	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-3
--	--	ESD 228-1	SB	TB102200, Electrical Connector Change	28-Apr-58	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-3

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	ESD 228-2	SB	TB102200-2 and -3, Thrust Washer and Rotor Shaft Replacement	22-Apr-58	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-3
--	--	ESD 228-3	SB	TB102200-2 and -3, Rework of Electrical Lead Sleeving on Lead and Connector Assy.	31-Aug-59	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-3
--	--	ESD 228-4	SB	TB102200-2, Replacement of Electrical Lead Assembly, P/N TB102258	09-Dec-59	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-3
--	--	ESD 228-5	SB	TB102200-2 and -3, Replacement of Bleeder Plug	29-Dec-59	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-3
--	--	ESD 228-6	SB	TB102200, Revise Calibration Test Limits	24-Jun-65	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-3
--	--	ESD 262	SB	Install Fuel Control Pilot Guide	15-Apr-64	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-1	SB	Rework Pressurized Bearings	16-Apr-64	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-10	SB	Changes to Disassembly, Inspection, Reassembly, and Test Procedures	06-Aug-65	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-11	SB	Rework Seal Carrier Assy., P/N 206327-1	20-Sep-65	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-12	SB	Stud Replacement	30-Nov-65	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-13	SB	Replace Impeller, P/N 209226	14-Apr-66	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-14	SB	Replace Fuel Control Mounting Studs	01-Feb-67	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-15	SB	Inspection of Impeller Parallelism	01-Jun-67	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-16	SB	Not Issued	--	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-17	SB	Replace Packing, P/N 90925-19	19-Jul-67	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-18	SB	Revise Test Procedure	13-Sep-67	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-19	SB	Erosion Relief Gears	14-Sep-67	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-2	SB	Replace Fixed and Pressurized Bearings	17-Apr-64	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-20	SB	Increase Impeller Nut Torque	12-Dec-67	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-21	SB	Tang Drive Gears	08-Feb-68	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-22	SB	Replace Impeller, P/N 209706-1	01-Apr-68	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	ESD 262-23	SB	Replace Impeller Bypass Valve Stem Assembly, P/N 206363-1	14-Jun-68	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-24	SB	Install Stub Bracket	04-Oct-68	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-25	SB	Rework Impeller Bypass Strainer Assembly, P/N 206377-1	24-Feb-69	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-26	SB	Replace Filter Bypass Valve Assembly P/N 206364-1	02-Jun-69	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-27	SB	Replace Rotating Seal Ring, P/N 208236 and Spring Retaining Washer, P/N 208239	17-Nov-70	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-28	SB	Rework Spline Shaft, P/N 208235	01-May-72	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-29	SB	Rework Filter Bypass Valve Guide Assembly, P/N 207127-1	01-Nov-71	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-3	SB	Incorporate New Gear Housing Assembly	29-May-64	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-30	SB	Conversion of P/N 243600, P/N 358200 and P/N 371900 to 378200	01-Sep-72	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-31	SB	Replace Control Shaft, P/N 207149	01-May-72	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-32	SB	Rework Filter Bypass Valve Guide Assembly, P/N 214242-1	01-Dec-76	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-33	SB	Chrome Plating of Main Drive Shaft	01-Sep-78	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-34	SB	Rework Impeller, Impeller Gear Train Plate Assembly and Impeller Cover Assembly	15-Jan-80	30-Nov-92	3	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-35	SB	Install New Studs on Inlet Pad	01-Jul-80	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-36	SB	Replace Impeller Washer P/N 209707 with New Spring Washer, P/N 216283	30-Apr-81	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-37	SB	Replace Impeller Drive Gear Assembly and Control Shaft with New Impeller Drive Gear Assembly P/N 216652 or P/N 216653	01-Jul-82	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-38	SB	Introduction of Longer Inlet Flange Studs	20-Nov-90	01-Sep-92	1	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-39	SB	Introduction of New Main Drive Shaft	30-Apr-97	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-4	SB	Incorporate New Impeller Drive Gear Assembly	29-May-64	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-40	SB	Introduction of New Control Drive Shaft	04-May-98	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-41	SB	Introduction of Improved Fuel Pump	20-Nov-02	15-Sep-08	2	--	Eaton Euclid	59875	CMM Ref. 73-11-1

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	ESD 262-5	SB	Rework Filter Cover Assembly	29-May-64	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-6	SB	Replace Gears, Fixed and Pressurized Bearings	26-Aug-64	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-7	SB	Rework Fixed and Pressurized Bearings	26-Aug-64	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-8	SB	Replace Impeller, P/N 207216	02-Jul-65	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 262-9	SB	Replace Seal Loading Spring, P/N 206328	06-Aug-65	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-1
--	--	ESD 263	SB	Rework of Rotor and Shaft Assembly and Prime Pump Element	19-Oct-64	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-1
--	--	ESD 263-1	SB	Incorporation of New Impeller Nut, P/N 209379	01-Nov-65	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-1
--	--	ESD 263-2	SB	Replacement of Rotor Shaft	01-Nov-65	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-1
--	--	ESD 263-3	SB	Rework of Prime Pump Element	30-Sep-66	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-1
--	--	ESD 263-4	SB	Prime Pump Inlet Port and Exhaust Port Wear Limits	12-Jan-68	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-1
--	--	ESD 263-5	SB	Improved Motor and Rework of Prime Pump Element and Shaft Bearings (All 258000-3 and 382300-1)	15-Jan-75	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-5
--	--	ESD 263-6	SB	Rework Volute Housing Assembly and Filter	15-Jun-76	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-5
--	--	ESD 263-7	SB	Rework of Impeller and Volute Housing	30-Apr-81	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-5
--	--	ESD 268	SB	Addition of Water Drain Hole in Volute Housing	15-Feb-66	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-2
--	--	ESD 268-1	SB	Application of an Improved Water Resistant Coating to the Rotor and Stator	10-Jan-67	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-2
--	--	ESD 270-1	SB	Replace Transfer Valve Assembly P/N 211260-1	09-Feb-70	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-10	SB	Replace Filter Bolt, P/N 211224, and Filter Bolt Nut, P/N 211277	15-Feb-72	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-11	SB	Replace Filter Bypass and Heater Bypass Valve Springs, P/N 212102	15-Feb-72	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-12	SB	Replace Hydraulic Stage Drive Shaft P/N 214505, Gear Train Driven Gear P/N 214085, and Matched Set Gears P/N 212612-1	15-May-72	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-13	SB	Grease Lubricated Main Stage and Boost Stage Gear Splines	01-Jul-72	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-14	SB	Rework Bearing Retainer Plate Assembly, P/N 212795-1	15-Jun-72	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	ESD 270-15	SB	Install Support Bracket	15-Jun-72	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-16	SB	Inspection and Rework of Locking Nut, P/N 212767	15-Jun-72	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-17	SB	Inspect Filter and Rework Element Cavity in Pump Housing Assembly	15-Jun-72	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-18	SB	Replace Booster Stage Drive Shaft P/N 214317-1 and Boost Stage Shaft P/N 212336	15-Jun-72	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-19	SB	Inspection and Rework of Gear Train Plate P/N 212795-1 and Impeller Cover Assembly, P/N's 212849-1 and 212849-2	01-Dec-72	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-2	SB	Replace Gear Train Driver Gear P/N 212806	22-Apr-70	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-20	SB	Replace Cover Assembly, P/N 212849-1 -212849-3, and Rework Plate and Carrier Assembly, P/N 214320-1	01-Dec-72	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-21	SB	Replace Hydraulic Stage Drive Shaft, P/N 214325	01-Dec-72	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-22	SB	Incorporate Grease Lubricated Hydraulic Shaft	01-Sep-73	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-23	SB	Replace O-Ring Packing, P/N 210690	01-Oct-73	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-24	SB	Replace Hydraulic Drive Shaft, Hydraulic Stage Driver Gear, and Gear Train Driven Gear	01-Sep-74	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-25	SB	Conversion of Models 373400 and 382400 to Model 389400	15-Feb-75	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-26	SB	Inspect Hydraulic Drive Shaft Splines	15-Jul-75	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-27	SB	Align Hydraulic Stage and Boost Drive Shafts	01-Oct-75	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-28	SB	Replace Hydraulic Stage Shaft, Hydraulic Stage Driver Gear and Gear Train Driven Gear with No-Spline Drive System	15-Jan-77	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-29	SB	Replace Main Drive Shaft	01-Mar-79	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-3	SB	Control Compression of Impeller Bypass Screen Assembly P/N 212630-1	18-Dec-70	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-30	SB	Replace Main Stage Gears	15-Mar-79	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-31	SB	Rework Nut, Spanner P/N 215472	01-Sep-79	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-32	SB	Install Splined Sleeve in Gear Train Drive Section	15-Feb-81	01-Apr-85	3	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-33	SB	Conversion of Model 389400 to Model 703000	30-Apr-81	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	ESD 270-34	SB	Inspection of Shroud Section of Impeller P/N 214713	15-Apr-85	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-35	SB	Replace Bronze Bearing P/N 217049 with Carbon Bearing P/N 217682	01-Apr-86	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-36	SB	Replace Gear Train Driver and Driven Gears Made of Nitralloy with Gear Train Driver and Driven Gears made of CPM-10V Material	01-Jul-86	01-Oct-88	1	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-37	SB	Inspection of Fuel Pump and Related Parts for Wear	01-Mar-87	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-38	SB	Introduce Argo-Tech Main Fuel Gear Pump Model 715000	15-Mar-87	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-39	SB	Replace Hydraulic Stage Driven Gear Bearings	15-Sep-87	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-4	SB	Replace Gear Train Driver Gear, P/N 213824 and Driven Gear, P/N 212793	18-Jan-71	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-40	SB	Replace Main Stage Gears	01-Dec-87	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-41	SB	Provide Fluorosilicone "O" Ring Packing In Drive Shaft Seal and Housing Split Line Area	15-Mar-88	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-42	SB	Replace Hydraulic Stage Gears	01-Jul-88	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-43	SB	Machine Main Gear Housing Mounting Flange to Accept New QUAD Ring	15-Dec-89	21-Aug-93	2	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-44	SB	Introduction of New Grease Lubricant	15-Jun-90	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-45	SB	Introduction of Hydraulic Drive Gear Spacer Wedge P/N 218522	01-Aug-91	18-Jan-93	1	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-46	SB	Replacement of Preformed Packings	06-Oct-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-47	SB	Introduction of Improved Stationary Shaft Seal	06-Aug-00	19-Mar-02	2	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-48	SB	Introduction of New Boost Stage Shaft and Boost Stage & Control Drive Shaft	01-May-01	30-Jul-02	1	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-5	SB	Replace Impeller Bypass Valve Spring, P/N 210725	18-Jan-71	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-6	SB	Replace Impeller Bypass Screen Assembly, P/N 212630-1	16-Aug-71	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-7	SB	Rework Drive Shaft, P/N 212334	01-Nov-71	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-8	SB	Revise Port Markings on Gear Housing Assembly, P/N 211304-1	15-Feb-72	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01
--	--	ESD 270-9	SB	Replace Main Stage Bearings, P/N 212285-1, P/N 212288-1 and P/N 212289-1	15-Feb-72	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-01

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	ESD 271-1	SB	Rework Control Drive Shaft, P/N 215140	01-Mar-76	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	ESD 271-10	SB	Introduction of New Hydraulic Drive Shaft	31-Dec-90	17-Jan-91	1	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	ESD 271-11	SB	Introduction of New Grease Lubricant	02-Jan-91	15-Apr-91	1	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	ESD 271-12	SB	Introduction of Main Fuel Gear Pump Models	01-May-94	01-Apr-95	1	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	ESD 271-13	SB	Installation Instructions of Improved Erosion Wedge Kit	30-Nov-98	29-Jan-99	1	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	ESD 271-2	SB	Conversion of Model 390600 Pump to 386900 Pump	01-May-79	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	ESD 271-3	SB	Conversion of Model 386900 Pump to 390600 Pump	01-May-79	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	ESD 271-4	SB	Replace Main Stage Gear	01-Apr-80	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	ESD 271-5	SB	Replace Main Drive Shaft	30-Apr-81	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	ESD 271-6	SB	Replace Washer P/N AM960-516 (90790-6)	01-Jun-81	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	ESD 271-7	SB	Install "O" Ring Seal on Hydraulic Housing	01-Jun-81	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	ESD 271-8	SB	Modification to Main Stage Bearings to Add Pressure Pads for Better Lubrication Flow	15-Feb-83	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	ESD 271-9	SB	Replace Socket Head Cap Screw P/N 93426-1	01-Aug-86	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-02
--	--	ESD 272-1 (706600-73-1)	SB	Machining of Fuel Pump Body	01-Oct-85	15-Nov-92	1	--	Eaton Euclid	59875	CMM Ref. 73-10-04
--	--	ESD 273-1	SB	Machining of Fuel Pump Body	01-May-85	--	--	--	Eaton Euclid	59875	CMM Ref. 73-10-05
--	--	ESD 273-2	SB	Introduction of New Stationary Shaft Seal	20-May-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-10-05
--	--	ESD 274-1 (710500-73-1)	SB	Machining of Fuel Pump Body	01-Oct-85	--	--	--	Eaton Euclid	59875	CMM Ref. 73-10-08
--	--	ESD 274-2 (710500-73-2)	SB	Add Packing to Main Drive Shaft	30-Nov-90	--	--	--	Eaton Euclid	59875	CMM Ref. 73-10-08
--	--	ESD 274-3 (710500-73-3)	SB	Inspection/Rework of Motive Flow Port	30-Apr-92	15-Jan-04	1	--	Eaton Euclid	59875	CMM Ref. 73-10-08
--	--	ESD 274-4 (710500-73-4)	SB	Introduction of New Pump Model, 845400-1	10-Oct-06	--	--	--	Eaton Euclid	59875	CMM Ref. 73-10-08
--	--	ESD 275-1	SB	Replace Main Stage Gears	01-Sep-87	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-04

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	ESD 275-10	SB	Introduction of Main Fuel Gear Pump Model 722100	06-Apr-92	31-May-92	1	--	Eaton Euclid	59875	CMM Ref. 73-11-04
--	--	ESD 275-11	SB	Introduction of New Stationary Shaft Seal	21-Oct-93	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-04
--	--	ESD 275-12	SB	Introduction of Main Fuel Gear Pump Model 825500	11-Jul-94	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-04
--	--	ESD 275-13	SB	Introduction of Alternate O-Ring Packings	01-Sep-94	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-04
--	--	ESD 275-14	SB	Introduction of New Main Stage Bearings	31-Oct-94	28-Jul-95	2	--	Eaton Euclid	59875	CMM Ref. 73-11-04
--	--	ESD 275-15	SB	Introduction of New Filter Cover Locking Nuts	05-Jan-96	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-04
--	--	ESD 275-16	SB	Replacement of Stationary Shaft Seal Preformed Packing	30-Apr-96	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-04
--	--	ESD 275-2	SB	Introduction of New Pump Fuel Filter Element P/N 218231	15-Jan-89	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-04
--	--	ESD 275-3	SB	Introduction of New Pump Bypass Valve P/N 217493 and O-Ring P/N M87175-1-132	01-Apr-89	15-Jul-89	1	--	Eaton Euclid	59875	CMM Ref. 73-11-04
--	--	ESD 275-4	SB	Introduction of Special Through-Bolts for Filter Cover	01-Jun-89	15-Jul-89	1	--	Eaton Euclid	59875	CMM Ref. 73-11-04
--	--	ESD 275-5	SB	Instruction for Inscribing Identification on Fuel Filter	15-Aug-89	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-04
--	--	ESD 275-6	SB	Introduce a New Filter and New Filter Cover, Which Provides a Filter Non-Interchangeability Feature.	15-Jun-90	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-04
--	--	ESD 275-7	SB	Introduction of Anti-Fretting Pad	15-Jul-90	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-04
--	--	ESD 275-8	SB	Introduction of New Grease Lubricant	15-Aug-90	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-04
--	--	ESD 275-9	SB	Introduction of Main Fuel Gear Pump Model 721000	15-Jan-91	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-04
--	--	ESD 277-1	SB	Replace Filter Bypass Valve Spring and Cover and the Fuel Filter Element	01-Jan-89	--	--	--	Eaton Euclid	59875	CMM Ref. 73-10-03
--	--	ESD 278-1	SB	Inspection/Rework of Motive Flow Port	30-Apr-92	15-Jan-04	1	--	Eaton Euclid	59875	CMM Ref. 73-10-09
--	--	ESD 280-1	SB	Replacement of Impending By-Pass Filter Indicator	15-Jun-90	--	--	--	Eaton Euclid	59875	CMM Ref. 49-30-01
--	--	ESD 280-2	SB	Introduction of New Preformed Packings on Port Cover	02-Apr-91	--	--	--	Eaton Euclid	59875	CMM Ref. 49-30-01
--	--	ESD 280-3	SB	Inspection/Rework of Motive Flow Port	02-Apr-91	31-Oct-95	2	--	Eaton Euclid	59875	CMM Ref. 49-30-01
--	--	ESD 280-4	SB	Rework of Motive Flow Port	31-Jul-96	--	--	--	Eaton Euclid	59875	CMM Ref. 49-30-01

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	ESD 280-5	SB	Introduction of New Grease Lubricant	31-Jul-96	--	--	--	Eaton Euclid	59875	CMM Ref. 49-30-01
--	--	ESD 280-6	SB	Introduction of Alternate O-Ring Part Numbers	10-Mar-98	05-Sep-98	1	--	Eaton Euclid	59875	CMM Ref. 49-30-01
--	--	ESD 281-1	SB	Introduction of Main Fuel Gear Pump Model 825600	01-Oct-95	--	--	--	Eaton Euclid	59875	CMM Ref. 73-10-12
--	--	ESD 281-2	SB	Introduction of New Stationary Shaft Seal	20-May-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-10-12
--	--	ESD 282-1 [and GE90 S/B 73-0013]	SB	Rework of VIN: 828500-1 to VIN: 828500-2	15-Jan-96	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-03
--	--	ESD 282-2	SB	Replacement of Interstage Strainer Performed Packing	15-Jan-96	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-03
--	--	ESD 282-3	SB	NEVER ISSUED	--	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-03
--	--	ESD 282-4 [and GE90 S/B 73-0058]	SB	Introduction of Improved Fuel Pump VIN: 828500-3 (GE 1689M10P09)	29-Sep-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-03
--	--	ESD 283-1	SB	Upgrade Instructions Main Fuel Pump 721400-1 to 721400-2 (RR RB211 Mod 73-B246)	30-Sep-95	--	--	--	Eaton Euclid	59875	CMM Ref. 73-12-11
--	--	ESD 283-2	SB	Upgrade Instructions Main Fuel Pump 721400-2 to 721400-3(RR RB211 Mod 73-C373)	07-Jan-98	--	--	--	Eaton Euclid	59875	CMM Ref. 73-12-11
--	--	ESD 283-3	SB	Replacement of the Inlet Screen Assembly(RR RB211 Mod 73- C583)	24-Jul-98	--	--	--	Eaton Euclid	59875	CMM Ref. 73-12-11
--	--	ESD 283-4	SB	Deletion of the Inlet Screen Assembly (R.R. RB211 MOD 73-C999)	12-Jul-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-12-11
--	--	ESD 283-5	SB	Introduction of a Pressure Relief Valve Featuring a Revised 'O' Ring Seal and Back-up Ring on the Main Engine Fuel Pump (RR RB211 MOD 73-C999)	20-Oct-00	--	--	--	Eaton Euclid	59875	CMM Ref. 73-12-11
--	--	ESD 284-1	SB	Introduction of New Main Stage Bearings	05-Jan-96	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-05
--	--	ESD 284-2	SB	Introduction of New Filter Cover Locking Nuts	05-Jan-96	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-05
--	--	ESD 284-3	SB	Replacement of Stationary Shaft Seal Performed Packing	01-May-96	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-05
--	--	ESD 285-1	SB	Recall/Replacement of Main Fuel Pump, Impeller Drive Shafts	31-Mar-97	--	--	--	Eaton Euclid	59875	CMM Ref. 73-16-01
--	--	ESD 285-2	SB	Replacement of the Filter Bypass Valve Spring	21-Sep-06	--	--	--	Eaton Euclid	59875	CMM Ref. 73-16-01
--	--	ESD 288-1	SB	Introduction of New Stationary Shaft Seal	20-May-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-10-10
--	--	ESD 289-1	SB	Introduction of New Stationary Shaft Seal	01-Jun-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-10-11
--	--	ESD 291-1 (398000-28-1)	SB	Inspection & Recall of Argo-Tech Repaired Units	20-Jan-03	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-6

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
--	--	ESD 291-2 (398000-28-2)	SB	Introduction of new pump model, 398000-2	08-Nov-07	13-Nov-15	2	--	Eaton Euclid	59875	CMM Ref. 28-20-6
--	--	ESD 293-1 (831100-28-1)	SB	Introduction Of PN: 831100-2	15-Dec-99	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-07
--	--	ESD 293-2 (831100-28-2)	SB	Introduction of PN: 831100-3 & PN: 831100-4	27-Jan-04	--	--	--	Eaton Euclid	59875	CMM Ref. 28-20-07
--	--	ESD 295-1 [and RB211-73-F123]	SB	Introduction Of A Revised HP Fuel Pump Featuring A Change Of Material For The Sealing Rings And Modified Cooling Ring Grooves (Argo-Tech)	20-Sep-06	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-21
--	--	ESD 295-2 [and RB211-73-G544]	SB	Deletion of the Inlet Screen Assembly (R.R. RB211 MOD 73-G544)	11-May-11	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-21
--	--	GE90 SB 73-0013 [and ESD 282-1]	SB	Rework of VIN: 828500-1 to VIN: 828500-2	23-Oct-95	19-Jan-96	1	--	Eaton Euclid	59875	CMM Ref. 73-11-03
--	--	GE90 SB 73-0124	SB	Main Fuel Pump Interstage Strainer Assembly Inspection	09-Oct-12	02-May-18	6	--	Eaton Euclid	59875	CMM Ref. 73-11-03
--	--	GE90-100 SB 73-0009	SB	Engine Fuel and Control - Fuel Pump (72-00-05) - Casting Change	18-Feb-05	15-Mar-12	1	--	Eaton Euclid	59875	CMM Ref. 73-11-77
--	--	GE90-100 SB 73-0070	SB	Main Fuel Pump Interstage Strainer Assembly Inspection	10-May-12	02-May-18	7	--	Eaton Euclid	59875	CMM Ref. 73-11-77
--	--	GEnX-1B SB 73-0067 [and 82933-73-0002]	SB	Introduction of a New or Reworked Main Fuel Pump	01-Feb-18	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-06
--	--	GEnX-2B SB 73-0071 [and 82933-73-0002]	SB	Introduction of a New or Reworked Main Fuel Pump	07-Dec-17	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-06
--	--	GEnX-2B SB 73-0073 [and 82933-73-0003]	SB	Introduction of New Main Fuel Pump Strainer	15-Feb-18	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-06
--	--	Mod 73-B946	SB	Engine Fuel and Control - HP Fuel Pump - Introduction of a HP Fuel Pump Assembly supplied by Argo-Tech Company - Mod 73-B946	27-Sep-99	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-21
--	--	RB.211-73-G070	SB	Life Policy - Non-Modification Service Bulletin - Non - Mod 73-G070. Establishes recommended life limits	11-Dec-08	03-Nov-10	1	--	Eaton Euclid	59875	CMM Ref. 73-12-11 73-12-12
--	--	RB211-73-F123 [and ESD 295-1]	SB	Introduction Of A Revised HP Fuel Pump Featuring A Change Of Material For The Sealing Rings And Modified Cooling Ring Grooves (Argo-Tech)	11-Sep-06	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-21
--	--	RB211-73-G544 [and ESD 295-2]	SB	Deletion of the Inlet Screen Assembly (R.R. RB211 MOD 73-G544)	06-May-11	--	--	--	Eaton Euclid	59875	CMM Ref. 73-11-21
--	--	CFM56-7B SB 73-0234	SB	Introduction of a High Time Scheduled Overhaul on the Main Fuel Pump	24-Jul-19	--	--	--	Eaton Euclid	59875	--
--	--	CFM56-7B SB 73-0235	SB	Introduction of a Scheduled Overhaul on the Main Fuel Pump	24-Jul-19	--	--	--	Eaton Euclid	59875	--
15886-3	--	32-40-01	CMM	Solenoid Parking Brake Shut-Off	02-May-11	07-Sep-11	Rev 1	--	Eaton Glenolden	16780 & 97484	OK
1A1869	--	79-22-06	CMM	Chip Collector	--	Oct 2/13	Rev 4	CF6	Eaton Glenolden	16780 & 97484	OK
1A475	--	79-22-06	CMM	Chip Collector	--	Oct 2/13	Rev 4	CF6	Eaton Glenolden	16780 & 97484	OK

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
1A6473	--	79-22-02	CMM	Chip Detector w/Self-Closing Valve	--	Nov 19/99	Rev 2	PW4000	Eaton Glenolden	16780 & 97484	OK
1A6505	--	79-22-02	CMM	Chip Detector w/Self-Closing Valve	--	Nov 19/99	Rev 2	PW4000	Eaton Glenolden	16780 & 97484	OK
1A6618	--	79-22-04	CMM	Chip Collector w/Self-Closing Valve	Oct 15/92	Oct 15/92	Initial	APU	Eaton Glenolden	16780 & 97484	OK
1A6794	--	79-22-10	CMM	Chip Collector w/Self-Closing Valve	Dec 15/97	Dec 15/97	Initial	V2500	Eaton Glenolden	16780 & 97484	OK
1A6902	--	79-22-07	CMM	Chip Collector w/Self-Closing Valve	Mar 15/95	Mar 15/95	Initial	JT9D	Eaton Glenolden	16780 & 97484	OK
1A6925	--	79-22-07	CMM	Chip Collector w/Self-Closing Valve	Mar 15/95	Mar 15/95	Initial	JT9D	Eaton Glenolden	16780 & 97484	OK
1A6945	--	79-22-09	CMM	Chip Collector w/Self-Closing Valve	--	Jan 3/00	Rev 2	JT8D	Eaton Glenolden	16780 & 97484	OK
1A6947	--	79-22-09	CMM	Chip Collector w/Self-Closing Valve	--	Jan 3/00	Rev 2	JT8D	Eaton Glenolden	16780 & 97484	OK
1A6948	--	79-22-09	CMM	Chip Collector w/Self-Closing Valve	--	Jan 3/00	Rev 2	JT8D	Eaton Glenolden	16780 & 97484	OK
1A7091	--	79-22-12	CMM	Chip Collector w/Self-Closing Valve	Sep 15/96	Sep 15/96	Initial	JT9D	Eaton Glenolden	16780 & 97484	OK
1A7476	--	79-22-16	CMM	Chip Collector w/Self-Closing Valve	Dec 15/97	Dec 15/97	Initial	BR715	Eaton Glenolden	16780 & 97484	OK
1A7802	--	79-22-16	CMM	Chip Collector w/Self-Closing Valve	Dec 15/97	Dec 15/97	Initial	BR715	Eaton Glenolden	16780 & 97484	OK
1B6488	--	79-22-03	CMM	Chip Detector w/ Self-Closing Valve	Jul 15/93	Jul 15/93	Initial	PW4000	Eaton Glenolden	16780 & 97484	OK
1B6550	--	79-21-52	CMM	Chip Detector	--	Oct 20/00	Rev 1	CFM56	Eaton Glenolden	16780 & 97484	OK
1B6820	--	79-23-00	CMM	Chip Detector	Feb 28/94	Feb 28/94	Initial	AE2100	Eaton Glenolden	16780 & 97484	OK
1B7802	--	79-22-46	CMM	Chip Detector	--	Jan 29/04	Rev 1	TRENT 500/900	Eaton Glenolden	16780 & 97484	OK
1B7830	--	63-41-20	CMM	Chip Detector w/Adapter	Feb 15/02	Feb 15/02	Initial	AB139	Eaton Glenolden	16780 & 97484	OK
1B7839	--	63-41-20	CMM	Chip Detector w/SCV	Feb 15/02	Feb 15/02	Initial	AB139	Eaton Glenolden	16780 & 97484	OK
1B9102	--	79-22-48	CMM	Chip Detector	May 15/11	May 15/11	Initial	TRENT 700	Eaton Glenolden	16780 & 97484	OK
1D1934	--	79-24-01	CMM	Full Flow Debris Monitor	--	Apr 15/94	Reissue	ALF502/ LF507	Eaton Glenolden	16780 & 97484	OK
1D2316	--	79-24-01	CMM	Full Flow Debris Monitor	--	Apr 15/94	Reissue	ALF502/ LF507	Eaton Glenolden	16780 & 97484	OK

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
1D6549	--	79-21-51	CMM	Debris Monitor	--	Mar 7/12	Rev 3	CFM56	Eaton Glenolden	16780 & 97484	OK
1D7829	--	63-41-20	CMM	Debris Monitor	Feb 15/02	Feb 15/02	Initial	AB139	Eaton Glenolden	16780 & 97484	OK
1F2870-3	--	79-23-00	CMM	Lubriclone	Feb 28/94	Feb 28/94	Initial	AE2100	Eaton Glenolden	16780 & 97484	OK
1F2976 Series	--	79-21-39	CMM	DMS Separator	--	Oct 23/19	Rev 3	GE90	Eaton Glenolden	16780 & 97484	See Corrected Rev and Rev Date
1F6875	--	79-23-05	CMM	Lubriclone	--	Mar 7/12	Rev 1	AE1107C	Eaton Glenolden	16780 & 97484	OK
1F8550	--	79-11-24	CMM	DMS Separator	--	Apr 14/04	Rev 1	GE90-115B	Eaton Glenolden	16780 & 97484	OK
1F8664-4	--	79-36-13	CMM	ODM Separator	Jun 30/06	Jun 30/06	Initial	GP7200	Eaton Glenolden	16780 & 97484	OK
1F8852	--	79-11-10	CMM	ODMS Separator	--	Apr 04/22	Rev 1	TRENT 1000/TRENT 7000	Eaton Glenolden	16780 & 97484	OK
1F8962	--	79-21-20	CMM	DMS Separator	--	Nov 14/17	Rev 1	GENx	Eaton Glenolden	16780 & 97484	See Corrected Rev and Rev Date
1F9114	--	79-34-12	CMM	Oil Debris Monitoring Separator	May 5/16	May 5/16	Initial	TRENT XWB	Eaton Glenolden	16780 & 97484	OK
1F9128	--	79-36-05	CMM	Oil Debris Monitoring Separator	--	Oct 27/16	Rev 4	LEAP	Eaton Glenolden	16780 & 97484	See Corrected Rev Date
1F9243	--	79-36-05	CMM	Oil Debris Monitoring Separator	--	Oct 27/16	Rev 4	LEAP	Eaton Glenolden	16780 & 97484	See Corrected Rev Date
1F9298-1	--	79-33-03	CMM	DMS Oil Separator	Apr 26/21	Apr 26/21	Initial	GE9x	Eaton Glenolden	16780 & 97484	Added 02-Feb-2022
1F9298-2	--	79-23-01	CMM	Tank Pressurizing Valve	Apr 26/21	Apr 26/21	Initial	GE9x	Eaton Glenolden	16780 & 97484	Added 02-Feb-2022
1G2977 Series	--	79-21-38	CMM	DMS Sensor	--	Jun 26/17	Rev 2	GE90	Eaton Glenolden	16780 & 97484	See Corrected Rev and Rev Date
1G8085	--	79-36-11	CMM	DMS Sensor	Jun 30/06	Jun 30/06	Initial	GP7200	Eaton Glenolden	16780 & 97484	OK
1G8842	--	79-21-30	CMM	DMS Sensor	--	Jun 27/17	Rev 1	GENx	Eaton Glenolden	16780 & 97484	See Corrected Rev and Rev Date
1G8977	--	79-21-30	CMM	ODMS Sensor	--	May 10/16	Rev 2	TRENT 1000/TRENT XWB	Eaton Glenolden	16780 & 97484	See Corrected Rev Date
1G9205	--	79-36-10	CMM	Oil Debris Monitoring Sensor	--	Apr 14/20	Rev 5	LEAP	Eaton Glenolden	16780 & 97484	See Corrected Rev Date
1G9215	--	79-36-10	CMM	Oil Debris Monitoring Sensor	--	Apr 14/20	Rev 5	LEAP	Eaton Glenolden	16780 & 97484	Added 27-Jul-2021
1G9244	--	79-36-10	CMM	Oil Debris Monitoring Sensor	--	Apr 14/20	Rev 5	LEAP	Eaton Glenolden	16780 & 97484	Added 27-Jul-2021

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
1G9245	--	79-36-10	CMM	Oil Debris Monitoring Sensor	--	Apr 14/20	Rev 5	LEAP	Eaton Glenolden	16780 & 97484	See Corrected Rev Date
1G9255	--	79-21-31	CMM	QDM Sensor	--	Apr 16/19	Initial	TRENT 7000	Eaton Glenolden	16780 & 97484	See Corrected Rev , Rev Date and Platfor Number
1G9261	--	79-33-01	CMM	DMS Sensor	Apr 27/22	Apr 27/22	Rev 1	GE9x	Eaton Glenolden	16780 & 97484	Added 26-May-2022
1H118-45	--	63-41-10	CMM	QDM Signal Conditioner	--	Mar 31/98	Rev 1	EH101	Eaton Glenolden	16780 & 97484	OK
1H2983 Series	--	79-21-41	CMM	DMS Conditioner	--	Feb11/20	Rev 2	GE90	Eaton Glenolden	16780 & 97484	See Corrected Rev and Rev Date
1H8086	--	79-36-12	CMM	ODM Conditioner	--	Nov 07/19	Rev 1	GP7200	Eaton Glenolden	16780 & 97484	See Corrected Rev and Rev Date
1H8843	--	79-21-40	CMM	DMS Conditioner	--	Nov 15/19	Rev 1	GEnx	Eaton Glenolden	16780 & 97484	See Corrected Rev and Rev Date
1H9026	--	79-21-40	CMM	ODMS Signal Conditioner	Nov 18/09	Nov 18/09	Initial	TRENT 1000	Eaton Glenolden	16780 & 97484	OK
1H9181	--	79-34-14	CMM	Oil Debris Signal Conditioner	Feb 25/15	Feb 25/15	Initial	TRENT XWB	Eaton Glenolden	16780 & 97484	OK
1H9193	--	79-36-20	CMM	Oil Debris Monitoring Signal Conditioner	--	Nov 08/21	Rev 3	LEAP	Eaton Glenolden	16780 & 97484	See updated Rev and Date
1H9251	--	79-36-20	CMM	Oil Debris Monitoring Signal Conditioner	--	Nov 08/21	Rev 3	LEAP	Eaton Glenolden	16780 & 97484	See updated Rev and Date
1H9260	--	79-33-02	CMM	Debris Monitoring System(DMS) Signal Conditioner	Apr 27/22	Apr 27/22	Rev 1	GE9x	Eaton Glenolden	16780 & 97484	Added 27-May-2022
1J2496	--	79-22-11	CMM	Power Module	Feb 1/94	Feb 1/94	Initial	Cobra	Eaton Glenolden	16780 & 97484	OK
1J7589	--	77-42-03	CMM	Smart Zapper Power Module	Jan 03/00	Jan 03/00	Initial	Seaking	Eaton Glenolden	16780 & 97484	OK
1J7895	--	63-41-21	CMM	Power Module	Feb 15/02	Feb 15/02	Initial	AB139	Eaton Glenolden	16780 & 97484	OK
1Z7628	--	77-42-04	CMM	Smart Zapper Maint. Panel	Jan 03/00	Jan 03/00	Initial	Seaking	Eaton Glenolden	16780 & 97484	OK
2A7831	--	63-41-20	CMM	Oil Filler	Feb 15/02	Feb 15/02	Initial	AB139	Eaton Glenolden	16780 & 97484	OK
2A7840-1	--	63-41-20	CMM	Oil Filler	Feb 15/02	Feb 15/02	Initial	AB139	Eaton Glenolden	16780 & 97484	OK
2B7841	--	63-41-20	CMM	Vented Breather	Feb 15/02	Feb 15/02	Initial	AB139	Eaton Glenolden	16780 & 97484	OK
2E3249	--	49-90-30	CMM	Level Sensor	Jan 18/08	Jan 18/08	Initial	36-150 APU	Eaton Glenolden	16780 & 97484	OK
2F8566	--	63-41-20	CMM	E/O Sensor	Feb 15/02	Feb 15/02	Initial	AB139	Eaton Glenolden	16780 & 97484	OK

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
2Z6468	--	79-23-00	CMM	Self-Closing Valve	Feb 28/94	Feb 28/94	Initial	AE2100	Eaton Glenolden	16780 & 97484	OK
2Z7802	--	79-22-47	CMM	DMS Inhibitor	--	Mar 07/11	Rev 1	TRENT 500/900	Eaton Glenolden	16780 & 97484	See Corrected Rev and Rev Date
2Z8914	--	79-11-10	CMM	Filter Bowl Assembly	--	Apr 04/22	Rev 1	TRENT 1000,TRENT 7000	Eaton Glenolden	16780 & 97484	OK
4J6588	--	79-31-10	CMM	Electric Chip Detector	--	May 9/94	Rev 2	LM6000	Eaton Glenolden	16780 & 97484	OK
A693	--	79-24-01	CMM	Full Flow Debris Monitor	--	Apr 15/94	Reissue	ALF502/ LF507	Eaton Glenolden	16780 & 97484	OK
B4354-1	--	79-22-06	CMM	Chip Detector	--	Oct 2/13	Rev 4	CF6	Eaton Glenolden	16780 & 97484	OK
B4901	--	79-22-08	CMM	Chip Detector w/Self-Closing Valve	--	Mar 31/99	Rev 1	PW2000 F117PW-100	Eaton Glenolden	16780 & 97484	OK
B4902	--	79-22-14	CMM	Chip Detector w/Self-Closing Valve	--	May 9/08	Rev 1	PW4000	Eaton Glenolden	16780 & 97484	OK
B4903	--	79-22-14	CMM	Chip Detector w/Self-Closing Valve	--	May 9/08	Rev 1	PW4000	Eaton Glenolden	16780 & 97484	OK
S247-4	--	63-41-20	CMM	Sight Gauge	Feb 15/02	Feb 15/02	Initial	AB139	Eaton Glenolden	16780 & 97484	OK
VA3503	--	79-21-04	CMM	Chip Detector	--	May 10/96	Rev 1	RB211	Eaton Glenolden	16780 & 97484	OK
VA3508	--	79-21-05	CMM	Chip Detector	--	May 09/08	Rev 3	BR710, TRENT 700/800	Eaton Glenolden	16780 & 97484	--
VB3447	--	79-21-03	CMM	Chip Detector	--	May 24/96	Rev 1	RB211	Eaton Glenolden	16780 & 97484	OK
VB3521-2	--	79-22-45	CMM	Chip Detector	--	Nov 1/99	Rev 3	V2500	Eaton Glenolden	16780 & 97484	OK
100000-60	100000-60	SB 100000-60-27-1	SB	LINEAR ACTUATOR	01-Feb-02	--	Initial	FOKKER	Grand Rapids	17472, 72121 & 09145	--
100500-1/ -3	1005000	21-25-25	CMM	Linear Electromechanical Actuator	01-Oct-77	--	1	--	Grand Rapids	17472, 72121 & 09145	--
100800-1	100800	32-50-01	CMM	Nose Wheel Steering Elect Disconnect Actuator Assy	01-Feb-80	--	1	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
1029D100-1	1029D	52-34-07	CMM	PWR UNIT ELECT LOCK ACTUATOR	19-Nov-10	--	3	767	Grand Rapids	17472, 72121 & 09145	--
1029D100-1	1029D	SB 1029D100-52-1	SB	INSTALLATION OF ANTI-ROTATION PIN	09-Jun-11	--	Initial	Boeing	Grand Rapids	17472, 72121 & 09145	--
104E100-1	104E	SB 104E100-1	SB	ENERGY ABSORBING GEAR	--	--	--	--	Grand Rapids	17472, 72121 & 09145	--
104E100-3	104E	27-41-10*	CMM	TAILPLANE TRIM ACTUATOR	01-Jun-78	--	--	*ONTIC	Grand Rapids	17472, 72121 & 09145	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
104E100-3	104E	SB 104E100-3*	SB	BALL LUBRICATION	14-Oct-97	--	--	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
105C100-1	105C	27-50-00	CMM	FLAP ACTUATION SYSTEM	01-Jun-78	--	1	--	Grand Rapids	17472, 72121 & 09145	--
106E100-1	106E	27-51-03*	CMM	CONTROL UNIT	01-Jun-78	--	1	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
1073D100-13	1073D	SB 1073D100-27-1	SB	FLEXSHAFT BORE PLUG	21-May-98	--	1	IAI ASTRA SPX PH II	Grand Rapids	17472, 72121 & 09145	--
1073D100-15	1073D	SB 1073D100-27-1	SB	FLEXSHAFT BORE PLUG	21-May-98	--	1	IAI ASTRA SPX PH II	Grand Rapids	17472, 72121 & 09145	--
1074D100	1074D	SB 1072D100-27-01	SB	BRAKE PLATE INSPECTION	11-Sep-97	--	Initial	IAI ASTRA SPX	Grand Rapids	17472, 72121 & 09145	--
1075D100	1075D	SB 1075D100-27-1	SB	COVER REPLACEMENT	18-Apr-07	--	2	Gulfstream	Grand Rapids	17472, 72121 & 09145	--
1077D100	1077D	SB 1072D100-27-1	SB	BRAKE PLATE INSPECTION	11-Sep-97	--	Initial	IAI ASTRA SPX	Grand Rapids	17472, 72121 & 09145	--
107E100-1	107E	SB 107E100-1	SB	OVERTRAVEL STOPS	19-Oct-76	--	A	INCOMPLETE	Grand Rapids	17472, 72121 & 09145	--
107E100-3	107E	27-51-06*	CMM	BALLSCREW JACK	01-Jun-78	--	1	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
108D100-1	108D	27-51-05*	CMM	BEVEL GEARBOX	01-Oct-74	--	--	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
109D100-1	109D	27-52-01*	CMM	SYNCHRO GEARBOX	01-Nov-74	--	--	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
1104SD	1104	SB 1104SD100-27-1	SB	MOISTURE INGRESS PROTECTION	12-May-00	--	Initial	852/853/854 Flaps	Grand Rapids	17472, 72121 & 09145	--
1104SD	1104	SB 1104SD100-27-2	SB	SEAL INSPECTION&REPLACEMENT	08-Jun-06	--	1	Bombardier	Grand Rapids	17472, 72121 & 09145	--
110E100-10 /-21/-22	110E	27-51-04*	CMM	TRANSMISSION SHAFT	01-Feb-76	--	--	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
114D100	114D	52-30-10	CMM	ROTARY E-M ACTUATOR	01-Jun-99	--	2	L1011	Grand Rapids	17472, 72121 & 09145	--
115B135	115B	52-30-16	CMM	Mechanical Overload Clutch	05-Jul-11	--	1	--	Grand Rapids	17472, 72121 & 09145	--
115D100/-1	115D	52-30-11	CMM	ROTARY E-M ACTUATOR	01-Sep-99	--	4	L1011	Grand Rapids	17472, 72121 & 09145	--
116900-2 /-3	116900	24-09-01	CMM	Linear Electromechanical Actuator	31-May-88	--	1	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
116D100	116D	52-30-12	CMM	ROTARY GEARBOX	15-Oct-99	--	1	747	Grand Rapids	17472, 72121 & 09145	--
117000-2/-3	117000	66-20-01	CMM	LINEAR E-M ACTUATOR	12-Oct-09	--	3	SIKORSKY	Grand Rapids	17472, 72121 & 09145	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
118000-2	118000	76-10-01	CMM	Fuel Control Rotary Actuator	01-Jan-00	30-Apr-18	3	CH-46	Grand Rapids	17472, 72121 & 09145	--
122900-1	122900	52-10-01	CMM	Electromechanical Rotary Actuator	11-Jan-93	--	A	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
123SA100-1	123SA	27-52-02*	CMM	ASYMMETRY SIGNAL SENSOR	01-Apr-75	--	--	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
124E100-1	124E	52-30-08*	CMM	LINEAR E-M ACTUATOR	01-Feb-75	--	--	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
126300-1	1263	21-30-02	CMM	RAM AIR INTAKE ACTUATOR	23-May-06	--	3	Reference	Grand Rapids	17472, 72121 & 09145	--
130E100-11	130E	SB 130E100-52-3	SB	BRAKE PLATE CONVERSION	01-Nov-92	--	--	CANCELLED	Grand Rapids	17472, 72121 & 09145	--
130E100-13	130E	SB 130E100-52-6	SB	REPLCMNT OF MECH OVRLD CLUTCH	12-Nov-13	04-Sep-17	1	767	Grand Rapids	17472, 72121 & 09145	--
130E100-15	130E	SB 130E100-52-5	SB	REPLCMNT OF MECH OVRLD CLUTCH	19-Oct-15	04-Sep-17	1	747	Grand Rapids	17472, 72121 & 09145	--
130E100-2 /-4 /-13	130E	52-30-15	CMM	ROTARY E-M ACTUATOR	31-Aug-16	--	7	747/ 767	Grand Rapids	17472, 72121 & 09145	--
130E100-4/-11/-13	130E	SB 130E100-52-4	SB	LUBRICATION OMISSION	29-Jul-94	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
130E100-4/-9/-11	130E	SB 130E100-52-2	SB	BRAKE PLATE CONVERSION	25-Oct-93	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
130E100-9	130E	SB 130-52-1	SB	MOTOR MOUNT	08-Sep-83	--	--	--	Grand Rapids	17472, 72121 & 09145	--
130E100-9	130E100	SB 130-52-1	SB	Sub Door Rotary Actuator	08-Sep-83	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
130E100-9 /-11 /-15	130E	52-21-01	CMM	SUD DOOR ROTARY ACTUATOR	31-Aug-16	--	9	747	Grand Rapids	17472, 72121 & 09145	--
131200-1	131200	24-09-02	CMM	LINEAR E-M ACTUATOR	30-Sep-89	--	1	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
134000-1	134000	24-09-03	CMM	Linear Electromechanical Actuator	01-Apr-92	--	1	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
134000-1/ -3	134000	27-30-01	CMM	Linear Electromechanical Actuator	01-Aug-92	--	1	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
136200-1A/ -1B	136200	38-21-06	CMM	Electro-Mechanical Actuator Assembly	15-Nov-96	--	1	--	Grand Rapids	17472, 72121 & 09145	--
137600-1	137600	24-09-53	CMM	ACTUATOR	31-Mar-93	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
137900-1/-2	137900	52-51-01	CMM	Passenger Door Linear Actuator Assembly	20-Apr-10	--	4	FOKKER	Grand Rapids	17472, 72121 & 09145	--
148E100	148E100	148E100-52-01	SB	Brake Plate Conversion	28-Sep-18	--	Initial	747-E4B	Grand Rapids	17472	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
166D100	166D	25-50-02*	CMM	SILL ACTUATOR	15-May-78	--	1	*REPLD BY 25-50-04	Grand Rapids	17472, 72121 & 09145	--
166D100	166D	25-50-04	CMM	SILL ACTUATOR	01-Sep-99	--	3	FOKKER A-300	Grand Rapids	17472, 72121 & 09145	--
181D100	181D	25-50-01	CMM	LOCK ACTUATOR	01-May-75	--	--	--	Grand Rapids	17472, 72121 & 09145	--
308E100	308E	25-50-03	CMM	E-M POWER UNIT	01-Nov-75	--	--	--	Grand Rapids	17472, 72121 & 09145	--
484D100-1	484D	27-50-01	CMM	Wing Leading Edge Slat Actuation System	01-Jul-82	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
485D100-3	485D	27-50-02	CMM	Power Unit	01-Jun-81	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
486D100-1	486D	27-50-03	CMM	LINEAR MECHANICAL ACTUATOR	01-Jun-81	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
487D100-1	487D	27-50-04	CMM	ASYMMETRY DETECTOR	01-Jul-82	--	1	--	Grand Rapids	17472, 72121 & 09145	--
487D200-1	487D	27-50-05	CMM	ASYMMETRY CONTROL	01-Jul-82	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
496D100-1/-2	496D	27-53-03	CMM	ROTARY E-M ACTUATOR	01-Aug-82	--	Initial	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
497D100-1/-5/-7/-9/-11	497D	27-40-08	CMM	HORIZ TRIM ACTUATOR	30-Mar-10	--	1	CESSNA	Grand Rapids	17472, 72121 & 09145	--
5060D100-7	5060D	SB 5060D100-29-1	SB	BALL BEARING REPLACEMENT	17-Dec-84	--	Initial	SKURKA	Grand Rapids	17472, 72121 & 09145	--
5068D100-3/-5	5068D	SB 5068-52-1	SB	NEW MOTOR	15-Sep-83	--	Initial	747757767	Grand Rapids	17472, 72121 & 09145	--
5060D100-9	5060D	SB 5060D100-29-2	SB	GROUND STRAP & MOUNTING FOOT	01-Jun-90	--	Initial	SKURKA	Grand Rapids	17472, 72121 & 09145	--
5076D100-5	5076D	SB 5076-29-1	SB	BRAKE ROTOR REPLACEMENT	20-Sep-83	--	--	757/767	Grand Rapids	17472, 72121 & 09145	--
5076D100-9/-11	5076D	SB 5076-29-2	SB	CORROSION CHECK	03-Jan-95	--	--	757/767	Grand Rapids	17472, 72121 & 09145	--
524D100-1	524D	52-10-01	CMM	Passenger Door Actuator	01-Nov-79	--	Initial	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
5283D100-1/-3/-5/-9/-	5283D	SB 5283BRB1/1	SB	BRUSH REPLACEMENT	05-Mar-96	--	Initial	SUNDSTRAND	Grand Rapids	17472, 72121 & 09145	--
5283D100-13/-15/-17/-	5283D	SB 5283BRB1/1	SB	BRUSH REPLACEMENT	05-Mar-96	--	Initial	SUNDSTRAND	Grand Rapids	17472, 72121 & 09145	--
5283D100-21/-23	5283D	SB 5283BRB1/1	SB	BRUSH REPLACEMENT	05-Mar-96	--	Initial	SUNDSTRAND	Grand Rapids	17472, 72121 & 09145	--
6010N0001-02	6010N	SB 27-1	SB	ROD WIPER SEAL	27-Jun-83	--	Initial	MD-80/MD-90	Grand Rapids	17472, 72121 & 09145	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
6010N0001-02/-03/-4	6010N	27-09-02	CMM	AUTOSLAT ACTUATOR	01-Apr-94	--	13	MD-80/MD-90	Grand Rapids	17472, 72121 & 09145	--
6010N0001-04	6010N	SB 6010N-27-2	SB	BRUSH MODIFICATION	15-May-92	--	1	MD-80/MD-90	Grand Rapids	17472, 72121 & 09145	--
6010N0001-04	6010N	SB 6010N-27-3	SB	MOTOR REPLACEMENT	01-Jun-92	--	Initial	MD80/MD90	Grand Rapids	17472, 72121 & 09145	--
601200-02	6012A	27-64-10	CMM	LINEAR ACTUATOR	20-Oct-11	--	3	727/737	Grand Rapids	17472, 72121 & 09145	--
6013 ALL	6013	SB 27-2	SB	RUDDER RATIO CHANGER	16-Apr-71	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
601300-04	6013D	27-21-02	CMM	LINEAR ACTUATOR	27-Jan-75	--	5	747	Grand Rapids	17472, 72121 & 09145	--
601300-05	6013E	SB 6013E-27-4	SB	RUDDER RATIO CHANGER	15-Jun-76	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
601300-09	6013F	27-21-04	CMM	LINEAR ACTUATOR	27-Aug-74	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
601300-11	6013L	27-21-06	CMM	LINEAR ACTUATOR	23-Dec-08	--	4	--	Grand Rapids	17472, 72121 & 09145	--
601300-11	6013H	SB 6013H-27-6	SB	LINEAR ACTUATOR	01-Aug-94	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
601395(H)	60139	27-20-01	CMM	CONTROL MOTOR-MPC PRODUCTS	25-Oct-74	--	--	VEM-GR 6013	Grand Rapids	17472, 72121 & 09145	--
6013J0001-01	6013J/6013K	27-21-07	CMM	LINEAR ACTUATOR	31-Aug-16	--	7	--	Grand Rapids	17472, 72121 & 09145	--
6013J0001-01	6013J	SB 6013J-27-1	SB	RUDDER RATIO CHANGER ACTUATOR	01-Aug-92	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
6013K0001-01	6013K	SB 6013K-27-1	SB	INSPECTION OF SERVO MOTOR	21-Sep-11	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
602600-01	6026	52-09-04	CMM	CARGO DOOR LATCH ACTUATOR	05-Aug-10	--	12	DC-10	Grand Rapids	17472, 72121 & 09145	--
6026C001-01	6026C	52-09-04	CMM	CARGO DOOR LATCH ACTUATOR	05-Aug-10	--	12	DC-10	Grand Rapids	17472, 72121 & 09145	--
6026D001-01	6026D	52-09-04	CMM	CARGO DOOR LATCH ACTUATOR	05-Aug-10	--	12	DC-10	Grand Rapids	17472, 72121 & 09145	--
6026E001-01	6026E	52-09-04	CMM	CARGO DOOR LATCH ACTUATOR	05-Aug-10	--	12	DC-10	Grand Rapids	17472, 72121 & 09145	--
6026F0001-01	6026F	52-09-06	CMM	CARGO DOOR LATCH ACTUATOR	21-Oct-11	--	1	MD11	Grand Rapids	17472, 72121 & 09145	--
6039D	6039D0001-01	52-30-18	CMM	Electromechanical Linear Actuator	15-Mar-01	--	Initial	Airbus/ F-15 (Dual)	Grand Rapids	17472, 72121 & 09145	--
6094A0001-03	6094A	SB 6094A0001-27-01	SB	REPLACEMENT OF RADIAL BEARINGS	09-Oct-09	--	Initial	Embraer P100	Grand Rapids	17472	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
6094A0001-03	6094A	SB 6094A0001-27-02	SB	HALL EFFECT MOTOR SCREENING	09-Oct-09	--	Initial	Embraer P100	Grand Rapids	17472	--
6094A0001-03/-05	6094A	27-50-23	CMM	FLAP ACTUATOR	14-Nov-12	--	3	Embraer P100	Grand Rapids	17472	--
6094A0001-05	6094A	SB 6094A0001-27-04	SB	RETROFIT -05 TO -08 CONFIGURATION	03-Jul-14	20-Dec-18	2	Embraer P100	Grand Rapids	17472	--
6094A0001-08	6094A	27-50-25	CMM	FLAP ACTUATOR	15-Mar-14	--	Initial	Embraer P100	Grand Rapids	17472	--
6094A0001-XX	6094A	SB 6094A0001-27-03	SB	RETROFIT -03 TO -05 CONFIGURATION	05-May-15	--	1	Embraer P100	Grand Rapids	17472	--
6094A0001-08	6094A	SB 6094A0001-27-05	SB	INCORPORATION OF -08 MOD 1	20-Dec-18	--	Initial	Embraer P100	Grand Rapids	17472	--
630300-04	6303	SB 6303-76-4	SB	ENGINE CONDITION CONTROL	20-Jul-77	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
630300-04	6303	SB 76-1	SB	ENGINE CONDITION CONTROL	22-Apr-71	--	2	747	Grand Rapids	17472, 72121 & 09145	--
630300-05	6303	SB 6303-76-4	SB	ENGINE CONDITION CONTROL	20-Jul-77	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
630300-05	6303	SB 6303D-76-3	SB	ENGINE CONDITION CONTROL	23-Jul-76	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
630300-05	6303	SB 76-1	SB	ENGINE CONDITION CONTROL	22-Apr-71	--	2	747	Grand Rapids	17472, 72121 & 09145	--
630300-06	6303E	76-11-01	CMM	ROTARY ACTUATOR	15-Mar-95	--	5	747	Grand Rapids	17472, 72121 & 09145	--
630300-06	6303	SB 6303-76-4	SB	ENGINE CONDITION CONTROL	20-Jul-77	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
630300-06	6303	SB 6303D-76-3	SB	ENGINE CONDITION CONTROL	23-Jul-76	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
630300-06	6303	SB 6303E-76-2	SB	ENGINE CONDITION CONTROL	07-Aug-75	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
630300-06	6303E	SB 6303E-76-2	SB	ENGINE CONDITION CONTROL	07-Aug-75	--	--	747	Grand Rapids	17472, 72121 & 09145	--
630500-02	6305B	52-09-02	CMM	CARGO DOOR ACTUATOR	09-Jun-10	--	18	DC-10	Grand Rapids	17472, 72121 & 09145	--
630500-02	6305B	SB 52-1	SB	REPLACE PLANETARY GEARS	28-Sep-73	--	Initial	DC-10	Grand Rapids	17472, 72121 & 09145	--
630500-02	6305J	SB 52-4 (DAC)	SB	NEW GEARBOX	23-Nov-88	--	Initial	DC-10	Grand Rapids	17472, 72121 & 09145	--
630500-02	6305B	SB 52-77 (DAC)	SB	REPLACE PLANETARY GEARS	27-Sep-73	--	Initial	DC-10	Grand Rapids	17472, 72121 & 09145	--
630500-04	6305D	52-09-02	CMM	CARGO DOOR ACTUATOR	09-Jun-10	--	18	DC-10	Grand Rapids	17472, 72121 & 09145	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
630500-04	6305J	SB 52-4 (DAC)	SB	NEW GEARBOX	23-Nov-88	--	Initial	DC-10	Grand Rapids	17472, 72121 & 09145	--
630500-06	6305F	52-09-02	CMM	CARGO DOOR ACTUATOR	09-Jun-10	--	18	DC-10	Grand Rapids	17472, 72121 & 09145	--
630500-06	6305J	SB 52-4 (DAC)	SB	NEW GEARBOX	23-Nov-88	--	Initial	DC-10	Grand Rapids	17472, 72121 & 09145	--
630500-07	6305G	52-09-02	CMM	CARGO DOOR ACTUATOR	09-Jun-10	--	18	DC-10/MD-11	Grand Rapids	17472, 72121 & 09145	--
630500-07	6305J	SB 52-4 (DAC)	SB	NEW GEARBOX	23-Nov-88	--	Initial	DC-10	Grand Rapids	17472, 72121 & 09145	--
6305H0001-01	6305H	52-49-11	CMM	ROTARY ELECTRO-MECH ACTUATOR	01-May-84	--	1	KC-10	Grand Rapids	17472, 72121 & 09145	--
6305J0001-01	6305J	52-09-02	CMM	CARGO DOOR ACTUATOR	09-Jun-10	--	18	MD-11	Grand Rapids	17472, 72121 & 09145	--
630900-01	6309A	25-35-01	CMM	ROTARY ACTUATOR	24-Aug-70	--	Initial	DC-10	Grand Rapids	17472, 72121 & 09145	--
630900-02	6309A	25-35-02	CMM	SELF RETRACTING POWERED ROLLER	01-Apr-91	--	2	DC-10	Grand Rapids	17472, 72121 & 09145	--
631500-01/-03	6315A	25-52-45	CMM	SELF RETRACTING POWERED ROLLER	15-Dec-10	--	4	DC-10	Grand Rapids	17472, 72121 & 09145	--
631500-02/-04	6315B	25-52-46	CMM	SPRING LOADED POWERED ROLLER	15-Dec-10	--	3	DC-10	Grand Rapids	17472, 72121 & 09145	--
6315E0001-01	6315E	25-52-60	CMM	SELF RETRACTING POWERED ROLLER	17-Dec-10	--	3	KC-10	Grand Rapids	17472, 72121 & 09145	--
6315F0001-01	6315F/6315H	25-52-61	CMM	SELF RETRACTING POWERED ROLLER	15-Sep-10	--	4	MD-11	Grand Rapids	17472, 72121 & 09145	--
6315G0001-01	6315G/6315J	25-52-62	CMM	SPRING LOADED POWERED ROLLER	22-Oct-10	--	4	MD-11	Grand Rapids	17472, 72121 & 09145	--
631900-01	6319A	25-52-11	CMM	CARGO LONG. SHUTTLE DRIVE UNIT	01-Apr-90	--	8	DC-10	Grand Rapids	17472, 72121 & 09145	--
6322A0001-02/-04	6322A	52-09-05	CMM	PASSENGER DOOR ACTUATOR	21-Aug-12	--	9	DC-10	Grand Rapids	17472, 72121 & 09145	--
6323A0001-01/-02	6323A	27-63-01	CMM	SPOILER CONTROLLER ACTUATOR	01-Jul-93	--	6	DC-10/MD-11	Grand Rapids	17472, 72121 & 09145	--
6328A0001-01	6328A	25-52-47	CMM	CARGO LOADING ROLLER ASSY	29-Mar-11	--	4	DC-10/MD-11	Grand Rapids	17472, 72121 & 09145	--
6329A0001-01	6329A	76-11-02	CMM	ENGINE CONDITION ACTUATOR	04-Jan-88	--	1	767	Grand Rapids	17472, 72121 & 09145	--
6329A0001-01	6329A	SB 6329A-76-5	SB	ENGINE CONDITION CONTROL	10-Feb-84	--	Initial	767	Grand Rapids	17472, 72121 & 09145	--
6329A0001-01	6329A	SB 6329A-76-6	SB	ENGINE CONDITION CONTROL	24-Apr-87	--	Initial	767	Grand Rapids	17472, 72121 & 09145	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
6329A0001-01	6329A	SB 6329A-76-7	SB	ENGINE CONDITION CONTROL	15-Apr-90	--	1	767	Grand Rapids	17472, 72121 & 09145	--
6329B0001-01	6329B	76-11-02	CMM	ENGINE CONDITION CONTROL	04-Jan-88	--	1	747/767	Grand Rapids	17472, 72121 & 09145	--
6329B0001-01	6329B	SB 6329B-76-1	SB	ENGINE CONDITION CONTROL	15-Apr-90	--	1	747/767	Grand Rapids	17472, 72121 & 09145	--
6329C0001-01	6329C	76-11-03	CMM	ENGINE CONDITION CONTROL	08-Jul-10	--	1	747/767	Grand Rapids	17472, 72121 & 09145	--
6329C0001-01	6329C	SB 6329C-76-1	SB	ENGINE CONDITION CONTROL	15-Apr-90	--	Initial	767	Grand Rapids	17472, 72121 & 09145	--
6329D0001-01	6329D	76-11-03	CMM	ENGINE CONDITION CONTROL	08-Jul-10	--	1	747/767	Grand Rapids	17472, 72121 & 09145	--
6329D0001-01	6329D	SB 6329D-76-1	SB	ENGINE CONDITION CONTROL	15-Apr-90	--	Initial	747/767	Grand Rapids	17472, 72121 & 09145	--
6329E0001-01	6329E	76-11-04	CMM	ENGINE CONDITION CONTROL	25-Jun-13	--	2	767	Grand Rapids	17472, 72121 & 09145	--
6329F0001-01	6329F	76-11-05	CMM	ENGINE CONDITION CONTROL	01-May-90	--	Initial	747/767	Grand Rapids	17472, 72121 & 09145	--
6338A0001-02	6338A	76-12-01	CMM	FUEL SHUT-OFF CONTROL	01-Jun-88	--	2	A310	Grand Rapids	17472, 72121 & 09145	--
6338A0001-02	6338A	SB 6338A-76-1	SB	FUEL SHUT-OFF CONTROL	15-Sep-87	--	--	A310	Grand Rapids	17472, 72121 & 09145	--
6338A0001-02	6338A	SB PW4NAC 73-5	SB	FUEL SHUTOFF CONTROL (P&W)	23-Jun-88	--	Initial	A310	Grand Rapids	17472, 72121 & 09145	--
6338A0001-03	6338A	76-12-01	CMM	FUEL SHUT-OFF CONTROL	01-Jun-88	--	2	A310	Grand Rapids	17472, 72121 & 09145	--
6338A0001-03	6338A	SB PW4NAC 73-5	SB	FUEL SHUTOFF CONTROL (P&W)	23-Jun-88	--	Initial	A310	Grand Rapids	17472, 72121 & 09145	--
6338A0001-05	6338A	76-12-01	CMM	FUEL SHUT-OFF CONTROL	01-Jun-88	--	2	A310	Grand Rapids	17472, 72121 & 09145	--
6338A0001-07	6338A	76-12-01	CMM	FUEL SHUT-OFF CONTROL	01-Jun-88	--	2	A310	Grand Rapids	17472, 72121 & 09145	--
6338B0001-02	6338B	76-12-02	CMM	FUEL SHUT-OFF CONTROL	01-Nov-89	--	Initial	A310	Grand Rapids	17472, 72121 & 09145	--
6351A0001-01	6351A	SB 6351A-25-1	SB	IMPROVEMENT MODIFICATIONS	01-Apr-93	--	Initial	MD-11	Grand Rapids	17472, 72121 & 09145	--
6351A0001-01	6351A	SB 6351A-25-2	SB	UPGRADE TO -05	01-Sep-95	--	Initial	MD-11	Grand Rapids	17472, 72121 & 09145	--
6351A0001-01/-02/-03	6351A	25-52-63	CMM	POWERED ROLLER TURNTABLE	08-Jun-10	--	3	MD-11	Grand Rapids	17472, 72121 & 09145	--
6351A0001-02	6351A	SB 6351A-25-1	SB	IMPROVEMENT MODIFICATIONS	01-Apr-93	--	Initial	MD-11	Grand Rapids	17472, 72121 & 09145	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
6351A0001-02	6351A	SB 6351A-25-2	SB	UPGRADE TO -05	01-Sep-95	--	Initial	MD-11	Grand Rapids	17472, 72121 & 09145	--
6351A0001-03	6351A	SB 6351A-25-2	SB	UPGRADE TO -05	01-Sep-95	--	Initial	MD-11	Grand Rapids	17472, 72121 & 09145	--
6351A0001-04	6351A	SB 6351A-25-2	SB	UPGRADE TO -05	01-Sep-95	--	Initial	MD-11	Grand Rapids	17472, 72121 & 09145	--
6351A0001-04/-06	6351A	25-52-64	CMM	POWERED ROLLER TURNTABLE	08-Jun-10	--	1	MD-11	Grand Rapids	17472, 72121 & 09145	--
6351A0001-05	6351A	SB 6351A-25-3	SB	UPGRADE TO -06	01-May-96	--	Initial	MD-11	Grand Rapids	17472, 72121 & 09145	--
6355B0001-01/-02/-03	6355B	27-40-02	CMM	STAB TRIM MOTOR	10-Nov-10	--	4	737	Grand Rapids	17472, 72121 & 09145	--
6355B0001-02	6355B	SB 6355B100-27-1	SB	STABILIZER TRIM ELECTRIC MOTOR	30-Jun-00	--	--	737	Grand Rapids	17472, 72121 & 09145	--
6355C0001-01	6355C	27-40-10	CMM	STAB ILIZER TRIM MOTOR	12-Feb-04	12/22/21	11	737	Grand Rapids	17472, 72121 & 09145	--
6355C0001-01	6355C	6355C0001-27-01	SB	STAB ILIZER TRIM MOTOR	02-Jun-10	--	Initial	737	Grand Rapids	17472	--
6355C0001-01	6355C	6355C0001-27-02	SB	STAB ILIZER TRIM MOTOR	16-Apr-15	--	Initial	737	Grand Rapids	17472	--
6355C0001-01	6355C	6355C0001-27-03	SB	STAB ILIZER TRIM MOTOR	01-Jul-17	--	Initial	737	Grand Rapids	17472	--
6355C0001-02	6355C	27-40-10	CMM	STAB ILIZER TRIM MOTOR	12-Feb-04	12/22/21	11	737	Grand Rapids	17472	--
6355C0001-02	6355C	6355C0001-27-04	SB	STAB ILIZER TRIM MOTOR	30-Apr-20	--	Initial	737	Grand Rapids	17472	--
6356A0001-02	6356A	25-50-01	CMM	SELF-ERECTING PDU	14-Jan-08	--	1	767	Grand Rapids	17472, 72121 & 09145	--
6356B0001-02	6356B	25-50-02	CMM	SPRING LOADED PDU	07-Jan-08	--	1	767	Grand Rapids	17472, 72121 & 09145	--
6361A0001-1	6361A	27-40-09	CMM	HORIZ TRIM ACTUATOR	24-Jul-02	--	Initial	CESSNA	Grand Rapids	17472, 72121 & 09145	--
6361B0001-04	6361B	27-40-11	CMM	HORIZ TRIM ACTUATOR	31-Jul-15	--	2	CESSNA	Grand Rapids	17472, 72121 & 09145	--
6361G0001-01	6361G	27-40-12	CMM	HORIZ TRIM ACTUATOR	17-Feb-15	--	Initial	CESSNA	Grand Rapids	17472, 72121 & 09145	--
6375A0001-001	6375A	27-20-03	CMM	PEDALS ADJUST ROTARY ACTUATOR	18-Sep-12	--	2	Embraer	Grand Rapids	17472, 72121 & 09145	--
6450A0001-03	6450A	SB 6450A-28-1	SB	BOOM WINCH TO -04	01-Jul-97	--	1	KC10	Grand Rapids	17472, 72121 & 09145	--
651300-07	6513E	27-44-10	CMM	ROTARY ACTUATOR	20-Jul-11	--	6	737	Grand Rapids	17472, 72121 & 09145	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
651300-07	6513E	SB 27-1044 (BAC)	SB	ROTARY ACTUATOR	22-Jul-70	--	1	737	Grand Rapids	17472, 72121 & 09145	--
651300-07	6513E	SB 737-27-1101	SB	ROTARY ACTUATOR (BOEING SB)	01-Feb-80	--	Initial	737	Grand Rapids	17472, 72121 & 09145	--
651300-08	6513F	27-44-10	CMM	ROTARY ACTUATOR	20-Jul-11	--	6	737	Grand Rapids	17472, 72121 & 09145	--
651300-08	6513	SB 6513F-27-1	SB	STABILIZER TRIM ACTUATOR	15-Jul-76	--	Initial	737	Grand Rapids	17472, 72121 & 09145	--
651300-08	6513F	SB 737-27-1101	SB	ROTARY ACTUATOR (BOEING)	01-Feb-80	--	Initial	737	Grand Rapids	17472, 72121 & 09145	--
658D100-1	658D	SB 658-27-1	SB	REPLACE MOTOR	26-Sep-83	--	--	747/757/767	Grand Rapids	17472, 72121 & 09145	--
658D100-1, -3, -5, -7/-9	658D	27-21-08	CMM	RUDDER TRIM ACTUATOR	11-Jul-12	--	11	747/757/767	Grand Rapids	17472, 72121 & 09145	--
658D100-XX	658D	27-21-01*	CMM	RUDDER TRIM ACTUATOR	15-Dec-88	--	5	*REPLD BY 27-21-08, Obsolete	Grand Rapids	17472, 72121 & 09145	--
664D100-5	664D	SB 664D100-52-01	SB	BRAKE PLATE CONVERSION	18-Jul-08	--	2	767	Grand Rapids	17472, 72121 & 09145	--
664D100-5 /-7	664D	52-34-01	CMM	CARGO DOOR LIFT LATCH ACTUATOR	31-Jul-15	--	7	767	Grand Rapids	17472, 72121 & 09145	--
664D100-5	664D	SB 664D100-52-02	SB	UPGRADE 664D100-5 TO -7	18-Jul-08	16-Sep-09	1	767	Grand Rapids	17472	--
664D100-7	664D	SB 664D100-52-3	SB	INSTALLATION OF ANTI-ROTATION PIN	14-Mar-11	--	Initial	767	Grand Rapids	17472	--
6707A0001-01	6707A	27-20-02	CMM	RUDDER TRIM CONTROL SWITCH	01-Aug-94	--	1	777	Grand Rapids	17472, 72121 & 09145	--
674D100-13, -15	674D	SB 674D100-27-01	SB	THERMAL BLANKET	17-Sep-97	--	Initial	IAI	Grand Rapids	17472, 72121 & 09145	--
675300-01	6753A	52-09-03	CMM	RIGHT ANGLE DRIVE GEARBOX	01-May-91	--	2	DC-10	Grand Rapids	17472, 72121 & 09145	--
677D100-15	677D	SB 677D100-27-01	SB	THERMAL BLANKET	17-Sep-97	--	Initial	IAI	Grand Rapids	17472, 72121 & 09145	--
677D100-17	677D	SB 677D100-27-01	SB	THERMAL BLANKET	17-Sep-97	--	Initial	IAI	Grand Rapids	17472, 72121 & 09145	--
677D100-19	677D	SB 677D100-27-02	SB	THERMAL BLANKET	17-Sep-97	--	Initial	IAI	Grand Rapids	17472, 72121 & 09145	--
677D100-20	677D	SB 677D100-27-02	SB	THERMAL BLANKET	17-Sep-97	--	Initial	IAI	Grand Rapids	17472, 72121 & 09145	--
681D100-5/7/-9	681D	27-11-01	CMM	LINEAR ACTUATOR	01-May-84	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
684D100-1	684D	SB 684-27-02	SB	CAM SWITCH & BRAKE DISC	17-Apr-87	--	--	747/757/767/777	Grand Rapids	17472, 72121 & 09145	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
684D100-1/-3/-5/-7/-9/	684D	27-62-01	CMM	SPEED BRAKE LINEAR ACTUATOR	01-Mar-81	26-Jul-19	16	--	Grand Rapids	17472	--
684D100-1-3/-5	684D	SB 684D100-27-10	SB	CAM SWITCH & BRAKE DISC	10-May-89	--	--	747/757/767/777	Grand Rapids	17472, 72121 & 09145	--
684D100-7 /-9	684D	SB 684D100-27-11	SB	BRAKE PLATE CONVERSION	16-Jul-09	--	1	747/757/767/777	Grand Rapids	17472, 72121 & 09145	--
690500-04/690500-06	6905C/6905F	27-21-01	CMM	CONTROL UNIT	15-Aug-91	--	5	747	Grand Rapids	17472, 72121 & 09145	--
690500-06	6905	SB 27-3	SB	RUDDER RATIO CHANGER	18-Apr-75	--	1	747	Grand Rapids	17472, 72121 & 09145	--
690500-08	6905H	27-21-03	CMM	CONTROL UNIT	22-Dec-10	--	10	747	Grand Rapids	17472, 72121 & 09145	--
690500-08	6905H	SB 6905H-27-6	SB	RUDDER RATIO CHANGER	23-Nov-76	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
690500-08	6905J	SB 6905H-27-7	SB	RUDDER RATIO CHANGER	15-Dec-81	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
690500-08	6905H	SB 6905H-27-8	SB	RUDDER RATIO CHANGER CONTROL	01-Mar-95	--	1	747	Grand Rapids	17472, 72121 & 09145	--
690500-09	6905J/6905L	27-21-05	CMM	CONTROL UNIT	25-May-11	--	5	747	Grand Rapids	17472, 72121 & 09145	--
690500-09	6905J	SB 6905H-27-6	SB	RUDDER RATIO CHANGER	23-Nov-76	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
690500-09	6905H	SB 6905H-27-7	SB	RUDDER RATIO CHANGER	15-Dec-81	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
690500-09	6905J	SB 6905J-27-9	SB	RUDDER RATIO CHANGER CONTROL	01-Mar-95	--	1	747	Grand Rapids	17472, 72121 & 09145	--
6905K0001-01	6905K	27-21-03	CMM	CONTROL UNIT	22-Dec-10	--	10	747	Grand Rapids	17472, 72121 & 09145	--
692D100-1	692D	SB 692D100-52-1	SB	REPLACE NOBACK	14-Dec-83	--	--	--	Grand Rapids	17472, 72121 & 09145	--
692D100-1	692D	SB 692D100-52-1	SB	Large Forward Cargo Door Rotary Actuator	14-Dec-83	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
692D100-13	692D	SB 692D100-52-4	SB	REWORK & RE-IDENTIFICATION OF ACTUATORS	14-Aug-14	--	3	767/777	Grand Rapids	17472, 72121 & 09145	--
692D100-2	692D	SB 692D100-52-1	SB	REPLACE NOBACK	14-Dec-83	--	--	--	Grand Rapids	17472, 72121 & 09145	--
692D100-2	692D	SB 692D100-52-3	SB	REPLACE BOLTS	06-Jan-87	--	--	?ISSUED?	Grand Rapids	17472, 72121 & 09145	--
692D100-2	692D	SB 692D100-52-1	SB	Large Forward Cargo Door Rotary Actuator	14-Dec-83	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
692D100-2/-3/-5/-9/-11	692D	52-34-02	CMM	CARGO DOOR ROTARY ACTUATOR	01-Nov-81	26-Jul-19	16	767/777	Grand Rapids	17472, 72121	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
692D100-3	692D	SB 692D100-52-2	SB	OUTPUT CARRIER REPLACEMENT	25-Oct-84	--	Initial	767/777	Grand Rapids	17472, 72121 & 09145	--
692D100-3	692D1	SB 692D100-52-3	SB	MOD TO -5	25-Oct-84	--	Initial	757/767/777	Grand Rapids	17472, 72121 & 09145	--
692D100-3	692D	SB 692D100-52-2	SB	Large Forward Cargo Door Rotary Actuator	25-Aug-84	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
692D100-5	692D	SB 692D100-52-3	SB	Large Forward Cargo Door Rotary Actuator	06-Jan-87	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
724D100-1	724D	SB 724D100-32-1	SB	IDENTIFICATION REPLACEMENT	01-Jun-86	--	--	--	Grand Rapids	17472, 72121 & 09145	--
724D100-1	724D	SB 724D100-32-2	SB	BRAKE PLATE CONVERSION	16-Nov-92	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
724D100-1 /-3	724D	32-35-01	CMM	ALTERNATE LANDING GEAR ACTUATR	24-Aug-11	--	3	757/767	Grand Rapids	17472, 72121 & 09145	--
762B0001-03	7620B	SB 7620B-32-1	SB	LANDING GEAR CONTROL	01-Feb-95	--	initial	T-45	Grand Rapids	17472, 72121 & 09145	--
778D100-1/-7/-9/-11	778D	27-11-05	CMM	LINEAR ACTUATOR	08-Dec-16	--	2	Lear 45	Grand Rapids	17472, 72121 & 09145	--
8025A0001-04	8025A0001	27-50-24	CMM	FLAP SYSTEM CONTROL UNIT	20-Aug-09	--	Initial	VLJ	Grand Rapids	17472, 72121 & 09145	--
8025A0001-05	8025	SB 8025A0001-27-01	SB	REPLACEMENT OF POWER PWA	30-Jul-10	--	Initial	Embraer VLJ	Grand Rapids	17472, 72121 & 09145	--
8025A0001-XX	8025	SB 8025A0001-27-02	SB	UPGRADE TO 8025B0001-04 CONFIG.	14-Nov-12	--	Initial	Embraer VLJ	Grand Rapids	17472, 72121 & 09145	--
804D100-3	804D	52-31-01	CMM	CARGO DOOR POWER DRIVE UNIT	02-Mar-11	--	2	MD11	Grand Rapids	17472, 72121 & 09145	--
806D100-1	806D	52-31-02	CMM	CARGO DOOR ROTARY ACTUATOR	01-Sep-99	--	1	MD11	Grand Rapids	17472, 72121 & 09145	--
806D100-1	806D100	SB MD11-52A033	SB	ACTUATOR	10-Oct-96	--	--	MD-11	Grand Rapids	17472, 72121 & 09145	--
807D100-1	807D	52-31-03	CMM	CARGO DOOR ROTARY ACTUATOR	02-Aug-11	--	1	--	Grand Rapids	17472, 72121 & 09145	--
846D1--03	846D	SB 846D100-27-1	SB	FLIGHT CONTROLS-MTR BRAKE	15-May-99	--	Initial	MD-80/MD-90/717	Grand Rapids	17472, 72121 & 09145	--
848D100-1	848D	52-31-04	CMM	PIN LATCH ROTARY ACTUATOR	15-Oct-92	--	--	--	Grand Rapids	17472, 72121 & 09145	--
852D100/853D100	852D/853D	SB 852D100-27-03	SB	ACTUATOR GEAR BACKLASH	01-Apr-98	--	C	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
852D100-11	852D100	27-50-12	CMM	INBOARD/OUTBOARD FLAP ACTUATOR	01-Apr-03	--	5	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
852D100-19/-21	852D100	27-50-21	CMM	INBOARD/OUTBOARD FLAP ACTUATOR	04-Oct-07	--	5	CRJ 200	Grand Rapids	17472, 72121 & 09145	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
852D100-19/-21	852D	SB 852D100-27-04	SB	REPLACEMENT OF SEALS - MOD	31-Jul-09	--	4	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
852D100-21	852D	SB 852D100-27-05	SB	RPCLMT OF GEARSET -NITAL ETCH	27-Mar-09	--	Initial	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
852D100-23/-25	852D100	27-50-22	CMM	INBOARD/OUTBOARD FLAP ACTUATOR	28-Jul-08	26-Jul-19	4	CRJ 200	Grand Rapids	17472	--
852D100-25	852D	SB 852D100-27-06	SB	RPCLMT OF GEARSET -NITAL ETCH	27-Mar-09	--	Initial	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
852D100-25	852D	SB 852D100-27-07	SB	RPCLMT OF GEARSET -PITCH VARIATION	27-Mar-09	--	Initial	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
852D100-25	852D	SB 852D100-27-08	SB	SCREW REPLACEMENT	26-Jun-15	--	Initial	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
852D100-9	852D	SB 852D100-27-02	SB	LUBRICANT MIX CHANGE	24-May-96	--	Initial	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
852D100-9/ 853D100-9	852D/853	27-50-19	CMM	INBOARD/OUTBOARD FLAP ACTUATOR	01-Jul-98	--	1	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-1	853D	SB 853D100-27-1	SB	ACTUATOR HEALTH CHECK PROGRAM	09-Feb-00	--	B	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-10	853D	SB 852D100-27-02	SB	LUBRICANT MIX CHANGE	24-May-96	--	Initial	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-10	853D	SB 853D100-27-1	SB	ACTUATOR HEALTH CHECK PROGRAM	09-Feb-00	--	B	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-11	853D	SB 853D100-27-1	SB	ACTUATOR HEALTH CHECK PROGRAM	09-Feb-00	--	B	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-11/-12/-13/-1	853D100	27-50-12	CMM	INBOARD/OUTBOARD FLAP ACTUATOR	01-Apr-03	--	5	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-12	853D	SB 853D100-27-1	SB	ACTUATOR HEALTH CHECK PROGRAM	09-Feb-00	--	B	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-13	853D	SB 853D100-27-1	SB	ACTUATOR HEALTH CHECK PROGRAM	09-Feb-00	--	B	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-13/-14	853D	SB 853D100-27-2	SB	HEALTH CHECK SAMPLING	11-Feb-00	--	A	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-14	853D	SB 853D100-27-1	SB	ACTUATOR HEALTH CHECK PROGRAM	09-Feb-00	--	B	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-19/-20	853/854D100	27-50-21	CMM	INBOARD/OUTBOARD FLAP ACTUATOR	04-Oct-07	--	5	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-19/-20	853D	SB 853D100-27-3	SB	ACTUATOR BOLT INSPECTION	30-Jun-02	--	Initial	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-19/-20	853	SB 853D100-27-04	SB	REPLACEMENT OF SEALS - MOD	31-Jul-09	--	4	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-2	853D	SB 853D100-27-1	SB	ACTUATOR HEALTH CHECK PROGRAM	09-Feb-00	--	B	CRJ 200	Grand Rapids	17472, 72121 & 09145	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
853D100-23/-24	853D100	27-50-22	CMM	INBOARD/OUTBOARD FLAP ACTUATOR	28-Jul-08	26-Jul-19	4	CRJ 200	Grand Rapids	17472	--
853D100-3	853D	SB 853D100-27-1	SB	ACTUATOR HEALTH CHECK PROGRAM	09-Feb-00	--	B	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-4	853D	SB 853D100-27-1	SB	ACTUATOR HEALTH CHECK PROGRAM	09-Feb-00	--	B	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-5	853D	SB 853D100-27-1	SB	ACTUATOR HEALTH CHECK PROGRAM	09-Feb-00	--	B	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-6	853D	SB 853D100-27-1	SB	ACTUATOR HEALTH CHECK PROGRAM	09-Feb-00	--	B	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-7	853D	SB 853D100-27-1	SB	ACTUATOR HEALTH CHECK PROGRAM	09-Feb-00	--	B	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-8	853D	SB 853D100-27-1	SB	ACTUATOR HEALTH CHECK PROGRAM	09-Feb-00	--	B	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-9	853D	SB 852D100-27-02	SB	LUBRICANT MIX CHANGE	24-May-96	--	Initial	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
853D100-9	853D	SB 853D100-27-1	SB	ACTUATOR HEALTH CHECK PROGRAM	09-Feb-00	--	B	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
854D100	854D	SB 852D100-27-03	SB	ACTUATOR GEAR BACKLASH	01-Apr-98	--	C	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
854D100	854D	SB 853D100-27-3	SB	ACTUATOR BOLT INSPECTION	30-Jun-02	--	Initial	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
854D100-10	854D	SB 852D100-27-02	SB	LUBRICANT MIX CHANGE	24-May-96	--	Initial	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
854D100-11/-12	854D100	27-50-12	CMM	INBOARD/OUTBOARD FLAP ACTUATOR	01-Apr-03	--	5	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
854D100-19/-20	854D100	27-50-21	CMM	INBOARD/OUTBOARD FLAP ACTUATOR	04-Oct-07	--	5	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
854D100-19/-20	854	SB 854D100-27-01	SB	REPLACEMENT OF SEALS - MOD	31-Jul-09	--	4	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
854D100-23/-24	854D100	27-50-22	CMM	INBOARD/OUTBOARD FLAP ACTUATOR	28-Jul-08	26-Jul-19	4	CRJ 200	Grand Rapids	17472	--
854D100-9	854D	SB 852D100-27-02	SB	LUBRICANT MIX CHANGE	24-May-96	--	Initial	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
854D100-9/-10	854D	27-50-19	CMM	INBOARD/OUTBOARD FLAP ACTUATOR	01-Jul-98	--	1	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
855D100-11	855D	SB 855D100-27-4	SB	Inspection of Lockwire	01-Jul-04	--	Initial	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
855D100-11	855D	SB 855D100-27-06	SB	Modification of 855D100-11 to 855D100-15 BPSU	19-Jul-12	--	3	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
855D100-11/-15	855D	27-50-20	CMM	Brake Position Sensor Unit (BPSU)	15-Mar-02	09-Apr-18	8	CRJ 200	Grand Rapids	17472, 72121 & 09145	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
855D100-5	855D	SB 855D100-27-1	SB	CONNECTOR SEALANT/TO 9	01-Sep-98	--	Initial	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
855D100-5	855D	SB 855D100-27-1	SB	Notice of Superseding Document	03-May-00	--	1	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
855D100-5	855D	SB 855D100-27-3	SB	Suffix "B" Modification Program	30-May-12	--	1	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
855D100-7	855D	SB 855D100-27-1	SB	CONNECTOR SEALANT/To -9	01-Sep-98	--	Initial	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
855D100-7	855D	SB 855D100-27-1	SB	Notice of Superseding Document	03-May-00	--	1	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
855D100-7	855D	SB 855D100-27-3	SB	Suffix "B" Modification Program	30-May-12	--	1	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
855D100-7/-9/-13	855D	27-50-14	CMM	Brake Position Sensor Unit (BPSU)	07-Jun-12	--	11	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
855D100-9	855D	SB 855D100-27-2	SB	REPLACE ENDBELL & SENSOR	14-Dec-99	--	Initial	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
855D100-9	855D	SB 855D100-27-2	SB	Notice of Superseding Document	03-May-00	--	1	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
855D100-9	855D	SB 855D100-27-3	SB	Suffix "B" Modification Program	30-May-12	--	1	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
855D100-9	855D	SB 855D100-27-05	SB	Modification of 855D100-9 to 855D100-13 BPSU	30-May-12	--	2	CRJ 200	Grand Rapids	17472, 72121 & 09145	--
864D100	864D	SB 864D100-27-01	SB	Nameplate Inspection/Identification	25-Jul-06	--	Initial	Bombardier	Grand Rapids	17472, 72121 & 09145	--
865D100-7	865D	27-50-13	CMM	POWER DRIVE UNIT/WING FLAP SYSTEM	29-Mar-10	--	5	CRJ	Grand Rapids	17472, 72121 & 09145	--
883D100-1	883D	52-31-05	CMM	DIRECTIONAL CHANGE GEARBOX	15-Oct-92	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
899D100-3	899D	27-50-18	CMM	ROTATION TRANSMITTER	01-May-95	--	0	PILATUS	Grand Rapids	17472, 72121 & 09145	--
921D100-1/-2	921D	52-32-01	CMM	Side Cargo Door Lift Mechanism Gearbox & Brake	01-Sep-93	19-Jun-18	2	747/767 Cargo Conversion	Grand Rapids	17472	--
922D100-1/-3	922D	52-32-02	CMM	RIGHT ANGLE DRIVE GEARBOX	03-Dec-10	--	1	747/767 Cargo Conversion	Grand Rapids	17472	--
924D100-1	924D	27-62-03	CMM	AUTO GROUND SPEEDBRAKE ACTUATR	04-Nov-15	--	5	777	Grand Rapids	17472, 72121 & 09145	--
931D100-1/-3	931D	52-21-06	CMM	LARGE CARGO DOOR POWER DRIVE	16-Nov-16	--	5	777	Grand Rapids	17472, 72121 & 09145	--
931D100-3	931D	SB 931D100-52-01	SB	Installation of Loctite on Clapper Screws	23-May-11	--	Initial	Boeing	Grand Rapids	17472, 72121 & 09145	--
951D100-5	951D	27-50-16	CMM	WING FLAP ACTUATOR	01-Aug-95	--	0	PILATUS	Grand Rapids	17472, 72121 & 09145	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
951D100-5	951D	SB 27-005 (PILATUS)	SB	CHECK FLAP ACTUATORS	18-Nov-98	--	Initial	PILATUS PC-12	Grand Rapids	17472, 72121 & 09145	--
951D100-7	951D	SB 27-005 (PILATUS)	SB	CHECK FLAP ACTUATORS	18-Nov-98	--	Initial	PILATUS PC-12	Grand Rapids	17472, 72121 & 09145	--
951D100-9	951D	SB 27-005 (PILATUS)	SB	CHECK FLAP ACTUATORS	18-Nov-98	--	Initial	PILATUS PC-12	Grand Rapids	17472, 72121 & 09145	--
952D100-5	952D	27-50-17	CMM	POWER DRIVE UNIT	01-Jun-95	--	0	PILATUS	Grand Rapids	17472, 72121 & 09145	--
964D100-1	964D	52-34-04	CMM	CARGO DOOR LIFT LATCH ACTUATOR	13-Sep-10	--	4	777	Grand Rapids	17472, 72121 & 09145	--
964D100-1	964	SB 964D100-52-1	SB	INSTALLATION OF ANTI-ROTATION PIN	09-Jun-11	--	Initial	Boeing	Grand Rapids	17472, 72121 & 09145	--
ABH4460-503	DAC	SB MDJJ-76-005	SB	THRUST CONTROL MODULE	06-Nov-96	--	--	MD-11	Grand Rapids	17472, 72121 & 09145	--
ABH7760-1	ABH7760	76-10-05 (DAC)	CMM	THRUST CONTROL (PRELIM)	08-Aug-91	--	Initial	MD-11	Grand Rapids	17472, 72121 & 09145	--
ABH7760-501	DAC	SB MDII-76-005	SB	THRUST CONTROL MODULE	06-Nov-96	--	--	MD-11	Grand Rapids	17472, 72121 & 09145	--
B6557	B6557	SB 6557	SB	FLEXIBLE DRIVE SHAFTS	01-Aug-79	--	--	--	Grand Rapids	17472, 72121 & 09145	--
CL-600-2B19	CL600	SB A601R-27-069	SB	BACKLASH MEASUREMENT	31-Jul-96	--	A	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
CL-600-2B19	CL600	SB 601R-27-111	SB	Repetitive Rplcmnt of No. 3 Flap Actuators	06-Mar-00	--	Initial	CRJ	Grand Rapids	17472, 72121 & 09145	--
CL-600-2B19	CL600	SB 601R-27-114	SB	Skew Detection System	22-Mar-02	--	Initial	CRJ	Grand Rapids	17472, 72121 & 09145	--
D1049	D1049	24-01-01	CMM	Actuator	15-Jul-59	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
D1522-4, -5	D1522	27-53-01*	CMM	ROTARY E-M ACTUATOR	01-Aug-99	--	4	*ONTIC EMBRAER	Grand Rapids	17472, 72121 & 09145	--
D1548-1/-2	D1548	SB D1548*	SB	D1548 TO D3879 CHANGE	--	--	--	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
D1931-2	D1931	32-31-01*	CMM	DIRECT CURRENT MOTOR	01-Feb-82	--	Initial	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
D2063	D2063	52-30-01*	CMM	ROTARY E-M ACTUATOR	15-Sep-70	--	1	*REPLD BY 52-30-07	Grand Rapids	17472, 72121 & 09145	--
D2063	D2063	SB D2063-52-1	SB	TIME DELAY RELAY	24-Feb-84	--	--	747	Grand Rapids	17472, 72121 & 09145	--
D2063	D2063	SB D2063-52-2	SB	SAFETY UPLOCK/NO-BACK	01-Aug-92	--	--	747	Grand Rapids	17472, 72121 & 09145	--
D2063	D2063	SB D2063-52-1	SB	Cargo Door Rotary Actuator	24-Feb-84	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
D2063	D2063	SB D2063-52-6	SB	BRAKE PLATE CONVERSION	01-Feb-99	--	1	747	Grand Rapids	17472, 72121 & 09145	--
D2063, -1, -7, MD1-2, N	D2063	52-30-07	CMM	ROTARY ACTUATOR	11-Feb-05	--	8	747	Grand Rapids	17472, 72121 & 09145	--
D2063/-1/-6/-7/-9	D2063	SB D2063-52-6	SB	NEWBRAKEPLATE&CLAPPER	01-Feb-99	--	1	747	Grand Rapids	17472, 72121 & 09145	--
D2063-1	D2063	SB D2063-52-1	SB	TIME DELAY RELAY	24-Feb-84	--	--	747	Grand Rapids	17472, 72121 & 09145	--
D2063-1	D2063	SB D2063-52-4	SB	SAFETY UPLOCK/NO BACK	01-Aug-92	--	--	747	Grand Rapids	17472, 72121 & 09145	--
D2063-1	D2063	SB D2063-52-1	SB	Cargo Door Rotary Actuator	24-Feb-84	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
D2063-1	D2063	SB D2063-52-6	SB	BRAKE PLATE CONVERSION	01-Feb-99	--	1	747	Grand Rapids	17472, 72121 & 09145	--
D2063-11	D2063	52-30-17	CMM	ROTARY ACTUATOR	01-Sep-88	11-May-17	13	747	Grand Rapids	17472, 72121 & 09145	* Rev. 7 Not Released
D2063-11	D2063	SB D2063-52-7	SB	LUBRICATION OMISSION	31-Aug-93	--	--	747	Grand Rapids	17472, 72121 & 09145	--
D2063-12	D2063	52-30-17	CMM	ROTARY ACTUATOR	01-Sep-88	11-May-17	13	747	Grand Rapids	17472, 72121 & 09145	* Rev. 7 Not Released
D2063-12	D2063	SB D2063-52-8	SB	MOD KIT COMPLETION-FROM-11 TO -12	17-Jun-09	--	4	747	Grand Rapids	17472, 72121 & 09145	--
D2063-12	D2063	SB D2063-52-9	SB	INTRODUCTION OF NEW TORQUE LIMITER	20-Mar-17	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
D2063-6	D2063	SB D2063-52-6	SB	BRAKE PLATE CONVERSION	01-Feb-99	--	1	747	Grand Rapids	17472, 72121 & 09145	--
D2063-6, MD6-1	D2063	52-30-13	CMM	ROTARY E-M ACTUATOR	20-Apr-12	--	7	747	Grand Rapids	17472, 72121 & 09145	--
D2063-7	D2063	SB D2063-52-5	SB	SAFETY UPLOCK/NO BACK	01-Feb-99	--	1	747	Grand Rapids	17472, 72121 & 09145	--
D2063-7	D2063	SB D2063-52-6	SB	BRAKE PLATE CONVERSION	01-Feb-99	--	1	747	Grand Rapids	17472, 72121 & 09145	--
D2063-9	D2063	52-30-17	CMM	ROTARY ACTUATOR	01-Sep-88	11-May-17	13	747	Grand Rapids	17472, 72121 & 09145	* Rev. 7 Not Released
D2063-9	D2063	SB D2063-52-3	SB	TORQUE LIMITER AND CLUTCH	01-Sep-87	--	--	747	Grand Rapids	17472, 72121 & 09145	--
D2063-9	D2063	SB D2063-52-7	SB	LUBRICATION OMISSION	31-Aug-93	--	--	747	Grand Rapids	17472, 72121 & 09145	--
D2063-9	D2063	SB D2063-52-6	SB	BRAKE PLATE CONVERSION	01-Feb-99	--	1	747	Grand Rapids	17472, 72121 & 09145	--
D2063MD-1	D2063	SB D2063-52-6	SB	BRAKE PLATE CONVERSION	01-Feb-99	--	1	747	Grand Rapids	17472, 72121 & 09145	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
D2063MD1-1	D2063	SB D2063-52-6	SB	BRAKE PLATE CONVERSION	01-Feb-99	--	1	747	Grand Rapids	17472, 72121 & 09145	--
D2063MD7-1	D2063	SB D2063-52-6	SB	BRAKE PLATE CONVERSION	01-Feb-99	--	1	747	Grand Rapids	17472, 72121 & 09145	--
D2067-3	D2067	SB D2067-52-1	SB	ACTUATOR ARM ATTACHMENT	01-May-82	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
D2067-3	D2067	SB D2067-52-2	SB	MOUNTING INTERFACE	01-May-85	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
D2067-3 thru -9	D2067	SB D2067-52-04	SB	Bolt Inspection/Replacement on Arm	13-Jul-10	--	1	747	Grand Rapids	17472, 72121 & 09145	--
D2067-3, -4, -5, -6,-7,-8	D2067	52-30-02	CMM	ROTARY MECHANICAL ACTUATOR	19-Jul-12	--	8	747	Grand Rapids	17472, 72121 & 09145	--
D2067-3/-4/-5/-6	D2067	SB D2067-52-2	SB	Cargo Door Rotary Actuator	10-Feb-84	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
D2067-4	D2067	SB D2067-52-1	SB	ACTUATOR ARM ATTACHMENT	01-May-82	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
D2067-4	D2067	SB D2067-52-2	SB	MOUNTING INTERFACE	01-May-85	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
D2067-5	D2067	SB D2067-52-2	SB	MOUNTING INTERFACE	01-May-85	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
D2067-6	D2067	SB D2067-52-2	SB	MOUNTING INTERFACE	01-May-85	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
D2067-7	D2067	SB D2067-52-3	SB	MOUNTING INTERFACE	11-Jul-83	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
D2070	D2070	SB D2070-52-1	SB	UPGRADE TO MD-2	15-Aug-94	--	Initial	747/757/767	Grand Rapids	17472, 72121 & 09145	--
D2070	D2070	SB D2070-52-2	SB	NEW MOTOR BRAKE MATERIAL	20-Jul-93	--	Initial	747/757/767	Grand Rapids	17472, 72121 & 09145	--
D2070, -1	D2070	52-30-03	CMM	ROTARY ACTUATOR	01-Apr-99	--	5	747/757/767	Grand Rapids	17472, 72121 & 09145	--
D2070-1	D2070	SB D2070-1	SB	MOD TO -2	01-Aug-78	--	--	747/757/767	Grand Rapids	17472, 72121 & 09145	--
D2070-1	D2070	SB D2070-52-2	SB	NEW MOTOR BRAKE MATERIAL	20-Jul-93	--	Initial	747/757/767	Grand Rapids	17472, 72121 & 09145	--
D2070-11	D2070	SB D2070-52-4	SB	PLUG DRAIN HOLES	30-Sep-96	--	Initial	747/757/767	Grand Rapids	17472, 72121 & 09145	--
D2070-11	D2070	SB D2070-52-7	SB	REPLACEMENT MECH. OVERLOAD CLUTCH	10-Jan-07	--	2	767	Grand Rapids	17472, 72121 & 09145	--
D2070-11	D2070	SB D2070-52-8	SB	REPLACEMENT TORQUE LIMITER ASSY	03-Jul-07	--	3	767	Grand Rapids	17472, 72121 & 09145	--
D2070-11	D2070	SB D2070-52-10	SB	APPLICATION OF THREAD-LOCKING	28-Oct-14	--	Initial	767	Grand Rapids	17472, 72121 & 09145	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
D2070-2	D2070	SB D2070-52-2	SB	NEW MOTOR BRAKE MATERIAL	20-Jul-93	--	Initial	747/757/767	Grand Rapids	17472, 72121 & 09145	--
D2070-2, D2070MD2-1/	D2070	52-30-09	CMM	ROTARY ACTUATOR	25-Jan-11	--	13	747/757/767	Grand Rapids	17472, 72121 & 09145	--
D2070-3	D2070	SB D2070-52-3	SB	NEW BRAKE PLATE MATERIAL	21-Mar-06	--	B	747/757/767	Grand Rapids	17472, 72121 & 09145	--
D2070-3	D2070	SB D2070-52-4	SB	PLUG DRAIN HOLES	30-Sep-96	--	Initial	747/757/767	Grand Rapids	17472, 72121 & 09145	--
D2070-3/-11	D2070	52-34-03	CMM	ROTARY ACTUATOR	27-Sep-10	--	9	747/757/767	Grand Rapids	17472, 72121 & 09145	--
D2070-9	D2070	SB D2070-52-5	SB	REPLACEMENT MECH. OVERLOAD CLUTCH	10-Jan-07	--	3	747	Grand Rapids	17472, 72121 & 09145	--
D2070-9	D2070	SB D2070-52-6	SB	REPLACEMENT TORQUE LIMITER ASSY	06-Jul-07	--	4	747	Grand Rapids	17472, 72121 & 09145	--
D2070-9	D2070	SB D2070-52-9	SB	APPLICATION OF THREAD-LOCKING	28-Oct-14	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
D2070MD-1/-MD-2	D2070	SB D2070-52-2	SB	NEW BRAKE PLATE MATERIAL	20-Jul-93	--	Initial	747/757/767	Grand Rapids	17472, 72121 & 09145	--
D2070MD1-2	D2070	SB D2070-52-2	SB	NEW MOTOR BRAKE MATERIAL	20-Jul-93	--	Initial	747/757/767	Grand Rapids	17472, 72121 & 09145	--
D2070MD-2	D2070	SB D2070-52-2	SB	NEW MOTOR BRAKE MATERIAL	20-Jul-93	--	Initial	747/757/767	Grand Rapids	17472, 72121 & 09145	--
D2163, -1	D2163	32-30-02	CMM	DC MOTOR	15-Aug-99	--	1	*REPLS 32-30-01	Grand Rapids	17472, 72121 & 09145	--
D2173-2	D2173	SB D2173SB1	SB	INSPECTION INTERVALS	26-Sep-83	--	--	--	Grand Rapids	17472, 72121 & 09145	--
D2173-2, -3, -5, -7	D2173	27-53-00*	CMM	WING FLAP ACTUATION SYSTEM	15-Dec-98	--	3	*ONTIC EMBRAER 110/122	Grand Rapids	17472, 72121 & 09145	--
D2173-21	D2173	SB D2173SB1	SB	INSPECTION INTERVALS	26-Sep-83	--	--	--	Grand Rapids	17472, 72121 & 09145	--
D2173-3	D2173	SB D2173SB1	SB	INSPECTION INTERVALS	26-Sep-83	--	--	--	Grand Rapids	17472, 72121 & 09145	--
D2173-31	D2173	SB D2173SB1	SB	INSPECTION INTERVALS	26-Sep-83	--	--	--	Grand Rapids	17472, 72121 & 09145	--
D2173-5	D2173	SB D2173SB1	SB	INSPECTION INTERVALS	26-Sep-83	--	--	--	Grand Rapids	17472, 72121 & 09145	--
D2173-7	D2173	SB D2173SB1	SB	INSPECTION INTERVALS	26-Sep-83	--	--	--	Grand Rapids	17472, 72121 & 09145	--
D2246	D2246	SB D2246-1	SB	WORM GEAR WEAR	10-Feb-76	--	--	--	Grand Rapids	17472, 72121 & 09145	--
D2246	D2246	SB D2246-2	SB	ADD RETAINING RING	16-Jul-76	--	--	--	Grand Rapids	17472, 72121 & 09145	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
D2246	D2246	SB D2246-3	SB	IMPROVED COMPONENTS	13-Nov-80	--	--	--	Grand Rapids	17472, 72121 & 09145	--
D2246-3, -4, -5, -6	D2246	27-53-02*	CMM	Linear Mechanical Actuator	01-Sep-99	--	3	*ONTIC EMBRAER	Grand Rapids	17472, 72121 & 09145	--
D2246-3, -4, -5, -6	D2246	27-53-02	CMM	LINEAR ACTUATOR	01-Oct-83	--	2	--	Grand Rapids	17472, 72121 & 09145	--
D2399-2 /-3	D2399	52-30-04	CMM	NOSE CARGO DOOR DRIVE UNIT	15-Nov-72	22-May-17	7	747	Grand Rapids	17472, 72121 & 09145	--
D2401-10	D2401	52-30-05	CMM	LINEAR LATCH ACTUATOR	02-Aug-02	--	5	747	Grand Rapids	17472, 72121 & 09145	--
D2401-10	D2401	SB D2401-A13193	SB	SHEAR SECTION SHAFT INSPECTION	17-Mar-76	--	A	747	Grand Rapids	17472, 72121 & 09145	--
D2401-10	D2401	SB D2401-52-2	SB	Cargo Door Linear Latch Actuator	01-Aug-84	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
D2401-11	D2401	SB D2401-52-1	SB	Cargo Door Linear Latch Actuator	01-Aug-84	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
D2401-11/-12/-13/-14/	D2401	52-30-14	CMM	LINEAR LATCH ACTUATOR	08-Sep-11	--	10	747	Grand Rapids	17472, 72121 & 09145	--
D2401-12	D2401	SB D2401-52-1	SB	Cargo Door Linear Latch Actuator	01-Aug-84	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
D2401-7	D2401	52-30-05	CMM	LINEAR LATCH ACTUATOR	02-Aug-02	--	5	747	Grand Rapids	17472, 72121 & 09145	--
D2401-7	D2401	SB D2401-A13193	SB	SHEAR SECTION SHAFT INSPECTION	17-Mar-76	--	A	747	Grand Rapids	17472, 72121 & 09145	--
D2401-7	D2401	SB D2401-52-2	SB	Cargo Door Linear Latch Actuator	01-Aug-84	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
D2401-7/-8	D2401	SB 2401-A13208	SB	LIMIT SWITCH	17-Mar-76	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
D2401-7/-8/-9/-10/-11/	D2401	SB D2401-52-1	SB	TIME DELAY RELAY	01-Aug-84	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
D2401-8	D2401	52-30-05	CMM	LINEAR LATCH ACTUATOR	02-Aug-02	--	5	747	Grand Rapids	17472, 72121 & 09145	--
D2401-8	D2401	SB D2401-A13193	SB	SHEAR SECTION SHAFT INSPECTION	17-Mar-76	--	A	747	Grand Rapids	17472, 72121 & 09145	--
D2401-8	D2401	SB D2401-52-2	SB	Cargo Door Linear Latch Actuator	01-Aug-84	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
D2401-9	D2401	52-30-05	CMM	LINEAR LATCH ACTUATOR	02-Aug-02	--	5	747	Grand Rapids	17472, 72121 & 09145	--
D2401-9	D2401	SB 2401-A13208	SB	LIMIT SWITCH	17-Mar-76	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
D2401-9	D2401	SB D2401-A13193	SB	SHEAR SECTION SHAFT INSPECTION	17-Mar-76	--	A	747	Grand Rapids	17472, 72121 & 09145	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
D2401-9	D2401	SB D2401-52-2	SB	Cargo Door Linear Latch Actuator	01-Aug-84	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
D2405-3	D2405	SB D2405-52-1	SB	PRODUCT IMPROVEMENTS	01-Nov-76	--	--	747	Grand Rapids	17472, 72121 & 09145	--
D2405-3, -4, -5	D2405	52-30-06	CMM	PUSH-PULL LINEAR ACTUATOR	20-Oct-11	--	5	747	Grand Rapids	17472, 72121 & 09145	--
D2405-4	D2405	SB D2405-52-2	SB	REPLACE SCREWS	01-Oct-99	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
D2490	D2490	52-42-01*	CMM	RETRACTOR SPRING	01-Jun-84	--	2	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
D2490	D2490	SB D2490-52-42-1*	SB	SHROUD RADIUS	--	--	--	*ONTIC	Grand Rapids	17472, 72121 & 09145	--
D2839-1	D2839	32-30-02	CMM	DC MOTOR	15-Aug-99	--	1	*REPLS 32-30-01	Grand Rapids	17472, 72121 & 09145	--
DC-10	6305	SB 52-160 (DAC)	SB	CARGO DOORS	20-Jan-78	--	Initial	DC-10	Grand Rapids	17472, 72121 & 09145	--
GSE601302-02	6013	SB 6013H-27-5	SB	TEST FIXTURE, LINEAR ACTUATOR	23-Nov-76	--	Initial	747	Grand Rapids	17472, 72121 & 09145	--
RD2067-3	D2067	SB D2067-52-2	SB	MOUNTING INTERFACE	01-May-85	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
RD2067-4	D2067	SB D2067-52-2	SB	MOUNTING INTERFACE	01-May-85	--	Initial	--	Grand Rapids	17472, 72121 & 09145	--
6355D0001	6355D	27-40-13	CMM	STABILIZER TRIM MOTOR	01-Aug-16	12/17/21	4	737MAX	Grand Rapids	17472	--
6355-1230-05,-06,-07,	6355D	27-40-14	CMM	CONTROL PWA	27-Jul-18	12/16/21	2	737MAX	Grand Rapids	17472	--
6355-1220	6355D	27-40-15	CMM	FILTER PWA	27-Jul-18	--	Initial	737MAX	Grand Rapids	17472	--
15886-3	--	32-40-01	CMM	Solenoid Parking Brake Shut-Off	02-May-11	--	Initial	--	Grand Rapids	17472	--
6329E0001-01	6329	SIL 6329E-76-01	SL	ENGINE CONDITION CONTROL_6329E0001-01	04-Feb-15	24-Feb-15	1	767	Grand Rapids	17472	--
497D100-11	497D	SL497D100-01	SL	Horizontal Trim Actuator_497D100-11	14-May-02	01-Apr-03	A	Cessna	Grand Rapids	17472	--
1090D100-1	1090D	SL1090D100-1	SL	POWER DRIVE UNIT INSPECTION_1090D100-1	20-Jun-01	--	Initial	AIRBUS A300	Grand Rapids	17472	--
1090D100-3	1090D	SL1090D100-3	SL	MOTOR SHAFT HARDNESS INSPECTION_1090D100-1	01-May-02	--	Initial	AIRBUS A300	Grand Rapids	17472	--
1090D100-1	1090D	SL1090D100-4	SL	MOTOR SHAFT HARDNESS INSPECTION_1090D100-1	24-Feb-04	--	Initial	AIRBUS A300	Grand Rapids	17472	--
1104SD100	1104SD	1104SD100-SIL-2	SL	FLAP SYSTEM FLEX SHAFT INSPECTION AND EVALUATION_857DSD100, 1104SD100	25-Jan-99	--	Initial	CRJ 200	Grand Rapids	17472	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
1104SD100	1104SD	1104SD100-SIL-3	SL	FLAP SYSTEM FLEX SHAFT INSPECTION AND EVALUATION_1104SD100	08-Jun-06	--	Initial	CRJ 200	Grand Rapids	17472	--
1104SD100-102, -202, -302	1104SD	1104SD100-SIL-4	SL	FLAP SYSTEM FLEX SHAFT APPLICATION OF GREASE LABEL_1104SD101-102, 1104SD100-202, 1104SD100-302, 1104SD100-402	21-Oct-13	--	Initial	CRJ 200	Grand Rapids	17472	--
6094A0001-03	6094A	SL7020A0001-02	SL	FLAP ACTUATOR HALL EFFECT SENSOR RETROFIT_6094A0001-03	01-Sep-09	--	Initial	Embraer P-100	Grand Rapids	17472	--
7622A0001-03	7622A	SL7622A0001-03-01	SL	ONE TIME INSPECT FOR HANDLE JAMMING_7622A0001-03	15-Oct-08	02-Mar-09	1	C-17	Grand Rapids	17472	--
7622A0001-03	7622A	SL7622A0001-03-02	SL	MANDATORY HOUSING ASSY REWORK_7622A0001-03	15-Oct-08	--	Initial	C-17	Grand Rapids	17472	--
7622A0001-03	7622A	SL7622A0001-03-03	SL	REWORK OF HANDLE LOCK CAM_7622A0001-03	07-Mar-13	25-Jan-17	1	C-17	Grand Rapids	17472	--
7624A0001-03	7624A	SL7624A0001-03	SL	FIELD INSPECTION TO PREVENT RESTRICTED MOVEMENT_7624A0001-03	14-Sep-07	02-Nov-07	2	BAE HAWK	Grand Rapids	17472	--
7624D0001-02	7624D	SL7624D0001-02-01	SL	REQUIRED INSPECTION AND MODIFICATION TO ELIMINATE BINDING_7624D0001-02	07-Mar-05	30-Jan-06	3	BAE HAWK	Grand Rapids	17472	--
7624D0001-02	7624D	SL7624D0001-02-02	SL	INSPECTION TO ELIMINATE JAMMING_7624D0001-02	30-Jan-06	26-Jun-08	1	BAE HAWK	Grand Rapids	17472	--
7624D0001-01/-02	7624D	SL7624D0001-02-03	SL	REQUIRED INSPECTION TO PREVENT RESTRICTED MOVEMENT_7624D0001-01, 7624D0001-02	14-Aug-07	17-Oct-08	3	BAE HAWK	Grand Rapids	17472	--
7624D0001-01/-02	7624D	SL7624D0001-03	SL	NOTICE OF POSSIBLE INVERTED INDICATORS_7624D0001-01, 7624D0001-02	03-Oct-06	--	Initial	BAE HAWK	Grand Rapids	17472	--
100000-14	100000	SL100000-14	SL	Notice to Repair Focus Factory of Corresponding Motors/Jackscrews_100000-14	21-Dec-07	--	Initial	C-130	Grand Rapids	17472	--
100000-75	100000	SL100000-75	SL	Notice to Repair Focus Factory of Corresponding Motors/Jackscrews_100000-75	21-Dec-07	--	Initial	--	Grand Rapids	17472	--
7630A0001, 7630F0001	7630A, 7630F, 1073D	SIL G150-27-1	SL	LOW TEMPERATURE HEALTH CHECK_1114D100, 1117D100, 1073D100-13, 1073D100-15	15-Feb-16	22-Mar-17	1	G150	Grand Rapids	17472	--
1114D100, 1117D100, 1073D100-13, 1073D100-15	1114D, 1117D, 1073D	SIL G100-27-1	SL	LOW TEMPERATURE HEALTH CHECK_7630A0001, 7630F0001, 1073D100-21, 1073D100-23, 1073D100-25, 1073D100-28	22-Mar-17	--	Initial	G100	Grand Rapids	17472	--
674D100, 677D100, 673D100	674D, 677D, 673D	SIL 1125-27-082	SL	LOW TEMPERATURE HEALTH CHECK_674D100, 677D100, 673D100	20-Sep-95	22-Mar-17	4	ASSTR 1125	Grand Rapids	17472	--
138400-4, -5	138400	SL138400	SL	138400 CONFIGURATION_138400-4, 138400-5	10-Sep-04	29-Apr-13	3	777	Grand Rapids	17472	--
138400-6	138400	SL138400-06-02	SL	RAM AIR ACTUATOR SPARE PARTS PROVISIONING_138400-6	22-Jul-09	13-Jan-11	1	777	Grand Rapids	17472	--
102000-1, -2, -3, -4, -7, -14	102000	SI102000-1-901	SL	LANDING GEAR ACTUATOR NO-BACK INSPECTION_102000-1, 102000-2, 102000-3, 102000-4, 102000-7, 102000-14	24-Sep-01	03-Apr-03	2	MOONEY M20	Grand Rapids	17472	--
102000-7	1020000	SL102000-1-902	SL	LANDING GEAR ACTUATOR MOTOR REPLACEMENT_102000-7	10-Apr-08	--	Initial	MOONEY M20	Grand Rapids	17472	--
852D100-23/-25	852D	SIL852D100-23/-25	SL	Inboard Flap Actuators - Replacement of Limited Life Components for CRJ100/200 Aircraft_852D100-23, 852D100-25	14-Aug-12	--	Initial	CRJ100/200	Grand Rapids	17472	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
853D100-23/-24	853D	SIL853D100-23/-24	SL	OUTBOARD Flap Actuators – Replacement of Limited Life Components for CRJ100/200 Aircraft_853D100-23_853D100-24	14-Aug-12	--	Initial	CRJ100/200	Grand Rapids	17472	--
854D100-23/-24	854D	SIL854D100-23/-24	SL	OUTBOARD Flap Actuators – Replacement of Limited Life Components for CRJ100/200 Aircraft_854D100-23_854D100-24	14-Aug-12	--	Initial	CRJ100/200	Grand Rapids	17472	--
853D100-19, 20, 854D1	853D/854D	SIL853D100-19-01	SL	FLAP ACTUATOR BOLT INSPECTION	18-Mar-02	--	Initial	CRJ100/200	Grand Rapids	17472	--
1073D100-25-27	1073D	SIL1073D100-27-2	SL	Product Improvement –Implementation of 'C' Improvement_1073D100-25, 1073D100-27	21-Nov-16	13-Oct-17	1	G150	Grand Rapids	17472	--
6013K0001-01	6013K	SIL 6013K-27-1	SL	Availabilty of Component 601389-02 Servo Motor_6013K0001-01	15-Dec-11	--	Initial	747	Grand Rapids	17472	--
6013L0001-01	6013L	SIL 6013L-27-1	SL	Availabilty of Component 601389-02 Servo Motor_6013L0001-01	19-Jan-12	--	Initial	747	Grand Rapids	17472	--
6314N00001-02	6314N	SIL6314N00001-02	SL	Reliabilty/ product improvement_6314N0001-02	18-Jun-10	--	Initial	Learjet	Grand Rapids	17472	--
6329E0001-01	6329E	SIL6329E-76-01	SL	Evaluation of Switch Assemblies_6329E0001-01	04-Feb-15	24-Feb-15	1	767	Grand Rapids	17472	--
6355C0001-01	6355C	SIL6355C0001-27-1	SL	Product Improvement -Replacement of Washer, Mod 8_6355C0001-01	22-Nov-11	--	Initial	737	Grand Rapids	17472	--
6355C0001-01	6355C	SIL6355C0001-27-2	SL	Product Improvement, Implementation of Mod 9	13-Dec-13	03-Jul-14	1	737	Grand Rapids	17472	--
6703A0001-01,-02, -03	6703A	SIL 6703-01	SL	Rotary Posistion Transmitter Assembly_6703A0001-01, 6703A0001-02, 6703A0001-03	08-Dec-14	--	Initial	--	Grand Rapids	17472	--
7906A00001-01,-02	7906A	SIL 7906A00001-01/-02	SL	Evaluation of RVDT Sensor_7906A0001-01, 7906A00001-02	15-Jul-14	02-Feb-15	1	Embraer P-100	Grand Rapids	17472	--
852D100-19, -21	852D	SIL852D100-19/-21	SL	inboard Flap Actuators – replacement of components for sustained Performance_852D100-19, 852D100-21	08-Feb-07	20-Feb-08	2	CRJ100/200	Grand Rapids	17472	--
857SD100-1	857SD	857D100SIL-1	SL	Flex Shaft Assembly_857SD100-1	20-May-93	--	Initial	CRJ100/200	Grand Rapids	17472	--
1075D100-4	1075D	SIL1075D100-27-2	SL	FSECU- Replace of SIP resistor_1075D100-4	25-Mar-11	--	Initial	G150	Grand Rapids	17472	--
130E100-4, -9, -11	130E	SL130E100-52-1	SL	Asbestos Containing Actuators_130E100-4, 130E100-9, 130E100-11	01-Sep-09	--	Initial	747/767	Grand Rapids	17472	--
130E100-13, -15	130E	SL130E100-52-2	SL	MOTOR SHAFT HARDNESS INSPECTION_130E100-13, 130E100-15	24-Feb-04	--	Initial	747/767	Grand Rapids	17472	--
130E100-13	130E	SL130E100-13	SL	Mechanical Drive Housing Replacement_130E100-13	15-May-06	--	Initial	747/767	Grand Rapids	17472	--
130E100-13, -15	130E	SL130E100-1	SL	Power Drive unit Inspaction 130E100-13, 130E100-15	26-Oct-01	--	Initial	747/767	Grand Rapids	17472	--
658D100-3,-5,-7, -9	658D	SL658D100-001	SL	Clarification of Spare Motor Provisioning_658D100-3, 658D100-5, 658D100-7, 658D100-9	28-Oct-04	12-Apr-10	1	747/757/767	Grand Rapids	17472	--
658D100-3,-5,-7, -9	658D	SL658D100-002	SL	Rudder Trim Actuator Part Availabilty_658D100-3, 658D100-5, 658D100-7, 658D100-10	10-Nov-05	--	Initial	747/757/767	Grand Rapids	17472	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
658D100-3,-5,-7, -10	658D	SL658D100-3/-5/-7/-9	SL	Rudder Trim Actuator Modification_658D100-3, 658D100-5, 658D100-7, 658D100-11	30-Mar-02	--	Initial	747/757/767	Grand Rapids	17472	--
658D100-3	658D	SL658D100-3	SL	Rudder Trim Intermittent Operation_658D100-3	01-Mar-90	--	Initial	747/757/768	Grand Rapids	72121	--
664D100-1, -3, -5	664D	SL664D100-52-1	SL	Asbestos Containing Actuators_664D100-1, 6664D100-3, 664D100-5	01-Sep-09	--	Initial	767	Grand Rapids	17472	--
664D100-5, -7	664D	SL664D100-5/-7	SL	Notive of change to Acceptance Testing_664D100-5, 664D100-7	18-Jan-05	--	Initial	767	Grand Rapids	17472	--
684D100-1,-3, -5, -7	684D	SL684D100-27-1	SL	Abestos Containing Actuators_684D100-1, 684D100-3, 684D100-5, 684D100-7, 684D100-9	01-Sep-09	--	Initial	757/767	Grand Rapids	17472	--
684D100-1,-3, -5, -7, -9,	684D	SL684D100-27-2	SL	Spare Parts Provisioning_684D100-1, 684D100-3, 684D100-5, 684D100-7, 684D100-9,684D100-11, 684D100-13, 684D100-15, 684D100-17	17-Jul-14	--	Initial	747/757/767/777	Grand Rapids	17472	--
692D100-9, -13	692D	SL692D100-01	SL	No-Back Assembly Application_692D100-9, 692D100-13	27-Oct-03	20-Jan-04	1	767	Grand Rapids	17472	--
724D100-1	724D	SL724D100-32-1	SL	Abestos Containing Actuators_724D100-1	01-Sep-09	--	Initial	767	Grand Rapids	17472	--
852D100-19	852D	SL852D100-27-05	SL	Ballscrew Axial Endplay Check_852D100-19	26-Mar-07	--	Initial	CRJ100/200	Grand Rapids	17472	--
852D100-23, -25	852D	SL852D100-27-06	SL	Flap Actuator Torque Limiter Reset Verification-After Modification_852D100-23, 852D100-25	14-Mar-08	25-Mar-08	1	CRJ100/200	Grand Rapids	17472	--
852D100-21	852D	SL852D100-27-07	SL	Pinion Gear P/N 852SE174 Retrofit Program_852D100-21	14-Apr-08	04-Feb-09	1	CRJ100/200	Grand Rapids	17472	--
855D100-11	855D	SL855D100-11	SL	BPSU POTENTIOMETER RETROFIT PROGRAM_855D100-11	10-Dec-02	--	Initial	CRJ100/200	Grand Rapids	17472	--
852D100-19, 853D100-19	852D853D854D	SL864D100-27-01	SL	FLAP ACTUATOR TORQUE LIMITER RESET- RETROFIT PROGRAM_852D100-19, 853D100-19, 853D100-20,	06-Nov-06	25-Feb-08	1	CRJ100/200	Grand Rapids	17472	--
852D100-19, 853D100-19	852D853D854D	SL864D100-27-02	SL	Actuator Serial Number Identification on In-Service Units_852D100-19, 853D100-19, 853D100-20, 854D100-19, 854D100-20, 854D100-21, 854D100-22	03-Jan-08	--	Initial	CRJ100/200	Grand Rapids	17472	--
852D100-25, 853D100-25	852D853D854D	SL864D100-27-03	SL	FLAP ACTUATOR TORQUE LIMITER RESET- RETROFIT PROGRAM_852D100-25, 853D100-23, 854D100-23	11-Dec-08	--	Initial	CRJ100/200	Grand Rapids	17472	--
924D100-1	924D	SL924D100-27-1	SL	AUTO GROUND SPEEDBRAKE ACTUATOR-SPARE PARTS PROVISIONING_924D100-1	16-Jun-14	--	Initial	777	Grand Rapids	17472	--
6355B0001-03	6355B	SL6355B0001-4	SL	6355-0130 DC-DC CONVERTER_6355B0001-03	09-Oct-03	--	Initial	737	Grand Rapids	17472	--
6355B0001-02,-03	6355B	SL6355B0001-5	SL	6355B0001 UNCONFORMED FAILURES_6355B0001-02, 6355B0001-03	24-Aug-04	--	Initial	737	Grand Rapids	17472	--
6355B0001-02,-03	6355B	SL6355B0001-6	SL	STABILIZER TRIM MOTOR EMI FILTER_6355B0001-02, 6355B0001-03	01-Oct-05	27-Oct-05	1	737	Grand Rapids	17472	--
6355B0001-02,-03	6355B	SL6355B0001-7	SL	STM PENDING PRODUCT REPAIR OBSOLESCENCE_6355B0001-02, 6355B0001-03	25-Mar-11	--	Initial	737	Grand Rapids	17472	--
6355B0001-02,-03	6355B	SL6355B0001-8	SL	6355B0001-2/-3 HSTM OBSOLESCENCE_6355B0001-02, 6355B0001-03	27-Feb-14	--	Initial	737	Grand Rapids	17472	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
D2063, -1,-6,-7,-9,-11,-1	D2063	SL-D2063-52-1	SL	PRODUCT IMPROVEMENT AND OBSOLESCENCE_D2063, D2063-1, D2063-6, D2063-7, D2063-9, D2063-11, D2063-12	30-Apr-03	--	Initial	747	Grand Rapids	17472	--
D2063-9/-11	D2063	SL-D2063-52-2	SL	MECHANICAL OVERLOAD CLUTCH REPLACEMENT	18-Aug-04	--	Initial	747	Grand Rapids	17472	--
D2063, -1,-6,-7,-9, MD-1	D2063	SL-D2063-52-3	SL	ASBESTOS CONTAINING ACTUATORS_D2063, D2063-1, D2063-6, D2063-7, D2063-9, D2063MD-1, D2063MD1-1, D2063MD1-2	01-Sep-09	--	Initial	747	Grand Rapids	17472	--
D2067-8, -9	D2067	SL D2067-52-1	SL	PREVENTITIVE MAINTENANCE-LUBRICATION _D2067-8, D2067-9	25-Jan-17	22-May-17	1	747	Grand Rapids	17472	--
D2070-2, -9	D2070	SL D2070-52-01	SL	Rotary Actuators – Clarification of Actuator Part Number Designation_D2070-2, D2070-9	27-Apr-09	09-Jun-09	1	747	Grand Rapids	17472	--
D2070, -1, -2, MD1-2, M	D2070	SL D2070-52-2	SL	ASBESTOS CONTAINING ACTUATORS_D2070, D2070-1, D2070-2, D2070MD1-2, D2070MD-2, D2070-3	01-Sep-09	--	Initial	747	Grand Rapids	17472	--
D2399-2 /-3	D2399	SL D2399-1	SL	ELIMINATION OF B5963 STIFFENERS_D2399-2, D2399-3	13-May-04	--	Initial	747	Grand Rapids	17472	--
D2399-2	D2399	SL D2399-02	SL	D2399 CONFIGURATIONS_D2399-2	11-Mar-05	18-Jan-11	2	747	Grand Rapids	17472	--
D2399-2 /-3	D2399	SL D2399	SL	D2586 COVER REWORK_D2399-2, D2399-3	22-Apr-04	--	Initial	747	Grand Rapids	17472	--
D2401-11,-12,-13,-14	D2401	SL D2401-52-1	SL	Asbestos Containing Actuators_D2401-11, D2401-12, D2401-13, D2401-15	01-Sep-09	--	Initial	747	Grand Rapids	17472	--
D2405-3,-4	D2405	SL D2405-52-3	SL	Asbestos Containing Actuators_D2405-3, D2405-4	01-Sep-09	--	Initial	747	Grand Rapids	17472	--
8025A0001-04, -05	8025A	SL UMGSE702004S001-	SL	EMB 500 Flap Rigging Tool User Manual_8025A0001-04, 8025A0001-05	12-Mar-10	--	Initial	Embraer P-100	Grand Rapids	17472	--
6314N0001-02	6314N	SL6314N0001-02-01	SL	FINAL FUNCTIONAL CHECK PROCEDURE, OUTBOUND UNITS_6314N0001-02	29-Mar-12	--	Initial	LEARJET	Grand Rapids	17472	--
631500-01, -02, -03, -04	6315	SIL6315-01	SL	ELECTRIC POWERED ROLLER ASSEMBLY_631500-01, 631500-02, 631500-03, 631500-04, 6315E0001-01, 6315E0001-01, 6315E0001-01	17-Jun-03	--	Initial	DC-10/ MD-11	Grand Rapids	17472	--
964D100-1	964D	SL964D100-1	SL	Cargo Door Lift Latch Actuator Assembly Notice of Change to Acceptance Testing_964D100-1	18-Jan-05	--	Initial	777	Grand Rapids	17472	--
806D100-1	806D	SL806D100-1	SL	SECOND AND THIRD STAGE CARRIER REPLACEMENT_806D100-1	08-Mar-04	--	Initial	MD-11	Grand Rapids	17472	--
807D100-1	807D	SL807D100-1	SL	SECOND AND THIRD STAGE CARRIER REPLACEMENT_807D100-1	08-Mar-04	--	Initial	MD-11	Grand Rapids	17472	--
855D100-9	855D	SL855D100-9	SL	UNITS WITH NO FAULT FOUND_855D100-9	09-Dec-03	--	Initial	CRJ100/200	Grand Rapids	17472	--
865D100-7	865D	SL865D100	SL	865D144 HOUSING REWORK_865D100-7	--	10-Dec-02	1	CRJ100/200	Grand Rapids	17472	--
1073D100-13/-15	1075D	SL1075D101-13-01	SL	FIELD UNITS "AB" MANDATORY UPGRADE- INSPECTION_1075D100-13, 1075D100-13	11-Feb-04	--	Initial	G150	Grand Rapids	17472	--
6328A0001-01	6328A	SL6328A0001-01	SL	CARGO ROLLER UNIT DISCLOSURE_6328A0001-01	03-Jan-02	--	Initial	DC-10/ MD-11	Grand Rapids	17472	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
40574 (3715)	--	28-20-01	CMM	ACTUATOR	--	11/25/03	8	B727/B737	Eaton Irvine	86090	SB61163-28-09; SB3715-20-05
40574-2 (3715-7)	--	28-20-01	CMM	ACTUATOR	--	11/25/03	8	B727	Eaton Irvine	86090	SB61163-28-09; SB3715-20-05; SB138
40574-4(EM487-4)	--	28-20-33	CMM	ACTUATOR (DC)	--	APR17/2015	5	B727/B737	Eaton Irvine	86090	SB40574-28-01; SB61163-28-08 SB61163-28-01 SB61163-28-00
40575 (3360)	--	28-20-03	CMM	ACTUATOR	--	06/25/02	7	B727	Eaton Irvine	86090	SB3360-20-01 SB12.1.3360
40665(3715-1)	--	NONE	CMM	ACTUATOR	--	07/01/77	1	B737	Eaton Irvine	86090	--
40884-1,-3,-4, -6,	--	28-23-53	CMM	VALVE UNIT	--	SEP 20/2011	1	B747/B757/B767	Eaton Irvine	86090	SB60160-28-4
40884-7, -23	--	28-20-29	CMM	VALVE UNIT	--	SEP 16/2011	1	B757/B777	Eaton Irvine	86090	--
40884-8	--	28-20-37	CMM	VALVE UNIT	--	AUG 31/2011	1	B777	Eaton Irvine	86090	--
40885-2, -4, -10	--	28-20-32	CMM	CONTROL UNIT	--	SEP 17/2015	5	B747/B757/B767	Eaton Irvine	86090	SB60160-28-4; SB40885-28-01
40885-5,-7	--	28-20-30	CMM	CONTROL UNIT	--	SEP 12/2011	2	B757/B777	Eaton Irvine	86090	SB40885-28-02
40885-8	--	28-20-36	CMM	CONTROL UNIT	--	AUG 5/2011	1	B777	Eaton Irvine	86090	SIL40885-8_122015
40885-24	--	28-20-34	CMM	CONTROL UNIT	--	JAN20/00	--	B767-400	Eaton Irvine	86090	--
4982	--	NONE	CMM	MOTOR ASSEMBLY	--	08/29/89	B	CONV 580	Eaton Irvine	86090	--
60007-1	--	28-20-22	CMM	REFUEL OVERPRESS REG	--	15-Oct-91	--	DC9/MD80	Eaton Irvine	86090	--
60051/60128	--	*	CMM	(*SEE 61183/61185)	--	--	--	*	Eaton Irvine	86090	--
60102	--	28-20-08	CMM	FUEL SCAVENGE EJECTOR	--	01-Jun-71	--	DC10/L1011	Eaton Irvine	86090	--
60127/ 6568	--	28-20-3	CMM	MANUAL FUEL SHUTOFF VLV	--	22-Sep-67	--	B727/B737	Eaton Irvine	86090	SB162, SB162A
60160-SERIES	--	28-20-05	CMM	PRESS FUEL SHUTOFF VLV	--	NOV 17/2016	10	B747/B757/B767	Eaton Irvine	86090	SIL60160-28-1 SIL60160-28-3 SB60160- 28-4 SB115
60160-8	--	**	CMM	**SEE 40885-5, -7 & 40884-7	--	--	--	B777-200	Eaton Irvine	86090	**
60213- SERIES	--	28-23-68	CMM	PRESS FUEL RECEPT & DEFUELING VALVE ASSEMBLY	--	Mar 20/2015	2	B747/B707/B767	Eaton Irvine	86090	SIL60213-28-2
60273-3,-4	--	82-20-03	CMM	WATER INJECTION PUMP	--	10/05/72	1	B747	Eaton Irvine	86090	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
60273-6 THRU -9	--	82-20-07	CMM	WATER INJECTION PUMP	--	05/01/75	1	B747	Eaton Irvine	86090	SB129
60281, -1	--	82-20-04	CMM	WATER INJECTION CHECK VALVE	--	08/15/72	1	B747	Eaton Irvine	86090	SB117
60324	--	28-20-07	CMM	FUEL/ WATER SCAVENGE EJECT	--	01/07/1970	--	DC10/MD11/ L1011	Eaton Irvine	86090	--
60456, -1	--	82-20-06	CMM	WATER INJECTION PUMP	--	--	1	DC10	Eaton Irvine	86090	--
60490	--	28-51-05	CMM	FUEL PRESSURE REG ASSEMBLY	--	--	--	BEECH	Eaton Irvine	86090	--
60605	--	28-20-09	CMM	M.O. FUEL SHUTOFF VALVE	--	12/28/1973	--	B727	Eaton Irvine	86090	SB162
60785	--	NONE	CMM	SURGE TANK/ PRESSURE RELIEF VALVE	--	01/10/1976	--	B737	Eaton Irvine	86090	--
61162	--	28-20-17	CMM	FUEL SHUTOFF VALVE	--	10/15/95	1	B737	Eaton Irvine	86090	SB162A
61163	--	28-20-18	CMM	FUEL SHUTOFF VALVE	--	APR 12/2013	5	B737	Eaton Irvine	86090	SB138, SB162A, SB61163-28-01, SB61163-28-02/03, SB61163-28-04, SB61163-28-05
61183, 61185	--	28-20-02	CMM	FUEL SHUTOFF VALVE	--	11/1/96	3	B727/B737	Eaton Irvine	86090	SB61183-28-02, SB61183-28-03, SB61163-28-08, SB61163-28-09, SB61163-28-01, SB129
61520-7, -8, -11, -12	--	28-26-52	CMM	DUAL REGULATED AERIAL PRESSURE REFUEL COUPLING	--	JUN 14/2013	2	KC-10; A330	Eaton Irvine	86090	--
61560-1	--	28-20-23	CMM	REFUEL VALVE	--	15-Mar-92	--	J-41	Eaton Irvine	86090	--
61561	--	28-20-24	CMM	REFUEL SOLENOID VALVE	--	15-Mar-92	--	J-41	Eaton Irvine	86090	--
61562	--	28-20-25	CMM	REFUEL/ DEFUEL COUPLING	--	15-Mar-92	--	J-41	Eaton Irvine	86090	--
61563	--	28-20-26	CMM	DEFUEL VALVE	--	15-Mar-92	--	J-41	Eaton Irvine	86090	--
61564	--	28-20-27	CMM	CHECK VALVE	--	15-Mar-92	--	J-41	Eaton Irvine	86090	--
6173	--	82-1-1	CMM	WATER INJECTION PUMP	--	31-Jan-58	--	B707	Eaton Irvine	86090	--
6173-1	--	NONE	--	WATER INJECTION PUMP	--	21-Jan-72	--	DC8	Eaton Irvine	86090	--
6187-1	--	28-1-1	CMM	REGULATOR VALVE	--	05-May-61	--	880/990	Eaton Irvine	86090	--
6191-1THRU-8,-13	--	28-1-1	CMM	FUEL JETTISON PUMP	--	15-Mar-62	--	880/990	Eaton Irvine	86090	--
6211	--	38-1-1	CMM	WATER CHECK/ DRAIN VALVE	--	01-Dec-58	--	B707	Eaton Irvine	86090	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
6347	--	--	CMM	(SEE 61871-1)	--	--	--	--	Eaton Irvine	86090	--
6523, -1	--	82-1-2	CMM	WATER INJECTION PUMP	--	09/29/65	1	B707	Eaton Irvine	86090	SB103, SB108
6535, -3	--	28-20-4	CMM	BOOST PUMP BYPASS CHECK VALVE	--	2/7/68	--	B727/B737	Eaton Irvine	86090	--
6562	--	28-20-1	CMM	M.O. FUEL SHUTOFF VALVE	--	06/27/68	2	B727	Eaton Irvine	86090	SB162
6563	--	--	CMM	(SEE 60128, 61183/ 61185)	--	--	--	--	Eaton Irvine	86090	--
6864	--	NONE	--	WATER ALCOHOL INJECTOR PUMP	--	08/29/89	A	CONV 580	Eaton Irvine	86090	--
6867	--	--	CMM	(SEE 60007-1)	--	--	--	--	Eaton Irvine	86090	--
6956-2	--	82/20/01	CMM	WATER METHANOL INJECTOR PUMP	--	30/03/1967	--	CONV 600	Eaton Irvine	86090	--
AE708821-1	AA118	24-20-01	CMM	Teflon Hose Assemblies	--	01-Aug-91	R0	A340/CFM56-5C2	Jackson, MI	00624	--
AE708821-2	AA118	24-20-01	CMM	Teflon Hose Assemblies	--	01-Aug-91	R0	A340/CFM56-5C2	Jackson, MI	00624	--
AE94794M	ASB107	25-65-11	CMM	Escape Slide Coupling	--	01-Jul-76	R1	B747	Jackson, MI	00624	--
AE708816-2	AA117	28-20-01	CMM	Teflon Hose Assemblies	--	01-Aug-91	R0	A340	Jackson, MI	00624	--
AE708817-2	AA137	28-20-02	CMM	Teflon Hose Assemblies	--	01-May-03	R0	A340	Jackson, MI	00624	--
AE708817-3	AA137	28-20-02	CMM	Teflon Hose Assemblies	--	01-May-03	R0	A340	Jackson, MI	00624	--
AE708817-4	AA137	28-20-02	CMM	Teflon Hose Assemblies	--	01-May-03	R0	A340	Jackson, MI	00624	--
AE703242-1	ASB81	28-21-01	CMM	Fuel Line Assemblies and Coupling Half	--	01-Nov-05	R3	B747	Jackson, MI	00624	--
AE703242-2	ASB81	28-21-01	CMM	Fuel Line Assemblies and Coupling Half	--	01-Nov-05	R3	B747	Jackson, MI	00624	--
AE94639Z	ASB81	28-21-01	CMM	Fuel Line Assemblies and Coupling Half	--	01-Nov-05	R3	B747	Jackson, MI	00624	--
AE707418-1	AA161A	28-32-18	CMM	Teflon Hose Assemblies	--	01-Feb-13	B	A320/CFM56-5	Jackson, MI	00624	--
AE707419-1	AA161A	28-32-18	CMM	Teflon Hose Assemblies	--	01-Feb-13	B	A320/CFM56-5	Jackson, MI	00624	--
AE707419-3	AA161A	28-32-18	CMM	Teflon Hose Assemblies	--	01-Feb-13	B	A320/CFM56-5	Jackson, MI	00624	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
AE707420-2	AA161A	28-32-18	CMM	Teflon Hose Assemblies	--	01-Feb-13	B	A320/CFM56-5	Jackson, MI	00624	--
AE705925-31	AA161A	28-32-18	CMM	Teflon Hose Assemblies	--	01-Feb-13	B	A320/CFM56-5	Jackson, MI	00624	--
AE705926-17	AA161A	28-32-18	CMM	Teflon Hose Assemblies	--	01-Feb-13	B	A320/CFM56-5	Jackson, MI	00624	--
AE705926-21	AA161A	28-32-18	CMM	Teflon Hose Assemblies	--	01-Feb-13	B	A320/CFM56-5	Jackson, MI	00624	--
AE705926-23	AA161A	28-32-18	CMM	Teflon Hose Assemblies	--	01-Feb-13	B	A320/CFM56-5	Jackson, MI	00624	--
AE705926-24	AA161A	28-32-18	CMM	Teflon Hose Assemblies	--	01-Feb-13	B	A320/CFM56-5	Jackson, MI	00624	--
AE705926-25	AA161A	28-32-18	CMM	Teflon Hose Assemblies	--	01-Feb-13	B	A320/CFM56-5	Jackson, MI	00624	--
AE95615G	ASB85	29-00-01	CMM	Spoiler System Swivel Joint	--	01-Mar-70	R0	B707	Jackson, MI	00624	--
AE706293-1	ASB134	29-00-01	CMM	Hydraulic Hose Assemblies	--	05-Jun-05	--	B737	Jackson, MI	00624	Superseded by 29-00-03
AE706293-2	ASB134	29-00-01	CMM	Hydraulic Hose Assemblies	--	05-Jun-05	--	B737	Jackson, MI	00624	Superseded by 29-00-03
AE706293-3	ASB134	29-00-01	CMM	Hydraulic Hose Assemblies	--	05-Jun-05	--	B737	Jackson, MI	00624	Superseded by 29-00-03
AE706293-10	ASB134	29-00-01	CMM	Hydraulic Hose Assemblies	--	05-Jun-05	--	B737	Jackson, MI	00624	Superseded by 29-00-03
AE89205G	NA	29-00-02	CMM	Type 3200 Hose-Attaching Self Sealing Quick Disconnect Coupling Half	--	01-May-95	R0	MD-90	Jackson, MI	00624	--
AE89206K	NA	29-00-02	CMM	Type 3200 Hose-Attaching Self Sealing Quick Disconnect Coupling Half	--	01-May-95	R0	MD-90	Jackson, MI	00624	--
AE706293-12	ASB139	29-00-03	CMM	Hydraulic Hose Assemblies	--	01-Oct-84	R0	B737	Jackson, MI	00624	--
AE706293-14	ASB139	29-00-03	CMM	Hydraulic Hose Assemblies	--	01-Oct-84	R0	B737	Jackson, MI	00624	--
AE706293-15	ASB139	29-00-03	CMM	Hydraulic Hose Assemblies	--	01-Oct-84	R0	B737	Jackson, MI	00624	--
AE706293-17	ASB139	29-00-03	CMM	Hydraulic Hose Assemblies	--	01-Oct-84	R0	B737	Jackson, MI	00624	--
AE702872-1	ASB82	29-09-01	CMM	Hydraulic Hose Assemblies	--	01-Oct-69	R0	B747	Jackson, MI	00624	--
AE702875-2	ASB82	29-09-01	CMM	Hydraulic Hose Assemblies	--	01-Oct-69	R0	B747	Jackson, MI	00624	--
AE702875-3	ASB82	29-09-01	CMM	Hydraulic Hose Assemblies	--	01-Oct-69	R0	B747	Jackson, MI	00624	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
AE702876-1	ASB82	29-09-01	CMM	Hydraulic Hose Assemblies	--	01-Oct-69	R0	B747	Jackson, MI	00624	--
AE702876-2	ASB82	29-09-01	CMM	Hydraulic Hose Assemblies	--	01-Oct-69	R0	B747	Jackson, MI	00624	--
AE703104-1	ASB82	29-09-01	CMM	Hydraulic Hose Assemblies	--	01-Oct-69	R0	B747	Jackson, MI	00624	--
AE703105-1	ASB82	29-09-01	CMM	Hydraulic Hose Assemblies	--	01-Oct-69	R0	B747	Jackson, MI	00624	--
AE703105-2	ASB82	29-09-01	CMM	Hydraulic Hose Assemblies	--	01-Oct-69	R0	B747	Jackson, MI	00624	--
AE95826N	ASB87	29-09-02	CMM	Self-Sealing Adapters	--	01-Dec-81	R2	DC-10	Jackson, MI	00624	--
AE96211M	ASB87	29-09-02	CMM	Self-Sealing Adapters	--	01-Dec-81	R2	DC-10	Jackson, MI	00624	--
AE96212K	ASB87	29-09-02	CMM	Self-Sealing Adapters	--	01-Dec-81	R2	DC-10	Jackson, MI	00624	--
AE96213M	ASB87	29-09-02	CMM	Self-Sealing Adapters	--	01-Dec-81	R2	DC-10	Jackson, MI	00624	--
AE96214K	ASB87	29-09-02	CMM	Self-Sealing Adapters	--	01-Dec-81	R2	DC-10	Jackson, MI, Tijuana, MX	00624	--
AE96412N	ASB87	29-09-02	CMM	Self-Sealing Adapters	--	01-Dec-81	R2	DC-10	Jackson, MI	00624	--
AE96692N	ASB87	29-09-02	CMM	Self-Sealing Adapters	--	01-Dec-81	R2	DC-10	Jackson, MI	00624	Superseded by AE96787N
AE96787N	ASB87	29-09-02	CMM	Self-Sealing Adapters	--	01-Dec-81	R2	DC-10	Jackson, MI, Tijuana, MX	00624	--
AE97908N	ASB87	29-09-02	CMM	Self-Sealing Adapters	--	01-Dec-81	R2	DC-10	Jackson, MI	00624	--
AE98033N	ASB87	29-09-02	CMM	Self-Sealing Adapters	--	01-Dec-81	R2	DC-10	Jackson, MI	00624	--
AE98434N	ASB87	29-09-02	CMM	Self-Sealing Adapters	--	01-Dec-81	R2	DC-10	Jackson, MI	00624	--
AE95394M	ASB89	29-09-03	CMM	Self-Sealing Couplings	--	01-Dec-71	R1	DC-10	Jackson, MI, Tijuana, MX	00624	--
AE95396P	ASB89	29-09-03	CMM	Self-Sealing Couplings	--	01-Dec-71	R1	DC-10	Jackson, MI, Tijuana, MX	00624	--
AE95473P	ASB89	29-09-03	CMM	Self-Sealing Couplings	--	01-Dec-71	R1	DC-10	Jackson, MI	00624	--
AE95614G	ASB92	29-09-04	CMM	Self-Sealing Couplings	--	01-Dec-81	R2	A340	Jackson, MI, Tijuana, MX	00624	--
AE95733P	ASB92	29-09-04	CMM	Self-Sealing Couplings	--	01-Dec-81	R2	A340	Jackson, MI	00624	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
AE95798K	ASB92	29-09-04	CMM	Self-Sealing Couplings	--	01-Dec-81	R2	A340	Jackson, MI, Tijuana, MX	00624	--
AE95997P	ASB92	29-09-04	CMM	Self-Sealing Couplings	--	01-Dec-81	R2	A340	Jackson, MI, Tijuana, MX	00624	--
AE81266P	ASB92	29-09-04	CMM	Self-Sealing Couplings	--	01-Dec-81	R2	A340	Jackson, MI, Tijuana, MX	00624	--
AE95613H	ASB93	29-09-05	CMM	Self-Sealing Couplings	--	01-Dec-71	R1	A340	Jackson, MI, Tijuana, MX	00624	--
AE95817K	ASB93	29-09-05	CMM	Self-Sealing Couplings	--	01-Dec-71	R1	A340	Jackson, MI, Tijuana, MX	00624	--
AE97003J	ASB112	29-09-06	CMM	Self-Sealing Coupling Halves	--	01-Apr-74	R0	A300, A310	Jackson, MI, Tijuana, MX	00624	--
AE97004J	ASB112	29-09-06	CMM	Self-Sealing Coupling Halves	--	01-Apr-74	R0	A300, A310	Jackson, MI, Tijuana, MX	00624	--
AE96927E	ASB113	29-09-07	CMM	Heavy Duty Plane Swivel Joint Assemblies	--	01-Apr-74	R0	A300	Jackson, MI	00624	--
AE96928E	ASB113	29-09-07	CMM	Heavy Duty Plane Swivel Joint Assemblies	--	01-Apr-74	R0	A300	Jackson, MI	00624	--
AE96993E	ASB103	29-09-08	CMM	Self-Sealing Coupling	--	01-Sep-73	R0	A300, A310, A320, A340	Jackson, MI, Tijuana, MX	00624	--
AE96995P	ASB95	29-09-09	CMM	Self-Sealing Couplings	--	01-Apr-11	R2	A300, A310, A330	Jackson, MI, Tijuana, MX	00624	--
AE96996P	ASB95	29-09-09	CMM	Self-Sealing Couplings	--	01-Apr-11	R2	A300, A310, A330	Jackson, MI, Tijuana, MX	00624	--
AE96997M	ASB95	29-09-09	CMM	Self-Sealing Couplings	--	01-Apr-11	R2	A300, A310, A330	Jackson, MI, Tijuana, MX	00624	--
AE97048P	ASB95	29-09-09	CMM	Self-Sealing Couplings	--	01-Apr-11	R2	A300, A310, A330	Jackson, MI, Tijuana, MX	00624	--
AE94185N	ASB75	29-09-11	CMM	Hydraulic Couplings	--	01-Jan-70	R0	B747	Jackson, MI, Tijuana, MX	00624	--
AE94185P	ASB75	29-09-11	CMM	Hydraulic Couplings	--	01-Jan-70	R0	B747	Jackson, MI, Tijuana, MX	00624	--
AE84760Z	ASB151	29-09-15	CMM	Swivel Joint Assembly	--	01-Apr-15	R1	A320	Jackson, MI	00624	Limited Repair Capability
AE76853G	ASB151	29-09-15	CMM	Swivel Joint Assembly	--	01-Apr-15	R1	A320	Jackson, MI, Tijuana, MX	00624	--
AE80531K	ASB150	29-10-01	CMM	Self Sealing Quick Disconnect Coupling Assembly	--	01-Dec-09	R4	A320	Jackson, MI, Tijuana, MX	00624	Being Revised 11-2017
AE80532N	ASB150	29-10-01	CMM	Self Sealing Quick Disconnect Coupling Assembly	--	01-Dec-09	R4	A320	Jackson, MI, Tijuana, MX	00624	Being Revised 11-2017
AE86195G	ASB152	29-10-02	CMM	Fill Valve Assembly	--	01-Sep-99	R0	A320, A330, A340	Jackson, MI, Tijuana, MX	00624	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
AE99118J	ASB153	29-10-03	CMM	Bulkhead Self Sealing Quick Disconnect Coupling Half Assembly	--	01-Feb-89	R0	CL600	Jackson, MI	00624	--
AE99119J	ASB153	29-10-03	CMM	Bulkhead Self Sealing Quick Disconnect Coupling Half Assembly	--	01-Feb-89	R0	CL600	Jackson, MI, Tijuana, MX	00624	--
AE96993E	ASB154	29-10-04	CMM	Bulkhead Self Sealing Quick Disconnect Coupling Half Assembly	--	01-Feb-89	R0	A300, A310, A320, A340	Jackson, MI, Tijuana, MX	00624	--
AE90328E	ASB157	29-10-05	CMM	Bulkhead Self Sealing Quick Disconnect Coupling Half Assembly	--	01-Dec-87	R0	DC-9	Jackson, MI	00624	--
AE90328G	ASB157	29-10-05	CMM	Bulkhead Self Sealing Quick Disconnect Coupling Half Assembly	--	01-Dec-87	R0	DC-9	Jackson, MI, Tijuana, MX	00624	--
AE90328K	ASB157	29-10-05	CMM	Bulkhead Self Sealing Quick Disconnect Coupling Half Assembly	--	01-Dec-87	R0	DC-9	Jackson, MI	00624	--
AE99116K	ASB169A	29-10-05	CMM	Bulkhead Self Sealing Quick Disconnect Coupling Half Assembly	--	01-Aug-97	R0	A320, A321	Jackson, MI, Tijuana, MX	00624	--
AE99118K	ASB169A	29-10-05	CMM	Bulkhead Self Sealing Quick Disconnect Coupling Half Assembly	--	01-Aug-97	R0	A320, A321	Jackson, MI, Tijuana, MX	00624	--
AE99119K	ASB169A	29-10-05	CMM	Bulkhead Self Sealing Quick Disconnect Coupling Half Assembly	--	01-Aug-97	R0	A320, A321	Jackson, MI, Tijuana, MX	00624	--
AE90420Z	ASB158	29-10-06	CMM	Bulkhead Self Sealing Quick Disconnect Coupling Half Assembly	--	01-Dec-87	R0	BAE JS41, DC-9	Jackson, MI	00624	--
AE90573E	ASB159	29-10-07	CMM	Hose Half Self Sealing Quick Disconnect Coupling Half Assembly	--	01-Dec-87	R0	DC-9	Jackson, MI	00624	--
AE90573G	ASB159	29-10-07	CMM	Hose Half Self Sealing Quick Disconnect Coupling Half Assembly	--	01-Dec-87	R0	DC-9	Jackson, MI, Tijuana, MX	00624	--
AE90573K	ASB159	29-10-07	CMM	Hose Half Self Sealing Quick Disconnect Coupling Half Assembly	--	01-Dec-87	R0	DC-9	Jackson, MI	00624	--
AE708818-1	AA113	29-10-11	CMM	Teflon Hose Assemblies	--	01-Aug-91	R0	A340	Jackson, MI	00624	--
AE708819-1	AA116	29-10-12	CMM	Teflon Hose Assemblies	--	01-Aug-91	R0	A340	Jackson, MI	00624	--
AE708820-1	AA116	29-10-12	CMM	Teflon Hose Assemblies	--	01-Aug-91	R0	A340	Jackson, MI	00624	--
AE708822-3	AA115A	29-10-14	CMM	Aeroquip Teflon Hose Assemblies	--	01-Jan-05	R1	A340	Jackson, MI	00624	--
AC115-08H0115	NA	29-10-15	CMM	Medium and High Pressure Teflon Hose Assemblies	--	01-Apr-12	R0	NA	Jackson, MI, Tijuana, MX	00624	--
AC1635A20H0214	NA	29-10-15	CMM	Medium and High Pressure Teflon Hose Assemblies	--	01-Apr-12	R0	NA	Jackson, MI	00624	--
AE1010743M0187	NA	29-10-15	CMM	Medium and High Pressure Teflon Hose Assemblies	--	01-Apr-12	R0	NA	Jackson, MI	00624	--
AE1010744M0174	NA	29-10-15	CMM	Medium and High Pressure Teflon Hose Assemblies	--	01-Apr-12	R0	NA	Jackson, MI	00624	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
AC1634A20H0144	NA	29-10-15	CMM	Medium and High Pressure Teflon Hose Assemblies	--	01-Apr-12	R0	NA	Jackson, MI	00624	--
AE1010563N0144	NA	29-10-15	CMM	Medium and High Pressure Teflon Hose Assemblies	--	01-Apr-12	R0	NA	Jackson, MI	00624	--
AC116-08H0180	NA	29-10-15	CMM	Medium and High Pressure Teflon Hose Assemblies	--	01-Apr-12	R0	NA	Jackson, MI, Tijuana, MX	00624	--
AE3663	ASB114	29-11-01	CMM	Teflon Hose Assemblies	--	01-Jul-76	R0	DC-10	Jackson, MI, Tijuana, MX	00624	--
AE3668	ASB114	29-11-01	CMM	Teflon Hose Assemblies	--	01-Jul-76	R0	DC-10	Jackson, MI	00624	--
AE3669	ASB114	29-11-01	CMM	Teflon Hose Assemblies	--	01-Jul-76	R0	DC-10	Jackson, MI	00624	--
AE704322-1	ASB114	29-11-01	CMM	Teflon Hose Assemblies	--	01-Jul-76	R0	DC-10	Jackson, MI	00624	--
AE704323-1	ASB114	29-11-01	CMM	Teflon Hose Assemblies	--	01-Jul-76	R0	DC-10	Jackson, MI	00624	--
AE704324-1	ASB114	29-11-01	CMM	Teflon Hose Assemblies	--	01-Jul-76	R0	DC-10	Jackson, MI	00624	--
AE1007313	ASB114	29-11-01	CMM	Teflon Hose Assemblies	--	01-Jul-76	R0	DC-10	Jackson, MI	00624	--
AE1007868	ASB114	29-11-01	CMM	Teflon Hose Assemblies	--	01-Jul-76	R0	DC-10	Jackson, MI	00624	--
AE1008713	ASB114	29-11-01	CMM	Teflon Hose Assemblies	--	01-Jul-76	R0	DC-10	Jackson, MI	00624	--
AE1008990	ASB114	29-11-01	CMM	Teflon Hose Assemblies	--	01-Jul-76	R0	DC-10	Jackson, MI	00624	--
AE1009014	ASB114	29-11-01	CMM	Teflon Hose Assemblies	--	01-Jul-76	R0	DC-10	Jackson, MI	00624	--
AE1009061	ASB114	29-11-01	CMM	Teflon Hose Assemblies	--	01-Jul-76	R0	DC-10	Jackson, MI	00624	--
AE7009062	ASB114	29-11-01	CMM	Teflon Hose Assemblies	--	01-Jul-76	R0	DC-10	Jackson, MI	00624	--
AE705777-28	ASB126	29-11-02	CMM	Hydraulic Hose Assemblies	--	01-Oct-84	R1	B767	Jackson, MI	00624	--
AE705777-31	ASB126	29-11-02	CMM	Hydraulic Hose Assemblies	--	01-Oct-84	R1	B767	Jackson, MI	00624	--
AE705777-32	ASB126	29-11-02	CMM	Hydraulic Hose Assemblies	--	01-Oct-84	R1	B767	Jackson, MI	00624	--
AE705777-34	ASB126	29-11-02	CMM	Hydraulic Hose Assemblies	--	01-Oct-84	R1	B767	Jackson, MI	00624	--
AE705777-36	ASB126	29-11-02	CMM	Hydraulic Hose Assemblies	--	01-Oct-84	R1	B767	Jackson, MI, Tijuana, MX	00624	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
AE705777-38	ASB126	29-11-02	CMM	Hydraulic Hose Assemblies	--	01-Oct-84	R1	B767	Jackson, MI	00624	--
AE705777-74	ASB126	29-11-02	CMM	Hydraulic Hose Assemblies	--	01-Oct-84	R1	B767	Jackson, MI	00624	--
AE705777-75	ASB126	29-11-02	CMM	Hydraulic Hose Assemblies	--	01-Oct-84	R1	B767	Jackson, MI	00624	--
AE705777-46	ASB136	29-11-03	CMM	Hydraulic Hose Assemblies	--	01-Nov-83	R0	B757, B767	Jackson, MI	00624	--
AE705777-50	ASB136	29-11-03	CMM	Hydraulic Hose Assemblies	--	01-Nov-83	R0	B757, B767	Jackson, MI	00624	--
AE705777-52	ASB136	29-11-03	CMM	Hydraulic Hose Assemblies	--	01-Nov-83	R0	B757, B767	Jackson, MI	00624	--
AE705777-56	ASB136	29-11-03	CMM	Hydraulic Hose Assemblies	--	01-Nov-83	R0	B757, B767	Jackson, MI	00624	--
AE704435-2	AA37	29-11-04	CMM	Medium Pressure Teflon Hose Assembly	--	01-Jun-90	R0	B747	Jackson, MI	00624	--
AE705777-82	ASB141	29-11-05	CMM	Hydraulic Hose Assemblies	--	01-Sep-85	R0	B757, B767	Jackson, MI	00624	--
AE705777-83	ASB141	29-11-05	CMM	Hydraulic Hose Assemblies	--	01-Sep-85	R0	B757, B767	Jackson, MI	00624	--
AE707874-1	ASB172	29-11-48	CMM	Hydraulic Hose Assemblies: Suction, Press, and Pump Case Drain	--	01-Aug-08	R2	A320	Redditch UK	U2569	--
AE707874-2	ASB172	29-11-48	CMM	Hydraulic Hose Assemblies: Suction, Press, and Pump Case Drain	--	01-Aug-08	R2	A320	Redditch UK	U2569	--
AE707874-3	ASB172	29-11-48	CMM	Hydraulic Hose Assemblies: Suction, Press, and Pump Case Drain	--	01-Aug-08	R2	A320	Redditch UK	U2569	--
AE707875-1	ASB172	29-11-48	CMM	Hydraulic Hose Assemblies: Suction, Press, and Pump Case Drain	--	01-Aug-08	R2	A320	Redditch UK	U2569	--
AE707875-2	ASB172	29-11-48	CMM	Hydraulic Hose Assemblies: Suction, Press, and Pump Case Drain	--	01-Aug-08	R2	A320	Redditch UK	U2569	--
AE707910-1	ASB172	29-11-48	CMM	Hydraulic Hose Assemblies: Suction, Press, and Pump Case Drain	--	01-Aug-08	R2	A320	Jackson, MI	00624	--
AE707910-2	ASB172	29-11-48	CMM	Hydraulic Hose Assemblies: Suction, Press, and Pump Case Drain	--	01-Aug-08	R2	A320	Jackson, MI	00624	--
AE707876-1	ASB172	29-11-48	CMM	Hydraulic Hose Assemblies: Suction, Press, and Pump Case Drain	--	01-Aug-08	R2	A320	Redditch UK	U2569	--
AE707876-2	ASB172	29-11-48	CMM	Hydraulic Hose Assemblies: Suction, Press, and Pump Case Drain	--	01-Aug-08	R2	A320	Jackson, MI	00624	--
AE95683N	ASB104	29-11-49	CMM	Self-Sealing Couplings	--	01-Jun-73	R1	L1011	Jackson, MI	00624	--
AE95683P	ASB104	29-11-49	CMM	Self-Sealing Couplings	--	01-Jun-73	R1	L1011	Jackson, MI	00624	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
AE96824N	ASB104	29-11-49	CMM	Self-Sealing Couplings	--	01-Jun-73	R1	L1011	Jackson, MI	00624	--
AE96824P	ASB104	29-11-49	CMM	Self-Sealing Couplings	--	01-Jun-73	R1	L1011	Jackson, MI	00624	--
AE703541-1	ASB90	29-11-57	CMM	Teflon Hose Assemblies	--	01-Jun-73	R2	L1011	Jackson, MI	00624	--
AE703542-1	ASB90	29-11-57	CMM	Teflon Hose Assemblies	--	01-Jun-73	R2	L1011	Jackson, MI	00624	--
AE703543-1	ASB90	29-11-57	CMM	Teflon Hose Assemblies	--	01-Jun-73	R2	L1011	Jackson, MI	00624	--
AE703543-2	ASB90	29-11-57	CMM	Teflon Hose Assemblies	--	01-Jun-73	R2	L1011	Jackson, MI	00624	--
AE1007519N0326	ASB90	29-11-57	CMM	Teflon Hose Assemblies	--	01-Jun-73	R2	L1011	Jackson, MI	00624	--
AE1007520J0342	ASB90	29-11-57	CMM	Teflon Hose Assemblies	--	01-Jun-73	R2	L1011	Jackson, MI	00624	--
AE1007521M0304	ASB90	29-11-57	CMM	Teflon Hose Assemblies	--	01-Jun-73	R2	L1011	Jackson, MI	00624	--
AE1008043N0326	ASB90	29-11-57	CMM	Teflon Hose Assemblies	--	01-Jun-73	R2	L1011	Jackson, MI	00624	--
AE3428J0426-350	ASB90	29-11-57	CMM	Teflon Hose Assemblies	--	01-Jun-73	R2	L1011	Jackson, MI	00624	--
AE1008123J0444	ASB90	29-11-57	CMM	Teflon Hose Assemblies	--	01-Jun-73	R2	L1011	Jackson, MI	00624	--
AE1008042N0390	ASB90	29-11-57	CMM	Teflon Hose Assemblies	--	01-Jun-73	R2	L1011	Jackson, MI	00624	--
AE1007828M0400	ASB90	29-11-57	CMM	Teflon Hose Assemblies	--	01-Jun-73	R2	L1011	Jackson, MI	00624	--
AE3582M0520-000	ASB90	29-11-57	CMM	Teflon Hose Assemblies	--	01-Jun-73	R2	L1011	Jackson, MI	00624	--
AE3583M0494-012	ASB90	29-11-57	CMM	Teflon Hose Assemblies	--	01-Jun-73	R2	L1011	Jackson, MI	00624	--
AE706127-1	ASB131	29-11-58	CMM	Hydraulic Hose Assemblies	--	01-Nov-84	R1	B757	Jackson, MI	00624	--
AE706127-11	ASB131	29-11-58	CMM	Hydraulic Hose Assemblies	--	01-Nov-84	R1	B757	Jackson, MI	00624	--
AE706127-67	ASB131	29-11-58	CMM	Hydraulic Hose Assemblies	--	01-Nov-84	R1	B757	Jackson, MI	00624	--
AE706128-1	ASB131	29-11-58	CMM	Hydraulic Hose Assemblies	--	01-Nov-84	R1	B757	Jackson, MI	00624	--
AE706128-3	ASB131	29-11-58	CMM	Hydraulic Hose Assemblies	--	01-Nov-84	R1	B757	Jackson, MI	00624	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
AE706128-69	ASB131	29-11-58	CMM	Hydraulic Hose Assemblies	--	01-Nov-84	R1	B757	Jackson, MI	00624	--
AE95685G	ASB105	29-12-03	CMM	Self-Sealing Couplings	--	01-Jul-73	R1	L1011	Jackson, MI	00624	--
AE95686G	ASB105	29-12-03	CMM	Self-Sealing Couplings	--	01-Jul-73	R1	L1011	Jackson, MI	00624	--
AE95687G	ASB105	29-12-03	CMM	Self-Sealing Couplings	--	01-Jul-73	R1	L1011	Jackson, MI, Tijuana, MX	00624	--
AE96825G	ASB105	29-12-03	CMM	Self-Sealing Couplings	--	01-Jul-73	R1	L1011	Jackson, MI	00624	--
AE96994E	ASB102	29-14-21	CMM	Self-Sealing Coupling	--	01-Sep-73	R0	NA	Jackson, MI	00624	--
AE709283-501	AA146D	29-18-49	CMM	Teflon Hose Assemblies	--	01-Nov-07	R2	MD-90	Jackson, MI	00624	Being Revised - 11-2017
AE709283-503	AA146D	29-18-49	CMM	Teflon Hose Assemblies	--	01-Nov-07	R2	MD-90	Jackson, MI	00624	Being Revised - 11-2017
AE709283-505	AA146D	29-18-49	CMM	Teflon Hose Assemblies	--	01-Nov-07	R2	MD-90	Jackson, MI	00624	Being Revised - 11-2017
AE709283-507	AA146D	29-18-49	CMM	Teflon Hose Assemblies	--	01-Nov-07	R2	MD-90	Jackson, MI	00624	Being Revised - 11-2017
AE709284-501	AA146D	29-18-49	CMM	Teflon Hose Assemblies	--	01-Nov-07	R2	MD-90	Jackson, MI	00624	Being Revised - 11-2017
AE709284-503	AA146D	29-18-49	CMM	Teflon Hose Assemblies	--	01-Nov-07	R2	MD-90	Jackson, MI	00624	Being Revised - 11-2017
AE709284-505	AA146D	29-18-49	CMM	Teflon Hose Assemblies	--	01-Nov-07	R2	MD-90	Jackson, MI	00624	Being Revised - 11-2017
AE709284-507	AA146D	29-18-49	CMM	Teflon Hose Assemblies	--	01-Nov-07	R2	MD-90	Jackson, MI	00624	Being Revised - 11-2017
AE709284-509	AA146D	29-18-49	CMM	Teflon Hose Assemblies	--	01-Nov-07	R2	MD-90	Jackson, MI	00624	Being Revised - 11-2017
AE709366-501	AA146D	29-18-49	CMM	Teflon Hose Assemblies	--	01-Nov-07	R2	MD-90	Jackson, MI	00624	Being Revised - 11-2017
AE709366-503	AA146D	29-18-49	CMM	Teflon Hose Assemblies	--	01-Nov-07	R2	MD-90	Jackson, MI	00624	Being Revised - 11-2017
AE709215-2	AA201	29-18-49	CMM	Teflon Hose Assemblies	--	01-Oct-11	R1	A330	Jackson, MI	00624	--
AE709216-2	AA201	29-18-49	CMM	Teflon Hose Assemblies	--	01-Oct-11	R1	A330	Jackson, MI	00624	--
AE709217-1	AA201	29-18-49	CMM	Teflon Hose Assemblies	--	01-Oct-11	R1	A330	Jackson, MI	00624	--
AE709218-3	AA201	29-18-49	CMM	Teflon Hose Assemblies	--	01-Oct-11	R1	A330	Jackson, MI	00624	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
AE709218-4	AA201	29-18-49	CMM	Teflon Hose Assemblies	--	01-Oct-11	R1	A330	Jackson, MI	00624	--
AE709224-2	AA201	29-18-49	CMM	Teflon Hose Assemblies	--	01-Oct-11	R1	A330	Jackson, MI	00624	--
AE709225-3	AA201	29-18-49	CMM	Teflon Hose Assemblies	--	01-Oct-11	R1	A330	Jackson, MI	00624	--
AE709240-2	AA201	29-18-49	CMM	Teflon Hose Assemblies	--	01-Oct-11	R1	A330	Jackson, MI	00624	--
AE81383M	ASB127	29-19-01	CMM	Hydraulic Couplings	--	01-Nov-82	R1	B737, B747, B767, B777	Jackson, MI, Tijuana, MX	00624	--
AE81383N	ASB127	29-19-01	CMM	Hydraulic Couplings	--	01-Nov-82	R1	B737, B747, B767, B777	Jackson, MI, Tijuana, MX	00624	--
AE80994M	ASB127	29-19-01	CMM	Hydraulic Couplings	--	01-Nov-82	R1	B737, B747, B767, B777	Jackson, MI, Tijuana, MX	00624	--
AE80994N	ASB127	29-19-01	CMM	Hydraulic Couplings	--	01-Nov-82	R1	B737, B747, B767, B777	Jackson, MI, Tijuana, MX	00624	--
300503S11-6D5	ASB137	29-19-02	CMM	Coupling Half, Quick Disconnect Self Sealing Bulkhead with Cap	--	01-Mar-84	R0	NA	Jackson, MI, Tijuana, MX	00624	--
AE708323-1	AA160	29-19-50	CMM	Teflon Hose Assemblies	--	01-Dec-93	R0	PWA 300, BAE 125	Jackson, MI	00624	--
AE708323-2	AA160	29-19-50	CMM	Teflon Hose Assemblies	--	01-Dec-93	R0	PWA 300, BAE 125	Jackson, MI	00624	--
AE708324-1	AA160	29-19-50	CMM	Teflon Hose Assemblies	--	01-Dec-93	R0	PWA 300, BAE 125	Jackson, MI	00624	--
AE708324-2	AA160	29-19-50	CMM	Teflon Hose Assemblies	--	01-Dec-93	R0	PWA 300, BAE 125	Jackson, MI	00624	--
AE708325-3	AA160	29-19-50	CMM	Teflon Hose Assemblies	--	01-Dec-93	R0	PWA 300, BAE 125	Jackson, MI	00624	--
AE708325-4	AA160	29-19-50	CMM	Teflon Hose Assemblies	--	01-Dec-93	R0	PWA 300, BAE 125	Jackson, MI	00624	--
AE708378-1	AA160	29-19-50	CMM	Teflon Hose Assemblies	--	01-Dec-93	R0	PWA 300, BAE 125	Jackson, MI, Tijuana, MX	00624	--
AE708379-1	AA160	29-19-50	CMM	Teflon Hose Assemblies	--	01-Dec-93	R0	PWA 300, BAE 125	Jackson, MI	00624	--
AE709017-1	AA160	29-19-50	CMM	Teflon Hose Assemblies	--	01-Dec-93	R0	PWA 300, BAE 125	Jackson, MI	00624	--
AE709017-2	AA160	29-19-50	CMM	Teflon Hose Assemblies	--	01-Dec-93	R0	PWA 300, BAE 125	Jackson, MI	00624	--
AE709018-1	AA160	29-19-50	CMM	Teflon Hose Assemblies	--	01-Dec-93	R0	PWA 300, BAE 125	Jackson, MI	00624	--
AE710155-1	AA159	29-20-51	CMM	Teflon Hose Assemblies	--	01-Dec-93	R0	A321	Jackson, MI	00624	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
AE93905E	ASB91	32-32-01	CMM	Ball Bearing Swivel Joint	--	01-Oct-70	R0	B747	Jackson, MI	00624	--
AE93905G	ASB91	32-32-01	CMM	Ball Bearing Swivel Joint	--	01-Oct-70	R0	B747	Jackson, MI	00624	--
AE93905H	ASB91	32-32-01	CMM	Ball Bearing Swivel Joint	--	01-Oct-70	R0	B747	Jackson, MI	00624	--
AE93905J	ASB91	32-32-01	CMM	Ball Bearing Swivel Joint	--	01-Oct-70	R0	B747	Jackson, MI	00624	--
AE76315G	NA	32-32-21	CMM	Module, Hydraulic Swivel (Ref: GE PN 6-0452-1)	--	01-May-14	R2	B787	Jackson, MI	00624	--
AE76920G	NA	32-32-22	CMM	Module, Hydraulic Swivel (Ref: GE PN 6-0453-2)	--	01-May-14	R2	B787	Jackson, MI	00624	--
AE76317J	NA	32-32-23	CMM	Module, Hydraulic Swivel (Ref: GE PN 6-0454-1)	--	01-May-14	R2	B787	Jackson, MI	00624	--
AE75757G	NA	32-35-14	CMM	Bleed Valve (Ref: GE PN 6-0451-1)	--	01-Mar-14	R1	B787	Jackson, MI	00624	--
AE85763E	AA169	32-40-01	CMM	Landing Gear Swivel	--	01-Mar-96	R0	DHC-8	Jackson, MI	00624	--
AE85379E	AA170	32-40-02	CMM	Landing Gear Swivel	--	01-Mar-96	R0	DHC-8	Jackson, MI	00624	--
AE85762E	AA170	32-40-02	CMM	Landing Gear Swivel	--	01-Mar-96	R0	DHC-8	Jackson, MI	00624	--
AE86642E	AA170	32-40-02	CMM	Landing Gear Swivel	--	01-Mar-96	R0	DHC-8	Jackson, MI	00624	--
AE75051E	NA	32-50-12	CMM	Swivel Assembly LH / RH	--	01-Feb-08	R0	Global Express	Jackson, MI	00624	--
AE75052E	NA	32-50-12	CMM	Swivel Assembly LH / RH	--	01-Feb-08	R0	Global Express	Jackson, MI	00624	--
AE75782J	AA219	32-53-11	CMM	Change Over Valve	--	01-Mar-09	C	A340	Jackson, MI	00624	--
AE95716G	ASB96	34-11-01	CMM	Self-Sealing Coupling Half	--	01-Jun-71	R0	B747	Jackson, MI, Tijuana, MX	00624	--
1177-5	ASB96	34-11-01	CMM	Self-Sealing Coupling Half	--	01-Jun-71	R0	B747	Jackson, MI, Tijuana, MX	00624	--
AE95717G	ASB97	34-11-02	CMM	Self-Sealing Coupling Half	--	01-Jun-71	R0	B747	Jackson, MI, Tijuana, MX	00624	--
AE1007616E	ASB100	49-10-01	CMM	Type AR1136 Hose Assemblies	--	01-Aug-71	R0	DC-10	Jackson, MI	00624	--
AE1007616G	ASB100	49-10-01	CMM	Type AR1136 Hose Assemblies	--	01-Aug-71	R0	DC-10	Jackson, MI	00624	--
AE1007616K	ASB100	49-10-01	CMM	Type AR1136 Hose Assemblies	--	01-Aug-71	R0	DC-10	Jackson, MI	00624	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
AE1007690G	ASB100	49-10-01	CMM	Type AR1136 Hose Assemblies	--	01-Aug-71	R0	DC-10	Jackson, MI	00624	--
AE1007690H	ASB100	49-10-01	CMM	Type AR1136 Hose Assemblies	--	01-Aug-71	R0	DC-10	Jackson, MI	00624	--
AE3236E	ASB100	49-10-01	CMM	Type AR1136 Hose Assemblies	--	01-Aug-71	R0	DC-10	Jackson, MI	00624	--
AE3236H	ASB100	49-10-01	CMM	Type AR1136 Hose Assemblies	--	01-Aug-71	R0	DC-10	Jackson, MI	00624	--
AE3237E	ASB100	49-10-01	CMM	Type AR1136 Hose Assemblies	--	01-Aug-71	R0	DC-10	Jackson, MI	00624	--
AE708172-1	AA96	71-01-02	CMM	Teflon Hose Assemblies	--	01-Apr-91	R0	MD-11	Jackson, MI	00624	--
M666301-8-0186	AA97	71-01-03	CMM	Teflon Hose Assemblies	--	01-Apr-91	R0	MD-11	Jackson, MI	00624	--
M666301-6-0204	AA97	71-01-03	CMM	Teflon Hose Assemblies	--	01-Apr-91	R0	MD-11	Jackson, MI	00624	--
AE708168-2	AA97	71-01-03	CMM	Teflon Hose Assemblies	--	01-Apr-91	R0	MD-11	Jackson, MI	00624	--
AE704312-5	AA98	71-01-04	CMM	Teflon Hose Assemblies	--	01-Apr-91	R0	CF6-80C2	Jackson, MI	00624	--
AE708163-3	AA99A	71-01-05	CMM	Teflon Hose Assemblies	--	01-Feb-00	R1	MD-11	Jackson, MI	00624	--
AE708164-2	AA99A	71-01-05	CMM	Teflon Hose Assemblies	--	01-Feb-00	R1	MD-11	Jackson, MI	00624	--
AE708166-1	AA100C	71-01-06	CMM	Teflon Hose Assemblies	--	01-Mar-10	R2	MD-11	Jackson, MI	00624	Being Revised - 11-2017
AE708166-3	AA100C	71-01-06	CMM	Teflon Hose Assemblies	--	01-Mar-10	R2	MD-11	Jackson, MI	00624	Being Revised - 11-2017
AE708166-4	AA100C	71-01-06	CMM	Teflon Hose Assemblies	--	01-Mar-10	R2	MD-11	Jackson, MI	00624	Being Revised - 11-2017
AE708167-3	AA100C	71-01-06	CMM	Teflon Hose Assemblies	--	01-Mar-10	R2	MD-11	Jackson, MI	00624	Being Revised - 11-2017
AE708167-4	AA100C	71-01-06	CMM	Teflon Hose Assemblies	--	01-Mar-10	R2	MD-11	Jackson, MI	00624	Being Revised - 11-2017
AE706058-18	AA101	71-01-07	CMM	Teflon Hose Assemblies	--	01-Apr-91	R0	MD-11	Jackson, MI, Tijuana, MX	00624	--
AE708677-3	AA101	71-01-07	CMM	Teflon Hose Assemblies	--	01-Apr-91	R0	MD-11	Jackson, MI	00624	--
AE708347-1	AA102	71-01-08	CMM	Teflon Hose Assemblies	--	01-Apr-91	R0	MD-11	Jackson, MI, Tijuana, MX	00624	--
AE3660060G0343	AA102	71-01-08	CMM	Teflon Hose Assemblies	--	01-Apr-91	R0	MD-11	Jackson, MI	00624	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
AE366000G0127	AA102	71-01-08	CMM	Teflon Hose Assemblies	--	01-Apr-91	R0	MD-11	Jackson, MI, Tijuana, MX	00624	--
AE3660060H0331	AA102	71-01-08	CMM	Teflon Hose Assemblies	--	01-Apr-91	R0	MD-11	Jackson, MI	00624	--
AE708347-3	AA102	71-01-08	CMM	Teflon Hose Assemblies	--	01-Apr-91	R0	MD-11	Jackson, MI	00624	--
AE3663419G0282	AA102	71-01-08	CMM	Teflon Hose Assemblies	--	01-Apr-91	R0	MD-11	Jackson, MI	00624	--
AE3663419H0256	AA102	71-01-08	CMM	Teflon Hose Assemblies	--	01-Apr-91	R0	MD-11	Jackson, MI	00624	--
AE6020H0080-000	AA102	71-01-08	CMM	Teflon Hose Assemblies	--	01-Apr-91	R0	MD-11	Jackson, MI, Tijuana, MX	00624	--
AE3660066H0390	AA102	71-01-08	CMM	Teflon Hose Assemblies	--	01-Apr-91	R0	MD-11	Jackson, MI, Tijuana, MX	00624	--
AE3660066G0390	AA102	71-01-08	CMM	Teflon Hose Assemblies	--	01-Apr-91	R0	MD-11	Jackson, MI, Tijuana, MX	00624	--
AE704312-5	AA98	73-01-04	CMM	Rubber Hose Assemblies	--	01-Dec-94	R0	CF6-80C2	Jackson, MI	00624	--
AE709962-1	AA300	73-10-01	CMM	Teflon Hose Assembly	--	01-Aug-14	R1	CF6-80C2	Jackson, MI	00624	Being revised - 11-2017. Replacing -501 with -503
AE706401-1	ASB135	73-11-01	CMM	Medium Pressure Teflon Hose Assemblies	--	01-Jul-83	R0	B757	Jackson, MI, Tijuana, MX	00624	--
AE706428-1	ASB135	73-11-01	CMM	Medium Pressure Teflon Hose Assemblies	--	01-Jul-83	R0	B757	Jackson, MI	00624	--
AE707631-1	ASB173	73-11-48	CMM	Fuel Pump Return Hose Assembly Fuel Supply Hose Assembly	--	01-May-89	R0	NA	Redditch UK	U2569	--
AE707632-1	ASB173	73-11-48	CMM	Fuel Pump Return Hose Assembly Fuel Supply Hose Assembly	--	01-May-89	R0	NA	Jackson, MI	00624	--
AE703400-3	ASB99	73-12-01	CMM	Rubber Hose Assemblies	--	01-Aug-75	R1	McDonnell Douglas DC-10, Series 10 and 30, Boeing MD-10-10F, MD-10-30F	Jackson, MI	00624	--
AE703402-2	ASB99	73-12-01	CMM	Rubber Hose Assemblies	--	01-Aug-75	R1	McDonnell Douglas DC-10, Series 10 and 30, Boeing MD-10-10F, MD-10-30F	Jackson, MI	00624	--
AE703630-1	ASB99	73-12-01	CMM	Rubber Hose Assemblies	--	01-Aug-75	R1	McDonnell Douglas DC-10, Series 10 and 30, Boeing MD-10-10F, MD-10-30F	Jackson, MI	00624	--
AE704312-2	ASB99	73-12-01	CMM	Rubber Hose Assemblies	--	01-Aug-75	R1	McDonnell Douglas DC-10, Series 10 and 30, Boeing MD-10-10F, MD-10-30F	Jackson, MI	00624	--
AE704313-1	ASB99	73-12-01	CMM	Rubber Hose Assemblies	--	01-Aug-75	R1	McDonnell Douglas DC-10, Series 10 and 30, Boeing MD-10-10F, MD-10-30F	Jackson, MI	00624	--
AE704314-1	ASB99	73-12-01	CMM	Rubber Hose Assemblies	--	01-Aug-75	R1	McDonnell Douglas DC-10, Series 10 and 30, Boeing MD-10-10F, MD-10-30F	Jackson, MI	00624	--
AE704318-1	ASB99	73-12-01	CMM	Rubber Hose Assemblies	--	01-Aug-75	R1	McDonnell Douglas DC-10, Series 10 and 30, Boeing MD-10-10F, MD-10-30F	Jackson, MI	00624	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
AE1006944H0144	ASB99	73-12-01	CMM	Rubber Hose Assemblies	--	01-Aug-75	R1	McDonnell Douglas DC-10, Series 10 and 30, Boeing MD-10-10F, MD-10-30F	Jackson, MI	00624	--
AE707667-1	ASB174	73-22-48	CMM	Pressure Switch Air-Hose Assembly	--	01-May-89	R0	NA	Redditch UK	U2569	--
AE709688-503	AA147A	78-31-17	CMM	Teflon Hose Assemblies	--	01-Dec-97	R0	MD-90	Jackson, MI	00624	--
AE709688-504	AA147A	78-31-17	CMM	Teflon Hose Assemblies	--	01-Dec-97	R0	MD-90	Jackson, MI	00624	--
AE709688-505	AA147A	78-31-17	CMM	Teflon Hose Assemblies	--	01-Dec-97	R0	MD-90	Jackson, MI	00624	--
AE709688-506	AA147A	78-31-17	CMM	Teflon Hose Assemblies	--	01-Dec-97	R0	MD-90	Jackson, MI	00624	--
AE709688-509	AA147A	78-31-17	CMM	Teflon Hose Assemblies	--	01-Dec-97	R0	MD-90	Jackson, MI	00624	--
AE709377-1	AA147A	78-31-17	CMM	Teflon Hose Assemblies	--	01-Dec-97	R0	MD-90	Jackson, MI	00624	--
AE709380-1	AA147A	78-31-17	CMM	Teflon Hose Assemblies	--	01-Dec-97	R0	MD-90	Jackson, MI	00624	--
AE706058-8	AA158A	78-33-19	CMM	Teflon Hose Assemblies	--	01-May-03	R1	PWA 300, BAE 125-1000	Jackson, MI	00624	--
AE708322-8	AA158A	78-33-19	CMM	Teflon Hose Assemblies	--	01-May-03	R1	PWA 300, BAE 125-1000	Jackson, MI	00624	--
AE708322-11	AA158A	78-33-19	CMM	Teflon Hose Assemblies	--	01-May-03	R1	PWA 300, BAE 125-1000	Jackson, MI	00624	--
AE709461-1	AA158A	78-33-19	CMM	Teflon Hose Assemblies	--	01-May-03	R1	PWA 300, BAE 125-1000	Jackson, MI	00624	--
AE707422-1	AA157	78-34-20	CMM	Rubber Hose Assemblies	--	01-Dec-93	R0	CFM56-5	Jackson, MI	00624	--
AE719264-17	NA	78-34-30	CMM	Hose Assembly, Track Lock Pressure Hose Assembly, Track Lock Return	--	01-Jun-11	R7	B787	Jackson, MI	00624	--
AE719265-15	NA	78-34-30	CMM	Hose Assembly, Track Lock Pressure Hose Assembly, Track Lock Return	--	01-Jun-11	R7	B787	Jackson, MI	00624	--
AE719754-1	NA	78-34-31	CMM	Hose Assembly, Track Lock Drain	--	01-Jun-11	R4	B787	Jackson, MI	00624	--
AE719756-1	NA	78-34-31	CMM	Hose Assembly, Track Lock Drain	--	01-Jun-11	R4	B787	Jackson, MI	00624	--
AE719268-9	NA	78-34-32	CMM	Hose Assembly, Track Lock Pressure Hose Assembly, Track Lock Return	--	01-Jul-10	R3	B787	Jackson, MI	00624	--
AE719269-7	NA	78-34-32	CMM	Hose Assembly, Track Lock Pressure Hose Assembly, Track Lock Return	--	01-Jul-10	R3	B787	Jackson, MI	00624	--
AE719755-1	NA	78-34-33	CMM	Hose Assembly, Track Lock Drain	--	01-Jun-11	R4	B787	Jackson, MI	00624	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
AE719268-17	NA	78-34-34	CMM	Hose Assembly, Track Lock Pressure Hose Assembly, Track Lock Return	--	01-Aug-11	R0	B787	Jackson, MI	00624	--
AE719269-15	NA	78-34-34	CMM	Hose Assembly, Track Lock Pressure Hose Assembly, Track Lock Return	--	01-Aug-11	R0	B787	Jackson, MI	00624	--
AE706058-59	AA112	79-30-01	CMM	Teflon Hose Assemblies	--	01-Aug-91	R0	A340	Jackson, MI	00624	--
AE3663162E0081	AA112	79-30-01	CMM	Teflon Hose Assemblies	--	01-Aug-91	R0	A340	Jackson, MI	00624	--
AE705615-1	AA21	AE705615-73-01	SB	Engine Fuel & Control - Fuel Line Hose Install Bumper to Prevent Field Removal of Coupling Nut Retaining	--	01-Aug-90	A	B767	Jackson, MI	00624	--
AE706825-1	AA22	AE706825-73-02	SB	Engine Fuel & Control - Fuel Line Hose Install Bumper to Prevent Field Removal of Coupling Nut Retaining	--	01-Aug-90	A	B767	Jackson, MI	00624	--
AE706825-5	AA22	AE706825-73-02	SB	Engine Fuel & Control - Fuel Line Hose Install Bumper to Prevent Field Removal of Coupling Nut Retaining	--	01-Aug-90	A	B767	Jackson, MI	00624	--
AE71882E	NA	AE71882E-32-01	SB	1800 Style Coupling Half Quick Disconnect Rework Instructions for Seal Replacement	--	13-Sep-17	--	E145	Jackson, MI, Tijuana, MX	00624	--
AE74593G	NA	AE74593G-32-01	SB	1800 Style Coupling Half Quick Disconnect Rework Instructions for Seal Replacement	--	12-Jan-17	A	E170, E190	Jackson, MI	00624	--
AE75848G	NA	AE75848G-32-01	SB	1800 Style Coupling Half Quick Disconnect Rework Instructions for Seal Replacement	--	12-Jan-17	A	E170, E190	Jackson, MI, Tijuana, MX	00624	--
AE80994M	AA122	AE80994M/29-003	SB	Hydraulic Power / Hydraulic Coupling Assembly Ground System Pressure Disconnect - Add A Ring to Cap to Prevent Wire Chafing	--	01-Dec-91	--	B767	Jackson, MI, Tijuana, MX	00624	--
AE81090J	AA111	AE81090J-32-01	SB	Landing Gear Hydraulic Swivel - Bushing and Seal Replacement	--	01-Sep-91	--	B767	Jackson, MI	00624	--
AE87771G	NA	AE87771G-32-01	SB	1800 Style Coupling Half Quick Disconnect Rework Instructions for Seal Replacement	--	12-Jan-17	A	CRJ-100/200/700, ARJ-700	Jackson, MI, Tijuana, MX	00624	--
940732	165W01020	29-11-26	CMM	AC Driven Motorpump Assembly	--	Jan 30/12	5	737	Eaton Jackson, MS	62983 & 90166	--
940732	165W01020	29-22	TR	N/A	--	Oct 05/07	Original	737	Eaton Jackson, MS	62983 & 90166	--
961627	165W01022	29-11-26	CMM	AC Driven Motorpump Assembly	--	Jan 30/12	5	737	Eaton Jackson, MS	62983 & 90166	--
961627	165W01022	29-22	TR	N/A	--	Oct 05/07	Original	737	Eaton Jackson, MS	62983 & 90166	--
303925	4V146R002	73-10-1	CMM	Fuel Pump	--	Apr 15/67	3	PT6A, PT6B	Eaton Jackson, MS	62983 & 90166	--
297094	4V146R100	4V14 28-20-1	CMM	Vane Type Fuel Pump Assembly	--	Apr 1/78	6	PT6A, PT6B	Eaton Jackson, MS	62983 & 90166	--
961521	53WK16005-1	80-10-10	CMM	Hydraulic Starter	--	Oct 1/77	Original	Boeing Hydrofoil	Eaton Jackson, MS	62983 & 90166	--
961602	53WK20002	81-10-10	CMM	Hydraulic Starter	--	Dec 1/80	Original	TSB A/C Engine	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
961596	64WE07501	29-21-25	CMM	Hydraulic Pump/Motor	--	Nov 1/85	1	A300, A310	Eaton Jackson, MS	62983 & 90166	--
N/A	65WE002 Series	75-1	CMM	Stratopower Hyd. Pump	--	Nov 25/85	Original	--	Eaton Jackson, MS	62983 & 90166	--
N/A	65WE002 Series	75-1	CMM	Stratopower Hyd. Pump	--	Mar-00	Chg Pkg	--	Eaton Jackson, MS	62983 & 90166	--
N/A	65WE00241	29-9	TR	N/A	--	01-Feb-06	Original	--	Eaton Jackson, MS	62983 & 90166	--
961545	65WE01019-2	29-10-01	CMM	Hydraulic Pump	--	Jun 1/66	Original	HFB Hansa Jet 320	Eaton Jackson, MS	62983 & 90166	--
961540	65WE01035	29-10-10	CMM	Hydraulic Pump	--	Aug 15/94	4	Westland 30 Series	Eaton Jackson, MS	62983 & 90166	--
961564	65WE01036	29-10-10	CMM	Hydraulic Pump	--	Aug 15/94	4	Westland 30 Series	Eaton Jackson, MS	62983 & 90166	--
938090	65WE01036-2	29-10-10	CMM	Hydraulic Pump	--	Aug 15/94	4	Westland 30 Series	Eaton Jackson, MS	62983 & 90166	--
961612	65WE01042	29-10-69	CMM	Hydraulic Pump	--	Oct 15/98	Original	Canadair Water Bomber	Eaton Jackson, MS	62983 & 90166	--
960949	66W	69-1	CMM	Hydraulic Pump	--	Jan 15/04	1	Various Models (Sikorski S-61, CH54A and CH54B)	Eaton Jackson, MS	62983 & 90166	--
265567	A-0643-089A and A-064	29-20-01	CMM	Hydraulic Motorpump	--	Sep 30/87	9	727	Eaton Jackson, MS	62983 & 90166	--
298113	A-0643-089C	29-10-01	CMM	Power Transfer Hydraulic Motorpump	--	Jun 1/65	Original	DC-9	Eaton Jackson, MS	62983 & 90166	--
298113	A-0643-089C	29-20-02	CMM	Hydraulic Motorpump	--	Sep 1/80	3	DC-9	Eaton Jackson, MS	62983 & 90166	--
405063	A-0643-089E	29-20-02	CMM	Hydraulic Motorpump	--	Sep 1/80	3	DC-9	Eaton Jackson, MS	62983 & 90166	--
518735	A-0643-089F	29-20-02	CMM	Hydraulic Motorpump	--	Dec 15/95	1	767	Eaton Jackson, MS	62983 & 90166	--
201779	AA-19020A	29-21-12	CMM	PF-3906-5 Series Constant Displacement Hydraulic Pumps and Motorpumps	--	Jul 15/86	Original	Nihon YS-11, YS - 11A	Eaton Jackson, MS	62983 & 90166	--
202897	AS-19058	29-20-01	CMM	Hydraulic Motorpump Assembly	--	Feb 15/78	1	707	Eaton Jackson, MS	62983 & 90166	--
202894	AS-19058 Motor	29-20-01	CMM	Electric Motor Assembly for AS-19058 Motorpump	--	Nov 1/63	Original	707, 720B	Eaton Jackson, MS	62983 & 90166	--
283554	AS-19088	52-34-01	CMM	Hydraulic Motorpump	--	Jun 15/72	Original	DC-8, DC-10	Eaton Jackson, MS	62983 & 90166	--
283553	AS-19088 Motor Only	52-34-03	CMM	Electric Motor for AS-19088 Motorpump	--	Jun 15/72	Original	DC-8, DC-10	Eaton Jackson, MS	62983 & 90166	--
283553	AS-19088 Motor Only	52-1	TR	N/A	--	May 28/08	Original	DC-8, DC-10	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
282726	AS-19088 Pump Only	52-34-02	CMM	Hydraulic Pump for AS-19088 Motorpump	--	Jun 15/72	Original	DC-8, DC-10	Eaton Jackson, MS	62983 & 90166	--
279952	AS-19570-B	29-10-19	CMM	Hydraulic Motorpump	--	Oct 30/87	10	727, 737	Eaton Jackson, MS	62983 & 90166	--
361108	AS-19570-B	29-10-21	CMM	Electric Motor for AS-19570-B & AS-19570-B-GB1 Motorpumps	--	Dec 30/85	10	BAC 1-11, 727, 737	Eaton Jackson, MS	62983 & 90166	--
268737	AS-19570-B-GB1	29-10-19	CMM	Hydraulic Motorpump	--	Oct 30/87	10	BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
323636	AS-19570-C	29-10-19	CMM	Hydraulic Motorpump	--	Oct 30/87	10	727, 737	Eaton Jackson, MS	62983 & 90166	--
364404	AS-19570-C	29-10-21	CMM	Electric Motor for AS-19570-C & AS-19570-C-GB1 Motorpumps	--	Dec 30/85	10	BAC 1-11, 727, 737	Eaton Jackson, MS	62983 & 90166	--
776655	AS-19570-C-GB1	29-10-19	CMM	Hydraulic Motorpump	--	Oct 30/87	10	BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
287358	AS-19593	29-21-10	CMM	Hydraulic Motorpump Assembly	--	Oct 15/82	5	DC-9	Eaton Jackson, MS	62983 & 90166	--
288326	AS-19593-A	29-21-10	CMM	Hydraulic Motorpump Assembly	--	Oct 15/82	5	DC-9	Eaton Jackson, MS	62983 & 90166	--
414770	AS-19593-B	29-21-10	CMM	Hydraulic Motorpump Assembly	--	Oct 15/82	5	DC-9	Eaton Jackson, MS	62983 & 90166	--
428117	AS-19593-C	29-21-10	CMM	Hydraulic Motorpump Assembly	--	Oct 15/82	5	DC-9	Eaton Jackson, MS	62983 & 90166	--
249848	AS-63664-LE	29-10-01	CMM	Hydraulic Pump - AS-63660-Series	--	Jul 15/82	9	DC-8	Eaton Jackson, MS	62983 & 90166	--
249849	AS-63665-LE	29-10-01	CMM	Hydraulic Pump - AS-63660-Series	--	Jul 15/82	9	DC-8	Eaton Jackson, MS	62983 & 90166	--
569885	AS-63665-LF	29-10-01	CMM	Hydraulic Pump - AS-63660-Series	--	Jul 15/82	9	DC-8	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	29-10-03	CMM	Variable Displacement Hydraulic Pump	--	Jan 15/10	15	DC-9 & MD-80	Eaton Jackson, MS	62983 & 90166	--
3029981-001	AS-66411-L-S666B	29-10-03	CMM	Variable Displacement Hydraulic Pump	--	Jan 15/10	15	DC-9 & MD-80	Eaton Jackson, MS	62983 & 90166	--
3029981-001	AS-66411-L-S666B	29-14	TR	N/A	--	Aug 15/06	Original	DC-9, MD-80	Eaton Jackson, MS	62983 & 90166	--
316841	AS-66651-L8A	29-10-10	CMM	Variable Displacement AS-66650/AS-66690	--	Jan 30/85	8	707, 720, 727, 737 & Convair 22, 30	Eaton Jackson, MS	62983 & 90166	--
291086	AS-66698-L8A	29-10-10	CMM	Variable Displacement AS-66650/AS-66690	--	Jan 30/85	8	BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
623447	CMF3-100-4	29-10-67	CMM	Hydraulic Motor Assembly	--	Sep 15/97	Original	AMX	Eaton Jackson, MS	62983 & 90166	--
390017	CMV3-075-1C	27-1	TR	N/A	--	Nov 15/04	Original	DC-10 & MD-11	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
418575	CMV3-075-1D	27-43-01	CMM	Hydraulic Motor Assembly	--	Jul 15/05	9	Boeing DC-10 & MD-11	Eaton Jackson, MS	62983 & 90166	--
610353	EA-50182-7	29-10-01	CMM	Hydraulic Motorpump	--	Dec 15/83	5	CV-580	Eaton Jackson, MS	62983 & 90166	--
612457	EA-50182-8	29-10-01	CMM	Hydraulic Motorpump	--	Dec 15/83	5	CV-580	Eaton Jackson, MS	62983 & 90166	--
329443	ELECT MTR SUBASSY	29-10-07	CMM	Electric Motor Subassembly	--	Dec 1/87	4	DC-8	Eaton Jackson, MS	62983 & 90166	--
569668	MF1-019-1	27-50-07	CMM	Constant Displacement Hydraulic Motor	--	Sept 30/11	6	757	Eaton Jackson, MS	62983 & 90166	--
569668	MF1-019-1	27-4	TR	N/A	--	Oct 18/13	Original	757	Eaton Jackson, MS	62983 & 90166	--
622634	MF1-019-3	27-50-07	CMM	Constant Displacement Hydraulic Motor	--	Sept 30/11	6	757	Eaton Jackson, MS	62983 & 90166	--
622634	MF1-019-3	27-4	TR	N/A	--	Oct 18/13	Original	757	Eaton Jackson, MS	62983 & 90166	--
887087	MF1-019-3A	27-50-09	CMM	Constant Displacement Hydraulic Motor	--	Sept 15/11	2	757	Eaton Jackson, MS	62983 & 90166	--
887087	MF1-019-3A	27-2	TR	N/A	--	Mar 15/05	Original	757	Eaton Jackson, MS	62983 & 90166	--
569670	MF1-060-18	27-50-06	CMM	Constant Displacement Hydraulic Motor	--	Dec 20/10	4	737-300/-400/-500 & 757	Eaton Jackson, MS	62983 & 90166	--
342381	MF1-095-6	27-40-01	CMM	Hydraulic Motor	--	May 15/04	3	747, 777	Eaton Jackson, MS	62983 & 90166	--
342381	MF1-095-6	27-3	TR	N/A	--	Jan 04/10	Original	747, 777	Eaton Jackson, MS	62983 & 90166	--
253478	MF110B008A	27-50-2	CMM	Constant Displacement Hydraulic Motor	--	Nov 30/64	1	707	Eaton Jackson, MS	62983 & 90166	--
973600	MF1-152-13	27-50-08	CMM	Constant Displacement Hydraulic Motor	--	July 30/10	5	737-600/-700/-800	Eaton Jackson, MS	62983 & 90166	--
569672	MF1-152-9	27-50-08	CMM	Constant Displacement Hydraulic Motor	--	July 30/10	5	757	Eaton Jackson, MS	62983 & 90166	--
123789	MF30-3913-30-S159-2	27-00-01	CMM	Hydraulic Motor	--	Oct 15/66	1	DC-6	Eaton Jackson, MS	62983 & 90166	--
390984	MF3-044-2B	27-51-09	CMM	Hydraulic Motor	--	Jul 15/80	2	L-1011	Eaton Jackson, MS	62983 & 90166	--
395840	MF3-044-3	27-51-09	CMM	Hydraulic Motor	--	Jul 15/80	2	L-1011	Eaton Jackson, MS	62983 & 90166	--
373364	MF3-075-4A	27-81-02	CMM	Hydraulic Motor	--	Apr 15/82	3	L-1011	Eaton Jackson, MS	62983 & 90166	--
391357	MF3-075-4B	27-81-02	CMM	Hydraulic Motor	--	Apr 15/82	3	L-1011	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
174883	MF36-3907-30Z	27-00-01	CMM	Hydraulic Motor	--	May 1/68	1	Nihon YS-11& YS - 11A	Eaton Jackson, MS	62983 & 90166	--
293843	MF36-3909-11Z-S595-3	27-50-05	CMM	Constant Displacement Hydraulic Motor	--	Jun 1/80	Original	Lockheed Model 1329	Eaton Jackson, MS	62983 & 90166	--
283689	MF36-3909-20Z-S595-3	27-50-05	CMM	Constant Displacement Hydraulic Motor	--	Jun 1/80	Original	Lockheed Model 1329	Eaton Jackson, MS	62983 & 90166	--
309742	MF36-3909-20Z-S658-3	None	CMM	Hydraulic Motor	--	Jul 1/72	Original	Nihon YS-11(S/N 2001 thru 2010 only)	Eaton Jackson, MS	62983 & 90166	--
114082	MF45-3911-20Z	27-00-01	CMM	Hydraulic Motor	--	Apr 1/83	5	AJ-1	Eaton Jackson, MS	62983 & 90166	--
120793	MF9-3911-25Z	27-00-01	CMM	Hydraulic Motor	--	Apr 1/83	5	757	Eaton Jackson, MS	62983 & 90166	--
414768	Motor (AS-19593-B)	29-21-12	CMM	Electric Motor for AS-19593 Motorpump	--	Dec 30/85	6	DC-9	Eaton Jackson, MS	62983 & 90166	--
428135	Motor (AS-19593-C)	29-21-12	CMM	Electric Motor for AS-19593 Motorpump	--	Dec 30/85	6	DC-9	Eaton Jackson, MS	62983 & 90166	--
518157	Motor (MPEV3-032-10A)	29-21-22	CMM	Electric Motor for MPEV3-032-10 Motorpumps	--	Aug 01/11	5	A319, A320, A321	Eaton Jackson, MS	62983 & 90166	--
693337	Motor (MPEV3-032-10E)	29-21-22	CMM	Electric Motor for MPEV3-032-10 Motorpumps	--	Aug 01/11	5	A319, A320, A321, A330, A340	Eaton Jackson, MS	62983 & 90166	--
3029700-001	Motor (MPEV3-032-17)	29-21-22	CMM	Electric Motor for MPEV3-032-10 Motorpumps	--	Aug 01/11	5	A340	Eaton Jackson, MS	62983 & 90166	--
414469	Motor for (MPEV3-032-	29-21-08	CMM	A/C Electric Motor	--	May 15/93	10	MD-80, DC-10 & A300 BAE-146	Eaton Jackson, MS	62983 & 90166	--
612458	Motor Only	29-10-01	CMM	Electric Motor for EA-51082 Motorpumps	--	Dec 30/85	6	CV-580	Eaton Jackson, MS	62983 & 90166	--
693488	Motor Only	29-21-08	CMM	Electric Motor for MPEV3-032-1D/-1E/-1F-/GB1	--	May 15/93	10	MD-80, DC-10 & A300 BAE-146	Eaton Jackson, MS	62983 & 90166	--
378000	MPEV1-060-2	29-10-21	CMM	Electric Motor for MPEV1-060-2 Motorpumps	--	Dec 30/85	10	BAC 1-11, 727, 737	Eaton Jackson, MS	62983 & 90166	--
3032668-002	MPEV3-004-1C	29-19-01	CMM	D.C. Motorpump Assembly	--	Jul 23/14	Original	Honda HA-420	Eaton Jackson, MS	62983 & 90166	--
3032668-003	MPEV3-004-1C	29-19-01	CMM	D.C. Motorpump Assembly	--	Jul 23/14	Original	Honda HA-420	Eaton Jackson, MS	62983 & 90166	--
623859	MPEV3-008-2B	29-11-21	CMM	Variable Displacement Electric Motorpump	--	Jun 30/96	2	EMB-120	Eaton Jackson, MS	62983 & 90166	--
623859	MPEV3-008-2B	29-18	TR	N/A	--	Mar 26/07	Original	EMB-120	Eaton Jackson, MS	62983 & 90166	--
623859	MPEV3-008-2B	29-24	TR	N/A	--	Oct 31/07	Original	EMB-120	Eaton Jackson, MS	62983 & 90166	--
887173	MPEV3-008-2C	29-11-21	CMM	Variable Displacement Electric Motorpump	--	Jun 30/96	2	EMB-120	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
971533	MPEV3-008-6	29-10-60	CMM	Variable Displacement Electric Motorpump	--	Feb 28/14	4	EMB-135/-145	Eaton Jackson, MS	62983 & 90166	--
971533	MPEV3-008-6	29-3	TR	N/A	--	Oct 15/04	Original	EMB-145	Eaton Jackson, MS	62983 & 90166	--
971533	MPEV3-008-6	29-41	TR	N/A	--	Apr 16/12	Original	EMB-145	Eaton Jackson, MS	62983 & 90166	--
971533	MPEV3-008-6	29-51	TR	N/A	--	Oct 28/13	Original	Embraer 135, 145	Eaton Jackson, MS	62983 & 90166	--
570721	MPEV3-011-25	29-11-17	CMM	Var. Displ. Hyd Motorpump Assy	--	Sept 20/83	Original	--	Eaton Jackson, MS	62983 & 90166	--
731840	MPEV3-011-25C	29-11-22	CMM	Hydraulic Motorpump Assembly	--	Nov 20/10	4	DHC-8	Eaton Jackson, MS	62983 & 90166	--
849557	MPEV3-011-25D	29-11-22	CMM	Hydraulic Motorpump Assembly	--	Nov 20/10	4	DHC-8	Eaton Jackson, MS	62983 & 90166	--
849557	MPEV3-011-25D	29-11	TR	N/A	--	Sept 04/06	Original	DHC-8	Eaton Jackson, MS	62983 & 90166	--
887030	MPEV3-011-30	29-10-43	CMM	Hydraulic Motorpump Assembly	--	Sep 1/91	Original	Fokker 100	Eaton Jackson, MS	62983 & 90166	--
848847	MPEV3-012-2B	29-10-45	CMM	Variable Displacement Hydraulic Motorpump	--	Mar 30/11	3	CRJ, A300, A310	Eaton Jackson, MS	62983 & 90166	--
848847	MPEV3-012-2B	29-5	TR	N/A	--	June 13/05	Original	CRJ, A300, A310	Eaton Jackson, MS	62983 & 90166	--
848847	MPEV3-012-2B	29-10	TR	N/A	--	May 25/06	Original	CRJ, A300, A310	Eaton Jackson, MS	62983 & 90166	--
848847	MPEV3-012-2B	29-26	TR	N/A	--	Mar 05/08	Original	CRJ, A300, A310	Eaton Jackson, MS	62983 & 90166	--
3030288-001	MPEV3-012-5	29-10-88	CMM	AC Var. Displ. Elec. Motorpump Assy.	--	May 01/04	Original	S-92 Sikorsky	Eaton Jackson, MS	62983 & 90166	--
3030288-001	MPEV3-012-5	29-52	TR	N/A	--	Feb 12/14	Original	Sikorsky S-92	Eaton Jackson, MS	62983 & 90166	--
428153	MPEV3-022-14E	29-11-08	CMM	Variable Displacement Hydraulic Motorpump	--	Oct 30/00	7	L-1011	Eaton Jackson, MS	62983 & 90166	--
693980	MPEV3-022-14F	29-11-08	CMM	Variable Displacement Hydraulic Motorpump	--	Oct 30/00	7	L-1011	Eaton Jackson, MS	62983 & 90166	--
328759	MPEV3-022-3A	29-10-15	CMM	Electric Motor Subassembly	--	Nov 01/74	1	BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
327784	MPEV3-022-5	29-10-05	CMM	AC Electric Hydraulic Motorpump	--	Sep 15/82	3	DC-8	Eaton Jackson, MS	62983 & 90166	--
396362	MPEV3-032-10	29-12	TR	N/A	--	July 10/06	Original	A300, MD-80, DC-10	Eaton Jackson, MS	62983 & 90166	--
518150	MPEV3-032-10A	29-21-20	CMM	Hydraulic Motorpump Assembly	--	Aug 01/11	5	A319, A320, A321	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
518157	MPEV3-032-10A	29-8	TR	N/A	--	Feb 23/06	Original	A319, A320, A321	Eaton Jackson, MS	62983 & 90166	--
693335	MPEV3-032-10B	29-21-20	CMM	Hydraulic Motorpump Assembly	--	Aug 01/11	5	A319, A320, A321, A330, A340	Eaton Jackson, MS	62983 & 90166	--
3029683-001	MPEV3-032-17	29-21-20	CMM	Hydraulic Motorpump Assembly	--	Aug 01/11	5	A340	Eaton Jackson, MS	62983 & 90166	--
414470	MPEV3-032-1E	29-21-06	CMM	Hydraulic Motorpump Assembly	--	May 15/93	7	MD-80, DC-10 A300/A310	Eaton Jackson, MS	62983 & 90166	--
624372	MPEV3-032-1F	29-21-06	CMM	Hydraulic Motorpump Assembly	--	May 15/93	7	MD-80, DC-10	Eaton Jackson, MS	62983 & 90166	--
861555	MPEV3-032-1G	29-10-47	CMM	Hydraulic Motorpump Assembly	--	Oct 15/00	3	A300, A310, MD-80, MD-90, MD-11, DC-10	Eaton Jackson, MS	62983 & 90166	--
861555	MPEV3-032-1G	29-13	TR	N/A	--	Jan 29/07	Original	A300, A310, MD-80, MD-90, MD-11, DC-10	Eaton Jackson, MS	62983 & 90166	--
861555	MPEV3-032-1G	29-56	TR	N/A	--	Aug 27/14	Original	A300B, A300-600, A310-200, A310-300, MD-80, MD-90, DC-10, MD-11	Eaton Jackson, MS	62983 & 90166	--
861686	MPEV3-032-1H	29-10-46	CMM	Hydraulic Motorpump Assembly	--	Nov 1/00	2	A300, A310, BAC-146	Eaton Jackson, MS	62983 & 90166	--
520831	MPEV3-032-EA1	29-10-46	CMM	Hydraulic Motorpump Assembly	--	Nov 1/00	2	A300, A310, BAC-146	Eaton Jackson, MS	62983 & 90166	--
715776	MPEV3-032-GB1	29-21-06	CMM	Hydraulic Motorpump Assembly	--	May 15/93	7	BAE -146	Eaton Jackson, MS	62983 & 90166	--
731430	MPEV3-056-10	29-10-38	CMM	AC Driven Motorpump Assembly NOTE: Superseded by MPEV3-056-10A	--	Jan 15/90	Original	727, 737	Eaton Jackson, MS	62983 & 90166	--
887480	MPEV3-056-10A	29-10-52	CMM	AC Driven Motorpump Assembly NOTE: This manual supersedes 29-10-38	--	Nov 1/01	3	727, 737	Eaton Jackson, MS	62983 & 90166	--
622199	MPEV3-056-6D	29-11-16	CMM	AC Driven Motorpump Assembly	--	Oct 2/20	12	747-400, 757, 767	Eaton Jackson, MS	62983 & 90166	--
623303	MPEV3-056-6F	29-11-16	CMM	AC Driven Motorpump Assembly	--	Oct 2/20	12	747-400, 757, 767	Eaton Jackson, MS	62983 & 90166	--
731966	MPEV3-056-6H	29-11-16	CMM	AC Driven Motorpump Assembly	--	Oct 2/20	12	747-400, 757, 767, 777	Eaton Jackson, MS	62983 & 90166	--
3033115-100	MPEV3-056-6J	29-11-16	CMM	AC Driven Motorpump Assembly	--	Oct 2/20	12	747-400, 757, 767, 777	Eaton Jackson, MS	62983 & 90166	--
624206	MPEV3-056-7	29-10-35	CMM	AC Driven Motorpump Assembly - NOTE: Superseded by MPEV3-056-7A	--	Jan 15/90	Original	727, 737	Eaton Jackson, MS	62983 & 90166	--
887477	MPEV3-056-7A	29-10-49	CMM	AC Driven Motorpump Assembly NOTE: This manual supersedes 29-10-35	--	Feb 15/16	7	727, 737	Eaton Jackson, MS	62983 & 90166	--
887477	MPEV3-056-7A	29-19	TR	N/A	--	Sept 04/07	Original	727, 737	Eaton Jackson, MS	62983 & 90166	--
887477	MPEV3-056-7A	29-40	TR	N/A	--	Mar 21/12	Original	727, 737	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
731428	MPEV3-056-9	29-10-37	CMM	AC Driven Motorpump Assembly - NOTE: Superseded by MPEV3-056-9A	--	Jan 15/90	Original	727, 737	Eaton Jackson, MS	62983 & 90166	--
887479	MPEV3-056-9A	29-10-51	CMM	AC Driven Motorpump Assembly NOTE: This manual supersedes 29-10-37	--	Nov 1/01	3	727, 737	Eaton Jackson, MS	62983 & 90166	--
395812	MPHF1-152-2B	29-11-33	CMM	Hydraulic Power Transfer Package	--	Feb 15/86	6	Airbus A300, A310	Eaton Jackson, MS	62983 & 90166	--
404250	MPHF1-152-3	29-10-30	CMM	Hydraulic Power Transfer Package	--	Aug 15/11	10	Airbus A300, A310	Eaton Jackson, MS	62983 & 90166	--
571191	MPHF-1-152-3A	29-10-30	CMM	Hydraulic Power Transfer Package	--	Aug 15/11	10	Airbus A300, A310	Eaton Jackson, MS	62983 & 90166	--
622362	MPHF3-160-8C	29-20-16	CMM	Power Transfer Hydraulic Motorpump NOTE: This manual supersedes 29-20-15	--	Jan 07/11	6	757, Gulfstream V	Eaton Jackson, MS	62983 & 90166	--
622532	MPHF3-160-8D	29-20-16	CMM	Power Transfer Hydraulic Motorpump NOTE: This manual supersedes 29-20-15	--	Jan 07/11	6	757, Gulfstream V	Eaton Jackson, MS	62983 & 90166	--
3029686-001, 3029686-	MPHF3-160-9, MPHF3-	29-25-01	CMM	Power Transfer Hyd. Motorpump	--	Nov 16/11	1	Gulfstream V	Eaton Jackson, MS	62983 & 90166	--
974014	MPHV3-115-1B	29-10-57	CMM	Hydraulic Power Transfer Package	--	Jul 31/01	1	A319, A320	Eaton Jackson, MS	62983 & 90166	--
971600	MPHV3-115-1C	29-10-57	CMM	Hydraulic Power Transfer Package	--	Jul 31/01	1	A319, A320	Eaton Jackson, MS	62983 & 90166	--
319571	MS30-3913-25Z-S656-5	27-00-01	CMM	Hydraulic Motor	--	Oct 15/66	1	DC-8	Eaton Jackson, MS	62983 & 90166	--
206040	MS9-3911-30-S431	27-00-01	CMM	Hydraulic Motor	--	Apr 1/83	5	DC-8	Eaton Jackson, MS	62983 & 90166	--
248507	MS9-3911-30-S431-4C	27-00-02	CMM	Constant Displacement Hydraulic Motor	--	Jan 15/93	6	DC-8	Eaton Jackson, MS	62983 & 90166	--
188911	MS9-3911-30ZE	27-00-01	CMM	Hydraulic Motor	--	Apr 1/83	5	707, 720, 727, 737	Eaton Jackson, MS	62983 & 90166	--
240863	MS9-3911-30ZE-4C	27-00-02	CMM	Constant Displacement Hydraulic Motor	--	Jan 15/93	6	707, 720, 727, 737	Eaton Jackson, MS	62983 & 90166	--
240486	PF17-3911-25ZE-4C	29-10-01	CMM	Hydraulic Pump and Motorpumps	--	May 1/64	1	DC-6	Eaton Jackson, MS	62983 & 90166	--
N/A	PF-3906-2 & PS-3906-2	N/A	CMM	Constand Displacement Hydraulic Pumps and Motorpumps	--	Oct 22/58	Original	N/A	Eaton Jackson, MS	62983 & 90166	--
3031934-001	PF4-002-1	29-19-03	CMM	Hyd. Vane Pump Assy.	--	Nov 07/14	Original	Cessna Mustang	Eaton Jackson, MS	62983 & 90166	--
887182	PF4-038-11C	73-10-02	CMM	Vane Type Fuel Pump Assembly	--	Apr 15/03	1	Pratt and Whitney	Eaton Jackson, MS	62983 & 90166	--
972716	PF4-038-17B	73-20-04	CMM	Vane Type Fuel Pump Assembly	--	Jan 15/96	Original	Cessna Citation X	Eaton Jackson, MS	62983 & 90166	--
972716	PF4-038-17B	73-2	TR	N/A	--	Aug 11/05	Original	Cessna Citation X	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
972716	PF4-038-17B	73-4	TR	N/A	--	Nov 21/08	Original	Cessna Citation X	Eaton Jackson, MS	62983 & 90166	--
972716	PF4-038-17B	73-5	TR	N/A	--	Cancelled	Original	Cessna Citation X	Eaton Jackson, MS	62983 & 90166	--
406138	PF4-057-6A	28-20-05	CMM	Vane Type Fuel Pump Assembly	--	Oct 1/79	1	Jetstream 31/41	Eaton Jackson, MS	62983 & 90166	--
414199	PF4-057-6B	28-20-05	CMM	Vane Type Fuel Pump Assembly	--	Oct 1/79	1	Jetstream 31/41	Eaton Jackson, MS	62983 & 90166	--
429969	PF4-057-6C	28-20-05	CMM	Vane Type Fuel Pump Assembly	--	Oct 1/79	1	Jetstream 31/41	Eaton Jackson, MS	62983 & 90166	--
428337	PF4-057-6D	28-20-05	CMM	Vane Type Fuel Pump Assembly	--	Oct 1/79	1	Jetstream 31/41	Eaton Jackson, MS	62983 & 90166	--
569392	PF4-094-2C	28-20-02	CMM	Vane Type Fuel Pump Assembly	--	Mar 1/80	1	JT15-D Engine	Eaton Jackson, MS	62983 & 90166	--
569196	PPE4-094 Series	73-1	TR	N/A	--	July 18/03	Original	TFE-731 Engine	Eaton Jackson, MS	62983 & 90166	--
3032683-000	PPEF-004-1C	29-11-37	CMM	Hyd. Pump Assy	--	Sep 23/15	1	Embraer LJ	Eaton Jackson, MS	62983 & 90166	--
3032683-001	PPEF-004-1D	29-11-37	CMM	Hyd. Pump Assy	--	Sep 23/15	1	Embraer LJ	Eaton Jackson, MS	62983 & 90166	--
3032683-002	PPEF-004-1E	29-11-37	CMM	Hyd. Pump Assy	--	Sep 23/15	1	Embraer LJ	Eaton Jackson, MS	62983 & 90166	--
3032683-003	PPEF-004-1F	29-11-37	CMM	Hyd. Pump Assy	--	Sep 23/15	1	Embraer LJ	Eaton Jackson, MS	62983 & 90166	--
3032683-000	PPEF4-004-1C	29-42	TR	N/A	--	May 08/12	Original	Embraer LJ	Eaton Jackson, MS	62983 & 90166	--
3032683-000	PPEF4-004-1C	29-48	TR	N/A	--	Apr 17/13	Original	Phenom 100	Eaton Jackson, MS	62983 & 90166	--
3032988-001	PPEF4-004-2A	29-11-39	CMM	Hyd. Pump Assy (Power Pack)	--	Dec 02/16	1	Embraer VLJ	Eaton Jackson, MS	62983 & 90166	--
3032988-002	PPEF4-004-2B	29-11-39	CMM	Hyd. Pump Assy (Power Pack)	--	Dec 02/16	1	Embraer VLJ	Eaton Jackson, MS	62983 & 90166	--
570500	PPEV3-011-12A	29-11-19	CMM	Hyd. Packaged Pump Assy	--	Jan 10/12	2	Beech 1900	Eaton Jackson, MS	62983 & 90166	--
624494	PPEV3-011-12B	29-11-19	CMM	Hyd. Packaged Pump Assy	--	Jan 10/12	2	Beech 1900	Eaton Jackson, MS	62983 & 90166	--
624831	PPEV3-011-12C	29-11-19	CMM	Hyd. Packaged Pump Assy	--	Jan 10/12	2	Beech 1900	Eaton Jackson, MS	62983 & 90166	--
971652	PPEV3-011-12D	29-11-19	CMM	Hyd. Packaged Pump Assy	--	Jan 10/12	2	Beech 1900	Eaton Jackson, MS	62983 & 90166	--
571641	PPEV3-011-13	29-11-19	CMM	Hyd. Packaged Pump Assy	--	Jan 10/12	2	King Air 200, 300, 350	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
624499	PPEV3-011-13A	29-11-19	CMM	Hyd. Packaged Pump Assy	--	Jan 10/12	2	King Air 200, 300, 350	Eaton Jackson, MS	62983 & 90166	--
624832	PPEV3-011-13B	29-11-19	CMM	Hyd. Packaged Pump Assy	--	Jan 10/12	2	King Air 200, 300, 350	Eaton Jackson, MS	62983 & 90166	--
971518	PPEV3-011-13C	29-11-19	CMM	Hyd. Packaged Pump Assy	--	Jan 10/12	2	King Air 200, 300, 350	Eaton Jackson, MS	62983 & 90166	--
569196	PPF4-094-Series	73-21-32A	CMM	Vane Type Fuel Pump This manual supersedes 73-21-32	--	Feb 15/91	4	TFE-731 Engine	Eaton Jackson, MS	62983 & 90166	--
3031096-001	PPV3-045-1A	29-20-24	CMM	Var. Displ. Pump Package Assy	--	May 01/04	Original	S-92 Sikorsky	Eaton Jackson, MS	62983 & 90166	--
202716	PS24-3906-25ZH-4	29-20-1	CMM	Hydraulic Pump for AS-19058 Motorpump	--	Mar 1/78	3	707, 720B	Eaton Jackson, MS	62983 & 90166	--
405894	Pump for (MPEV3-032-3	29-21-07	CMM	Hydraulic Pump	--	May 15/93	8	A300, MD-80, DC-10	Eaton Jackson, MS	62983 & 90166	--
420609	Pump for (MPEV3-032-0	29-21-07	CMM	Hydraulic Pump	--	May 15/93	8	BAE -146	Eaton Jackson, MS	62983 & 90166	--
612469	Pump Only	29-10-01	CMM	Pump Assembly for EA-51082 Motorpumps	--	Dec 15/83	5	CV-580	Eaton Jackson, MS	62983 & 90166	--
268679	Pump Only	29-10-20	CMM	Pumps for AS-19570 and MPEV1-060- 2 Motorpumps	--	Dec 15/83	10	BAC 1-11, 727, 737	Eaton Jackson, MS	62983 & 90166	--
265156	Pump Only	29-10-20	CMM	Hydraulic Pumps for AS-19570 and MPEV1-060-2 Motorpumps	--	Dec 15/83	10	BAC 1-11, 727, 737	Eaton Jackson, MS	62983 & 90166	--
288339	Pump Only	29-21-11	CMM	Hydraulic Pump and Impeller Assembly for AS-19593, AS-19593-A, AS-19593-B, and AS-19593-C Motorpumps	--	Dec 15/83	6	DC-9	Eaton Jackson, MS	62983 & 90166	--
518203	Pump Only (MPEV3-032	29-21-21	CMM	Hydraulic Pump	--	Aug 01/11	5	A319, A320, A321	Eaton Jackson, MS	62983 & 90166	--
693830	Pump Only (MPEV3-032	29-21-21	CMM	Hydraulic Pump	--	Aug 01/11	5	A319, A320, A321, A330, A340	Eaton Jackson, MS	62983 & 90166	--
3029683-001	Pump Only (MPEV3-032	29-21-21	CMM	Hydraulic Pump	--	Aug 01/11	5	A340	Eaton Jackson, MS	62983 & 90166	--
418173	PV173L021U	29-11-06	CMM	Variable Displacement Hydraulic Pump	--	June 1/83	2	Pratt & Whitney	Eaton Jackson, MS	62983 & 90166	--
571097	PV173L021V	29-11-06	CMM	Variable Displacement Hydraulic Pump	--	June 1/83	2	Pratt & Whitney	Eaton Jackson, MS	62983 & 90166	--
570441	PV173L021W	29-11-06	CMM	Variable Displacement Hydraulic Pump	--	June 1/83	2	Pratt & Whitney	Eaton Jackson, MS	62983 & 90166	--
848846	PV3-019-1A	29-10-56	CMM	Variable Displacement Hydraulic Pump	--	Feb 05/10	2	Falcon 2000	Eaton Jackson, MS	62983 & 90166	--
3031749-001	PV3-019-1B	29-10-56	CMM	Variable Displacement Hydraulic Pump	--	Feb 05/10	2	Falcon 2000	Eaton Jackson, MS	62983 & 90166	--
402431	PV3-022-25	29-11-14	CMM	Variable Displacement Hydraulic Pump	--	May 15/92	2	MU 300	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
569105	PV3-022-28	29-11-12	CMM	Variable Displacement Hydraulic Pump	--	Oct 1/81	Original	Bell 214ST	Eaton Jackson, MS	62983 & 90166	--
570796	PV3-022-29	29-11-20	CMM	Variable Displacement Hydraulic Pump	--	Sep 15/84	Original	EMB-120	Eaton Jackson, MS	62983 & 90166	--
847705	PV3-022-36	29-10-91	CMM	Variable Displacement Hydraulic Pump Subassembly	--	Jun 01/08	Original	Y7-200A XIAN AIRCRAFT (XAC)	Eaton Jackson, MS	62983 & 90166	--
3032249-002	PV3-022-47A	29-10-97	CMM	Hyd. Pump Assy	--	July 15/09	Original	Embraer LJ	Eaton Jackson, MS	62983 & 90166	--
3032682-000	PV3-022-50	29-10-96	CMM	Var. Displ. Hyd. Pump	--	Nov 15/08	Original	Pratt & Whitney	Eaton Jackson, MS	62983 & 90166	--
329452	PV3-022-8	29-10-06	CMM	Variable Displacement Hydraulic Pump Subassembly	--	Sep 15/82	3	DC-8	Eaton Jackson, MS	62983 & 90166	--
351285	PV3-022-8A	29-10-06	CMM	Variable Displacement Hydraulic Pump	--	Sep 15/82	3	DC-8	Eaton Jackson, MS	62983 & 90166	--
971808	PV3-032-11	29-11-15	CMM	Variable Displacement Hydraulic Pump	--	May 29/15	8	EMB 135/145	Eaton Jackson, MS	62983 & 90166	--
971808	PV3-032-11	29-1	TR	N/A	--	Dec 05/03	Original	EMB-135/-145	Eaton Jackson, MS	62983 & 90166	--
971808	PV3-032-11	29-21	TR	N/A	--	Oct 01/07	Original	EMB 135/145	Eaton Jackson, MS	62983 & 90166	--
971808	PV3-032-11	29-28	TR	N/A	--	Mar 25/08	Original	EMB-135/-145	Eaton Jackson, MS	62983 & 90166	--
570347	PV3-032-3	29-11-15	CMM	Variable Displacement Hydraulic Pump	--	May 29/15	8	DHC-8	Eaton Jackson, MS	62983 & 90166	--
570347	PV3-032-3	29-1	TR	N/A	--	Dec 05/03	Original	DHC-8	Eaton Jackson, MS	62983 & 90166	--
570347	PV3-032-3	29-21	TR	N/A	--	Oct 01/07	Original	DHC-8	Eaton Jackson, MS	62983 & 90166	--
570347	PV3-032-3	29-28	TR	N/A	--	Mar 25/08	Original	DHC-8	Eaton Jackson, MS	62983 & 90166	--
887031	PV3-032-9	29-10-42	CMM	Variable Displacement Hydraulic Pump	--	May 30/96	1	Fokker 100	Eaton Jackson, MS	62983 & 90166	--
333861	PV3-044-16B	29-10-11	CMM	Var. Displ. Hyd. Pump	--	Feb 15/82	3	--	Eaton Jackson, MS	62983 & 90166	--
384925	PV3-044-26	29-10-22	CMM	Variable Displacement Hydraulic Pump	--	May 15/96	2	Fairchild Metro II/III	Eaton Jackson, MS	62983 & 90166	--
418397	PV3-044-30A	29-11-09	CMM	Variable Displacement Hydraulic Pump	--	Aug 15/83	1	Jetstar II	Eaton Jackson, MS	62983 & 90166	--
428131	PV3-044-33	29-11-05	CMM	Variable Displacement Hydraulic Pump	--	May 31/96	4	CL-600	Eaton Jackson, MS	62983 & 90166	--
570527	PV3-044-38A	29-11-18	CMM	Variable Displacement Hydraulic Pump	--	May 31/96	3	CL-601	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
570527	PV3-044-38A	29-33	TR	N/A	--	Feb 01/10	Original	CL-601	Eaton Jackson, MS	62983 & 90166	--
731515	PV3-044-38B	29-11-18	CMM	Variable Displacement Hydraulic Pump	--	May 31/96	3	CL-601 3A/3R	Eaton Jackson, MS	62983 & 90166	--
731515	PV3-044-38B	29-33	TR	N/A	--	Feb 01/10	Original	CL-601 3A/3R	Eaton Jackson, MS	62983 & 90166	--
622738	PV3-044-41	29-11-05	CMM	Variable Displacement Hydraulic Pump	--	May 31/96	4	CL-600	Eaton Jackson, MS	62983 & 90166	--
731334	PV3-044-41A	29-11-05	CMM	Variable Displacement Hydraulic Pump	--	May 31/96	4	CL-600	Eaton Jackson, MS	62983 & 90166	--
887055	PV3-044-48	29-10-44	CMM	Variable Displacement Hydraulic Pump	--	Feb 1/05	4	CRJ	Eaton Jackson, MS	62983 & 90166	--
887055	PV3-044-48	29-20	TR	N/A	--	Sept 07/07	Original	CRJ	Eaton Jackson, MS	62983 & 90166	--
887055	PV3-044-48	29-34	TR	N/A	--	Aug 23/10	Original	CRJ	Eaton Jackson, MS	62983 & 90166	--
320598	PV3-044-8	29-11-11	CMM	Variable Displacement Hydraulic Pump	--	Aug 15/96	2	Bell 412	Eaton Jackson, MS	62983 & 90166	--
731633	PV3-044-8A	29-11-11	CMM	Variable Displacement Hydraulic Pump	--	Aug 15/96	2	Bell 412	Eaton Jackson, MS	62983 & 90166	--
388222	PV3-075-10	29-21-05	CMM	Variable Displacement Hydraulic Pump	--	Oct 1/80	1	L-1011	Eaton Jackson, MS	62983 & 90166	--
390060	PV3-075-12	29-21-15	CMM	Variable Displacement Hydraulic Pump	--	Oct 1/80	1	A300	Eaton Jackson, MS	62983 & 90166	--
569935	PV3-075-21	29-15-07	CMM	Variable Displacement Hydraulic Pump	--	Feb 15/82	Original	CH-47C	Eaton Jackson, MS	62983 & 90166	--
328837	PV3-075-5	29-10-09	CMM	Hydraulic Pump	--	Oct 1/80	3	Nihon YS-11	Eaton Jackson, MS	62983 & 90166	--
973748	PV3-090-1	29-20-29	CMM	Hyd. Pump Assy	--	Jan 28/11	Original	S-92 Sikorsky	Eaton Jackson, MS	62983 & 90166	--
971910	PV3-115-34E	29-10-55	CMM	Ram Air Turbine Hydraulic Pump	--	Aug 30/96	Original	777	Eaton Jackson, MS	62983 & 90166	--
971910	PV3-115-34E	29-6	TR	N/A	--	June 13/05	Original	777	Eaton Jackson, MS	62983 & 90166	--
971910	PV3-115-34E	29-16	TR	N/A	--	Feb 26/07	Original	777	Eaton Jackson, MS	62983 & 90166	--
971910	PV3-115-34E	29-27	TR	N/A	--	Mar 14/08	Original	777	Eaton Jackson, MS	62983 & 90166	--
973930	PV3-115-34F	29-10-55	CMM	Ram Air Turbine Hydraulic Pump	--	Aug 30/96	Original	777	Eaton Jackson, MS	62983 & 90166	--
862536	PV3-115-EA5	29-10-48	CMM	Variable Displacement Hydraulic Pump	--	Mar 25/10	2	Fokker 100	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3029091-001	PV3-160-12C	29-10-74	CMM	Variable Displacement Hydraulic Pump	--	Oct 15/00	Original	Gulfstream V	Eaton Jackson, MS	62983 & 90166	--
3029076-001	PV3-160-15	29-39	TR	N/A	--	Jan 05/12	Original	Samsung Aerospace	Eaton Jackson, MS	62983 & 90166	--
371380	PV3-160-4	29-10-18	CMM	Variable Displacement Hydraulic Pump	--	Mar 15/13	18	707, 720, 727, 737	Eaton Jackson, MS	62983 & 90166	--
371380	PV3-160-4	29-15	TR	N/A	--	Aug 15/06	Original	707, 720, 727, 737	Eaton Jackson, MS	62983 & 90166	--
371380	PV3-160-4	29-36	TR	N/A	--	Jan 31/11	Original	707, 720, 727, 737	Eaton Jackson, MS	62983 & 90166	--
424244	PV3-160-4A	29-10-18	CMM	Variable Displacement Hydraulic Pump	--	Mar 15/13	18	707, 720, 727, 737	Eaton Jackson, MS	62983 & 90166	--
424244	PV3-160-4A	29-36	TR	N/A	--	Jan 31/11	Original	707, 720, 727, 737	Eaton Jackson, MS	62983 & 90166	--
623337	PV3-160-4B	29-10-18	CMM	Variable Displacement Hydraulic Pump	--	Mar 15/13	18	707, 720, 727, 737	Eaton Jackson, MS	62983 & 90166	--
623337	PV3-160-4B	29-36	TR	N/A	--	Jan 31/11	Original	707, 720, 727, 737	Eaton Jackson, MS	62983 & 90166	--
623339	PV3-160-4C	29-10-18	CMM	Variable Displacement Hydraulic Pump	--	Mar 15/13	18	707, 720, 727, 737	Eaton Jackson, MS	62983 & 90166	--
623339	PV3-160-4C	29-36	TR	N/A	--	Jan 31/11	Original	707, 720, 727, 737	Eaton Jackson, MS	62983 & 90166	--
569653	PV3-160-8	29-10-18	CMM	Variable Displacement Hydraulic Pump	--	Mar 15/13	18	DC-8	Eaton Jackson, MS	62983 & 90166	--
569653	PV3-160-8	29-36	TR	N/A	--	Jan 31/11	Original	DC-8	Eaton Jackson, MS	62983 & 90166	--
623977	PV3-240-10	29-11-34	CMM	Variable Displacement Hydraulic Pump	--	May 15/17	9	747, 757, 767, A300-600, A310, A319, A320, A321	Eaton Jackson, MS	62983 & 90166	--
623977	PV3-240-10	29-29	TR	N/A	--	Jun 16/09	Original	747, 757, 767, A300-600, A310, A319, A320, A321	Eaton Jackson, MS	62983 & 90166	--
623977	PV3-240-10	29-35	TR	N/A	--	Jan 06/11	Original	747, 757, 767, A300-600, A310, A319, A320, A321	Eaton Jackson, MS	62983 & 90166	--
623977, 887111, 88767	PV3-240-10, PV3-240-10	29-55	TR	N/A	--	Oct 07/14	Original	747, 757, 767, A300-600, A310, A319, A320, A321	Eaton Jackson, MS	62983 & 90166	--
887111	PV3-240-10A	29-11-34	CMM	Variable Displacement Hydraulic Pump	--	May 15/17	9	747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
887111	PV3-240-10A	29-29	TR	N/A	--	Jun 16/09	Original	747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
887111	PV3-240-10A	29-35	TR	N/A	--	Jan 06/11	Original	747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
887673	PV3-240-10C	29-11-34	CMM	Variable Displacement Hydraulic Pump	--	May 15/17	9	747, 757, 767, A300-600, A310, A319, A320, A321	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
887673	PV3-240-10C	29-29	TR	N/A	--	Jun 16/09	Original	747, 757, 767, A300-600, A310, A319, A320, A321	Eaton Jackson, MS	62983 & 90166	--
887673	PV3-240-10C	29-35	TR	N/A	--	Jan 06/11	Original	747, 757, 767, A300-600, A310, A319, A320, A321	Eaton Jackson, MS	62983 & 90166	--
3031863-001	PV3-240-10D	29-11-34	CMM	Variable Displacement Hydraulic Pump	--	May 15/17	9	747, 757, 767, A300-600, A310, A319, A320, A321	Eaton Jackson, MS	62983 & 90166	--
3031863-001	PV3-240-10D	29-29	TR	N/A	--	Jun 16/09	Original	747, 757, 767, A300-600, A310, A319, A320, A321	Eaton Jackson, MS	62983 & 90166	--
3031863-001	PV3-240-10D	29-35	TR	N/A	--	Jan 06/11	Original	747, 757, 767, A300-600, A310, A319, A320, A321	Eaton Jackson, MS	62983 & 90166	--
849589	PV3-240-18	29-10-61	CMM	Variable Displacement Hydraulic Pump	--	July 31/18	9	737-600,700,800,900	Eaton Jackson, MS	62983 & 90166	910387
849589	PV3-240-18	29-1	TR	N/A	--	Dec 15/02	Original	737-600, 700, 800, 900	Eaton Jackson, MS	62983 & 90166	--
849589	PV3-240-18	29-4	TR	N/A	--	Oct 18/04	Original	737-600, 700, 800, 900	Eaton Jackson, MS	62983 & 90166	--
849589	PV3-240-18	29-17	TR	N/A	--	Mar 19/07	Original	737-600, -700, -800, -900	Eaton Jackson, MS	62983 & 90166	--
849589	PV3-240-18	29-30r1	TR	N/A	--	Jan 13/10	1	737-600, -700, -800, -900	Eaton Jackson, MS	62983 & 90166	--
849589	PV3-240-18	29-57	TR	N/A	--	Sept 29/14	Original	737-600/-700/-800/-900	Eaton Jackson, MS	62983 & 90166	--
849589	PV3-240-18	29-58	TR	N/A	--	Oct 01/14	Original	737-600/-700/-800/-900	Eaton Jackson, MS	62983 & 90166	--
849589	PV3-240-18	29-60	TR	N/A	--	Aug 06/15	Original	737-600/-700/-800/-900	Eaton Jackson, MS	62983 & 90166	--
849589	PV3-240-18	29-62	TR	N/A	--	Nov 16/16	Original	737-600/-700/-800/-900	Eaton Jackson, MS	62983 & 90166	--
350880	PV3-240-2	29-11-02	CMM	Var. Displ. Hyd. Pump	--	May 15/86	18	747, L-1011	Eaton Jackson, MS	62983 & 90166	--
350880-1	PV3-240-2A	29-11-02	CMM	Var. Displ. Hyd. Pump	--	May 15/86	18	747, L-1011, DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-2	PV3-240-2B	29-11-02	CMM	Var. Displ. Hyd. Pump	--	May 15/86	18	DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-3	PV3-240-2C	29-11-02	CMM	Var. Displ. Hyd. Pump	--	May 15/86	18	DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-5	PV3-240-2E	29-11-02	CMM	Var. Displ. Hyd. Pump	--	May 15/86	18	DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	29-11-03	CMM	Variable Displacement Hydraulic Pump	--	Apr 10/12	26	A300, 310, B747,757,767, DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	29-7	TR	N/A	--	Oct 30/05	Original	A300, 310, B747, 757, 767, DC-10	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
350880-6	PV3-240-2F	29-25	TR	N/A	--	Jan 25/08	Original	A300, 310, B747, 757, 767, DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	29-32	TR	N/A	--	Oct 19/09	Original	A300, 310, B747, 757, 767, DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	29-37	TR	N/A	--	Feb 15/11	Original	A300, 310, B747, 757, 767, DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-7	PV3-240-2G	29-11-04	CMM	Variable Displacement Hydraulic Pump	--	May 15/11	21	A300, 310, B747, 757, 767, L-1011	Eaton Jackson, MS	62983 & 90166	--
623272	PV3-240-2H	29-11-03	CMM	Variable Displacement Hydraulic Pump	--	Apr 10/12	26	DC-10	Eaton Jackson, MS	62983 & 90166	--
623272	PV3-240-2H	29-7	TR	N/A	--	Oct 30/05	Original	DC-10	Eaton Jackson, MS	62983 & 90166	--
623272	PV3-240-2H	29-32	TR	N/A	--	Oct 19/09	Original	DC-10	Eaton Jackson, MS	62983 & 90166	--
623272	PV3-240-2H	29-37	TR	N/A	--	Feb 15/11	Original	DC-10	Eaton Jackson, MS	62983 & 90166	--
N/A	PV3-300-13 Series	29-10-41	CMM	Var. Displ. Hdy. Pump (England Controlled, See Bedhampton Index)	--	N/A	N/A	A330, A340	Eaton Jackson, MS	62983 & 90166	--
972424	PV3-300-16C	29-10-58	CMM	Variable Displacement Hydraulic Pump	--	Nov 14/14	5	777	Eaton Jackson, MS	62983 & 90166	--
972424	PV3-300-16C	29-31	TR	N/A	--	Sept 21/09	Original	777	Eaton Jackson, MS	62983 & 90166	--
972424, 972952	PV3-300-16C, PV3-300-	29-43	TR	N/A	--	July 02/12	Original	777	Eaton Jackson, MS	62983 & 90166	--
972424	PV3-300-16C, PV3-300-	29-47	TR	N/A	--	Oct 25/12	Original	767, 777	Eaton Jackson, MS	62983 & 90166	--
972952	PV3-300-16C, PV3-300-	29-47	TR	N/A	--	Oct 25/12	Original	767, 777	Eaton Jackson, MS	62983 & 90166	--
972424, 972952	PV3-300-16C, PV3-300-	29-49	TR	N/A	--	Sept 11/13	Original	767, 777	Eaton Jackson, MS	62983 & 90166	--
972424, 972952	PV3-300-16C, PV3-300-	29-50	TR	N/A	--	Sept 11/13	Original	767, 777	Eaton Jackson, MS	62983 & 90166	--
972952	PV3-300-16D	29-10-58	CMM	Variable Displacement Hydraulic Pump	--	Nov 14/14	5	777	Eaton Jackson, MS	62983 & 90166	--
972952	PV3-300-16D	29-31	TR	N/A	--	Sept 21/09	Original	777	Eaton Jackson, MS	62983 & 90166	--
848028	PV3-300-19	29-10-62	CMM	Variable Displacement Hydraulic Pump	--	Jun 1/99	Original	--	Eaton Jackson, MS	62983 & 90166	--
314450	PVB-022-1 for (MPEV3-4	29-10-16	CMM	Variable Displacement Hydraulic Pump	--	July 15/80	2	BAC1-11	Eaton Jackson, MS	62983 & 90166	--
314470	PVB-022-2	29-15-02	CMM	Variable Displacement Hydraulic Pump	--	Dec 30/97	3	Falcon 50	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
974641	Reservoir Level Switch	29-10-65	CMM	Reservoir Level Switch Assembly	--	July 15/03	1	DHC-8	Eaton Jackson, MS	62983 & 90166	--
3031174-001	Reservoir Level Switch	29-10-65	CMM	Reservoir Level Switch Assembly	--	July 15/03	1	DHC-8	Eaton Jackson, MS	62983 & 90166	--
974641	Reservoir Level Switch	974641-29-02	CMM	Reservoir Level Switch - New Part Number - Reliability Improvements	--	Oct 31/02	Original	DHC-8	Eaton Jackson, MS	62983 & 90166	--
3032763-001	RRS-306-2A	29-11-38	CMM	Hyd. Reservoir Assembly	--	Mar 29/13	2	Embraer LJ	Eaton Jackson, MS	62983 & 90166	--
3032763-001, 3032763-	RRS-306-2A, RRS-306-2B	29-53	TR	N/A	--	May 22/14	Original	EMB 300	Eaton Jackson, MS	62983 & 90166	--
3032763-002	RRS-306-2B	29-11-38	CMM	Hyd. Reservoir Assembly	--	Mar 29/13	2	Embraer LJ	Eaton Jackson, MS	62983 & 90166	--
3032763-003	RRS-306-2C	29-11-38	CMM	Hyd. Reservoir Assembly	--	Mar 29/13	2	Embraer LJ	Eaton Jackson, MS	62983 & 90166	--
997305	Rudder Isolation Valve	29-10-66	CMM	Rudder Isolation Valve	--	Jan 15/01	Original	DHC-8	Eaton Jackson, MS	62983 & 90166	--
3031863-002	Hydraulic Pump Assembly	29-11-10	CMM	Variable Displacement Hydraulic Pump	May 17/17	--	0	A320NEO	Eaton Jackson, MS	62983 & 90166	--
3031863-002	PV3-240-10F	29-66	TR	--	Dec 19/17	--	Original	A320NEO (Only)	Eaton Jackson, MS	62983 & 90166	--
849589	PV3-240-18	29-67	TR	--	Dec 20/17	--	Original	737-600/-700/-800/-900	Eaton Jackson, MS	62983 & 90166	--
623977, 887111, 88767	PV3-240-10, PV3-240-18	29-68	TR	--	Dec 21/17	--	Original	747, 757, 767, A300-600, A310, A319, A320CEO, A321	Eaton Jackson, MS	62983 & 90166	--
623977, 887111, 88767	PV3-240-10, PV3-240-18	29-69	TR	--	Jan 05/18	--	Original	747, 757, 767, A300-600, A310, A319, A320CEO, A321	Eaton Jackson, MS	62983 & 90166	--
3033037-101	PV3-240-25A	29-10-26	CMM	Hydraulic Pump Assembly	Apr 30/15	--	Original	Embraer E2-E190	Eaton Jackson, MS	62983 & 90166	--
3033041-101	MPEV3-012-7A	29-12-02	CMM	AC Electric Hydraulic Motorpump Assembly	Mar 30/15	--	Original	Embraer E2-E190	Eaton Jackson, MS	62983 & 90166	--
3022144-100	MPEV3-032-EA4	29-22-02	CMM	AC Electric Motor Driven Pump Assembly	Mar 05/18	--	Original	Embraer E2-E190	Eaton Jackson, MS	62983 & 90166	--
3033045-100	MPHF3-160-10	29-25-02	CMM	Power Transfer Hyd Motorpump Assembly	--	Apr 19/18	1	Embraer E2-E190	Eaton Jackson, MS	62983 & 90166	--
3033096-100	MPEV3-056-7B	29-22-09	CMM	AC Driven Motorpump Assembly	Oct 31/19	--	2	737-Max	Eaton Jackson, MS	62983 & 90166	--
961627940732	165W01020165W0102	29-70	TR	N/A	Jan 23/18	--	Original	737	Eaton Jackson, MS	62983 & 90166	--
30318636-002	PV3-240-10F	29-71	TR	N/A	Jan 30/18	--	Original	NEOA320	Eaton Jackson, MS	62983 & 90166	--
--	--	--	--	--	--	--	--	--	--	--	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
265156	AS-19570-B	265156-29-01	SB	Housing and Retainer Rework	Dec 31/64	--	Original	727, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
265156	AS-19570-B, AS-19570-C	265156-29-02	SB	Preparation of Sealing Surfaces for Shaft Seal Carbon Washers	Oct 17/67	--	1	727, 737, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
265156	AS-19570-B	265156-29-03	SB	Improved Lubrication of End Bell Bearing	Feb 01/65	--	Original	727, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
265156	AS-19570-B	265156-29-04	SB	Corrections in Overhaul Manual	Dec 07/64	--	Original	727, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
265156	AS-19570-B	265156-29-05	SB	Contact (connector pin) Replacement	Mar 15/65	--	1	727, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
265156	AS-19570-B	265156-29-06	SB	This SB has been cancelled	N/A	--	N/A	N/A	Eaton Jackson, MS	62983 & 90166	--
265156	AS-19570-B	265156-29-07	SB	Conversion of Model AS-19570-B to Model AS-19570-C for Boeing 727 Aircraft	Mar 09/67	--	Original	727	Eaton Jackson, MS	62983 & 90166	--
265156	AS-19570-B, AS-19570-C	265156-29-08	SB	Housing Subassembly Rework	July 12/67	--	Original	727, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
265156	AS-19570-B, AS-19570-C	265156-29-09	SB	Incorporation of Teflon Back-up Ring	Oct 17/67	--	Original	727, 737, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
265156	AS-19570-B, AS-19570-C	265156-29-10	SB	Yoke Arm Clevis Pin Hole Rework	Feb 01/68	--	Original	727, 737, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
265156	AS-19570-B, AS-19570-C	265156-29-11	SB	Conversion of Model AS-19570-B to Model AS-19570-B-GB1 and AS-19570-C to AS-19570-C-GB1	May 15/79	--	2	BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
265156	AS-19570-B, AS-19570-C, AS-19570-B-GB1	265156-29-12	SB	Knurling of Electric Motor Rotor	Mar 24/70	--	2	727, 737, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
265156	AS-19570-B, AS-19570-C	265156-29-13	SB	Incorporation of New Shaft Seal	Oct 01/70	--	1	727, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
265156	AS-19570-B, AS-19570-C	265156-29-14	SB	Change in Material for Bearing Inner Races	Sept 24/70	--	Original	727, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
265156	AS-19570-B, AS-19570-C, AS-19570-B-GB1	265156-29-15	SB	Outlet Pintle Bearing Change	Dec 10/71	--	Original	727, 737, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
265156	AS-19570-B, AS-19570-C	265156-29-16	SB	Change in Material for Knuckles and Fixed Bearing Retainer	June 09/71	--	Original	727, 737, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
279952, 268737, 323636	AS-19570-B, AS-19570-B-GB1, AS-19570-C	279952-29-17	SB	Improved Electric Motor Rotor	Mar 29/72	--	Original	727, 737, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
279952, 268737, 323636	AS-19570-B, AS-19570-B-GB1, AS-19570-C	279952-29-18	SB	Material Change for Shaft Seal Washer in Electric Motor	Apr 14/72	--	Original	727, 737, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
265156	AS-19570-B, AS-19570-C	279952-29-19	SB	Change in Material for Universal Link Pins	May 08/72	--	Original	727, 737, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
265156	AS-19570-B, AS-19570-C	279952-29-20	SB	Electrical Receptacle Change	July 05/73	--	Original	727, 737, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
279952	AS-19570-C	279952-29-21	SB	Optional Electrical Receptacle	Dec 20/74	--	Original	727, 737	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
323636, 776655, 378001	AS-19570-C, AS-19570-C-GB1, MPEV-060-2	279952-29-22	SB	Replacement of Finger Spring	Feb 01/83	--	1	727, 737	Eaton Jackson, MS	62983 & 90166	--
323636, 776655, 378001	AS-19570-C, AS-19570-C-GB1, MPEV-060-2	279952-29-23	SB	Shaft, Pistons and Cylinder Block Subassembly Change	Mar 10/82	--	Original	727, 737, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
323636, 378001	AS-19570-C, MPEV1-060-2	279952-29-24	SB	Conversion From Bent Axis to Inline Pump	Feb 06/89	--	Original	727, 737	Eaton Jackson, MS	62983 & 90166	--
232636, 378001, 77665	AS-19570-C, MPEV1-060-2, AS-19570C-GB1	279952-29-25	SB	Pumps for AS-19570 and MPEV1-060-2 Motorpumps - Thrust Bearing Change	May 21/04	--	1	727, 737, BAC 1-11	Eaton Jackson, MS	62983 & 90166	--
3029091-001	PV3-160-12C	3029091-001-29-01	SB	Introduction on New Model PV3-160-12D	July 31/00	--	Original	Gilfstream V	Eaton Jackson, MS	62983 & 90166	--
848882	PF4-038-11D	3029309-001-73-01	SB	Introduction of Model PF4-038-11F	May 01/01	--	Original	PW305A, PW305B	Eaton Jackson, MS	62983 & 90166	--
3031096-001	PPV3-045-1A	3031096-001-29-01	SB	Shaft Seal	Nov 15/05	--	Original	Sikorsky S-92	Eaton Jackson, MS	62983 & 90166	--
3031096-001	PPV3-045-1A	3031096-001-29-02	SB	Housing Modification	Feb 18/08	--	Rev. 1	Sikorsky S-92	Eaton Jackson, MS	62983 & 90166	--
3031863-001	PV3-240-10D	3031863-001-29-01	SB	Hydraulic Pump Lift Limiter Retainer Replacement	May 10/10	--	Original	747, 757, 767, A318, A319, A320, A321, DC-10, MD10, MD11	Eaton Jackson, MS	62983 & 90166	--
3031863-001	PV3-240-10D	3031863-001-29-02	SB	Introduction of new pump part number, PN 3031863-002 (PV3-240-10F)	May 17/17	--	Rev. 1	A320NEO (Only)	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	314195-29-01	SB	Replacement of Electrically Depressurized Dual Range Valve Subassembly	Mar 05/69	--	1	DC-9	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	314195-29-02	SB	Incorporation of an Improved Spool and Sleeve Subassembly in the Dual Range Control Valve Subassembly	Nov 20/67	--	1	DC-9	Eaton Jackson, MS	62983 & 90166	--
314195, 311608	AS-66411-L-S666, AS-6641-L-S661-S	314195-29-03	SB	Pilot Valve and Bushing Subassembly Replacement	Nov 30/67	--	Original	DC-9	Eaton Jackson, MS	62983 & 90166	--
314195, 311608	AS-66411-L-S666, AS-6641-L-S661-S	314195-29-04	SB	Conversion of Model AS-66411-L-S661-S to AS-66411-L-S666	Mar 25/98	--	Original	DC-9	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	314195-29-05	SB	Rework mounting flange subassembly and replace rear radial bearing to provide increased flow through the bearing	Sept 22/70	--	3	DC-9	Eaton Jackson, MS	62983 & 90166	--
308485, 311608, 3029981-001	AS-66411-L-S661, AS-66411-L-S661-S, AS-66411-L-S666	314195-29-06	SB	Improved plunger and seat replacement in outlet flange blocking valve	Aug 22/68	--	Original	DC-9	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	314195-29-07	SB	Repositioning outer race of rear radial bearing and removal of spring washer	Mar 18/69	--	Original	DC-9	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	314195-29-08	SB	Rework of Yoke to Improve Assembly Operations	Apr 03/69	--	Original	DC-9	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	314195-29-09 (29-28)	SB	Improved Shaft Seal Element Material	July 01/69	--	Original	DC-9	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	314195-29-10	SB	Pump Attachment Clamp Change	Sept 22/70	--	Original	DC-9	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	314195-29-11	SB	Change in Material for Knuckles and Fixed Bearing Retainer	Mar 29/71	--	Original	DC-9	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
314195	AS-66411-L-S666	314195-29-12	SB	Change in Material for Shaft Sealing Washer	June 23/71	--	Original	DC-9	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	314195-29-13	SB	Change in Material for Universal Link Pins	Oct 06/72	--	1	DC-9	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	314195-29-14	SB	Replacement of Finger Spring	Feb 01/63	--	1	DC-9	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	314195-29-15	SB	Shaft, Pistons and Cylinder Block Subassembly Change	Mar 10/82	--	Original	DC-9	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	314195-29-16	SB	Installation of Non-Matallic Drive Shaft Coupling Adapter	June 24/83	--	Original	DC-9	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	314195-29-17	SB	Control Spring Cavity Dimension of Dual Range Control Valve	Nov 21/88	--	Original	DC-9, MD-80	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	314195-29-18	SB	Incorporation of New Blocking Valve Flange	July 01/92	--	Original	DC-9, MD-80	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	314195-29-19	SB	Modification of Double Ended Polyimide Adapter Coupling Shaft	June 01/99	--	2	DC-9, MD-80	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	314195-29-20	SB	Modification of Double Ended Polyimide Adapter Coupling Shaft	June 01/99	--	2	DC-9, MD-80	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	314195-29-21	SB	Installation of Foot Valve Spacer	Dec 01/98	--	Original	DC-9, MD-80	Eaton Jackson, MS	62983 & 90166	--
314195	AS-66411-L-S666	314195-29-23	SB	Introduction of AS-66411-L-S666B	Mar 30/05	--	Original	DC-9, MD-80 (except MD-82 and MD-88 with PV3-760-4 pumps installed)	Eaton Jackson, MS	62983 & 90166	--
320598	PV3-044-8	320598-29-01	SB	Introduction of Model PV3-044-8A	Dec 28/92	--	Rev. 1	Bell 212/412	Eaton Jackson, MS	62983 & 90166	--
320598, 731633	PV3-044-8, PV3-044-8A	320598-29-02	SB	Product Improvement - Compensator Spring Guide	Nov 15/01	--	Original	Bell 212/412	Eaton Jackson, MS	62983 & 90166	--
314450, 328759, 328833	PVB-022-1 for (MPEV3-022-3A),	328759-29-07	SB	Variable Displacement Hydraulic Pump - Shaft Seal Change	July 12/90	--	Original	BAC1-11	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-01	SB	New Piston and Shoe Subassemblies	May 24/74	--	Original	DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-02	SB	Modification of 412680 Valve Block and Inserts Subassembly	Mar 13/74	--	Original	DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-03	SB	Modification of Bushing and Valves Subassembly, P/N 412338	Mar 13/74	--	Original	DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-04	SB	Yoke Subassembly Modification	June 03/74	--	Original	DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-05	SB	Modification of Piston Shoe Bearing Plate and Yoke Subassembly	June 03/74	--	Original	DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-06	SB	Change in Parting Line Seals Between Valve Block, Adapter Block and Housing	Apr 02/74	--	Original	DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-07	SB	Shaft Seal Mating Ring Retainer Change	Sept 18/74	--	Original	DC-10	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
350880-6	PV3-240-2F	350880-6-29-08	SB	Adapter Block Roller Bearing Retention	Jan 20/75	--	2	DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-09	SB	Modification of Adapter and Case Relief Valve Subassembly	July 05/74	--	Original	DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-10	SB	Improved Mounting Screws and Washers	Nov 04/74	--	Original	DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-11	SB	Solenoid Valve Improvements	Apr 21/75	--	Original	DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-12	SB	Yoke Control Spring Change	Aug 20/76	--	Original	DC-10	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-13	SB	Pressure Control Changes	Feb 28/77	--	Original	DC-10, A300B	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-14	SB	Repair of Part Number 401052 Blocking Valve Piston and Seat Subassembly	Apr 15/78	--	Original	DC-10, A300B	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-15	SB	Replacement of Compensator Spring	Oct 20/78	--	Original	DC-10, A300B	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-16	SB	Repair of Solenoid Valve	Oct 20/78	--	Original	DC-10, A300B	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-17	SB	Shaft Seal Element Change	May 20/79	--	Original	DC-10, A300B, 747	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-18	SB	Replacement of Coupling Shaft/Gear Box Packing	May 20/79	--	Original	DC-10, A300B, 747	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-19	SB	Yoke Spring and Spring Guide Change	June 10/80	--	Original	DC-10, A300B, 747	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-20	SB	Incorporation of Parting Line Control Pressure Seal Tube	Jan 31/96	--	2	DC-10/MD-11, A300/A310, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-21	SB	Replacement of Solenoid Valve	May 15/81	--	1	DC-10, A300B, 747	Eaton Jackson, MS	62983 & 90166	--
350880-6	PV3-240-2F	350880-6-29-22	SB	Variable Displacement Hydraulic Pump - Solenoid Valve	June 20/83	--	Original	DC-10, A300/A310, B747, B757, B767, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350080-6	PV3-240-2F	350880-6-29-23	SB	Addition of Parting Line Control Pressure Seal Tube Spacer and Shim Kit	Feb 15/84	--	Original	DC-10, A300B, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350080-6	PV3-240-2F	350880-6-29-24	SB	Replacement of Piston-Shoe Hold Down Retainer Plate Screws	July 05/84	--	1	DC-10, A300B, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350080-6	PV3-240-2F	350880-6-29-25	SB	Replacement of Impeller Key, Washer, and Screw	Nov 01/84	--	Original	DC-10/MD-11, A300/A310, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350080-6	PV3-240-2F	350880-6-29-26	SB	Shaft Seal Change	May 15/86	--	Original	DC-10/MD-11, A300/A310, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350080-6, 623372	PV3-240-2F, PV3-240-2H	350880-6-29-27	SB	Coupling Shaft Packing Change	Dec 15/86	--	Original	DC-10, A300, A310, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350080-6	PV3-240-2F	350880-6-29-28	SB	Face Seal Change	Jan 15/93	--	2	DC-10, MD-11, A300, A310, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
350080-6	PV3-240-2F	350880-6-29-29	SB	Incorporation of Transfer Tube Spacer	Dec 09/88	--	1	DC-10, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350080-6	PV3-240-2F	350880-6-29-30	SB	Shaft Seal Assembly	Dec 09/88	--	1	DC-10, A300, A310, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350080-6	PV3-240-2F	350880-6-29-31	SB	Modification Plate Change	Sept 04/87	--	Original	DC-10, A300, A310, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350080-6, 623372	PV3-240-2F, PV3-240-2H	350880-6-29-32	SB	Yoke Control Spring Change	July 23/90	--	1	DC-10, A300, A310, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350080-6, 623372	PV3-240-2F, PV3-240-2H	350880-6-29-33	SB	Introduction of Threaded Control Pressure Seal Tube	Oct 15/96	--	4	DC-10, A300, A310, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350080-6	PV3-240-2F	350880-6-29-34	SB	Longer Mounting Bolts to Increase Grip	Feb 18/91	--	Original	DC-10, A300, A310, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350080-6	PV3-240-2F	350880-6-29-35	SB	Introduction of Ductile Iron Cylinder Block	Jan 03/94	--	1	DC-10, A300, A310, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350080-6	PV3-240-2F	350880-6-29-36	SB	Incorporation of Polyimide Coupling Shaft	Sept 08/92	--	Original	DC-10, MD-11, A300, A310, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350080-6	PV3-240-2F	350880-6-29-37	SB	New Blocking Valve Plug	Oct 01/96	--	1	DC-10, MD-11, A300, A310, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350080-6	PV3-240-2F	350880-6-29-38	SB	Carbon Shaft Seal Product Improvement	Jan 31/00	--	2	DC-10, MD-11, A300, A310, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350080-6	PV3-240-2F	350880-6-29-39	SB	Blocking Valve Carbon Filled Teflon Backup Rings	Feb 15/98	--	Original	DC-10, MD-11, A300, A310, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350080-6	PV3-240-2F	350880-6-29-41	SB	Introduction of Service Part - Improved New Blocking Valve	Mar 01/04	--	Original	DC-10, MD-11, A300, A310, 747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
350880-7	PV3-240-2G	350880-7-29-31	SB	Variable Displacement Hydraulic Pump - Blocking Valve	Mar 01/04	--	Original	A300, A310, 747, 757, 767, L-1011	Eaton Jackson, MS	62983 & 90166	--
371380	PV3-160-4	371380-29-01	SB	Foot Valve Modification	Feb 10/72	--	Original	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380	PV3-160-4	371380-29-02	SB	New Piston Shoe Retaining Plate	Feb 10/72	--	Original	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380	PV3-160-4	371380-29-03	SB	Bushing and Valves Subassembly Modification	Feb 10/72	--	Original	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380	PV3-160-4	371380-29-04	SB	New Piston and Shoe Subassemblies	July 25/72	--	Original	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380	PV3-160-4	371380-29-05	SB	Modification Record Plate Added	July 14/72	--	Original	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380	PV3-160-4	371380-29-06	SB	New Actuator Piston	Nov 01/72	--	Original	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380	PV3-160-4	371380-29-07	SB	Improved Yoke Control Spring	Mar 25/75	--	1	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380	PV3-160-4	371380-29-08	SB	Improved Pressure Compensator Valve	Dec 06/73	--	Original	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
371380	PV3-160-4	371380-29-09	SB	New Solenoid Valve	Sep 30/74	--	Original	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380	PV3-160-4	371380-29-10	SB	Improved Mounting Screws and Washers	Mar 15/75	--	1	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380	PV3-160-4	371380-29-11	SB	Solenoid Valve Improvements	Apr 21/75	--	Original	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380, 424244, 623337, 623339	PV3-160-4, PV3-160-4A, PV3-160-4B, PV3-160-4C	371380-29-13	SB	Conversion of Assembly PN 371380 (PV3-160-4) to PN 424244 (PV3-160-4A) and PN 623337 (PV3-160-4B) to PN 623339 (PV3-160-4C)	Jul 15/03	--	2	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380, 424244	PV3-160-4, PV3-160-4A	371380-29-14	SB	New Piston and Shoe Subassemblies	Aug 10/83	--	1	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380	PV3-160-4	371380-29-15	SB	Yoke Control Spring Seat Modification	Apr 15/78	--	Original	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380	PV3-160-4	371380-29-16	SB	Modification of Compensator Spring Guide	Oct 15/78	--	Original	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380	PV3-160-4	371380-29-17	SB	Repair of Solenoid Valve	Oct 20/78	--	Original	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380, 424244	PV3-160-4, PV3-160-4A	371380-29-18	SB	Shaft Seal Element Change	Aug 10/83	--	1	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380, 424244	PV3-160-4, PV3-160-4A	371380-29-19	SB	Yoke Spring and Spring Guide Change	Aug 10/83	--	1	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380, 424244	PV3-160-4, PV3-160-4A	371380-29-20	SB	Installation of Non-Metallic Drive Shaft Coupling Adapter	Jan 15/96	--	1	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
424244, 623339	PV3-160-4A, PV3-160-4C	371380-29-21	SB	Incorporation of Steel Valve Plate Spacer	Dec 14/92	--	Original	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380, 569653	PV3-160-4, PV3-160-4B	371380-29-22	SB	Convert Models	Dec 23/92	--	Original	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
371380, 424244, 623337, 623339, 569653	PV3-160-4, PV3-160-4A, PV3-160-4B, PV3-160-4C, PV3-160-8	371380-29-24	SB	Introduction of Blocking Valve Product Improvements	Jul 16/98	--	1	707, 727, 737, DC-8, MD-80, MD-90	Eaton Jackson, MS	62983 & 90166	--
373364	MF3-075-4A	373364-27-01	SB	Conversion of Assembly PN 373364 (MF3-075-4A) to PN 391357 (MF3-075-4B)	June 22/72	--	Original	L-1011	Eaton Jackson, MS	62983 & 90166	--
391357	MF3-075-4B	373364-27-03	SB	Change in Material for Shaft Sealing Element	Nov 15/73	--	Original	L-1011	Eaton Jackson, MS	62983 & 90166	--
391357	MF4-075-4B	373364-27-04	SB	Change in Design of Shaft Seal Mating Ring	Apr 15/74	--	Original	L-1011	Eaton Jackson, MS	62983 & 90166	--
390017	CMV3-075-1C, CMV3-075-1D	390017-27-01	SB	Shaft Seal improvement	Jan 21/72	--	Original	DC-10	Eaton Jackson, MS	62983 & 90166	--
390017	CMV3-075-1C	390017-27-02	SB	Conversion of Assy PN 390017 (CMV3-075-1C) to Assy PN 418575 (CMV3-075-1D) to Provide new mounting screws, washers, and sealing screws	Dec 02/74	--	Original	DC-10	Eaton Jackson, MS	62983 & 90166	--
418575	CMV3-075-1D	390017-29-03	SB	Replacement of Piston-Shoe Hold Down Retainer Plate Screws	Jan 25/84	--	Original	DC-10	Eaton Jackson, MS	62983 & 90166	--
418575	CMV3-075-1D	390017-29-04	SB	Replacement of Piston-Shoe Hold Down Retainer Plate Screws	Oct 07/87	--	1	DC-10	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
418575	CMV3-075-1D	390017-29-05	SB	Housing and Insert Subassembly and Thrust Bearing Change	July 20/95	--	2	DC-10/MD-11	Eaton Jackson, MS	62983 & 90166	--
391357	MF3-075-4B	391357-27-02	SB	Mounting Flange, Pins, and Bearing Subassembly	July 27/73	--	1	L-1011	Eaton Jackson, MS	62983 & 90166	--
405893	MPEV3-032-1D/-1E/-1F/-1G/-1H	405893-29-19	SB	Hydraulic Motorpump - Drive Shaft Roller Bearing Race Repair	Sep 15/94	--	Original	A300, MD-80, DC-10	Eaton Jackson, MS	62983 & 90166	--
518735	A-0643-089-F	518735-29-01	SB	Increased Spotface and add modification plate	Feb 15/91	--	Original	Boeing 767	Eaton Jackson, MS	62983 & 90166	--
569668	MF1-019-1	569668-27-01	SB	Conversion of Hydraulic Motor Assembly 569668 (MF1-019-1) to 622634 (MF1-019-3)	Dec 11/84	--	Original	Boeing 757	Eaton Jackson, MS	62983 & 90166	--
622634	MF1-019-3	569668-27-02	SB	Introduction of New Model MF1-019-3A (PN 887087)	Aug 26/91	--	Original	Boeing 757	Eaton Jackson, MS	62983 & 90166	--
569672	MF1-152-9	569672-27-01	SB	Introduction of New Model MF1-152-13 (PN 973600)	Oct 15/99	--	Rev. 1	Boeing 737/757	Eaton Jackson, MS	62983 & 90166	--
569672	MF1-152-9	569672-27-02	SB	Conversion of New Model MF1-152-13 (PN 973600) to Model MF1-152-9 (PN 569672)	Oct 15/99	--	Rev. 1	Boeing 737/757	Eaton Jackson, MS	62983 & 90166	--
570347	PV3-032-3	570347-29-01	SB	Rework of Housing to Eliminate Yoke Control Spring Interference	Jan 12/84	--	Original	DeHavillan DHC-8	Eaton Jackson, MS	62983 & 90166	--
570347	PV3-032-3	570347-29-02	SB	Addition of Teflon Retainer to Pilot Valve Bushin	Aug 01/92	--	Rev. 2	DeHavillan DHC-8	Eaton Jackson, MS	62983 & 90166	--
570347	PV3-032-3	570347-29-03	SB	Replacement of Spring Guides	Sept 15/92	--	Original	DeHavillan DHC-8	Eaton Jackson, MS	62983 & 90166	--
570347	PV3-032-3	570347-29-04	SB	Replacement of Aluminum Fittings with Steel Fittings	Sept 20/92	--	Original	DeHavillan DHC-8	Eaton Jackson, MS	62983 & 90166	--
570500, 571641	PPEV3-011-12A, PPEV3-011-13	570500-29-01	SB	Locating Pin Change	June 15/85	--	Original	Beech 1900, King Air 200/300	Eaton Jackson, MS	62983 & 90166	--
624494, 624499	PPEV3-011-12B, PPEV3-011-13A	570500-29-02	SB	Addition of Pump Inlet Port Filter Screen	July 05/85	--	Original	Beech 1900, King Air 200/300	Eaton Jackson, MS	62983 & 90166	--
570500, 624494, 571641	PPEV3-011-12A, PPEV3-011-12B, PPEV3-011-13, PPEV3-011-13A	570500-29-03	SB	Model Change - New Pressure Switch	Sept 09/91	--	Rev. 1	Beech 1900, King Air 200/300	Eaton Jackson, MS	62983 & 90166	--
570527	PV3-044-38A	570527-29-01	SB	Conversion of 570527 (PV3-044-38A) pumps to 731515 (PV3-044-38B) pumps.	Apr 30/86	--	Original	Vickers 570527, Canadair 601-75100-3	Eaton Jackson, MS	62983 & 90166	--
570527, 731515	PV3-044-38A, PV3-044-38B	570527-29-02	SB	Product Improvement to Incorporate Face Seal	Apr 30/96	--	Rev. 1	CL-601	Eaton Jackson, MS	62983 & 90166	--
570721, 624043, 624345	MPEV3-011-25, MPEV3-011-25A, MPEV3-011-25B	570721-29-06	SB	Conversion of MPEV3-011-25/-25A/-25B to MPVE3-011-25C (731840)	June 15/87	--	Original	DHC-8	Eaton Jackson, MS	62983 & 90166	--
622199	MPEV3-056-6D	622199-29-01	SB	Conversion of Model MPEV3-056-6D (622199) to MPEV3-056-6F (623303)	Dec 01/83	--	Original	Boeing 757/767	Eaton Jackson, MS	62983 & 90166	--
623303	MPEV3-056-6F	622199-29-02	SB	Gerotor Retaining Plate and Closure Change	Jan 20/85	--	Rev. 1	Boeing 757/767	Eaton Jackson, MS	62983 & 90166	--
623303	MPEV3-056-6F	622199-29-03	SB	Constant Horsepower Compensator Sleeve and spool Subassembly Change	Feb 14/85	--	Original	Boeing 757/767	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
623303	MPEV3-056-6F	622199-29-04	SB	Wave Spring Change in Shaft Subassembly	Apr 01/86	--	Original	Boeing 757/767	Eaton Jackson, MS	62983 & 90166	--
623303	MPEV3-056-6F	622199-29-05	SB	Alternate Bearing Change	Aug 10/87	--	Original	Boeing 757/767	Eaton Jackson, MS	62983 & 90166	--
731966	MPEV3-056-6H	622199-29-06	SB	Model Change	Sept 10/87	--	Original	Boeing 747/757/767	Eaton Jackson, MS	62983 & 90166	--
623303, 731966	MPEV3-056-6F, MPEV3-056-6H	622199-29-07	SB	Inspection to Insure Proper Assembly of Tube and Plug Subassembly	May 30/91	--	Original	Boeing 747-400/757/767	Eaton Jackson, MS	62983 & 90166	--
623303	MPEV3-056-6F	622199-29-08	SB	Modification of Model MPEV3-056-6F (623303) with shock mounts to MPEV3-056-6H (731966) without shock mounts	May 01/92	--	Original	Boeing 767	Eaton Jackson, MS	62983 & 90166	--
622199, 623247, 623303, 731966	MPEV3-056-6D, MPEV3-056-6E, MPEV3-056-6F, MPEV3-056-6H	622199-29-09	SB	Repair Procedure for Housing, P/N 622154	Feb 01/96	--	Rev. 1	Boeing 747-400/757/767/777	Eaton Jackson, MS	62983 & 90166	--
622199, 623247, 623303, 731966	MPEV3-056-6D, MPEV3-056-6E, MPEV3-056-6F, MPEV3-056-6H	622199-29-10	SB	Yoke Subassembly Product Improvement	June 01/99	--	Original	Boeing 747-400/757/767/777	Eaton Jackson, MS	62983 & 90166	--
622199, 623303, 731966	MPEV3-056-6D, MPEV3-056-6F, MPEV3-056-6H	622199-29-11	SB	Introduction of Service Part - tungsten Carbide Element	Jan 12/04	--	Original	Boeing 747-400, 747-400D, 747-400F, 757, 767, 777	Eaton Jackson, MS	62983 & 90166	--
623303, 731966	MPEV3-056-6D, MPEV3-056-6F, MPEV3-056-6H	622199-29-12	SB	Introduction of Service Part -- Ceramic Bearing (In-Process)	--	--	Original	Boeing 747-400, 757, 767, 777	Eaton Jackson, MS	62983 & 90166	--
622199	MPEV3-056-6D	622199-29-13	SB	Introduction of New Retainer Hold Down Plate Screw (In-Process)	--	--	Rev. 1	Boeing 747/757/767	Eaton Jackson, MS	62983 & 90166	--
622362	MPHF3-160-8C	622362-29-01	SB	Conversion of 622362 (MPHF3-160-8C) to 622532 (MPHF3-160-8D) Power Transfer Motorpump Assembly	May 15/84	--	Original	Boeing 757	Eaton Jackson, MS	62983 & 90166	--
623303	MPEV3-056-6F	623303-29-01	SB	Introduction of New Retainer Hold Down Plate Screw (In-Process)	--	--	Rev. 1	Boeing 747/757/767	Eaton Jackson, MS	62983 & 90166	--
623977	PV3-240-10	623977-29-01	SB	Reworked Seepage Drain Port	Nov 01/98	--	Original	Boeing 747, Airbus A320	Eaton Jackson, MS	62983 & 90166	--
623977	PV3-240-10	623977-29-02	SB	Rework of Bolt Ear	Dec 09/88	--	Original	Boeing 747, Airbus A320	Eaton Jackson, MS	62983 & 90166	--
623977	PV3-240-10	623977-29-03	SB	Introduction of Model PV3-240-10A (Part No. 887111)	Apr 30/91	--	Original	Boeing 747/767	Eaton Jackson, MS	62983 & 90166	--
623977	PV3-240-10	623977-29-06	SB	Introduction of Model PV3-240-10C (PN 887673)	May 07/93	--	Rev. 1	Boeing 747/757/767, Douglas MD-11, Airbus A320/A321	Eaton Jackson, MS	62983 & 90166	--
623977	PV3-240-10	623977-29-07	SB	Incorporation of Polymide Coupling Shaft	Sept 08/92	--	Original	Boeing 747/767, Douglas MD-11, Airbus A320	Eaton Jackson, MS	62983 & 90166	--
623977, 887111, 887673	PV3-240-10, PV3-240-10A, PV3-240-10C	623977-29-08	SB	Carbon Shaft Seal Product Improvement	June 01/00	--	Rev. 4	Boeing 747/757/767, Douglas DC-10, MD-11, Airbus A320	Eaton Jackson, MS	62983 & 90166	--
623977, 887111, 887673	PV3-240-10, PV3-240-10A, PV3-240-10C	623977-29-09	SB	Plug Change	Apr 30/96	--	Original	Boeing 747/757/767, Douglas DC-10, MD-11, Airbus A300/A310/A320	Eaton Jackson, MS	62983 & 90166	--
887111, 887673	PV3-240-10A, PV3-240-10C	623977-29-11	SB	Repair of Adapter Block Sealing Face (In-Process)	--	--	Rev. 3	Boeing 747/757/767, Douglas DC-10, MD-11, Airbus A300/A310/A319/A320/A321	Eaton Jackson, MS	62983 & 90166	--
887111, 887673	PV3-240-10A, PV3-240-10C	623977-29-12	SB	Blocking Valve Carbon Filled Teflon Backup Rings	June 15/98	--	Rev. 1	Boeing 747/747-400/757/767, Douglas DC-10, MD-11, Airbus A300/A310/A319/A320/A320	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
623977, 887111, 887673	PV3-240-10, PV3-240-10A, PV3-240-10C	623977-29-13	SB	Product Improvement to Solenoid Valve	July 01/98	--	Original	Boeing 747/747-400/757/767, Douglas DC-10, MD-11, Airbus A300/A310/A319/A320/A320	Eaton Jackson, MS	62983 & 90166	--
623977	PV3-240-10	623977-29-14	SB	Introduction of New Retainer Hold Down Plate Screw	June 25/04	--	Original	Boeing 747/757/767, Douglas DC-10, MD-11, Airbus A300/A310/A319/A320/A320	Eaton Jackson, MS	62983 & 90166	--
624206	MPEV3-056-7	624206-29-01	SB	Properly install sleeve into housing Subassembly, Modify Control Piston, Install Modification Plate and the Introduction of New Model MPEV3	Oct 30/96	--	Rev. 2	Boeing 727/737	Eaton Jackson, MS	62983 & 90166	--
693335	MPEV3-032-10B	693335-29-01	SB	Addition of Screen, PN 518362, and Spring Curved Washer, PN 570782	Mar 23/90	--	Rev. 1	Airbus A320	Eaton Jackson, MS	62983 & 90166	--
693335	MPEV3-032-10B	693335-29-02	SB	Repair Procedure For Thermal Switches	Apr 15/95	--	Rev. 1	Airbus A320	Eaton Jackson, MS	62983 & 90166	--
693335	MPEV3-032-10B	693335-29-03	SB	Valve Plate Piston Bore Improvement	Sept 01/93	--	Rev. 1	Airbus A320	Eaton Jackson, MS	62983 & 90166	--
693335	MPEV3-032-10B	693335-29-04	SB	Identify Product Improvement and Rotor Shaft Repair Procedure	June 01/99	--	Rev. 1	Airbus A320	Eaton Jackson, MS	62983 & 90166	--
693335	MPEV3-032-10B	693335-29-05	SB	Incorporate Requirement for Inspection of Motor Flame Arrestor	Jan 30/98	--	Rev 1	Airbus A320	Eaton Jackson, MS	62983 & 90166	--
693335	MPEV3-032-10B	693335-29-06 (This SB)	SB	Introduction of a New Inlet Transfer Tube	Oct 15/98	--	Original	Airbus A320	Eaton Jackson, MS	62983 & 90166	--
693335	MPEV3-032-10B	693335-29-07	SB	Incorporation of Additional Breather Plug	June 01/99	--	Original	Airbus A319/A320/A321/A330/A340	Eaton Jackson, MS	62983 & 90166	--
693335	MPEV3-032-10B	693335-29-08	SB	Free of Charge (FOC) Retrofit of Electric Motorpump Rotors	May 15/04	--	Rev. 3	Airbus A319/A320/A321/A330/A340	Eaton Jackson, MS	62983 & 90166	--
693335	MPEV3-032-10B	693335-29-09	SB	Rework of Rotor Shaft	Jan 30/99	--	Original	Airbus A319/A320/A321/A330/A340	Eaton Jackson, MS	62983 & 90166	--
693335	MPEV3-032-10B	693335-29-10	SB	Removal of Lockwire	Dec 15/98	--	Draft	Airbus A319/A320/A321/A330/A340	Eaton Jackson, MS	62983 & 90166	--
693335	MPEV3-032-10B	693335-29-11	SB	Free of Charge (FOC) Retrofit replacement of One Piece Transfer Tube with previous configuration	Jan 04/00	--	Original	Airbus A319/A320/A321/A330/A340	Eaton Jackson, MS	62983 & 90166	--
693335	MPEV3-032-10B	693335-29-12	SB	Introduction of New Model - MPEV3-032-17 (In-Process)	--	--	Original	Airbus A320	Eaton Jackson, MS	62983 & 90166	--
693335, 3029683-001	MPEV3-032-10B, MPEV3-032-17	693335-29-13	SB	Introduction of New Model - MPEV3-032-17	Aug 15/07	--	Original	Airbus A320/A340-500/-600	Eaton Jackson, MS	62983 & 90166	--
731428	MPEV3-056-9	731428-29-01	SB	Properly install sleeve into housing Subassembly, Modify Control Piston, Install Modification Plate and the	Oct 30/96	--	Rev. 2	Boeing 727/737	Eaton Jackson, MS	62983 & 90166	--
731430	MPEV3-056-10	731430-29-01	SB	Properly install sleeve into housing Subassembly, Modify Control Piston, Install Modification Plate and the Introduction of New Model MPEV3	Oct 30/96	--	Rev. 2	Boeing 727/737	Eaton Jackson, MS	62983 & 90166	--
731840	MPEV3-011-25C	731840-29-01	SB	Introduction of New Model MPEV3-011-25D	May 15/97	--	Original	DHC-8-100/-200/-300	Eaton Jackson, MS	62983 & 90166	--
731966	MPEV3-056-6H	731966-29-01	SB	Introduction of New Retainer Hold Down Plate Screw (In-Process)	--	--	Original	Boeing 747/757/767/777	Eaton Jackson, MS	62983 & 90166	--
848028	PV3-300-19	848028-29-01	SB	Service Flow Limits	Mar 31/00	--	Original	Tupolev TU 204	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
848137	MPEV3-040-2B	848137-29-01	SB	Introduction of New Model MPEV3-040-2C	April 30/94	--	Original	Airbus A330/A340	Eaton Jackson, MS	62983 & 90166	--
849377	MPEV3-040-2C	848137-29-02	SB	Product Improvement	Jan 15/97	--	Original	Airbus A330/A340	Eaton Jackson, MS	62983 & 90166	--
848354	PV3-300-13C	848354-29-01	SB	Introduction of New Model PV3-300-13E	Aug 01/95	--	Original	Airbus A330/A340	Eaton Jackson, MS	62983 & 90166	--
848354	PV3-300-13C	848354-29-02	SB	Introduction of New Model PV3-300-13F	Sept 01/95	--	Original	Airbus A330/A340	Eaton Jackson, MS	62983 & 90166	--
848354, 971844, 972630	PV3-300-13C, PV3-300-13E, PV3-300-13F	848354-29-04	SB	Repair of Yoke Subassembly	Oct 30/98	--	Original	Airbus A330/A340	Eaton Jackson, MS	62983 & 90166	--
848354, 971844, 972630	PV3-300-13C, PV3-300-13E, PV3-300-13F	848354-29-05	SB	Replace Aluminum Screw Thread Reducer Bushing	June 01/97	--	Original	Airbus A330/A340	Eaton Jackson, MS	62983 & 90166	--
848354, 972630	PV3-300-13E, PV3-300-13F	848354-29-06	SB	Introduction of New Model PV3-300-13H	Oct 30/98	--	Rev. 1	Airbus A330/A340	Eaton Jackson, MS	62983 & 90166	--
848354, 971844, 972630, 974947	PV3-300-13C, PV3-300-13E, PV3-300-13F, PV3-300-13H	848354-29-07	SB	Introduction of New Model PV3-300-12K	Jan 08/00	--	Rev. 2	Airbus A330	Eaton Jackson, MS	62983 & 90166	--
974976	PV3-300-13K	848354-29-08	SB	Introduction of New Model PV3-300-13L	Jan 08/00	--	Original	Airbus A330/A340	Eaton Jackson, MS	62983 & 90166	--
848354, 971844, 672630, 974947, 974976, 974800	PV3-300-13C, PV3-300-13E, PV3-300-13F, PV3-300-13H, PV3-300-13K, PV3-300-13L	848354-29-09	SB	Service Flow Limits	June 01/00	--	Rev. 1	Airbus A330/A340	Eaton Jackson, MS	62983 & 90166	--
971844, 848354, 974947, 974976	PV3-300-13E, PV3-300-13F, PV3-300-13H, PV3-300-13K	848354-29-10	SB	Removal of the Filter Screen	June 01/00	--	Original	Airbus A330/A340	Eaton Jackson, MS	62983 & 90166	--
974800	PV3-300-13L	848354-29-11	SB	Reduce Parting Line Leakage	June 01/00	--	Original	Airbus A330	Eaton Jackson, MS	62983 & 90166	--
972630, 974976, 974800	--	848354-29-12	SB	Lapping of Blocking Valve Seat	June 01/00	--	Rev. 1	Airbus A330/A340	Eaton Jackson, MS	62983 & 90166	--
974976	PV3-300-13K	848354-29-13	SB	Replacement of Blocking Valve Seat, Blocking Valve Seat Seal, Blocking Valve Piston, Blocking Valve Piston Seal and Blocking Valve Springs	June 01/00	--	Original	Airbus A330/A340	Eaton Jackson, MS	62983 & 90166	--
974800	PV3-300-13L	848354-29-14	SB	Blocking Valve Improvement	June 01/00	--	Original	Airbus A330	Eaton Jackson, MS	62983 & 90166	--
848354, 971844, 972630, 974947, 974976, 974800	PV3-300-13C, PV3-300-13E, PV3-300-13F, PV3-300-13H, PV3-300-13K, PV3-300-13L	848354-29-15	SB	Carbon Shaft Seal Improvement	June 01/00	--	Original	Airbus A330	Eaton Jackson, MS	62983 & 90166	--
972630	PV3-300-13F	848354-29-16	SB	Replacement of Blocking Valve Seat, Blocking Valve Seat Seal, Blocking Valve Piston, Blocking Valve Piston Seal and Blocking Valve Springs	June 01/00	--	Original	Airbus A340	Eaton Jackson, MS	62983 & 90166	--
848354, 971844, 972630, 974947, 974976	PV3-300-13C, PV3-300-13E, PV3-300-13F, PV3-300-13H, PV3-300-13K	848354-29-17	SB	Adapter Block Repair	June 01/00	--	Original	Airbus A330/A340	Eaton Jackson, MS	62983 & 90166	--
972630, 974800	PV3-300-13K, PV3-300-13L	848354-29-18	SB	Product Improvement - Removal of Orifice Set Screw in Valve Blocks	May 26/00	--	Original	Airbus A330	Eaton Jackson, MS	62983 & 90166	--
--	--	848354-29-19	SB	--	--	--	--	Airbus A330/A340	Eaton Jackson, MS	62983 & 90166	--
848846	PV3-019-1A	848846-29-01	SB	Product Improvement to Incorporate New Coupling shaft	Nov 15/95	--	Original	Falcon 2000	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
848846	PV3-019-1A	848846-29-02	SB	Product Improvement to Incorporate New Shim and Reduce Torque on the Impeller Cover and Inlet Fitting	June 01/97	--	Original	Falcon 2000	Eaton Jackson, MS	62983 & 90166	--
848846	PV3-019-1A	848846-29-03	SB	Product Improvement to Incorporate Alignment Pin	May 15/99	--	Rev. 1	Falcon 2000	Eaton Jackson, MS	62983 & 90166	--
848846	PV3-019-1A	848846-29-04	SB	Introduction of New Model PV3-019-1B	Oct 15/05	--	Original	Falcon 2000 & F2000EX	Eaton Jackson, MS	62983 & 90166	--
848847	MPEV3-012-2B	848847-29-01	SB	Disconnecting Varistor from Electric Motor	May 15/00	--	Original	Canadair RJ, CL 600/601/604	Eaton Jackson, MS	62983 & 90166	--
887182	PF4-038-11C	848882-73-01	SB	Introduction of Model PF4-038-11D	May 01/01	--	Original	PW305A, PW305B	Eaton Jackson, MS	62983 & 90166	--
849363	PV3-300-16B	849363-29-03	SB	Introduction of New Model PV3-300-16C	Aug 01/95	--	Original	Boeing 777	Eaton Jackson, MS	62983 & 90166	--
849589	PV3-240-18	849589-29-01	SB	New Pump Housing	Nov 01/00	--	Original	Boeing 737-600/700/800	Eaton Jackson, MS	62983 & 90166	--
849589	PV3-240-18	849589-29-02	SB	New Actuator Piston	Aug 15/03	--	Rev. 1	Boeing 737-600/700/800/900	Eaton Jackson, MS	62983 & 90166	--
849589	PV3-240-18	849589-29-03	SB	Spring Guide with Wear Seat	Nov 30/02	--	Original	Boeing 737-600/700/800/900	Eaton Jackson, MS	62983 & 90166	--
849589	PV3-240-18	849589-29-04	SB	Repair of Yoke Subassembly	May 30/06	--	Original	Boeing 737-600/700/800/900	Eaton Jackson, MS	62983 & 90166	--
849589	PV3-240-18	849589-29-05	SB	Introduction of New Retainer Hold Down Plate Screw	Mar 01/04	--	Original	Boeing 737-600/700/800/90	Eaton Jackson, MS	62983 & 90166	--
849589	PV3-240-18	849589-29-06	SB	Introduction of New Impeller Screw	Oct 15/09	--	Original	Boeing 737-600/700/800/900	Eaton Jackson, MS	62983 & 90166	--
861555	MPEV3-032-1A	861555-29-01	SB	Valve Plate Piston Bore Improvement	Aug 09/94	--	Original	Douglas DC-10/MD-80, Airbus A300/A310	Eaton Jackson, MS	62983 & 90166	--
861555	MPEV3-032-1G	861555-29-02	SB	Drive Shaft Roller Bearing Race Repair	Sept 15/94	--	Original	Douglas MD-80, MD-11 and DC-10, Airbus A300/A310	Eaton Jackson, MS	62983 & 90166	--
861555	MPEV3-032-1G	861555-29-05	SB	Service Part - Valve Plate/Housing Packing	Nov 15/01	--	Original	Boeing DC-10/MD-80/B717, Airbus A300/A310	Eaton Jackson, MS	62983 & 90166	--
861555	MPEV3-032-1G	861555-29-A04	SB	Inspection/Health Check of the AC Electric Motor	Dec 01/98	--	Original	Boeing MD-80, MD-90, MD-11, and DC-10, Airbus A300/A310	Eaton Jackson, MS	62983 & 90166	--
861686	MPEV3-032-1H	861686-29-01	SB	Introduction of Model MPEV3-032-1G	May 15/93	--	Original	Airbus A300/A310	Eaton Jackson, MS	62983 & 90166	--
861686, 520831	MPEV3-032-1H & MPEV3-032-EA1	861686-29-02	SB	Drive Plate Piston Bore Improvement	Aug 01/98	--	Original	Airbus A300/A310, BAe/AVRO 146/RJ	Eaton Jackson, MS	62983 & 90166	--
861686, 520831	MPEV3-032-1H & MPEV3-032-EA1	861686-29-03	SB	Drive Shaft Roller Bearing Race Repair	Aug 01/98	--	Rev. 2	Airbus A300/A310, BAe 146/RJ	Eaton Jackson, MS	62983 & 90166	--
861686, 520831	MPEV3-032-1H & MPEV3-032-EA1	861686-29-04	SB	Introduction of a New Inlet Transfer Tube	Nov 01/98	--	Original	Airbus A300/A310, BAe 146/RJ	Eaton Jackson, MS	62983 & 90166	--
862536	PV3-115-EA5	862536-29-01	SB	Incorporation of Steel Actuator Piston Sleeve	Sept 31/92	--	Original	Fokker 100	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
862536	PV3-115-EA5	862536-29-02	SB	Modification of Mounting Flange	Mar 01/93	--	Original	Fokker 100	Eaton Jackson, MS	62983 & 90166	--
887055	PV3-044-48	887055-29-01	SB	Product Improvement to Incorporate Longer Valve Plate Bolts and Inserts	Oct 15/97	--	Rev. 1	Canadair RJ, Challenger CL-601-3R, Challenger CL-604	Eaton Jackson, MS	62983 & 90166	--
887055	PV3-044-48	887055-29-02	SB	Drive Shaft roller Bearing Race Repair	Jan 15/99	--	Original	Canadair RJ, Challenger CL-604, Challenger CL-601/-3R	Eaton Jackson, MS	62983 & 90166	--
887055	PV3-044-48	887055-29-03	SB	Coupling shaft Packing Change	Jan 15/99	--	Original	Canadair RJ, Challenger CL-604, Challenger CL-601/-3R	Eaton Jackson, MS	62983 & 90166	--
887055	PV3-044-48	887055-29-04	SB	Sealing Screw Packing Change	Aug 30/99	--	Rev. 1	Canadair RJ, Challenger CL-604	Eaton Jackson, MS	62983 & 90166	--
887055	PV3-044-48	887055-29-05	SB	Repair of Yoke Subassembly	Jan 27/05	--	Rev. 1	Canadair RJ, Challenger CL-604, Challenger CL-601/-3R	Eaton Jackson, MS	62983 & 90166	--
887055	PV3-044-48	887055-29-06	SB	System Overpressure/Overheating Conditions	May 20/04	--	Original	Canadair RJ, CL-600-2B19, Challenger CL-604, CL-600-2B16 (604 variant), Challenger CL-601/-3R, CL-600-2B16 (601-3R variant)	Eaton Jackson, MS	62983 & 90166	--
887055	PV3-044-48	887055-29-07	SB	Product Improvement - Removal of Sealing Screws	July 15/06	--	Original	CRJ 100/200, CL 601/604	Eaton Jackson, MS	62983 & 90166	--
887055	PV3-044-48	887055-29-08	SB	Product Improvement - Spring Guide and Wear Plug S.A. (In-Process)	--	--	Original	CRJ 100/200	Eaton Jackson, MS	62983 & 90166	--
887111	PV3-240-10A	887111-29-01	SB	Replacement of Actuator Piston and Sleeve, and Blocking Valve Spring	Apr 16/91	--	Original	Boeing 747/767	Eaton Jackson, MS	62983 & 90166	--
887111	PV3-240-10A	887111-29-02	SB	Introduction of Model PV3-240-10C (PN 887673)(60B00200-12)	Nov 01/91	--	Original	Boeing 747/767	Eaton Jackson, MS	62983 & 90166	--
887111	PV3-240-10A	887111-29-03	SB	Incorporation of Polyimide Coupling Shaft	July 01/04	--	Rev. 1	Boeing 747/767	Eaton Jackson, MS	62983 & 90166	--
887111	PV3-240-10A	887111-29-03	SB	Incorporation of Polyimide Coupling Shaft	Sept 08/92	--	Original	Boeing 747/767	Eaton Jackson, MS	62983 & 90166	--
887111	PV3-240-10A	887111-29-04	SB	Introduction of New Retainer Hold Down Plate Screw	June 24/04	--	Original	Boeing 747/757/767, DC-10, and MD-11	Eaton Jackson, MS	62983 & 90166	--
887111	PV3-240-10A	887111-29-05	SB	Incorporation of Adapter Block/Housing Parting Line Seal Improvement (In-Process)	May 10/10	--	Rev. 2	Boeing 747/767	Eaton Jackson, MS	62983 & 90166	--
887111	PV3-240-10A	887111-29-14	SB	Variable Displacement Hydraulic Pump - Yoke Screws	Jun 25/04	--	Original	747, 757, 767	Eaton Jackson, MS	62983 & 90166	--
887477	MPEV3-056-7A	887477-29-01	SB	Actuator Piston Wear	Oct 01/95	--	Original	Boeing 727/737	Eaton Jackson, MS	62983 & 90166	--
887477	MPEV3-056-7A	887477-29-02	SB	Corrected Part Number	Sept 18/01	--	Rev. 1	Boeing 727/737	Eaton Jackson, MS	62983 & 90166	--
887477	MPEV3-056-7A	887477-29-03	SB	Electric Motor Assembly Improvement	June 01/00	--	Original	Boeing 727/737	Eaton Jackson, MS	62983 & 90166	--
887477	MPEV3-056-7A	887477-29-04	SB	Introduction of New Retainer Hold Down Plate Screw	Apr 23/04	--	Original	Boeing 727/737	Eaton Jackson, MS	62983 & 90166	--
887477	MPEV3-056-7A	887477-29-05	SB	Reliability Improvement	Dec 30/05	--	Original	Boeing 727/737	Eaton Jackson, MS	62983 & 90166	--

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
887479	MPEV3-056-9A	887479-29-04	SB	AC Driven Motorpump Assembly - New yoke screws.	Jun 24/04	--	Original	727, 737	Eaton Jackson, MS	62983 & 90166	--
887480	MPEV3-056-10A	887480-29-01	SB	Actuator Piston Wear	Oct 01/95	--	Original	Boeing 727/737	Eaton Jackson, MS	62983 & 90166	--
887480	MPEV3-056-10A	887480-29-02	SB	Corrected Part Number	Sept 18/01	--	Rev. 1	Boeing 727/737	Eaton Jackson, MS	62983 & 90166	--
887480	MPEV3-056-10A	887480-29-03	SB	Electric Motor Assembly Improvement	Dec 01/01	--	Rev. 1	Boeing 727/737	Eaton Jackson, MS	62983 & 90166	--
887480	MPEV3-056-10A	887480-29-04	SB	AC Driven Motorpump Assembly - New yoke screws.	Jun 24/04	--	Original	727, 737	Eaton Jackson, MS	62983 & 90166	--
887673	PV3-240-10C	887673-29-01	SB	Incorporation of Polyimide Coupling Shaft	Sept 08/92	--	Rev. 1	Boeing 747/757/767, Douglas DC-10, MD-11, Airbus A300/A310/A320	Eaton Jackson, MS	62983 & 90166	--
887673	PV3-240-10C	887673-29-01	SB	Incorporation of Polyimide Coupling Shaft	Sept 08/92	--	Original	Boeing 747/757/767, Douglas DC-10, MD-11, Airbus A300/A310/A320	Eaton Jackson, MS	62983 & 90166	--
887673	PV3-240-10C	887673-29-02	SB	Carbon Shaft Seal Field Test	Mar 15/96	--	Rev. 1	Boeing 747/757/767, Douglas DC-10, MD-11, Airbus A320	Eaton Jackson, MS	62983 & 90166	--
887673	PV3-240-10C	887673-29-02	SB	Carbon Shaft Seal Field Test	Mar 15/96	--	Rev.	Boeing 747/757/767, Douglas DC-10, MD-11, Airbus A320	Eaton Jackson, MS	62983 & 90166	--
887111, 887673	PV3-240-10A, PV3-240-10C	887673-29-03	SB	Product Improvement to Reduce External Leakage	Apr 15/02	--	Original	Boeing 747/757/767, Douglas DC-10, MD-11, Airbus A300/A310/A319/A320/A320	Eaton Jackson, MS	62983 & 90166	--
887673	PV3-240-10C	887673-29-04	SB	Introduction of New Retainer Hold Down Plate Screw	June 25/04	--	Original	Boeing 747/757/767, Douglas DC-10, MD-11, Airbus A300/A310/A319/A320/A320	Eaton Jackson, MS	62983 & 90166	--
887673	PV3-240-10C	887673-29-05	SB	Incorporation of Adapter Block/Housing Parting Line Seal Improvement	Feb. 01/10	--	Rev. 1	Boeing 747/757/767, Douglas DC-10, MD-11, MD-10, Airbus A300/A310/A319/A320/A321, Lockheed L-1011	Eaton Jackson, MS	62983 & 90166	--
623977, 887673	PV3-240-10, PV3-240-10C	887673-29-06	SB	Introduction of new part number, PN 3031863-001 (PV3-240-10D)	Oct 11/11	--	Rev. 2	Airbus A300/A310/A318/A319/A320/A321	Eaton Jackson, MS	62983 & 90166	--
623977, 887111, 88767	PV3-240-10, PV3-240-10A, PV3-240-10C	887673-29-07	SB	Introduction of new pump part number, PN 3031863-001 (PV3-240-10D)	Nov. 11/11	--	Rev. 3	Boeing 747/757/767	Eaton Jackson, MS	62983 & 90166	--
971533	MPEV3-008-6	971533-29-01	SB	Motor Bearing Product Improvement	Sept 01/98	--	Original	Embraer 135/145	Eaton Jackson, MS	62983 & 90166	--
971533	MPEV3-008-6	971533-29-02	SB	Corrosion Reduction - Filter Box	July 12/07	--	Original	Embraer 135/145	Eaton Jackson, MS	62983 & 90166	--
971808	PV3-032-11	971808-29-01	SB	Replacement of Paper Gasket with Rubber Gasket	Mar 01/01	--	Original	Embraer 135/145	Eaton Jackson, MS	62983 & 90166	--
971808	PV3-032-11	971808-29-02	SB	Product Improvement - Modification Plate Relocation	Sept 18/01	--	Rev. 1	Embraer 135/145	Eaton Jackson, MS	62983 & 90166	--
971808	PV3-032-11	971808-29-03	SB	Product Modification - Valve Plate/Housing Packing	Jan 15/06	--	Original	Embraer 135/145	Eaton Jackson, MS	62983 & 90166	--
971808	PV3-032-11	971808-29-09	SB	Introduction of New Model - PV3-032-11A (PN 3031512-001)(In-Process)	--	--	Original	Embraer 135/145	Eaton Jackson, MS	62983 & 90166	--
971910	PV3-115-34E	971910-29-01	SB	Inspect for Leakage at the Compensator Bushing	Oct 31/97	--	Rev. 1	B-777-200	Eaton Jackson, MS	62983 & 90166	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
971910	PV3-115-34E	971910-29-02	SB	Introduction of Model PV3-115-34F	Aug 30/96	--	Original	B-777-200	Eaton Jackson, MS	62983 & 90166	--
973930	PV3-115-34F	971910-29-03	SB	Removal of Drive Shaft Spacer	May 15/99	--	Original	B-777-200	Eaton Jackson, MS	62983 & 90166	--
972424	PV3-300-16C	972424-29-01	SB	Improved Compensator Spring	Apr 15/96	--	Original	Boeing 777	Eaton Jackson, MS	62983 & 90166	--
972424	PV3-300-16C	972424-29-02	SB	Introduction of New Model PV3-300-16D	June 30/97	--	Original	Boeing 777	Eaton Jackson, MS	62983 & 90166	--
972424, 972952	PV3-300-16C, PV3-300-16D	972424-29-03	SB	Incorporation of New Valve Plate	June 30/97	--	Original	Boeing 777	Eaton Jackson, MS	62983 & 90166	--
972424, 972952	PV3-300-16C, PV3-300-16D	972424-29-04	SB	Product Improvement - Actuator Piston Sleeve Retention	Aug 01/02	--	Original	Boeing 777 & 767-400	Eaton Jackson, MS	62983 & 90166	--
972424,972952	PV3-300-16C, PV3-300-16D	972424-29-05	SB	Cylinder Block - Reliability Improvement	June 20/14	--	Original	B747-8F & B777	Eaton Jackson, MS	62983 & 90166	--
972461	MPEV3-040-10A	972461-29-01	SB	Introduction of New Model MPEV3-040-10C	Feb 15/96	--	Original	Boeing 777	Eaton Jackson, MS	62983 & 90166	--
973122	MPEV3-040-10C	973122-29-01	SB	Lockwire of Feed Thru Retainer Cap and Therman Switch	June 18/97	--	Original	Boeing 777	Eaton Jackson, MS	62983 & 90166	--
997635	MPEV3-040-10D	973122-29-03	SB	Lockwire Attachment Feature	June 15/98	--	Original	Boeing 747, 757, & 777	Eaton Jackson, MS	62983 & 90166	--
973122	MPEV3-040-10C	973122-29-A02	SB	Motorpump Recall/Modification	June 15/98	--	Rev. 3	Boeing 747, 757, & 777	Eaton Jackson, MS	62983 & 90166	--
973122, 997635	MPEV3-040-10C, MPEV3-040-10D	973122-29-A04	SB	Inspection/Repair of Gerotor/Stator	Jan 20/00	--	Rev. 1	Boeing 747, 757, & 777	Eaton Jackson, MS	62983 & 90166	--
973748	PV3-090-1	973748-29-01	SB	Incorporate New Coupling Shaft	Nov 30/07	--	Original	--	Eaton Jackson, MS	62983 & 90166	--
974014	MPHV3-115-1B	974014-29-01	SB	Introduction of New Model MPHV3-115-1C	Jan 20/00	--	Original	Airbus A318/A319/A320/A321	Eaton Jackson, MS	62983 & 90166	--
974540	MPEV3-032-15	974540-29-01	SB	Screw Change	Jan 15/02	--	Original	--	Eaton Jackson, MS	62983 & 90166	--
974540	MPEV3-032-15	974540-29-02	SB	Recall Electric Motor Tail Bearing	June 17/02	--	Original	--	Eaton Jackson, MS	62983 & 90166	--
974641	N/A	974641-29-01	SB	Replacement of High Profile Electrical Connector Screws	June 22/98	--	1	De Havilland DHC-8-100/200/300	Eaton Jackson, MS	62983 & 90166	--
974641	N/A	974641-29-02	SB	Introduce New PN Switch	Oct 31/02	--	Original	De Havilland DHC-8	Eaton Jackson, MS	62983 & 90166	--
997635	MPEV3-040-10D	997635-29-05	SB	Introduction of New Model MPEV3-040-10E (In-Process)	--	--	Original	Boeing 747, 757, & 777	Eaton Jackson, MS	62983 & 90166	--
Various	Various	62983-29-01	SIL	Vendor Service Information Letter - Shaft Seal Grommet - Material Composition	Dec 06/21	--	Original	Airbus A300/A310/A319/A320/A330/340 DC-10	Eaton Jackson, MS	62983 & 90166	--
28450	--	28-21-04	CMM	Normally Closed Solenoid Operated Fuel Shutoff Valve	--	01-Oct-03	1	Fokker 100	Eaton, LA	99643	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
35990	--	28-64-01	CMM	Dual Solenoid Operated Shutoff Valve	--	30-Nov-92	1	MD11	Eaton, LA	99643	--
36500	--	N/A	CMM	Stabilizer Control Module Solenoid Valve	--	15-May-86	1	Boeing 747	Eaton, LA	99643	--
44250	--	52-34-01	CMM	Hydraulic Pressure Relief Valve	--	01-Jul-72	0	DC10, MD11	Eaton, LA	99643	--
45080	--	45080-29-1	SB	Introduction of 45080-1	--	Jul 27/84	--	Boeing 757 and 767	Eaton, LA	99643	--
45980	--	45980-27-1	SB	Introduction of 45980-1	--	Aug 14/87	--	Airbus A300/A310	Eaton, LA	99643	--
45990	--	45990-27-1	SB	Introduction of 45990-1	--	Aug 14/87	--	Airbus A300/A310	Eaton, LA	99643	--
50790	--	25-32-30	CMM	Galley Lift Drive Damper	--	30-Nov-72	0	Lockheed L1011	Eaton, LA	99643	--
51370	--	25-54-01	CMM	Baggage Conveyor Damper	--	31-Jan-74	0	Lockheed L1011	Eaton, LA	99643	--
53200	--	32-40-01	CMM	Single Hydraulic Power Brake Valve	--	01-Jan-77	0	DeHavilland DHC-7	Eaton, LA	99643, 76050, 09790 & 52906	--
58570	--	32-44-11	CMM	Single Hydraulic Power Brake Valve	--	01-Jun-78	1	DeHavilland DHC-7	Eaton, LA	99643, 76050, 09790 & 52906	--
62380	--	32-30-56	CMM	Nose Gear Bay Door Sequence Valve	--	15-Jun-78	0	DeHavilland DHC-7	Eaton, LA	99643, 76050, 09790 & 52906	--
62530	--	21-71-03	CMM	Free Reverse Flow Solenoid Shutoff Valve	--	15-Oct-79	0	Lockheed L1011	Eaton, LA	99643, 76050, 09790 &	--
62630	--	32-30-01	CMM	Relief Rapid Response Valve	--	15-May-99	1	Boeing 747	Eaton, LA	99643, 76050, 09790 & 52906	--
65400	--	29-29-06	CMM	3 Way Normally Open Solenoid Valve	--	01-May-86	1	Boeing 767	Eaton, LA	99643, 76050, 09790 &	--
65860	--	65860-27-01	SB	Clutch Ring Replacement	--	Jul 10/94	--	Boeing 747, 757, 767	Eaton, LA	99643, 76050, 09790 &	--
65860	--	65860-27-02	SB	Introduction of 65860-1	--	Sep 1/00	--	Boeing 747, 757, 767	Eaton, LA	99643, 76050, 09790 &	--
66490	--	66490-27-01	SB	Introduction of 66490-1	--	Sep 10/85	--	DeHavilland DHC-7	Eaton, LA	99643, 76050, 09790 &	--
66950	--	29-11-01	CMM	Reservoir Pressurization Shutoff Valve	--	01-Jan-82	0	Boeing 767, 777	Eaton, LA	99643, 76050, 09790 &	--
67030	--	27-80-01	CMM	Solenoid Operated Shutoff Valve	--	15-Aug-86	1	Airbus A310	Eaton, LA	99643, 76050, 09790 &	--
68280	--	29-20-15	CMM	Hand Pump Selector Valve	--	15-Jan-85	0	Saab 340	Eaton, LA	99643, 76050, 09790 &	--
68530	--	68530-27-01	SB	Motor Assembly Replacement	--	Jul 1/96	--	Boeing 747	Eaton, LA	99643, 76050, 09790 &	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
68530	--	68530-27-02	SB	Clutch Ring Replacement	--	Jul 1/96	--	Boeing 747	Eaton, LA	99643, 76050, 09790 &	--
68640	--	68640-32-1	SB	Introduction of 68640-2	--	Jan 25/84	--	Boeing 747	Eaton, LA	99643, 76050, 09790 & 52906	--
68770	--	68770-29-1	SB	Introduction of 68770-1	--	Jan 3/84	--	Boeing 757	Eaton, LA	99643, 76050, 09790 &	--
69220	--	32-30-46	CMM	Hydraulic Mechanically Operated L.G. Bypass Valve	--	09-Oct-87	0	DeHavilland DHC-8	Eaton, LA	99643, 76050, 09790 & 52906	--
70170	--	32-32-02	CMM	Mechanically Operated Dump Valve	--	01-Jul-86	0	Fokker 50	Eaton, LA	99643, 76050, 09790 & 52906	--
70171	--	32-32-06	CMM	Mechanically Operated Directional Control Valve	--	01-Jan-87	0	Fokker 50	Eaton, LA	99643, 76050, 09790 & 52906	--
70172	--	70172 Bulletin 1	SB	Introduction of 70172-1	--	Mar 6/86	--	Fokker 50	Eaton, LA	99643, 76050, 09790 &	--
70184	--	70184 Bulletin 1	SB	Increase of Braking Pressure	--	Jan 9/86	--	Fokker 50	Eaton, LA	99643, 76050, 09790 &	--
70184	--	70184 Bulletin 2	SB	Introduction of 70184-1	--	Feb 1/88	--	Fokker 50	Eaton, LA	99643, 76050, 09790 &	--
70185	--	70185-32-07	SB	Introduction of 70185-1	--	Nov 8/89	--	Fokker 50	Eaton, LA	99643, 76050, 09790 & 52906	--
70205	--	70205-32-01	SB	Clutch Ring Replacement	--	May 1/94	--	Boeing 767	Eaton, LA	99643, 76050, 09790 & 52906	--
70205	--	70205-32-02	SB	Introduction of 70205-1	--	Dec 1/99	--	Boeing 767	Eaton, LA	99643, 76050, 09790 & 52906	--
70218	--	32-32-04	CMM	2 Position 3 Way Normally Open Valve	--	15-Jan-87	0	Fokker 50	Eaton, LA	99643, 76050, 09790 & 52906	--
70237	--	70237-32-01	SB	Introduction of 70237-1	--	Sep 15/92	--	Fokker 50	Eaton, LA	99643, 76050, 09790 & 52906	--
70267	--	32-71-03	CMM	Tailskid Blocking Valve	--	30-Sep-88	1	Boeing 767	Eaton, LA	99643, 76050, 09790 & 52906	--
70268	--	29-12-02	CMM	Pneumatic Pressure Regulator, Pressure and Vacuum Relief	--	30-May-00	2	Fokker 50	Eaton, LA	99643, 76050, 09790 &	--
70269	--	Service Letter MRC-040	SB	Check Torque	--	Apr 6/00	--	Boeing 767	Eaton, LA	99643, 76050, 09790 &	--
70371	--	32-71-01	CMM	0.9 GPM Flow Regulator	--	20-Sep-88	1	Boeing 767	Eaton, LA	99643, 76050, 09790 & 52906	--
70379	--	32-44-02	CMM	Brake Shutoff Valve	--	15-May-03	1	Fokker 100	Eaton, LA	99643, 76050, 09790 & 52906	--
70379	--	70379-32-01	SB	New Poppet Assembly	--	Sep 15/01	--	Fokker 100	Eaton, LA	99643, 76050, 09790 & 52906	--
70599	--	32-41-02	CMM	Pressure Operated Brake Source Selector Valve	--	15-Mar-94	4	Boeing 747	Eaton, LA	99643, 76050, 09790 & 52906	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
70705	--	32-30-03	CMM	Shuttle Valve	--	01-May-88	0	Fokker 100	Eaton, LA	99643, 76050, 09790 & 52906	--
70841	--	70841-29-01	SB	Introduction of 70841-3	--	Jan 1/92	--	Saab 340	Eaton, LA	99643, 76050, 09790 &	--
70902	--	70902-29-01	SB	Introduction of 70902-3	--	Sep 12/96	--	Airbus A330/A340	Eaton, LA	99643, 76050, 09790 &	--
70902	--	Service Letter MRC-099	SB	Retrofit/Upgrade to Full Life Unit 70902-3	--	Sep 12/96	--	Airbus A330/A340	Eaton, LA	99643, 76050, 09790 &	--
71128	--	21-20-00	CMM	Solenoid Operated Normally Closed Shutoff Valve	--	01-Oct-92	0	Saab 340	Eaton, LA	99643, 76050, 09790 &	--
71205	--	32-41-03	CMM	Pressure Operated Shutoff Valve	--	01-Nov-95	1	Boeing 747	Eaton, LA	99643, 76050, 09790 & 52906	--
71367	--	27-52-05	CMM	Hydraulic Flow Regulator	--	15-Jun-92	0	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
71404	--	71404-32-01	SB	Introduction of 71404-1	--	Feb 1/97	--	Boeing 747, 757, 767, 777	Eaton, LA	99643, 76050, 09790 & 52906	--
71425	--	32-53-01	CMM	EDP/ADP Pressure and Case Drain Filter Module	--	01-Nov-94	1	Boeing 777	Eaton, LA	99643, 76050, 09790 & 52906	--
71444	--	32-32-09	CMM	Main Landing Gear Priority Valve	--	01-Mar-94	0	Boeing 777	Eaton, LA	99643, 76050, 09790 & 52906	--
71461	--	71461-32-01	SB	Introduction of 71461-1	--	Jun 15/94	--	Airbus A330/A340	Eaton, LA	99643, 76050, 09790 & 52906	--
71522	--	32-44-10	CMM	Changeover Valve	--	01-Nov-95	0	Fokker 100	Eaton, LA	99643, 76050, 09790 & 52906	--
71523	--	32-52-05	CMM	Bypass Valve	--	01-Nov-95	0	Fokker 100	Eaton, LA	99643, 76050, 09790 & 52906	--
71562	--	52-33-01	CMM	3 Position 4 Way Hydraulic Valve	--	15-Apr-96	0	Airbus A300-600	Eaton, LA	99643, 76050, 09790 &	--
71756	--	27-51-06	CMM	Priority Valve-Flow Control Module	--	01-Sep-95	0	Boeing 777	Eaton, LA	99643, 76050, 09790 &	--
71784	--	32-31-02	CMM	Hydraulic System Transfer Valve Module	--	15-Feb-03	1	Boeing 737-600,-700,-800,-900	Eaton, LA	99643, 76050, 09790 & 52906	--
71934	--	29-11-13	CMM	EDP/ADP Pressure and Case Drain Filter Module	--	01-Nov-00	0	Boeing 767	Eaton, LA	99643, 76050, 09790 &	--
71970	--	29-11-20	CMM	Pressure Relief Valve	--	01-Jul-00	0	Boeing 767-400	Eaton, LA	99643, 76050, 09790 &	--
72061	--	32-31-19	CMM	Center Landing Gear Fuse	--	15-Jul-02	0	Airbus A340-500/-600	Eaton, LA	99643, 76050, 09790 & 52906	--
72470	--	29-21-19	CMM	Hydraulic Ram Air Turbine Transfer Valve	--	01-Nov-10	0	Boeing 747-8	Eaton, LA	99643, 76050, 09790 &	--
72471	--	29-21-20	CMM	Hydraulic Ram Air Turbine Isolation Valve	--	01-Nov-10	0	Boeing 747-8	Eaton, LA	99643, 76050, 09790 &	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
10300-10	--	29-13-06	CMM	Normally Closed Solenoid Operated Skydrol Valve	--	01-Oct-03	1	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
18220-3, -5 (ES)	--	29-10-01	CMM	Hydraulic Solenoid Shutoff Valve	--	30-Aug-04	4	DC8/DC9	Eaton, LA	,09790	--
22190-6, -7	--	27-81-41	CMM	Solenoid Operated Hydraulic Isolation Valve	--	15-Nov-76	1	Lockheed L1011	Eaton, LA	99643, 76050, 09790 &	--
22890-2	--	N/A	CMM	Manually Operated Hydraulic Lock Sequence	--	17-Dec-68	D	Boeing 707	Eaton, LA	99643, 76050, 09790 &	--
29600-2	--	29-11-05	CMM	Pneumatic Pressure Regulator, Pressure and Vacuum Relief	--	01-Nov-00	2	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
29600-2	--	Service Letter MRC-694	SB	New Plug	--	Jun 15/94	--	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
29600-3	--	38-40-01	CMM	Pneumatic Pressure Regulator, Pressure and Vacuum Relief	--	01-Nov-00	2	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
29600-3	--	Service Letter MRC-694	SB	New Plug	--	Jun 15/94	--	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
29680-1	--	29680-1-32-01	SB	Screw Replacement	--	Apr 15/92	--	Fokker 100	Eaton, LA	99643, 76050, 09790 & 52906	--
29680-1, -2	--	32-32-18	CMM	Pressure Reducer	--	01-Jun-94	2	Fokker 100	Eaton, LA	99643, 76050, 09790 & 52906	--
29680-2	--	29680-2-32-01	SB	Screw Replacement	--	Apr 15/92	--	Fokker 100	Eaton, LA	99643, 76050, 09790 & 52906	--
29700-550	--	27-52-03	CMM	Hydraulic Flow Regulator	--	15-May-86	0	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
29700-550	--	Service Letter SIL-29700	SB	Inspection of Spring Part Number 9905-2 and Body Part Number 21106	--	Nov 4/09	--	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
36300-2, -3	--	29-30-01	CMM	Reservoir Pressurization Module	--	15-Jun-84	2	Boeing 747	Eaton, LA	99643, 76050, 09790 &	--
36370-4, -5, -6	--	29-30-03	CMM	Module Assembly Pressure System	--	01-Jul-02	8	Boeing 747	Eaton, LA	99643, 76050, 09790 &	--
36610-3	--	32-30-01	CMM	Landing Gear Selector Valve	--	15-May-70	0	Boeing 747	Eaton, LA	99643, 76050, 09790 & 52906	--
37540-1	--	52-34-01	CMM	Solenoid Cargo Door Restraint	--	15-Dec-90	2	Boeing 747	Eaton, LA	99643, 76050, 09790 &	--
41140-3, -5	--	27-11-20	CMM	3 Way Normally Closed Solenoid Valve	--	15-Jul-85	4	Lockheed L1011	Eaton, LA	99643, 76050, 09790 &	--
41300-11, -13, -21, -25	--	32-43-04	CMM	Dual Power Brake Valve	--	15-Aug-80	4	Lockheed L1011	Eaton, LA	99643, 76050, 09790 & 52906	--
41390-1	--	32-43-03	CMM	Hydraulic Shuttle Valve	--	01-Apr-73	1	Lockheed L1011	Eaton, LA	99643, 76050, 09790 & 52906	--
41390-10	--	29-09-02	CMM	Hydraulic Shuttle Valve	--	31-Dec-86	1	Fokker 50	Eaton, LA	99643, 76050, 09790 &	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
41390-10	--	41390-10 Bulletin 1	SB	Broken O-Ring Groove	--	Mar 25/86	--	Fokker 50	Eaton, LA	99643, 76050, 09790 &	--
42350, -3	--	36-11-22	CMM	Air Relief Valve	--	01-Jan-78	4	Lockheed L1011	Eaton, LA	99643, 76050, 09790 &	--
42800-3, -5, -6, -7, -9	--	27-11-26	CMM	Control Surface Damper	--	01-Sep-89	8	Lockheed L1011	Eaton, LA	99643, 76050, 09790 &	--
42800-3,-5	--	42800-27-2	SB	Introduction of 42800-7	--	Feb 1/78	--	Lockheed L1011	Eaton, LA	99643, 76050, 09790 &	--
42800-3,-5,-7	--	42800-27-3	SB	Increase Travel Margin in Extend Direction	--	Sep 8/82	--	Lockheed L1011	Eaton, LA	99643, 76050, 09790 &	--
42800-6	--	42800-27-4	SB	Introduction of 42800-9	--	Apr 2/82	--	Lockheed L1011	Eaton, LA	99643, 76050, 09790 &	--
43830-5	--	43830-27-1	SB	Introduction of 43830-7	--	Sep 26/83	--	Lockheed L1011	Eaton, LA	99643, 76050, 09790 &	--
43830-5,-7	--	27-21-16	CMM	Actuator, Rudder Deflection Limiter	--	15-Aug-90	3	Lockheed L1011	Eaton, LA	99643, 76050, 09790 &	--
44430-1	--	32-52-01	CMM	2 Way Hydraulic Relief Valve	--	01-May-98	1	DC10, MD11	Eaton, LA	99643, 76050, 09790 & 52906	--
44520, 44540, 44560, 4	--	27-09-03	CMM	2 Position 3 Way Solenoid Pilot Operated Hydraulic Selector Valve	--	01-Mar-99	7	Airbus A300, A310	Eaton, LA	99643, 76050, 09790 &	--
45080, -1	--	29-09-05	CMM	3 Way Normally Closed Solenoid Valve	--	15-Jul-03	4	Boeing 727, 737, 747, 757, 767	Eaton, LA	99643, 76050, 09790 &	--
45980, -1	--	45980-27-02	SB	Introduction of 45980-2,-3 Screw Replacement	--	Oct 11/07	--	Airbus A300/A310	Eaton, LA	99643, 76050, 09790 &	--
45980,-1	--	27-09-02	CMM	Priority Valve	--	15-Nov-93	5	Airbus A300, A310	Eaton, LA	99643, 76050, 09790 &	--
45990, -1	--	45990-27-02	SB	Introduction of 45990-2,-3 Screw Replacement	--	Oct 11/07	--	Airbus A300/A310	Eaton, LA	99643, 76050, 09790 &	--
45990,-1	--	27-09-02	CMM	Priority Valve	--	15-Nov-93	5	Airbus A300, A310	Eaton, LA	99643, 76050, 09790 &	--
48300-9, -11	--	29-11-75	CMM	Differential Pressure Sensing Hydraulic Check Valve	--	15-May-80	5	Lockheed L1011	Eaton, LA	99643, 76050, 09790 &	--
5160-2 (ES)	--	21-62-05	CMM	Ram Ventilating Air Valve	--	15-Dec-71	0	Boeing 747	Eaton, LA	,09790	--
5160-3 (ES)	--	21-62-06	CMM	Ram Ventilating Air Valve	--	01-Jun-75	0	Boeing 747	Eaton, LA	,09790	--
5160-4	--	21-48-01	CMM	Ram Ventilating Air Valve	--	08-Dec-10	0	Boeing 747-8	Eaton, LA	99643, 76050, 09790 &	--
52890-5, -7	--	29-21-18	CMM	Manifold Check Valve	--	15-Jun-81	1	Lockheed L1011	Eaton, LA	99643, 76050, 09790 &	--
53820-1, -2, -3, -5	--	32-40-01	CMM	Pneumatic Brake Valve Assembly	--	15-May-78	1	Boeing 727	Eaton, LA	99643, 76050, 09790 & 52906	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
55540-2,-5,-6	--	32-30-04	CMM	Solenoid Operated Valve	--	15-Mar-93	2	Canadair CRJ	Eaton, LA	99643, 76050, 09790 & 52906	--
57420,-1,-3,-5	--	32-30-10	CMM	Solenoid Operated Landing Gear Valve	--	15-Mar-00	0	DeHavilland DHC-7 and DHC-8	Eaton, LA	99643, 76050, 09790 & 52906	--
57420,-1,-3,-5	--	57420-32-01	SB	End Cap Replacement	--	Mar 1/99	--	DeHavilland DHC-7 and DHC-8	Eaton, LA	99643, 76050, 09790 & 52906	--
58120, -1, -2	--	78-32-01	CMM	Door Unlock Thrust Reverser Actuator	--	01-Oct-98	7	DC9-80, MD80. Boeing 727-200, 737	Eaton, LA	99643, 76050, 09790 & 52906	--
61750,-1	--	32-30-02	CMM	Solenoid Operated Landing Gear Valve	--	01-Feb-99	2	Canadair CRJ	Eaton, LA	99643, 76050, 09790 & 52906	--
62130-2, -7	--	27-60-02	CMM	On/Off Spoiler Manifold	--	11-Apr-17	3	Canadair CL600	Eaton, LA	99643, 76050, 09790 &	--
62490-7B	--	36-10-21	CMM	Bleed Air Check Valve	--	01-Jan-05	2	Canadair CRJ	Eaton, LA	99643, 76050, 09790 &	--
62630-1, -4	--	32-32-01	CMM	Relief Rapid Response Valve	--	15-May-99	2	Boeing 757, 767	Eaton, LA	99643, 76050, 09790 & 52906	--
63240, -1	--	78-30-01	CMM	Thrust Reverser Actuator	--	15-May-99	4	MD80, Boeing 727-200	Eaton, LA	99643, 76050, 09790 &	--
63940, 63950	--	27-09-04	CMM	2 Position 3 Way Solenoid Pilot Operated Hydraulic Selector Valve	--	22-Aug-84	1	Airbus A300	Eaton, LA	99643, 76050, 09790 &	--
64710-3, -4	--	27-09-01	CMM	Elevator Damper	--	30-Sep-86	4	Canadair CL600	Eaton, LA	99643, 76050, 09790 &	--
6510,-3 (ES)	--	29-18-02	CMM	Reservoir Fill Selector Valve	--	01-Oct-96	1	Boeing 747	Eaton, LA	,09790	--
65480-1, -2	--	27-09-01	CMM	Aileron Flutter Damper	--	30-Sep-86	4	Canadair CL600	Eaton, LA	99643, 76050, 09790 &	--
65860, -1	--	27-41-01	CMM	2 Position 3 Way Motor Operated Valve	--	01-Mar-04	3	Boeing 747, 757, 767, 777	Eaton, LA	99643, 76050, 09790 &	--
65950-1, -3	--	27-60-21	CMM	Ground Spoiler Selector Solenoid Valve	--	10-Jan-86	3	DeHavilland DHC-7/DHC-8	Eaton, LA	99643, 76050, 09790 &	--
65960,-1,-3	--	27-58-31	CMM	Solenoid Valve, Unloading, Flight Spoiler Servo	--	15-Jan-86	1	DeHavilland DHC-7/DHC-8	Eaton, LA	99643, 76050, 09790 &	--
65960,-1,-3	--	65960-27-01	SB	Screw Replacement	--	Feb 15/07	--	Dehavilland DHC-7/DHC-8	Eaton, LA	99643, 76050, 09790 &	--
66490,-1	--	27-14-26	CMM	Second Stage Flap Dump Solenoid Valve	--	01-Sep-86	1	DeHavilland DHC-7	Eaton, LA	99643, 76050, 09790 &	--
66490,-1	--	66940-27-02	SB	Screw Replacement	--	Feb 15/07	--	Dehavilland DHC-7	Eaton, LA	99643, 76050, 09790 &	--
66760-1, -2, -3, -4, -5	--	27-51-05	CMM	Flap and Slat Hydraulic Pressurization Module	--	15-Apr-99	5	Boeing 757	Eaton, LA	99643, 76050, 09790 &	--
66760-1,-2,-3	--	66760-2-27-02	SB	Introduction of 66760-4 and 66760-5	--	Nov 30/89	--	Boeing 757	Eaton, LA	99643, 76050, 09790 &	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
66760-2	--	66760-2-27-01	SB	Introduction of 66760-3	--	Apr 6/89	--	Boeing 757	Eaton, LA	99643, 76050, 09790 &	--
66790-1	--	27-51-03	CMM	Hydraulic Flap and Slate Control Valve Module	--	15-Aug-01	4	Boeing 757	Eaton, LA	99643, 76050, 09790 &	--
66790-1	--	Service Letter BER-1291	SB	Redesigned T-20860	--	Jan 15/92	--	Boeing 757	Eaton, LA	99643, 76050, 09790 &	--
66940, -3	--	27-51-01	CMM	3 Way Normally Closed Solenoid Valve	--	15-Jan-84	1	Boeing 757	Eaton, LA	99643, 76050, 09790 &	--
67110-1,-2	--	32-32-05	CMM	Landing Gear Uplock Actuator	--	15-Jan-04	2	Saab 340/2000	Eaton, LA	99643, 76050, 09790 & 52906	--
67110-1,-2	--	Service Letter MRC-995	SB	External Oil Leakage	--	Sep 6/96	--	Saab 340, 2000	Eaton, LA	99643, 76050, 09790 &	--
67530-2	--	32-13-01	CMM	Pressure Operated Restrictor Check Valve	--	15-Dec-01	2	Boeing 747	Eaton, LA	99643, 76050, 09790 & 52906	--
67530-2	--	Service Letter TS-192-16	SB	Check Torque	--	Jan 8/92	--	Boeing 747	Eaton, LA	99643, 76050, 09790 &	--
67940,-1,-2	--	29-11-02	CMM	Pressure Sensitive Flow Limiter Valve	--	15-Feb-00	3	Boeing 737-300,-400,-500 and 757	Eaton, LA	99643, 76050, 09790 &	--
67940-2	--	67940-29-01	SB	Piston Ring Replacement	--	Apr 23/92	--	Boeing 737-300,-400,-500 and 757	Eaton, LA	99643, 76050, 09790 &	--
68160-1	--	68160-27-01	SB	Introduction of 68160-3	--	May 25/85	--	Boeing 747	Eaton, LA	99643, 76050, 09790 &	--
68160-1, -2, -3	--	27-51-02	CMM	Trailing Edge Flap Control Module	--	15-Jun-04	7	Boeing 747	Eaton, LA	99643, 76050, 09790 &	--
68370-16	--	32-32-15	CMM	Emergency Uplock Landing Gear Valve	--	15-Jan-95	0	Saab 340	Eaton, LA	99643, 76050, 09790 & 52906	--
68370-2	--	32-31-10	CMM	Emergency Uplock Landing Gear Valve	--	30-Jul-00	1	Saab 340	Eaton, LA	99643, 76050, 09790 & 52906	--
68420,-1,-2	--	32-42-25	CMM	Hydraulic Parking Brake Valve	--	15-Dec-03	2	Saab 340	Eaton, LA	99643, 76050, 09790 & 52906	--
68530, -1	--	27-51-08	CMM	Motor Operated Cartridge Valve	--	01-Feb-00	1	Boeing 747	Eaton, LA	99643, 76050, 09790 &	--
68640, -2	--	32-34-01	CMM	Pressure Operated Restrictor Check Valve	--	01-Jul-86	0	Boeing 747	Eaton, LA	99643, 76050, 09790 & 52906	--
68770-1	--	29-11-03	CMM	Relief Valve	--	01-Apr-83	0	Boeing 757	Eaton, LA	99643, 76050, 09790 &	--
69210,-1	--	32-10-41	CMM	Hydraulic Sequence Mechanical Valve	--	01-Jan-05	1	DeHavilland DHC-8	Eaton, LA	99643, 76050, 09790 & 52906	--
69660, -1, -3	--	29-11-04	CMM	Solenoid Pilot Operated Hydraulic System Transfer Valve	--	01-Sep-04	3	Boeing 737-300,-400,-500	Eaton, LA	99643, 76050, 09790 &	--
69660-1	--	69660-29-01	SB	Introduction of 69660-3	--	Aug 1/91	--	Boeing 737-300,-400,-500	Eaton, LA	99643, 76050, 09790 &	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
69660-3	--	69660-29-02	SB	Inspection of Actuator	--	Feb 15/93	--	Boeing 737-300,-400,-500	Eaton, LA	99643, 76050, 09790 &	--
69730-2, -5	--	27-60-20	CMM	Ground Spoiler Selector Solenoid Valve	--	15-Jun-93	2	DeHavilland DHC-7	Eaton, LA	99643, 76050, 09790 &	--
69730-3	--	69730-3-27-01	SB	Switch Repair	--	Oct 1/85	--	DeHavilland DHC-7	Eaton, LA	99643, 76050, 09790 &	--
69730-5	--	69730-5-27-01	SB	Screw Replacement	--	Feb 6/89	--	DeHavilland DHC-7	Eaton, LA	99643, 76050, 09790 &	--
70172-1	--	32-32-03	CMM	Hydraulic Pressure Reducer and Relief Valve	--	01-Nov-86	0	Fokker 50	Eaton, LA	99643, 76050, 09790 & 52906	--
70184, -1	--	32-44-03	CMM	Brake Control Valve	--	15-Dec-04	4	Fokker 50	Eaton, LA	99643, 76050, 09790 & 52906	--
70185, -1	--	32-32-07	CMM	Mechanically Operated Sequence Valve	--	15-Dec-04	2	Fokker 50	Eaton, LA	99643, 76050, 09790 & 52906	--
70205, -1	--	32-71-02	CMM	2 Position 4 Way Motor Operated Valve	--	15-Dec-99	2	Boeing 767	Eaton, LA	99643, 76050, 09790 & 52906	--
70237, -1	--	32-44-01	CMM	Brake Shutoff Valve	--	15-May-03	2	Fokker 50	Eaton, LA	99643, 76050, 09790 & 52906	--
70237-1	--	70237-32-02	SB	New Poppet Assembly	--	Sep 15/01	--	Fokker 50	Eaton, LA	99643, 76050, 09790 & 52906	--
70269, -1	--	32-71-04	CMM	Tail Skid Control Module	--	18-Apr-14	6	Boeing 767	Eaton, LA	99643, 76050, 09790 & 52906	--
70385,-1,-2,-3,-10	--	27-22-01	CMM	Rudder Manifold, Active	--	15-Apr-92	3	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
70385-1	--	70385-1-27-01	SB	Introduction of 70385-10	--	Oct 30/87	--	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
70385-10	--	70385-27-01	SB	Introduction of 70385-2	--	Aug 15/89	--	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
70385-2	--	70385-2-27-01	SB	New Pressure Gage	--	Aug 15/91	--	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
70385-2	--	70385-2-27-02	SB	Introduction of 70385-3	--	Apr 15/93	--	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
70385-2,-3,-10	--	70385-27-04	SB	Replacement of End Cap Screws	--	Dec 1/98	--	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
70385-2,-3,-10 and 70385-1	--	Service Letter SIL-70385	SB	Inspection of Closure Part Number 46597-1	--	Aug 30/10	--	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
70385-3	--	70385-3-27-01	SB	Introduction of 70385-2	--	Apr 15/93	--	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
70386,-1,-2,-3,-10	--	27-22-01	CMM	Rudder Manifold, Standby	--	15-Apr-92	3	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
70386-1	--	70386-1-27-01	SB	Introduction of 70386-10	--	Oct 30/87	--	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
70386-10	--	70386-27-01	SB	Introduction of 70386-2	--	Aug 15/89	--	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
70386-2	--	70386-2-27-01	SB	New Pressure Gage	--	Aug 15/91	--	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
70386-2	--	70386-2-27-02	SB	Introduction of 70386-3	--	Apr 15/93	--	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
70386-2,-3,-10	--	70386-27-04	SB	Replacement of End Cap Screws	--	Dec 1/98	--	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
70386-3	--	70386-3-27-01	SB	Introduction of 70386-2	--	Apr 15/93	--	Fokker 100	Eaton, LA	99643, 76050, 09790 &	--
70396, -1	--	32-44-04	CMM	Brake Control Valve	--	30-Aug-87	1	Fokker 100	Eaton, LA	99643, 76050, 09790 & 52906	--
70507-2	--	70507-32-02	SB	Introduction of 70507-3	--	Jun 1/97	--	Boeing 747, 757, 767, 777	Eaton, LA	99643, 76050, 09790 & 52906	--
70507-2, -3	--	32-41-01	CMM	Dual Brake Metering Valve	--	15-Jan-98	2		Eaton, LA	99643, 76050, 09790 & 52906	--
70507-2,-3	--	70507-32-01	SB	Bolt Replacement	--	Jun 1/97	--	Boeing 747, 757, 767, 777	Eaton, LA	99643, 76050, 09790 & 52906	--
70507-2,-3	--	70507-32-03	SB	Bolt Replacement	--	Jan 10/11	--	Boeing 747, 757, 767, 777	Eaton, LA	99643, 76050, 09790 & 52906	--
70577-40,-41,-42,-43,-4	--	52-10-05	CMM	Rotary Hydraulic Snubber	--	01-Oct-02	1	Boeing 757	Eaton, LA	99643, 76050, 09790 &	--
70577-TAB (ES)	--	52-10-02	CMM	Rotary Hydraulic Snubber	--	15-Aug-02	3	Boeing 747	Eaton, LA	,09790	--
70699, -1	--	32-32-08	CMM	Shuttle Valve	--	01-May-88	0	Fokker 50	Eaton, LA	99643, 76050, 09790 & 52906	--
70729-1	--	32-44-05	CMM	Brake Control Valve	--	01-Nov-89	0	Fokker 100	Eaton, LA	99643, 76050, 09790 & 52906	--
70729-1	--	70729-32-01	SB	New Spring and Guide	--	Dec 1/00	--	Fokker 100	Eaton, LA	99643, 76050, 09790 & 52906	--
70739-1	--	27-82-01	CMM	Leading Edge Slat Actuator	--	10-Sep-14	1	MD-11	Eaton, LA	99643, 76050, 09790 &	--
70740-1	--	32-44-06	CMM	Integrated Brake Control Valve	--	15-Mar-13	4	MD-11	Eaton, LA	99643, 76050, 09790 & 52906	--
70741-3	--	70741-52-01	SB	Modification of Piston Rod Assembly	--	Aug 15/95	--	MD-11	Eaton, LA	99643, 76050, 09790 &	--
70741-3, -5	--	27-52-04	CMM	Inboard Trailing Edge Flap Actuator	--	15-Feb-96	1	MD-11	Eaton, LA	99643, 76050, 09790 &	--
70781-3, -5, -7	--	27-52-02	CMM	Trailing Edge Flap Outboard Actuator	--	01-Mar-96	2	MD-11	Eaton, LA	99643, 76050, 09790 &	--
70781-5	--	70781-52-01	SB	Modification of Piston Rod Assembly	--	Aug 15/96	--	MD-11	Eaton, LA	99643, 76050, 09790 &	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
70781-7	--	70781-52-02	SB	Corrosion on Gland	--	Dec 1/05	--	MD-11	Eaton, LA	99643, 76050, 09790 &	--
70837,1,-,2	--	70837-27-02	SB	Repair or Bearings	--	Feb 15/93	--	Saab 340	Eaton, LA	99643, 76050, 09790 &	--
70837-1	--	70837-27-01	SB	Introduction of 7087-2	--	Jan 1/92	--	Saab 340	Eaton, LA	99643, 76050, 09790 &	--
70837-1, -2	--	27-50-01	CMM	Flap Actuator Hydraulic Cylinder	--	15-Jan-01	2	Saab 340	Eaton, LA	99643, 76050, 09790 &	--
70841, -2, -3, -4	--	29-01-01	CMM	Self Pressurized Hydraulic Reservoir	--	15-Oct-98	1	Saab 340	Eaton, LA	99643, 76050, 09790 &	--
70841-2	--	70841-29-02	SB	Introduction of 70841-3	--	Jan 1/92	--	Saab 340	Eaton, LA	99643, 76050, 09790 &	--
70841-3	--	70841-29-03	SB	Cracked Ports	--	May 1/93	--	Saab 340	Eaton, LA	99643, 76050, 09790 &	--
70857-1	--	70857-32-01	SB	Upgrade of Linkage Assembly	--	Jan 8/92	--	Saab 340	Eaton, LA	99643, 76050, 09790 & 52906	--
70857-1	--	70857-32-02	SB	Upgrade of Plug	--	Jan 15/92	--	Saab 340	Eaton, LA	99643, 76050, 09790 & 52906	--
70857-1	--	70857-32-03	SB	Introduction of 70857-2	--	Jan 9/92	--	Saab 340	Eaton, LA	99643, 76050, 09790 & 52906	--
70857-1	--	70857-32-04	SB	Introduction of 70857-2	--	Jan 9/92	--	Saab 340	Eaton, LA	99643, 76050, 09790 & 52906	--
70857-1, -2	--	32-50-01	CMM	Nose Wheel Steering System	--	15-Mar-97	1	Saab 340	Eaton, LA	99643, 76050, 09790 & 52906	--
70857-1,-2	--	Service Letter MRC-792	SB	Squeaking or Chirping Sound	--	Jul 28/92	--	Saab 340	Eaton, LA	99643, 76050, 09790 &	--
70857-1,-2	--	Service Letter MRC-394	SB	Leakage from Servo Output Pinion Cover	--	Mar 2/94	--	Saab 340	Eaton, LA	99643, 76050, 09790 &	--
70902, -3, -4, -5, -6	--	29-11-10	CMM	Ground Service Manifold	--	15-Oct-09	2	Airbus A330/A340	Eaton, LA	99643, 76050, 09790 &	--
70902-3	--	70902-29-02	SB	Replacement of Cap	--	Mar 15/02	--	Airbus A330/A340	Eaton, LA	99643, 76050, 09790 &	--
70902-3	--	70902-29-03	SB	Introduction of 70902-4	--	Mar 15/02	--	Airbus A330/A340	Eaton, LA	99643, 76050, 09790 &	--
70902-3,-4	--	70902-29-04	SB	Screw Replacement	--	Jun 1/07	--	Airbus A330/A340	Eaton, LA	99643, 76050, 09790 &	--
70912, -1	--	32-34-02	CMM	In-Line Hydraulic Priority Relief Valve	--	15-Jul-00	2	Boeing 767	Eaton, LA	99643, 76050, 09790 & 52906	--
71035-3	--	29-11-12	CMM	Hydraulic Priority Valve	--	15-Apr-03	1	Airbus A330/A340	Eaton, LA	99643, 76050, 09790 &	--
71035-3	--	71035-29-01	SB	Replacement of Closure, End Cap and Guide	--	Jul 15/02	--	Airbus A330/A340	Eaton, LA	99643, 76050, 09790 &	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
71089-2, -3	--	27-51-11	CMM	Trailing Edge Flap Flow Module	--	15-Dec-97	0	Boeing 747	Eaton, LA	99643, 76050, 09790 &	--
71121-1, -2 (ES)	--	25-50-01	CMM	Maindeck Cargo System Shock Absorbers	--	01-Apr-71	0	Boeing 747	Eaton, LA	,09790	--
71145-1	--	29-19-01	CMM	Hydraulic Solenoid Valve	--	01-Nov-93	0	Airbus A340	Eaton, LA	99643, 76050, 09790 &	--
71166-4, -5	--	27-51-25	CMM	Flap Actuator Hydraulic Cylinder	--	01-Dec-96	1	Saab 2000	Eaton, LA	99643, 76050, 09790 &	--
71178-1	--	71178-1-32-01	SB	Cracked Manifold	--	Mar 1/94	--	Airbus A330/A340	Eaton, LA	99643, 76050, 09790 & 52906	--
71178-1	--	71178-1-32-02	SB	Introduction of 71178-2	--	May 15/85	--	Airbus A330/A340	Eaton, LA	99643, 76050, 09790 & 52906	--
71178-1, -2	--	32-11-41	CMM	Right Wing Hydraulic Fuse Unit and Manifold	--	17-Mar-14	4	Airbus A330/A340	Eaton, LA	99643, 76050, 09790 & 52906	--
71179-1	--	71179-1-32-01	SB	Cracked Manifold	--	Mar 1/94	--	Airbus A330/A340	Eaton, LA	99643, 76050, 09790 & 52906	--
71179-1	--	71179-1-32-02	SB	Introduction of 71179 -2	--	May 15/85	--	Airbus A330/A340	Eaton, LA	99643, 76050, 09790 & 52906	--
71179-1, -2	--	32-11-41	CMM	Left Wing Hydraulic Fuse Unit and Manifold	--	17-Mar-14	4	Airbus A330/A340	Eaton, LA	99643, 76050, 09790 & 52906	--
71304-1, -2	--	32-42-26	CMM	Hydraulic Parking Brake Valve	--	15-Aug-97	1	Saab 2000	Eaton, LA	99643, 76050, 09790 & 52906	--
71311-2, -3	--	29-10-01	CMM	Self Pressurized Hydraulic Reservoir	--	15-Apr-97	1	Saab 2000	Eaton, LA	99643, 76050, 09790 &	--
71396-3	--	71396-3-78-01	SB	Introduction of 71396-4	--	May 15/97	--	Airbus A330	Eaton, LA	99643, 76050, 09790 &	--
71396-3, -4	--	78-36-13	CMM	Power Door System Actuator	--	15-May-96	0	Airbus A330	Eaton, LA	99643, 76050, 09790 &	--
71404,-1,-2	--	32-41-04	CMM	Dual Brake Metering Valve	--	10-Aug-10	3	Boeing 737-600,-700,-800,-900, 747, 757, 767, 777	Eaton, LA	99643, 76050, 09790 & 52906	--
71404,-1	--	71404-32-02	SB	Hydraulic Leakage of Models 737-600,-700,-800,-900	--	Apr 19/06	--	Boeing 737-600.-700,-800,-900, 747, 757, 767, 777	Eaton, LA	99643, 76050, 09790 & 52906	--
71404,-1	--	71404-32-03	SB	Introduction of 71404-2	--	Feb 20.09	--	Boeing 737-600.-700,-800,-900, 747, 757, 767, 777	Eaton, LA	99643, 76050, 09790 & 52906	--
71461, -1, -2	--	32-31-18	CMM	Nose Door Fuse Manifold	--	01-Oct-00	3	Airbus A330/A340	Eaton, LA	99643, 76050, 09790 & 52906	--
71461-1	--	71461-32-02	SB	Introduction of 71461-2	--	Aug 15/98	--	Airbus A330/A340	Eaton, LA	99643, 76050, 09790 & 52906	--
71476,-1,-4	--	52-11-01	CMM	Pneumatic Actuator	--	15-Jul-98	3	Boeing 777	Eaton, LA	99643, 76050, 09790 &	--
71890 (ES)	--	28-09-09	CMM	Check Valve	--	15-Feb-72	0	Boeing 747	Eaton, LA	,09790	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
72029-2	--	32-31-23	CMM	Nose Landing Gear Hydraulic Fuse Unit	--	15-Jul-02	0	Airbus A340-500/-600	Eaton, LA	99643, 76050, 09790 & 52906	--
72372-5,-6,-7,-8	--	52-11-12	CMM	Flight Lock Assembly	--	01-Jun-12	2	Boeing 787	Eaton, LA	99643	--
72435-101, -109 (ES)	--	38-31-14	CMM	4 Inch Manually Operated Ball Valve	--	01-Mar-79	2	Lockheed L1011	Eaton, LA	,09790	--
72497,-1,-2	--	29-22-01	CMM	EDP/ADP Pressure and Case Drain Filter Module	--	15-Jan-15	1	Boeing 747-8	Eaton, LA	99643, 76050, 09790 &	--
72538-3,-4	--	52-11-10	CMM	EPAS Actuator Assembly	--	09-Sep-13	2	Boeing 787	Eaton, LA	99643, 76050, 09790 &	--
73220-1, -2, -3 (ES)	--	25-60-01	CMM	Door Balance System, Life Raft Compartment	--	15-Jan-95	A	Boeing 727, 747	Eaton, LA	,09790	--
77865-1 (ES)	--	38-31-15	CMM	4 Inch Manually Operated Ball Valve	--	01-Feb-88	3	Airbus A310	Eaton, LA	,09790	--
77920-1 (ES)	--	25-60-02	CMM	Door Balance System, Life Raft Compartment	--	01-May-80	0	Boeing 747	Eaton, LA	,09790	--
78695-1, -2 (ES)	--	52-11-01	CMM	Hydraulic Snubber Unit - Entry Service Door	--	18-May-81	0	Boeing 767	Eaton, LA	,09790	--
80810-1 (ES)	--	29-18-04	CMM	Reservoir Fill Selector Valve	--	01-Dec-96	2	Boeing 737	Eaton, LA	,09790	--
8195-20	--	29-09-01	CMM	Hydraulic Pressure Snubber	--	15-Aug-72	0	Boeing 707, 727	Eaton, LA	99643, 76050, 09790 &	--
8195-33, -35	--	29-31-01	CMM	Hydraulic Pressure Snubber	--	15-Dec-99	2	Boeing 747	Eaton, LA	99643, 76050, 09790 &	--
84535-1 (ES)	--	21-58-01	CMM	Shutoff Valve	--	01-May-90	0	Boeing 747	Eaton, LA	,09790	--
84650,-1	--	28-13-01	CMM	Relief Valve Assembly	--	01-Sep-14	1	Boeing 747-8	Eaton, LA	99643, 76050, 09790 &	--
85305-1 (ES)	--	38-31-16	CMM	4 Inch Waste Valve	--	01-Nov-89	0	MD11	Eaton, LA	,09790	--
86705-1 (ES)	--	21-22-01	CMM	Shutoff Valve	--	15-Apr-91	0	Boeing 747	Eaton, LA	,09790	--
87020-2 (ES)	--	52-48-20	CMM	Environmental Control System Door Snubber	--	01-Jun-97	2	Boeing 777	Eaton, LA	,09790	--
87090-5 (ES)	--	52-36-01	CMM	Bulk Cargo Door Snubber	--	15-Apr-95	0	Boeing 777	Eaton, LA	,09790	--
87135-1,-2,-3,-4 (ES)	--	38-20-01	CMM	Gray Water Valve	--	01-Dec-96	0	MD-11	Eaton, LA	,09790	--
87290-1 (ES)	--	21-22-02	CMM	Shutoff Valve	--	15-Nov-13	2	Boeing 747	Eaton, LA	,09790	--
GA7463-3 (ES)	--	52-49-01	CMM	Rotary Hydraulic Snubber	--	01-May-79	2	Boeing 747, 767, 777	Eaton, LA	,09790	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
72538-52-01	--	72538-52-01	SB	Service Bulleting for Door System - EPAS Pressure Relief Valve - Inspection, 72538-4.	24-Mar-21	--	0	Boeing 787	Eaton, LA	99643, 76050, 09790 &	--
70846	--	29-13-01	CMM	Accumulator - 70846	15-Sep-95	--	0	--	Eaton, LA	99643, 76050, 09790 &	--
70847	--	31-31-01	CMM	U.C Selector Valve	15-Sep-95	09-Mar-18	1	--	Eaton, LA	99643, 76050, 09790 &	--
70843	--	32-31-01	CMM	Nose Wheel Actuator	30-Sep-00	--	1	--	Eaton, LA	99643, 76050, 09790 & 52906	--
0724000-1	--	28-20-24	OM	REFUELLING CPLG	01-Jul-68	06-May-87	1	BRUNEI OPV, HFB 320 (HANSA JET), MB326, SD-330, SD-360, SHORTS SC7 SKYVAN, Type 45	Titchfield, UK	K2523	--
0724000-2	--	28-20-24	OM	REFUELLING CPLG	01-Jul-68	06-May-87	1	BRUNEI OPV, HFB 320 (HANSA JET), MB326, SD-330, SD-360, SHORTS SC7 SKYVAN, Type 45	Titchfield, UK	K2523	--
0724000-3	--	28-20-24	OM	REFUELLING CPLG	01-Jul-68	06-May-87	1	BRUNEI OPV, HFB 320 (HANSA JET), MB326, SD-330, SD-360, SHORTS SC7 SKYVAN, Type 45	Titchfield, UK	K2523	--
0724140	--	28-20-85	CMM	COVER ASSEMBLIES	01-Nov-82	29-Jun-98	7	BAC 1-11, BRUNEI OPV, HFB 320 (HANSA JET), LYNX, MB326	Titchfield, UK	K2523	0724140/0727180 OBSOLETE
0724210	--	28-N4-4	OM	SWITCH UNIT	01-May-62	--	0	BAC 1-11	Titchfield, UK	K2523	--
0724255	--	28-20-41	OM	SWITCH UNIT	01-Jul-68	--	0	ARGOSY	Titchfield, UK	K2523	--
0724275	--	28-22-77	OM	ADPTR UNIT & SWITCH (RE/DEFUEL CP)	01-Feb-75	04-Jan-06	3	LYNX	Titchfield, UK	K2523	--
0724300	--	28-21-96	OM	MK 24 REFUEL CPLG	01-Apr-73	--	0	CASA 212	Titchfield, UK	K2523	--
0724330	--	FR24-83	TDS	PRES REF ADAPTOR ASSY	01-Dec-83	--	0	Not Known	Titchfield, UK	K2523	--
0724340	--	28-23-10	OM	A/C ADAPTOR & SWITCH UNIT	01-Nov-76	01-Jan-85	1	LYNX	Titchfield, UK	K2523	--
0724370	--	28-21-30	CMM	REFUEL ADAPTOR (HIFR)	15-Jun-94	24-May-95	1	EH101	Titchfield, UK	K2523	--
0725000-1	--	28-20-24	OM	REFUELLING CPLG	01-Jul-68	06-May-87	1	BRUNEI OPV, HFB 320 (HANSA JET), MB326, SD-330, SD-360, SHORTS SC7 SKYVAN, Type 45	Titchfield, UK	K2523	--
0725000-2	--	28-20-24	OM	REFUELLING CPLG	01-Jul-68	06-May-87	1	BRUNEI OPV, HFB 320 (HANSA JET), MB326, SD-330, SD-360, SHORTS SC7 SKYVAN, Type 45	Titchfield, UK	K2523	--
0725000-3	--	28-20-24	OM	REFUELLING CPLG	01-Jul-68	06-May-87	1	BRUNEI OPV, HFB 320 (HANSA JET), MB326, SD-330, SD-360, SHORTS SC7 SKYVAN, Type 45	Titchfield, UK	K2523	--
0725000-4	--	28-20-24	OM	REFUELLING CPLG	01-Jul-68	06-May-87	1	BRUNEI OPV, HFB 320 (HANSA JET), MB326, SD-330, SD-360, SHORTS SC7 SKYVAN, Type 45	Titchfield, UK	K2523	--
0725000-5	--	28-20-24	OM	REFUELLING CPLG	01-Jul-68	06-May-87	1	BRUNEI OPV, HFB 320 (HANSA JET), MB326, SD-330, SD-360, SHORTS SC7 SKYVAN, Type 45	Titchfield, UK	K2523	--
0725095	--	28-21-07	CMM	VALVE REFUEL/DEFUEL	01-Dec-85	17-Jun-11	3	BAe ATP, JS61, N250	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
0725115	--	28-21-24	CMM	REFUEL/DEFUEL ADAPTOR	10-Jun-94	14-Jun-04	1	EH101	Titchfield, UK	K2523	--
0725145	--	0725175-28-01	SB	Refuel Coupling - Screw Torque Values	22-Jan-09	10-Jan-16	3	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
0725145	--	28-25-40	CMM	REFUEL COUPLING	06-May-87	26-Apr-18	9	A319, A320, A321	Titchfield, UK	K2523	--
0725175	--	0725175-28-01	SB	Refuel Coupling - Screw Torque Values	22-Jan-09	10-Jan-16	3	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
0725175	--	28-25-40	CMM	REFUEL COUPLING	06-May-87	26-Apr-18	9	A319, A320, A321	Titchfield, UK	K2523	--
0725185	--	0725175-28-01	SB	Refuel Coupling - Screw Torque Values	22-Jan-09	10-Jan-16	3	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
0725185	--	28-25-40	CMM	REFUEL COUPLING	06-May-87	26-Apr-18	9	A319, A320, A321	Titchfield, UK	K2523	--
0725295	--	28-21-58	CMM	REFUEL ADAPTORS	30-Nov-92	--	0	SAAB 2000	Titchfield, UK	K2523	--
0725345	--	28-21-58	CMM	REFUEL ADAPTORS	30-Nov-92	--	0	SAAB 2000	Titchfield, UK	K2523	--
0726082	--	82-40-4	OM	WATER METH REF UNIT	01-Apr-70	30-Sep-04	6	F27	Titchfield, UK	K2523	--
0726090	--	82-40-4	OM	WATER METH REF UNIT	01-Apr-70	30-Sep-04	6	F27	Titchfield, UK	K2523	--
0726102	--	82-40-4	OM	WATER METH REF UNIT	01-Apr-70	30-Sep-04	6	F27	Titchfield, UK	K2523	--
0726112	--	82-40-4	OM	WATER METH REF UNIT	01-Apr-70	30-Sep-04	6	F27	Titchfield, UK	K2523	--
0726122	--	82-40-4	OM	WATER METH REF UNIT	01-Apr-70	30-Sep-04	6	F27	Titchfield, UK	K2523	--
0726130	--	82-40-4	OM	WATER METH REF UNIT	01-Apr-70	30-Sep-04	6	F27	Titchfield, UK	K2523	--
0726145	--	82-40-10	OM	WATER METH REF UNIT	01-Oct-75	--	0	F27	Titchfield, UK	K2523	--
0726150	--	82-40-4	OM	WATER METH REF UNIT	01-Apr-70	30-Sep-04	6	F27	Titchfield, UK	K2523	--
0726160	--	82-40-4	OM	WATER METH REF UNIT	01-Apr-70	30-Sep-04	6	F27	Titchfield, UK	K2523	--
0726170	--	82-40-4	OM	WATER METH REF UNIT	01-Apr-70	30-Sep-04	6	F27	Titchfield, UK	K2523	--
0726230	--	28-N4-7	OM	SHUT OFF VALVE	01-Mar-64	--	0	Not Known	Titchfield, UK	K2523	--
0726280	--	82-20-3	OM	WATER VALVE	01-Nov-64	--	0	BAC 1-11	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
0726285	--	82-40-4	OM	WATER METH REF UNIT	01-Apr-70	30-Sep-04	6	F27	Titchfield, UK	K2523	--
0726290	--	82-15-4247-284	SB	WATER METH VALVE - CHANGE OF SO LEVEL	01-Aug-68	30-Jan-68	1	Not Known	Titchfield, UK	K2523	--
0726290	--	82-40-5	OM	WATER METH REF VALVE	01-Feb-68	21-Apr-08	1	VARIOUS	Titchfield, UK	K2523	--
0726295	--	82-40-6	OM	WATER METH REF VALVE	01-Feb-69	--	0	Not Known	Titchfield, UK	K2523	--
0726310	--	82-40-12	OM	WATER METH REF UNIT	01-Dec-76	--	0	F28	Titchfield, UK	K2523	--
0726330	--	82-40-13	OM	WATER METH REF UNIT	01-Jul-77	--	0	F27	Titchfield, UK	K2523	--
0727130	--	28-N4-3	OM	CPLG UNIT SEALING CAP	01-Dec-62	--	0	Not Known	Titchfield, UK	K2523	--
0727180	--	28-20-85	CMM	COVER ASSEMBLIES	01-Nov-82	29-Jun-98	7	BAC 1-11, BRUNEI OPV, HFB 320 (HANSA JET), LYNX, MB326	Titchfield, UK	K2523	0724140/0727180 OBSOLETE
0727180	--	28-9-4647-35	SB	COVER ASSY - STRONGER HANDLE HINGE POINTS	01-Aug-67	--	0	Not Known	Titchfield, UK	K2523	--
0727200	--	28-20-85	CMM	COVER ASSEMBLIES	01-Nov-82	29-Jun-98	7	BAC 1-11, BRUNEI OPV, HFB 320 (HANSA JET), LYNX, MB326	Titchfield, UK	K2523	0724140/0727180 OBSOLETE
0727210	--	28-20-85	CMM	COVER ASSEMBLIES	01-Nov-82	29-Jun-98	7	BAC 1-11, BRUNEI OPV, HFB 320 (HANSA JET), LYNX, MB326	Titchfield, UK	K2523	0724140/0727180 OBSOLETE
0727210	--	28-28-19794	SB	COVER ASSY - NEW STOP PIN	--	--	0	Not Known	Titchfield, UK	K2523	--
0727490	--	28-21-25	CMM	COVER AND CABLE ASSEMBLY	30-May-94	30-Jan-97	1	EH101	Titchfield, UK	K2523	Westlands 1 CRC + 1 copy
0727510	--	0727510-28-1	SB	FLUSH COVER & CABLE-INTRO RETRACTABLE CABLE ASSY	07-Jun-91	02-Oct-92	2	A319, A320, A321	Titchfield, UK	K2523	--
0727510	--	28-25-41	CMM	FLUSH COVER AND CABLE ASSEMBLY	01-May-87	08-Jan-20	13	A310, A319, A320, A321	Titchfield, UK	K2523	--
0727510	--	SIL-CS-7-05	SIL	FLUSH COVER - INCORRECT CIRCLIPS	--	--	0	A310, A319, A320, A321	Titchfield, UK	K2523	TASK CANCELLED
0727537	--	28-21-57	CMM	REFUEL ADAPTOR CAP	01-Nov-92	14-Jan-98	1	N250, SAAB 2000	Titchfield, UK	K2523	--
0727540	--	0727510-28-1	SB	FLUSH COVER & CABLE-INTRO RETRACTABLE CABLE ASSY	07-Jun-91	02-Oct-92	2	A319, A320, A321	Titchfield, UK	K2523	--
0727540	--	28-25-41	CMM	FLUSH COVER AND CABLE ASSEMBLY	01-May-87	08-Jan-20	13	A310, A319, A320, A321	Titchfield, UK	K2523	--
0727540	--	SIL-2008-01	SIL	FLUSH COVER AND CABLE ASSEMBLY 0727540 - SPLIT-RING AND CHAIN DAMAGE	21-Jan-08	--	0	A318, A319, A320, A321	Titchfield, UK	K2523	--
0727540	--	SIL-CS-7-05	SIL	FLUSH COVER - INCORRECT CIRCLIPS	--	--	0	A310, A319, A320, A321	Titchfield, UK	K2523	TASK CANCELLED

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
0727600	--	28-10-95	CMM	WATER DRAIN VALVE	01-Apr-92	27-Aug-93	1	F100, F70	Titchfield, UK	K2523	--
0727601	--	28-10-95	CMM	WATER DRAIN VALVE	01-Apr-92	27-Aug-93	1	F100, F70	Titchfield, UK	K2523	--
0727602	--	28-10-95	CMM	WATER DRAIN VALVE	01-Apr-92	27-Aug-93	1	F100, F70	Titchfield, UK	K2523	--
0727638	--	28-21-31	CMM	REFUELLING ADAPTOR CAP	16-Oct-96	14-Mar-03	1	LEARJET 45	Titchfield, UK	K2523	--
0728111	--	28-10-15	OM	PROBE VALVE	01-Mar-68	--	0	Not Known	Titchfield, UK	K2523	--
0728112	--	28-10-15	OM	PROBE VALVE	01-Mar-68	--	0	Not Known	Titchfield, UK	K2523	--
0728113	--	28-10-15	OM	PROBE VALVE	01-Mar-68	--	0	Not Known	Titchfield, UK	K2523	--
0728120	--	28-10-16	CMM	NOZZLE/BREAKJOINT CPLG	01-Nov-68	--	0	Not Known	Titchfield, UK	K2523	--
0728130	--	28-10-16	CMM	NOZZLE/BREAKJOINT CPLG	01-Nov-68	--	0	Not Known	Titchfield, UK	K2523	--
0728220	--	28-10-44	OM	BREAKJOINT COUPLING	01-Jun-75	27-Jul-98	1	AV8A	Titchfield, UK	K2523	--
0728252	--	28-10-43	OM	RECEPTION CPLG	01-Feb-75	01-Jan-85	1	LYNX	Titchfield, UK	K2523	--
0728365	--	0728365-28-1	SB	WING CONN. & WATER/FUEL DRAIN VALVE LARGER HOLES	01-Jul-84	--	0	Not Known	Titchfield, UK	K2523	--
0728365	--	28-21-05	CMM	DROP TANK WING CONNECTION WITH NRV	01-Sep-84	--	0	Not Known	Titchfield, UK	K2523	SB 0728365-28-1
0728485	--	28-10-56	CMM	FUEL/AIR CONNECTION (PYLON FITTING)	04-Jun-96	--	0	KT-1	Titchfield, UK	K2523	--
0728495	--	28-10-57	CMM	FUEL/AIR CONNECTION (TANK FITTING)	04-Jun-96	--	0	KT-1	Titchfield, UK	K2523	--
0728505	--	28-10-58	CMM	FUEL/AIR CONNECTION (WING FITTING)	04-Jun-96	--	0	KT-1	Titchfield, UK	K2523	--
0733040	--	0733095-28-2	SB	FUEL SYSTEM WATER DRAIN VALVES - SEALS SPLITTING	--	01-Mar-89	1	BAE 146	Titchfield, UK	K2523	--
0733040	--	0733095-28-3	SB	WATER/FUEL DRAIN VALVE - INTRODUCTION OF NEW WATER DRAIN VALVE	10-Sep-02	--	0	BAE 146	Titchfield, UK	K2523	--
0733040	--	28-10-60	CMM	WATER/FUEL DRAIN VALVES	12-Jun-80	31-Mar-11	6	BAE 146	Titchfield, UK	K2523	--
0733050	--	0733095-28-2	SB	FUEL SYSTEM WATER DRAIN VALVES - SEALS SPLITTING	--	01-Mar-89	1	BAE 146	Titchfield, UK	K2523	--
0733050	--	28-10-60	CMM	WATER/FUEL DRAIN VALVES	12-Jun-80	31-Mar-11	6	BAE 146	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
700-1-19308-000	--	MM248	MM	PROCESS UNIT PRESS RATIO	--	--	0	TORNADO	Titchfield, UK	K2523	--
700-1-19338-100	--	73-10-16	CMM	CONTROL UNIT, PROTECTION	01-Apr-81	01-Oct-84	1	LYNX	Titchfield, UK	K2523	--
700-1-22490-000	--	MM273	MM	Generator Control Unit	--	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-400	--	24-20-20	CMM	GENERATOR CONTROL UNIT	16-Feb-81	07-Apr-11	7	BAE 146	Titchfield, UK	K2523	TR1 dated 25/02/94
700-1-22490-400	--	24-9-1338	SB	INTRODUCTION OF IMPROVED GCU	12-Dec-90	12-Dec-90	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-400	--	HGE24-07-1347	SB	Minor design changes	06-Aug-90	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-400	--	HGE24-08-1368	SB	Minor design changes	17-Aug-90	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-400	--	HGE24-09-1338	SB	Introduction of improved generator control unit with new base assembly embodying two 2-pole changeov	12-Dec-90	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-400	--	HGE24-10-1366	SB	Introduction of noise suppression capacitor in under frequency protection circuit input signal	13-Aug-90	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-400	--	HGE24-11-1363	SB	Introduction of printed wiring board assemblies incorporating pads interposed between transistors an	12-Sep-90	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-400	--	HGE24-16-1380	SB	Introduction of GCU Mk 410 and GCU Mk 510 incorporating new overcurrent and undervoltage protection	14-Aug-91	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-400	--	HGE24-18-1404	SB	Introduction of GCU type 420 and GCU type 520 incorporating an unbalanced current detector circuit	01-Apr-93	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-400	--	HGE24-19-1409	SB	Introduction of improved standard components to OV-OP board and tag board assemblies	20-Aug-93	20-Oct-94	1	BAE 146	Titchfield, UK	K2523	--
700-1-22490-400	--	HGE24-23	SB	GCU - Underfrequency trip level setting	11-Mar-94	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-410	--	HGE24-18-1404	SB	Introduction of GCU type 420 and GCU type 520 incorporating an unbalanced current detector circuit	01-Apr-93	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-420	--	24-20-24	CMM	GCU	25-Jun-93	05-Jun-18	9	BAE 146	Titchfield, UK	K2523	--
700-1-22490-420	--	HGE24-19-1409	SB	Introduction of improved standard components to OV-OP board and tag board assemblies	20-Aug-93	20-Oct-94	1	BAE 146	Titchfield, UK	K2523	--
700-1-22490-420	--	HGE24-20-1418	SB	Introduction of undervoltage board incorporating capacitors of reduced value to eliminate unacceptab	15-Jun-93	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-420	--	HGE24-21-1419	SB	Introduction of alternative rotary switch assembly	17-Feb-94	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-420	--	HGE24-23	SB	GCU - Underfrequency trip level setting	11-Mar-94	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-420	--	HGE24-24-1434(OM)	SB	GCU - Minor design changes	23-Jul-96	--	0	BAE 146	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
700-1-22490-420	--	HGE24-25-1433	SB	GCU - Improved frequency control	23-Jul-96	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-420	--	HGE24-26-1437	SB	GCU - UV-DP PWB assembly - Introduction of an additional diode	23-Jul-96	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-420	--	HGE24-28-1459(OM)	SB	GCU - Minor design changes	17-Dec-98	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-420	--	HGE24-29-1455	SB	GCU - Introduce uprated components to improve unit reliability	23-Aug-00	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-500	--	HGE24-11-1363	SB	Introduction of printed wiring board assemblies incorporating pads interposed between transistors an	12-Sep-90	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-500	--	HGE24-16-1380	SB	introduction of GCU MK 410 and GCU Mk 510 incorporating new overcurrent and undervoltage protection	14-Aug-91	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-500	--	HGE24-17-1379	SB	IMPROVED PWBs	--	--	--	BAE 146	Titchfield, UK	K2523	TO BE WRITTEN
700-1-22490-500	--	HGE24-18-1404	SB	Introduction of GCU type 420 and GCU type 520 incorporating an unbalanced current detector circuit	01-Apr-93	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-500	--	HGE24-19-1409	SB	Introduction of improved standard components to OV-OP board and tag board assemblies	20-Aug-93	20-Oct-94	1	BAE 146	Titchfield, UK	K2523	--
700-1-22490-500	--	HGE24-23	SB	GCU - Underfrequency trip level setting	11-Mar-94	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-520	--	24-20-24	CMM	GCU	25-Jun-93	05-Jun-18	9	BAE 146	Titchfield, UK	K2523	--
700-1-22490-520	--	HGE24-18-1404	SB	Introduction of GCU type 420 and GCU type 520 incorporating an unbalanced current detector circuit	01-Apr-93	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-520	--	HGE24-19-1409	SB	Introduction of improved standard components to OV-OP board and tag board assemblies	20-Aug-93	20-Oct-94	1	BAE 146	Titchfield, UK	K2523	--
700-1-22490-520	--	HGE24-20-1418	SB	Introduction of undervoltage board incorporating capacitors of reduced value to eliminate unacceptab	15-Jun-93	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-520	--	HGE24-21-1419	SB	Introduction of alternative rotary switch assembly	17-Feb-94	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-520	--	HGE24-23	SB	GCU - Underfrequency trip level setting	11-Mar-94	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-520	--	HGE24-24-1434(OM)	SB	GCU - Minor design changes	23-Jul-96	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-520	--	HGE24-25-1433	SB	GCU - Improved frequency control	23-Jul-96	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-520	--	HGE24-26-1437	SB	GCU - UV-DP PWB assembly - Introduction of an additional diode	23-Jul-96	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-520	--	HGE24-28-1459(OM)	SB	GCU - Minor design changes	17-Dec-98	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22490-520	--	HGE24-29-1455	SB	GCU - Introduce uprated components to improve unit reliability	23-Aug-00	--	0	BAE 146	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
700-1-22490-520	--	HGE24-30-CA040	SB	GCU - Correction of manufacturer's deficiency	26-Jan-01	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22535-000	--	MM284	MM	--	--	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22563-000	--	MM285	MM	--	--	--	0	BAE 146	Titchfield, UK	K2523	--
700-1-22680-000	--	73-10-18	CMM	CONTROL UNIT, PROTECTION	01-Jan-85	--	0	GEM	Titchfield, UK	K2523	--
7012060H01	--	47-21-01	CMM	VALVE-1IN REMOTE	07-May-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	--
7012060H02	--	47-21-01	CMM	VALVE-1IN REMOTE	07-May-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	--
7012060H03	--	47-21-01	CMM	VALVE-1IN REMOTE	07-May-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	--
7012061H01	--	47-22-01	CMM	VALVE-1 1/2IN CHECK	02-May-08	23-Sep-15	2	BOEING 787	Titchfield, UK	K2523	--
7012062H01	--	47-22-02	CMM	VALVE-1 1/4IN CHECK	06-May-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	--
7012063H01	--	47-22-03	CMM	VALVE-2IN CHECK ARRESTOR	07-May-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	--
7012063H02	--	47-22-03	CMM	VALVE-2IN CHECK ARRESTOR	07-May-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	--
7012064H01	--	28-11-20	CMM	VALVE BODY-TELL TALE	03-Jun-08	29-Feb-12	2	BOEING 787	Titchfield, UK	K2523	REMOVE CDCCL STATUS AT REV 2
7012066H01	--	28-13-01++	CMM	(HS) VALVE-VENT FLOAT	02-May-08	23-Sep-15	3	BOEING 787	Titchfield, UK	K2523	Formerly 47-21-02
7012066H02	--	28-13-01++	CMM	(HS) VALVE-VENT FLOAT	02-May-08	23-Sep-15	3	BOEING 787	Titchfield, UK	K2523	Formerly 47-21-02
7012066H03	--	28-13-01++	CMM	(HS) VALVE-VENT FLOAT	02-May-08	23-Sep-15	3	BOEING 787	Titchfield, UK	K2523	Formerly 47-21-02
7012067H01	--	28-13-04+	CMM	VALVE-VENT DRAIN	01-May-08	31-Mar-11	1	BOEING 787	Titchfield, UK	K2523	Previously 47-21-07
7012067H02	--	28-13-04+	CMM	VALVE-VENT DRAIN	01-May-08	31-Mar-11	1	BOEING 787	Titchfield, UK	K2523	Previously 47-21-07
7012069H01	--	28-13-02++	CMM	VALVE-PRESSURE RELIEF	17-Dec-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	PARKER COMPONENT, previously 47-21-03
7012069H02	--	28-13-02++	CMM	VALVE-PRESSURE RELIEF	17-Dec-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	PARKER COMPONENT, previously 47-21-03
7012069H03	--	28-13-02++	CMM	VALVE-PRESSURE RELIEF	17-Dec-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	PARKER COMPONENT, previously 47-21-03
7012069H05	--	28-13-02++	CMM	VALVE-PRESSURE RELIEF	17-Dec-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	PARKER COMPONENT, previously 47-21-03

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
7012070H01	--	47-21-09	CMM	ACTUATOR-VALVE	01-May-08	22-May-14	3	BOEING 787	Titchfield, UK	K2523	--
7012070H02	--	47-21-09	CMM	ACTUATOR-VALVE	01-May-08	22-May-14	3	BOEING 787	Titchfield, UK	K2523	--
7012070H03	--	47-21-09	CMM	ACTUATOR-VALVE	01-May-08	22-May-14	3	BOEING 787	Titchfield, UK	K2523	--
7012073H01	--	28-11-21	CMM	VALVE BODY	28-Feb-08	12-Jun-15	3	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
7012074H01	--	28-13-06+	CMM	VALVE-2 1/2IN CHECK	06-May-08	23-Sep-15	2	BOEING 787	Titchfield, UK	K2523	Previously 47-22-04
7012074H02	--	28-13-06+	CMM	VALVE-2 1/2IN CHECK	06-May-08	23-Sep-15	2	BOEING 787	Titchfield, UK	K2523	Previously 47-22-04
7012075H01	--	47-21-04	ACMM	PUMP-EJECTOR	01-Aug-07	25-Sep-15	3	BOEING 787	Titchfield, UK	K2523	--
7012079H01	--	28-13-03+	CMM	VALVE-VENT FLOAT	31-Mar-11	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	Previously 47-21-05
7012079H02	--	28-13-03+	CMM	VALVE-VENT FLOAT	31-Mar-11	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	Previously 47-21-05
7012079H03	--	28-13-03+	CMM	VALVE-VENT FLOAT	31-Mar-11	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	Previously 47-21-05
7012079H04	--	28-13-03+	CMM	VALVE-VENT FLOAT	31-Mar-11	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	Previously 47-21-05
7012080H01	--	47-21-06	CMM	VALVE 1 1/2IN REMOTE	07-May-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	--
7012080H02	--	47-21-06	CMM	VALVE 1 1/2IN REMOTE	07-May-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	--
7013072H01	--	28-24-23	CMM	DRIVESHAFT-VALVE	02-Oct-09	12-Jun-15	5	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
7013073H01	--	47-21-08	CMM	CLAMP-V BAND	--	--	0	--	Titchfield, UK	K2523	(HS LOGO) TO BE WRITTEN
7013074H01	--	28-24-23	CMM	DRIVESHAFT-VALVE	02-Oct-09	12-Jun-15	5	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
702AA02	--	28-23-16	OM	RELIEF VALVE	29-Sep-78	--	0	BAE 125	Titchfield, UK	K2523	--
702AA17	--	SL64	OM	PRV	01-Oct-65	01-Jan-67	1	Not Known	Titchfield, UK	K2523	--
702AH02	--	49-90-36	OM	RELIEF VALVE	01-Jan-64	01-Mar-66	1	Not Known	Titchfield, UK	K2523	--
702AK02	--	56-40-1	OM	RELIEF VALVE	01-Aug-60	01-Dec-61	1	Not Known	Titchfield, UK	K2523	--
702BD10	--	49-90-36	OM	RELIEF VALVE	01-Jan-64	01-Mar-66	1	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
702CB02-2	--	28-20-74	CMM	PRV	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
703AA07	--	38-10-23+	OM	NRV	01-Jun-66	--	0	BAC 1-11	Titchfield, UK	K2523	*EX-SAUNDERS
703AA07	--	38-5-1	OM	NRV	01-May-59	01-Nov-60	1	Not Known	Titchfield, UK	K2523	--
703AA15	--	28-20-48	OM	NRV	01-Oct-67	--	0	Not Known	Titchfield, UK	K2523	--
703AA15	--	49-90-37	OM	NRV	01-Jan-64	--	0	Not Known	Titchfield, UK	K2523	--
703AA18	--	SL64	OM	PRV	01-Oct-65	01-Jan-67	1	Not Known	Titchfield, UK	K2523	--
703AA19	--	SL64	OM	PRV	01-Oct-65	01-Jan-67	1	Not Known	Titchfield, UK	K2523	--
703AA20	--	72-50-01	OM	RELIEF VALVE	01-Nov-70	01-Jul-87	1	TRIDENT	Titchfield, UK	K2523	--
703AB15	--	49-90-37	OM	NRV	01-Jan-64	--	0	Not Known	Titchfield, UK	K2523	--
703BA09	--	37-10-46	OM	NRV	01-Oct-63	01-Mar-66	1	Not Known	Titchfield, UK	K2523	--
704AA12	--	38-10-1+	OM	PRV	01-Jul-60	--	0	Not Known	Titchfield, UK	K2523	*OUT OF PRINT
704BA03	--	38-5-1	OM	NRV	01-May-59	01-Nov-60	1	Not Known	Titchfield, UK	K2523	--
704CA24	--	21-40-83	CMM	NRV	01-Jul-82	07-Apr-11	1	JS31, JS32	Titchfield, UK	K2523	--
705AA17B	--	21-40-61	OM	NRV	13-Apr-66	04-Dec-67	1	SHORTS SC7 SKYVAN	Titchfield, UK	K2523	--
705AA19	--	29-11-05	CMM	INWARD-OUTWARD VENT VALVE	01-Sep-82	18-Mar-11	2	JS31, JS32	Titchfield, UK	K2523	--
705AB15	--	28-20-63+	OM	PR/NRV	01-Apr-66	--	0	SHORTS SC7 SKYVAN	Titchfield, UK	K2523	*EX-SAUNDERS
705BA01	--	28-09-23	OM	PR/NRV	01-Sep-66	--	0	Not Known	Titchfield, UK	K2523	--
705BA10-1	--	28-20-66+	OM	NRV	01-Jun-67	01-Feb-68	4	Not Known	Titchfield, UK	K2523	*EX-SAUNDERS
705BA28	--	28-20-69	OM	NRV	01-Mar-68	--	0	Not Known	Titchfield, UK	K2523	--
706AA08	--	26-1-1	OM	NRV	01-Jul-59	--	0	F27	Titchfield, UK	K2523	--
706AA14B	--	21-40-79	OM	NRV	01-Jul-75	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
706AA16	--	26-1-2	OM	3/4' BSP NRV	01-Jan-61	--	0	F27, F28	Titchfield, UK	K2523	--
706AA19	--	28-20-62+	OM	NRV	01-Mar-66	01-Jun-66	1	SHORTS SC7 SKYVAN	Titchfield, UK	K2523	*EX-SAUNDERS
706BB04	--	SL62	OM	PR/NRV	01-Aug-66	--	0	Not Known	Titchfield, UK	K2523	--
706BB10	--	28-09-21	OM	NRV	01-Jul-62	01-Jan-65	1	Not Known	Titchfield, UK	K2523	--
706BB10-1	--	28-09-21	OM	NRV	01-Jul-62	01-Jan-65	1	Not Known	Titchfield, UK	K2523	--
706BB21	--	28-10-66+	OM	NRV	01-Feb-68	01-Apr-68	1	Not Known	Titchfield, UK	K2523	* EX-SAUNDERS
706DB10	--	28-09-56	OM	NRV	01-Nov-69	--	0	Not Known	Titchfield, UK	K2523	--
708AA12B	--	21-40-72	OM	NRV	01-May-71	--	0	Not Known	Titchfield, UK	K2523	--
708BA22	--	28-20-67+	CMM	NRV	13-Apr-93	13-Apr-93	0	Not Known	Titchfield, UK	K2523	* EX-SNDRS / OUT OF PRINT
708BA24	--	28-20-76	OM	VALVE	01-Nov-66	--	0	Not Known	Titchfield, UK	K2523	--
708CA10-1	--	28-20-73+	OM	NRV	--	01-Jan-71	2	Not Known	Titchfield, UK	K2523	*EX-SAUNDERS
708CA28-1	--	28-20-78	OM	FLAPTYPE NRV	--	01-Jun-87	2	F100, F28, F70	Titchfield, UK	K2523	--
708CA29	--	28-10-71	CMM	INWARD/OUTWARD VENT VALVE	--	01-Jun-87	2	F100, F28, F70	Titchfield, UK	K2523	--
708CA29	--	28-708CA29-1	SB	1in INWARD/OUTWARD VENT VALVE - IMPROVED SPEC.	04-Jul-94	--	0	F100, F70	Titchfield, UK	K2523	--
708CB02	--	28-20-5	OM	PR/NRV	01-Dec-60	06-May-11	1	BAC 1-11, BAe 748	Titchfield, UK	K2523	--
708CB02	--	82-20-2	OM	PR/NRV	28-Feb-67	03-Jun-11	1	BAe 748	Titchfield, UK	K2523	X refers to 28-20-5 &-6
708CB02-2	--	28-20-6+	OM	PR/NRV	01-Jul-62	06-May-11	4	BAe 748	Titchfield, UK	K2523	*EX-SAUNDERS
708CB02-2	--	82-20-2	OM	PR/NRV	28-Feb-67	03-Jun-11	1	BAe 748	Titchfield, UK	K2523	X refers to 28-20-5 &-6
708GA10	--	28-20-73+	OM	NRV	--	01-Jan-71	2	Not Known	Titchfield, UK	K2523	*EX-SAUNDERS
FRS480	--	28-4-3512	SB	PIPE CONNECTORS - IMPROVED LOCKING CIRCLIP	31-Mar-66	--	0	Not Known	Titchfield, UK	K2523	--
FRS480	--	28-7-3989	SB	PIPE CONNECTORS - IMPROVED LOCKING CIRCLIP	22-Mar-67	--	0	Not Known	Titchfield, UK	K2523	--

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRS480	--	SIL-2010-01	SIL	Installation of FRS Couplings	14-Jun-10	--	0	NIMROD, VC10	Titchfield, UK	K2523	--
FRS480	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS495	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS495	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS495	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS525	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS525	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS525	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS546	--	28-09-51	OM	FR PIPE CONNECTORS & DRIP SHIELDS	01-Sep-68	--	0	Not Known	Titchfield, UK	K2523	--
FRS559	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS565	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS565	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS565	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS591	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS594	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS594	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS594	--	28-4-3512	SB	PIPE CONNECTORS - IMPROVED LOCKING CIRCLIP	31-Mar-66	--	0	Not Known	Titchfield, UK	K2523	--
FRS594	--	28-7-3989	SB	PIPE CONNECTORS - IMPROVED LOCKING CIRCLIP	22-Mar-67	--	0	Not Known	Titchfield, UK	K2523	--
FRS594	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS595	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS595	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRS595	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS596	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS596	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS596	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS597	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS597	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS597	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS598	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS614	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS625	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS625	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS625	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS630	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS633	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS633	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS633	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS636	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS648	--	28-09-51	OM	FR PIPE CONNECTORS & DRIP SHIELDS	01-Sep-68	--	0	Not Known	Titchfield, UK	K2523	--
FRS650	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS650	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS650	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRS679	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS679	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS679	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS680	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS709805	--	28-10-01	CMM	Inward Vent Valve	--	04-Jan-17	0	KC46A	Titchfield, UK	K2523	--
FRS709806	--	28-88-36	CMM	SPILL VALVE ASSY	01-Aug-88	04-Mar-14	3	MK 32 POD	Titchfield, UK	K2523	EX FRL MIL SYS
FRS750	--	28-09-10	OM	FR SCREWED LW PIPE CONNECTORS	01-Feb-66	--	0	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
FRS760	--	28-09-10	OM	FR SCREWED LW PIPE CONNECTORS	01-Feb-66	--	0	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
FRS764	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS767	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS768	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS769	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS770	--	28-09-10	OM	FR SCREWED LW PIPE CONNECTORS	01-Feb-66	--	0	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
FRS771	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS779	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS785	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS785	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS785	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS789	--	28-09-51	OM	FR PIPE CONNECTORS & DRIP SHIELDS	01-Sep-68	--	0	Not Known	Titchfield, UK	K2523	--
FRS791	--	28-09-51	OM	FR PIPE CONNECTORS & DRIP SHIELDS	01-Sep-68	--	0	Not Known	Titchfield, UK	K2523	--
FRS805	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRS810	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS818	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS830	--	28-09-51	OM	FR PIPE CONNECTORS & DRIP SHIELDS	01-Sep-68	--	0	Not Known	Titchfield, UK	K2523	--
FRS845	--	28-09-10	OM	FR SCREWED LW PIPE CONNECTORS	01-Feb-66	--	0	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
FRS855	--	28-09-10	OM	FR SCREWED LW PIPE CONNECTORS	01-Feb-66	--	0	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
FRS865	--	28-09-10	OM	FR SCREWED LW PIPE CONNECTORS	01-Feb-66	--	0	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
FRS895	--	28-09-48	OM	FR SCREWED LW PIPE CONNECTOR	01-Jan-69	--	0	Not Known	Titchfield, UK	K2523	--
FRS896	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS897	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS965	--	28-09-51	OM	FR PIPE CONNECTORS & DRIP SHIELDS	01-Sep-68	--	0	Not Known	Titchfield, UK	K2523	--
FRS985	--	28-09-51	OM	FR PIPE CONNECTORS & DRIP SHIELDS	01-Sep-68	--	0	Not Known	Titchfield, UK	K2523	--
FRS990	--	28-09-51	OM	FR PIPE CONNECTORS & DRIP SHIELDS	01-Sep-68	--	0	Not Known	Titchfield, UK	K2523	--
FRS990	--	28-4-3512	SB	PIPE CONNECTORS - IMPROVED LOCKING CIRCLIP	31-Mar-66	--	0	Not Known	Titchfield, UK	K2523	--
FRS990	--	28-7-3989	SB	PIPE CONNECTORS - IMPROVED LOCKING CIRCLIP	22-Mar-67	--	0	Not Known	Titchfield, UK	K2523	--
FRS995H7	--	28-09-11	CMM	PIPE CONNECTORS	01-May-84	10-May-99	1	HAWK	Titchfield, UK	K2523	(5off)
FRS995J7	--	28-09-11	CMM	PIPE CONNECTORS	01-May-84	10-May-99	1	HAWK	Titchfield, UK	K2523	(5off)
HE15159-1	--	HE15159-1	TDS	PRESSURE SWITCH	--	--	0	Not Known	Titchfield, UK	K2523	--
HE7109-3	--	7109-3	TDS	PRESSURE SWITCH	--	--	0	Not Known	Titchfield, UK	K2523	SHORTS
HE7109-3	--	7109-3+	TDS	PRESSURE SWITCH	--	--	0	Not Known	Titchfield, UK	K2523	MISC
HTE12529-2	--	12529-2	TDS	PRESSURE SWITCH	05-Jun-87	--	0	--	Titchfield, UK	K2523	--
HTE1326	--	28-11-11	OM	DRAIN VALVE ASSEMBLY	23-Oct-74	08-Aug-00	1	CONCORDE	Titchfield, UK	K2523	--

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE1420	--	41-40-19	CMM	QD COUPLING PYLON TANK	01-Nov-87	--	0	AM-X	Titchfield, UK	K2523	--
HTE1451-1	--	28-20-03	CMM	ACTUATOR, TWIN MOTOR	03-Jun-82	24-Jun-11	11	BAE 146	Titchfield, UK	K2523	BASIC MANUAL
HTE1501	--	28-20-01	CMM	FUEL PUMP	--	20-Apr-01	2	A310	Titchfield, UK	K2523	--
HTE170021	--	28-23-05	ACMM	VEE-BAND CLAMP	25-Sep-12	25-Sep-12	0	A310, A310-MR11, A319, A320, A321, A330, A340, A340-500, A340-600, BAE 125, BAE 146, F100, ISATE/CAMBANGED	Titchfield, UK	K2523	Re-issued (orig. iss.16-07-91),
HTE190001	--	28-01-11	CMM	TWIN MOTOR ACTUATOR	12-Jan-87	15-Jan-19	18	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
HTE190001	--	HTE190001-28-001	SB	TWIN MOTOR ACTUATOR	30-Mar-90	30-Mar-90	0	A320	Titchfield, UK	K2523	--
HTE190001	--	HTE190001-28-002	SB	TWIN MOTR ACT BEVEL & SPUR GEAR ASSY-BROKEN SPIGOT	29-Apr-96	29-Apr-96	0	A319, A320, A321	Titchfield, UK	K2523	--
HTE190001	--	HTE190001-28-003	SB	TWIN MOTOR ACTUATOR LOCATING DOWEL CHECK PROCEDURE	30-Mar-04	21-Dec-05	1	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	Check procedure for locating dowel
HTE190001-1	--	28-01-11	CMM	TWIN MOTOR ACTUATOR	12-Jan-87	15-Jan-19	18	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
HTE190001-1	--	HTE190001-28-001	SB	TWIN MOTOR ACTUATOR	30-Mar-90	30-Mar-90	0	A320	Titchfield, UK	K2523	--
HTE190001-1	--	HTE190001-28-002	SB	TWIN MOTR ACT BEVEL & SPUR GEAR ASSY-BROKEN SPIGOT	29-Apr-96	29-Apr-96	0	A319, A320, A321	Titchfield, UK	K2523	--
HTE190001-1	--	HTE190001-28-003	SB	TWIN MOTOR ACTUATOR LOCATING DOWEL CHECK PROCEDURE	30-Mar-04	21-Dec-05	1	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	Check procedure for locating dowel
HTE190001-1	--	HTE190001-28-004	SB	HTE TYPE ELECTRICAL ACTUATOR - POSSIBLE MICROSWITCH FAILURE	29-Oct-06	16-Feb-09	1	A319, A320	Titchfield, UK	K2523	--
HTE190001-2	--	28-01-11	CMM	TWIN MOTOR ACTUATOR	12-Jan-87	15-Jan-19	18	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
HTE190001-2	--	HTE190001-28-002	SB	TWIN MOTR ACT BEVEL & SPUR GEAR ASSY-BROKEN SPIGOT	29-Apr-96	29-Apr-96	0	A319, A320, A321	Titchfield, UK	K2523	--
HTE190001-2	--	HTE190001-28-003	SB	TWIN MOTOR ACTUATOR LOCATING DOWEL CHECK PROCEDURE	30-Mar-04	21-Dec-05	1	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	Check procedure for locating dowel
HTE190001-2	--	HTE190001-28-004	SB	HTE TYPE ELECTRICAL ACTUATOR - POSSIBLE MICROSWITCH FAILURE	29-Oct-06	16-Feb-09	1	A319, A320	Titchfield, UK	K2523	--
HTE190007-1	--	28-20-19+	CMM	TWIN MOTOR ACTUATOR	11-Oct-90	16-Jun-08	2	BAE 125	Titchfield, UK	K2523	*EX-HTE
HTE190021	--	28-23-51	CMM	ACTUATOR, TWIN MOTOR	01-May-92	17-Aug-15	8	A319, A319CJ	Titchfield, UK	K2523	*OUT OF PRINT
HTE190021	--	HTE190021-28-1	SB	TWIN MOTOR ACTUATOR - INGRESS OF MOISTURE	29-Sep-95	27-Feb-96	1	A330, A340	Titchfield, UK	K2523	--
HTE190021	--	HTE190021-28-2	SB	TWIN MOTOR ACTUATOR LOCATING DOWEL CHECK PROCEDURE	17-Mar-03	30-Mar-04	1	A319CJ, A330, A340	Titchfield, UK	K2523	--

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE190021	--	HTE190026-24-1	SB	NEW TWIN MOTOR ACTUATOR PN FRH010041	26-Oct-00	--	0	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
HTE190021	--	K2523-24-001	SIL	Obsolete Actuator	03-Oct-16	--	0	A330, A340	Titchfield, UK	K2523	--
HTE190021	--	SIL-PS-1-96	SIL	TWIN MOTOR ACTUATORS - DAMAGED GEAR TEETH	22-Jan-96	--	0	Not Known	Titchfield, UK	K2523	--
HTE190021	--	SIL-PS-2-97	SIL	TWIN MOTOR ACTUATOR - INGRESS OF MOISTURE	19-Jun-97	--	0	A330, A340	Titchfield, UK	K2523	--
HTE190026	--	28-23-51	CMM	ACTUATOR, TWIN MOTOR	01-May-92	17-Aug-15	8	A319, A319CJ	Titchfield, UK	K2523	*OUT OF PRINT
HTE190026	--	HTE190021-28-1	SB	TWIN MOTOR ACTUATOR - INGRESS OF MOISTURE	29-Sep-95	27-Feb-96	1	A330, A340	Titchfield, UK	K2523	--
HTE190026	--	HTE190021-28-2	SB	TWIN MOTOR ACTUATOR LOCATING DOWEL CHECK PROCEDURE	17-Mar-03	30-Mar-04	1	A319CJ, A330, A340	Titchfield, UK	K2523	--
HTE190026	--	HTE190026-24-1	SB	NEW TWIN MOTOR ACTUATOR PN FRH010041	26-Oct-00	--	0	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
HTE190026	--	K2523-24-001	SIL	Obsolete Actuator	03-Oct-16	--	0	A330, A340	Titchfield, UK	K2523	--
HTE190026	--	SIL-PS-1-96	SIL	TWIN MOTOR ACTUATORS - DAMAGED GEAR TEETH	22-Jan-96	--	0	Not Known	Titchfield, UK	K2523	--
HTE190026	--	SIL-PS-2-97	SIL	TWIN MOTOR ACTUATOR - INGRESS OF MOISTURE	19-Jun-97	--	0	A330, A340	Titchfield, UK	K2523	--
HTE1940	--	38-12-17	OM	3 PORT SOV	01-Jan-77	--	0	Not Known	Titchfield, UK	K2523	FAXED FROM BAE (LOST)
HTE1943	--	25-30-62	CMM	3/8 INCH BALL VALVE	23-Jan-73	--	0	Not Known	Titchfield, UK	K2523	--
HTE1956	--	32-40-03	CMM	FUEL FILLER CAP	31-Jul-84	--	0	JAGUAR	Titchfield, UK	K2523	--
HTE1957	--	28-10-15+	CMM	2.5 INCH FUEL CAP	25-Mar-86	--	0	Not Known	Titchfield, UK	K2523	*EX-HTE
HTE1972	--	32-40-03	CMM	FUEL FILLER CAP	31-Jul-84	--	0	JAGUAR	Titchfield, UK	K2523	--
HTE200000	--	29-10-32+	CMM	ACTUATOR, SINGLE MOTOR	31-Oct-86	22-Apr-11	6	BAe ATP	Titchfield, UK	K2523	--
HTE200002	--	28-01-10	CMM	ACTUATOR, SINGLE MOTOR	01-Sep-88	25-Feb-20	18	A310, A318, A319, A320, A321, A340	Titchfield, UK	K2523	--
HTE200002	--	HTE200002-28-001	SB	MODIFICATION OF SINGLE MOTOR ACTUATOR	13-Jan-92	08-Mar-02	2	A310, A319, A320, A321, A340	Titchfield, UK	K2523	--
HTE200002	--	HTE200002-28-002	SB	Actuator - Microswitch - Cracked Plain Lever	27-Jul-09	--	0	A320	Titchfield, UK	K2523	--
HTE200002-1	--	28-01-10	CMM	ACTUATOR, SINGLE MOTOR	01-Sep-88	25-Feb-20	18	A310, A318, A319, A320, A321, A340	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE200002-1	--	HTE200002-28-001	SB	MODIFICATION OF SINGLE MOTOR ACTUATOR	13-Jan-92	08-Mar-02	2	A310, A319, A320, A321, A340	Titchfield, UK	K2523	--
HTE200005	--	28-20-28+	CMM	ACTUATOR, SINGLE MOTOR	29-Sep-86	23-Dec-14	5	BAe ATP, JS61	Titchfield, UK	K2523	--
HTE200007	--	29-00-03	CMM	ACTUATOR, SINGLE MOTOR	25-Oct-89	--	0	IAI VARIOUS AIRCRAFT	Titchfield, UK	K2523	--
HTE200018	--	29-00-02	CMM	ACTUATOR, SINGLE MOTOR	03-Jul-89	27-Oct-14	2	Not Known	Titchfield, UK	K2523	--
HTE200024	--	36-10-10+	CMM	OUTLET DUCT FLAP ACTUATOR	27-Nov-89	06-Jan-15	8	JS31, JS32	Titchfield, UK	K2523	INCL.ACTUATOR HTE200024
HTE200025	--	28-00-03	CMM	ACTUATOR, SINGLE MOTOR	--	07-Sep-05	3	Not Known	Titchfield, UK	K2523	--
HTE200031	--	29-00-11	CMM	ACTUATOR, SINGLE MOTOR	17-Jan-92	12-May-09	1	Not Known	Titchfield, UK	K2523	--
HTE200032	--	29-10-06	CMM	ACTUATOR, SINGLE MOTOR	20-Feb-92	18-Mar-11	4	JS41	Titchfield, UK	K2523	--
HTE200033	--	21-00-05+	CMM	ACTUATOR, SINGLE MOTOR	30-Oct-90	--	0	Not Known	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE200036	--	24-09-57	CMM	ROTARY ACTUATOR	19-Dec-94	17-Oct-14	4	EH101	Titchfield, UK	K2523	--
HTE200045	--	24-09-59	CMM	ROTARY ACTUATOR	10-Jan-95	20-Feb-96	1	N250 (LUCAS)	Titchfield, UK	K2523	--
HTE200-3MK3	--	HTE200-3	OM	QUICK RELEASE AIR START COUPLING	--	--	0	Not Known	Titchfield, UK	K2523	--
HTE200-3MK4	--	HTE200-3	OM	QUICK RELEASE AIR START COUPLING	--	--	0	Not Known	Titchfield, UK	K2523	--
HTE210005	--	21-60-11	CMM	ACTUATOR, SINGLE MOTOR	05-May-92	05-Jun-08	4	LYNX	Titchfield, UK	K2523	--
HTE210005-1	--	21-60-11	CMM	ACTUATOR, SINGLE MOTOR	05-May-92	05-Jun-08	4	LYNX	Titchfield, UK	K2523	--
HTE210007	--	28-00-10	CMM	ACTUATOR, SINGLE MOTOR	01-Oct-88	24-Dec-14	6	AM-X	Titchfield, UK	K2523	--
HTE210009	--	28-00-10	CMM	ACTUATOR, SINGLE MOTOR	01-Oct-88	24-Dec-14	6	AM-X	Titchfield, UK	K2523	--
HTE210010	--	28-00-10	CMM	ACTUATOR, SINGLE MOTOR	01-Oct-88	24-Dec-14	6	AM-X	Titchfield, UK	K2523	--
HTE210011	--	28-00-10	CMM	ACTUATOR, SINGLE MOTOR	01-Oct-88	24-Dec-14	6	AM-X	Titchfield, UK	K2523	--
HTE210014	--	29-10-09	CMM	ACTUATOR, SINGLE MOTOR	15-May-87	27-Apr-22	9	BAE 146	Titchfield, UK	K2523	--
HTE210014	--	HTE9479-29-002	SB	ELECTRICALLY ACTUATED BALL VALVE	27-Nov-86	27-Jan-87	2	BAE 146	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE210014	--	HTE9490-32-002	SB	ELECTRICALLY ACTUATED BALL VALVE	27-Nov-86	04-Mar-87	3	BAE 146	Titchfield, UK	K2523	--
HTE210014	--	HTE9531-29-003	SB	HYDRAULIC PUMP ISOLATION VALVE	27-Nov-86	27-Jan-87	2	BAE 146	Titchfield, UK	K2523	--
HTE210014	--	HTE9635-29-001	SB	ELECTRICALLY ACTUATED BALL VALVE	27-Nov-86	27-Jan-87	2	BAE 146	Titchfield, UK	K2523	--
HTE210014	--	SIL-PS-6-96	SIL	SINGLE MOTOR ACTUATOR - ALTVE ELECTRICAL CONNECTOR	19-Sep-96	20-Jun-97	1	BAE 146	Titchfield, UK	K2523	--
HTE210016-1	--	21-20-09	CMM	ACTUATOR, SINGLE MOTOR	07-Apr-92	22-May-08	2	JAS 39	Titchfield, UK	K2523	--
HTE210021	--	28-30-03	CMM	SINGLE MOTOR ACTUATOR	28-Jul-94	09-May-16	5	EH101	Titchfield, UK	K2523	--
HTE210033	--	29-10-21+	CMM	SINGLE MOTOR ACTUATOR	16-Oct-92	16-Jul-13	7	F100	Titchfield, UK	K2523	--
HTE210035	--	21-31-02	CMM	ACTUATOR, SINGLE MOTOR	22-Oct-91	02-Jul-08	2	Not Known	Titchfield, UK	K2523	--
HTE210039	--	28-20-34+	CMM	ACTUATOR, SINGLE MOTOR	13-May-91	30-Sep-04	2	F50	Titchfield, UK	K2523	*EX-HTE
HTE210043	--	24-09-58	CMM	FOUR POSITION ACTUATOR	04-Nov-94	06-Jan-09	4	EH101	Titchfield, UK	K2523	--
HTE210043-1	--	24-09-58	CMM	FOUR POSITION ACTUATOR	04-Nov-94	06-Jan-09	4	EH101	Titchfield, UK	K2523	--
HTE210043-1	--	HTE210043-24-001	SB	--	15-Mar-05	--	0	EH101	Titchfield, UK	K2523	DRAFT ONLY
HTE210045	--	75-20-02	CMM	ACTUATOR, SINGLE MOTOR	10-Mar-93	25-Mar-08	4	JAS 39	Titchfield, UK	K2523	--
HTE210047	--	24-09-60	CMM	ROTARY ACTUATOR	06-Mar-95	17-Apr-08	3	EH101	Titchfield, UK	K2523	--
HTE210048	--	24-09-61	CMM	ROTARY ACTUATOR	07-Mar-95	27-Nov-08	4	EH101	Titchfield, UK	K2523	--
HTE211/3/A	--	80-10-03	CMM	3 INCH AIR START NIPPLE WITH NRV	03-Mar-67	--	0	Not Known	Titchfield, UK	K2523	--
HTE220005	--	21-60-04	CMM	ACTUATOR	19-Nov-86	04-Mar-08	4	JAS 39	Titchfield, UK	K2523	--
HTE220016	--	21-60-04	CMM	ACTUATOR	19-Nov-86	04-Mar-08	4	JAS 39	Titchfield, UK	K2523	--
HTE220017	--	21-60-05	CMM	MODULATING ACTUATOR	08-Nov-91	16-May-08	4	JAS 39	Titchfield, UK	K2523	--
HTE220018	--	21-60-04	CMM	ACTUATOR	19-Nov-86	04-Mar-08	4	JAS 39	Titchfield, UK	K2523	--
HTE220018	--	HTE220018-21-1	SB	ACTUATOR- IMPROVED MOTOR AND POTENTIOMETER DRIVE C	06-Oct-97	09-Feb-98	1	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE220019	--	21-60-05	CMM	MODULATING ACTUATOR	08-Nov-91	16-May-08	4	JAS 39	Titchfield, UK	K2523	--
HTE220019	--	HTE220019-21-1	SB	ACTUATOR- IMPROVED MOTOR AND POTENTIOMETER DRIVE C	06-Oct-97	09-Feb-98	1	Not Known	Titchfield, UK	K2523	--
HTE230008	--	28-23-57	CMM	SCAVENGE PUMP	20-Dec-96	--	0	LEARJET 45	Titchfield, UK	K2523	--
HTE230009	--	28-23-56	CMM	FUEL EJECTOR PUMP	20-Dec-96	--	0	LEARJET 45	Titchfield, UK	K2523	--
HTE230011	--	28-25-13	CMM	TRANSFER JET PUMP	05-Sep-94	--	0	KT-1	Titchfield, UK	K2523	--
HTE230012	--	28-25-14	CMM	DELIVERY JET PUMP	08-Sep-94	--	0	KT-1	Titchfield, UK	K2523	--
HTE250003	--	21-20-06	CMM	ACTUATED BUTTERFLY VALVE	30-Mar-92	04-May-00	3	JAS 39	Titchfield, UK	K2523	--
HTE250019	--	21-00-06	CMM	CABIN EXHAUST VALVE	17-Aug-90	07-Apr-11	1	JS31, JS32	Titchfield, UK	K2523	--
HTE250034	--	21-20-08	CMM	AIR BOOST VALVE	26-Apr-89	07-Apr-11	1	BAE 146	Titchfield, UK	K2523	--
HTE250058	--	21-30-20	CMM	5.5 IN. EMERGENCY SOV	09-Jul-90	--	0	BAE 125	Titchfield, UK	K2523	--
HTE250072	--	21-40-76	CMM	2in ACTUATED BUTTERFLY VALVE	28-Jun-96	07-Apr-11	6	BAE 146, HAWKER800XP, HS 125	Titchfield, UK	K2523	--
HTE250072	--	HTE250072-21-1	SB	Modify HTE250072 to HTE250072-1	30-Sep-05	--	0	HAWKER800XP	Titchfield, UK	K2523	--
HTE250072-1	--	21-40-76	CMM	2in ACTUATED BUTTERFLY VALVE	28-Jun-96	07-Apr-11	6	BAE 146, HAWKER800XP, HS 125	Titchfield, UK	K2523	--
HTE250072-1	--	HTE250072-21-1	SB	Modify HTE250072 to HTE250072-1	30-Sep-05	--	0	HAWKER800XP	Titchfield, UK	K2523	--
HTE250076	--	21-40-10	CMM	ACTUATED BUTTERFLY VALVE	12-Jul-91	19-Dec-14	7	BAE 146	Titchfield, UK	K2523	--
HTE250076-1	--	21-40-10	CMM	ACTUATED BUTTERFLY VALVE	12-Jul-91	19-Dec-14	7	BAE 146	Titchfield, UK	K2523	--
HTE250076-1	--	HTE250076-21-1	SB	2 1/2IN MOT. BUTTERFLY VALVE - EXCESSIVE LEAKAGE	12-Sep-96	--	0	BAE 146	Titchfield, UK	K2523	--
HTE250078	--	21-31-01	CMM	ACTUATED 63MM ECS SOV	18-Oct-91	03-Dec-08	2	EFA	Titchfield, UK	K2523	--
HTE250087	--	21-20-06	CMM	ACTUATED BUTTERFLY VALVE	30-Mar-92	04-May-00	3	JAS 39	Titchfield, UK	K2523	--
HTE250088	--	21-00-27	CMM	ACTUATED BUTTERFLY VALVE	01-Oct-90	07-Apr-08	2	BAE 125, HAWKER1000XP	Titchfield, UK	K2523	--
HTE250095	--	21-00-06+	CMM	ACTUATED BUTTERFLY VALVE	30-Oct-90	--	0	JAGUAR	Titchfield, UK	K2523	DUPLICATE ATA NO.

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE250102	--	21-30-01	CMM	2.5 INCH ACTUATED BUTTERFLY VALVE	31-Mar-93	--	0	BAE 125	Titchfield, UK	K2523	--
HTE250110	--	21-20-10	CMM	ACTUATED BUTTERFLY VALVE	19-Feb-92	07-Apr-11	3	BAE 146	Titchfield, UK	K2523	--
HTE250113-1	--	21-20-05	CMM	ELECTRI ACTUATED ISOLATION VALVE	03-May-94	18-Apr-16	2	A300, A300-400, A300-600, A310	Titchfield, UK	K2523	--
HTE250113-2	--	21-20-05	CMM	ELECTRI ACTUATED ISOLATION VALVE	03-May-94	18-Apr-16	2	A300, A300-400, A300-600, A310	Titchfield, UK	K2523	--
HTE250114	--	75-20-01+	CMM	1 INCH ACTUATED BUTTERFLY VALVE	10-Mar-93	12-Mar-04	2	JAS 39	Titchfield, UK	K2523	*EX-HTE
HTE250130	--	21-20-12	CMM	ELEC ACTUATED ECS LP SHUT OFF VALVE	01-Mar-95	29-Mar-99	2	EH101	Titchfield, UK	K2523	--
HTE250132	--	21-20-17	CMM	ECS CHANGEOVER VALVE	15-Oct-98	--	0	EH101	Titchfield, UK	K2523	--
HTE250133	--	21-20-13	CMM	ELEC ACTUATED ECS CHANGE OVER VALVE	08-Mar-95	03-Feb-03	2	EH101	Titchfield, UK	K2523	--
HTE250138	--	38-31-77	CMM	ELECT. ACT. 63MM AIR SOV	17-Oct-94	30-May-03	2	AOA GTG - TOILET SYS	Titchfield, UK	K2523	Paper and disk format.
HTE250138-1	--	38-31-77	CMM	ELECT. ACT. 63MM AIR SOV	17-Oct-94	30-May-03	2	AOA GTG - TOILET SYS	Titchfield, UK	K2523	Paper and disk format.
HTE261	--	80-10-02	CMM	PRESSURE CAP	06-May-68	--	0	HS 125	Titchfield, UK	K2523	--
HTE262	--	80-10-01+	CMM	AIR START NIPPLE WITH NRV	06-May-68	--	0	Not Known	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE262	--	HTE.SB.80.1	SB	AIR START NRV - INTRO OF IMPROVED HINGE PIN	01-Nov-71	--	0	Not Known	Titchfield, UK	K2523	--
HTE2672	--	A129-001M	CMM	CARBON FIBRE COMPOSITE CONTROL TUBE	01-Mar-90	--	0	Not Known	Titchfield, UK	K2523	--
HTE2673	--	A129-002M	CMM	CARBON FIBRE COMPOSITE CONTROL TUBE	01-Mar-90	--	0	Not Known	Titchfield, UK	K2523	--
HTE2674	--	A129-003M	CMM	CARBON FIBRE COMPOSITE CONTROL TUBE	01-Mar-90	--	0	Not Known	Titchfield, UK	K2523	--
HTE2675	--	A129-004M	CMM	CARBON FIBRE COMPOSITE CONTROL TUBE	01-Mar-90	--	0	Not Known	Titchfield, UK	K2523	--
HTE2703	--	28-10-14+	CMM	FUEL FILLER CAP	25-Mar-86	--	0	Not Known	Titchfield, UK	K2523	*EX-HTE
HTE2705	--	82-20-01	CMM	ACTUATED BALL VALVE	08-Dec-76	--	0	Not Known	Titchfield, UK	K2523	--
HTE2915	--	29-11-03+	CMM	ACT. CABIN AIR SOV	01-Aug-84	--	0	Not Known	Titchfield, UK	K2523	*EX-HTE
HTE2932	--	28-01-13	CMM	FUEL SOV	24-Oct-85	14-Jul-09	3	F50	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE2991	--	28-20-27+	CMM	FUEL SERVICE COCK	01-Aug-86	11-Feb-15	3	BAe ATP	Titchfield, UK	K2523	--
HTE2992	--	28-20-27+	CMM	FUEL SERVICE COCK	01-Aug-86	11-Feb-15	3	BAe ATP	Titchfield, UK	K2523	--
HTE2993	--	28-20-27+	CMM	FUEL SERVICE COCK	01-Aug-86	11-Feb-15	3	BAe ATP	Titchfield, UK	K2523	--
HTE2994	--	28-20-31+	CMM	ACT. LP COCK	02-May-91	22-Apr-11	5	BAe ATP	Titchfield, UK	K2523	*EX-HTE
HTE310002	--	34-00-01	TDS	STATIC DRAIN VALVE	09-Jul-90	22-Apr-11	2	JS41	Titchfield, UK	K2523	--
HTE310003	--	34-00-02	TDS	STATIC DRAIN VALVE	09-Jul-90	22-Apr-11	2	JS31	Titchfield, UK	K2523	--
HTE310004	--	34-00-03	TDS	STATIC DRAIN VALVE	09-Jul-90	22-Apr-11	2	JS31, JS32	Titchfield, UK	K2523	--
HTE310016	--	28-25-15	CMM	FUEL TANK DRAIN VALVE	12-Sep-94	--	0	KT-1, TUCANO	Titchfield, UK	K2523	--
HTE310018	--	28-00-02	CMM	FUEL TANK WATER DRAIN VAL.	20-Mar-89	22-Apr-11	1	BAe ATP	Titchfield, UK	K2523	--
HTE310019	--	28-25-57	CMM	REFUEL GALLERY AIR INLET VALVE	--	10-Aug-07	4	A319, A320	Titchfield, UK	K2523	--
HTE310020	--	28-25-73	CMM	DEPRESSURISING VALVE	19-Mar-91	--	0	A330, A340	Titchfield, UK	K2523	--
HTE310021	--	28-25-57	CMM	REFUEL GALLERY AIR INLET VALVE	--	10-Aug-07	4	A319, A320	Titchfield, UK	K2523	--
HTE310021-1	--	28-25-57	CMM	REFUEL GALLERY AIR INLET VALVE	--	10-Aug-07	4	A319, A320	Titchfield, UK	K2523	--
HTE310028	--	28-25-44	CMM	FUEL DRAIN VALVE	20-Jul-87	28-Jun-12	3	A319, A320, A321	Titchfield, UK	K2523	--
HTE361-1	--	30-00-2	CMM	4.5 INCH DOUBLE FLAP NRV	01-Oct-68	--	0	Not Known	Titchfield, UK	K2523	--
HTE363-1	--	21-20-2	CMM	3 INCH DOUBLE FLAP NRV	01-Oct-68	25-May-74	1	Not Known	Titchfield, UK	K2523	--
HTE363-1	--	HTE.SB.80.2	SB	INTRODUCTION OF IMPROVED HINGE PIN	07-Jan-74	--	0	Not Known	Titchfield, UK	K2523	--
HTE363-2	--	21-20-2	CMM	3 INCH DOUBLE FLAP NRV	01-Oct-68	25-May-74	1	Not Known	Titchfield, UK	K2523	--
HTE365	--	80-10-01	CMM	3 INCH DOUBLE FLAP NRV	06-Apr-68	--	0	Not Known	Titchfield, UK	K2523	--
HTE365	--	HTE.SB.80.3	SB	INTRODUCTION OF CLEARANCE RADIUS OF VALVE FLAPS	23-Apr-74	--	0	Not Known	Titchfield, UK	K2523	--
HTE365-4	--	80-10-08	CMM	DOUBLE FLAP NRV	01-Oct-82	07-May-13	2	NIMROD	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE366-1	--	80-10-06	CMM	4 INCH DOUBLE FLAP NRV	01-Feb-69	--	0	Not Known	Titchfield, UK	K2523	--
HTE366-2	--	80-10-06	CMM	4 INCH DOUBLE FLAP NRV	01-Feb-69	--	0	Not Known	Titchfield, UK	K2523	--
HTE366-2	--	HTE.SB.80.2	SB	INTRODUCTION OF IMPROVED HINGE PIN	07-Jan-74	--	0	Not Known	Titchfield, UK	K2523	--
HTE370015-1	--	28-23-55	CMM	SPPR Adaptor	15-Oct-96	22-Feb-00	1	LEARJET 45	Titchfield, UK	K2523	--
HTE390143	--	A129-004M	CMM	CARBON FIBRE COMPOSITE CONTROL TUBE	01-Mar-90	--	0	Not Known	Titchfield, UK	K2523	--
HTE390160	--	A129-003M	CMM	CARBON FIBRE COMPOSITE CONTROL TUBE	01-Mar-90	--	0	Not Known	Titchfield, UK	K2523	--
HTE390178	--	A129-002M	CMM	CARBON FIBRE COMPOSITE CONTROL TUBE	01-Mar-90	--	0	Not Known	Titchfield, UK	K2523	--
HTE400001	--	29-11-14	TDS	1/4 INWARD VENT NRV	01-Aug-86	18-Mar-11	2	BAe ATP	Titchfield, UK	K2523	--
HTE400003	--	29-10-47	CMM	1/2 HP NRV	01-Aug-86	18-Mar-11	3	BAe ATP	Titchfield, UK	K2523	--
HTE400004	--	29-00-08	TDS	1/4 LINE NRV	09-Jul-90	06-May-11	2	JS31, JS32, JS41	Titchfield, UK	K2523	--
HTE400004-1	--	29-00-08	TDS	1/4 LINE NRV	09-Jul-90	06-May-11	2	JS31, JS32, JS41	Titchfield, UK	K2523	--
HTE400005	--	29-00-09	CMM	3/8 LINE NRV	09-Jul-90	06-May-11	2	JS31, JS32, JS41	Titchfield, UK	K2523	--
HTE400005-1	--	29-00-09	CMM	3/8 LINE NRV	09-Jul-90	06-May-11	2	JS31, JS32, JS41	Titchfield, UK	K2523	--
HTE400033	--	38-10-13	CMM	1/4 NRV	01-Aug-86	13-May-11	1	BAe ATP	Titchfield, UK	K2523	--
HTE400062	--	29-10-05	CMM	NRV	10-May-76	03-Sep-96	2	C-23A (MILITARY 330), C-23B (MILITARY 360), SD-330, SD-360, SHERPA/UTT	Titchfield, UK	K2523	--
HTE400064	--	28-00-06	TDS	CHECK TEE VALVE	09-Jul-90	22-Apr-11	1	JS31, JS32, JS41	Titchfield, UK	K2523	--
HTE400071	--	28-00-09	TDS	ICE PROTECTION NRV	09-Jul-90	22-Apr-11	1	JS31, JS32	Titchfield, UK	K2523	--
HTE400089-1	--	79-20-03	ACMM	SIGHT GLASS NRV	29-Apr-96	--	0	LYNX	Titchfield, UK	K2523	--
HTE400096	--	29-00-05	CMM	3/8 IN. LINE NRV	09-Jan-91	--	0	BAE 125	Titchfield, UK	K2523	--
HTE400097-1	--	29-00-04	CMM	1/4 IN. LINE NRV	17-Apr-90	--	0	BAE 125	Titchfield, UK	K2523	--
HTE400098-1	--	29-00-06	CMM	1/4 INCH LINE NRV	17-Apr-90	--	0	BAE 125	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE400115	--	26-20-01	CMM	CHECK VALVE	08-Feb-91	20-Feb-19	5	A319, A320, A321, A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
HTE400117	--	36-10-10	CMM	3/4 INCH CHECK VALVE	18-Feb-91	29-Mar-02	1	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
HTE400127	--	38-40-02	CMM	3/8 INCH NRV	06-Nov-92	10-May-94	1	A330, A340, A340-600	Titchfield, UK	K2523	--
HTE400179	--	38-10-15	CMM	WATER/WASTE NON-RETURN VALVE	08-Mar-93	21-Mar-06	1	A330, A340, A380	Titchfield, UK	K2523	--
HTE400180	--	38-40-02	CMM	3/8 INCH NRV	06-Nov-92	10-May-94	1	A330, A340, A340-600	Titchfield, UK	K2523	--
HTE400200	--	36-10-15	CMM	NON-RETURN VALVE	01-Dec-95	13-May-11	2	BAE 146	Titchfield, UK	K2523	--
HTE400207	--	38-40-02	CMM	3/8 INCH NRV	06-Nov-92	10-May-94	1	A330, A340, A340-600	Titchfield, UK	K2523	--
HTE400215	--	28-25-16	CMM	1/4IN CHECK VALVE & RESTRICTOR	30-Aug-94	--	0	KT-1	Titchfield, UK	K2523	--
HTE400216	--	28-25-17	CMM	1/4 IN CHECK VALVE & RESTRICTOR	30-Aug-94	--	0	KT-1	Titchfield, UK	K2523	--
HTE400217	--	28-25-18	CMM	3/4IN CHECK VALVE	30-Aug-94	--	0	KT-1	Titchfield, UK	K2523	--
HTE400218	--	28-25-19	CMM	1/2IN CHECK VALVE	24-Aug-94	--	0	KT-1	Titchfield, UK	K2523	--
HTE4100-001	--	HTE4100-001	OM	2 1/2 IN DOUBLE FLAP NRV	--	--	0	Not Known	Titchfield, UK	K2523	--
HTE410012	--	29-00-01	TDS	LINE NRV	03-Jun-90	06-May-11	1	JS31, JS32	Titchfield, UK	K2523	--
HTE4119	--	36-10-02	CMM	3 INCH DOUBLE FLAP NRV	--	10-May-74	2	Not Known	Titchfield, UK	K2523	--
HTE4119	--	HTE.SB.80.2	SB	INTRODUCTION OF IMPROVED HINGE PIN	07-Jan-74	--	0	Not Known	Titchfield, UK	K2523	--
HTE4119	--	HTE.SB.80.3	SB	INTRODUCTION OF CLEARANCE RADIUS OF VALVE FLAPS	23-Apr-74	--	0	Not Known	Titchfield, UK	K2523	--
HTE4119-1	--	36-10-02	CMM	3 INCH DOUBLE FLAP NRV	--	10-May-74	2	Not Known	Titchfield, UK	K2523	--
HTE4138	--	80-10-07	CMM	DOUBLE FLAP NRV	17-Mar-71	01-Oct-75	4	TAY ENGINE (F100 AC)	Titchfield, UK	K2523	--
HTE4168	--	75-00-07	CMM	63MM DOUBLE FLAP NON RETURN VALVE	17-Feb-03	--	0	HS 125	Titchfield, UK	K2523	(Based on TMRC 92-90-29)
HTE4172	--	36-14-13	OM	DOUBLE FLAP NRV	01-Aug-72	--	0	Not Known	Titchfield, UK	K2523	--
HTE4178	--	28-12-72	CMM	DOUBLE FLAP NRV	23-Nov-76	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE4181	--	21-20-01+	CMM	4 INCH DOUBLE FLAP NRV	29-Aug-74	--	0	Not Known	Titchfield, UK	K2523	*EX-HTE
HTE4187	--	21-10-01+	CMM	2 IN. DOUBLE FLP. NRV	27-Jun-74	--	0	SD-330, SD-360	Titchfield, UK	K2523	*EX-HTE
HTE4194	--	36-10-03	CMM	6 INCH NRV	29-Aug-75	24-Jun-98	1	BOEING 747	Titchfield, UK	K2523	--
HTE4195	--	80-10-10	CMM	NRV	01-Nov-76	01-Feb-86	1	SPEY, TAY ENGINE (F100 AC)	Titchfield, UK	K2523	--
HTE420000	--	29-11-17	TDS	PRV	01-Aug-86	10-Jun-11	1	BAe ATP	Titchfield, UK	K2523	--
HTE420003	--	29-10-41	TDS	1/2 FULL FLOW PRV	01-Aug-86	18-Mar-11	2	BAe ATP	Titchfield, UK	K2523	--
HTE420003-1	--	29-10-41	TDS	1/2 FULL FLOW PRV	01-Aug-86	18-Mar-11	2	BAe ATP	Titchfield, UK	K2523	--
HTE420014	--	28-00-05	CMM	THERMAL RELIEF VALVE	31-May-90	22-Apr-11	1	JS31, JS32	Titchfield, UK	K2523	--
HTE420015	--	36-10-08	CMM	PRESSURE RELIEF VALVE	01-Apr-86	13-May-11	1	BAE 146	Titchfield, UK	K2523	--
HTE420026	--	28-20-32+	CMM	PRESSURE RELIEF VALVE	20-May-91	--	0	A310	Titchfield, UK	K2523	*EX-HTE
HTE420043	--	29-10-17	CMM	PRV	19-Apr-88	22-Apr-11	2	BAE 146	Titchfield, UK	K2523	--
HTE420044	--	28-16-41	CMM	PRESS HOLDING VALVE	20-Jul-87	30-Sep-03	2	A319, A320	Titchfield, UK	K2523	--
HTE420063-2	--	32-00-10	CMM	1/4 IN. LINE PRV	09-Jan-91	--	0	BAE 125	Titchfield, UK	K2523	--
HTE420074	--	HTE420074-AM-X-001	SB	AM-X WING TANK PRESSURE RELIEF VALVE	21-Mar-91	--	0	AM-X	Titchfield, UK	K2523	--
HTE420079	--	38-40-03	CMM	RELIEF VALVE	10-Jun-91	13-May-11	2	BAE 146	Titchfield, UK	K2523	--
HTE420080	--	28-26-01	CMM	PRESSURE HOLDING VALVE	22-Mar-91	--	0	A340	Titchfield, UK	K2523	--
HTE420086	--	28-16-02	CMM	PRESSURE HOLDING VALVE	09-Nov-92	21-Aug-17	4	A321	Titchfield, UK	K2523	--
HTE4273	--	HTE4273-001	SB	4 INCH NRV CONVERSION	09-May-89	--	0	Not Known	Titchfield, UK	K2523	--
HTE4328-001	--	38-41-11	OM	NON RETURN VALVE ASSEMBLY	17-Aug-73	--	0	CONCORDE	Titchfield, UK	K2523	--
HTE4344-1	--	36-10-07	CMM	SINGLE FLAP NRV	--	13-May-11	7	BAE 146	Titchfield, UK	K2523	--
HTE4345-1	--	36-10-07	CMM	SINGLE FLAP NRV	--	13-May-11	7	BAE 146	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE4345-2	--	36-10-07	CMM	SINGLE FLAP NRV	--	13-May-11	7	BAE 146	Titchfield, UK	K2523	--
HTE4350	--	28-23-61	ACMM	1/4 INCH SINGLE FLAP NRV	30-Jun-07	19-Sep-12	1	BAE 125, HAWKER800XP, HS 125	Titchfield, UK	K2523	--
HTE4373-1	--	36-10-05	CMM	NRV	--	22-Apr-11	2	BAE 146	Titchfield, UK	K2523	--
HTE4373-1	--	HTE4373-36-1	SB	PNEUMATIC - NON-RETURN VALVE - REPLACE VALVE FLAPS	08-Feb-88	--	0	BAE 146	Titchfield, UK	K2523	--
HTE4373-2	--	36-10-05	CMM	NRV	--	22-Apr-11	2	BAE 146	Titchfield, UK	K2523	--
HTE4373-2	--	HTE4373-36-1	SB	PNEUMATIC - NON-RETURN VALVE - REPLACE VALVE FLAPS	08-Feb-88	--	0	BAE 146	Titchfield, UK	K2523	--
HTE4389	--	28-00-08	TDS	FUEL SYSTEM NRV	09-Jul-90	22-Apr-11	1	JS31	Titchfield, UK	K2523	--
HTE4390	--	29-00-07	TDS	LINE NRV	05-Jun-90	06-May-11	1	JS31, JS32	Titchfield, UK	K2523	--
HTE4393-1	--	21-30-02+	CMM	63MM NON-RETURN VALVE	26-Apr-88	--	0	JAS 39	Titchfield, UK	K2523	*EX-HTE
HTE440007	--	36-14-01	CMM	DOUBLE FLAP NRV	26-May-86	01-Nov-07	2	F100, F70	Titchfield, UK	K2523	--
HTE440021-1	--	75-00-05	CMM	4.875 INCH DOUBLE FLAP NRV	29-Mar-93	25-Sep-08	5	RB211-524	Titchfield, UK	K2523	--
HTE440021-1	--	HTE440021-1-SB-001	SB	MODIFICATION OF 4.875 INCH DOUBLE FLAP NON-RETURN VALVE	12-Jun-91	29-Jun-98	2	RB211	Titchfield, UK	K2523	--
HTE440021-2	--	75-00-05	CMM	4.875 INCH DOUBLE FLAP NRV	29-Mar-93	25-Sep-08	5	RB211-524	Titchfield, UK	K2523	--
HTE440021-2	--	HTE440021-1-SB-001	SB	MODIFICATION OF 4.875 INCH DOUBLE FLAP NON-RETURN VALVE	12-Jun-91	29-Jun-98	2	RB211	Titchfield, UK	K2523	--
HTE440022-1	--	21-20-08+	CMM	50MM NON-RETURN VALVE	26-Apr-88	14-Mar-95	1	JAS 39	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE440022-4	--	21-20-08+	CMM	50MM NON-RETURN VALVE	26-Apr-88	14-Mar-95	1	JAS 39	Titchfield, UK	K2523	DUPLICATE ATA NO.
0733094	--	28-10-60	CMM	WATER/FUEL DRAIN VALVES	12-Jun-80	31-Mar-11	6	BAE 146	Titchfield, UK	K2523	--
0733095	--	0733095-28-2	SB	FUEL SYSTEM WATER DRAIN VALVES - SEALS SPLITTING	--	01-Mar-89	1	BAE 146	Titchfield, UK	K2523	--
0733095	--	0733095-28-3	SB	WATER/FUEL DRAIN VALVE - INTRODUCTION OF NEW WATER DRAIN VALVE	10-Sep-02	--	0	BAE 146	Titchfield, UK	K2523	--
0733095	--	28-10-60	CMM	WATER/FUEL DRAIN VALVES	12-Jun-80	31-Mar-11	6	BAE 146	Titchfield, UK	K2523	--
0733095-1	--	0733095-28-3	SB	WATER/FUEL DRAIN VALVE - INTRODUCTION OF NEW WATER DRAIN VALVE	10-Sep-02	--	0	BAE 146	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
0733095-1	--	28-10-60	CMM	WATER/FUEL DRAIN VALVES	12-Jun-80	31-Mar-11	6	BAE 146	Titchfield, UK	K2523	--
0733120	--	0728365-28-1	SB	WING CONN. & WATER/FUEL DRAIN VALVE LARGER HOLES	01-Jul-84	--	0	Not Known	Titchfield, UK	K2523	--
0733215	--	0733215-28-1	SB	WATER DRAIN VALVE-LIGHTNING SAFE - LEAKAGE PROBLEM	04-Jul-95	--	0	A330, A340	Titchfield, UK	K2523	--
0733215	--	0733215-28-2	SB	WATER DRAIN VALVE-LIGHTNING SAFE - CRACKED INSERT	21-Nov-95	--	0	A330, A340	Titchfield, UK	K2523	--
0733215	--	28-11-42	CMM	WATER DRAIN VALVE (INDIRECT)	01-Jan-92	20-Apr-98	3	A330, A340, N250	Titchfield, UK	K2523	--
0733220	--	0733215-28-1	SB	WATER DRAIN VALVE-LIGHTNING SAFE - LEAKAGE PROBLEM	04-Jul-95	--	0	A330, A340	Titchfield, UK	K2523	--
0733220	--	0733215-28-2	SB	WATER DRAIN VALVE-LIGHTNING SAFE - CRACKED INSERT	21-Nov-95	--	0	A330, A340	Titchfield, UK	K2523	--
0733220	--	28-11-43	CMM	WATER DRAIN VALVE (DIRECT)	01-Jan-92	02-Feb-96	2	A330, A340, N250	Titchfield, UK	K2523	--
0733235	--	0733235-28-01	SB	Introduction of New Water-Fuel Drain Valve	--	--	0	SAAB 2000	Titchfield, UK	K2523	TO BE WRITTEN
0733235	--	28-10-53	CMM	WATER/FUEL DRAIN VALVE	01-Nov-92	--	0	SAAB 2000	Titchfield, UK	K2523	--
1003825-1	--	47-21-14	ACMM	1 INCH CHECK VALVE	09-Dec-15	--	0	C17A	Titchfield, UK	K2523	Changes funded by HS (UTC)
102AA01	--	28-10-73	OM	SPV	01-Apr-69	18-Mar-11	1	BAC 1-11, BAe 748	Titchfield, UK	K2523	--
102AB06	--	30-70-51	OM	1/4IN HOT AIR SPHERICAL PLUG VALVE	01-Aug-64	01-Mar-66	1	BAC 1-11	Titchfield, UK	K2523	--
102AL04	--	30-1-1	OM	1 1/4IN HOT AIR SP AERO VALVE	30-Apr-59	30-Dec-63	3	COMET 4	Titchfield, UK	K2523	--
103AA01	--	21-30-1	OM	3/8 IN BSP SPV	21-Nov-60	--	0	Not Known	Titchfield, UK	K2523	S/SEDED BY 21-50-10
103AA01	--	21-50-10	OM	3/8 IN BSP SPV (SEAL DEFLATION)	01-Jul-64	--	0	Not Known	Titchfield, UK	K2523	S/SEDES 21-30-1
103AA01	--	28-20-7	OM	3/8 IN BSP SPV (FUEL SYSTEM)	21-Jul-64	06-May-11	2	BAe 748	Titchfield, UK	K2523	--
103AA01	--	34-10-33	OM	3/8 IN BSP SPV (NAV/AIR DATA SYSTEM)	01-Oct-65	--	0	Not Known	Titchfield, UK	K2523	--
103AB01	--	31-20-41	OM	SPV	25-Jun-65	--	0	Not Known	Titchfield, UK	K2523	--
103AM52AC	--	49-30-01	OM	3/8 IN MOT PR/SPV	01-Mar-67	03-Jun-11	1	BAe 748	Titchfield, UK	K2523	--
103AR03	--	SL66	OM	HIGH PRESSURE SPV	01-Oct-65	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
103AR05	--	SL66	OM	HIGH PRESSURE SPV	01-Oct-65	--	0	Not Known	Titchfield, UK	K2523	--
103BA04	--	29-10-54	OM	3/8 IN SP DRAIN VALVE	01-Sep-63	--	0	BAC 1-11	Titchfield, UK	K2523	--
103BA09	--	38-30-24	CMM	3/8 IN SPV	01-Apr-80	13-May-11	5	BAE 146	Titchfield, UK	K2523	--
103BB04-1	--	29-10-55	OM	3/8 IN DIA SP DRAIN VALVE	01-Feb-64	01-Sep-67	2	BAC 1-11	Titchfield, UK	K2523	--
103FE01	--	34-10-32	OM	SPV	01-Feb-65	01-Mar-66	1	Not Known	Titchfield, UK	K2523	--
103JF01	--	SL82	OM	SPV	01-May-66	--	0	Not Known	Titchfield, UK	K2523	--
103NA01	--	21-30-02	CMM	SPV	01-Jul-82	07-Apr-11	2	JS31, JS32, JS41	Titchfield, UK	K2523	--
104AR11	--	38-10-59	OM	1/2 IN SPV	01-Apr-64	01-Dec-65	1	BAC 1-11	Titchfield, UK	K2523	--
104AR11-1	--	38-10-59	OM	1/2 IN SPV	01-Apr-64	01-Dec-65	1	BAC 1-11	Titchfield, UK	K2523	--
104BM52GA	--	28-20-70	OM	MOTORISED SPV	01-Jun-68	--	0	Not Known	Titchfield, UK	K2523	--
104CM14AD	--	49-30-51	OM	MOT PR/SP VALVE	01-Oct-64	01-Sep-67	1	BAC 1-11	Titchfield, UK	K2523	--
104CR11	--	38-09-25+	CMM	SPV	--	--	0	Not Known	Titchfield, UK	K2523	*OUT OF PRINT
104CR11	--	38-1-2	OM	MANUALLY OPERATED SPV (WATER)	04-Apr-60	04-Feb-64	3	COMET 4	Titchfield, UK	K2523	--
104EA11	--	38-09-23+	OM	SPV	28-Sep-62	28-Mar-68	2	TRIDENT	Titchfield, UK	K2523	(EX SAUNDERS)
104FB11	--	38-09-25	OM	SPV	01-Jul-63	01-Mar-68	2	Not Known	Titchfield, UK	K2523	--
104M2	--	104M2-49-1	SB	MOT. VALVES - ALTVE ELECTRIC MOTORS	01-Mar-81	--	0	Not Known	Titchfield, UK	K2523	--
104M2	--	49-30-52	OM	MOTORISED PR SPV	01-Jan-68	01-Nov-69	2	BAC 1-11	Titchfield, UK	K2523	--
105AR03	--	28-20-61+	OM	SPV	01-Apr-66	--	0	SHORTS SC7 SKYVAN	Titchfield, UK	K2523	*EX-SAUNDERS
105BM10	--	82-30-51	OM	MOT SPV	01-May-64	01-Nov-65	1	BAC 1-11	Titchfield, UK	K2523	--
105BM53GA	--	28-21-66	OM	MOTORISED SPV	01-Jul-68	--	0	Not Known	Titchfield, UK	K2523	--
105BM56-1CA	--	29-10-53	OM	MOT SPV	01-Dec-63	01-Jan-67	2	BAC 1-11	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
105BM56CA	--	29-10-53	OM	MOT SPV	01-Dec-63	01-Jan-67	2	BAC 1-11	Titchfield, UK	K2523	--
105BR02	--	29-1-1	CMM	SP/PR VALVE	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
105BR02-1	--	29-10-2	CMM	SPV	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
105BR02A	--	29-10-32	OM	SPV	01-Apr-68	--	0	Not Known	Titchfield, UK	K2523	--
105BR09-1	--	29-10-31	OM	PRES RELIEF/SPV	01-Apr-63	01-Apr-68	4	Not Known	Titchfield, UK	K2523	--
105BR62	--	29-10-71	OM	SPV	01-Jul-65	01-Nov-67	3	F28	Titchfield, UK	K2523	--
106AE02	--	28-20-64	OM	3/4 IN SPV	01-Nov-67	--	0	SHORTS SC7 SKYVAN	Titchfield, UK	K2523	--
106AL02	--	SL60	OM	SPV	01-Apr-66	04-Aug-05	1	Not Known	Titchfield, UK	K2523	--
106AR02	--	SL60	OM	SPV	01-Apr-66	04-Aug-05	1	Not Known	Titchfield, UK	K2523	--
106BR12B	--	38-09-25+	CMM	SPV	--	--	0	Not Known	Titchfield, UK	K2523	*OUT OF PRINT
106BR12B	--	38-1-2	OM	MANUALLY OPERATED SPV (WATER)	04-Apr-60	04-Feb-64	3	COMET 4	Titchfield, UK	K2523	--
106BR16	--	29-10-21	OM	SPV	01-Oct-62	--	0	Not Known	Titchfield, UK	K2523	--
106CR03	--	29-1-1	CMM	SP/PR VALVE	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
106CR03-1	--	29-10-3	CMM	SPV	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
106DA12	--	38-10-3+	OM	SPV	01-Jun-60	--	0	VANGUARD	Titchfield, UK	K2523	--
106DB12	--	38-10-3+	OM	SPV	01-Jun-60	--	0	VANGUARD	Titchfield, UK	K2523	--
106DM50B	--	SL61	OM	SPV MOT	01-Aug-66	--	0	Not Known	Titchfield, UK	K2523	--
106EC12-1	--	38-09-22++	OM	3/4IN DIA SPV	01-Aug-63	01-Sep-71	1	Not Known	Titchfield, UK	K2523	**EX-SAUNDERS MANUAL
106FM12-1-AC	--	82-30-21	OM	3/4 IN MOT SP VALVE	01-Jun-65	01-Oct-70	4	Not Known	Titchfield, UK	K2523	--
106FM12-1-EC	--	24-09-2-9085	SB	MODIFICATION FRCA 9085	--	01-Sep-74	1	Not Known	Titchfield, UK	K2523	--
106FM12-1-EC	--	82-30-21	OM	3/4 IN MOT SP VALVE	01-Jun-65	01-Oct-70	4	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
106FM12-1-FC	--	82-30-01	OM	MOTORISED SPV	01-Sep-74	--	0	Not Known	Titchfield, UK	K2523	--
106GC12	--	38-10-21	OM	SPV	01-Jan-64	--	0	Not Known	Titchfield, UK	K2523	--
107AR02	--	29-1-1	CMM	SP/PR VALVE	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
107AR02-1	--	29-10-1	CMM	SPV	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
108AR04	--	28-10-61+	OM	SPV	01-Oct-65	01-Dec-67	1	SHORTS SC7 SKYVAN	Titchfield, UK	K2523	* EX SAUNDERS
108AR09	--	38-1-4	OM	SPV	06-Jul-60	29-Nov-60	1	COMET 4	Titchfield, UK	K2523	--
108AR11	--	29-1-1	CMM	SP/PR VALVE	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
108AR11-1	--	29-10-1	CMM	SPV	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
108BA09	--	38-30-23	OM	SPV	01-May-65	01-Sep-71	2	Not Known	Titchfield, UK	K2523	--
108BM531B	--	29-10-1	CMM	SPV	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
108BM56-1CA	--	29-10-53	OM	MOT SPV	01-Dec-63	01-Jan-67	2	BAC 1-11	Titchfield, UK	K2523	--
108BR09	--	38-1-1	OM	SPV	26-Jun-59	29-Apr-60	1	COMET 4	Titchfield, UK	K2523	--
108BR09M5	--	38-1-1	OM	SPV	26-Jun-59	29-Apr-60	1	COMET 4	Titchfield, UK	K2523	--
108BR14	--	SL67	OM	SPV	01-Mar-66	--	0	Not Known	Titchfield, UK	K2523	--
108BR61-1	--	29-10-12	OM	SPV	01-Mar-66	01-Jun-66	1	VARIOUS	Titchfield, UK	K2523	--
108DM51-1AC	--	28-20-2	OM	MOT SPV	01-Jun-66	22-Apr-11	6	BAC 1-11, BAe 748	Titchfield, UK	K2523	SEE 28-20-2* FOR 110AM51C
108DM51-1-AC	--	28-1-1	OM	MOTORISED SPV	01-Jan-61	01-Jul-85	4	HERALD	Titchfield, UK	K2523	HERALD A/C ONLY
108DM51-1-AC	--	28-20-2	OM	MOT SPV	01-Jun-66	22-Apr-11	6	BAC 1-11, BAe 748	Titchfield, UK	K2523	SEE 28-20-2* FOR 110AM51C
108DM51-1-AC	--	82-20-6	OM	MOTORISED SPV (WATER METHS)	01-Feb-67	03-Jun-11	1	BAe 748	Titchfield, UK	K2523	X refers to 28-20-2
108DM51-1B	--	28-20-2	OM	MOT SPV	01-Jun-66	22-Apr-11	6	BAC 1-11, BAe 748	Titchfield, UK	K2523	SEE 28-20-2* FOR 110AM51C
108DM51-1-B	--	28-1-1	OM	MOTORISED SPV	01-Jan-61	01-Jul-85	4	HERALD	Titchfield, UK	K2523	HERALD A/C ONLY

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
108DM51-1-B	--	82-20-6	OM	MOTORISED SPV (WATER METHS)	01-Feb-67	03-Jun-11	1	BAe 748	Titchfield, UK	K2523	X refers to 28-20-2
108DM51AC	--	28-1-1	OM	MOTORISED SPV	01-Jan-61	01-Jul-85	4	HERALD	Titchfield, UK	K2523	HERALD A/C ONLY
108DM51AC	--	28-20-2	OM	MOT SPV	01-Jun-66	22-Apr-11	6	BAC 1-11, BAe 748	Titchfield, UK	K2523	SEE 28-20-2* FOR 110AM51C
108DM51AC	--	82-20-6	OM	MOTORISED SPV (WATER METHS)	01-Feb-67	03-Jun-11	1	BAe 748	Titchfield, UK	K2523	X refers to 28-20-2
108DM51B	--	28-1-1	OM	MOTORISED SPV	01-Jan-61	01-Jul-85	4	HERALD	Titchfield, UK	K2523	HERALD A/C ONLY
108DM51B	--	28-20-2	OM	MOT SPV	01-Jun-66	22-Apr-11	6	BAC 1-11, BAe 748	Titchfield, UK	K2523	SEE 28-20-2* FOR 110AM51C
108DM51B	--	82-20-6	OM	MOTORISED SPV (WATER METHS)	01-Feb-67	03-Jun-11	1	BAe 748	Titchfield, UK	K2523	X refers to 28-20-2
108DM52-1-B	--	82-5-1	CMM	PR/SPV	--	--	2	Not Known	Titchfield, UK	K2523	OUT OF PRINT
108DM54-1-B	--	28-1-3	OM	MOTORISED SPV	01-Dec-61	01-May-66	2	Not Known	Titchfield, UK	K2523	--
108DM54B	--	28-1-3	OM	MOTORISED SPV	01-Dec-61	01-May-66	2	Not Known	Titchfield, UK	K2523	--
108FM50-1-EC	--	28-20-13+	OM	MOTORISED SPV	01-Feb-63	01-Nov-66	1	BAC 1-11	Titchfield, UK	K2523	*EX-SAUNDERS
108FR04	--	82-21-1	OM	SPV	01-Dec-60	03-Jun-11	1	BAe 748	Titchfield, UK	K2523	--
108FR61	--	29-10-71	OM	SPV	01-Jul-65	01-Nov-67	3	F28	Titchfield, UK	K2523	--
108M2	--	104M2-49-1	SB	MOT. VALVES - ALTVE ELECTRIC MOTORS	01-Mar-81	--	0	Not Known	Titchfield, UK	K2523	--
108M2	--	29-10-56	OM	MOT SPV	01-Dec-68	07-Feb-00	2	BAC 1-11	Titchfield, UK	K2523	--
11-0029-4001	--	SIL-2008-02	SIL	TF-57160-1 - FILTER - Change of PN	--	--	0	HS 125	Titchfield, UK	K2523	TO BE WRITTEN
1104D	--	28-20-47	OM	TAPER PLUG MULTIWAY VALVE	01-Oct-67	30-Nov-04	1	VARIOUS	Titchfield, UK	K2523	--
110AM50-1-C	--	SL51	OM	MOT SPV	01-Sep-61	--	0	Not Known	Titchfield, UK	K2523	--
110AM51-1-C	--	28-20-2+	OM	MOT SPV	--	01-Jul-65	1	Not Known	Titchfield, UK	K2523	SEE 28-20-2 FOR 108DM51*
110AM51C	--	28-20-2+	OM	MOT SPV	--	01-Jul-65	1	Not Known	Titchfield, UK	K2523	SEE 28-20-2 FOR 108DM51*
110AM54EC	--	29-10-11	OM	SPV	01-Dec-62	12-Mar-04	7	BAC 1-11	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
110AM55EC	--	29-10-11	OM	SPV	01-Dec-62	12-Mar-04	7	BAC 1-11	Titchfield, UK	K2523	--
110BA06	--	38-10-4	OM	SPV	03-May-60	--	0	Not Known	Titchfield, UK	K2523	--
110BA07	--	38-10-6	OM	SPV	01-Oct-60	01-Mar-61	1	Not Known	Titchfield, UK	K2523	--
110BD61	--	28-20-72+	OM	PR/SPV	01-Sep-65	01-Nov-66	1	Not Known	Titchfield, UK	K2523	*EX-SAUNDERS
110BG-02	--	28-20-31	OM	PR/SPV	01-May-63	22-Oct-04	3	Not Known	Titchfield, UK	K2523	--
110BL05	--	28-20-86	OM	PR/SPV	01-Mar-70	--	0	Not Known	Titchfield, UK	K2523	--
110BM51-1-B	--	28-20-1	OM	MOTORISED PR/SPV	01-Mar-60	01-Dec-63	2	BAC 1-11	Titchfield, UK	K2523	--
110BM51B	--	28-20-1	OM	MOTORISED PR/SPV	01-Mar-60	01-Dec-63	2	BAC 1-11	Titchfield, UK	K2523	--
110BR02	--	28-20-4	OM	1 1/4 IN PR/SPV	--	22-Apr-11	2	BAe 748	Titchfield, UK	K2523	--
110BR05	--	28-20-86	OM	PR/SPV	01-Mar-70	--	0	Not Known	Titchfield, UK	K2523	--
110DB28	--	28-10-90	CMM	1 1/4IN PR/SPV	01-Jan-87	17-Oct-14	5	F100, F28, F50, F70	Titchfield, UK	K2523	--
110DD30	--	28-10-72	OM	MOTORISED SPV	29-Jun-72	18-Mar-96	3	F28	Titchfield, UK	K2523	--
110DM51B	--	28-1-2	OM	MOTORISED SPV	01-Mar-60	01-Jun-66	2	Not Known	Titchfield, UK	K2523	--
110EM51AB	--	28-20-52	OM	MOT PR/SP VALVE	01-Oct-63	01-Feb-86	3	BAC 1-11	Titchfield, UK	K2523	--
110JR02	--	28-20-4	OM	1 1/4 IN PR/SPV	--	22-Apr-11	2	BAe 748	Titchfield, UK	K2523	--
110M2	--	28-09-9075-19776	SB	LW MOTOR UNITS - IMPROVED SEALING	01-Jun-70	09-Oct-70	1	F27, F28	Titchfield, UK	K2523	--
110M2	--	28-20-77	OM	1 1/4in MOT PR/SPV	01-Nov-70	01-Mar-85	3	F28	Titchfield, UK	K2523	EX SAUNDERS
110M21	--	110M21-28-1	SB	MOT. VALVES - ALTVE ELECTRIC MOTORS	01-Apr-77	01-Mar-81	1	Not Known	Titchfield, UK	K2523	--
110M21	--	28-09-9075-19776	SB	LW MOTOR UNITS - IMPROVED SEALING	01-Jun-70	09-Oct-70	1	F27, F28	Titchfield, UK	K2523	--
110M21	--	28-22-75	OM	1 1/4 IN MOTORISED PR SPV	01-Oct-74	29-Jan-85	1	F27, F28	Titchfield, UK	K2523	--
110M3	--	104M2-49-1	SB	MOT. VALVES - ALTVE ELECTRIC MOTORS	01-Mar-81	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
110M3	--	28-20-53+	OM	1 1/4IN MOT PR/SPV	--	01-Aug-84	2	BAC 1-11	Titchfield, UK	K2523	*EX-SAUNDERS
110M8-1	--	110M21-28-1	SB	MOT. VALVES - ALTVE ELECTRIC MOTORS	01-Apr-77	01-Mar-81	1	Not Known	Titchfield, UK	K2523	--
110M8-1	--	28-09-9075-19776	SB	LW MOTOR UNITS - IMPROVED SEALING	01-Jun-70	09-Oct-70	1	F27, F28	Titchfield, UK	K2523	--
110M8-1	--	28-10-72	OM	MOTORISED SPV	29-Jun-72	18-Mar-96	3	F28	Titchfield, UK	K2523	--
1112000-1	--	28-20-26	OM	MK 12 PRESS REFUELLING VALVE	01-Mar-67	07-Apr-99	1	BAC 1-11, COMET 4, VISCOUNT 700/800	Titchfield, UK	K2523	--
1112000-3	--	28-20-26	OM	MK 12 PRESS REFUELLING VALVE	01-Mar-67	07-Apr-99	1	BAC 1-11, COMET 4, VISCOUNT 700/800	Titchfield, UK	K2523	--
1112000-4	--	28-20-26	OM	MK 12 PRESS REFUELLING VALVE	01-Mar-67	07-Apr-99	1	BAC 1-11, COMET 4, VISCOUNT 700/800	Titchfield, UK	K2523	--
1112580	--	28-20-26	OM	MK 12 PRESS REFUELLING VALVE	01-Mar-67	07-Apr-99	1	BAC 1-11, COMET 4, VISCOUNT 700/800	Titchfield, UK	K2523	--
1112675	--	28-20-26	OM	MK 12 PRESS REFUELLING VALVE	01-Mar-67	07-Apr-99	1	BAC 1-11, COMET 4, VISCOUNT 700/800	Titchfield, UK	K2523	--
1127000	--	28-B27-1	OM	MK 27 SEL REF DEF	01-Feb-60	--	0	Not Known	Titchfield, UK	K2523	--
1127060	--	28-B27-2	OM	MK 27 SEL REF/DEF	01-Aug-71	01-Aug-87	3	Not Known	Titchfield, UK	K2523	--
1127110	--	28-B27-3	OM	MK 27 SEL REF/DEF	01-May-63	--	0	Not Known	Titchfield, UK	K2523	--
1127145	--	28-20-32	OM	MK 27 SEL REF/DEF	01-Jun-68	--	0	Not Known	Titchfield, UK	K2523	--
1127155	--	28-20-66	OM	MK 27 SELECTOR REFUEL/DEFUEL	01-Sep-69	--	0	Not Known	Titchfield, UK	K2523	--
1128010	--	28-22-58	OM	MK 28 SEL REF/DEF	14-Feb-74	06-May-11	2	BAC 1-11, BAe 748	Titchfield, UK	K2523	PDF Manual & next Rev CRC to Prwk for issue
112AM50AF	--	28-20-79+	OM	1 1/2 IN MOTORISED SPV	01-Feb-70	--	0	Not Known	Titchfield, UK	K2523	SEE 28-20-79 FOR 114M1*
112BA04-26	--	28-2-1+	CMM	MOTORISED PR/SPV	--	--	1	Not Known	Titchfield, UK	K2523	OUT OF PRINT
112BA04-34	--	28-2-1+	CMM	MOTORISED PR/SPV	--	--	1	Not Known	Titchfield, UK	K2523	OUT OF PRINT
112BA04-36	--	28-2-1+	CMM	MOTORISED PR/SPV	--	--	1	Not Known	Titchfield, UK	K2523	OUT OF PRINT
112BA04-36A	--	28-2-1+	CMM	MOTORISED PR/SPV	--	--	1	Not Known	Titchfield, UK	K2523	OUT OF PRINT
112BA04-36B	--	28-2-1+	CMM	MOTORISED PR/SPV	--	--	1	Not Known	Titchfield, UK	K2523	OUT OF PRINT

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
112BL04	--	28-1-1+	CMM	PR/SPV	--	--	2	Not Known	Titchfield, UK	K2523	OUT OF PRINT
112BM51-1-B	--	28-20-1	OM	MOTORISED PR/SPV	01-Mar-60	01-Dec-63	2	BAC 1-11	Titchfield, UK	K2523	--
112BM51B	--	28-20-1	OM	MOTORISED PR/SPV	01-Mar-60	01-Dec-63	2	BAC 1-11	Titchfield, UK	K2523	--
112BM55EC	--	28-30-12+	OM	MOT PR/SPV	01-Feb-66	01-Aug-67	1	BAC 1-11	Titchfield, UK	K2523	--
112BR07	--	38-1-1	OM	SPV	26-Jun-59	29-Apr-60	1	COMET 4	Titchfield, UK	K2523	--
112BR07M5	--	38-1-1	OM	SPV	26-Jun-59	29-Apr-60	1	COMET 4	Titchfield, UK	K2523	--
112BR62	--	28-22-22	OM	PR/SPV	27-Sep-62	--	0	Not Known	Titchfield, UK	K2523	--
112CL07-1	--	38-09-21	OM	SPV	01-Jan-63	--	0	Not Known	Titchfield, UK	K2523	--
112CM51-1-B	--	28-20-1	OM	MOTORISED PR/SPV	01-Mar-60	01-Dec-63	2	BAC 1-11	Titchfield, UK	K2523	--
112CM51B	--	28-20-1	OM	MOTORISED PR/SPV	01-Mar-60	01-Dec-63	2	BAC 1-11	Titchfield, UK	K2523	--
112CR62	--	28-22-26	OM	1 1/2 IN PR/SPV	21-Jan-74	--	0	Not Known	Titchfield, UK	K2523	--
112DL07-1	--	38-09-21	OM	SPV	01-Jan-63	--	0	Not Known	Titchfield, UK	K2523	--
112GM50EC	--	28-20-12+	OM	SPV	01-Jan-63	01-Nov-66	1	BAC 1-11	Titchfield, UK	K2523	*EX-SAUNDERS
1139050	--	28-B39-1	OM	MK 39 SEL REF/DEF	01-Apr-60	01-Dec-62	1	VANGUARD	Titchfield, UK	K2523	--
1139080	--	28-22-67	OM	MK 39 SEL REF/DEF (FUELLING VALVE)	14-Feb-74	--	0	Not Known	Titchfield, UK	K2523	--
1139085	--	28-20-33	OM	MK 39 SEL REF/DEF	01-Jul-68	--	0	Not Known	Titchfield, UK	K2523	--
1139115	--	28-20-22	OM	REF VALVE MK 39	01-Oct-67	01-Mar-86	2	Not Known	Titchfield, UK	K2523	--
1141070	--	28-3-41	SB	MK 41 REF/DEF VALVE - IMPROVED INDICATOR SWITCH	10-Dec-65	--	0	Not Known	Titchfield, UK	K2523	--
1141070	--	28-B41-1	OM	MK 41 SEL REF/DEF	01-May-63	28-Sep-05	3	BAC 1-11	Titchfield, UK	K2523	--
1141080	--	28-20-12	OM	MK 41 SELECTOR REFUEL/DEFUEL	01-Oct-69	28-Sep-05	4	BAC 1-11	Titchfield, UK	K2523	--
1141090	--	28-20-11	OM	MK 41 SELECTOR REFUEL/DEFUEL	01-Sep-65	03-Jan-12	12	BAC 1-11	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
1141120	--	28-20-63	OM	MK41 REFUEL/DEFUEL VALVE	01-May-69	28-Sep-05	6	BAC 1-11	Titchfield, UK	K2523	--
1141130	--	28-20-63	OM	MK41 REFUEL/DEFUEL VALVE	01-May-69	28-Sep-05	6	BAC 1-11	Titchfield, UK	K2523	--
1147000	--	28-22-26	OM	1 1/2 IN PR/SPV	21-Jan-74	--	0	Not Known	Titchfield, UK	K2523	--
1148120	--	28-22-79	CMM	MK 48 REFUEL VALVE	20-May-99	03-Apr-15	2	HARRIER	Titchfield, UK	K2523	Orig. 9/6/75 updated CMM
1148250	--	1148250	OM	Mk.48 Refuelling Valve	--	--	0	SEA HARRIER	Titchfield, UK	K2523	--
1148265	--	28-20-45	CMM	REFUEL VALVE	01-Mar-84	27-Aug-15	4	HAWK	Titchfield, UK	K2523	(5copies)
1148350	--	PSD-194	CMM	Refuelling Valve	06-Aug-12	23-Nov-12	1	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	TCH (pub NOT PN)=HAL, BAE for info only
114DA30	--	28-10-91	CMM	1 3/4IN SPV	01-Jan-87	20-Feb-96	3	F100, F28	Titchfield, UK	K2523	--
114M1	--	28-09-9075-19776	SB	LW MOTOR UNITS - IMPROVED SEALING	01-Jun-70	09-Oct-70	1	F27, F28	Titchfield, UK	K2523	--
114M1	--	28-20-79	OM	MOTORISED SPV	01-Sep-68	05-Dec-97	3	F100, F28	Titchfield, UK	K2523	SEE 28-20-79* FOR 112AM*
114M11	--	110M21-28-1	SB	MOT. VALVES - ALTVE ELECTRIC MOTORS	01-Apr-77	01-Mar-81	1	Not Known	Titchfield, UK	K2523	--
114M11	--	28-09-9075-19776	SB	LW MOTOR UNITS - IMPROVED SEALING	01-Jun-70	09-Oct-70	1	F27, F28	Titchfield, UK	K2523	--
114M11	--	28-20-79	OM	MOTORISED SPV	01-Sep-68	05-Dec-97	3	F100, F28	Titchfield, UK	K2523	SEE 28-20-79* FOR 112AM*
1150140	--	28-22-28	OM	SENSOR VALVE	01-Jul-74	16-Sep-87	1	Not Known	Titchfield, UK	K2523	--
1150185	--	1150240-28-1	SB	DELETION OF PISTON SEAL	01-Nov-77	01-May-78	1	Not Known	Titchfield, UK	K2523	--
1150185	--	28-22-71	OM	ELEMENT ASSEMBLIES	01-Apr-78	10-Jun-99	7	CONCORDE	Titchfield, UK	K2523	--
1150190	--	1150240-28-1	SB	DELETION OF PISTON SEAL	01-Nov-77	01-May-78	1	Not Known	Titchfield, UK	K2523	--
1150190	--	28-22-27	OM	BODY ASSEMBLIES	--	01-Apr-78	1	Not Known	Titchfield, UK	K2523	--
1150195	--	28-22-27	OM	BODY ASSEMBLIES	--	01-Apr-78	1	Not Known	Titchfield, UK	K2523	--
1150200-1	--	28-22-30	OM	SOLENOID VALVE	01-May-74	23-Aug-02	3	CONCORDE	Titchfield, UK	K2523	--
1150200-2	--	28-22-30	OM	SOLENOID VALVE	01-May-74	23-Aug-02	3	CONCORDE	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
1150230	--	28-22-71	OM	ELEMENT ASSEMBLIES	01-Apr-78	10-Jun-99	7	CONCORDE	Titchfield, UK	K2523	--
1150235	--	28-22-27	OM	BODY ASSEMBLIES	--	01-Apr-78	1	Not Known	Titchfield, UK	K2523	--
1154000	--	28-22-76	OM	MK 54 REFUEL DEFUEL VALVE	01-Apr-75	23-Apr-08	9	LYNX	Titchfield, UK	K2523	--
1154035	--	28-22-74	OM	MK 54 REFUEL DEFUEL VALVE	01-Apr-75	08-May-09	9	SD-330, SD-360	Titchfield, UK	K2523	--
1154065	--	28-21-09	CMM	MK54 REF/DEF VALVE & SOL.VALVE ASSY	01-Feb-87	11-Nov-13	7	BAe ATP, JS61	Titchfield, UK	K2523	INC SOL VLV 3801225
1154126	--	28-21-28	CMM	MK 54 REFUEL/DEFUEL VALVE	30-Jun-94	17-Oct-14	3	EH101	Titchfield, UK	K2523	INCLUDES SOLENOID VALVE
1155020	--	28-21-91	OM	MK 55 REFUEL & FLOAT PILOT VALVES	01-Jul-73	08-Oct-08	4	CASA 212	Titchfield, UK	K2523	--
1155030	--	28-21-91	OM	MK 55 REFUEL & FLOAT PILOT VALVES	01-Jul-73	08-Oct-08	4	CASA 212	Titchfield, UK	K2523	--
1157020	--	1157020-28-1	SB	FUEL SYSTEM- REFUEL/DEFUEL VALVE	01-May-85	01-Nov-85	2	A300, A300-600, A310	Titchfield, UK	K2523	--
1157020	--	1157020-28-2	SB	MK57 VALVE CANISTER SPRING REPLACEMENT	--	--	0	A300-600, A310	Titchfield, UK	K2523	CANCELLED
1157020	--	28-22-16	CMM	CANISTER MK 57 VALVE	12-Oct-72	18-Jan-11	5	A300, A300-600, A310	Titchfield, UK	K2523	--
1157020	--	28-22-16-11088	SB	VALVE CANISTER ATTACHMENT STUDS	01-Dec-76	--	0	A300, A300-600, A310	Titchfield, UK	K2523	--
1157020	--	SIL-2007-05	SIL	MK57 VALVE CANISTER - DIFFICULTY OF VALVE ELEMENT INSTALLATION	18-Jun-07	--	0	A300, A300-600, A310	Titchfield, UK	K2523	--
1157060	--	1157060-28-1	SB	MK 57 VALVE - SEALING OF ELECTRICAL CONNECTORS	01-Nov-85	--	2	A300, A310	Titchfield, UK	K2523	--
1157060	--	1157060-28-2	SB	MK 57 Valve Seal Replacement	25-Feb-10	--	0	A300-600, A310	Titchfield, UK	K2523	--
1157060	--	28-22-69	CMM	MK 57 VALVE ELEMENT	01-Apr-74	10-Jul-15	17	A300, A300-400, A300-600, A310	Titchfield, UK	K2523	--
1157060	--	SIL-2008-10	SIL	REFUEL / DEFUEL VALVE IN SERVICE FLIGHT EVALUATION	12-Jan-08	--	0	A300-600	Titchfield, UK	K2523	--
1157060	--	SIL-2009-03	SIL	FUEL, OPTIONAL ELEMENT ASSEMBLY	--	--	0	A300, A300-400, A300-600, A310	Titchfield, UK	K2523	CANCELLED
1157060	--	SIL-CS-1-06	SIL	MK 57 VALVE ELEMENT- FUEL SPILLAGE	27-Jan-06	--	0	A300-600, A310	Titchfield, UK	K2523	BASIC MANUAL
1157060	--	SIL-CS-3-03	SIL	MK 57 REFUEL VALVE ELEMENT - OBSOLETE MATERIAL	15-Apr-03	--	0	A300, A300-600, A310	Titchfield, UK	K2523	--
1158000-15	--	28-25-52	CMM	REFUEL VALVE CANISTER & CHECK VLVE	02-Mar-87	14-Nov-18	9	A319, A320, A321	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
1158000-17	--	28-25-51	CMM	REFUEL VALVE ELEMENT	01-Mar-87	10-Dec-96	2	A320 NEO	Titchfield, UK	K2523	--
1158000-21	--	1158000-28-001	SB	REPAIR FAILED REFUEL VALVES	03-Oct-11	26-Jan-12	1	A319, A320, A321	Titchfield, UK	K2523	SUPERSEDED
1158000-21	--	1158000-28-002	SB	Introduction of new Refuel Valve	27-Mar-13	--	0	A319, A320, A321	Titchfield, UK	K2523	--
1158000-21	--	1158000-28-003	SB	Introduction of Improved Refuel Valve	22-Apr-13	26-Jan-16	1	A318, A319, A320, A321	Titchfield, UK	K2523	--
1158000-21	--	28-25-61	CMM	REFUEL VALVE - ELEMENT ASSEMBLY	01-May-88	21-Feb-19	18	A318, A319, A320, A321	Titchfield, UK	K2523	--
1158000-21	--	SIL-PS-2-96	SIL	IDENTIFICATION OF SOLENOID VALVE ASSY PN 3802045	15-Feb-96	--	0	A319, A320, A321	Titchfield, UK	K2523	--
1158000-21R	--	1158000-28-001	SB	REPAIR FAILED REFUEL VALVES	03-Oct-11	26-Jan-12	1	A319, A320, A321	Titchfield, UK	K2523	SUPERSEDED
1158000-21R	--	1158000-28-003	SB	Introduction of Improved Refuel Valve	22-Apr-13	26-Jan-16	1	A318, A319, A320, A321	Titchfield, UK	K2523	--
1158000-21R	--	28-25-61	CMM	REFUEL VALVE - ELEMENT ASSEMBLY	01-May-88	21-Feb-19	18	A318, A319, A320, A321	Titchfield, UK	K2523	--
1158000-45	--	1158000-28-002	SB	Introduction of new Refuel Valve	27-Mar-13	--	0	A319, A320, A321	Titchfield, UK	K2523	--
1158000-45	--	1158000-28-003	SB	Introduction of Improved Refuel Valve	22-Apr-13	26-Jan-16	1	A318, A319, A320, A321	Titchfield, UK	K2523	--
1158000-45	--	28-25-61	CMM	REFUEL VALVE - ELEMENT ASSEMBLY	01-May-88	21-Feb-19	18	A318, A319, A320, A321	Titchfield, UK	K2523	--
1158100-25	--	SIL-PS-1-97	SIL	REFUEL SOV - INTRO OF CRES SCREWS	14-Apr-97	--	0	Not Known	Titchfield, UK	K2523	--
1158100-26	--	SIL-PS-1-97	SIL	REFUEL SOV - INTRO OF CRES SCREWS	14-Apr-97	--	0	Not Known	Titchfield, UK	K2523	--
1158100-27	--	SIL-PS-1-97	SIL	REFUEL SOV - INTRO OF CRES SCREWS	14-Apr-97	--	0	Not Known	Titchfield, UK	K2523	--
1159000-1	--	28-23-14	OM	PRES CONT VALVE	11-Jul-77	10-Apr-08	7	BAE 125	Titchfield, UK	K2523	--
116CM70GA	--	28-21-69	OM	MOTORISED SPV	01-Aug-69	--	0	CONCORDE	Titchfield, UK	K2523	--
116FM50F	--	21-20-23	OM	MOTORISED SPV	01-Mar-63	01-Sep-71	3	Not Known	Titchfield, UK	K2523	--
116FM50X	--	21-20-23	OM	MOTORISED SPV	01-Mar-63	01-Sep-71	3	Not Known	Titchfield, UK	K2523	--
116PM50EC	--	28-30-13+	OM	SPV	01-Dec-66	--	0	BAC 1-11, VC10	Titchfield, UK	K2523	* EX SAUNDERS
12-0007	--	28-24-23	CMM	DRIVESHAFT-VALVE	02-Oct-09	12-Jun-15	5	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
12-0008	--	28-24-23	CMM	DRIVESHAFT-VALVE	02-Oct-09	12-Jun-15	5	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
12-0009	--	28-24-23	CMM	DRIVESHAFT-VALVE	02-Oct-09	12-Jun-15	5	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
12-0029	--	28-24-23	CMM	DRIVESHAFT-VALVE	02-Oct-09	12-Jun-15	5	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
12-0030	--	28-24-23	CMM	DRIVESHAFT-VALVE	02-Oct-09	12-Jun-15	5	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
12-0031	--	28-24-23	CMM	DRIVESHAFT-VALVE	02-Oct-09	12-Jun-15	5	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
12-0057	--	28-30-19	CMM	Fuel Selector Manifold	--	--	0	US101	Titchfield, UK	K2523	TO BE WRITTEN
12-0065	--	28-24-23	CMM	DRIVESHAFT-VALVE	02-Oct-09	12-Jun-15	5	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
12-0066	--	28-24-23	CMM	DRIVESHAFT-VALVE	02-Oct-09	12-Jun-15	5	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
12-0067	--	28-24-23	CMM	DRIVESHAFT-VALVE	02-Oct-09	12-Jun-15	5	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
12-0084	--	28-24-23	CMM	DRIVESHAFT-VALVE	02-Oct-09	12-Jun-15	5	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
12-0127	--	28-20-23+	CMM	Valve Driveshaft	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
12-0128	--	28-20-23+	CMM	Valve Driveshaft	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
12-0130	--	28-20-23+	CMM	Valve Driveshaft	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
120BM70GC	--	28-30-66	OM	MOTORISED SPV	01-May-68	01-Oct-68	1	Not Known	Titchfield, UK	K2523	--
120HE01N1	--	21-50-21	CMM	MOTORISED SPV	01-Feb-66	--	0	Not Known	Titchfield, UK	K2523	--
124BM70-1-GA	--	28-30-67	OM	MOTORISED SPV	01-Sep-69	--	0	Not Known	Titchfield, UK	K2523	--
124BM71GA	--	28-21-70	OM	MOTORISED SPV	18-Jul-69	--	0	Not Known	Titchfield, UK	K2523	--
124CM50EC	--	28-30-11	OM	SPV	01-Nov-62	01-Nov-66	2	BAC 1-11	Titchfield, UK	K2523	--
12A02	--	38-20-12	OM	SP WATER VALVE	01-Sep-62	--	0	BAC 1-11	Titchfield, UK	K2523	--
12B02	--	38-20-13	OM	SP WATER VALVE	01-Jan-64	01-Dec-67	1	BAC 1-11	Titchfield, UK	K2523	--
12C0088	--	28-20-04_K2523_1	CMM	Selector Valve Component Maintenance Manual	--	--	0	CH-53K	Titchfield, UK	K2523	TO BE WRITTEN

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
12C0088-1100	--	28-20-04_K2523_1	CMM	Selector Valve Component Maintenance Manual	--	--	0	CH-53K	Titchfield, UK	K2523	TO BE WRITTEN
12D0024	--	12D0024-32-01	SB	MODIFICATION OF DOOR BY-PASS VALVE	--	--	0	A330, A340	Titchfield, UK	K2523	TO BE WRITTEN
12D0024	--	32-31-31	CMM	DOOR BYPASS VALVE	26-May-99	15-Oct-14	8	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
12D0024	--	FRH530014D-32-1	SB	DOOR BY-PASS VALVE - BROKEN BOLTS.	03-Apr-07	12-Sep-07	1	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
12D0162	--	12D0024-32-01	SB	MODIFICATION OF DOOR BY-PASS VALVE	--	--	0	A330, A340	Titchfield, UK	K2523	TO BE WRITTEN
12D0162	--	32-31-31	CMM	DOOR BYPASS VALVE	26-May-99	15-Oct-14	8	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
12F0012	--	28-24-26	CMM	VALVE-3/4IN REMOTE	04-Dec-07	26-Jun-17	5	BOEING 787	Titchfield, UK	K2523	--
12F0032	--	28-24-26	CMM	VALVE-3/4IN REMOTE	04-Dec-07	26-Jun-17	5	BOEING 787	Titchfield, UK	K2523	--
12F0069	--	28-24-26	CMM	VALVE-3/4IN REMOTE	04-Dec-07	26-Jun-17	5	BOEING 787	Titchfield, UK	K2523	--
12F0074	--	28-24-26	CMM	VALVE-3/4IN REMOTE	04-Dec-07	26-Jun-17	5	BOEING 787	Titchfield, UK	K2523	--
12H0005	--	47-21-01	CMM	VALVE-1IN REMOTE	07-May-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	--
12H0011	--	28-24-25	CMM	VALVE-1IN PEDESTAL	04-Dec-07	23-Sep-15	3	Boeing 777X, BOEING 787	Titchfield, UK	K2523	--
12H0011	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320X, A320X MRTT, A321X	Titchfield, UK	K2523	--
12H0035	--	47-21-01	CMM	VALVE-1IN REMOTE	07-May-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	--
12H0058	--	47-21-11	CMM	Valve 1 inch Pedestal	23-Sep-15	--	0	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
12H0068	--	28-24-25	CMM	VALVE-1IN PEDESTAL	04-Dec-07	23-Sep-15	3	Boeing 777X, BOEING 787	Titchfield, UK	K2523	--
12H0077	--	47-21-01	CMM	VALVE-1IN REMOTE	07-May-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	--
12H0087	--	28-20-03_K2523_1	CMM	4 Position Ball Valve Component Maintenance Manual	--	--	0	CH-53K	Titchfield, UK	K2523	TO BE WRITTEN
12H0087-1100	--	28-20-03_K2523_1	CMM	4 Position Ball Valve Component Maintenance Manual	--	--	0	CH-53K	Titchfield, UK	K2523	TO BE WRITTEN
12H0121	--	28-25-00	CMM	1 Inch Pedestal Valve	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
12K0006	--	47-21-06	CMM	VALVE 1 1/2IN REMOTE	07-May-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
12K0036	--	47-21-06	CMM	VALVE 1 1/2IN REMOTE	07-May-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	--
12K0063	--	47-21-13	CMM	1.5 Pedestal Ball Valve	23-Sep-15	--	0	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
12K0122	--	28-25-01	CMM	1.5 Inch Pedestal Valve	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
12K0147	--	47-21-15	CMM	Remote 1.5 in Valve	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
12M0003	--	28-31-02	CMM	VALVE BODY-2IN (JETTISON NOZZLE)	04-Dec-07	10-Jul-17	3	Boeing 777X, BOEING 787	Titchfield, UK	K2523	--
12M0015	--	28-24-33	CMM	VALVE-2IN REMOTE	30-Jan-08	05-May-11	2	BOEING 787	Titchfield, UK	K2523	INCORPORATED INTO 28-24-22
12M0027	--	28-31-02	CMM	VALVE BODY-2IN (JETTISON NOZZLE)	04-Dec-07	10-Jul-17	3	Boeing 777X, BOEING 787	Titchfield, UK	K2523	--
12M0028	--	28-24-33	CMM	VALVE-2IN REMOTE	30-Jan-08	05-May-11	2	BOEING 787	Titchfield, UK	K2523	INCORPORATED INTO 28-24-22
12M0033	--	28-24-22	CMM	VALVE-2IN REMOTE	29-Jan-08	23-Sep-15	4	Boeing 777X, BOEING 787	Titchfield, UK	K2523	--
12M0034	--	28-24-22	CMM	VALVE-2IN REMOTE	29-Jan-08	23-Sep-15	4	Boeing 777X, BOEING 787	Titchfield, UK	K2523	--
12M0034	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A320	Titchfield, UK	K2523	--
12M0037	--	28-31-02	CMM	VALVE BODY-2IN (JETTISON NOZZLE)	04-Dec-07	10-Jul-17	3	Boeing 777X, BOEING 787	Titchfield, UK	K2523	--
12M0075	--	28-24-22	CMM	VALVE-2IN REMOTE	29-Jan-08	23-Sep-15	4	Boeing 777X, BOEING 787	Titchfield, UK	K2523	--
12M0076	--	28-24-22	CMM	VALVE-2IN REMOTE	29-Jan-08	23-Sep-15	4	Boeing 777X, BOEING 787	Titchfield, UK	K2523	--
12M0090	--	28-24-06	CMM	2IN LP ENGINE VALVE (I/B)	07-Dec-01	04-Sep-15	6	A340-500, A340-600	Titchfield, UK	K2523	--
12M0090	--	FRH120199-28-01	SB	Replacement LP Inboard Valve	05-Nov-12	--	0	A340-500, A340-600	Titchfield, UK	K2523	--
12M0091	--	28-24-06	CMM	2IN LP ENGINE VALVE (I/B)	07-Dec-01	04-Sep-15	6	A340-500, A340-600	Titchfield, UK	K2523	--
12M0134-1100	--	28-24-41	CMM	LOW PRESSURE FUEL VALVE	11-May-92	01-Nov-18	6	A330, A330 NEO, A340	Titchfield, UK	K2523	--
12M0135-1100	--	28-23-41	CMM	FUEL CROSSFEED VALVE	30-Jan-91	10-May-16	8	A330, A330 NEO, A340	Titchfield, UK	K2523	--
12M0143	--	28-25-03	CMM	2 Inch Pedestal Valve	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
12M0170-1100	--	28-23-06_K2523	CMM	2 Inch Motorised Shut-Off Valve Component Maintenance Manual	--	--	0	KF-X	Titchfield, UK	K2523	TO BE WRITTEN

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
12M0171	--	28-23-07_K2523	CMM	Valve, 2in Inline Component Maintenance Manual	--	--	0	--	Titchfield, UK	K2523	TO BE WRITTEN
12P0119	--	28-22-00	CMM	2.5 Inch Remote Valve	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
12P0139	--	28-22-05+	CMM	2.5 Inch Remote Valve	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
12P0154	--	28-22-47	CMM	2.5 inch Remote Valve	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
12R0110	--	28-10-02++	CMM	3 inch Shut Off Valve	--	--	0	KC390	Titchfield, UK	K2523	TO BE WRITTEN
1304000-3	--	38-10-61	CMM	PRES CONT SHUT OFF VALVE	01-Sep-81	03-Dec-85	1	A310	Titchfield, UK	K2523	--
132BA06	--	38-3-1++	OM	4IN SP WASTE VALVE	01-Jul-60	--	0	Not Known	Titchfield, UK	K2523	--
132BA11	--	38-30-3	OM	SPV	01-Jul-63	01-Apr-68	3	Not Known	Titchfield, UK	K2523	--
132BA11-1	--	38-30-3	OM	SPV	01-Jul-63	01-Apr-68	3	Not Known	Titchfield, UK	K2523	--
132BE06	--	38-3-1++	OM	4IN SP WASTE VALVE	01-Jul-60	--	0	Not Known	Titchfield, UK	K2523	--
132BE11	--	38-30-3	OM	SPV	01-Jul-63	01-Apr-68	3	Not Known	Titchfield, UK	K2523	--
132BE11-1	--	38-30-3	OM	SPV	01-Jul-63	01-Apr-68	3	Not Known	Titchfield, UK	K2523	--
132EC11	--	38-30-3	OM	SPV	01-Jul-63	01-Apr-68	3	Not Known	Titchfield, UK	K2523	--
132EC11-1	--	38-30-3	OM	SPV	01-Jul-63	01-Apr-68	3	Not Known	Titchfield, UK	K2523	--
132FC06	--	38-3-1++	OM	4IN SP WASTE VALVE	01-Jul-60	--	0	Not Known	Titchfield, UK	K2523	--
132FD06	--	38-3-1++	OM	4IN SP WASTE VALVE	01-Jul-60	--	0	Not Known	Titchfield, UK	K2523	--
132FD11	--	38-30-3	OM	SPV	01-Jul-63	01-Apr-68	3	Not Known	Titchfield, UK	K2523	--
132FD11-1	--	38-30-3	OM	SPV	01-Jul-63	01-Apr-68	3	Not Known	Titchfield, UK	K2523	--
132HF08-1	--	38-30-22	OM	SPV	01-Apr-64	--	0	Not Known	Titchfield, UK	K2523	--
132HF08A	--	38-30-22	OM	SPV	01-Apr-64	--	0	Not Known	Titchfield, UK	K2523	--
132HF11	--	38-30-21	OM	SPV	01-Jul-63	01-Nov-67	4	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
132HF11-1	--	38-30-21	OM	SPV	01-Jul-63	01-Nov-67	4	Not Known	Titchfield, UK	K2523	--
132HF11-2	--	38-30-21	OM	SPV	01-Jul-63	01-Nov-67	4	Not Known	Titchfield, UK	K2523	--
132HG08-1	--	38-30-22	OM	SPV	01-Apr-64	--	0	Not Known	Titchfield, UK	K2523	--
132HG08A	--	38-30-22	OM	SPV	01-Apr-64	--	0	Not Known	Titchfield, UK	K2523	--
132HG11	--	38-30-21	OM	SPV	01-Jul-63	01-Nov-67	4	Not Known	Titchfield, UK	K2523	--
132HG11-1	--	38-30-21	OM	SPV	01-Jul-63	01-Nov-67	4	Not Known	Titchfield, UK	K2523	--
132HG11-2	--	38-30-21	OM	SPV	01-Jul-63	01-Nov-67	4	Not Known	Titchfield, UK	K2523	--
132JF11	--	38-30-1	OM	SPV	05-Dec-69	--	0	Not Known	Titchfield, UK	K2523	--
132KF11	--	38-30-51	OM	SPV	01-Oct-67	17-Oct-86	1	BAC 1-11	Titchfield, UK	K2523	--
132LF11	--	38-30-51	OM	SPV	01-Oct-67	17-Oct-86	1	BAC 1-11	Titchfield, UK	K2523	--
137600-1	--	24-09-53	CMM	ACTUATOR ASSEMBLY	31-Mar-93	--	0	F100	Titchfield, UK	K2523	EATON MANUAL (F100 A/STR)
1380216-2	--	21-52-29	CMM	5IN CHECK VALVE	15-Dec-04	--	0	A380	Titchfield, UK	K2523	HAMILTON SUNDSTRAND
1380226-1	--	21-63-20	CMM	3.5 IN CHECK VALVE	15-Dec-04	30-Aug-08	2	A380	Titchfield, UK	K2523	HAMILTON SUNDSTRAND
1380226-2	--	21-63-20	CMM	3.5 IN CHECK VALVE	15-Dec-04	30-Aug-08	2	A380	Titchfield, UK	K2523	HAMILTON SUNDSTRAND
16-0014	--	47-00-03	CMM	Ram Air Modulating Valve	--	--	0	LEARJET 85	Titchfield, UK	K2523	TO BE WRITTEN
1604130	--	28-10-04	OM	PRESS RELIEF VALVE MK 4	01-Aug-69	07-Nov-05	2	CASA 212, HFB 320 (HANSA JET), MB326, MB339	Titchfield, UK	K2523	--
1604255	--	28-10-04	OM	PRESS RELIEF VALVE MK 4	01-Aug-69	07-Nov-05	2	CASA 212, HFB 320 (HANSA JET), MB326, MB339	Titchfield, UK	K2523	--
1604260	--	28-10-04	OM	PRESS RELIEF VALVE MK 4	01-Aug-69	07-Nov-05	2	CASA 212, HFB 320 (HANSA JET), MB326, MB339	Titchfield, UK	K2523	--
1604265	--	28-10-04	OM	PRESS RELIEF VALVE MK 4	01-Aug-69	07-Nov-05	2	CASA 212, HFB 320 (HANSA JET), MB326, MB339	Titchfield, UK	K2523	--
1604270	--	28-10-04	OM	PRESS RELIEF VALVE MK 4	01-Aug-69	07-Nov-05	2	CASA 212, HFB 320 (HANSA JET), MB326, MB339	Titchfield, UK	K2523	--
1604270	--	28-10-35	OM	PRESS RELIEF VALVE MK 4	01-May-73	07-Nov-05	3	CASA 212	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
1604275	--	28-10-04	OM	PRESS RELIEF VALVE MK 4	01-Aug-69	07-Nov-05	2	CASA 212, HFB 320 (HANSA JET), MB326, MB339	Titchfield, UK	K2523	--
1604280	--	28-10-04	OM	PRESS RELIEF VALVE MK 4	01-Aug-69	07-Nov-05	2	CASA 212, HFB 320 (HANSA JET), MB326, MB339	Titchfield, UK	K2523	--
1608280	--	28-10-5	OM	PRESSURE RELIEF VALVE	01-Jan-65	09-Aug-00	2	YS11	Titchfield, UK	K2523	--
1608305	--	28-20-34	CMM	JETTISON	01-Jul-68	--	0	Not Known	Titchfield, UK	K2523	--
1608450	--	28-10-14	OM	OVERFLOW VALVE	01-Jun-68	01-Apr-88	2	F28	Titchfield, UK	K2523	--
1608516	--	82-10-1	OM	PRESSURE RELIEF VALVE	01-Aug-68	01-Oct-69	1	Not Known	Titchfield, UK	K2523	--
1608550	--	28-10-26	OM	OVERFLOW VALVE	01-Oct-72	01-Oct-72	1	Not Known	Titchfield, UK	K2523	--
1608555	--	28-10-33	OM	OVERFLOW VALVE	01-May-71	09-Apr-13	6	F100, F28	Titchfield, UK	K2523	--
1608565	--	28-10-45	OM	OVERFLOW VALVE	12-Aug-75	08-Oct-12	11	F100, F28, F70	Titchfield, UK	K2523	--
16M0015	--	47-00-03	CMM	Ram Air Modulating Valve	--	--	0	LEARJET 85	Titchfield, UK	K2523	TO BE WRITTEN
16V0028	--	47-32-11	CMM	MODULATING RAM AIR CONTROL VALVE	--	--	0	KC390	Titchfield, UK	K2523	TO BE WRITTEN
1CZ135630A3	--	27-10-02	CMM	CUB JAGUAR ACTUATOR	01-Dec-80	--	0	MATADOR	Titchfield, UK	K2523	--
1CZ135830A	--	24-09-113	OM	ACTUATOR	19-Jan-66	09-Mar-05	6	DART ENGINE	Titchfield, UK	K2523	--
1CZ136080A	--	24-09-113	OM	ACTUATOR	19-Jan-66	09-Mar-05	6	DART ENGINE	Titchfield, UK	K2523	--
1CZ82360-A10	--	24-09-114	CMM	CUB JAGUAR ACTUATOR	04-Jan-66	14-May-69	2	HS 748, NIMROD	Titchfield, UK	K2523	--
1CZ82360-A11	--	24-09-114	CMM	CUB JAGUAR ACTUATOR	04-Jan-66	14-May-69	2	HS 748, NIMROD	Titchfield, UK	K2523	--
20-0005	--	28-13-02++	CMM	VALVE-PRESSURE RELIEF	17-Dec-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	PARKER COMPONENT, previously 47-21-03
20-0015	--	28-13-02++	CMM	VALVE-PRESSURE RELIEF	17-Dec-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	PARKER COMPONENT, previously 47-21-03
20-0020	--	28-13-02++	CMM	VALVE-PRESSURE RELIEF	17-Dec-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	PARKER COMPONENT, previously 47-21-03
20-0034	--	28-13-02++	CMM	VALVE-PRESSURE RELIEF	17-Dec-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	PARKER COMPONENT, previously 47-21-03
20-0047-1100	--	28-25-42	CMM	Check Valve 1 3/4"	15-May-13	17-Oct-16	2	A330, A330 NEO, A340	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
203AA81	--	38-10-60	OM	MULTIWAY SPV	01-Nov-64	14-Aug-08	5	BAC 1-11	Titchfield, UK	K2523	--
203AB81	--	38-10-60	OM	MULTIWAY SPV	01-Nov-64	14-Aug-08	5	BAC 1-11	Titchfield, UK	K2523	--
204BA80	--	38-10-20	OM	MULTIWAY 'T' PORTISPV	01-Jun-69	--	0	Not Known	Titchfield, UK	K2523	--
204CA80	--	38-1-3	OM	SP,MW,V	30-Jul-59	28-Aug-62	2	Not Known	Titchfield, UK	K2523	--
204DB80	--	38-1-3	OM	SP,MW,V	30-Jul-59	28-Aug-62	2	Not Known	Titchfield, UK	K2523	--
204DC80	--	38-10-22+	OM	SP,MW,V (T-PORT)	01-Jun-65	--	0	Not Known	Titchfield, UK	K2523	*EX-SAUNDERS
205BA80	--	38-10-3	OM	SPV	01-Jun-60	05-Mar-65	1	BAe 748	Titchfield, UK	K2523	--
205BR02	--	38-10-1	OM	SP,MW,V	01-Apr-60	01-Oct-63	1	Not Known	Titchfield, UK	K2523	--
205BR04-1	--	38-10-57	OM	M/WAY SPV	01-Sep-63	01-Jun-67	1	BAC 1-11	Titchfield, UK	K2523	--
205CR04-1	--	38-10-56	OM	M/WAY SPV	01-Nov-64	01-Sep-67	2	BAC 1-11	Titchfield, UK	K2523	--
205DR04	--	38-10-57	OM	M/WAY SPV	01-Sep-63	01-Jun-67	1	BAC 1-11	Titchfield, UK	K2523	--
205M1	--	38-10-54	OM	M/WAY SPV	01-Nov-67	01-Mar-68	1	BAC 1-11	Titchfield, UK	K2523	--
206BA83-2	--	38-09-3	OM	SP/MW,V (T-PORT)	01-Mar-66	01-Jul-67	1	Not Known	Titchfield, UK	K2523	Most of the manual is missing
206BA91-2	--	38-09-4	OM	MW SPV	01-Mar-66	01-Jul-67	1	Not Known	Titchfield, UK	K2523	--
208AA92	--	38-10-2+	OM	MW SPV	01-Jun-60	--	0	VANGUARD	Titchfield, UK	K2523	--
208CD82	--	38-09-1+	OM	SPV	01-Nov-60	--	0	VANGUARD	Titchfield, UK	K2523	* EX SAUNDERS
208CD82-1	--	38-09-1+	OM	SPV	01-Nov-60	--	0	VANGUARD	Titchfield, UK	K2523	* EX SAUNDERS
208DD82	--	38-09-2	OM	MULTI-WAY SPV	02-Nov-60	12-Aug-87	1	Not Known	Titchfield, UK	K2523	--
208DD82-1	--	38-09-2	OM	MULTI-WAY SPV	02-Nov-60	12-Aug-87	1	Not Known	Titchfield, UK	K2523	--
20A03	--	29-20-3	OM	SPV	01-Nov-60	22-Apr-11	2	BAe 748	Titchfield, UK	K2523	--
20A03	--	34-10-10	OM	SPV	02-Nov-65	03-Sep-71	1	BAC 1-11	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
20A03	--	34-10-51	OM	SPV	03-Jul-64	02-Nov-65	1	BAC 1-11	Titchfield, UK	K2523	Title page shows May 69
20A04	--	28-09-61	OM	SPV	01-Sep-65	--	0	SHORTS SC7 SKYVAN	Titchfield, UK	K2523	--
20C0003	--	28-24-28	CMM	VALVE-DRAIN	04-Dec-07	26-Jun-17	3	BOEING 787	Titchfield, UK	K2523	--
20G04	--	28-22-21	OM	MANUALLY OPERATED SP AERO VALVE	11-May-62	17-Mar-66	1	Not Known	Titchfield, UK	K2523	Title page shows Jan 69
20K0032	--	28-25-42	CMM	Check Valve 1 3/4"	15-May-13	17-Oct-16	2	A330, A330 NEO, A340	Titchfield, UK	K2523	--
20K0032	--	K2523-28-003	SIL	JET PUMP CHECK VALVE	24-Jun-13	--	0	A330, A340	Titchfield, UK	K2523	--
20P0008	--	28-13-06+	CMM	VALVE-2 1/2IN CHECK	06-May-08	23-Sep-15	2	BOEING 787	Titchfield, UK	K2523	Previously 47-22-04
20P0023	--	28-13-06+	CMM	VALVE-2 1/2IN CHECK	06-May-08	23-Sep-15	2	BOEING 787	Titchfield, UK	K2523	Previously 47-22-04
20R0010	--	20R0016-28-01	SB	Introduction of new valve head	--	--	0	BOEING 787	Titchfield, UK	K2523	TO BE WRITTEN
20R0010	--	28-24-32	CMM	VALVE-3IN CHECK	24-Jul-08	10-Jul-17	2	BOEING 787	Titchfield, UK	K2523	--
20R0016	--	20R0016-28-01	SB	Introduction of new valve head	--	--	0	BOEING 787	Titchfield, UK	K2523	TO BE WRITTEN
20R0016	--	28-24-32	CMM	VALVE-3IN CHECK	24-Jul-08	10-Jul-17	2	BOEING 787	Titchfield, UK	K2523	--
21-0007	--	28-22-04+	CMM	Drain Valve	19-Nov-08	26-Jun-17	4	Boeing 777X, BOEING 787	Titchfield, UK	K2523	--
21-0013	--	28-13-05+	CMM	Drain Valve 1 1/2 inch	15-Nov-08	23-Sep-15	2	BOEING 787	Titchfield, UK	K2523	Previously 47-21-10
212BM82CC	--	28-22-27+	OM	PR,SP,MW MOTORISED	01-Sep-66	01-Sep-71	3	Not Known	Titchfield, UK	K2523	*EX-SAUNDERS
212CB10	--	28-22-23	OM	MW SPV	01-Jun-62	02-Jun-05	3	VARIOUS	Titchfield, UK	K2523	SEE 28-22-23* FOR 208EA11
216CH80P3	--	SL28	OM	SP/MW	01-Jan-58	--	0	Not Known	Titchfield, UK	K2523	--
21F0010	--	28-24-31	CMM	VALVE-3/4IN CHECK	03-Dec-07	23-Sep-15	3	BOEING 787	Titchfield, UK	K2523	--
21F0015	--	SIL-2008-07	SIL	FUEL - TRIM TANK - INTRODUCE NEW CHECK VALVE	20-May-08	--	0	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
21H0005	--	47-22-02	CMM	VALVE-1 1/4IN CHECK	06-May-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	--
21H0028	--	47-32-10+	CMM	NEA Check Valve	--	--	0	MRJ70	Titchfield, UK	K2523	TO BE WRITTEN

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
21K0003	--	47-22-01	CMM	VALVE-1 1/2IN CHECK	02-May-08	23-Sep-15	2	BOEING 787	Titchfield, UK	K2523	--
21K0040	--	28-11-00	CMM	1.5 Inch Check Valve	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
21M0006	--	47-22-03	CMM	VALVE-2IN CHECK ARRESTOR	07-May-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	--
21M0009	--	28-24-27	CMM	VALVE-2IN CHECK	12-May-08	26-Jun-17	3	BOEING 787	Titchfield, UK	K2523	--
21M0017	--	47-22-03	CMM	VALVE-2IN CHECK ARRESTOR	07-May-08	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	--
21M0018	--	28-24-27	CMM	VALVE-2IN CHECK	12-May-08	26-Jun-17	3	BOEING 787	Titchfield, UK	K2523	--
21M0018	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRRT, A318, A319, A320, A321, A320, A320-MRRT, A320	Titchfield, UK	K2523	--
21M0024	--	28-24-43	CMM	Check Valve 2in	31-Mar-10	--	0	A318	Titchfield, UK	K2523	A318 for Marshalls Aerospace
21M0049	--	28-11-03	CMM	2 Inch Check Arrestor Valve	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
21T0012	--	21-63-20	CMM	3.5 IN CHECK VALVE	15-Dec-04	30-Aug-08	2	A380	Titchfield, UK	K2523	HAMILTON SUNDSTRAND
21T0023	--	28-13-07	CMM	(HS) Anti Cross Flow Check Valve	23-Sep-15	23-Sep-15	0	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
21T0041	--	28-25-29	CMM	Anti-Cross Flow Check Valve	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
21V0020	--	36-15-03	CMM	DUCT & NON-RETURN VALVE	28-Sep-01	08-Jan-19	3	A319, A320, A321	Titchfield, UK	K2523	--
21V0020	--	FRH220034V-36-001	SB	DUCT AND NON-RETURN VALVE - VALVE FLAP CRACKING	--	--	0	A319, A320, A321	Titchfield, UK	K2523	CANCELLED
21V0020	--	K2523-36-001	SIL	SIL New NRV in Duct	05-Apr-11	--	0	A319, A320, A321	Titchfield, UK	K2523	--
21V0020	--	K2523-36-002	SIL	Intorduction of New Top Level PN	--	--	0	--	Titchfield, UK	K2523	TO BE WRITTEN
21V0060	--	36-15-04	CMM	Air Non-Return Valve Component Maintenance Manual	--	--	0	A321XLR	Titchfield, UK	K2523	TO BE WRITTEN
23-0001-1100	--	28-24-34	CMM	VALVE-PRES-RELIEF	05-Dec-07	23-Sep-15	3	BOEING 787	Titchfield, UK	K2523	--
2303135	--	28-12-02	OM	FUEL DELIVERY SYSTEM	01-Jan-70	--	0	Not Known	Titchfield, UK	K2523	--
2303180	--	28-12-02	OM	FUEL DELIVERY SYSTEM	01-Jan-70	--	0	Not Known	Titchfield, UK	K2523	--
248800-5	--	28-20-1++	OM	FUEL BOOSTER PUMP AND HOUSING PACKAGE	30-Jun-64	29-Nov-69	3	BAC 1-11	Titchfield, UK	K2523	DUPLICATE ATA NO.

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
248900-6	--	28-20-1++	OM	FUEL BOOSTER PUMP AND HOUSING PACKAGE	30-Jun-64	29-Nov-69	3	BAC 1-11	Titchfield, UK	K2523	DUPLICATE ATA NO.
249000-7	--	28-20-1++	OM	FUEL BOOSTER PUMP AND HOUSING PACKAGE	30-Jun-64	29-Nov-69	3	BAC 1-11	Titchfield, UK	K2523	DUPLICATE ATA NO.
249000-7	--	Pu28-19-2475	SB	TRW 249000-7. Introduction of new pump and housing assembly incorporating a more positive electrical	05-Apr-79	20-Apr-80	1	BAC 1-11	Titchfield, UK	K2523	--
25-0007	--	1157060-28-2	SB	MK 57 Valve Seal Replacement	25-Feb-10	--	0	A300-600, A310	Titchfield, UK	K2523	--
25-0007	--	28-22-69	CMM	MK 57 VALVE ELEMENT	01-Apr-74	10-Jul-15	17	A300, A300-400, A300-600, A310	Titchfield, UK	K2523	--
25-0007	--	SIL-2009-03	SIL	FUEL, OPTIONAL ELEMENT ASSEMBLY	--	--	0	A300, A300-400, A300-600, A310	Titchfield, UK	K2523	CANCELLED
25H0003	--	28-21-34	CMM	REFUEL/DEFUEL VALVE	13-Dec-07	13-Dec-07	0	US101	Titchfield, UK	K2523	--
25P0001	--	25P0001-28-01	SB	REPLACEMENT OF THE FLAPPER VALVE SPRING	--	12-Mar-19	0	BOEING 787	Titchfield, UK	K2523	--
25P0001	--	28-24-20	CMM	ADAPTOR-REFUEL	31-Jan-08	14-Aug-15	1	BOEING 787	Titchfield, UK	K2523	BELONGS TO ZODIAC
25P0001	--	K2523-28-005	SIL	Replace Refuel Adaptor Handle and Linkage Assy	--	--	0	BOEING 787	Titchfield, UK	K2523	TO BE WRITTEN
25P0001	--	K2523-28-011	SIL	FUEL SYSTEM - NEW FLAT SEAL	10-Jan-18	--	0	BOEING 787	Titchfield, UK	K2523	ZODIAC TO AUTHOR
25P0001	--	K2523-28-21	SIL	Service Information Letter - Change of Ownership	19-Nov-21	19-Nov-21	0	BOEING 787	Titchfield, UK	K2523	BASIC MANUAL
25P0002	--	28-24-21	CMM	CAP-REFUEL ADAPTOR	31-Jan-08	31-Oct-09	2	BOEING 787	Titchfield, UK	K2523	INTERTECHNIQUE PART
25R0017	--	28-25-40	CMM	REFUEL COUPLING	06-May-87	26-Apr-18	9	A319, A320, A321	Titchfield, UK	K2523	--
28-0001	--	28-13-04+	CMM	VALVE-VENT DRAIN	01-May-08	31-Mar-11	1	BOEING 787	Titchfield, UK	K2523	Previously 47-21-07
28-0002	--	28-13-03+	CMM	VALVE-VENT FLOAT	31-Mar-11	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	Previously 47-21-05
28-0003	--	28-13-01++	CMM	(HS) VALVE-VENT FLOAT	02-May-08	23-Sep-15	3	BOEING 787	Titchfield, UK	K2523	Formerly 47-21-02
28-0006	--	28-13-03+	CMM	VALVE-VENT FLOAT	31-Mar-11	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	Previously 47-21-05
28-0007	--	28-13-01++	CMM	(HS) VALVE-VENT FLOAT	02-May-08	23-Sep-15	3	BOEING 787	Titchfield, UK	K2523	Formerly 47-21-02
28-0014	--	28-21-45	CMM	Vent Drain Float Valve	31-Mar-10	--	0	A318	Titchfield, UK	K2523	A318 for Marshalls Aerospace
28-0016	--	28-13-03+	CMM	VALVE-VENT FLOAT	31-Mar-11	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	Previously 47-21-05

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
28-0017	--	28-13-01++	CMM	(HS) VALVE-VENT FLOAT	02-May-08	23-Sep-15	3	BOEING 787	Titchfield, UK	K2523	Formerly 47-21-02
28-0018	--	28-13-03+	CMM	VALVE-VENT FLOAT	31-Mar-11	23-Sep-15	1	BOEING 787	Titchfield, UK	K2523	Previously 47-21-05
28-0020	--	28-13-10	CMM	Float Valve	15-Apr-11	01-Sep-17	1	Boeing 747-8	Titchfield, UK	K2523	--
28-0028	--	28-13-00	CMM	Vent Float Valve	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
28-0029	--	28-13-11	CMM	Vent Float Valve	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
28-0030	--	28-13-12	CMM	Vent Drain Valve	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
28-0033	--	28-12-44	CMM	Float Vent Valve	24-Oct-18	28-Mar-19	1	A320, A330	Titchfield, UK	K2523	--
28-0033	--	K2523-28-013	SIL	Introduction of new FVV	05-Jun-18	05-Jun-18	0	A320, A330	Titchfield, UK	K2523	--
2980030-101	--	28-20-60+	ACMM	COLLECTOR CELL JET PUMP	31-Dec-01	--	0	A340-500, A340-600	Titchfield, UK	K2523	PARKER HANNIFIN MANUAL
2980031-101	--	28-20-61++	ACMM	FWD TRANSFER PUMP	31-Dec-01	--	0	A340-500, A340-600	Titchfield, UK	K2523	PARKER HANNIFIN MANUAL
2980046-101	--	28-20-54+	CMM	FUEL CHECK VALVE	19-Sep-01	--	0	A340-500, A340-600	Titchfield, UK	K2523	PARKER HANNIFIN MANUAL
30042-0000-0102	--	28-46-34	CMM	A320 CONTROL UNIT	01-Aug-87	--	0	Not Known	Titchfield, UK	K2523	NOT UPDATED
30042-0000-0201	--	28-46-34	CMM	A320 CONTROL UNIT	01-Aug-87	--	0	Not Known	Titchfield, UK	K2523	NOT UPDATED
3022109-000	--	29-20-01+++	CMM	Selector Valve (Eaton Vickers Owned)	--	--	0	A380	Titchfield, UK	K2523	USE ALT PUB NUMBER INSTEAD
3022109-000	--	29-31-01+	CMM	Selector Valve (Eaton Vickers)	02-Jan-08	--	0	A380	Titchfield, UK	K2523	--
3032793-005	--	PSD-377	CMM	EDP Minor Rework	12-Aug-21	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
3342860-64	--	38-10-43	CMM	MOT WATER VALVE	01-Jun-81	16-Jan-19	5	A300, A300-400, A300-600, A310	Titchfield, UK	K2523	--
34-0001	--	28-11-20	CMM	VALVE BODY-TELL TALE	03-Jun-08	29-Feb-12	2	BOEING 787	Titchfield, UK	K2523	REMOVE CDCCL STATUS AT REV 2
34-0001	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320XLR, A320XLR-MRTT, A320XLR-MRTT	Titchfield, UK	K2523	--
34-0003	--	28-11-21	CMM	VALVE BODY	28-Feb-08	12-Jun-15	3	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
34-0005	--	28-11-22	CMM	VALVE (AND ACTUATION MECHANISM)	05-Dec-07	23-Sep-15	2	BOEING 787	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
34-0012	--	28-11-21	CMM	VALVE BODY	28-Feb-08	12-Jun-15	3	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
34-0012	--	K2523-28-015	SIL	INTRODUCTION OF NEW DRAIN VALVES	--	--	0	BOEING 787	Titchfield, UK	K2523	TO BE WRITTEN
34-0015	--	28-11-24	CMM	VALVE	31-Mar-10	--	0	A318	Titchfield, UK	K2523	A318 for Marshalls Aerospace
34-0016	--	28-11-23	CMM	Fuel Drain Valve Sump	31-Mar-10	--	0	A318	Titchfield, UK	K2523	A318 for Marshalls Aerospace
34-0018	--	28-11-32	CMM	Indirect Drain Valve	--	--	0	HA-420	Titchfield, UK	K2523	TO BE WRITTEN
34-0020	--	28-11-32	CMM	Indirect Drain Valve	--	--	0	HA-420	Titchfield, UK	K2523	TO BE WRITTEN
34-0021	--	28-11-21	CMM	VALVE BODY	28-Feb-08	12-Jun-15	3	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
34-0021	--	K2523-28-015	SIL	INTRODUCTION OF NEW DRAIN VALVES	--	--	0	BOEING 787	Titchfield, UK	K2523	TO BE WRITTEN
34-0029	--	28-11-13	CMP	Valve	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
34-0030	--	28-11-05	CMM	Sump Drain Valve Body	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
34-0032	--	28-11-47	CMM	Sump Drain Valve Body	--	--	0	Boeing 777X	Titchfield, UK	K2523	--
34-0040	--	28-11-21	CMM	VALVE BODY	28-Feb-08	12-Jun-15	3	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
34-0040	--	K2523-28-015	SIL	INTRODUCTION OF NEW DRAIN VALVES	--	--	0	BOEING 787	Titchfield, UK	K2523	TO BE WRITTEN
34-0041	--	28-11-21	CMM	VALVE BODY	28-Feb-08	12-Jun-15	3	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
34-0041	--	K2523-28-015	SIL	INTRODUCTION OF NEW DRAIN VALVES	--	--	0	BOEING 787	Titchfield, UK	K2523	TO BE WRITTEN
3408155	--	28-20-20	OM	MK8 PROBE NOZZLE ASSY	01-Oct-67	--	0	Not Known	Titchfield, UK	K2523	--
3408170-240	--	28-20-35	CMM	MK8 PROBE NOZZLE ASSY	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3408290	--	28-22-78	CMM	PROBE NOZZLE WITH NRV	19-Nov-98	18-Aug-08	2	AV8A	Titchfield, UK	K2523	OM SUPERSEDED BY THIS
3408320	--	28-22-78	CMM	PROBE NOZZLE WITH NRV	19-Nov-98	18-Aug-08	2	AV8A	Titchfield, UK	K2523	OM SUPERSEDED BY THIS
3502000	--	28-M2-3	OM	MK2 FLOAT SWITCH	01-Dec-60	01-Jan-61	1	BAC 1-11	Titchfield, UK	K2523	--
3502120	--	28-09-45	OM	MK 2C AND 4C FLOAT SWITCHES	01-Nov-69	26-Jul-17	3	BAC 1-11	Titchfield, UK	K2523	BASIC MANUAL

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3502120	--	28-09-47	OM	MK 2 AND MK 4 FLOAT SWITCHES	01-Dec-66	--	0	BAC 1-11	Titchfield, UK	K2523	BASIC MANUAL
3502120	--	28-1-3455	SB	FLOAT SW - REDUCTION OF FRICTION	15-Mar-65	--	0	Not Known	Titchfield, UK	K2523	--
3502120	--	28-40-4263	SB	Mk.2 and Mk.4 Float Switches (SB)	01-Feb-73	--	0	--	Titchfield, UK	K2523	*OUT OF PRINT
3502120-44	--	28-40-72	OM	MK2 FLOAT SWITCHES	01-Dec-66	18-Jul-03	1	BAC 1-11	Titchfield, UK	K2523	--
3502120-45	--	28-40-72	OM	MK2 FLOAT SWITCHES	01-Dec-66	18-Jul-03	1	BAC 1-11	Titchfield, UK	K2523	--
3502120-46	--	28-40-72	OM	MK2 FLOAT SWITCHES	01-Dec-66	18-Jul-03	1	BAC 1-11	Titchfield, UK	K2523	--
3502120-47	--	28-40-72	OM	MK2 FLOAT SWITCHES	01-Dec-66	18-Jul-03	1	BAC 1-11	Titchfield, UK	K2523	--
3502120-57	--	28-40-72	OM	MK2 FLOAT SWITCHES	01-Dec-66	18-Jul-03	1	BAC 1-11	Titchfield, UK	K2523	--
3502120-63	--	28-09-45	OM	MK 2C AND 4C FLOAT SWITCHES	01-Nov-69	26-Jul-17	3	BAC 1-11	Titchfield, UK	K2523	BASIC MANUAL
3502120-63	--	28-40-70	OM	MK 2C & 4C FLOAT SWITCHES	01-Jan-69	24-Jul-17	6	BAC 1-11	Titchfield, UK	K2523	--
3502120-64	--	28-41-23	CMM	Mk. 2 FLOAT SWITCH SERIES 64	01-Sep-78	--	0	--	Titchfield, UK	K2523	--
3504100	--	28-09-45	OM	MK 2C AND 4C FLOAT SWITCHES	01-Nov-69	26-Jul-17	3	BAC 1-11	Titchfield, UK	K2523	BASIC MANUAL
3504100	--	28-09-47	OM	MK 2 AND MK 4 FLOAT SWITCHES	01-Dec-66	--	0	BAC 1-11	Titchfield, UK	K2523	BASIC MANUAL
3504100	--	28-1-3455	SB	FLOAT SW - REDUCTION OF FRICTION	15-Mar-65	--	0	Not Known	Titchfield, UK	K2523	--
3504100	--	28-40-4263	SB	Mk.2 and Mk.4 Float Switches (SB)	01-Feb-73	--	0	--	Titchfield, UK	K2523	*OUT OF PRINT
3504100	--	28-M4-3	OM	MK 4 FLOAT SWITCH	01-Mar-60	01-Feb-65	2	BAC 1-11	Titchfield, UK	K2523	--
3504100-105	--	28-20-84	OM	MK4 FLOAT SWITCHES	01-Nov-67	--	0	COMET 4	Titchfield, UK	K2523	--
3504100-106	--	28-20-84	OM	MK4 FLOAT SWITCHES	01-Nov-67	--	0	COMET 4	Titchfield, UK	K2523	--
3504100-107	--	28-20-84	OM	MK4 FLOAT SWITCHES	01-Nov-67	--	0	COMET 4	Titchfield, UK	K2523	--
3504100-11	--	28-40-66	OM	MK 4 FLOAT SWITCHES	01-May-65	--	0	Not Known	Titchfield, UK	K2523	--
3504100-115	--	28-20-83	OM	MK 4 FLOAT SWITCH	01-Dec-82	21-Dec-04	3	MB326	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3504100-13	--	28-40-74	OM	MK 4 FLOAT SWITCH	01-Mar-67	01-Mar-87	2	HJT16 KIRAN	Titchfield, UK	K2523	--
3504100-135	--	28-12-05	OM	MK 4C FLOAT SWITCH	01-May-70	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3504100-147	--	28-M4-147	OM	MK4 FLOAT SWITCH	01-Oct-61	--	0	Not Known	Titchfield, UK	K2523	--
3504100-15	--	28-M4-15	OM	MK 4 FLOAT SWITCH	01-May-60	--	0	Not Known	Titchfield, UK	K2523	--
3504100-153	--	28-40-74	OM	MK 4 FLOAT SWITCH	01-Mar-67	01-Mar-87	2	HJT16 KIRAN	Titchfield, UK	K2523	--
3504100-154	--	28-M4-154	OM	MK4 FLOAT SWITCH	01-Oct-61	--	0	Not Known	Titchfield, UK	K2523	--
3504100-157	--	28-M4-157	OM	MK4 FLOAT SWITCH	01-Oct-60	--	0	BAC 1-11	Titchfield, UK	K2523	--
3504100-158	--	28-M4-158	OM	MK4 FLOAT SWITCH	01-Jun-61	--	0	Not Known	Titchfield, UK	K2523	--
3504100-159	--	28-M4-159	OM	MK4 FLOAT SWITCH	01-Jun-61	--	0	Not Known	Titchfield, UK	K2523	--
3504100-168	--	28-20-83	OM	MK 4 FLOAT SWITCH	01-Dec-82	21-Dec-04	3	MB326	Titchfield, UK	K2523	--
3504100-171	--	28-20-84	OM	MK4 FLOAT SWITCHES	01-Nov-67	--	0	COMET 4	Titchfield, UK	K2523	--
3504100-172	--	28-20-84	OM	MK4 FLOAT SWITCHES	01-Nov-67	--	0	COMET 4	Titchfield, UK	K2523	--
3504100-174	--	28-12-05	OM	MK 4C FLOAT SWITCH	01-May-70	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3504100-2	--	28-41-16	OM	MK 4C FLOAT SWITCH	01-Aug-75	--	0	Not Known	Titchfield, UK	K2523	--
3504100-202	--	28-M4-202	OM	MK4 FLOAT SWITCH	01-Jun-63	--	0	BAC 1-11	Titchfield, UK	K2523	--
3504100-203	--	28-M4-202	OM	MK4 FLOAT SWITCH	01-Jun-63	--	0	BAC 1-11	Titchfield, UK	K2523	--
3504100-204	--	28-M4-204	OM	MK4 FLOAT SWITCHES	01-May-62	--	0	Not Known	Titchfield, UK	K2523	--
3504100-207	--	28-40-55	OM	MK4 FLOAT SWITCHES	01-Feb-65	--	0	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3504100-209	--	28-40-66	OM	MK 4 FLOAT SWITCHES	01-May-65	--	0	Not Known	Titchfield, UK	K2523	--
3504100-210	--	28-40-20	OM	MK4 FLOAT SWITCHES	01-Apr-69	04-Jan-05	1	BAC 1-11	Titchfield, UK	K2523	--
3504100-211	--	28-40-20	OM	MK4 FLOAT SWITCHES	01-Apr-69	04-Jan-05	1	BAC 1-11	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3504100-213	--	28-40-20	OM	MK4 FLOAT SWITCHES	01-Apr-69	04-Jan-05	1	BAC 1-11	Titchfield, UK	K2523	--
3504100-214	--	28-40-20	OM	MK4 FLOAT SWITCHES	01-Apr-69	04-Jan-05	1	BAC 1-11	Titchfield, UK	K2523	--
3504100-217	--	28-40-20	OM	MK4 FLOAT SWITCHES	01-Apr-69	04-Jan-05	1	BAC 1-11	Titchfield, UK	K2523	--
3504100-219	--	28-40-85	CMM	MK4C FLOAT SWITCHES	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3504100-220	--	28-40-85	CMM	MK4C FLOAT SWITCHES	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3504100-221	--	28-40-85	CMM	MK4C FLOAT SWITCHES	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3504100-222	--	28-40-85	CMM	MK4C FLOAT SWITCHES	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3504100-223	--	28-40-85	CMM	MK4C FLOAT SWITCHES	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3504100-224	--	28-40-85	CMM	MK4C FLOAT SWITCHES	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3504100-225	--	28-40-85	CMM	MK4C FLOAT SWITCHES	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3504100-226	--	28-40-85	CMM	MK4C FLOAT SWITCHES	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3504100-227	--	28-40-20	OM	MK4 FLOAT SWITCHES	01-Apr-69	04-Jan-05	1	BAC 1-11	Titchfield, UK	K2523	--
3504100-236	--	28-40-78	CMM	MK4C FLOAT SWITCH	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3504100-238	--	28-17-4263-451	SB	FLOAT SW - INTRO OF NEW MICROSWITCH	26-Sep-68	01-Oct-69	1	Not Known	Titchfield, UK	K2523	--
3504100-238	--	28-40-21	OM	MK FLOAT SWITCH	01-Apr-66	--	0	BAC 1-11	Titchfield, UK	K2523	--
3504100-24	--	28-40-47	OM	MK 4 FLOAT SWITCH	01-Mar-66	--	0	Not Known	Titchfield, UK	K2523	Original Scanned
3504100-240	--	28-40-55	OM	MK4 FLOAT SWITCHES	01-Feb-65	--	0	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3504100-245	--	28-M4-245	OM	MK4 FLOAT SWITCH	01-Aug-64	--	0	Not Known	Titchfield, UK	K2523	--
3504100-246	--	28-40-65	OM	MK 4C FLOAT SWITCH	01-Nov-77	01-Nov-77	2	MB326	Titchfield, UK	K2523	--
3504100-247	--	28-40-64	OM	MK4 FLOAT SWITCH	01-Mar-65	--	0	Not Known	Titchfield, UK	K2523	--
3504100-249	--	28-40-11	OM	MK4 FLOAT SWITCH	01-Sep-65	--	0	BAC 1-11	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3504100-251	--	28-09-45	OM	MK 2C AND 4C FLOAT SWITCHES	01-Nov-69	26-Jul-17	3	BAC 1-11	Titchfield, UK	K2523	BASIC MANUAL
3504100-251	--	28-40-70	OM	MK 2C & 4C FLOAT SWITCHES	01-Jan-69	24-Jul-17	6	BAC 1-11	Titchfield, UK	K2523	--
3504100-252	--	28-40-11	OM	MK4 FLOAT SWITCH	01-Sep-65	--	0	BAC 1-11	Titchfield, UK	K2523	--
3504100-253	--	28-09-45	OM	MK 2C AND 4C FLOAT SWITCHES	01-Nov-69	26-Jul-17	3	BAC 1-11	Titchfield, UK	K2523	BASIC MANUAL
3504100-253	--	28-40-70	OM	MK 2C & 4C FLOAT SWITCHES	01-Jan-69	24-Jul-17	6	BAC 1-11	Titchfield, UK	K2523	--
3504100-255	--	28-41-21	OM	MK4 FLOAT SWITCH	01-Mar-74	--	0	Not Known	Titchfield, UK	K2523	--
3504100-256	--	28-41-22	OM	MK4 FLOAT SWITCH	01-Mar-74	--	0	Not Known	Titchfield, UK	K2523	--
3504100-266	--	28-09-45	OM	MK 2C AND 4C FLOAT SWITCHES	01-Nov-69	26-Jul-17	3	BAC 1-11	Titchfield, UK	K2523	BASIC MANUAL
3504100-266	--	28-40-70	OM	MK 2C & 4C FLOAT SWITCHES	01-Jan-69	24-Jul-17	6	BAC 1-11	Titchfield, UK	K2523	--
3504100-267	--	28-09-45	OM	MK 2C AND 4C FLOAT SWITCHES	01-Nov-69	26-Jul-17	3	BAC 1-11	Titchfield, UK	K2523	BASIC MANUAL
3504100-267	--	28-40-70	OM	MK 2C & 4C FLOAT SWITCHES	01-Jan-69	24-Jul-17	6	BAC 1-11	Titchfield, UK	K2523	--
3504100-268	--	28-09-45	OM	MK 2C AND 4C FLOAT SWITCHES	01-Nov-69	26-Jul-17	3	BAC 1-11	Titchfield, UK	K2523	BASIC MANUAL
3504100-268	--	28-40-70	OM	MK 2C & 4C FLOAT SWITCHES	01-Jan-69	24-Jul-17	6	BAC 1-11	Titchfield, UK	K2523	--
3504100-269	--	28-09-45	OM	MK 2C AND 4C FLOAT SWITCHES	01-Nov-69	26-Jul-17	3	BAC 1-11	Titchfield, UK	K2523	BASIC MANUAL
3504100-269	--	28-40-70	OM	MK 2C & 4C FLOAT SWITCHES	01-Jan-69	24-Jul-17	6	BAC 1-11	Titchfield, UK	K2523	--
3504100-270	--	28-09-45	OM	MK 2C AND 4C FLOAT SWITCHES	01-Nov-69	26-Jul-17	3	BAC 1-11	Titchfield, UK	K2523	BASIC MANUAL
3504100-270	--	28-40-70	OM	MK 2C & 4C FLOAT SWITCHES	01-Jan-69	24-Jul-17	6	BAC 1-11	Titchfield, UK	K2523	--
3504100-271	--	28-09-45	OM	MK 2C AND 4C FLOAT SWITCHES	01-Nov-69	26-Jul-17	3	BAC 1-11	Titchfield, UK	K2523	BASIC MANUAL
3504100-271	--	28-40-70	OM	MK 2C & 4C FLOAT SWITCHES	01-Jan-69	24-Jul-17	6	BAC 1-11	Titchfield, UK	K2523	--
3504100-272	--	28-09-45	OM	MK 2C AND 4C FLOAT SWITCHES	01-Nov-69	26-Jul-17	3	BAC 1-11	Titchfield, UK	K2523	BASIC MANUAL
3504100-272	--	28-40-70	OM	MK 2C & 4C FLOAT SWITCHES	01-Jan-69	24-Jul-17	6	BAC 1-11	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3504100-273	--	28-09-45	OM	MK 2C AND 4C FLOAT SWITCHES	01-Nov-69	26-Jul-17	3	BAC 1-11	Titchfield, UK	K2523	BASIC MANUAL
3504100-273	--	28-40-70	OM	MK 2C & 4C FLOAT SWITCHES	01-Jan-69	24-Jul-17	6	BAC 1-11	Titchfield, UK	K2523	--
3504100-274	--	28-40-69	OM	MK4 FLOAT SWITCH	01-Jul-67	--	0	Not Known	Titchfield, UK	K2523	--
3504100-276	--	28-40-76	OM	MK4C FLOAT SWITCH	01-Oct-69	15-Dec-04	2	BAC 1-11	Titchfield, UK	K2523	--
3504100-278	--	28-20-83	OM	MK 4 FLOAT SWITCH	01-Dec-82	21-Dec-04	3	MB326	Titchfield, UK	K2523	--
3504100-279	--	28-41-67	OM	MK4 FLOAT SWITCH	01-Sep-78	--	0	Not Known	Titchfield, UK	K2523	--
3504100-283	--	28-41-02	CMM	MK4 FLOAT SWITCH	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3504100-286	--	28-41-05	OM	MK4 FLOAT SWITCH	01-Jan-71	01-Apr-88	2	BAC 1-11	Titchfield, UK	K2523	--
3504100-288	--	28-41-48	OM	MK4 FLOAT SWITCHES	01-Jul-76	--	0	Not Known	Titchfield, UK	K2523	--
3504100-289	--	28-41-48	OM	MK4 FLOAT SWITCHES	01-Jul-76	--	0	Not Known	Titchfield, UK	K2523	--
3504100-38	--	28-41-17	OM	MK 4 FLOAT SWITCH	01-Aug-75	--	0	Not Known	Titchfield, UK	K2523	Scanned Original
3504100-43	--	28-40-68	OM	MK 4 FLOAT SWITCH	01-Oct-66	--	0	Not Known	Titchfield, UK	K2523	Original Scanned
3504100-47	--	28-41-18	OM	MK 4 FLOAT SWITCH	01-Jul-75	01-Jan-87	1	Not Known	Titchfield, UK	K2523	--
3504100-81	--	28-40-77	OM	MK 4 FLOAT SWITCH	01-Jun-67	--	0	Not Known	Titchfield, UK	K2523	--
3504100-90	--	28-M4-90	OM	MK 4 FLOAT SWITCH	01-Apr-60	--	0	Not Known	Titchfield, UK	K2523	--
3504100-91	--	28-M4-91	OM	MK 4 FLOAT SWITCH	01-May-60	--	0	Not Known	Titchfield, UK	K2523	--
3504100-95	--	28-12-05	OM	MK 4C FLOAT SWITCH	01-May-70	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3504100-99	--	28-M4-99	OM	MK4 FLOAT SWITCH	01-Apr-60	--	0	Not Known	Titchfield, UK	K2523	--
3508000	--	28-40-40	OM	FLUID LEVEL MAGNETIC INDICATOR	01-Aug-67	18-Sep-97	3	BAC 1-11, F27, F28	Titchfield, UK	K2523	--
3508000-1	--	28-40-32	OM	FLUID LEVEL MAGNETIC INDICATOR	01-Dec-65	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-105	--	28-40-50	OM	FLUID LEVEL IND (MAGNETIC)	01-Oct-65	23-Jul-07	3	BAC 1-11	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508000-106	--	28-40-37	OM	FLUID LEVEL IND (MAGNETIC)	01-Jun-68	24-Oct-03	8	F27	Titchfield, UK	K2523	--
3508000-109	--	28-40-39	OM	FLUID LEVEL INDICATOR (MAGNETIC)	01-Oct-65	01-Aug-87	2	Not Known	Titchfield, UK	K2523	--
3508000-110	--	28-40-39	OM	FLUID LEVEL INDICATOR (MAGNETIC)	01-Oct-65	01-Aug-87	2	Not Known	Titchfield, UK	K2523	--
3508000-111	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-112	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-113	--	28-29-4336-357	SB	MFLI - SURPLUS GRADUATIONS	01-Nov-70	--	0	VC10	Titchfield, UK	K2523	--
3508000-113	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-114	--	28-29-4336-357	SB	MFLI - SURPLUS GRADUATIONS	01-Nov-70	--	0	VC10	Titchfield, UK	K2523	--
3508000-114	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-115	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-116	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-117	--	28-29-4336-357	SB	MFLI - SURPLUS GRADUATIONS	01-Nov-70	--	0	VC10	Titchfield, UK	K2523	--
3508000-117	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-118	--	28-29-4336-357	SB	MFLI - SURPLUS GRADUATIONS	01-Nov-70	--	0	VC10	Titchfield, UK	K2523	--
3508000-118	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-121	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-122	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-123	--	28-29-4336-357	SB	MFLI - SURPLUS GRADUATIONS	01-Nov-70	--	0	VC10	Titchfield, UK	K2523	--
3508000-123	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-124	--	28-29-4336-357	SB	MFLI - SURPLUS GRADUATIONS	01-Nov-70	--	0	VC10	Titchfield, UK	K2523	--
3508000-124	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508000-127	--	28-29-4336-357	SB	MFLI - SURPLUS GRADUATIONS	01-Nov-70	--	0	VC10	Titchfield, UK	K2523	--
3508000-127	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-128	--	28-29-4336-357	SB	MFLI - SURPLUS GRADUATIONS	01-Nov-70	--	0	VC10	Titchfield, UK	K2523	--
3508000-128	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-129	--	28-29-4336-357	SB	MFLI - SURPLUS GRADUATIONS	01-Nov-70	--	0	VC10	Titchfield, UK	K2523	--
3508000-129	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-130	--	28-29-4336-357	SB	MFLI - SURPLUS GRADUATIONS	01-Nov-70	--	0	VC10	Titchfield, UK	K2523	--
3508000-130	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-131	--	28-29-4336-357	SB	MFLI - SURPLUS GRADUATIONS	01-Nov-70	--	0	VC10	Titchfield, UK	K2523	--
3508000-131	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-132	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-133	--	28-40-59	OM	FLUID LEVEL IND MAGNETIC	01-Oct-65	01-Aug-87	3	Not Known	Titchfield, UK	K2523	--
3508000-141	--	28-40-50	OM	FLUID LEVEL IND (MAGNETIC)	01-Oct-65	23-Jul-07	3	BAC 1-11	Titchfield, UK	K2523	--
3508000-142	--	28-40-50	OM	FLUID LEVEL IND (MAGNETIC)	01-Oct-65	23-Jul-07	3	BAC 1-11	Titchfield, UK	K2523	--
3508000-143	--	28-40-50	OM	FLUID LEVEL IND (MAGNETIC)	01-Oct-65	23-Jul-07	3	BAC 1-11	Titchfield, UK	K2523	--
3508000-144	--	28-40-50	OM	FLUID LEVEL IND (MAGNETIC)	01-Oct-65	23-Jul-07	3	BAC 1-11	Titchfield, UK	K2523	--
3508000-145	--	28-40-37	OM	FLUID LEVEL IND (MAGNETIC)	01-Jun-68	24-Oct-03	8	F27	Titchfield, UK	K2523	--
3508000-146	--	28-40-39	OM	FLUID LEVEL INDICATOR (MAGNETIC)	01-Oct-65	01-Aug-87	2	Not Known	Titchfield, UK	K2523	--
3508000-147	--	28-40-50	OM	FLUID LEVEL IND (MAGNETIC)	01-Oct-65	23-Jul-07	3	BAC 1-11	Titchfield, UK	K2523	--
3508000-148	--	28-40-50	OM	FLUID LEVEL IND (MAGNETIC)	01-Oct-65	23-Jul-07	3	BAC 1-11	Titchfield, UK	K2523	--
3508000-149	--	28-40-50	OM	FLUID LEVEL IND (MAGNETIC)	01-Oct-65	23-Jul-07	3	BAC 1-11	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508000-149	--	28-40-50	OM	FLUID LEVEL IND (MAGNETIC)	01-Oct-65	23-Jul-07	3	BAC 1-11	Titchfield, UK	K2523	--
3508000-150	--	28-40-50	OM	FLUID LEVEL IND (MAGNETIC)	01-Oct-65	23-Jul-07	3	BAC 1-11	Titchfield, UK	K2523	--
3508000-151	--	28-40-50	OM	FLUID LEVEL IND (MAGNETIC)	01-Oct-65	23-Jul-07	3	BAC 1-11	Titchfield, UK	K2523	--
3508000-152	--	28-40-39	OM	FLUID LEVEL INDICATOR (MAGNETIC)	01-Oct-65	01-Aug-87	2	Not Known	Titchfield, UK	K2523	--
3508000-153	--	28-2-4336-181	SB	MFLI - LONGER SCREWS ATTACHING COVER	20-Jul-65	--	0	Not Known	Titchfield, UK	K2523	--
3508000-153	--	28-40-59	OM	FLUID LEVEL IND MAGNETIC	01-Oct-65	01-Aug-87	3	Not Known	Titchfield, UK	K2523	--
3508000-154	--	28-2-4336-181	SB	MFLI - LONGER SCREWS ATTACHING COVER	20-Jul-65	--	0	Not Known	Titchfield, UK	K2523	--
3508000-154	--	28-40-59	OM	FLUID LEVEL IND MAGNETIC	01-Oct-65	01-Aug-87	3	Not Known	Titchfield, UK	K2523	--
3508000-155	--	28-2-4336-181	SB	MFLI - LONGER SCREWS ATTACHING COVER	20-Jul-65	--	0	Not Known	Titchfield, UK	K2523	--
3508000-155	--	28-40-59	OM	FLUID LEVEL IND MAGNETIC	01-Oct-65	01-Aug-87	3	Not Known	Titchfield, UK	K2523	--
3508000-156	--	28-40-49	OM	MAG FLUID LEVEL IND	01-Sep-64	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-157	--	28-29-4336-357	SB	MFLI - SURPLUS GRADUATIONS	01-Nov-70	--	0	VC10	Titchfield, UK	K2523	--
3508000-157	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-158	--	28-29-4336-357	SB	MFLI - SURPLUS GRADUATIONS	01-Nov-70	--	0	VC10	Titchfield, UK	K2523	--
3508000-158	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-159	--	28-29-4336-357	SB	MFLI - SURPLUS GRADUATIONS	01-Nov-70	--	0	VC10	Titchfield, UK	K2523	--
3508000-159	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-160	--	28-29-4336-357	SB	MFLI - SURPLUS GRADUATIONS	01-Nov-70	--	0	VC10	Titchfield, UK	K2523	--
3508000-160	--	28-40-42	OM	FLUID LEVEL INDICATORS MAG	01-Dec-64	15-Sep-97	4	BAC 1-11	Titchfield, UK	K2523	Original Scanned
3508000-161	--	28-2-4336-181	SB	MFLI - LONGER SCREWS ATTACHING COVER	20-Jul-65	--	0	Not Known	Titchfield, UK	K2523	--
3508000-161	--	28-40-59	OM	FLUID LEVEL IND MAGNETIC	01-Oct-65	01-Aug-87	3	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508000-161	--	28-5-40-59	SB	MFLI - MARKING OF GRADUATED TUBE	15-Aug-66	--	0	Not Known	Titchfield, UK	K2523	--
3508000-162	--	28-2-4336-181	SB	MFLI - LONGER SCREWS ATTACHING COVER	20-Jul-65	--	0	Not Known	Titchfield, UK	K2523	--
3508000-162	--	28-40-59	OM	FLUID LEVEL IND MAGNETIC	01-Oct-65	01-Aug-87	3	Not Known	Titchfield, UK	K2523	--
3508000-162	--	28-5-40-59	SB	MFLI - MARKING OF GRADUATED TUBE	15-Aug-66	--	0	Not Known	Titchfield, UK	K2523	--
3508000-163	--	28-2-4336-181	SB	MFLI - LONGER SCREWS ATTACHING COVER	20-Jul-65	--	0	Not Known	Titchfield, UK	K2523	--
3508000-163	--	28-40-59	OM	FLUID LEVEL IND MAGNETIC	01-Oct-65	01-Aug-87	3	Not Known	Titchfield, UK	K2523	--
3508000-163	--	28-5-40-59	SB	MFLI - MARKING OF GRADUATED TUBE	15-Aug-66	--	0	Not Known	Titchfield, UK	K2523	--
3508000-164	--	28-2-4336-181	SB	MFLI - LONGER SCREWS ATTACHING COVER	20-Jul-65	--	0	Not Known	Titchfield, UK	K2523	--
3508000-164	--	28-40-59	OM	FLUID LEVEL IND MAGNETIC	01-Oct-65	01-Aug-87	3	Not Known	Titchfield, UK	K2523	--
3508000-164	--	28-5-40-59	SB	MFLI - MARKING OF GRADUATED TUBE	15-Aug-66	--	0	Not Known	Titchfield, UK	K2523	--
3508000-176	--	28-40-62	OM	FLUID LEVEL IND MAG	01-May-65	01-Aug-87	2	HFB 320 (HANSA JET)	Titchfield, UK	K2523	Original Scanned
3508000-177	--	28-40-34	OM	FLUID LEVEL IND MAG	01-Jun-68	31-Jul-03	7	F28	Titchfield, UK	K2523	Original Scanned
3508000-178	--	28-40-34	OM	FLUID LEVEL IND MAG	01-Jun-68	31-Jul-03	7	F28	Titchfield, UK	K2523	Original Scanned
3508000-180	--	28-40-43	OM	MFLI	01-Feb-66	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-181	--	28-40-43	OM	MFLI	01-Feb-66	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-193	--	28-40-94	OM	FLUID LEVEL IND MAG	01-Aug-69	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-194	--	28-40-94	OM	FLUID LEVEL IND MAG	01-Aug-69	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-195	--	28-40-94	OM	FLUID LEVEL IND MAG	01-Aug-69	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-196	--	28-40-94	OM	FLUID LEVEL IND MAG	01-Aug-69	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-197	--	28-40-34	OM	FLUID LEVEL IND MAG	01-Jun-68	31-Jul-03	7	F28	Titchfield, UK	K2523	Original Scanned
3508000-198	--	28-40-34	OM	FLUID LEVEL IND MAG	01-Jun-68	31-Jul-03	7	F28	Titchfield, UK	K2523	Original Scanned

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508000-2	--	28-40-32	OM	FLUID LEVEL MAGNETIC INDICATOR	01-Dec-65	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-200	--	28-40-41	CMM	Magnetic Fluid Level Indicators	--	--	0	C27J	Titchfield, UK	K2523	TO BE WRITTEN
3508000-200	--	28-40-89	OM	FLUID LEVEL IND MAG	01-Aug-69	01-Aug-87	1	G222	Titchfield, UK	K2523	--
3508000-201	--	28-40-41	CMM	Magnetic Fluid Level Indicators	--	--	0	C27J	Titchfield, UK	K2523	TO BE WRITTEN
3508000-201	--	28-40-89	OM	FLUID LEVEL IND MAG	01-Aug-69	01-Aug-87	1	G222	Titchfield, UK	K2523	--
3508000-202	--	28-40-41	CMM	Magnetic Fluid Level Indicators	--	--	0	C27J	Titchfield, UK	K2523	TO BE WRITTEN
3508000-202	--	28-40-89	OM	FLUID LEVEL IND MAG	01-Aug-69	01-Aug-87	1	G222	Titchfield, UK	K2523	--
3508000-205	--	28-40-83	OM	FLUID LEVEL IND MAG	01-May-68	01-Aug-87	1	BAC 1-11	Titchfield, UK	K2523	--
3508000-206	--	28-40-83	OM	FLUID LEVEL IND MAG	01-May-68	01-Aug-87	1	BAC 1-11	Titchfield, UK	K2523	--
3508000-207	--	28-40-83	OM	FLUID LEVEL IND MAG	01-May-68	01-Aug-87	1	BAC 1-11	Titchfield, UK	K2523	--
3508000-208	--	28-40-83	OM	FLUID LEVEL IND MAG	01-May-68	01-Aug-87	1	BAC 1-11	Titchfield, UK	K2523	--
3508000-209	--	28-40-83	OM	FLUID LEVEL IND MAG	01-May-68	01-Aug-87	1	BAC 1-11	Titchfield, UK	K2523	--
3508000-22	--	28-40-33	OM	FLUID LEVEL INDICATOR (MAG)	01-Dec-65	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-220	--	28-40-37	OM	FLUID LEVEL IND (MAGNETIC)	01-Jun-68	24-Oct-03	8	F27	Titchfield, UK	K2523	--
3508000-221	--	28-40-34	OM	FLUID LEVEL IND MAG	01-Jun-68	31-Jul-03	7	F28	Titchfield, UK	K2523	Original Scanned
3508000-222	--	28-40-34	OM	FLUID LEVEL IND MAG	01-Jun-68	31-Jul-03	7	F28	Titchfield, UK	K2523	Original Scanned
3508000-223	--	28-40-34	OM	FLUID LEVEL IND MAG	01-Jun-68	31-Jul-03	7	F28	Titchfield, UK	K2523	Original Scanned
3508000-224	--	28-41-12	OM	FLUID LEVEL IND MAG	01-Feb-72	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-225	--	28-41-13	OM	MFLI	01-Feb-72	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-226	--	28-41-06	OM	FLUID LEVEL IND MAG	01-Mar-72	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-227	--	28-40-34	OM	FLUID LEVEL IND MAG	01-Jun-68	31-Jul-03	7	F28	Titchfield, UK	K2523	Original Scanned

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508000-228	--	28-40-34	OM	FLUID LEVEL IND MAG	01-Jun-68	31-Jul-03	7	F28	Titchfield, UK	K2523	Original Scanned
3508000-24	--	28-40-33	OM	FLUID LEVEL INDICATOR (MAG)	01-Dec-65	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-25	--	28-40-33	OM	FLUID LEVEL INDICATOR (MAG)	01-Dec-65	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-255	--	28-41-29	OM	FLUID LEVEL INDICATORS (MAG)	01-Jun-74	--	0	CONCORDE	Titchfield, UK	K2523	--
3508000-257	--	28-41-29	OM	FLUID LEVEL INDICATORS (MAG)	01-Jun-74	--	0	CONCORDE	Titchfield, UK	K2523	--
3508000-258	--	28-41-29	OM	FLUID LEVEL INDICATORS (MAG)	01-Jun-74	--	0	CONCORDE	Titchfield, UK	K2523	--
3508000-259	--	28-41-29	OM	FLUID LEVEL INDICATORS (MAG)	01-Jun-74	--	0	CONCORDE	Titchfield, UK	K2523	--
3508000-26	--	28-40-33	OM	FLUID LEVEL INDICATOR (MAG)	01-Dec-65	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-260	--	28-41-29	OM	FLUID LEVEL INDICATORS (MAG)	01-Jun-74	--	0	CONCORDE	Titchfield, UK	K2523	--
3508000-262	--	28-41-29	OM	FLUID LEVEL INDICATORS (MAG)	01-Jun-74	--	0	CONCORDE	Titchfield, UK	K2523	--
3508000-27	--	28-40-33	OM	FLUID LEVEL INDICATOR (MAG)	01-Dec-65	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-274	--	28-41-29	OM	FLUID LEVEL INDICATORS (MAG)	01-Jun-74	--	0	CONCORDE	Titchfield, UK	K2523	--
3508000-279	--	28-41-37	OM	FLUID LEVEL INDICATORS (MAG)	01-Sep-74	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-28	--	28-40-33	OM	FLUID LEVEL INDICATOR (MAG)	01-Dec-65	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-280	--	28-41-37	OM	FLUID LEVEL INDICATORS (MAG)	01-Sep-74	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-282	--	28-41-73	CMM	MAGNETIC FUEL LEVEL INDICATOR	01-Jul-80	06-May-11	3	BAE 146	Titchfield, UK	K2523	--
3508000-283	--	28-41-73	CMM	MAGNETIC FUEL LEVEL INDICATOR	01-Jul-80	06-May-11	3	BAE 146	Titchfield, UK	K2523	--
3508000-288	--	28-41-54	OM	FLUID LEVEL INDICATORS MAG	01-Nov-76	01-Aug-78	1	CONCORDE	Titchfield, UK	K2523	--
3508000-289	--	28-41-54	OM	FLUID LEVEL INDICATORS MAG	01-Nov-76	01-Aug-78	1	CONCORDE	Titchfield, UK	K2523	--
3508000-290	--	28-41-54	OM	FLUID LEVEL INDICATORS MAG	01-Nov-76	01-Aug-78	1	CONCORDE	Titchfield, UK	K2523	--
3508000-291	--	28-41-54	OM	FLUID LEVEL INDICATORS MAG	01-Nov-76	01-Aug-78	1	CONCORDE	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508000-292	--	28-41-54	OM	FLUID LEVEL INDICATORS MAG	01-Nov-76	01-Aug-78	1	CONCORDE	Titchfield, UK	K2523	--
3508000-293	--	28-41-54	OM	FLUID LEVEL INDICATORS MAG	01-Nov-76	01-Aug-78	1	CONCORDE	Titchfield, UK	K2523	--
3508000-294	--	28-41-54	OM	FLUID LEVEL INDICATORS MAG	01-Nov-76	01-Aug-78	1	CONCORDE	Titchfield, UK	K2523	--
3508000-3	--	28-40-32	OM	FLUID LEVEL MAGNETIC INDICATOR	01-Dec-65	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-30	--	28-40-33	OM	FLUID LEVEL INDICATOR (MAG)	01-Dec-65	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-31	--	28-40-33	OM	FLUID LEVEL INDICATOR (MAG)	01-Dec-65	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-32	--	28-40-39	OM	FLUID LEVEL INDICATOR (MAGNETIC)	01-Oct-65	01-Aug-87	2	Not Known	Titchfield, UK	K2523	--
3508000-33	--	28-40-39	OM	FLUID LEVEL INDICATOR (MAGNETIC)	01-Oct-65	01-Aug-87	2	Not Known	Titchfield, UK	K2523	--
3508000-34	--	28-40-39	OM	FLUID LEVEL INDICATOR (MAGNETIC)	01-Oct-65	01-Aug-87	2	Not Known	Titchfield, UK	K2523	--
3508000-35	--	28-40-39	OM	FLUID LEVEL INDICATOR (MAGNETIC)	01-Oct-65	01-Aug-87	2	Not Known	Titchfield, UK	K2523	--
3508000-36	--	28-40-39	OM	FLUID LEVEL INDICATOR (MAGNETIC)	01-Oct-65	01-Aug-87	2	Not Known	Titchfield, UK	K2523	--
3508000-37	--	28-40-39	OM	FLUID LEVEL INDICATOR (MAGNETIC)	01-Oct-65	01-Aug-87	2	Not Known	Titchfield, UK	K2523	--
3508000-38	--	28-2-4336-181	SB	MFLI - LONGER SCREWS ATTACHING COVER	20-Jul-65	--	0	Not Known	Titchfield, UK	K2523	--
3508000-38	--	28-40-59	OM	FLUID LEVEL IND MAGNETIC	01-Oct-65	01-Aug-87	3	Not Known	Titchfield, UK	K2523	--
3508000-4	--	28-40-32	OM	FLUID LEVEL MAGNETIC INDICATOR	01-Dec-65	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-40	--	28-40-33	OM	FLUID LEVEL INDICATOR (MAG)	01-Dec-65	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-41	--	28-40-33	OM	FLUID LEVEL INDICATOR (MAG)	01-Dec-65	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-42	--	28-40-33	OM	FLUID LEVEL INDICATOR (MAG)	01-Dec-65	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-43	--	28-40-33	OM	FLUID LEVEL INDICATOR (MAG)	01-Dec-65	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-5	--	28-40-32	OM	FLUID LEVEL MAGNETIC INDICATOR	01-Dec-65	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--
3508000-6	--	28-40-32	OM	FLUID LEVEL MAGNETIC INDICATOR	01-Dec-65	01-Aug-87	1	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508000-60	--	28-40-37	OM	FLUID LEVEL IND (MAGNETIC)	01-Jun-68	24-Oct-03	8	F27	Titchfield, UK	K2523	--
3508000-61	--	28-40-37	OM	FLUID LEVEL IND (MAGNETIC)	01-Jun-68	24-Oct-03	8	F27	Titchfield, UK	K2523	--
3508000-62	--	28-40-37	OM	FLUID LEVEL IND (MAGNETIC)	01-Jun-68	24-Oct-03	8	F27	Titchfield, UK	K2523	--
3508000-63	--	28-40-37	OM	FLUID LEVEL IND (MAGNETIC)	01-Jun-68	24-Oct-03	8	F27	Titchfield, UK	K2523	--
3508000-64	--	28-40-37	OM	FLUID LEVEL IND (MAGNETIC)	01-Jun-68	24-Oct-03	8	F27	Titchfield, UK	K2523	--
3508000-65	--	28-40-37	OM	FLUID LEVEL IND (MAGNETIC)	01-Jun-68	24-Oct-03	8	F27	Titchfield, UK	K2523	--
3508000-87	--	28-40-39	OM	FLUID LEVEL INDICATOR (MAGNETIC)	01-Oct-65	01-Aug-87	2	Not Known	Titchfield, UK	K2523	--
3508000-88	--	28-40-39	OM	FLUID LEVEL INDICATOR (MAGNETIC)	01-Oct-65	01-Aug-87	2	Not Known	Titchfield, UK	K2523	--
3508000-89	--	28-40-39	OM	FLUID LEVEL INDICATOR (MAGNETIC)	01-Oct-65	01-Aug-87	2	Not Known	Titchfield, UK	K2523	--
3508000-90	--	28-40-39	OM	FLUID LEVEL INDICATOR (MAGNETIC)	01-Oct-65	01-Aug-87	2	Not Known	Titchfield, UK	K2523	--
3508000-91	--	28-40-39	OM	FLUID LEVEL INDICATOR (MAGNETIC)	01-Oct-65	01-Aug-87	2	Not Known	Titchfield, UK	K2523	--
3508000-92	--	28-40-37	OM	FLUID LEVEL IND (MAGNETIC)	01-Jun-68	24-Oct-03	8	F27	Titchfield, UK	K2523	--
3508000-93	--	28-40-37	OM	FLUID LEVEL IND (MAGNETIC)	01-Jun-68	24-Oct-03	8	F27	Titchfield, UK	K2523	--
3508000-94	--	28-40-37	OM	FLUID LEVEL IND (MAGNETIC)	01-Jun-68	24-Oct-03	8	F27	Titchfield, UK	K2523	--
3508000-94	--	28-40-37-4336-281	SB	MFLI - KILOS IN LIEU OF IMP GALS	01-Sep-74	--	0	Not Known	Titchfield, UK	K2523	--
3508000-95	--	28-40-37	OM	FLUID LEVEL IND (MAGNETIC)	01-Jun-68	24-Oct-03	8	F27	Titchfield, UK	K2523	--
3508000-96	--	28-40-37	OM	FLUID LEVEL IND (MAGNETIC)	01-Jun-68	24-Oct-03	8	F27	Titchfield, UK	K2523	--
3508000-97	--	28-40-37	OM	FLUID LEVEL IND (MAGNETIC)	01-Jun-68	24-Oct-03	8	F27	Titchfield, UK	K2523	--
3508000-97	--	28-40-37-4599-054	SB	MFLI - KILOS IN LIEU OF IMP GALS	01-Jun-74	--	0	Not Known	Titchfield, UK	K2523	--
35081438	--	28-40-27	CMM	MAGNETIC FLUID LEVEL INDICATOR	01-Mar-91	01-Apr-91	1	Not Known	Titchfield, UK	K2523	28-40-27* FOR 3515000-196
35081442	--	28-40-16	CMM	MAGNETIC FLUID LEVEL INDICATORS	01-Nov-92	18-May-95	1	SAAB 2000, SAAB 340B	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
35081587	--	28-40-16	CMM	MAGNETIC FLUID LEVEL INDICATORS	01-Nov-92	18-May-95	1	SAAB 2000, SAAB 340B	Titchfield, UK	K2523	--
3508400-60	--	28-40-14	CMM	OUTER ASSY - MFLI	21-Dec-87	--	0	F50	Titchfield, UK	K2523	Original scanned
3508500-538	--	28-40-15	CMM	Inner Assembly for Magnetic Fluid Level Indicators	04-Feb-88	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
3508500-539	--	28-40-15	CMM	Inner Assembly for Magnetic Fluid Level Indicators	04-Feb-88	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
3508500-540	--	28-40-15	CMM	Inner Assembly for Magnetic Fluid Level Indicators	04-Feb-88	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
3508500-541	--	28-40-15	CMM	Inner Assembly for Magnetic Fluid Level Indicators	04-Feb-88	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
3508500-542	--	28-40-15	CMM	Inner Assembly for Magnetic Fluid Level Indicators	04-Feb-88	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
3508500-543	--	28-40-15	CMM	Inner Assembly for Magnetic Fluid Level Indicators	04-Feb-88	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
3508802-1	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508802-10	--	28-43-23	CMM	MAGNETIC FUEL LEVEL INDICATORS	01-May-87	07-Oct-05	5	A319, A320	Titchfield, UK	K2523	--
3508802-11	--	28-43-23	CMM	MAGNETIC FUEL LEVEL INDICATORS	01-May-87	07-Oct-05	5	A319, A320	Titchfield, UK	K2523	--
3508802-15	--	28-41-10	CMM	MFLI - OUTER ASSY	01-Jan-87	30-Sep-04	3	F50	Titchfield, UK	K2523	--
3508802-2	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508802-20	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508802-20	--	3508802(20to23)-28-1	SB	NEW END STOP FOR MFLI OUTER ASSEMBLIES	28-Jan-94	--	0	Not Known	Titchfield, UK	K2523	--
3508802-21	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508802-21	--	3508802(20to23)-28-1	SB	NEW END STOP FOR MFLI OUTER ASSEMBLIES	28-Jan-94	--	0	Not Known	Titchfield, UK	K2523	--
3508802-22	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508802-22	--	3508802(20to23)-28-1	SB	NEW END STOP FOR MFLI OUTER ASSEMBLIES	28-Jan-94	--	0	Not Known	Titchfield, UK	K2523	--
3508802-23	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508802-23	--	3508802(20to23)-28-1	SB	NEW END STOP FOR MFLI OUTER ASSEMBLIES	28-Jan-94	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508802-24	--	28-43-21	CMM	MFLI	01-May-87	21-Oct-10	0	A320	Titchfield, UK	K2523	Re-issued at Oct 21/10
3508802-24	--	3508802-39-28-1	SB	MFLI - INSPECTION FOR MISSING TOP STOPS	--	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN
3508802-24	--	SIL-CS-4-05	SIL	NON-PROCURABLE MFLIS	18-Jul-05	19-Apr-12	2	A319, A320, A321	Titchfield, UK	K2523	--
3508802-25	--	28-43-21	CMM	MFLI	01-May-87	21-Oct-10	0	A320	Titchfield, UK	K2523	Re-issued at Oct 21/10
3508802-25	--	3508802-39-28-1	SB	MFLI - INSPECTION FOR MISSING TOP STOPS	--	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN
3508802-25	--	SIL-CS-4-05	SIL	NON-PROCURABLE MFLIS	18-Jul-05	19-Apr-12	2	A319, A320, A321	Titchfield, UK	K2523	--
3508802-26	--	28-43-21	CMM	MFLI	01-May-87	21-Oct-10	0	A320	Titchfield, UK	K2523	Re-issued at Oct 21/10
3508802-26	--	3508802-39-28-1	SB	MFLI - INSPECTION FOR MISSING TOP STOPS	--	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN
3508802-26	--	SIL-CS-4-05	SIL	NON-PROCURABLE MFLIS	18-Jul-05	19-Apr-12	2	A319, A320, A321	Titchfield, UK	K2523	--
3508802-27	--	28-43-21	CMM	MFLI	01-May-87	21-Oct-10	0	A320	Titchfield, UK	K2523	Re-issued at Oct 21/10
3508802-27	--	3508802-39-28-1	SB	MFLI - INSPECTION FOR MISSING TOP STOPS	--	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN
3508802-27	--	SIL-CS-4-05	SIL	NON-PROCURABLE MFLIS	18-Jul-05	19-Apr-12	2	A319, A320, A321	Titchfield, UK	K2523	--
3508802-28	--	28-43-22	CMM	MFLI	01-May-87	01-May-90	2	A320	Titchfield, UK	K2523	DO NOT USE THIS PART -REF SIL-CS-4-05
3508802-28	--	3508802-39-28-1	SB	MFLI - INSPECTION FOR MISSING TOP STOPS	--	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN
3508802-28	--	SIL-CS-4-05	SIL	NON-PROCURABLE MFLIS	18-Jul-05	19-Apr-12	2	A319, A320, A321	Titchfield, UK	K2523	--
3508802-29	--	28-43-23	CMM	MAGNETIC FUEL LEVEL INDICATORS	01-May-87	07-Oct-05	5	A319, A320	Titchfield, UK	K2523	--
3508802-29	--	3508802-29-28-1	SB	MFLI - NEW DESIGN MOD No. FRCA9328	14-Oct-98	--	0	A319, A320	Titchfield, UK	K2523	--
3508802-3	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508802-30	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508802-31	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508802-32	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508802-34	--	28-43-21	CMM	MFLI	01-May-87	21-Oct-10	0	A320	Titchfield, UK	K2523	Re-issued at Oct 21/10
3508802-34	--	SIL-CS-4-05	SIL	NON-PROCURABLE MFLIS	18-Jul-05	19-Apr-12	2	A319, A320, A321	Titchfield, UK	K2523	--
3508802-35	--	28-43-24	CMM	OUTER ASSEMBLY - MFLI	01-Feb-88	01-Oct-90	3	A319, A320, A321	Titchfield, UK	K2523	--
3508802-35	--	3508802-29-28-1	SB	MFLI - NEW DESIGN MOD No. FRCA9328	14-Oct-98	--	0	A319, A320	Titchfield, UK	K2523	--
3508802-36	--	28-43-24	CMM	OUTER ASSEMBLY - MFLI	01-Feb-88	01-Oct-90	3	A319, A320, A321	Titchfield, UK	K2523	--
3508802-36	--	3508802-29-28-1	SB	MFLI - NEW DESIGN MOD No. FRCA9328	14-Oct-98	--	0	A319, A320	Titchfield, UK	K2523	--
3508802-37	--	28-43-24	CMM	OUTER ASSEMBLY - MFLI	01-Feb-88	01-Oct-90	3	A319, A320, A321	Titchfield, UK	K2523	--
3508802-37	--	3508802-29-28-1	SB	MFLI - NEW DESIGN MOD No. FRCA9328	14-Oct-98	--	0	A319, A320	Titchfield, UK	K2523	--
3508802-38	--	28-43-24	CMM	OUTER ASSEMBLY - MFLI	01-Feb-88	01-Oct-90	3	A319, A320, A321	Titchfield, UK	K2523	--
3508802-38	--	3508802-29-28-1	SB	MFLI - NEW DESIGN MOD No. FRCA9328	14-Oct-98	--	0	A319, A320	Titchfield, UK	K2523	--
3508802-39	--	28-43-25	CMM	OUTER ASSEMBLY - MFLI	01-Jan-88	28-Oct-02	3	A319, A320	Titchfield, UK	K2523	DO NOT USE THIS PART - REF SIL-CS-4-05
3508802-39	--	3508802-29-28-1	SB	MFLI - NEW DESIGN MOD No. FRCA9328	14-Oct-98	--	0	A319, A320	Titchfield, UK	K2523	--
3508802-39	--	3508802-39-28-1	SB	MFLI - INSPECTION FOR MISSING TOP STOPS	--	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN
3508802-39	--	SIL-CS-4-05	SIL	NON-PROCURABLE MFLIS	18-Jul-05	19-Apr-12	2	A319, A320, A321	Titchfield, UK	K2523	--
3508802-4	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508802-40	--	28-43-23	CMM	MAGNETIC FUEL LEVEL INDICATORS	01-May-87	07-Oct-05	5	A319, A320	Titchfield, UK	K2523	--
3508802-40	--	3508802-29-28-1	SB	MFLI - NEW DESIGN MOD No. FRCA9328	14-Oct-98	--	0	A319, A320	Titchfield, UK	K2523	--
3508802-44	--	28-43-52	CMM	MFLI OUTER ASSEMBLY	25-Sep-00	19-Apr-16	6	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
3508802-45	--	28-43-52	CMM	MFLI OUTER ASSEMBLY	25-Sep-00	19-Apr-16	6	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
3508802-46	--	28-43-52	CMM	MFLI OUTER ASSEMBLY	25-Sep-00	19-Apr-16	6	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
3508802-47	--	28-43-52	CMM	MFLI OUTER ASSEMBLY	25-Sep-00	19-Apr-16	6	A330, A340	Titchfield, UK	K2523	BASIC MANUAL

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508802-48	--	28-43-52	CMM	MFLI OUTER ASSEMBLY	25-Sep-00	19-Apr-16	6	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
3508802-49	--	28-43-52	CMM	MFLI OUTER ASSEMBLY	25-Sep-00	19-Apr-16	6	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
3508802-52	--	28-43-52	CMM	MFLI OUTER ASSEMBLY	25-Sep-00	19-Apr-16	6	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
3508802-53	--	28-43-52	CMM	MFLI OUTER ASSEMBLY	25-Sep-00	19-Apr-16	6	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
3508802-54	--	28-43-52	CMM	MFLI OUTER ASSEMBLY	25-Sep-00	19-Apr-16	6	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
3508802-55	--	28-43-52	CMM	MFLI OUTER ASSEMBLY	25-Sep-00	19-Apr-16	6	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
3508802-56	--	28-43-52	CMM	MFLI OUTER ASSEMBLY	25-Sep-00	19-Apr-16	6	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
3508802-57	--	28-43-52	CMM	MFLI OUTER ASSEMBLY	25-Sep-00	19-Apr-16	6	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
3508802-58	--	28-43-54	CMM	MFLI OUTER ASSEMBLY(UPPER & LOWER)	16-Apr-92	04-Mar-14	3	A340	Titchfield, UK	K2523	--
3508802-58	--	3508802-58-28-1	SB	MFLI OUTER ASSY (UPPER) POSSIBLE LEAKAGE	12-Oct-04	--	0	A340	Titchfield, UK	K2523	--
3508802-59	--	28-43-54	CMM	MFLI OUTER ASSEMBLY(UPPER & LOWER)	16-Apr-92	04-Mar-14	3	A340	Titchfield, UK	K2523	--
3508802-62	--	28-40-16	CMM	MAGNETIC FLUID LEVEL INDICATORS	01-Nov-92	18-May-95	1	SAAB 2000, SAAB 340B	Titchfield, UK	K2523	--
3508802-70	--	28-43-27	CMM	MFLI UPPER & LOWER OUTER ASSEMBLIES	21-May-93	08-Oct-14	3	A321	Titchfield, UK	K2523	--
3508802-71	--	28-43-27	CMM	MFLI UPPER & LOWER OUTER ASSEMBLIES	21-May-93	08-Oct-14	3	A321	Titchfield, UK	K2523	--
3508802-72	--	28-40-18	CMM	MAGNETIC FLUID LEVEL INDICATOR	01-Jul-92	18-Oct-93	1	F100, F70	Titchfield, UK	K2523	--
3508802-73	--	28-40-18	CMM	MAGNETIC FLUID LEVEL INDICATOR	01-Jul-92	18-Oct-93	1	F100, F70	Titchfield, UK	K2523	--
3508802-74	--	28-43-28	CMM	MFLI OUTER ASSEMBLIES	29-Jul-93	30-Apr-04	1	A321	Titchfield, UK	K2523	DO NOT USE THIS PART -REF SIL-CS-4-05
3508802-74	--	3508802-39-28-1	SB	MFLI - INSPECTION FOR MISSING TOP STOPS	--	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN
3508802-74	--	SIL-CS-4-05	SIL	NON-PROCURABLE MFLIS	18-Jul-05	19-Apr-12	2	A319, A320, A321	Titchfield, UK	K2523	--
3508802-75	--	28-43-28	CMM	MFLI OUTER ASSEMBLIES	29-Jul-93	30-Apr-04	1	A321	Titchfield, UK	K2523	DO NOT USE THIS PART -REF SIL-CS-4-05
3508802-75	--	3508802-39-28-1	SB	MFLI - INSPECTION FOR MISSING TOP STOPS	--	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508802-75	--	SIL-CS-4-05	SIL	NON-PROCURABLE MFLIS	18-Jul-05	19-Apr-12	2	A319, A320, A321	Titchfield, UK	K2523	--
3508802-76	--	28-43-28	CMM	MFLI OUTER ASSEMBLIES	29-Jul-93	30-Apr-04	1	A321	Titchfield, UK	K2523	DO NOT USE THIS PART -REF SIL-CS-4-05
3508802-76	--	3508802-39-28-1	SB	MFLI - INSPECTION FOR MISSING TOP STOPS	--	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN
3508802-76	--	SIL-CS-4-05	SIL	NON-PROCURABLE MFLIS	18-Jul-05	19-Apr-12	2	A319, A320, A321	Titchfield, UK	K2523	--
3508802-78	--	28-43-51	CMM	MFLI OUTER ASSEMBLY	01-Apr-92	30-Oct-00	2	A330, A340	Titchfield, UK	K2523	--
3508802-79	--	28-43-51	CMM	MFLI OUTER ASSEMBLY	01-Apr-92	30-Oct-00	2	A330, A340	Titchfield, UK	K2523	--
3508802-82	--	28-40-16	CMM	MAGNETIC FLUID LEVEL INDICATORS	01-Nov-92	18-May-95	1	SAAB 2000, SAAB 340B	Titchfield, UK	K2523	--
3508802-83	--	28-43-52	CMM	MFLI OUTER ASSEMBLY	25-Sep-00	19-Apr-16	6	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
3508802-84	--	28-43-52	CMM	MFLI OUTER ASSEMBLY	25-Sep-00	19-Apr-16	6	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
3508802-85	--	28-43-01	CMM	MAGNETIC FLUID LEVEL INDICATORS	20-Nov-95	--	0	N250	Titchfield, UK	K2523	--
3508802-86	--	28-43-01	CMM	MAGNETIC FLUID LEVEL INDICATORS	20-Nov-95	--	0	N250	Titchfield, UK	K2523	--
3508802-87	--	28-43-01	CMM	MAGNETIC FLUID LEVEL INDICATORS	20-Nov-95	--	0	N250	Titchfield, UK	K2523	--
3508802-88	--	28-43-01	CMM	MAGNETIC FLUID LEVEL INDICATORS	20-Nov-95	--	0	N250	Titchfield, UK	K2523	--
3508802-91	--	28-43-28	CMM	MFLI OUTER ASSEMBLIES	29-Jul-93	30-Apr-04	1	A321	Titchfield, UK	K2523	DO NOT USE THIS PART -REF SIL-CS-4-05
3508803-306	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508803-306	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-307	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508803-307	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-308	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508803-309	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508803-310	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508803-310	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-311	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508803-311	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-312	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508803-313	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508803-314	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508803-314	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-315	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508803-315	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-316	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508803-317	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508803-318	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508803-318	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-319	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508803-319	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-320	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508803-321	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508803-322	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508803-323	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508803-324	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508803-325	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508803-349	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-350	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-351	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-352	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-353	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-354	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-355	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-356	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-357	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-358	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-359	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-360	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508803-399	--	28-41-10	CMM	MFLI - OUTER ASSY	01-Jan-87	30-Sep-04	3	F50	Titchfield, UK	K2523	--
3508803-400	--	28-41-10	CMM	MFLI - OUTER ASSY	01-Jan-87	30-Sep-04	3	F50	Titchfield, UK	K2523	--
3508803-401	--	28-41-10	CMM	MFLI - OUTER ASSY	01-Jan-87	30-Sep-04	3	F50	Titchfield, UK	K2523	--
3508803-402	--	28-41-10	CMM	MFLI - OUTER ASSY	01-Jan-87	30-Sep-04	3	F50	Titchfield, UK	K2523	--
3508803-403	--	28-41-10	CMM	MFLI - OUTER ASSY	01-Jan-87	30-Sep-04	3	F50	Titchfield, UK	K2523	--
3508803-404	--	28-41-10	CMM	MFLI - OUTER ASSY	01-Jan-87	30-Sep-04	3	F50	Titchfield, UK	K2523	--
3508803-481	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508803-482	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508803-483	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508803-484	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508803-485	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508803-486	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508803-487	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508803-488	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508803-489	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508803-490	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508803-491	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508803-492	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508803-493	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508803-494	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508803-495	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508803-496	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508803-497	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508803-498	--	28-40-13	CMM	MAGNETIC FLUID LEVEL INDICATOR	06-May-87	29-Feb-12	5	F100, F70	Titchfield, UK	K2523	--
3508803-500	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-501	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-502	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-503	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-504	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-505	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508803-506	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-507	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-508	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-509	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-510	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-511	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-512	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-513	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-514	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-515	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-516	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-517	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-518	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-519	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-520	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-521	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-522	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-523	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-524	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-525	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-526	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508803-527	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-528	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-529	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-530	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-531	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-532	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-533	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-534	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-535	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-549	--	28-43-53	ACMM	MFLI INNER ASSY	01-Mar-92	17-Aug-12	3	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
3508803-555	--	28-43-53	ACMM	MFLI INNER ASSY	01-Mar-92	17-Aug-12	3	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
3508803-561	--	28-43-53	ACMM	MFLI INNER ASSY	01-Mar-92	17-Aug-12	3	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
3508803-567	--	28-43-53	ACMM	MFLI INNER ASSY	01-Mar-92	17-Aug-12	3	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
3508803-573	--	28-43-53	ACMM	MFLI INNER ASSY	01-Mar-92	17-Aug-12	3	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
3508803-579	--	28-43-53	ACMM	MFLI INNER ASSY	01-Mar-92	17-Aug-12	3	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
3508803-585	--	28-43-53	ACMM	MFLI INNER ASSY	01-Mar-92	17-Aug-12	3	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
3508803-591	--	28-43-53	ACMM	MFLI INNER ASSY	01-Mar-92	17-Aug-12	3	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
3508803-597	--	28-43-53	ACMM	MFLI INNER ASSY	01-Mar-92	17-Aug-12	3	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
3508803-641	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-647	--	28-40-18	CMM	MAGNETIC FLUID LEVEL INDICATOR	01-Jul-92	18-Oct-93	1	F100, F70	Titchfield, UK	K2523	--
3508803-650	--	28-40-18	CMM	MAGNETIC FLUID LEVEL INDICATOR	01-Jul-92	18-Oct-93	1	F100, F70	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508803-653	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-659	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-665	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
3508803-685	--	28-43-53	ACMM	MFLI INNER ASSY	01-Mar-92	17-Aug-12	3	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
3508803-690	--	28-43-01	CMM	MAGNETIC FLUID LEVEL INDICATORS	20-Nov-95	--	0	N250	Titchfield, UK	K2523	--
3508803-696	--	28-43-01	CMM	MAGNETIC FLUID LEVEL INDICATORS	20-Nov-95	--	0	N250	Titchfield, UK	K2523	--
3508803-702	--	28-43-01	CMM	MAGNETIC FLUID LEVEL INDICATORS	20-Nov-95	--	0	N250	Titchfield, UK	K2523	--
3508803-708	--	28-43-01	CMM	MAGNETIC FLUID LEVEL INDICATORS	20-Nov-95	--	0	N250	Titchfield, UK	K2523	--
3508930-306	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-306	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508930-307	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-307	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508930-308	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-309	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-310	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-310	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508930-311	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-311	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508930-312	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-313	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-314	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508930-314	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508930-315	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-315	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508930-316	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-317	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-318	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-318	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508930-319	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-319	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508930-320	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-321	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-322	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-323	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-324	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-325	--	28-41-84	CMM	MFLI-OUTER ASSY	01-Oct-84	06-May-11	3	BAe 748	Titchfield, UK	K2523	--
3508930-349	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508930-350	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508930-351	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508930-352	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508930-353	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508930-354	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3508930-355	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508930-356	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508930-358	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508930-359	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3508930-360	--	28-41-88	CMM	MFLI - OUTER ASSY	01-Jan-87	06-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	--
3509002	--	28-40-86	OM	INVERTED FLIGHT SWITCH	01-Aug-68	--	0	Not Known	Titchfield, UK	K2523	--
3514100	--	28-M14-3	OM	M14 & 22 FLOAT SWITCHES	01-Nov-69	05-Oct-01	4	VARIOUS	Titchfield, UK	K2523	--
3514100-105	--	28-M14-105	OM	MK 14 FLOAT SWITCHES	01-Sep-63	--	0	Not Known	Titchfield, UK	K2523	--
3514100-106	--	28-M14-105	OM	MK 14 FLOAT SWITCHES	01-Sep-63	--	0	Not Known	Titchfield, UK	K2523	--
3514100-107	--	28-M14-105	OM	MK 14 FLOAT SWITCHES	01-Sep-63	--	0	Not Known	Titchfield, UK	K2523	--
3514100-125	--	28-M14-125	OM	MK 14 FLOAT SWITCHES	01-Apr-63	--	0	Not Known	Titchfield, UK	K2523	--
3514100-126	--	28-M14-125	OM	MK 14 FLOAT SWITCHES	01-Apr-63	--	0	Not Known	Titchfield, UK	K2523	--
3514100-127	--	28-M14-125	OM	MK 14 FLOAT SWITCHES	01-Apr-63	--	0	Not Known	Titchfield, UK	K2523	--
3514100-147	--	28-M14-147	OM	M14 & 22 FLOAT SWITCHES	01-Sep-63	--	0	Not Known	Titchfield, UK	K2523	--
3514100-154	--	28-M14-147	OM	M14 & 22 FLOAT SWITCHES	01-Sep-63	--	0	Not Known	Titchfield, UK	K2523	--
3514100-171	--	28-M14-105	OM	MK 14 FLOAT SWITCHES	01-Sep-63	--	0	Not Known	Titchfield, UK	K2523	--
3514100-172	--	28-M14-105	OM	MK 14 FLOAT SWITCHES	01-Sep-63	--	0	Not Known	Titchfield, UK	K2523	--
3514100-201	--	28-M14-125	OM	MK 14 FLOAT SWITCHES	01-Apr-63	--	0	Not Known	Titchfield, UK	K2523	--
3514100-206	--	28-40-97	OM	MK 14 FLOAT SWITCH	01-Sep-71	01-Sep-71	1	Not Known	Titchfield, UK	K2523	--
3514100-212	--	28-40-95	OM	MK 14 FLOAT SWITCH	01-Aug-71	--	0	Not Known	Titchfield, UK	K2523	--
3514100-231	--	28-M14-231	OM	MK 14 FLOAT SWITCH	01-Mar-64	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3514100-235	--	28-41-20	CMM	MK 14 FLOAT SWITCH	01-Sep-71	15-Oct-14	4	TRIDENT, VC10	Titchfield, UK	K2523	Original files scanned
3514100-235	--	3514100-235-28-1	SB	FLOAT SW - INTRO OF NEW MICRO SW	01-Jan-85	01-Mar-85	1	TRIDENT	Titchfield, UK	K2523	--
3514100-261	--	28-40-73	OM	MK 14 FLOAT SWITCH	01-Jan-67	15-Jan-15	8	BAE 125	Titchfield, UK	K2523	--
3514100-262	--	28-40-73	OM	MK 14 FLOAT SWITCH	01-Jan-67	15-Jan-15	8	BAE 125	Titchfield, UK	K2523	--
3514100-263	--	28-40-73	OM	MK 14 FLOAT SWITCH	01-Jan-67	15-Jan-15	8	BAE 125	Titchfield, UK	K2523	--
3514100-264	--	28-40-73	OM	MK 14 FLOAT SWITCH	01-Jan-67	15-Jan-15	8	BAE 125	Titchfield, UK	K2523	--
3514100-265	--	28-40-79	OM	MK 14 FLOAT SWITCH	01-Jun-67	01-Oct-86	1	TRIDENT	Titchfield, UK	K2523	--
3514100-265	--	3514100-235-28-1	SB	FLOAT SW - INTRO OF NEW MICRO SW	01-Jan-85	01-Mar-85	1	TRIDENT	Titchfield, UK	K2523	--
3514100-277	--	28-40-82	OM	MK 14 FLOAT SWITCH	01-Aug-67	--	0	Not Known	Titchfield, UK	K2523	--
3514100-282	--	28-40-96	OM	MK 14 FLOAT SWITCHES	01-Oct-69	--	0	Not Known	Titchfield, UK	K2523	--
3514100-287	--	28-40-96	OM	MK 14 FLOAT SWITCHES	01-Oct-69	--	0	Not Known	Titchfield, UK	K2523	--
3514100-290	--	28-41-30	OM	MK 14 FLOAT SWITCHES	01-Jan-73	--	0	Not Known	Titchfield, UK	K2523	--
3514100-291	--	28-41-30	OM	MK 14 FLOAT SWITCHES	01-Jan-73	--	0	Not Known	Titchfield, UK	K2523	--
3514100-291	--	28-41-30	OM	MK 14 FLOAT SWITCHES	01-Jan-73	--	0	Not Known	Titchfield, UK	K2523	--
3514100-99	--	28-M14-99	OM	MK14 FLOAT SWITCH	01-Jan-64	--	0	Not Known	Titchfield, UK	K2523	--
3515000	--	28-40-53	OM	MK 15 FLOAT SWITCH	01-Mar-65	17-Aug-67	1	BAC 1-11, BAE 125, F28	Titchfield, UK	K2523	--
3515000-100	--	28-41-42	OM	MK 15 FLOAT SWITCH	01-Jul-75	--	0	HARRIER	Titchfield, UK	K2523	CANCELLED
3515000-100	--	28-41-94	CMM	MK 15 FLOAT SWITCH SERIES 100	18-Jun-98	--	0	HARRIER AV8B, HARRIER FRSZ, HARRIER GR2, HARRIER GR5, HARRIER TMK10, HARRIER TMKCO	Titchfield, UK	K2523	SUPERSEDES OM28-41-42
3515000-101	--	28-41-07	OM	MK 15 FLOAT SWITCH	01-Mar-71	--	0	Not Known	Titchfield, UK	K2523	--
3515000-103	--	28-40-81	OM	MK 15 FLOAT SWITCH	01-Jun-67	15-Jan-15	3	BAE 125	Titchfield, UK	K2523	PDF copy of SB_28-40-81 in History folder
3515000-105	--	28-10-67	CMM	MK15 FLOAT SWITCH	30-Sep-83	22-Nov-11	4	BAE 125	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3515000-106	--	28-10-65	CMM	MK15 FLOAT SWITCH	24-Jun-83	--	0	BAE 125	Titchfield, UK	K2523	--
3515000-107	--	28-10-66	CMM	MK15 FLOAT SWITCH	13-Jun-83	11-Nov-13	3	BAE 125	Titchfield, UK	K2523	--
3515000-116	--	28-41-82	CMM	MK 15 FLOAT SWITCH	01-Jan-84	--	0	Not Known	Titchfield, UK	K2523	--
3515000-124	--	28-41-78	CMM	MK 15 FLOAT SWITCH	01-Mar-83	--	0	Not Known	Titchfield, UK	K2523	--
3515000-125	--	79-30-14	OM	MK 15 FLOAT SWITCH	01-Jul-71	--	0	HARRIER AV8B, RR PEGASUS	Titchfield, UK	K2523	--
3515000-127	--	28-40-92	OM	MK 15 FLOAT SWITCH	01-Dec-68	24-Jul-17	4	F27, F28, F50	Titchfield, UK	K2523	PDF copy of SB_28-40-92 in History folder
3515000-135	--	28-40-12	CMM	MK15 FLOAT SWITCH	10-Apr-86	24-Jul-17	3	F100, F50, F70	Titchfield, UK	K2523	--
3515000-139	--	79-30-12	OM	MK 15 FLOAT SWITCH	01-Nov-70	--	0	BAE 125	Titchfield, UK	K2523	--
3515000-143	--	79-30-02	CMM	MK15 FLOAT SWITCH	01-Feb-84	--	0	Not Known	Titchfield, UK	K2523	--
3515000-149	--	28-41-85	CMM	MK15 FLOAT SWITCH	03-Jul-85	16-Oct-14	3	BAE 125	Titchfield, UK	K2523	S/SDS PN:3515000-140
3515000-150	--	28-41-24	CMM	MK15 FLOAT SWITCH	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3515000-151	--	28-41-24	CMM	MK15 FLOAT SWITCH	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3515000-156	--	28-41-91	CMM	MK 15 FLOAT SWITCH	12-Nov-90	01-Jul-92	1	BAE 125	Titchfield, UK	K2523	--
3515000-157	--	28-41-14	OM	MK15 FLOAT SWITCH	01-Aug-71	--	0	Not Known	Titchfield, UK	K2523	--
3515000-159	--	28-41-24	CMM	MK15 FLOAT SWITCH	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3515000-160	--	28-41-24	CMM	MK15 FLOAT SWITCH	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3515000-161	--	28-41-24	CMM	MK15 FLOAT SWITCH	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3515000-162	--	28-41-24	CMM	MK15 FLOAT SWITCH	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3515000-163	--	28-41-24	CMM	MK15 FLOAT SWITCH	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3515000-164	--	28-41-89	CMM	MK 15 FLOAT SWITCH	01-Oct-90	18-Mar-96	2	BAE 125	Titchfield, UK	K2523	--
3515000-165	--	28-41-03	OM	MK15 FLOAT SWITCH	01-Feb-74	14-Apr-08	2	BAE 125	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3515000-171	--	28-41-90	CMM	MK 15 FLOAT SWITCH	01-Oct-90	01-Jul-92	1	Not Known	Titchfield, UK	K2523	--
3515000-175	--	28-41-58	OM	MK 15 FLOAT SWITCH	01-Jul-76	06-May-11	2	BAe 748	Titchfield, UK	K2523	--
3515000-176	--	28-41-60	OM	MK 15 FLOAT SWITCH	01-Jan-77	06-May-11	2	BAe 748	Titchfield, UK	K2523	--
3515000-178	--	28-41-24	CMM	MK15 FLOAT SWITCH	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3515000-179	--	28-41-86	CMM	MK15 FLOAT SWITCH	01-Jan-85	--	0	Not Known	Titchfield, UK	K2523	--
3515000-181	--	28-41-87	CMM	MK15 FLOAT SWITCH	01-Dec-84	--	0	Not Known	Titchfield, UK	K2523	--
3515000-182	--	28-41-04	OM	MK FLOAT SWITCH	01-Feb-74	--	0	Not Known	Titchfield, UK	K2523	--
3515000-188	--	28-41-10+	CMM	MK15 FLOAT SWITCH 188	01-Jun-71	--	0	--	Titchfield, UK	K2523	--
3515000-190	--	28-40-22	CMM	MK15 FLOAT SW SERIES 190	01-Nov-85	--	0	JAGUAR	Titchfield, UK	K2523	--
3515000-192	--	28-40-23	CMM	MK15 FLOAT SW SERIES 192	01-Nov-85	12-Dec-96	1	JAGUAR	Titchfield, UK	K2523	--
3515000-193	--	28-40-24	CMM	MK15 FLOAT SWITCH SERIES 193	01-Nov-85	16-Dec-96	1	JAGUAR	Titchfield, UK	K2523	--
3515000-194	--	28-40-25	CMM	MK 15 FLOAT SWITCH SERIES 194	01-Nov-85	01-Apr-88	1	JAGUAR	Titchfield, UK	K2523	--
3515000-195	--	28-40-26	CMM	MK15 FLOAT SWITCH SERIES 195	01-Nov-85	--	0	Not Known	Titchfield, UK	K2523	--
3515000-196	--	28-40-27+	CMM	MK15 FLOAT SWITCH SERIES 196	01-Nov-85	16-Dec-96	1	Not Known	Titchfield, UK	K2523	SEE 28-40-27 FOR 35081438
3515000-201	--	28-41-42	OM	MK 15 FLOAT SWITCH	01-Jul-75	--	0	HARRIER	Titchfield, UK	K2523	CANCELLED
3515000-201	--	28-41-99	CMM	MK15 FLOAT SWITCH SERIES 201	01-Jun-98	20-Jan-07	1	HARRIER AV8B, HARRIER FKSZ, HARRIER GR2, HARRIER GR5, HARRIER TMK10, HARRIER TMK10	Titchfield, UK	K2523	SUPERSEDES OM28-41-42
3515000-205	--	28-41-40	OM	MK15 FLOAT SWITCH	01-Oct-74	07-Jan-15	3	LYNX	Titchfield, UK	K2523	--
3515000-206	--	28-41-39	OM	MK15 FLOAT SWITCH	01-Nov-74	30-Jan-07	4	LYNX	Titchfield, UK	K2523	--
3515000-209	--	28-41-25	OM	MK15 FLOAT SWITCH	01-Jun-74	--	0	SHORTS SC7 SKYVAN	Titchfield, UK	K2523	--
3515000-211	--	28-21-10	CMM	MK15 FLOAT SWITCH	01-Dec-85	04-Nov-11	2	BAe ATP, JS61	Titchfield, UK	K2523	--
3515000-212	--	28-21-11	CMM	MK15 FLOAT SW	10-Dec-85	10-Jun-11	1	BAe ATP, JS61	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3515000-214	--	28-41-38	OM	MK15 FLOAT SWITCH	01-Sep-74	--	0	Not Known	Titchfield, UK	K2523	--
3515000-215	--	28-41-41	OM	MK15 FLOAT SWITCH	01-Jan-75	30-Jan-07	3	LYNX	Titchfield, UK	K2523	--
3515000-219	--	28-41-28	OM	MK15 FLOAT SWITCH	01-Apr-74	30-Jan-07	1	Not Known	Titchfield, UK	K2523	--
3515000-220	--	28-40-28	CMM	MK 15 FLOAT SWITCH SERIES 220	01-Nov-85	12-Dec-96	1	JAGUAR	Titchfield, UK	K2523	--
3515000-223	--	PSD-204	CMM	MK15 Float Switch	06-Aug-12	28-Nov-12	1	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	TCH (pub NOT PN)=HAL, BAE for info only
3515000-235	--	28-41-36	OM	MK15 FLOAT SWITCH	17-Jun-75	--	0	SD-330	Titchfield, UK	K2523	--
3515000-237	--	29-30-07	CMM	FLOAT SWITCH	01-Aug-80	22-Apr-11	3	BAE 146	Titchfield, UK	K2523	--
3515000-238	--	28-41-32	OM	MK15 FLOAT SWITCH	01-Nov-74	13-Jan-09	3	CASA 212	Titchfield, UK	K2523	--
3515000-240	--	28-41-74	CMM	FLOAT SWITCH	01-Aug-80	20-Sep-18	11	BAE 146	Titchfield, UK	K2523	--
3515000-241	--	28-41-74	CMM	FLOAT SWITCH	01-Aug-80	20-Sep-18	11	BAE 146	Titchfield, UK	K2523	--
3515000-242	--	28-41-79	CMM	MK15 FLOAT SWITCH	01-Apr-84	30-Dec-11	2	HAWK, Hawk 132 (HAL), Hawk T-165 (SAUDI)	Titchfield, UK	K2523	BAE to approve
3515000-248	--	28-41-36	OM	MK15 FLOAT SWITCH	17-Jun-75	--	0	SD-330	Titchfield, UK	K2523	--
3515000-251	--	28-40-01+	CMM	MK 15 FLOAT SWITCH	29-Sep-94	15-Dec-08	6	EH101	Titchfield, UK	K2523	--
3515000-259	--	28-41-56	OM	MK15 FLOAT SWITCH	01-Dec-76	20-Aug-97	3	CASA 101	Titchfield, UK	K2523	--
3515000-260	--	28-41-57	OM	MK15 FLOAT SWITCH	01-Dec-76	--	0	CASA 101	Titchfield, UK	K2523	--
3515000-266	--	28-41-65	OM	FLOAT SWITCH	27-Oct-77	27-Mar-12	7	SD-330, SD-360	Titchfield, UK	K2523	--
3515000-266	--	SIL-2009-04	SIL	CDCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320 MRTT, A320	Titchfield, UK	K2523	--
3515000-267	--	28-41-65	OM	FLOAT SWITCH	27-Oct-77	27-Mar-12	7	SD-330, SD-360	Titchfield, UK	K2523	--
3515000-268	--	28-41-61	OM	MK15 FLOAT SWITCH	04-Jul-77	03-Aug-12	5	BAE 125	Titchfield, UK	K2523	--
3515000-269	--	28-41-61	OM	MK15 FLOAT SWITCH	04-Jul-77	03-Aug-12	5	BAE 125	Titchfield, UK	K2523	--
3515000-270	--	28-41-61	OM	MK15 FLOAT SWITCH	04-Jul-77	03-Aug-12	5	BAE 125	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3515000-271	--	28-21-10	CMM	MK15 FLOAT SWITCH	01-Dec-85	04-Nov-11	2	BAe ATP, JS61	Titchfield, UK	K2523	--
3515000-272	--	28-41-77	OM	MK15 FLOAT SWITCH	01-Jul-82	--	0	CASA 212	Titchfield, UK	K2523	--
3515000-273	--	28-41-64	OM	MK15 FLOAT SWITCH	14-Sep-77	05-Jan-15	1	F28	Titchfield, UK	K2523	--
3515000-274	--	28-23-36	CMM	FLOAT SWITCH MK15 SERIES 274	01-Nov-81	--	0	Not Known	Titchfield, UK	K2523	--
3515000-277	--	28-41-63	OM	MK15 FLOAT SWITCH	01-Aug-77	--	0	BAC 1-11	Titchfield, UK	K2523	--
3515000-280	--	28-41-81	CMM	MK15 FLOAT SWITCH	01-Sep-84	09-Mar-95	21	HAWK	Titchfield, UK	K2523	--
3515000-282	--	28-41-81	CMM	MK15 FLOAT SWITCH	01-Sep-84	09-Mar-95	21	HAWK	Titchfield, UK	K2523	--
3515000-288	--	28-41-71	OM	MK15 FLOAT SWITCH	01-Oct-79	06-May-11	2	BAe 748	Titchfield, UK	K2523	--
3515000-289	--	28-41-72	OM	MK15 FLOAT SWITCH	01-Sep-79	01-Apr-83	1	BAC 1-11	Titchfield, UK	K2523	--
3515000-290	--	28-41-80	CMM	MK15 FLOAT SWITCH	01-May-84	07-Feb-12	5	HAWK, Hawk T-165 (SAUDI)	Titchfield, UK	K2523	(5copies)
3515000-290	--	PSD-034	CMM	HIGH LEVEL SWITCH	15-Sep-97	02-Sep-08	4	T45	Titchfield, UK	K2523	Brough have PDF
3515000-293	--	28-41-75	OM	MK15 FLOAT SWITCH	01-Nov-80	06-May-11	2	BAe 748	Titchfield, UK	K2523	--
3515000-294	--	28-23-36	CMM	FLOAT SWITCH MK15 SERIES 274	01-Nov-81	--	0	Not Known	Titchfield, UK	K2523	--
3515000-298	--	28-41-76	CMM	FLOAT SWITCH MK15 SERIES 298	01-Nov-81	--	0	Not Known	Titchfield, UK	K2523	--
3515000-301	--	28-41-89	CMM	MK 15 FLOAT SWITCH	01-Oct-90	18-Mar-96	2	BAE 125	Titchfield, UK	K2523	--
3515000-307	--	28-40-17	CMM	MK 15 FLOAT SWITCH	01-Jul-92	--	0	Not Known	Titchfield, UK	K2523	--
3515000-312	--	28-40-35	CMM	MK15 FLOAT SWITCH	12-Jan-99	04-Mar-09	4	EH101	Titchfield, UK	K2523	--
3515000-313	--	PSD-034	CMM	HIGH LEVEL SWITCH	15-Sep-97	02-Sep-08	4	T45	Titchfield, UK	K2523	Brough have PDF
3515000-314	--	28-40-07	CMM	MK15 SERIES 314 FLOAT SWITCH	02-Jul-96	09-Apr-08	2	KT-1	Titchfield, UK	K2523	--
3515000-48	--	82-40-2	OM	MK 15 FLOAT SWITCH	01-Mar-65	--	0	BAC 1-11	Titchfield, UK	K2523	--
3515000-69	--	28-40-58	SB	MK 15 FLOAT SWITCH	01-Jul-67	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3515000-71	--	28-41-33	OM	MK 15 FLOAT SWITCH	01-Mar-74	--	0	Not Known	Titchfield, UK	K2523	--
3515000-72	--	28-40-54	OM	MK 15 FLOAT SWITCH	01-Jun-67	01-Jun-67	1	F28	Titchfield, UK	K2523	--
3515000-76	--	29-30-1	OM	MK 15 FLOAT SWITCH	01-Apr-65	30-Sep-83	1	BAE 125	Titchfield, UK	K2523	--
3515000-81	--	28-40-60	OM	MK 15 FLOAT SWITCH	01-Aug-71	01-Aug-71	1	Not Known	Titchfield, UK	K2523	--
3515000-85	--	28-41-42	OM	MK 15 FLOAT SWITCH	01-Jul-75	--	0	HARRIER	Titchfield, UK	K2523	CANCELLED
3515000-85	--	28-41-96	CMM	MK 15 FLOAT SWITCH SERIES 85	01-Jun-98	20-Jan-07	1	HARRIER AV8B, HARRIER FKSZ, HARRIER GR2, HARRIER GR5, HARRIER TMK10, HARRIER TMK60	Titchfield, UK	K2523	REPLACES OM28-41-42
3515000-86	--	28-41-42	OM	MK 15 FLOAT SWITCH	01-Jul-75	--	0	HARRIER	Titchfield, UK	K2523	CANCELLED
3515000-86	--	28-41-97	CMM	MK15 FLOAT SWITCH SERIES 86	29-May-98	20-Jan-07	1	HARRIER AV8B, HARRIER FKSZ, HARRIER GR2, HARRIER GR5, HARRIER TMK10, HARRIER TMK60	Titchfield, UK	K2523	REPLACES OM28-41-42
3515000-87	--	28-41-42	OM	MK 15 FLOAT SWITCH	01-Jul-75	--	0	HARRIER	Titchfield, UK	K2523	CANCELLED
3515000-87	--	28-41-98	CMM	MK 15 FLOAT SWITCH SERIES 87	08-Jun-98	20-Jan-07	1	HARRIER AV8B, HARRIER FKSZ, HARRIER GR2, HARRIER GR5, HARRIER TMK10, HARRIER TMK60	Titchfield, UK	K2523	SUPERSEDES OM28-41-42
3515000-88	--	28-40-80	OM	MK 15 FLOAT SWITCHES	01-Jul-67	--	0	Not Known	Titchfield, UK	K2523	--
3515000-89	--	28-40-80	OM	MK 15 FLOAT SWITCHES	01-Jul-67	--	0	Not Known	Titchfield, UK	K2523	--
3515000-95	--	28-40-71	OM	MK 15 FLOAT SWITCH	01-Oct-66	--	0	ISLANDER/TRISLANDER	Titchfield, UK	K2523	--
3522120	--	28-M14-3	OM	M14 & 22 FLOAT SWITCHES	01-Nov-69	05-Oct-01	4	VARIOUS	Titchfield, UK	K2523	--
3522120-44	--	28-40-98	OM	MK22 FLOAT SWITCH	23-Oct-69	--	0	Not Known	Titchfield, UK	K2523	--
3522120-45	--	28-40-98	OM	MK22 FLOAT SWITCH	23-Oct-69	--	0	Not Known	Titchfield, UK	K2523	--
3522120-47	--	28-M14-147	OM	M14 & 22 FLOAT SWITCHES	01-Sep-63	--	0	Not Known	Titchfield, UK	K2523	--
3522120-57	--	28-M14-147	OM	M14 & 22 FLOAT SWITCHES	01-Sep-63	--	0	Not Known	Titchfield, UK	K2523	--
3522120-62	--	28-M14-3	OM	M14 & 22 FLOAT SWITCHES	01-Nov-69	05-Oct-01	4	VARIOUS	Titchfield, UK	K2523	--
3530000-1	--	28-46-15	CMM	LEVEL AND TEMPERATURE SENSORS	01-Apr-86	20-Feb-12	9	A319, A320, A321, A330, A340, N250	Titchfield, UK	K2523	--
3530000-3	--	28-46-15	CMM	LEVEL AND TEMPERATURE SENSORS	01-Apr-86	20-Feb-12	9	A319, A320, A321, A330, A340, N250	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3540000-1	--	28-46-15	CMM	LEVEL AND TEMPERATURE SENSORS	01-Apr-86	20-Feb-12	9	A319, A320, A321, A330, A340, N250	Titchfield, UK	K2523	--
3540000-1	--	K2523-28-002	SIL	New Level Sensor	05-Mar-12	--	0	A318, A319, A320, A321	Titchfield, UK	K2523	--
3540000-3	--	28-46-15	CMM	LEVEL AND TEMPERATURE SENSORS	01-Apr-86	20-Feb-12	9	A319, A320, A321, A330, A340, N250	Titchfield, UK	K2523	--
3540000-3	--	SIL-2009-01	SIL	TEMPERATURE SENSOR, REPLACEMENT	12-Mar-09	--	0	A319, A320, A321, A330, A340	Titchfield, UK	K2523	--
3540000-4	--	28-46-15	CMM	LEVEL AND TEMPERATURE SENSORS	01-Apr-86	20-Feb-12	9	A319, A320, A321, A330, A340, N250	Titchfield, UK	K2523	--
3540000-4	--	SIL-2009-01	SIL	TEMPERATURE SENSOR, REPLACEMENT	12-Mar-09	--	0	A319, A320, A321, A330, A340	Titchfield, UK	K2523	--
3603105	--	28-A3-5	CMM	MK3 TRANSFER VALVE	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
3603110	--	28-20-23	OM	TRANSFER VALVE	01-Mar-67	01-Jul-87	2	Not Known	Titchfield, UK	K2523	--
3604150	--	28-22-98	OM	REFUEL VALVE ASSY	01-Jan-76	--	0	Not Known	Titchfield, UK	K2523	--
3604200	--	28-23-30	OM	REFUEL VALVE ASSY	01-Jan-81	01-Aug-85	2	SAAB VIGGEN	Titchfield, UK	K2523	Viggen is obsolete
3605080	--	28-20-57	OM	EQUAL FLOW VALVE	01-Jul-65	01-May-83	2	MB326	Titchfield, UK	K2523	--
3605080	--	28-21-4247-300	SB	EQUAL FLOW VALVE - CHANGE OF BUSH	17-Mar-69	--	0	Not Known	Titchfield, UK	K2523	--
3605195	--	28-20-89	OM	EQUAL FLOW VALVE	01-Apr-70	--	0	MB326	Titchfield, UK	K2523	--
3605198	--	28-22-10	OM	DUAL SHUT OFF VALVE	01-May-72	--	0	MB326	Titchfield, UK	K2523	--
3605200	--	28-20-92	OM	DUAL SHUT OFF VALVE	01-Apr-71	01-Jul-71	1	MB326	Titchfield, UK	K2523	--
3605290	--	28-23-23	OM	SHUT OFF VALVE	01-Jan-79	--	0	MB326	Titchfield, UK	K2523	--
3606100A	--	28-A6-1	OM	MK6 TRANSFER VALVE	01-Oct-60	--	0	Not Known	Titchfield, UK	K2523	--
3606100B	--	28-A6-1	OM	MK6 TRANSFER VALVE	01-Oct-60	--	0	Not Known	Titchfield, UK	K2523	--
3606100C	--	28-A6-1	OM	MK6 TRANSFER VALVE	01-Oct-60	--	0	Not Known	Titchfield, UK	K2523	--
3606260	--	28-23-27	OM	TRANSFER VALVE	01-Oct-79	06-May-11	2	BAe 748	Titchfield, UK	K2523	--
3609185	--	28-A9-3	OM	TRANSFER VALVE MK9	01-Nov-58	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3609200	--	28-20-53	OM	MK 9 DUAL TRANSFER VALVE	01-May-65	--	0	Not Known	Titchfield, UK	K2523	--
3609200	--	28-22-19519	SB	DUAL TRNSFR VALVE - INTRO OF TORSION SPRING	29-Sep-69	01-Mar-70	1	Not Known	Titchfield, UK	K2523	--
3609220	--	28-A9-5	OM	MK9 TRANSFER VALVE	01-Jun-62	--	0	Not Known	Titchfield, UK	K2523	--
3609245	--	28-20-54	OM	MK9 TRANSFER VALVE	01-May-65	01-Aug-69	1	Not Known	Titchfield, UK	K2523	--
3609245	--	28-23-19411	SB	TRNSFR VALVE - INTRO OF ORIENTATION HOLE	01-May-70	--	0	Not Known	Titchfield, UK	K2523	--
3609280	--	28-20-19	OM	MK9 DUAL TRANSFER VALVE	01-Jan-69	01-Aug-69	1	Not Known	Titchfield, UK	K2523	--
3609280	--	28-22-19519	SB	DUAL TRNSFR VALVE - INTRO OF TORSION SPRING	29-Sep-69	01-Mar-70	1	Not Known	Titchfield, UK	K2523	--
3609285	--	28-20-18	OM	MK9 DUAL TRANSFER VALVE	01-Aug-64	--	0	Not Known	Titchfield, UK	K2523	--
3609290	--	28-12-18747	SB	DUAL TRNSFR VALVE - NEW VALVE SEAT ASSY	30-Mar-68	27-May-71	1	Not Known	Titchfield, UK	K2523	--
3609290	--	28-20-77+	OM	MK 9 DUAL TRANSFER VALVE	01-Nov-70	01-Feb-89	2	Not Known	Titchfield, UK	K2523	--
3609290	--	28-38-1199	SB	DUAL TRNSFR VALVE - INTRO NEW FLOAT ARM	01-Jan-73	--	0	Not Known	Titchfield, UK	K2523	--
3609295	--	28-12-18747	SB	DUAL TRNSFR VALVE - NEW VALVE SEAT ASSY	30-Mar-68	27-May-71	1	Not Known	Titchfield, UK	K2523	--
3609295	--	28-20-77+	OM	MK 9 DUAL TRANSFER VALVE	01-Nov-70	01-Feb-89	2	Not Known	Titchfield, UK	K2523	--
3609295	--	28-38-1199	SB	DUAL TRNSFR VALVE - INTRO NEW FLOAT ARM	01-Jan-73	--	0	Not Known	Titchfield, UK	K2523	--
3610050	--	28-20-72	OM	MK 10 TRANSFER VALVE	01-Nov-69	--	0	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
3610060	--	28-A10-3	OM	MK10 TRANSFER VALVE	01-Nov-63	--	0	Not Known	Titchfield, UK	K2523	--
3610070	--	28-20-6	OM	TRANSFER VALVE MK 10	01-Sep-64	--	0	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
3615045	--	28-22-97	OM	TRANSFER VALVE MK15	01-Mar-76	24-Oct-14	4	MB326, MB339, SHORTS SC7 SKYVAN	Titchfield, UK	K2523	--
3706130-140	--	28-20-36	OM	FUEL/NO AIR MK 15 VALVE ASSY	01-Oct-68	--	0	Not Known	Titchfield, UK	K2523	--
3706130-145	--	28-20-36	OM	FUEL/NO AIR MK 15 VALVE ASSY	01-Oct-68	--	0	Not Known	Titchfield, UK	K2523	--
3706130-160	--	28-20-36	OM	FUEL/NO AIR MK 15 VALVE ASSY	01-Oct-68	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3706130-165	--	28-20-36	OM	FUEL/NO AIR MK 15 VALVE ASSY	01-Oct-68	--	0	Not Known	Titchfield, UK	K2523	--
3706190	--	28-22-73	OM	SOLENOID VALVE	26-Jun-75	--	0	SD-330	Titchfield, UK	K2523	--
3706225	--	28-10-83	CMM	SOLENOID VENT VALVE	01-Jun-84	03-Oct-12	5	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	BAE to approve
3706235	--	28-23-21	OM	SOLENOID VALVE	01-Mar-78	03-Dec-91	3	SD-330	Titchfield, UK	K2523	--
3706270	--	30-40-01	CMM	SOLENOID VALVE	03-Oct-80	28-Feb-12	4	BAE 146, BAe ATP, JS61	Titchfield, UK	K2523	--
3706315	--	28-21-08	CMM	SOLENOID VV	01-Apr-86	04-Nov-11	1	BAe ATP, JS61	Titchfield, UK	K2523	--
3708105	--	28-13-09	CMM	FUEL/NO AIR VALVE	26-Jun-95	--	0	N250	Titchfield, UK	K2523	--
3709000-5	--	28-23-08	OM	FUEL-NO AIR VALVE ASSY	01-Oct-76	01-Feb-84	1	CASA 101	Titchfield, UK	K2523	--
3709100-17	--	28-21-54	CMM	REFUEL SHUT-OFF VALVE	01-Nov-92	26-Jul-07	2	N250, SAAB 2000	Titchfield, UK	K2523	--
38-0001	--	28-24-29	CMM	JET PUMP-FUEL TRANSFER SCAVENGE	05-Dec-07	23-Sep-15	4	BOEING 787	Titchfield, UK	K2523	--
38-0002	--	28-24-30	CMM	JET PUMP-WATER SCAVENGE	05-Dec-07	26-Jun-17	4	BOEING 787	Titchfield, UK	K2523	--
38-0003	--	47-21-04	ACMM	PUMP-EJECTOR	01-Aug-07	25-Sep-15	3	BOEING 787	Titchfield, UK	K2523	--
38-0008	--	28-26-10	CMM	JET PUMP	31-May-04	18-Nov-13	3	A380	Titchfield, UK	K2523	--
38-0008	--	38-0008-28-01	SB	MODIFICATION OF COLLECTOR CELL JET PUMP	--	--	0	A380	Titchfield, UK	K2523	TO BE WRITTEN
38-0008	--	38-0008-28-02	SB	Retrofit Collector Cell Jet Pump	21-Jan-21	21-Jan-21	0	A380	Titchfield, UK	K2523	TO BE WRITTEN
38-0009	--	28-26-10	CMM	JET PUMP	31-May-04	18-Nov-13	3	A380	Titchfield, UK	K2523	--
38-0010	--	28-24-29	CMM	JET PUMP-FUEL TRANSFER SCAVENGE	05-Dec-07	23-Sep-15	4	BOEING 787	Titchfield, UK	K2523	--
38-0011	--	28-24-29	CMM	JET PUMP-FUEL TRANSFER SCAVENGE	05-Dec-07	23-Sep-15	4	BOEING 787	Titchfield, UK	K2523	--
38-0014	--	47-21-04	ACMM	PUMP-EJECTOR	01-Aug-07	25-Sep-15	3	BOEING 787	Titchfield, UK	K2523	--
38-0015	--	47-21-12	ACMM	Centre Tank Ejector Pump	25-Sep-15	30-Apr-16	1	BOEING 787, Boeing 787-9	Titchfield, UK	K2523	--
38-0019-1100	--	28-21-53++	ACMM	JET PUMP TYPE 8814	01-Jul-91	01-Dec-16	3	A330, A340	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
38-0019-1100	--	28-21-63	CMM	COLLECTOR CELL JET PUMP - Type 38-0019	07-Sep-16	22-Mar-18	1	A330 NEO	Titchfield, UK	K2523	--
38-0019-1100	--	PSD-364	CMM	Washer Salvage Scheme	20-Nov-20	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
38-0019-1200	--	28-21-63	CMM	COLLECTOR CELL JET PUMP - Type 38-0019	07-Sep-16	22-Mar-18	1	A330 NEO	Titchfield, UK	K2523	--
38-0019-1200	--	38-0019-28-01	SB	Collector Cell Jet Pump - Change of Washer Quantity	--	--	0	A330 NEO	Titchfield, UK	K2523	TO BE WRITTEN
38-0019-1200	--	PSD-363	CMM	Bolt removal - Jet Pump Collector Cell	20-Nov-20	24-Nov-20	2	--	Titchfield, UK	K2523	BASIC MANUAL
38-0020-1100	--	28-21-35	CMM	Jet Pump, Fuel Scavenge	13-Sep-16	13-Sep-16	0	A330 NEO	Titchfield, UK	K2523	--
38-0025	--	28-26-10	CMM	JET PUMP	31-May-04	18-Nov-13	3	A380	Titchfield, UK	K2523	--
38-0025	--	K2523-28-014	SIL	INTRODUCTION OF NEW JET PUMP	--	--	0	A380	Titchfield, UK	K2523	TO BE WRITTEN
3801215	--	28-21-28	CMM	MK 54 REFUEL/DEFUEL VALVE	30-Jun-94	17-Oct-14	3	EH101	Titchfield, UK	K2523	INCLUDES SOLENOID VALVE
3801225	--	28-21-09	CMM	MK54 REF/DEF VALVE & SOL.VALVE ASSY	01-Feb-87	11-Nov-13	7	BAe ATP, JS61	Titchfield, UK	K2523	INC SOL VLV 3801225
3802045	--	28-25-61	CMM	REFUEL VALVE - ELEMENT ASSEMBLY	01-May-88	21-Feb-19	18	A318, A319, A320, A321	Titchfield, UK	K2523	--
3802045	--	SIL-PS-2-96	SIL	IDENTIFICATION OF SOLENOID VALVE ASSY PN 3802045	15-Feb-96	--	0	A319, A320, A321	Titchfield, UK	K2523	--
39-0001-1100	--	28-24-39	CMM	PUMP BOOST	06-Dec-07	18-Feb-16	3	BOEING 787	Titchfield, UK	K2523	--
39-0001-1200	--	28-24-39	CMM	PUMP BOOST	06-Dec-07	18-Feb-16	3	BOEING 787	Titchfield, UK	K2523	--
39-0001-1300	--	28-24-39	CMM	PUMP BOOST	06-Dec-07	18-Feb-16	3	BOEING 787	Titchfield, UK	K2523	--
39-0001-1300	--	39-0001-28-01	SB	Modification to Boost Pump MK1500	15-Jun-17	06-Jun-19	1	BOEING 787	Titchfield, UK	K2523	--
39-0001-1300	--	K2523-28-006	SIL	Introduction of NewB787 Boost Pump	26-Sep-13	--	0	BOEING 787	Titchfield, UK	K2523	--
39-0001-1300	--	SIL-2009-04	SIL	CDCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A320	Titchfield, UK	K2523	--
39-0001-1400	--	28-24-39	CMM	PUMP BOOST	06-Dec-07	18-Feb-16	3	BOEING 787	Titchfield, UK	K2523	--
39-0001-1400	--	39-0001-28-01	SB	Modification to Boost Pump MK1500	15-Jun-17	06-Jun-19	1	BOEING 787	Titchfield, UK	K2523	--
39-0001-1400	--	K2523-28-006	SIL	Introduction of NewB787 Boost Pump	26-Sep-13	--	0	BOEING 787	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
39-0001-1500	--	28-24-39	CMM	PUMP BOOST	06-Dec-07	18-Feb-16	3	BOEING 787	Titchfield, UK	K2523	--
39-0001-1500	--	39-0001-28-01	SB	Modification to Boost Pump MK1500	15-Jun-17	06-Jun-19	1	BOEING 787	Titchfield, UK	K2523	--
39-0002-1100	--	28-24-37	CMM	PUMP-OVERRIDE/JETTISON	06-Dec-07	10-Jul-17	6	BOEING 787	Titchfield, UK	K2523	--
39-0002-1100	--	K2523-28-008	SIL	Introduction of New OJ Pump	29-Apr-14	--	0	BOEING 787	Titchfield, UK	K2523	--
39-0002-1100	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A340	Titchfield, UK	K2523	--
39-0003-1100	--	28-24-38	CMM	HOUSING-OVERRIDE/JETTISON PUMP	05-Feb-08	14-Aug-15	2	BOEING 787	Titchfield, UK	K2523	--
39-0003-1200	--	28-24-38	CMM	HOUSING-OVERRIDE/JETTISON PUMP	05-Feb-08	14-Aug-15	2	BOEING 787	Titchfield, UK	K2523	--
39-0003-1200	--	39-0003-28-01	SB	Introduction of New Seal	--	--	0	BOEING 787	Titchfield, UK	K2523	TO BE WRITTEN
39-0003-1200	--	K2523-28-020	SIL	Introduction of New Seal	--	23-Aug-21	0	BOEING 787	Titchfield, UK	K2523	TO BE WRITTEN
39-0004-1100	--	28-24-40	CMM	HOUSING-BOOST PUMP	06-Dec-07	10-Jul-17	3	BOEING 787	Titchfield, UK	K2523	--
39-0004-1100	--	39-0004-28-01	SB	Replacement of Valve Outlet Assembly	--	--	0	BOEING 787	Titchfield, UK	K2523	TO BE WRITTEN
39-0004-1100	--	K2523-28-017	SIL	Boost Pump Product Improvement Spring	--	--	0	BOEING 787	Titchfield, UK	K2523	TO BE WRITTEN
39-0004-1100	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A340	Titchfield, UK	K2523	--
39-0005-1100	--	28-24-35	CMM	PUMP-DC APU	31-Jul-07	13-Feb-19	8	BOEING 787	Titchfield, UK	K2523	ZODIAC
39-0005-1100	--	39-0005-28-01	SB	Replacement of motor electrical	--	09-Jul-19	0	BOEING 787	Titchfield, UK	K2523	Zodiac
39-0005-1100	--	K2523-28-21	SIL	Service Information Letter - Change of Ownership	19-Nov-21	19-Nov-21	0	BOEING 787	Titchfield, UK	K2523	BASIC MANUAL
39-0005-1200	--	28-24-35	CMM	PUMP-DC APU	31-Jul-07	13-Feb-19	8	BOEING 787	Titchfield, UK	K2523	ZODIAC
39-0005-1200	--	39-0005-28-01	SB	Replacement of motor electrical	--	09-Jul-19	0	BOEING 787	Titchfield, UK	K2523	Zodiac
39-0005-1200	--	39-0005-28-02	SB	Replacement of the motor electrical	--	--	0	BOEING 787	Titchfield, UK	K2523	CANCELLED
39-0005-1200	--	K2523-28-21	SIL	Service Information Letter - Change of Ownership	19-Nov-21	19-Nov-21	0	BOEING 787	Titchfield, UK	K2523	BASIC MANUAL
39-0005-1300	--	28-24-35	CMM	PUMP-DC APU	31-Jul-07	13-Feb-19	8	BOEING 787	Titchfield, UK	K2523	ZODIAC

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
39-0005-1300	--	39-0005-28-01	SB	Replacement of motor electrical	--	09-Jul-19	0	BOEING 787	Titchfield, UK	K2523	Zodiac
39-0005-1300	--	39-0005-28-02	SB	Replacement of the motor electrical	--	--	0	BOEING 787	Titchfield, UK	K2523	CANCELLED
39-0005-1300	--	K2523-28-21	SIL	Service Information Letter - Change of Ownership	19-Nov-21	19-Nov-21	0	BOEING 787	Titchfield, UK	K2523	BASIC MANUAL
39-0005-1400	--	28-24-35	CMM	PUMP-DC APU	31-Jul-07	13-Feb-19	8	BOEING 787	Titchfield, UK	K2523	ZODIAC
39-0005-1400	--	39-0005-28-02	SB	Replacement of the motor electrical	--	--	0	BOEING 787	Titchfield, UK	K2523	CANCELLED
39-0005-1400	--	K2523-28-21	SIL	Service Information Letter - Change of Ownership	19-Nov-21	19-Nov-21	0	BOEING 787	Titchfield, UK	K2523	BASIC MANUAL
39-0006-1100	--	28-24-36	CMM	HOUSING-DC PUMP APU	31-Jan-08	14-Aug-15	3	BOEING 787	Titchfield, UK	K2523	INTERTECHNIQUE RESPONSIBILITY. MAKE SURE ANY MODS FROM HERE ARE BASED ON TO THEM.
39-0006-1100	--	K2523-28-21	SIL	Service Information Letter - Change of Ownership	19-Nov-21	19-Nov-21	0	BOEING 787	Titchfield, UK	K2523	BASIC MANUAL
39-0024	--	28-20-10_K2523_1	CMM	Feed Pump Component Maintenance Manual	--	--	0	CH-53K	Titchfield, UK	K2523	TO BE WRITTEN
39-0024-1100	--	28-20-10_K2523_1	CMM	Feed Pump Component Maintenance Manual	--	--	0	CH-53K	Titchfield, UK	K2523	TO BE WRITTEN
39-0031	--	28-30-20	CMM	Dump Pump	09-Jul-19	20-Apr-21	1	CH-53K	Titchfield, UK	K2523	--
39-0043-1100	--	28-21-52+	CMM	CANISTER TYPE 8411	22-Jul-87	06-Dec-17	13	A320, A320 NEO	Titchfield, UK	K2523	--
39-0043-1100	--	PSD-384	CMM	Canister Insert Replacement	05-Oct-21	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
39-0044-1100	--	28-21-52+	CMM	CANISTER TYPE 8411	22-Jul-87	06-Dec-17	13	A320, A320 NEO	Titchfield, UK	K2523	--
39-0055-1100	--	28-22-09	CMM	Fuel Boost Pump	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
39-0056-1100	--	28-22-19	CMM	Fuel Boost Pump Housing	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
39-0057-1100	--	28-22-29	CMM	Override Jettison Fuel Pump	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
39-0057-1200	--	28-22-29	CMM	Override Jettison Fuel Pump	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
39-0059-1100	--	28-22-32	CMM	Override Jettison Fuel Pump Housing	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
39-0060-1100	--	28-25-04	CMM	DC APU Pump	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
39-0061-1100	--	28-25-05	CMM	DC APU Pump Housing	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
39-0062-1100	--	28-21-62	CMM	CANISTER TYPE 39-0062	--	08-Jul-19	1	A330 NEO	Titchfield, UK	K2523	--
39-0062-1100	--	K2523-28-010	SIL	Incorrect Part Marking	--	--	0	A330 NEO	Titchfield, UK	K2523	TO BE WRITTEN
39-0067-1100	--	28-26-26	CMM	Transfer Pump	--	--	0	A380	Titchfield, UK	K2523	TO BE WRITTEN
39-0067-1200	--	28-26-26	CMM	Transfer Pump	--	--	0	A380	Titchfield, UK	K2523	TO BE WRITTEN
3901035	--	28-20-21	OM	JETPUMP	01-Oct-69	01-Jan-83	2	F27, F28	Titchfield, UK	K2523	--
3901055	--	28-20-21	OM	JETPUMP	01-Oct-69	01-Jan-83	2	F27, F28	Titchfield, UK	K2523	--
3901100	--	28-20-21	OM	JETPUMP	01-Oct-69	01-Jan-83	2	F27, F28	Titchfield, UK	K2523	--
3901110	--	28-20-60	OM	JETPUMP WITH NRV	01-Jun-69	--	0	G222	Titchfield, UK	K2523	--
3901150	--	28-20-62	OM	JETPUMP WITH NRV	01-May-69	09-Sep-05	4	BAC 1-11	Titchfield, UK	K2523	--
3901170	--	28-21-89	OM	JETPUMP WITH NRV	01-Mar-72	24-Sep-01	1	VFW 614	Titchfield, UK	K2523	--
3901190	--	28-22-06	OM	JETPUMP	01-Jan-74	--	0	CASA 212	Titchfield, UK	K2523	--
3901200	--	28-20-91	OM	JETPUMP	01-Feb-71	--	0	Not Known	Titchfield, UK	K2523	--
3901335	--	28-21-02	CMM	JET PUMP	01-Jan-84	--	0	Not Known	Titchfield, UK	K2523	--
3901340	--	28-11-31	CMM	JET PUMP	01-Apr-83	07-Nov-18	5	A300, A300-400, A300-600, A310, A330, A340, A340-500, A340-600, MD11	Titchfield, UK	K2523	--
3901360	--	28-20-65	CMM	JET PUMP	01-Dec-83	--	0	F100, F27, F28, F70	Titchfield, UK	K2523	--
3901395	--	28-22-53	CMM	SCAVENGE JET PUMP	01-Jan-87	19-Nov-15	8	A318, A319, A320	Titchfield, UK	K2523	Previously 28-21-53
3901515	--	28-26-20	CMM	JET PUMP	10-Jul-93	22-Oct-04	3	A321	Titchfield, UK	K2523	--
3901554	--	28-21-29	CMM	JET PUMP	20-Jun-94	10-Feb-96	1	EH101	Titchfield, UK	K2523	--
3M1	--	24-09-11	OM	LIGHT WEIGHT MOTOR UNITS	01-Jul-70	27-Nov-13	4	BAC 1-11	Titchfield, UK	K2523	--
3M1	--	28-26-9072	SB	LW MOT VALVES - TO IMPROVE O/HAUL LIFE	17-Jun-70	--	0	Not Known	Titchfield, UK	K2523	--
3M1	--	28-33-8882	SB	LW MOTOR UNITS - IMPROVED TAB WASHER	01-Feb-71	01-Apr-71	1	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
3M12	--	24-09-11	OM	LIGHT WEIGHT MOTOR UNITS	01-Jul-70	27-Nov-13	4	BAC 1-11	Titchfield, UK	K2523	--
3M12	--	28-33-8882	SB	LW MOTOR UNITS - IMPROVED TAB WASHER	01-Feb-71	01-Apr-71	1	Not Known	Titchfield, UK	K2523	--
3M2	--	24-09-12	OM	LIGHT WEIGHT MOTOR UNIT	01-Aug-70	01-May-71	1	Not Known	Titchfield, UK	K2523	--
3M2	--	28-33-8882	SB	LW MOTOR UNITS - IMPROVED TAB WASHER	01-Feb-71	01-Apr-71	1	Not Known	Titchfield, UK	K2523	--
3M3	--	24-09-10	OM	LW MOTOR UNITS	01-Jun-70	01-Oct-14	6	F28	Titchfield, UK	K2523	--
3M3	--	28-09-9075-19776	SB	LW MOTOR UNITS - IMPROVED SEALING	01-Jun-70	09-Oct-70	1	F27, F28	Titchfield, UK	K2523	--
3M3	--	28-26-9072	SB	LW MOT VALVES - TO IMPROVE O/HAUL LIFE	17-Jun-70	--	0	Not Known	Titchfield, UK	K2523	--
3M3	--	28-27-9075	SB	LIGHTWEIGHT MOT SP VALVE SEALING	01-Jun-70	--	0	F28	Titchfield, UK	K2523	--
3M3	--	28-33-8882	SB	LW MOTOR UNITS - IMPROVED TAB WASHER	01-Feb-71	01-Apr-71	1	Not Known	Titchfield, UK	K2523	--
3M3-1	--	24-09-10	OM	LW MOTOR UNITS	01-Jun-70	01-Oct-14	6	F28	Titchfield, UK	K2523	--
3M3-1	--	28-09-9075-19776	SB	LW MOTOR UNITS - IMPROVED SEALING	01-Jun-70	09-Oct-70	1	F27, F28	Titchfield, UK	K2523	--
3M3-1	--	28-10-72	OM	MOTORISED SPV	29-Jun-72	18-Mar-96	3	F28	Titchfield, UK	K2523	--
3M4	--	24-09-10	OM	LW MOTOR UNITS	01-Jun-70	01-Oct-14	6	F28	Titchfield, UK	K2523	--
3M4	--	28-09-9075-19776	SB	LW MOTOR UNITS - IMPROVED SEALING	01-Jun-70	09-Oct-70	1	F27, F28	Titchfield, UK	K2523	--
3M4	--	28-26-9072	SB	LW MOT VALVES - TO IMPROVE O/HAUL LIFE	17-Jun-70	--	0	Not Known	Titchfield, UK	K2523	--
3M4	--	28-27-9075	SB	LIGHTWEIGHT MOT SP VALVE SEALING	01-Jun-70	--	0	F28	Titchfield, UK	K2523	--
3M4	--	28-33-8882	SB	LW MOTOR UNITS - IMPROVED TAB WASHER	01-Feb-71	01-Apr-71	1	Not Known	Titchfield, UK	K2523	--
3M4-1	--	24-09-10	OM	LW MOTOR UNITS	01-Jun-70	01-Oct-14	6	F28	Titchfield, UK	K2523	--
3M4-1	--	28-09-9075-19776	SB	LW MOTOR UNITS - IMPROVED SEALING	01-Jun-70	09-Oct-70	1	F27, F28	Titchfield, UK	K2523	--
4020201	--	28-10-24	OM	IFR POD	01-Oct-69	01-Feb-71	1	Not Known	Titchfield, UK	K2523	--
407-1-32460-000	--	24-20-19	CMM	CURRENT TRANSFORMER	--	24-Jul-17	4	BAE 146	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
408-1-00036-061	--	24-09-551	CMM	SWITCH	01-Nov-64	--	0	HS 125	Titchfield, UK	K2523	--
408-1-00036-160	--	24-09-551	CMM	SWITCH	01-Nov-64	--	0	HS 125	Titchfield, UK	K2523	--
408-1-00040-021	--	24-09-551	CMM	SWITCH	01-Nov-64	--	0	HS 125	Titchfield, UK	K2523	--
41094A010000	--	36-13-01	CMM	HP GROUND CONNECTOR & NRV	30-Sep-05	--	0	A380	Titchfield, UK	K2523	--
41095A010000	--	36-11-99	CMM	SERVICE AIR CHECK VALVE	30-Sep-05	--	0	A380	Titchfield, UK	K2523	--
412-1-20050	--	OSM448	CMM	RFI SUPPRESSION UNIT	31-Jul-69	--	0	JETSTREAM	Titchfield, UK	K2523	BASIC MANUAL
4127099	--	FR23-83	TDS	ADAPTOR ASSY 1 1/2IN/2 1/2IN BSP	01-Dec-83	22-Jan-02	1	BRUNEI OPV	Titchfield, UK	K2523	--
4127360	--	28-22-25	TDS	VENT & DRAIN VALVE ASSYS	01-Apr-83	30-Sep-02	2	A300, A300-400, A300-600, A310, A318, A319, A320, A321, A330, A340, A340-500, A340-600, A380	Titchfield, UK	K2523	--
4127420	--	FR20-83	TDS	1 1/2IN QUICK DISCONNECT	01-Dec-83	--	0	Not Known	Titchfield, UK	K2523	--
4127456	--	FR22-83	TDS	HOSE UNIT ADAPTOR	01-Dec-83	--	0	Not Known	Titchfield, UK	K2523	--
4127472	--	FR32-85	TDS	HOSE UNIT ADAPTOR	01-Oct-85	--	0	Not Known	Titchfield, UK	K2523	--
4127474	--	FR4-83	TDS	DEFUELLING TUBE ASSY	01-Apr-83	01-Dec-92	2	BRUNEI OPV	Titchfield, UK	K2523	--
4127479	--	FR33-85	TDS	STRAINER	01-Oct-85	--	0	Not Known	Titchfield, UK	K2523	--
4127543	--	FR21-83	TDS	BLANKING PLUG	01-Dec-83	--	0	Not Known	Titchfield, UK	K2523	--
412760	--	28-10-01	CMM	Inward Vent Valve	--	04-Jan-17	0	KC46A	Titchfield, UK	K2523	--
4128080	--	28-30-19212	SB	HE PRES CONT. - NEW HANDWHEEL	01-Dec-70	--	0	Not Known	Titchfield, UK	K2523	--
4128080	--	4128-2	SB	HEP CONTROLLER - MODIFIED OPERATING RING	22-Jan-68	--	1	Not Known	Titchfield, UK	K2523	pdf copy of technical servicing advice
4128080	--	4128-3	SB	HEP CONTROLLER - ENLARGED BLEED HOLE	22-Jan-68	--	1	Not Known	Titchfield, UK	K2523	pdf copy of technical servicing advice
4128080	--	4128-4	SB	HEP CONTROLLER - PROVISION OF SLOT IN BOLT	22-Jan-68	--	1	Not Known	Titchfield, UK	K2523	pdf copy of technical servicing advice
4128080	--	4128-5	SB	HEP CONTROLLER - NEW SPIGOT BUSH	16-Oct-68	--	1	Not Known	Titchfield, UK	K2523	scan copy of Technicl Servicing Advice
4137004	--	FR34-85	TDS	HOSE 1 1/2'X4M	01-Oct-85	01-Nov-88	1	BRUNEI OPV	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
4137005	--	FR9-88	TDS	HOSE ASSY 2 1/2' X 25M	01-Aug-88	01-Dec-92	1	Not Known	Titchfield, UK	K2523	--
4137006	--	FR34-85	TDS	HOSE 1 1/2'X4M	01-Oct-85	01-Nov-88	1	BRUNEI OPV	Titchfield, UK	K2523	--
4137011	--	FR13-88	TDS	HOSE ASSY (LAY FLAT)	01-Nov-88	--	0	Not Known	Titchfield, UK	K2523	--
4137027	--	FR10-88	TDS	HOSE ASSY 2'X2M	01-Aug-88	22-Jan-02	1	BRUNEI OPV	Titchfield, UK	K2523	--
42A10	--	28-20-93	OM	ELECTRICALLY OPERATED SPV	01-Jul-70	--	0	AV8A, HAWK	Titchfield, UK	K2523	PRELIMINARY
4320001	--	28-13-02	OM	HOSE DRUM AND TWO SPEED GEARBOX	01-May-70	--	0	Not Known	Titchfield, UK	K2523	--
4320042	--	28-13-03	OM	SPEED CONTROL	01-Apr-70	--	0	Not Known	Titchfield, UK	K2523	--
4320084	--	28-13-03	OM	SPEED CONTROL	01-Apr-70	--	0	Not Known	Titchfield, UK	K2523	--
43201076	--	28-13-04	OM	MK20 POD HOSEASSY,RECEP CPLG&DROG	01-Jun-70	--	0	Not Known	Titchfield, UK	K2523	--
43201143	--	28-13-03	OM	SPEED CONTROL	01-Apr-70	--	0	Not Known	Titchfield, UK	K2523	--
43201145	--	28-13-03	OM	SPEED CONTROL	01-Apr-70	--	0	Not Known	Titchfield, UK	K2523	--
4320705	--	28-13-05	OM	FLUID COOLER	01-Feb-71	--	0	Not Known	Titchfield, UK	K2523	--
4320805	--	28-13-02	OM	HOSE DRUM AND TWO SPEED GEARBOX	01-May-70	--	0	Not Known	Titchfield, UK	K2523	--
4320880	--	28-13-03	OM	SPEED CONTROL	01-Apr-70	--	0	Not Known	Titchfield, UK	K2523	--
4320911	--	24-13-01	OM	MK20 POD EQUIPMENT	01-Jun-70	--	0	Not Known	Titchfield, UK	K2523	--
4322120	--	28-10-9	OM	HELICOPTER REFUELLING COUPLING	01-May-66	--	0	Not Known	Titchfield, UK	K2523	--
4322147	--	28-10-9	OM	HELICOPTER REFUELLING COUPLING	01-May-66	--	0	Not Known	Titchfield, UK	K2523	--
4322250	--	FR14-88	TDS	COUPLING SUB-ASSY	01-Nov-88	--	0	Not Known	Titchfield, UK	K2523	--
43323070	--	28-87-58	CMM	VANE PUMP ASSY	01-Nov-88	--	0	Not Known	Titchfield, UK	K2523	MIL SYSTEMS DIV
43323169	--	28-87-41	CMM	TORQUE DRUM UNIT	01-Oct-88	--	0	Not Known	Titchfield, UK	K2523	MIL SYSTEMS DIV
43323226	--	28-87-62	CMM	SERVING CARRIAGE ASSY	01-Nov-88	--	0	Not Known	Titchfield, UK	K2523	MIL SYSTEMS DIV

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
43323240	--	28-88-31	CMM	CONTROL VALVE AND ACTUATOR ASSY	01-Aug-88	--	0	Not Known	Titchfield, UK	K2523	MIL SYSTEMS DIV
43323295	--	28-87-56	CMM	HOSE DRUM DRIVE UNIT	01-Oct-88	--	0	Not Known	Titchfield, UK	K2523	MIL SYSTEMS DIV
43323326	--	28-87-44	CMM	TENSATOR DRIVE ASSY	01-Mar-89	--	0	Not Known	Titchfield, UK	K2523	MIL SYSTEMS DIV
43323496	--	28-87-23	CMM	HOSE JETTISON UNIT	01-Nov-88	--	0	Not Known	Titchfield, UK	K2523	MIL SYSTEMS DIV
43323590	--	28-88-49	CMM	SNUBBING VALVE ASSY	01-Nov-88	--	0	Not Known	Titchfield, UK	K2523	MIL SYSTEMS DIV
43323605	--	28-87-52	CMM	GEAR BOX ASSY	01-Mar-89	--	0	Not Known	Titchfield, UK	K2523	MIL SYSTEMS DIV
43324049	--	28-87-57	CMM	GEAR BOX ASSY	01-Nov-88	--	0	Not Known	Titchfield, UK	K2523	MIL SYSTEMS DIV
43324810	--	28-89-91	CMM	FLIGHT ENGINEERS CONTROL PANEL	--	--	0	Not Known	Titchfield, UK	K2523	MIL SYSTEMS DIV
43324820	--	28-89-22	CMM	AIR REFLG OPERATORS CONTROL PANEL	01-Feb-89	--	0	Not Known	Titchfield, UK	K2523	MIL SYSTEMS DIV
43325800	--	28-88-15	CMM	MOTOR DRIVE UNIT	01-Feb-89	--	0	Not Known	Titchfield, UK	K2523	MIL SYSTEMS DIV
43325922	--	28-87-54	CMM	LINEAR ACTUATOR PARKING BRAKE ASSY	01-Feb-89	--	0	Not Known	Titchfield, UK	K2523	MIL SYSTEMS DIV
434-1-90639-000	--	MM232	MM	--	--	--	0	CONCORDE	Titchfield, UK	K2523	--
434-1-90639-001	--	77-30-77	CMM	VIBRATION INDICATOR	14-Oct-73	11-May-78	2	CONCORDE	Titchfield, UK	K2523	--
4420450	--	28-12-01	OM	FUEL TANK ASSY	01-Jan-70	--	0	Not Known	Titchfield, UK	K2523	--
4507000-13	--	28-40-87	CMM	REFUEL INDICATOR MK7	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
4620258	--	28-11-01	OM	POWER UNIT ASSY	01-Nov-69	--	0	Not Known	Titchfield, UK	K2523	--
4620273	--	28-11-02	OM	POWER UNIT GEARBOX ASSY	01-Jan-70	--	0	Not Known	Titchfield, UK	K2523	--
46H0009	--	29-10-24	CMM	SLIDING UNION TYPE 1 (SIZE 16)	06-Jan-06	11-Jun-18	3	A380	Titchfield, UK	K2523	--
46H0013	--	29-10-24	CMM	SLIDING UNION TYPE 1 (SIZE 16)	06-Jan-06	11-Jun-18	3	A380	Titchfield, UK	K2523	--
46H0013	--	FRH46111N-29-01	SB	Introduction of New LP Sliding Unions	08-Jan-15	--	0	A380	Titchfield, UK	K2523	--
46H0017	--	29-10-24	CMM	SLIDING UNION TYPE 1 (SIZE 16)	06-Jan-06	11-Jun-18	3	A380	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
46K0010	--	29-10-25	CMM	SLIDING UNION TYPE 2 (SIZE 24)	09-Jan-06	14-Apr-17	3	A380	Titchfield, UK	K2523	--
46K0014	--	29-10-25	CMM	SLIDING UNION TYPE 2 (SIZE 24)	09-Jan-06	14-Apr-17	3	A380	Titchfield, UK	K2523	--
46K0014	--	FRH46111N-29-01	SB	Introduction of New LP Sliding Unions	08-Jan-15	--	0	A380	Titchfield, UK	K2523	--
46M0011	--	29-10-26	CMM	SLIDING UNION TYPE 3 (SIZE 32)	10-Jan-06	09-Jun-14	1	A380	Titchfield, UK	K2523	--
46M0015	--	29-10-26	CMM	SLIDING UNION TYPE 3 (SIZE 32)	10-Jan-06	09-Jun-14	1	A380	Titchfield, UK	K2523	--
46M0015	--	FRH46111N-29-01	SB	Introduction of New LP Sliding Unions	08-Jan-15	--	0	A380	Titchfield, UK	K2523	--
4CZ144871	--	24-11-09	CMM	MOTOR PLESSEY TYPE C1606H/1&8	01-May-66	15-May-72	3	HUNTER, ISLANDER/TRISLANDER	Titchfield, UK	K2523	--
4CZ92025-1	--	24-09-16+	CMM	28V DC MOTOR	17-Nov-67	25-Apr-06	6	GULFSTREAM I, HS 748, YS11	Titchfield, UK	K2523	--
4CZ95868	--	24-09-18+	CMM	28V DC MOTOR TYPE C1305 A/8	30-Jan-68	04-Feb-09	5	BAe ATP, HS 748, VC10	Titchfield, UK	K2523	--
500-1-00257-002	--	30-10-02	CMM	JAGUAR RAT ACTUATOR	01-Nov-63	01-Oct-69	5	VC10	Titchfield, UK	K2523	See 113E-0126-16 in lieu
500-1-00257-301	--	30-10-02	CMM	JAGUAR RAT ACTUATOR	01-Nov-63	01-Oct-69	5	VC10	Titchfield, UK	K2523	See 113E-0126-16 in lieu
500-1-00925-002	--	24-09-102	CMM	ACTUATOR JAGUAR	01-Aug-68	15-May-05	4	DART ENGINE, F27, GULFSTREAM I, YS11	Titchfield, UK	K2523	--
500-1-01517-001	--	24-09-107	CMM	JAGUAR ACTUATORS	27-Sep-68	15-May-05	5	DART ENGINE	Titchfield, UK	K2523	--
500-1-01517-002	--	24-09-107	CMM	JAGUAR ACTUATORS	27-Sep-68	15-May-05	5	DART ENGINE	Titchfield, UK	K2523	--
500-1-01518-001	--	24-09-113	OM	ACTUATOR	19-Jan-66	09-Mar-05	6	DART ENGINE	Titchfield, UK	K2523	--
500-1-01520-001	--	24-09-113	OM	ACTUATOR	19-Jan-66	09-Mar-05	6	DART ENGINE	Titchfield, UK	K2523	--
500-1-01520-001	--	AC24-53-663	SB	Jaguar Actuator 500-1-01520-001 - Introduction of one piece cover -	28-Sep-67	--	0	F27	Titchfield, UK	K2523	--
500-1-01551	--	21-30-01+	CMM	SQUIRREL ACTUATOR	30-Sep-64	30-Oct-70	4	BAC 1-11	Titchfield, UK	K2523	--
500-1-01871	--	24-09-20+	CMM	KITE ACTUATOR	20-Jul-64	06-Mar-84	8	BAC 1-11	Titchfield, UK	K2523	--
500-1-01872	--	24-09-20+	CMM	KITE ACTUATOR	20-Jul-64	06-Mar-84	8	BAC 1-11	Titchfield, UK	K2523	--
500-1-02860-001	--	24-09-116	CMM	CUB PUMA ACTUATOR	01-Jul-66	01-Aug-75	0	HELICOPTER REFG	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
500-1-02952	--	24-09-117	CMM	ACTUATOR TYPE FOX	28-Nov-66	14-Aug-73	3	KIRAN	Titchfield, UK	K2523	--
500-1-03355-001	--	27-30-01+	CMM	JAGUAR RAT ACTUATOR	--	30-Oct-70	3	VC10	Titchfield, UK	K2523	--
500-1-03660-001	--	27-30-03	CMM	CUB JAGUAR ACTUATOR	20-Dec-80	--	0	MATADOR	Titchfield, UK	K2523	--
500-1-04118-001	--	24-09-113	OM	ACTUATOR	19-Jan-66	09-Mar-05	6	DART ENGINE	Titchfield, UK	K2523	--
500-1-04446-001	--	24-09-102	CMM	ACTUATOR JAGUAR	01-Aug-68	15-May-05	4	DART ENGINE, F27, GULFSTREAM I, YS11	Titchfield, UK	K2523	--
500-1-04446-002	--	24-09-102	CMM	ACTUATOR JAGUAR	01-Aug-68	15-May-05	4	DART ENGINE, F27, GULFSTREAM I, YS11	Titchfield, UK	K2523	--
500-1-04447-001	--	24-09-107	CMM	JAGUAR ACTUATORS	27-Sep-68	15-May-05	5	DART ENGINE	Titchfield, UK	K2523	--
500-1-04447-002	--	24-09-107	CMM	JAGUAR ACTUATORS	27-Sep-68	15-May-05	5	DART ENGINE	Titchfield, UK	K2523	--
500-1-04448-001	--	24-09-113	OM	ACTUATOR	19-Jan-66	09-Mar-05	6	DART ENGINE	Titchfield, UK	K2523	--
500-1-04560	--	MM164	MM	--	--	--	0	BAC 1-11	Titchfield, UK	K2523	--
500-1-04560-001	--	24-09-125	CMM	SQUIRREL ACTUATOR	18-Jan-68	30-Oct-70	3	BAC 1-11	Titchfield, UK	K2523	--
500-1-04790-001	--	24-09-126	CMM	Jaguar Actuator	10-Oct-68	15-Jun-70	1	DART ENGINE, YS11	Titchfield, UK	K2523	--
500-1-04900-001	--	24-09-21	CMM	JAGUAR ROTARY ACTUATOR	22-Jul-69	--	0	JETSTREAM	Titchfield, UK	K2523	BASIC MANUAL
500-1-20344	--	OSM334	CMM	DC ROTARY ACTUATOR	01-Feb-75	01-Oct-00	6	LYNX	Titchfield, UK	K2523	Inc 113E-0276-136. Dist'd by Westlands
500-1-20540	--	75-21-04	OM	3 IN MOTORISED VALVE	24-Feb-71	02-Jan-74	5	RB211, RB211-524	Titchfield, UK	K2523	--
500-1-20540-001	--	75-21-04	OM	3 IN MOTORISED VALVE	24-Feb-71	02-Jan-74	5	RB211, RB211-524	Titchfield, UK	K2523	--
500-1-20790-001	--	75-20-02+	CMM	SHREW ACTUATOR	12-Oct-73	01-Apr-82	3	CONCORDE	Titchfield, UK	K2523	--
500-1-21166-000	--	OSM334	CMM	DC ROTARY ACTUATOR	01-Feb-75	01-Oct-00	6	LYNX	Titchfield, UK	K2523	Inc 113E-0276-136. Dist'd by Westlands
500-1-21375-002	--	27-30-05	CMM	FOX ACTUATOR	10-Mar-84	07-Jan-09	2	JAGUAR	Titchfield, UK	K2523	--
500-1-21450-000	--	24-09-20+	CMM	KITE ACTUATOR	20-Jul-64	06-Mar-84	8	BAC 1-11	Titchfield, UK	K2523	--
500-1-21533-001	--	24-09-26+	CMM	ACTUATOR, CUB JAGUAR	10-Sep-91	--	0	BAe ATP	Titchfield, UK	K2523	BASIC MANUAL

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
500-1-21600	--	21600-52-01	SB	ACTUATOR MIS-DEPLOYMENT	--	--	0	GLOBAL EXPRESS	Titchfield, UK	K2523	TO BE WRITTEN
500-1-21600-001	--	21600-52-01	SB	ACTUATOR MIS-DEPLOYMENT	--	--	0	GLOBAL EXPRESS	Titchfield, UK	K2523	TO BE WRITTEN
500-1-21600-001	--	52-60-41	CMM	Door Step Actuator	15-Jul-10	18-Nov-13	1	GLOBAL EXPRESS	Titchfield, UK	K2523	--
500-1-21600-003	--	52-60-41	CMM	Door Step Actuator	15-Jul-10	18-Nov-13	1	GLOBAL EXPRESS	Titchfield, UK	K2523	--
501-1-05000	--	24-09-17++	CMM	AC MOTOR	01-Sep-62	01-Feb-68	0	VC10	Titchfield, UK	K2523	--
501-1-05490	--	24-09-14	CMM	28V DC MOTOR TYPE C1305B-10	07-Jun-67	--	0	VC10	Titchfield, UK	K2523	BASIC MANUAL
501-1-05550	--	24-09-10++	CMM	DC MOTOR	01-Aug-65	30-Nov-70	4	BAC 1-11, VC10	Titchfield, UK	K2523	--
501-1-05822	--	24-09-13++	CMM	AC INDUCTION MOTOR	07-Aug-67	08-May-68	2	VC10	Titchfield, UK	K2523	--
501-1-05913	--	24-09-04+	CMM	DC MOTOR	30-Oct-64	30-Nov-70	2	BAC 1-11	Titchfield, UK	K2523	--
501-1-06110	--	24-09-06+	CMM	DC MOTORS	01-Dec-65	01-Aug-77	3	HS 748	Titchfield, UK	K2523	--
501-1-06420	--	24-09-09+	CMM	DC MOTOR	01-Jun-67	01-May-80	2	VC10	Titchfield, UK	K2523	--
501-1-06590	--	24-09-10++	CMM	DC MOTOR	01-Aug-65	30-Nov-70	4	BAC 1-11, VC10	Titchfield, UK	K2523	--
501-1-06640	--	24-09-06+	CMM	DC MOTORS	01-Dec-65	01-Aug-77	3	HS 748	Titchfield, UK	K2523	--
501-1-06800	--	24-09-12++	CMM	28V DC MOTOR TYPE C2016 B/2	01-Jun-67	20-Oct-14	2	KIRAN	Titchfield, UK	K2523	--
501-1-07130	--	24-09-10++	CMM	DC MOTOR	01-Aug-65	30-Nov-70	4	BAC 1-11, VC10	Titchfield, UK	K2523	--
501-1-07710	--	24-09-901	CMM	SUPPRESSOR UNIT	25-May-68	18-Nov-69	1	JETSTREAM	Titchfield, UK	K2523	--
501-1-07720	--	24-09-13++	CMM	AC INDUCTION MOTOR	07-Aug-67	08-May-68	2	VC10	Titchfield, UK	K2523	--
501-1-07770	--	24-09-03	CMM	MOTOR	--	30-Mar-84	7	BAC 1-11	Titchfield, UK	K2523	--
501-1-07780	--	24-09-19+	OM	DC MOTOR TYPE C1610E-4	01-Mar-68	28-Oct-68	1	JETSTREAM	Titchfield, UK	K2523	--
501-1-07906	--	24-09-05+	CMM	28V DC MOTORS	31-Oct-67	30-Nov-70	3	BAC 1-11	Titchfield, UK	K2523	--
501-1-08010	--	MM209	MM	--	--	--	0	TRISTAR L1011	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
501-1-08400	--	24-09-03	CMM	MOTOR	--	30-Mar-84	7	BAC 1-11	Titchfield, UK	K2523	--
501-1-08436	--	49-41-04	CMM	APU ENGINE STARTER	01-Mar-71	01-Feb-73	1	TRISTAR L1011	Titchfield, UK	K2523	--
501-1-08440	--	OSM393	CMM	DC MOTOR	28-Feb-75	16-Oct-00	3	LYNX	Titchfield, UK	K2523	Inc into 113E-03194-136 Dist'd by Westlands
501-1-08554	--	49-41-06	CMM	APU ENGINE STARTER	01-Jul-72	01-Dec-74	1	TRISTAR L1011	Titchfield, UK	K2523	--
501-1-08560-001	--	27-20-01	CMM	RUDDER PEDAL SHAKER MOTOR	01-Sep-75	--	0	HARRIER	Titchfield, UK	K2523	--
501-1-08560-002	--	27-20-01	CMM	RUDDER PEDAL SHAKER MOTOR	01-Sep-75	--	0	HARRIER	Titchfield, UK	K2523	--
501-1-08582	--	24-09-03	CMM	MOTOR	--	30-Mar-84	7	BAC 1-11	Titchfield, UK	K2523	--
501-1-13641-000	--	24-09-03	CMM	MOTOR	--	30-Mar-84	7	BAC 1-11	Titchfield, UK	K2523	--
501-1-13775-001	--	80-10-01++	CMM	STARTER MOTOR	01-Apr-81	01-Feb-89	1	BAE 146	Titchfield, UK	K2523	*OUT OF PRINT
501-1-13775-001	--	HS80-01-1228	SB	Introduction of Formsprag Clutch	25-Jul-83	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-001	--	HS80-02-1227	SB	Introduction of Drive Shaft Shear Neck with reduced torque figure	20-Jun-85	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-001	--	HS80-04-1233	SB	Introduction of Starter Motor Type C6120A/4 incorporating re-designed Drive End Housing Assembly	10-Sep-85	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-001	--	HS80-05-1288	SB	Introduction of improved design Oil Filter Bolt	04-Jun-85	28-Nov-86	1	BAE 146	Titchfield, UK	K2523	--
501-1-13775-001	--	HS80-06	SB	Installed life	13-Jun-85	30-Jul-90	1	BAE 146	Titchfield, UK	K2523	--
501-1-13775-001	--	HS80-07	SB	Prevention of fluid ingress into Commutator End Housing Assembly	28-Jun-85	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-001	--	HS80-08-1273	SB	Introduction of improved sealing arrangement at Brush Cover Assembly	01-Dec-86	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-001	--	HS80-09-1275	SB	Introduction of Armature Shaft with Electroless Nickel Plating on splines and support journal	03-Dec-86	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-001	--	HS80-14-1331	SB	Introduction of Baulking feature to separated Drive Shaft	01-Aug-88	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-001	--	HS80-15-1324	SB	Introduction of new type of Bearing with Granodised steel Bearing Cage	04-Jan-88	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-001	--	HS80-18-1346	SB	Introduction of Emralon Dry Lubricant to Wound Armature Splines	03-May-87	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-001	--	HS80-20-1354	SB	Introduction of Armature Shaft with extended Spline Support diameter	30-Jul-90	--	0	BAE 146	Titchfield, UK	K2523	--

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
501-1-13775-001	--	HS80-21-1358	SB	Re-introduction of Bearings with Phenolic Bearing Cages	01-Feb-90	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	80-10-02+	CMM	STARTER MOTOR Type C6120A4, C6120A6, C6120A6A	01-Sep-85	03-Jun-11	8	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-02-1227	SB	Introduction of Drive Shaft Shear Neck with reduced torque figure	20-Jun-85	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-03-1226	SB	Change to introduce separated Drive Shaft	25-Apr-86	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-05-1288	SB	Introduction of improved design Oil Filter Bolt	04-Jun-85	28-Nov-86	1	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-06	SB	Installed life	13-Jun-85	30-Jul-90	1	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-07	SB	Prevention of fluid ingress into Commutator End Housing Assembly	28-Jun-85	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-08-1273	SB	Introduction of improved sealing arrangement at Brush Cover Assembly	01-Dec-86	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-09-1275	SB	Introduction of Armature Shaft with Electroless Nickel Plating on splines and support journal	03-Dec-86	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-11-1295	SB	Introduction of revised Windback Seal arrangement	25-Apr-86	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-12-1310	SB	Introduction of additional pre loading to Freewheel Housing Assembly Support Bearing	03-Dec-86	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-13-1321	SB	Introduction of Starter Motor Type C6120A/6	09-Sep-87	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-14-1331	SB	Introduction of Baulking feature to separated Drive Shaft	01-Aug-88	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-15-1324	SB	Introduction of new type of Bearing with Granodised steel Bearing Cage	04-Jan-88	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-16-1332	SB	Introduction of Freewheel Housing Assembly incorporating Sealing Plate with greater adhesion surface	01-Aug-88	--	3	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-17-1335	SB	Introduction of shorter retaining Bolts on Drive End Housing	01-Aug-88	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-18-1346	SB	Introduction of Emralon Dry Lubricant to Wound Armature Splines	03-May-87	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-20-1354	SB	Introduction of Armature Shaft with extended Spline Support diameter	30-Jul-90	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-21-1358	SB	Re-introduction of Bearings with Phenolic Bearing Cages	01-Feb-90	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-27-1495	SB	INTRO. NEW MAG SEAL	20-May-02	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-004	--	HS80-28-1543	SB	Introduce New Brush and Tag Assembly	03-Jan-06	03-Jan-06	0	BAE 146	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
501-1-13775-006	--	80-10-02+	CMM	STARTER MOTOR Type C6120A4, C6120A6, C6120A6A	01-Sep-85	03-Jun-11	8	BAE 146	Titchfield, UK	K2523	--
501-1-13775-006	--	HS80-06	SB	Installed life	13-Jun-85	30-Jul-90	1	BAE 146	Titchfield, UK	K2523	--
501-1-13775-006	--	HS80-14-1331	SB	Introduction of Baulking feature to separated Drive Shaft	01-Aug-88	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-006	--	HS80-15-1324	SB	Introduction of new type of Bearing with Granodised steel Bearing Cage	04-Jan-88	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-006	--	HS80-16-1332	SB	Introduction of Freewheel Housing Assembly incorporating Sealing Plate with greater adhesion surface	01-Aug-88	--	3	BAE 146	Titchfield, UK	K2523	--
501-1-13775-006	--	HS80-17-1335	SB	Introduction of shorter retaining Bolts on Drive End Housing	01-Aug-88	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-006	--	HS80-18-1346	SB	Introduction of Emralon Dry Lubricant to Wound Armature Splines	03-May-87	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-006	--	HS80-20-1354	SB	Introduction of Armature Shaft with extended Spline Support diameter	30-Jul-90	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-006	--	HS80-21-1358	SB	Re-introduction of Bearings with Phenolic Bearing Cages	01-Feb-90	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-006	--	HS80-22-1460	SB	Change of Bearing Cap Restraining Screws	04-Jun-98	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-006	--	HS80-23-1457	SB	Introduction of -06A ceramic bearings	15-Jan-97	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-006	--	HS80-24-1474	SB	Introduction of 4-pole magnetic seal	07-Feb-00	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-006	--	HS80-25-1481	SB	Modification of Starter Motor to Mk 8, Starter Motor - Starting - Electric	04-Oct-99	04-Mar-05	1	BAE 146	Titchfield, UK	K2523	Distributed as CD-0007 / OSM853
501-1-13775-006	--	HS80-26-1479	SB	Starter Motor - Change of bearing	07-Feb-00	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-006	--	HS80-27-1495	SB	INTRO. NEW MAG SEAL	20-May-02	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-006	--	HS80-28-1543	SB	Introduce New Brush and Tag Assembly	03-Jan-06	03-Jan-06	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-008	--	80-10-04	CMM	STARTER MOTOR TYPE C6120A8	26-Oct-99	03-Apr-12	5	BAE 146	Titchfield, UK	K2523	--
501-1-13775-008	--	HS80-27-1495	SB	INTRO. NEW MAG SEAL	20-May-02	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-008	--	HS80-28-1543	SB	Introduce New Brush and Tag Assembly	03-Jan-06	03-Jan-06	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-008	--	SIL-2008-06	SIL	STARTING - STARTER MOTOR - RE-LIFE	21-Apr-08	26-Feb-10	1	BAE 146	Titchfield, UK	K2523	--
501-1-13775-06A	--	80-10-02+	CMM	STARTER MOTOR Type C6120A4, C6120A6, C6120A6A	01-Sep-85	03-Jun-11	8	BAE 146	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
501-1-13775-06A	--	HS80-22-1460	SB	Change of Bearing Cap Restraining Screws	04-Jun-98	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-06A	--	HS80-24-1474	SB	Introduction of 4-pole magnetic seal	07-Feb-00	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-06A	--	HS80-25-1481	SB	Modification of Starter Motor to Mk 8, Starter Motor - Starting - Electric	04-Oct-99	04-Mar-05	1	BAE 146	Titchfield, UK	K2523	Distributed as CD-0007 / OSM853
501-1-13775-06A	--	HS80-26-1479	SB	Starter Motor - Change of bearing	07-Feb-00	--	0	BAE 146	Titchfield, UK	K2523	--
501-1-13775-06A	--	HS80-28-1543	SB	Introduce New Brush and Tag Assembly	03-Jan-06	03-Jan-06	0	BAE 146	Titchfield, UK	K2523	--
501-1-14072-000	--	24-09-03	CMM	MOTOR	--	30-Mar-84	7	BAC 1-11	Titchfield, UK	K2523	--
501-1-14561-002	--	SB4950136-49-1	SB	Intro APS Starter Motor MK 4	04-Sep-03	--	0	SUNDSTRAND APS3200	Titchfield, UK	K2523	Issued Internally 04/12/2004
501-1-14561-003	--	SB4950136-49-1	SB	Intro APS Starter Motor MK 4	04-Sep-03	--	0	SUNDSTRAND APS3200	Titchfield, UK	K2523	Issued Internally 04/12/2004
5020040	--	28-12-02	OM	FUEL DELIVERY SYSTEM	01-Jan-70	--	0	Not Known	Titchfield, UK	K2523	--
5020040	--	28-12-02	OM	FUEL DELIVERY SYSTEM	01-Jan-70	--	0	Not Known	Titchfield, UK	K2523	--
5020200	--	28-12-02	OM	FUEL DELIVERY SYSTEM	01-Jan-70	--	0	Not Known	Titchfield, UK	K2523	--
5020200	--	28-12-02	OM	FUEL DELIVERY SYSTEM	01-Jan-70	--	0	Not Known	Titchfield, UK	K2523	--
5020360	--	28-12-02	OM	FUEL DELIVERY SYSTEM	01-Jan-70	--	0	Not Known	Titchfield, UK	K2523	--
5020371	--	28-12-05	OM	MK 4C FLOAT SWITCH	01-May-70	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
502BA80	--	29-2-1	OM	TAPER PLUG VALVE (T-PORT)	01-Jun-59	30-Nov-60	2	COMET 4	Titchfield, UK	K2523	--
502CB80	--	38-2-1+	OM	TAPER PLUG VALVE	01-Jun-59	01-Feb-64	3	Not Known	Titchfield, UK	K2523	SEE 38-2-1 FOR 603AA/AB07
502DB90	--	29-2-1	OM	TAPER PLUG VALVE (T-PORT)	01-Jun-59	30-Nov-60	2	COMET 4	Titchfield, UK	K2523	--
502DB91	--	29-20-1	OM	1/4 IN DIA TP AERO VALVE	01-May-61	27-Jul-05	1	Not Known	Titchfield, UK	K2523	--
503-1-02090	--	24-30-01	CMM	STARTER - GENERATOR	29-Mar-74	28-Aug-08	1	JETSTREAM	Titchfield, UK	K2523	*OUT OF PRINT
503-1-02100	--	24-20-15	CMM	ALTERNATORS	30-Apr-74	22-Dec-14	1	JETSTREAM	Titchfield, UK	K2523	--
503-1-02550-002	--	OSM258	CMM	STARTER GENERATOR	04-Sep-69	--	0	JETSTREAM	Titchfield, UK	K2523	BASIC MANUAL

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
503-1-02700	--	24-20-15	CMM	ALTERNATORS	30-Apr-74	22-Dec-14	1	JETSTREAM	Titchfield, UK	K2523	--
503-1-04000-003	--	24-19-02	CMM	CURRENT TRANSFORMER PACKAGE	05-Oct-62	--	0	BAC 1-11	Titchfield, UK	K2523	--
503-1-04064-003	--	24-19-17	CMM	VOLTAGE REGULATOR	30-Sep-63	18-Dec-67	1	BAC 1-11, VC10	Titchfield, UK	K2523	--
503-1-04179-003	--	24-19-01	CMM	GENERATOR	01-Aug-62	01-Jun-78	1	VC10	Titchfield, UK	K2523	--
503-1-04827-006	--	24-20-09	CMM	GENERATOR	21-Aug-64	06-Jun-78	9	BAC 1-11	Titchfield, UK	K2523	--
503-1-04827-009	--	24-20-09	CMM	GENERATOR	21-Aug-64	06-Jun-78	9	BAC 1-11	Titchfield, UK	K2523	--
503-1-04903-003	--	24-21-04	CMM	CONTROL PANEL	03-Sep-64	01-Apr-82	8	BAC 1-11	Titchfield, UK	K2523	--
503-1-05288-001	--	24-21-05	CMM	RACK ELECTRICAL	30-May-69	30-May-69	1	BAC 1-11	Titchfield, UK	K2523	--
503-1-05820-001	--	OSM273	CMM	GENERATOR	01-Jan-74	--	0	Not Known	Titchfield, UK	K2523	--
503-1-06390-000	--	49-75-02	CMM	SPEED SENSING TACHOGENERATOR	01-Mar-73	01-Aug-75	1	TRISTAR L1011	Titchfield, UK	K2523	--
503-1-06680	--	24-20-18	CMM	GENERATOR 45/50 KVA AC	03-Oct-80	11-May-17	14	BAE 146	Titchfield, UK	K2523	--
503-1-06680	--	HGE24-3-1237	SB	INTRO OF NEW DRIVE	23-Jan-85	--	0	BAE 146	Titchfield, UK	K2523	--
503-1-06680-001	--	Ge24-34	SB	Generation - Failure of rectifier terminal in generator assembly	19-Sep-83	01-May-85	1	BAE 146	Titchfield, UK	K2523	--
503-1-06680-001	--	HGE24-03-1237	SB	Introduction of increased strength drive between splined stub shaft and main shaft of armature rotor	23-Jan-85	--	0	BAE 146	Titchfield, UK	K2523	--
503-1-06680-002	--	24-4-1314	SB	INTRO OF IMPROVED GENERATOR	24-Feb-87	09-Sep-87	1	BAE 146	Titchfield, UK	K2523	--
503-1-06680-002	--	Ge24-34	SB	Generation - Failure of rectifier terminal in generator assembly	19-Sep-83	01-May-85	1	BAE 146	Titchfield, UK	K2523	--
503-1-06680-002	--	HGE24-04-1314	SB	Introduction of improved generator with rotor windings retaining wedges of "Ninocast 80" material	24-Feb-87	09-Sep-87	1	BAE 146	Titchfield, UK	K2523	--
503-1-06680-003	--	24-20-18	CMM	GENERATOR 45/50 KVA AC	03-Oct-80	11-May-17	14	BAE 146	Titchfield, UK	K2523	--
503-1-06680-003	--	HGE24-12-1351	SB	Introduction of armature rotor assembly incorporating alternative diodes on exciter armature	19-Sep-90	--	0	BAE 146	Titchfield, UK	K2523	--
503-1-06680-003	--	HGE24-14-1371	SB	Introduction of flexible connector	26-Oct-94	--	0	BAE 146	Titchfield, UK	K2523	--
503-1-06680-003	--	HGE24-15-1376	SB	Introduction of new permanent magnet generator stator with improved side plates	23-Jan-91	--	0	BAE 146	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
503-1-06680-003	--	HGE24-32-0001	SB	INSPECTION OF ROTOR BANDING RINGS	11-Oct-10	--	0	BAE 146	Titchfield, UK	K2523	--
503-1-06680-003	--	HGE24-32-1489	SB	40/50 kVA Gen - Introduction of higher reliability diodes	23-Jul-01	--	0	BAE 146	Titchfield, UK	K2523	--
503-1-06680-003	--	SIL-CS-1-05	SIL	GENERATOR MAIN ROTOR STACK - SUSPECT WINDINGS	09-Feb-05	--	0	BAE 146	Titchfield, UK	K2523	--
503-1-06710-000	--	24-20-21	CMM	DRIVE GENERATOR	--	07-Apr-11	6	BAE 146	Titchfield, UK	K2523	--
503-1-06955-000	--	24-20-22	CMM	GENERATOR ADAPTOR	--	07-Apr-11	4	BAE 146	Titchfield, UK	K2523	--
503-1-07075-004	--	MM283	MM	--	--	--	0	BAE 146	Titchfield, UK	K2523	--
503-1-07930-002	--	PSD-200	CMM	12kW Generator	06-Aug-12	28-Nov-12	1	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	TCH (pub NOT PN)=HAL, BAE for info only
503AB80	--	28-21-76	OM	3/8 IN BSP MW VALVE	01-Nov-70	--	0	BULLDOG	Titchfield, UK	K2523	--
503CA90	--	28-20-38+	OM	TAPER PLUG FUEL VALVE	01-Jan-67	29-Jun-07	4	ISLANDER/TRISLANDER	Titchfield, UK	K2523	*EX-SAUNDERS
504-1-00739-001	--	27-50-01	CMM	SERVO UNIT SU15	01-Jan-69	01-Jun-78	1	VC10	Titchfield, UK	K2523	--
504-1-00739-002	--	27-50-01	CMM	SERVO UNIT SU15	01-Jan-69	01-Jun-78	1	VC10	Titchfield, UK	K2523	--
504-1-02071-001	--	27-50-01	CMM	SERVO UNIT SU15	01-Jan-69	01-Jun-78	1	VC10	Titchfield, UK	K2523	--
504-1-02071-002	--	27-50-01	CMM	SERVO UNIT SU15	01-Jan-69	01-Jun-78	1	VC10	Titchfield, UK	K2523	--
504-1-02343-001	--	27-50-01	CMM	SERVO UNIT SU15	01-Jan-69	01-Jun-78	1	VC10	Titchfield, UK	K2523	--
504-1-02343-002	--	27-50-01	CMM	SERVO UNIT SU15	01-Jan-69	01-Jun-78	1	VC10	Titchfield, UK	K2523	--
504-1-02344-001	--	27-50-01	CMM	SERVO UNIT SU15	01-Jan-69	01-Jun-78	1	VC10	Titchfield, UK	K2523	--
504-1-02344-002	--	27-50-01	CMM	SERVO UNIT SU15	01-Jan-69	01-Jun-78	1	VC10	Titchfield, UK	K2523	--
504AA81	--	28-20-46	OM	TP AERO VALVE	01-Nov-63	01-Oct-67	2	SHORTS SC7 SKYVAN	Titchfield, UK	K2523	--
506-1-00115	--	30-40-03	CMM	CONTROLLER	01-Jul-64	10-Apr-86	4	BAC 1-11, HS 125, VC10	Titchfield, UK	K2523	--
506-1-00169	--	30-40-41	CMM	CONTROLLER TYPE 18	01-Jun-61	01-Nov-67	0	HERALD	Titchfield, UK	K2523	--
506-1-00488	--	30-40-03	CMM	CONTROLLER	01-Jul-64	10-Apr-86	4	BAC 1-11, HS 125, VC10	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
506-1-00790	--	24-09-801	CMM	MAGNETIC INDICATOR, DRUM TYPE	17-Dec-68	--	0	VC10	Titchfield, UK	K2523	--
506-1-00830	--	30-40-03	CMM	CONTROLLER	01-Jul-64	10-Apr-86	4	BAC 1-11, HS 125, VC10	Titchfield, UK	K2523	--
506-1-00837-002	--	30-40-04	CMM	CONTROLLER TYPE 27	01-Sep-64	01-Mar-93	3	BAC 1-11	Titchfield, UK	K2523	--
506-1-04006-000	--	30-41-20	CMM	WINDSCREEN HEATING INVERTER CONTROL	--	--	0	JS41	Titchfield, UK	K2523	--
506-1-04040-002	--	75-24-11	CMM	SOLENOID VALVE ASSEMBLY TYPE SOV110 MK2	30-Mar-94	03-Nov-08	1	TRENT	Titchfield, UK	K2523	BASIC MANUAL
506-1-07200-053	--	MM198	MM	--	--	--	0	JETSTREAM	Titchfield, UK	K2523	--
506-1-07281-105	--	MM262-1	MM	--	--	--	0	Not Known	Titchfield, UK	K2523	--
506-1-07380	--	30-40-08	CMM	WINDSCREEN CONTROLLER	--	27-Jul-82	2	JETSTREAM	Titchfield, UK	K2523	--
506-1-07410	--	24-09-44+	CMM	MINIATURE MAGNETIC INDICATOR	03-May-71	--	0	BAC 1-11	Titchfield, UK	K2523	--
506-1-07571-001	--	MM183	MM	--	--	--	0	NIMROD	Titchfield, UK	K2523	--
506-1-07717-040	--	MM176	MM	--	--	--	0	JETSTREAM	Titchfield, UK	K2523	--
506-1-07717-046	--	MM176	MM	--	--	--	0	JETSTREAM	Titchfield, UK	K2523	--
506-1-07920	--	30-40-07	CMM	CONTROLLER TYPE 36	30-Mar-73	31-May-78	4	CONCORDE	Titchfield, UK	K2523	--
506-1-08036-001	--	MM223	MM	--	--	--	0	LYNX	Titchfield, UK	K2523	--
506-1-08036-002	--	MM223	MM	--	--	--	0	LYNX	Titchfield, UK	K2523	--
506-1-08063-100	--	30-40-07	CMM	CONTROLLER TYPE 36	30-Mar-73	31-May-78	4	CONCORDE	Titchfield, UK	K2523	--
506-1-08484-000	--	24-50-01	CMM	3-PHASE CONTACTOR	01-Feb-73	--	0	CONCORDE	Titchfield, UK	K2523	--
507-1-00034	--	24-09-201	CMM	RELAYS	--	19-Aug-65	1	BAC 1-11, VC10	Titchfield, UK	K2523	--
507-1-00035	--	24-09-207	CMM	RELAYS	19-Oct-65	--	0	BAC 1-11	Titchfield, UK	K2523	--
507-1-00140-002	--	24-09-22	CMM	P-TYPE SEALED RELAYS	21-Oct-68	17-Apr-74	2	BAC 1-11	Titchfield, UK	K2523	--
507-1-00330-002	--	24-09-22	CMM	P-TYPE SEALED RELAYS	21-Oct-68	17-Apr-74	2	BAC 1-11	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
507-1-00517-002	--	24-09-22	CMM	P-TYPE SEALED RELAYS	21-Oct-68	17-Apr-74	2	BAC 1-11	Titchfield, UK	K2523	--
507-1-00920-000	--	24-09-22	CMM	P-TYPE SEALED RELAYS	21-Oct-68	17-Apr-74	2	BAC 1-11	Titchfield, UK	K2523	--
507-1-01221	--	24-09-211	CMM	not known	29-Nov-68	--	0	--	Titchfield, UK	K2523	*OUT OF PRINT
508AA01	--	SL57A	OM	TAPER PLUG MWV	01-Sep-66	--	0	Not Known	Titchfield, UK	K2523	--
508AA02	--	SL57A	OM	TAPER PLUG MWV	01-Sep-66	--	0	Not Known	Titchfield, UK	K2523	--
508AC80	--	28-22-24+	OM	MW TAPER PLUG VALVE	01-Aug-72	--	0	Not Known	Titchfield, UK	K2523	SEE 28-22-24 FOR 712BA16*
508AD80	--	28-22-24+	OM	MW TAPER PLUG VALVE	01-Aug-72	--	0	Not Known	Titchfield, UK	K2523	SEE 28-22-24 FOR 712BA16*
508AE80-1	--	38-30-2	OM	TAPER PLUG VALVE	01-Mar-60	01-Apr-68	1	Not Known	Titchfield, UK	K2523	--
509-1-01060	--	24-09-502	OM	STATIC INVERTERS, TYPE 20VA & 40VA	14-Oct-64	01-Nov-83	3	A300, BAC 1-11, BAE 125, JETSTREAM, VC10	Titchfield, UK	K2523	--
509-1-01230	--	24-09-502	OM	STATIC INVERTERS, TYPE 20VA & 40VA	14-Oct-64	01-Nov-83	3	A300, BAC 1-11, BAE 125, JETSTREAM, VC10	Titchfield, UK	K2523	--
509-1-01780	--	MM155	MM	--	--	--	0	JETSTREAM	Titchfield, UK	K2523	--
509-1-02341-000	--	24-20-12	CMM	STATIC INVERTER	01-Feb-74	01-Aug-75	1	Not Known	Titchfield, UK	K2523	--
509-1-02360	--	77-30-08	CMM	POWER SUPPLY UNIT	15-Jan-73	--	0	CONCORDE	Titchfield, UK	K2523	--
509-1-02480-000	--	24-20-23	CMM	INVERTER SUPPRESSOR	01-Oct-88	--	0	T45	Titchfield, UK	K2523	--
509-1-02480-000	--	SM146	CMM	RFI FILTER	21-May-89	28-Feb-97	1	HAWK	Titchfield, UK	K2523	--
509-1-02480-000	--	TD-3D-0447	CMM	RFI FILTER	21-May-89	28-Feb-97	1	HAWK	Titchfield, UK	K2523	BASIC MANUAL
509-1-02530-000	--	24-30-04	CMM	TRU	--	13-Nov-14	12	BAE 146	Titchfield, UK	K2523	--
509-1-02530-000	--	HGE24-02-1219	SB	Changes in protection circuits to prevent spurious tripping	26-Oct-84	--	0	BAE 146	Titchfield, UK	K2523	--
509-1-02530-001	--	24-30-04	CMM	TRU	--	13-Nov-14	12	BAE 146	Titchfield, UK	K2523	--
509-1-02530-001	--	HGE24-05-1269	SB	Introduction of new front panel with revised cable layout to obviate use of butt splices	03-Aug-87	--	0	BAE 146	Titchfield, UK	K2523	--
509-1-02530-001	--	HGE24-06-1293	SB	Introduction of new front panel assembly incorporating relay board with increased length mounting sp	03-Aug-87	--	0	BAE 146	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
509-1-02530-001	--	HGE24-13-1369(OM)	SB	Minor design changes	15-Jan-91	--	0	BAE 146	Titchfield, UK	K2523	--
509-1-02530-001	--	HGE24-22-1421	SB	TRU - Replacement of neutral cable	10-Oct-94	--	0	BAE 146	Titchfield, UK	K2523	--
509-1-02530-001	--	HGE24-27-1413(OM)	SB	TRU - Alternative items (Rev 1)	10-Dec-96	--	0	BAE 146	Titchfield, UK	K2523	--
509-1-02530-001	--	HGE24-31-1488	SB	TRU - Rerouting of cable harness	25-Jun-01	--	0	BAE 146	Titchfield, UK	K2523	--
509-1-02950-010	--	PSD-203	CMM	Inverter	06-Aug-12	28-Nov-12	1	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	TCH (pub NOT PN)=HAL, BAE for info only
516-1-80000	--	24-09-401	OM	TRIP FREE CIRCUIT BREAKERS	09-Oct-63	23-Jul-73	3	BAC 1-11, HS 748	Titchfield, UK	K2523	--
5201015	--	28-30-1	OM	JETTISON VALVE MK1	01-Sep-65	--	0	BAC 1-11, VC10	Titchfield, UK	K2523	--
5201045	--	28-30-5	CMM	MK1 JETTISON VALVE	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
5202000	--	28-D2-1	OM	JETTISON VALVE MK2	01-Mar-62	--	0	Not Known	Titchfield, UK	K2523	--
5202050	--	28-D2-2	CMM	MK2 JETTISON VALVE	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
5202065	--	28-12-03	OM	JETTISON VALVE	01-Feb-70	--	0	Not Known	Titchfield, UK	K2523	--
5202090	--	28-D2-3	OM	JETTISON VALVE MK2	01-Dec-63	--	0	BAC 1-11	Titchfield, UK	K2523	--
5202110	--	28-30-4	OM	JETTISON VALVE MK2	01-Dec-65	22-Oct-04	1	BAC 1-11	Titchfield, UK	K2523	--
5202130	--	28-30-6	CMM	JETTISON VALVE	--	--	0	G222	Titchfield, UK	K2523	OUT OF PRINT
5202145	--	28-30-13	CMM	MK 2 JETTISON VALVE	27-Apr-99	14-May-04	1	AV8A	Titchfield, UK	K2523	--
53-0001	--	28-09-98	CMM	ACTUATOR VALVE	05-Feb-10	24-Jan-20	6	BOEING 787	Titchfield, UK	K2523	Changed from 24-09-70 on 4-Feb-10
53-0002	--	28-24-24	CMM	ADAPTER-ACTUATOR	05-Dec-07	24-Feb-14	2	Boeing 777X, BOEING 787, Boeing 787-9	Titchfield, UK	K2523	CDCCL designation removed Feb 2014
53-0003	--	47-21-08	CMM	CLAMP-V BAND	--	--	0	--	Titchfield, UK	K2523	(HS LOGO) TO BE WRITTEN
53-0005	--	28-24-24	CMM	ADAPTER-ACTUATOR	05-Dec-07	24-Feb-14	2	Boeing 777X, BOEING 787, Boeing 787-9	Titchfield, UK	K2523	CDCCL designation removed Feb 2014
53-0006	--	47-21-09	CMM	ACTUATOR-VALVE	01-May-08	22-May-14	3	BOEING 787	Titchfield, UK	K2523	--
53-0013	--	24-09-67	CMM	Actuator	31-Oct-07	18-Apr-16	3	F100	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
53-0013	--	53-0013-24-01	SB	Fuel, X-Feed Valve, Actuator, Loose Top-cap Screws	19-Feb-09	--	0	F100	Titchfield, UK	K2523	--
53-0013	--	53-0013-24-02	SB	Fuel, X-Feed Valve, New Actuator	10-Mar-09	--	0	F100	Titchfield, UK	K2523	--
53-0014	--	24-09-65	CMM	TWIN MOTOR ACTUATOR	28-Feb-01	16-Jul-18	7	A310-MRRT, A320, A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
53-0014	--	K2523-24-001	SIL	Obsolete Actuator	03-Oct-16	--	0	A330, A340	Titchfield, UK	K2523	--
53-0014	--	SIL-2009-07	SIL	INTRODUCTION OF IMPROVED TWIN MOTOR ACTUATOR	11-Nov-09	--	0	A319, A330, A340	Titchfield, UK	K2523	--
53-0016	--	28-09-98	CMM	ACTUATOR VALVE	05-Feb-10	24-Jan-20	6	BOEING 787	Titchfield, UK	K2523	Changed from 24-09-70 on 4-Feb-10
53-0016	--	53-0037-28-01	SB	Introduce New MOV Actuator	07-May-14	30-Mar-17	1	BOEING 787	Titchfield, UK	K2523	--
53-0017	--	47-21-09	CMM	ACTUATOR-VALVE	01-May-08	22-May-14	3	BOEING 787	Titchfield, UK	K2523	--
53-0027	--	24-09-67	CMM	Actuator	31-Oct-07	18-Apr-16	3	F100	Titchfield, UK	K2523	--
53-0027	--	53-0013-24-01	SB	Fuel, X-Feed Valve, Actuator, Loose Top-cap Screws	19-Feb-09	--	0	F100	Titchfield, UK	K2523	--
53-0027	--	53-0013-24-02	SB	Fuel, X-Feed Valve, New Actuator	10-Mar-09	--	0	F100	Titchfield, UK	K2523	--
53-0037	--	28-09-98	CMM	ACTUATOR VALVE	05-Feb-10	24-Jan-20	6	BOEING 787	Titchfield, UK	K2523	Changed from 24-09-70 on 4-Feb-10
53-0037	--	53-0037-28-01	SB	Introduce New MOV Actuator	07-May-14	30-Mar-17	1	BOEING 787	Titchfield, UK	K2523	--
53-0037	--	53-0037-28-02	SB	Modification of PCB Capacitors	10-Nov-15	26-Feb-16	1	BOEING 787	Titchfield, UK	K2523	--
53-0038	--	47-21-09	CMM	ACTUATOR-VALVE	01-May-08	22-May-14	3	BOEING 787	Titchfield, UK	K2523	--
53-0041	--	28-24-24	CMM	ADAPTER-ACTUATOR	05-Dec-07	24-Feb-14	2	Boeing 777X, BOEING 787, Boeing 787-9	Titchfield, UK	K2523	CDCCL designation removed Feb 2014
53-0043	--	47-01-03	CMM	Actuator	--	--	0	LEARJET 85	Titchfield, UK	K2523	TO BE WRITTEN
53-0049	--	28-09-98	CMM	ACTUATOR VALVE	05-Feb-10	24-Jan-20	6	BOEING 787	Titchfield, UK	K2523	Changed from 24-09-70 on 4-Feb-10
53-0049	--	53-0037-28-01	SB	Introduce New MOV Actuator	07-May-14	30-Mar-17	1	BOEING 787	Titchfield, UK	K2523	--
53-0049	--	53-0037-28-02	SB	Modification of PCB Capacitors	10-Nov-15	26-Feb-16	1	BOEING 787	Titchfield, UK	K2523	--
53-0053	--	28-20-06_K2523_1	CMM	Actuator 4 Position Selector Assembly Component Maintenance Manual	--	--	0	CH-53K	Titchfield, UK	K2523	TO BE WRITTEN

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
53-0056	--	28-09-99	CMM	Actuator Valve	--	--	0	Boeing 777X	Titchfield, UK	K2523	TO BE WRITTEN
53-0070	--	28-24-08	CMM	Actuator Adaptor	--	17-Jun-21	0	Boeing 777X	Titchfield, UK	K2523	CDCCL status removed by Boing in May 2019
53-0086	--	47-32-12	CMM	SINGLE MOTOR ACTUATOR	--	--	0	KC390	Titchfield, UK	K2523	TO BE WRITTEN
53-0087	--	28-23-09_K2523	CMM	2 Position Actuator Component Maintenance Manual	--	--	0	KF-X	Titchfield, UK	K2523	TO BE WRITTEN
550-1-00157	--	73-10-03	CMM	BP200 Mk4 FUEL PUMP	01-Jul-64	01-Nov-66	0	VC10	Titchfield, UK	K2523	--
550-1-00236	--	73-10-04	OM	MK 5 FUEL PUMP	14-Dec-64	01-Dec-83	11	SPEY	Titchfield, UK	K2523	*OUT OF PRINT - USE 73-11-04
550-1-00236	--	73-11-04	CMM	LOW PRESSURE FUEL PUMP BP230-6 Mk5	10-Feb-86	13-Nov-15	5	SPEY, TAY ENGINE	Titchfield, UK	K2523	--
550-1-00236	--	Pu73-5	SB	BP.230/6 Mk 5. Introduction of new transportation blanks.	20-Jan-71	--	0	BAC 1-11, F27, F28, GULFSTREAM I, TRIDENT	Titchfield, UK	K2523	--
550-1-00236	--	SIL-CS-4-06	SIL	Replace cover plate assys with asbestos gaskets attached	14-Feb-06	14-Feb-06	0	SPEY, TAY ENGINE	Titchfield, UK	K2523	BASIC
550-1-21129	--	28-10-02+	CMM	PUMP	01-Feb-66	01-Feb-78	1	NIMBUS 502	Titchfield, UK	K2523	--
550-1-21151	--	28-20-05+	CMM	FUEL TRANSFER PUMP 080 Mk2	01-Jul-64	01-Jan-68	1	VC10	Titchfield, UK	K2523	--
550-1-21736	--	28-20-01+++	CMM	MOTORISED GEAR TYPE PUMP	01-Nov-65	01-Aug-77	10	HS 125, HS 748	Titchfield, UK	K2523	--
550-1-23127	--	73-10-07	CMM	LP FUEL BACKING PUMP	18-May-73	28-Mar-13	9	JAGUAR	Titchfield, UK	K2523	--
550-1-23127-006	--	73-10-07	CMM	LP FUEL BACKING PUMP	18-May-73	28-Mar-13	9	JAGUAR	Titchfield, UK	K2523	--
550-1-23957-001	--	73-10-17	CMM	FUEL BACKING PUMP BP 255 Mk 1 & 2	01-May-81	28-Jan-15	3	HAWK, TAY ENGINE	Titchfield, UK	K2523	FINNISH HAWK
550-1-23957-002	--	73-10-17	CMM	FUEL BACKING PUMP BP 255 Mk 1 & 2	01-May-81	28-Jan-15	3	HAWK, TAY ENGINE	Titchfield, UK	K2523	FINNISH HAWK
550-1-23957-002	--	73-10-17+	CMM	FUEL BACKING PUMP BP 255 MK2	10-Jan-89	--	0	HAWK, TAY ENGINE	Titchfield, UK	K2523	*OUT OF PRINT (USE 73-10-17)
550-1-23957-002	--	73-11-17	CMM	FUEL BACKING PUMP BP 255 Mk2	31-Aug-89	--	0	HAWK (T-45), TAY ENGINE	Titchfield, UK	K2523	A1-F405A-762-000
554-1-20474	--	28-20-21+	CMM	FUEL FILTER	31-Mar-65	--	0	BAC 1-11	Titchfield, UK	K2523	--
554-1-20481	--	28-20-21+	CMM	FUEL FILTER	31-Mar-65	--	0	BAC 1-11	Titchfield, UK	K2523	--
556-1-13477	--	OSM552	CMM	HOSE ASSEMBLY	01-May-75	--	0	HARRIER	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
558-1-05991	--	28-21-49	CMM	CANISTER TYPE 8811	01-Jul-91	27-Jul-18	9	A330, A340	Titchfield, UK	K2523	--
558-1-05992	--	28-21-49	CMM	CANISTER TYPE 8811	01-Jul-91	27-Jul-18	9	A330, A340	Titchfield, UK	K2523	--
558-1-05993	--	28-21-49	CMM	CANISTER TYPE 8811	01-Jul-91	27-Jul-18	9	A330, A340	Titchfield, UK	K2523	--
558-2-05986	--	28-21-49	CMM	CANISTER TYPE 8811	01-Jul-91	27-Jul-18	9	A330, A340	Titchfield, UK	K2523	--
558-2-05987	--	28-21-49	CMM	CANISTER TYPE 8811	01-Jul-91	27-Jul-18	9	A330, A340	Titchfield, UK	K2523	--
568-1-23627	--	OSM498	CMM	PUMP & INV. FLT VALVE	01-Apr-75	01-Apr-92	1	HS 748	Titchfield, UK	K2523	--
568-1-24220	--	28-20-08++	CMM	FUEL PUMP TYPE 6903 MK 2	06-Jan-81	--	0	MATADOR	Titchfield, UK	K2523	--
568-1-24721-002	--	28-20-09++	CMM	FUEL PUMP 7202	01-May-81	20-Oct-14	4	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	BAE to approve
568-1-24958-004	--	MM289	MM	PUMP	--	16-Jan-09	3	FRL Equip	Titchfield, UK	K2523	--
568-1-24958-005	--	MM289	MM	PUMP	--	16-Jan-09	3	FRL Equip	Titchfield, UK	K2523	--
568-1-25191-001	--	MM263	MM	PUMP 7603 MK1	--	--	0	TORNADO	Titchfield, UK	K2523	--
568-1-25235-001	--	MM265	MM	--	--	--	0	TORNADO	Titchfield, UK	K2523	--
568-1-25300-004	--	MM270	MM	--	--	--	0	HARRIER AV8B	Titchfield, UK	K2523	--
568-1-25663	--	28-13-01+	CMM	PUMP 7814 MK1	01-Dec-80	13-Apr-22	7	BAE 146	Titchfield, UK	K2523	--
568-1-25663-001	--	28-13-01+	CMM	PUMP 7814 MK1	01-Dec-80	13-Apr-22	7	BAE 146	Titchfield, UK	K2523	--
568-1-25663-001	--	HPU28-03-2851	SB	Incorporation of strengthened end housing & new nameplate	30-Jan-95	--	0	BAE 146	Titchfield, UK	K2523	--
568-1-25664-001	--	28-13-02+	CMM	CHAMBER, TYPE 7815	01-Dec-80	22-Apr-11	2	BAE 146	Titchfield, UK	K2523	--
568-1-25665-001	--	28-22-01++	CMM	PUMP, TYPE 7902	01-Apr-81	19-Jan-15	6	BAE 146	Titchfield, UK	K2523	--
568-1-25665-001	--	HPU28-01-2714	SB	Fuel Boost Pump Type 7902 - Introduction of tri-wing type pump to isolating chamber attachment bolts	07-Jun-85	--	0	BAE 146	Titchfield, UK	K2523	--
568-1-25665-001	--	MM268	MM	PUMP AND CHAMBER	--	01-Apr-93	2	BAE 146	Titchfield, UK	K2523	--
568-1-25666-001	--	28-22-02+	CMM	CHAMBER TYPE 7903	01-Apr-81	10-Jun-11	5	BAE 146	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
568-1-25666-001	--	HPU28-02-2760	SB	Pump Isolating Chamber Type 7903 - Introduction of new slide valve sealing arrangement	01-Feb-88	--	0	BAE 146	Titchfield, UK	K2523	--
568-1-25666-001	--	MM268	MM	PUMP AND CHAMBER	--	01-Apr-93	2	BAE 146	Titchfield, UK	K2523	--
568-1-26713	--	28-1-2713	SB	INTRODUCTION OF MK2 PUMP INC A SEPARATE INDUCER	24-May-85	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713	--	28-20-37++	CMM	FUEL PUMP TYPE 8240	01-Nov-83	17-Oct-18	15	BOEING 737	Titchfield, UK	K2523	--
568-1-26713	--	28-2-2717	SB	INTRODUCTION OF MK3 PUMP INC INDUCER & REPRIME IMPELLER OF STAINLESS STEEL	24-May-85	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713	--	28-4-2730	SB	INTRODUCTION OF MK4 PUMP INCORPORATING IMPROVED MEANS OF VAPOUR CONE DISPERSION	05-Mar-86	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713	--	8240-28-03	SB	MINOR DESIGN CHANGES	13-Nov-91	--	0	BOEING	Titchfield, UK	K2523	--
568-1-26713	--	8240-28-05	SB	Introduction of Mk 5 pump incorporating split bearing for rotor journal support	04-Apr-90	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713	--	8240-28-06	SB	Minor design changes	13-Nov-91	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713	--	8240-28-07	SB	Minor design changes	13-Nov-91	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713	--	8240-28-08	SB	Minor design changes	13-Nov-91	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713	--	SL8240 NL1	SL	FUEL BOOST PUMPS - LOW PRESSURE	04-Nov-97	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-000	--	SL8240 NL1	SL	FUEL BOOST PUMPS - LOW PRESSURE	04-Nov-97	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-001	--	-1	SIL	Pump Removals - no fault found	02-Feb-88	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-001	--	28-20-37++	CMM	FUEL PUMP TYPE 8240	01-Nov-83	17-Oct-18	15	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-001	--	8240-28-04-2730	SB	Introduction of Mk 4 pump incorporating improved means of vapour cone dispersion	05-Mar-86	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-001	--	SIL-2009-04	SIL	CDCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320X, A320X MRTT, A320X	Titchfield, UK	K2523	--
568-1-26713-001	--	SIL-2009-08	SIL	INTERCHANGEABILITY OF O-RING SEALS	14-Oct-09	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-002	--	-1	SIL	Pump Removals - no fault found	02-Feb-88	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-002	--	28-20-37++	CMM	FUEL PUMP TYPE 8240	01-Nov-83	17-Oct-18	15	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-002	--	8240-28-04-2730	SB	Introduction of Mk 4 pump incorporating improved means of vapour cone dispersion	05-Mar-86	--	0	BOEING 737	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
568-1-26713-002	--	SIL-2009-08	SIL	INTERCHANGEABILITY OF O-RING SEALS	14-Oct-09	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-003	--	-1	SIL	Pump Removals - no fault found	02-Feb-88	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-003	--	28-20-37++	CMM	FUEL PUMP TYPE 8240	01-Nov-83	17-Oct-18	15	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-003	--	8240-28-04-2730	SB	Introduction of Mk 4 pump incorporating improved means of vapour cone dispersion	05-Mar-86	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-003	--	SIL-2009-08	SIL	INTERCHANGEABILITY OF O-RING SEALS	14-Oct-09	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-004	--	-1	SIL	Pump Removals - no fault found	02-Feb-88	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-004	--	28-20-37++	CMM	FUEL PUMP TYPE 8240	01-Nov-83	17-Oct-18	15	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-004	--	8240-28-07	SB	Minor design changes	13-Nov-91	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-004	--	8240-28-08	SB	Minor design changes	13-Nov-91	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-004	--	8240-28-09	SB	INTRO IMPREG. ROTOR ASSY	01-Feb-00	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-004	--	8240-28-10	SB	INTRO WELDED ROTORS ASSY	02-Feb-00	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-004	--	8240-28-11	SB	Non-procurable Sealing Rings	--	--	0	--	Titchfield, UK	K2523	TO BE WRITTEN
568-1-26713-004	--	SIL-2009-08	SIL	INTERCHANGEABILITY OF O-RING SEALS	14-Oct-09	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-004	--	SL8240 NL1	SL	FUEL BOOST PUMPS - LOW PRESSURE	04-Nov-97	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-005	--	28-20-37++	CMM	FUEL PUMP TYPE 8240	01-Nov-83	17-Oct-18	15	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-005	--	8240-28-07	SB	Minor design changes	13-Nov-91	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-005	--	8240-28-08	SB	Minor design changes	13-Nov-91	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-005	--	8240-28-09	SB	INTRO IMPREG. ROTOR ASSY	01-Feb-00	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-005	--	8240-28-10	SB	INTRO WELDED ROTORS ASSY	02-Feb-00	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-26713-005	--	8240-28-11	SB	Non-procurable Sealing Rings	--	--	0	--	Titchfield, UK	K2523	TO BE WRITTEN
568-1-26713-005	--	SIL-2009-08	SIL	INTERCHANGEABILITY OF O-RING SEALS	14-Oct-09	--	0	BOEING 737	Titchfield, UK	K2523	--

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
568-1-26713-005	--	SL8240 NL1	SL	FUEL BOOST PUMPS - LOW PRESSURE	04-Nov-97	--	0	BOEING 737	Titchfield, UK	K2523	--
568-1-27170-000	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A340	Titchfield, UK	K2523	--
568-1-27170-001	--	28-20-40+	CMM	PUMP TYPE 8413 MK 1 & 2	01-Oct-85	01-Dec-16	18	A300-600, A310-300, A319, A321, A330, A340	Titchfield, UK	K2523	--
568-1-27170-001	--	8413-28-01	SB	Minor design changes	07-Nov-91	07-Nov-91	0	A300-600, A310-300, A321, A330, A340	Titchfield, UK	K2523	--
568-1-27170-001	--	8413-28-02	SB	Minor design changes	13-Sep-93	13-Sep-93	0	A300-600, A310-300, A321, A330, A340	Titchfield, UK	K2523	--
568-1-27170-001	--	8413-28-03	SB	Introduction of SS drain plus - Introduction of terminal tag - Minor design changes	05-Dec-95	05-Dec-95	0	A300-600, A310-300, A321, A330, A340	Titchfield, UK	K2523	--
568-1-27170-002	--	28-20-40+	CMM	PUMP TYPE 8413 MK 1 & 2	01-Oct-85	01-Dec-16	18	A300-600, A310-300, A319, A321, A330, A340	Titchfield, UK	K2523	--
568-1-27170-002	--	8413-28-01	SB	Minor design changes	07-Nov-91	07-Nov-91	0	A300-600, A310-300, A321, A330, A340	Titchfield, UK	K2523	--
568-1-27170-002	--	8413-28-02	SB	Minor design changes	13-Sep-93	13-Sep-93	0	A300-600, A310-300, A321, A330, A340	Titchfield, UK	K2523	--
568-1-27170-002	--	8413-28-03	SB	Introduction of SS drain plus - Introduction of terminal tag - Minor design changes	05-Dec-95	05-Dec-95	0	A300-600, A310-300, A321, A330, A340	Titchfield, UK	K2523	--
568-1-27171-001	--	28-20-41+	CMM	MOUNTING PLATE TYPE 8414	01-Dec-85	02-Aug-16	6	A300-600, A310-300, A319, A321, A340	Titchfield, UK	K2523	--
568-1-27171-001	--	8414-28-01	SB	Mounting Plate Type 8414 - Improved bonding path - Minor Design Change	29-Mar-99	--	0	A300-600, A310-300, A321, A340	Titchfield, UK	K2523	--
568-1-27171-001	--	8414-28-02	SB	Fuel - Mounting Plate Type 8414 - Minor Design Change	02-Jun-99	--	0	A300-600, A310-300, A321, A340	Titchfield, UK	K2523	--
568-1-27171-002	--	28-20-41+	CMM	MOUNTING PLATE TYPE 8414	01-Dec-85	02-Aug-16	6	A300-600, A310-300, A319, A321, A340	Titchfield, UK	K2523	--
568-1-27202-001	--	28-21-51	CMM	FUEL PUMP TYPE 8410 Mk1 - Mk7	22-Jul-87	24-Apr-19	24	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
568-1-27202-001	--	MM290	MM	PUMP AND CANISTER	--	01-Mar-92	1	A319, A320, A321	Titchfield, UK	K2523	--
568-1-27202-002	--	1-91	SIL	--	04-Apr-91	--	0	A320	Titchfield, UK	K2523	--
568-1-27202-002	--	28-21-51	CMM	FUEL PUMP TYPE 8410 Mk1 - Mk7	22-Jul-87	24-Apr-19	24	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
568-1-27202-002	--	8410-28-01	SB	FUEL BOOSTER PUMP - MINOR DESIGN CHANGE	10-Jan-92	--	0	A320	Titchfield, UK	K2523	BASIC MANUAL
568-1-27202-002	--	8410-28-02	SB	Minor design change	07-Jul-94	--	0	A320	Titchfield, UK	K2523	BASIC MANUAL
568-1-27202-002	--	8410-28-03	SB	Introduction of Mk 5	12-Apr-96	01-Sep-11	1	A319, A319CJ, A320, A321	Titchfield, UK	K2523	BASIC MANUAL

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
568-1-27202-002	--	8410-28-05	SB	MODIFY 8410 MK2 & MK5 PUMPS	02-Oct-06	--	0	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
568-1-27202-002	--	8410-28-06	SB	Introduction of Improved Pump	04-Mar-11	--	0	A320	Titchfield, UK	K2523	--
568-1-27202-002	--	K2523-28-012	SIL	Non-Procurement Fuel Boost Pumps	--	--	0	--	Titchfield, UK	K2523	TO BE WRITTEN
568-1-27202-002	--	SIL-2007-02	SIL	TYPE 8410 PUMP SUPPORT - CHANGED SUPPORT OPTIONS	01-Mar-07	--	0	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
568-1-27202-002	--	SIL-CS-10-06	SIL	PUMP TYPE 8410 MK2 & MK5 NUT RETENTION	22-Nov-06	31-Jan-07	1	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
568-1-27202-005	--	28-21-51	CMM	FUEL PUMP TYPE 8410 Mk1 - Mk7	22-Jul-87	24-Apr-19	24	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
568-1-27202-005	--	8410-28-03	SB	Introduction of Mk 5	12-Apr-96	01-Sep-11	1	A319, A319CJ, A320, A321	Titchfield, UK	K2523	BASIC MANUAL
568-1-27202-005	--	8410-28-04	SB	Nut locking on pump, Type 8410	02-May-06	--	0	A318, A319, A320, A321	Titchfield, UK	K2523	WAS SIL-CS-3-06
568-1-27202-005	--	8410-28-05	SB	MODIFY 8410 MK2 & MK5 PUMPS	02-Oct-06	--	0	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
568-1-27202-005	--	8410-28-06	SB	Introduction of Improved Pump	04-Mar-11	--	0	A320	Titchfield, UK	K2523	--
568-1-27202-005	--	SIL-2007-02	SIL	TYPE 8410 PUMP SUPPORT - CHANGED SUPPORT OPTIONS	01-Mar-07	--	0	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
568-1-27202-005	--	SIL-CS-10-06	SIL	PUMP TYPE 8410 MK2 & MK5 NUT RETENTION	22-Nov-06	31-Jan-07	1	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
568-1-27202-005	--	SIL-CS-3-06	SIL	Pump type 8410 Gas Return Adaptor Nut Locking	31-Jan-06	--	0	A320	Titchfield, UK	K2523	SUPERSEDED BY 8410-28-04
568-1-27202-005	--	SIL-CS-7-06	SIL	Pump Type 8410 Mk 005 Nut Retention	--	08-May-06	1	A318, A319, A320, A321	Titchfield, UK	K2523	--
568-1-27202-006	--	28-21-51	CMM	FUEL PUMP TYPE 8410 Mk1 - Mk7	22-Jul-87	24-Apr-19	24	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
568-1-27202-006	--	8410-28-06	SB	Introduction of Improved Pump	04-Mar-11	--	0	A320	Titchfield, UK	K2523	--
568-1-27202-006	--	K2523-28-012	SIL	Non-Procurement Fuel Boost Pumps	--	--	0	--	Titchfield, UK	K2523	TO BE WRITTEN
568-1-27202-006	--	SIL-2009-04	SIL	CDCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A320	Titchfield, UK	K2523	--
568-1-27202-007	--	28-21-51	CMM	FUEL PUMP TYPE 8410 Mk1 - Mk7	22-Jul-87	24-Apr-19	24	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
568-1-27202-007	--	8410-28-06	SB	Introduction of Improved Pump	04-Mar-11	--	0	A320	Titchfield, UK	K2523	--
568-1-27202-02R	--	28-21-51	CMM	FUEL PUMP TYPE 8410 Mk1 - Mk7	22-Jul-87	24-Apr-19	24	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
568-1-27202-02R	--	8410-28-05	SB	MODIFY 8410 MK2 & MK5 PUMPS	02-Oct-06	--	0	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
568-1-27202-02R	--	8410-28-06	SB	Introduction of Improved Pump	04-Mar-11	--	0	A320	Titchfield, UK	K2523	--
568-1-27202-02R	--	SIL-2007-02	SIL	TYPE 8410 PUMP SUPPORT - CHANGED SUPPORT OPTIONS	01-Mar-07	--	0	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
568-1-27202-02R	--	SIL-CS-10-06	SIL	PUMP TYPE 8410 MK2 & MK5 NUT RETENTION	22-Nov-06	31-Jan-07	1	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
568-1-27202-05R	--	28-21-51	CMM	FUEL PUMP TYPE 8410 Mk1 - Mk7	22-Jul-87	24-Apr-19	24	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
568-1-27202-05R	--	8410-28-06	SB	Introduction of Improved Pump	04-Mar-11	--	0	A320	Titchfield, UK	K2523	--
568-1-27202-05R	--	K2523-28-012	SIL	Non-Procurement Fuel Boost Pumps	--	--	0	--	Titchfield, UK	K2523	TO BE WRITTEN
568-1-27202-05R	--	SIL-2007-02	SIL	TYPE 8410 PUMP SUPPORT - CHANGED SUPPORT OPTIONS	01-Mar-07	--	0	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
568-1-27202-05R	--	SIL-CS-10-06	SIL	PUMP TYPE 8410 MK2 & MK5 NUT RETENTION	22-Nov-06	31-Jan-07	1	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
568-1-27203-001	--	28-21-52+	CMM	CANISTER TYPE 8411	22-Jul-87	06-Dec-17	13	A320, A320 NEO	Titchfield, UK	K2523	--
568-1-27203-001	--	8411-28-02	SB	Cancelled SB	--	--	0	A318, A319, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN
568-1-27203-001	--	8411-28-03	SB	Introduction of New Canister & NRV	17-Mar-11	--	0	A319, A320, A321	Titchfield, UK	K2523	--
568-1-27203-001	--	MM290	MM	PUMP AND CANISTER	--	01-Mar-92	1	A319, A320, A321	Titchfield, UK	K2523	--
568-1-27203-002	--	28-21-52+	CMM	CANISTER TYPE 8411	22-Jul-87	06-Dec-17	13	A320, A320 NEO	Titchfield, UK	K2523	--
568-1-27203-002	--	8411-28-01	SB	Minor design change (Outlet valve sealing disc & washer)	18-Sep-96	--	0	A319, A320, A321	Titchfield, UK	K2523	--
568-1-27203-002	--	8411-28-02	SB	Cancelled SB	--	--	0	A318, A319, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN
568-1-27203-002	--	8411-28-03	SB	Introduction of New Canister & NRV	17-Mar-11	--	0	A319, A320, A321	Titchfield, UK	K2523	--
568-1-27203-002	--	SIL-2008-08	SIL	FUEL - ALTERNATIVE O-RING LUBRICANT	06-Aug-09	--	0	A320	Titchfield, UK	K2523	--
568-1-27203-003	--	28-21-52+	CMM	CANISTER TYPE 8411	22-Jul-87	06-Dec-17	13	A320, A320 NEO	Titchfield, UK	K2523	--
568-1-27203-003	--	8411-28-03	SB	Introduction of New Canister & NRV	17-Mar-11	--	0	A319, A320, A321	Titchfield, UK	K2523	--
568-1-27244-001	--	28-21-52+	CMM	CANISTER TYPE 8411	22-Jul-87	06-Dec-17	13	A320, A320 NEO	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
568-1-27244-001	--	8411-28-03	SB	Introduction of New Canister & NRV	17-Mar-11	--	0	A319, A320, A321	Titchfield, UK	K2523	--
568-1-27244-002	--	28-21-52+	CMM	CANISTER TYPE 8411	22-Jul-87	06-Dec-17	13	A320, A320 NEO	Titchfield, UK	K2523	--
568-1-27244-002	--	8411-28-01	SB	Minor design change (Outlet valve sealing disc & washer)	18-Sep-96	--	0	A319, A320, A321	Titchfield, UK	K2523	--
568-1-27244-002	--	8411-28-03	SB	Introduction of New Canister & NRV	17-Mar-11	--	0	A319, A320, A321	Titchfield, UK	K2523	--
568-1-27244-003	--	28-21-52+	CMM	CANISTER TYPE 8411	22-Jul-87	06-Dec-17	13	A320, A320 NEO	Titchfield, UK	K2523	--
568-1-27244-003	--	8411-28-03	SB	Introduction of New Canister & NRV	17-Mar-11	--	0	A319, A320, A321	Titchfield, UK	K2523	--
568-1-27340-100	--	28-21-01	CMM	Pump Type 8401	01-Feb-94	20-Jan-16	5	EH101	Titchfield, UK	K2523	--
568-1-27350-002	--	28-21-02+	CMM	MANIFOLD TYPE 8402 MK2	01-Mar-94	20-Jan-16	3	EH101	Titchfield, UK	K2523	--
568-1-27360-001	--	28-31-01	CMM	Pump Type 8316	01-Apr-94	15-Jan-09	3	EH101	Titchfield, UK	K2523	--
568-1-27360-100	--	28-31-01	CMM	Pump Type 8316	01-Apr-94	15-Jan-09	3	EH101	Titchfield, UK	K2523	--
568-1-27863-001	--	28-88-12+	CMM	RAT PUMP TYPE 8712	22-Jun-90	23-Oct-12	7	FRL Equip	Titchfield, UK	K2523	--
568-1-27863-001	--	8712-28-01	SB	Fuel Pump Type 8712 - Removal of possible interference fit of DC motor	17-Nov-99	--	0	MK 32 POD	Titchfield, UK	K2523	--
568-1-27863-002	--	28-88-12+	CMM	RAT PUMP TYPE 8712	22-Jun-90	23-Oct-12	7	FRL Equip	Titchfield, UK	K2523	--
568-1-27863-002	--	8712-28-01	SB	Fuel Pump Type 8712 - Removal of possible interference fit of DC motor	17-Nov-99	--	0	MK 32 POD	Titchfield, UK	K2523	--
568-1-27863-002	--	8712-28-02	SB	Addition of fittings to allow microswitch indication of end of travel	21-Jul-00	--	0	MK 32 POD	Titchfield, UK	K2523	--
568-1-27863-400	--	28-89-12	CMM	FUEL PUMP TYPE 8712 MK 400	26-Jan-16	06-Feb-19	1	FRL Equip, KC46A	Titchfield, UK	K2523	--
568-1-28300-001	--	28-21-50	CMM	FUEL PUMP TYPE 8810	01-Jul-91	02-Jul-18	14	A330, A340	Titchfield, UK	K2523	--
568-1-28300-001	--	8810-28-01	SB	Introduction of Mk 2 pump with improved fuse retention	10-Jun-94	--	0	A330, A340	Titchfield, UK	K2523	--
568-1-28300-001	--	8810-28-02	SB	Upgrade installation sealing rings	14-May-98	13-Sep-99	1	A330, A340	Titchfield, UK	K2523	--
568-1-28300-001	--	8810-28-03	SB	Conversion of Mk1 & Mk2 Pumps to Mk3 & Mk4 Pumps	02-Jul-01	--	0	A330, A340	Titchfield, UK	K2523	--
568-1-28300-002	--	28-21-50	CMM	FUEL PUMP TYPE 8810	01-Jul-91	02-Jul-18	14	A330, A340	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
568-1-28300-002	--	8810-28-02	SB	Upgrade installation sealing rings	14-May-98	13-Sep-99	1	A330, A340	Titchfield, UK	K2523	--
568-1-28300-002	--	8810-28-03	SB	Conversion of Mk1 & Mk2 Pumps to Mk3 & Mk4 Pumps	02-Jul-01	--	0	A330, A340	Titchfield, UK	K2523	--
568-1-28300-003	--	28-21-50	CMM	FUEL PUMP TYPE 8810	01-Jul-91	02-Jul-18	14	A330, A340	Titchfield, UK	K2523	--
568-1-28300-004	--	28-21-50	CMM	FUEL PUMP TYPE 8810	01-Jul-91	02-Jul-18	14	A330, A340	Titchfield, UK	K2523	--
568-1-28300-004	--	8810-28-03	SB	Conversion of Mk1 & Mk2 Pumps to Mk3 & Mk4 Pumps	02-Jul-01	--	0	A330, A340	Titchfield, UK	K2523	--
568-1-28300-004	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A322, A320-MRTT, A340	Titchfield, UK	K2523	--
568-1-28300-100	--	28-21-55+	CMM	TYPE 8810 - FUEL BOOST PUMP MK 100	25-Jun-02	08-Mar-22	11	A340-500, A340-600	Titchfield, UK	K2523	--
568-1-28300-100	--	8810-28-04	SB	Introduction of Pump 8810 Mk101	21-Dec-05	--	0	A340-500, A340-600	Titchfield, UK	K2523	BASIC MANUAL
568-1-28300-100	--	8810-28-05	SB	Intro of new pumps Mk102 and 103	25-May-12	24-Jan-19	2	A340	Titchfield, UK	K2523	--
568-1-28300-101	--	28-21-55+	CMM	TYPE 8810 - FUEL BOOST PUMP MK 100	25-Jun-02	08-Mar-22	11	A340-500, A340-600	Titchfield, UK	K2523	--
568-1-28300-101	--	8810-28-04	SB	Introduction of Pump 8810 Mk101	21-Dec-05	--	0	A340-500, A340-600	Titchfield, UK	K2523	BASIC MANUAL
568-1-28300-101	--	8810-28-05	SB	Intro of new pumps Mk102 and 103	25-May-12	24-Jan-19	2	A340	Titchfield, UK	K2523	--
568-1-28300-101	--	8810-28-06	SB	Inspection for Cavitation Erosion Damage	09-Nov-17	01-Mar-19	2	A330, A340	Titchfield, UK	K2523	--
568-1-28300-101	--	8810-28-07	SB	Main Tank Erosion	--	--	0	A330, A340	Titchfield, UK	K2523	TO BE WRITTEN
568-1-28300-102	--	28-21-55+	CMM	TYPE 8810 - FUEL BOOST PUMP MK 100	25-Jun-02	08-Mar-22	11	A340-500, A340-600	Titchfield, UK	K2523	--
568-1-28300-102	--	8810-28-05	SB	Intro of new pumps Mk102 and 103	25-May-12	24-Jan-19	2	A340	Titchfield, UK	K2523	--
568-1-28300-103	--	28-21-55+	CMM	TYPE 8810 - FUEL BOOST PUMP MK 100	25-Jun-02	08-Mar-22	11	A340-500, A340-600	Titchfield, UK	K2523	--
568-1-28300-103	--	8810-28-05	SB	Intro of new pumps Mk102 and 103	25-May-12	24-Jan-19	2	A340	Titchfield, UK	K2523	--
568-1-28300-103	--	8810-28-06	SB	Inspection for Cavitation Erosion Damage	09-Nov-17	01-Mar-19	2	A330, A340	Titchfield, UK	K2523	--
568-1-28300-103	--	8810-28-07	SB	Main Tank Erosion	--	--	0	A330, A340	Titchfield, UK	K2523	TO BE WRITTEN
568-1-28300-103	--	8810-28-08	SB	Modification of -103 pumps to -104 standard	--	04-Feb-22	1	A330, A340	Titchfield, UK	K2523	TO BE WRITTEN

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
568-1-28300-103	--	K2523-28-019	SIL	Introduction of New Pump -104	--	--	0	A330, A340	Titchfield, UK	K2523	TO BE WRITTEN
568-1-28300-104	--	8810-28-08	SB	Modification of -103 pumps to -104 standard	--	04-Feb-22	1	A330, A340	Titchfield, UK	K2523	TO BE WRITTEN
568-1-28300-104	--	K2523-28-019	SIL	Introduction of New Pump -104	--	--	0	A330, A340	Titchfield, UK	K2523	TO BE WRITTEN
568-1-28300-200	--	28-21-59	CMM	PUMP TYPE 8810 MK 200	28-Jul-05	07-Dec-20	6	A340-500	Titchfield, UK	K2523	--
568-1-28300-200	--	8810-28-06	SB	Inspection for Cavitation Erosion Damage	09-Nov-17	01-Mar-19	2	A330, A340	Titchfield, UK	K2523	--
568-1-28300-200	--	8810-28-07	SB	Main Tank Erosion	--	--	0	A330, A340	Titchfield, UK	K2523	TO BE WRITTEN
568-1-28301-003	--	28-21-49	CMM	CANISTER TYPE 8811	01-Jul-91	27-Jul-18	9	A330, A340	Titchfield, UK	K2523	--
568-1-28301-003	--	8811-28-01	SB	Minor design change	14-Aug-92	--	0	A330, A340	Titchfield, UK	K2523	--
568-1-28301-003	--	8811-28-02	SB	INTRODUCTION OF A SPECIALLY MODIFIED CANISTER	20-Jul-01	--	0	A330	Titchfield, UK	K2523	--
568-1-28301-003	--	SIL-2008-09	SIL	Changed Sealing Method for Captive Nuts	12-Sep-08	--	0	A320	Titchfield, UK	K2523	--
568-1-28301-03X	--	28-21-49	CMM	CANISTER TYPE 8811	01-Jul-91	27-Jul-18	9	A330, A340	Titchfield, UK	K2523	--
568-1-28301-03X	--	8811-28-02	SB	INTRODUCTION OF A SPECIALLY MODIFIED CANISTER	20-Jul-01	--	0	A330	Titchfield, UK	K2523	--
568-1-28301-102	--	28-21-56+	CMM	CANISTER	25-Jun-02	19-Apr-12	2	A340-500, A340-600	Titchfield, UK	K2523	--
568-1-28301-103	--	28-21-56+	CMM	CANISTER	25-Jun-02	19-Apr-12	2	A340-500, A340-600	Titchfield, UK	K2523	--
568-1-28405-001	--	28-21-53++	ACMM	JET PUMP TYPE 8814	01-Jul-91	01-Dec-16	3	A330, A340	Titchfield, UK	K2523	--
568-1-28439-001	--	MM295	MM	--	--	--	0	EFA	Titchfield, UK	K2523	--
568-1-28708-001	--	MM299	MM	--	--	--	0	EFA	Titchfield, UK	K2523	--
568-1-28708-002	--	28-22-03_K2523_1	CMP	(KSA Program Only) Pump Type 8904 MK 2 Component Maintenance Publication	--	--	0	EFA	Titchfield, UK	K2523	TO BE WRITTEN
568-1-29115-001	--	28-20-42+	CMM	Type 9106 Fuel Boost Pump	28-Jan-94	25-May-10	11	BOEING 777	Titchfield, UK	K2523	--
568-1-29115-001	--	9106 NL1	SL	Ex. 9106 Pumps Ser Nos 0011 to 0812	17-Aug-99	01-Sep-00	1	BOEING 777	Titchfield, UK	K2523	--
568-1-29115-001	--	9106-28-02	SB	Introduction of New Shaft and Rotor Assy	20-Apr-99	--	0	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
568-1-29115-001	--	9106-28-05	SB	9106 Pump - Intro of Alt Rotor Assemblies	28-Feb-03	28-Feb-03	0	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-29115-001	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320XLR, A320XLR-MRTT, A320XLR-MRTT	Titchfield, UK	K2523	--
568-1-29115-002	--	28-20-42+	CMM	Type 9106 Fuel Boost Pump	28-Jan-94	25-May-10	11	BOEING 777	Titchfield, UK	K2523	--
568-1-29115-002	--	9106 NL1	SL	Ex. 9106 Pumps Ser Nos 0011 to 0812	17-Aug-99	01-Sep-00	1	BOEING 777	Titchfield, UK	K2523	--
568-1-29115-002	--	9106-28-01	SB	9106 - Conversion Mk1 pump to Mk2	21-Mar-96	--	0	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-29115-002	--	9106-28-02	SB	Introduction of New Shaft and Rotor Assy	20-Apr-99	--	0	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-29115-002	--	9106-28-03	SB	Conversion of Mk2 Pump to Mk4 Pump	04-May-01	--	0	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-29115-002	--	9106-28-04	SB	Type 9106 Pump - Inducer Drive Pin Check	22-Jul-02	20-Nov-03	1	BOEING 777	Titchfield, UK	K2523	--
568-1-29115-002	--	9106-28-05	SB	9106 Pump - Intro of Alt Rotor Assemblies	28-Feb-03	28-Feb-03	0	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-29115-004	--	28-20-42+	CMM	Type 9106 Fuel Boost Pump	28-Jan-94	25-May-10	11	BOEING 777	Titchfield, UK	K2523	--
568-1-29115-004	--	9106-28-04	SB	Type 9106 Pump - Inducer Drive Pin Check	22-Jul-02	20-Nov-03	1	BOEING 777	Titchfield, UK	K2523	--
568-1-29116-001	--	28-20-43++	CMM	Housing Assembly Type 9107Mk1, 9109Mk2, 9206Mk1 & 9603Mk1	01-Feb-94	10-Dec-13	8	BOEING 777	Titchfield, UK	K2523	--
568-1-29116-001	--	9107-28-01	SB	Conversion of Mk1 & Mk2 Housings to Mk2 & Mk3 Housings	28-Jun-01	28-Jun-01	0	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-29116-001	--	9107-9109-9206-9603NL1	SL	MARCONI POWER AND CONTROL SYSTEMS HOUSING ASSYS	15-Jun-99	31-Mar-05	1	BOEING 777	Titchfield, UK	K2523	Distribute to OSM637 holders
568-1-29116-001	--	9107-9109-9206-9603NL2	SL	INTRODUCTION OF ALTERNATE FLAP VALVE	11-May-06	26-Sep-06	2	BOEING 777	Titchfield, UK	K2523	Distribute to OSM 637 holders
568-1-29116-001	--	9107-9603-28-01	SB	Introduction of New Boost Pump Housing	09-Apr-13	--	0	BOEING 777	Titchfield, UK	K2523	--
568-1-29116-002	--	28-20-43++	CMM	Housing Assembly Type 9107Mk1, 9109Mk2, 9206Mk1 & 9603Mk1	01-Feb-94	10-Dec-13	8	BOEING 777	Titchfield, UK	K2523	--
568-1-29116-002	--	9107-28-01	SB	Conversion of Mk1 & Mk2 Housings to Mk2 & Mk3 Housings	28-Jun-01	28-Jun-01	0	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-29116-002	--	9107-9603-28-01	SB	Introduction of New Boost Pump Housing	09-Apr-13	--	0	BOEING 777	Titchfield, UK	K2523	--
568-1-29116-003	--	28-20-43++	CMM	Housing Assembly Type 9107Mk1, 9109Mk2, 9206Mk1 & 9603Mk1	01-Feb-94	10-Dec-13	8	BOEING 777	Titchfield, UK	K2523	--
568-1-29116-003	--	9107-9603-28-01	SB	Introduction of New Boost Pump Housing	09-Apr-13	--	0	BOEING 777	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
568-1-29116-004	--	28-20-43++	CMM	Housing Assembly Type 9107Mk1, 9109Mk2, 9206Mk1 & 9603Mk1	01-Feb-94	10-Dec-13	8	BOEING 777	Titchfield, UK	K2523	--
568-1-29116-004	--	9107-9603-28-01	SB	Introduction of New Boost Pump Housing	09-Apr-13	--	0	BOEING 777	Titchfield, UK	K2523	--
568-1-29117-002	--	28-20-44+	CMM	PUMP TYPE 9108 Mk2 & Mk3	01-Jan-94	26-May-11	8	BOEING 777	Titchfield, UK	K2523	--
568-1-29117-002	--	9108-28-01	SB	INTRO. OF NEW INDUCER, STATOR AND EXTRACTION HANDLE	18-Jul-05	--	0	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-29117-002	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A340	Titchfield, UK	K2523	--
568-1-29117-003	--	28-20-44+	CMM	PUMP TYPE 9108 Mk2 & Mk3	01-Jan-94	26-May-11	8	BOEING 777	Titchfield, UK	K2523	--
568-1-29117-003	--	9108-28-01	SB	INTRO. OF NEW INDUCER, STATOR AND EXTRACTION HANDLE	18-Jul-05	--	0	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-29118-002	--	28-20-43++	CMM	Housing Assembly Type 9107Mk1, 9109Mk2, 9206Mk1 & 9603Mk1	01-Feb-94	10-Dec-13	8	BOEING 777	Titchfield, UK	K2523	--
568-1-29118-002	--	9107-28-01	SB	Conversion of Mk1 & Mk2 Housings to Mk2 & Mk3 Housings	28-Jun-01	28-Jun-01	0	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-29118-002	--	9107-9109-9206-9603NL1	SL	MARCONI POWER AND CONTROL SYSTEMS HOUSING ASSYS	15-Jun-99	31-Mar-05	1	BOEING 777	Titchfield, UK	K2523	Distribute to OSM637 holders
568-1-29118-002	--	9107-9109-9206-9603NL2	SL	INTRODUCTION OF ALTERNATE FLAP VALVE	11-May-06	26-Sep-06	2	BOEING 777	Titchfield, UK	K2523	Distribute to OSM 637 holders
568-1-29118-002	--	9109-20107-28-1	SB	FUEL - Jettison Pump - Introduction of New Housing	09-Apr-13	--	0	BOEING 777	Titchfield, UK	K2523	--
568-1-29118-003	--	28-20-43++	CMM	Housing Assembly Type 9107Mk1, 9109Mk2, 9206Mk1 & 9603Mk1	01-Feb-94	10-Dec-13	8	BOEING 777	Titchfield, UK	K2523	--
568-1-29118-003	--	9107-28-01	SB	Conversion of Mk1 & Mk2 Housings to Mk2 & Mk3 Housings	28-Jun-01	28-Jun-01	0	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-29118-003	--	9109-20107-28-1	SB	FUEL - Jettison Pump - Introduction of New Housing	09-Apr-13	--	0	BOEING 777	Titchfield, UK	K2523	--
568-1-29118-004	--	28-20-43++	CMM	Housing Assembly Type 9107Mk1, 9109Mk2, 9206Mk1 & 9603Mk1	01-Feb-94	10-Dec-13	8	BOEING 777	Titchfield, UK	K2523	--
568-1-29118-004	--	9109-20107-28-1	SB	FUEL - Jettison Pump - Introduction of New Housing	09-Apr-13	--	0	BOEING 777	Titchfield, UK	K2523	--
568-1-29118-005	--	28-20-43++	CMM	Housing Assembly Type 9107Mk1, 9109Mk2, 9206Mk1 & 9603Mk1	01-Feb-94	10-Dec-13	8	BOEING 777	Titchfield, UK	K2523	--
568-1-29118-005	--	9109-20107-28-1	SB	FUEL - Jettison Pump - Introduction of New Housing	09-Apr-13	--	0	BOEING 777	Titchfield, UK	K2523	--
568-1-29407-002	--	28-20-45+	CMM	PUMP TYPE 9121 Mk2	01-Jan-94	19-Feb-10	6	BOEING 777	Titchfield, UK	K2523	--
568-1-29407-002	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A340	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
568-1-29408-001	--	28-20-46+	CMM	Type 9122 Housing Assembly	01-Feb-94	14-Sep-12	3	BOEING 777	Titchfield, UK	K2523	--
568-1-29408-100	--	28-20-46+	CMM	Type 9122 Housing Assembly	01-Feb-94	14-Sep-12	3	BOEING 777	Titchfield, UK	K2523	--
568-1-29447-000	--	28-20-43++	CMM	Housing Assembly Type 9107Mk1, 9109Mk2, 9206Mk1 & 9603Mk1	01-Feb-94	10-Dec-13	8	BOEING 777	Titchfield, UK	K2523	--
568-1-29447-000	--	9107-9109-9206-9603NL1	SL	MARCONI POWER AND CONTROL SYSTEMS HOUSING ASSYS	15-Jun-99	31-Mar-05	1	BOEING 777	Titchfield, UK	K2523	Distribute to OSM637 holders
568-1-29500-003	--	MM294	MM	--	--	16-May-94	3	C17A	Titchfield, UK	K2523	--
568-1-29501-001	--	MM294	MM	--	--	16-May-94	3	C17A	Titchfield, UK	K2523	--
568-1-29507-001	--	28-20-43++	CMM	Housing Assembly Type 9107Mk1, 9109Mk2, 9206Mk1 & 9603Mk1	01-Feb-94	10-Dec-13	8	BOEING 777	Titchfield, UK	K2523	--
568-1-29507-001	--	9107-28-01	SB	Conversion of Mk1 & Mk2 Housings to Mk2 & Mk3 Housings	28-Jun-01	28-Jun-01	0	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-29507-001	--	9107-9109-9206-9603NL1	SL	MARCONI POWER AND CONTROL SYSTEMS HOUSING ASSYS	15-Jun-99	31-Mar-05	1	BOEING 777	Titchfield, UK	K2523	Distribute to OSM637 holders
568-1-29507-001	--	9107-9109-9206-9603NL2	SL	INTRODUCTION OF ALTERNATE FLAP VALVE	11-May-06	26-Sep-06	2	BOEING 777	Titchfield, UK	K2523	Distribute to OSM 637 holders
568-1-29507-002	--	28-20-43++	CMM	Housing Assembly Type 9107Mk1, 9109Mk2, 9206Mk1 & 9603Mk1	01-Feb-94	10-Dec-13	8	BOEING 777	Titchfield, UK	K2523	--
568-1-29507-002	--	9107-28-01	SB	Conversion of Mk1 & Mk2 Housings to Mk2 & Mk3 Housings	28-Jun-01	28-Jun-01	0	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-29515-001	--	28-22-11+	CMM	FUEL BOOST PUMP TYPE 9203	01-May-95	--	0	N250	Titchfield, UK	K2523	--
568-1-29516-001	--	28-22-12+	CMM	MANIFOLD	01-May-95	--	0	N250	Titchfield, UK	K2523	--
568-1-29684-001	--	28-21-54+	CMM	MOUNTING PLATE TYPE 9209	10-Sep-93	11-Dec-15	8	A310-MRTT, A330, A340	Titchfield, UK	K2523	--
568-1-29684-001	--	9209-28-01	SB	Minor design change (New valve spring)	08-Oct-01	08-Oct-01	0	A330, A340	Titchfield, UK	K2523	--
568-1-29684-001	--	K2523-28-018	SIL	Fuel System - Mounting Plate Type 9209 - Change of base plate	--	--	0	--	Titchfield, UK	K2523	TO BE WRITTEN
568-1-29684-001	--	SIL-2007-01	SIL	Type9209 Mounting Plate Wear Check	26-Jan-07	--	0	A330, A340	Titchfield, UK	K2523	--
568-1-29684-100	--	28-21-54+	CMM	MOUNTING PLATE TYPE 9209	10-Sep-93	11-Dec-15	8	A310-MRTT, A330, A340	Titchfield, UK	K2523	--
568-1-29684-100	--	SIL-2007-01	SIL	Type9209 Mounting Plate Wear Check	26-Jan-07	--	0	A330, A340	Titchfield, UK	K2523	--
568-1-30073-001	--	28-20-43++	CMM	Housing Assembly Type 9107Mk1, 9109Mk2, 9206Mk1 & 9603Mk1	01-Feb-94	10-Dec-13	8	BOEING 777	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
568-1-30073-001	--	9107-28-01	SB	Conversion of Mk1 & Mk2 Housings to Mk2 & Mk3 Housings	28-Jun-01	28-Jun-01	0	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-30073-001	--	9107-9109-9206-9603NL1	SL	MARCONI POWER AND CONTROL SYSTEMS HOUSING ASSYS	15-Jun-99	31-Mar-05	1	BOEING 777	Titchfield, UK	K2523	Distribute to OSM637 holders
568-1-30073-001	--	9107-9109-9206-9603NL2	SL	INTRODUCTION OF ALTERNATE FLAP VALVE	11-May-06	26-Sep-06	2	BOEING 777	Titchfield, UK	K2523	Distribute to OSM 637 holders
568-1-30073-001	--	9107-9603-28-01	SB	Introduction of New Boost Pump Housing	09-Apr-13	--	0	BOEING 777	Titchfield, UK	K2523	--
568-1-30073-002	--	28-20-43++	CMM	Housing Assembly Type 9107Mk1, 9109Mk2, 9206Mk1 & 9603Mk1	01-Feb-94	10-Dec-13	8	BOEING 777	Titchfield, UK	K2523	--
568-1-30073-003	--	28-20-43++	CMM	Housing Assembly Type 9107Mk1, 9109Mk2, 9206Mk1 & 9603Mk1	01-Feb-94	10-Dec-13	8	BOEING 777	Titchfield, UK	K2523	--
568-1-30073-003	--	9107-9603-28-01	SB	Introduction of New Boost Pump Housing	09-Apr-13	--	0	BOEING 777	Titchfield, UK	K2523	--
568-1-30073-004	--	28-20-43++	CMM	Housing Assembly Type 9107Mk1, 9109Mk2, 9206Mk1 & 9603Mk1	01-Feb-94	10-Dec-13	8	BOEING 777	Titchfield, UK	K2523	--
568-1-30073-004	--	9107-9603-28-01	SB	Introduction of New Boost Pump Housing	09-Apr-13	--	0	BOEING 777	Titchfield, UK	K2523	--
568-1-30080-001	--	28-20-47+	CMM	FUEL BOOST PUMP TYPE 9602	01-Jan-98	30-Apr-10	6	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-30080-001	--	9602-28-01	SB	INTRO OF NEW INDUCER, STATOR, EXTRACTION HANDLE AND MINOR REWORK	18-Jul-05	--	0	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-30080-001	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A320	Titchfield, UK	K2523	--
568-1-30080-001	--	SL9602NL1	SL	Induction stator reliability	14-Oct-03	14-Oct-03	0	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-30080-002	--	28-20-47+	CMM	FUEL BOOST PUMP TYPE 9602	01-Jan-98	30-Apr-10	6	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-30080-002	--	9602-28-01	SB	INTRO OF NEW INDUCER, STATOR, EXTRACTION HANDLE AND MINOR REWORK	18-Jul-05	--	0	BOEING 777	Titchfield, UK	K2523	BASIC MANUAL
568-1-30152-001	--	28-20-38++	CMM	Pump, Fuel Transfer Type 9712 Mk1	19-Nov-97	09-Jan-15	1	SAAB 2000	Titchfield, UK	K2523	BASIC MANUAL
568-1-30153-001	--	28-20-39	CMM	CANISTER TYPE 9713	01-Nov-97	--	0	SAAB 2000	Titchfield, UK	K2523	--
568-1-30163-001	--	MM307	MM	FUEL TRANSFER PUMP TYPE 9714	20-Jul-98	29-May-00	1	JSF	Titchfield, UK	K2523	GEC TITCHFIELD MANUAL
568-1-30522-001	--	28-26-12	CMM	PUMP OVERRIDE/JETTISON TYPE 20002 (BOEING PN S830U002-3)	10-Oct-03	28-Nov-08	2	BOEING 747	Titchfield, UK	K2523	--
568-1-30522-001	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A320	Titchfield, UK	K2523	--
568-1-30561-001	--	28-26-13	CMM	PUMP HOUSING TYPE 20003 (BOEING PN S830U002-2)	10-Oct-03	06-Dec-18	3	BOEING 747	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
568-1-30666-001	--	28-20-43++	CMM	Housing Assembly Type 9107Mk1, 9109Mk2, 9206Mk1 & 9603Mk1	01-Feb-94	10-Dec-13	8	BOEING 777	Titchfield, UK	K2523	--
568-1-30666-001	--	9107-9109-9206-9603NL2	SL	INTRODUCTION OF ALTERNATE FLAP VALVE	11-May-06	26-Sep-06	2	BOEING 777	Titchfield, UK	K2523	Distribute to OSM 637 holders
568-1-30666-001	--	9109-20107-28-1	SB	FUEL - Jettison Pump - Introduction of New Housing	09-Apr-13	--	0	BOEING 777	Titchfield, UK	K2523	--
568-1-30666-002	--	28-20-43++	CMM	Housing Assembly Type 9107Mk1, 9109Mk2, 9206Mk1 & 9603Mk1	01-Feb-94	10-Dec-13	8	BOEING 777	Titchfield, UK	K2523	--
568-1-30666-002	--	9109-20107-28-1	SB	FUEL - Jettison Pump - Introduction of New Housing	09-Apr-13	--	0	BOEING 777	Titchfield, UK	K2523	--
568-1-30685-001	--	28-26-14	CMM	PUMP FUEL BOOST TYPE 20004 (BOEING PN S830U001-3)	10-Oct-03	28-Nov-08	2	BOEING 747	Titchfield, UK	K2523	BASIC MANUAL
568-1-30685-001	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A340	Titchfield, UK	K2523	--
568-1-30690-001	--	28-26-15	CMM	PUMP HOUSING TYPE 20005 (BOEING PN S830U001-2)	10-Oct-03	20-Apr-09	2	BOEING 747	Titchfield, UK	K2523	--
568-1-30750-100	--	MM28-26-02	MM	Fuel Pp Type 20124 & Canr Type 20125	30-Jun-04	04-Mar-05	1	A380	Titchfield, UK	K2523	--
568-1-30750-100	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A340	Titchfield, UK	K2523	--
568-1-30750-101	--	28-26-02	CMM	FEED PUMP TYPE 20124	07-Mar-05	07-Oct-19	12	A380	Titchfield, UK	K2523	--
568-1-30750-101	--	SIL-2007-06	SIL	CAPACITOR REFORMING FOR A380 PUMPS	12-Sep-11	--	0	A380	Titchfield, UK	K2523	--
568-1-30750-101	--	SIL-2008-03	SIL	Introduction of Pump Variants	29-Feb-08	--	0	A380	Titchfield, UK	K2523	--
568-1-30750-101	--	SIL-2008-04	SIL	SPECIAL O-RING	29-Feb-08	16-Apr-08	1	A380	Titchfield, UK	K2523	--
568-1-30750-101	--	SIL-2008-05	SIL	INTRO OF NEW REMOVAL/INSTALI TOOL	29-Feb-08	--	0	A380	Titchfield, UK	K2523	--
568-1-30750-101	--	SIL-2009-09	SIL	A380 Time Line	06-Nov-09	--	0	A380	Titchfield, UK	K2523	--
568-1-30750-102	--	20124-28-001	SB	Improved Impeller Introduction	03-Dec-12	--	0	A380	Titchfield, UK	K2523	--
568-1-30750-102	--	28-26-02	CMM	FEED PUMP TYPE 20124	07-Mar-05	07-Oct-19	12	A380	Titchfield, UK	K2523	--
568-1-30750-102	--	SIL-2008-03	SIL	Introduction of Pump Variants	29-Feb-08	--	0	A380	Titchfield, UK	K2523	--
568-1-30750-102	--	SIL-2008-04	SIL	SPECIAL O-RING	29-Feb-08	16-Apr-08	1	A380	Titchfield, UK	K2523	--
568-1-30750-102	--	SIL-2009-09	SIL	A380 Time Line	06-Nov-09	--	0	A380	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
568-1-30750-103	--	20124-28-001	SB	Improved Impeller Introduction	03-Dec-12	--	0	A380	Titchfield, UK	K2523	--
568-1-30750-103	--	20124-28-002	SB	Introduction of Mark 105 pump	03-Aug-16	23-May-18	3	A380	Titchfield, UK	K2523	--
568-1-30750-103	--	28-26-02	CMM	FEED PUMP TYPE 20124	07-Mar-05	07-Oct-19	12	A380	Titchfield, UK	K2523	--
568-1-30750-105	--	20124-28-002	SB	Introduction of Mark 105 pump	03-Aug-16	23-May-18	3	A380	Titchfield, UK	K2523	--
568-1-30750-105	--	28-26-02	CMM	FEED PUMP TYPE 20124	07-Mar-05	07-Oct-19	12	A380	Titchfield, UK	K2523	--
568-1-30750-105	--	K2523-28-016	SIL	Introduction of Amendment 1 Feed Pump	--	--	0	A380	Titchfield, UK	K2523	TO BE WRITTEN
568-1-30750-151	--	28-26-02	CMM	FEED PUMP TYPE 20124	07-Mar-05	07-Oct-19	12	A380	Titchfield, UK	K2523	--
568-1-30750-151	--	SIL-2008-03	SIL	Introduction of Pump Variants	29-Feb-08	--	0	A380	Titchfield, UK	K2523	--
568-1-30750-151	--	SIL-2008-04	SIL	SPECIAL O-RING	29-Feb-08	16-Apr-08	1	A380	Titchfield, UK	K2523	--
568-1-30750-151	--	SIL-2008-05	SIL	INTRO OF NEW REMOVAL/INSTALI TOOL	29-Feb-08	--	0	A380	Titchfield, UK	K2523	--
568-1-30750-151	--	SIL-2009-09	SIL	A380 Time Line	06-Nov-09	--	0	A380	Titchfield, UK	K2523	--
568-1-30750-161	--	20124-28-001	SB	Improved Impeller Introduction	03-Dec-12	--	0	A380	Titchfield, UK	K2523	--
568-1-30751-100	--	MM28-26-02	MM	Fuel Pp Type 20124 & Canr Type 20125	30-Jun-04	04-Mar-05	1	A380	Titchfield, UK	K2523	--
568-1-30751-101	--	28-26-03	CMM	CANISTER TYPE 20125 (FEED)	31-Jan-05	03-Dec-13	6	A380	Titchfield, UK	K2523	-100 and -101 parts deleted - Rev 1
568-1-30751-101	--	MM28-26-02	MM	Fuel Pp Type 20124 & Canr Type 20125	30-Jun-04	04-Mar-05	1	A380	Titchfield, UK	K2523	--
568-1-30751-102	--	20125-28-001	SB	Introduction of New Strainer	31-Aug-11	--	0	A380	Titchfield, UK	K2523	--
568-1-30751-102	--	28-26-03	CMM	CANISTER TYPE 20125 (FEED)	31-Jan-05	03-Dec-13	6	A380	Titchfield, UK	K2523	-100 and -101 parts deleted - Rev 1
568-1-30751-103	--	20125-28-001	SB	Introduction of New Strainer	31-Aug-11	--	0	A380	Titchfield, UK	K2523	--
568-1-30751-103	--	28-26-03	CMM	CANISTER TYPE 20125 (FEED)	31-Jan-05	03-Dec-13	6	A380	Titchfield, UK	K2523	-100 and -101 parts deleted - Rev 1
568-1-30751-104	--	20125-28-001	SB	Introduction of New Strainer	31-Aug-11	--	0	A380	Titchfield, UK	K2523	--
568-1-30751-104	--	28-26-03	CMM	CANISTER TYPE 20125 (FEED)	31-Jan-05	03-Dec-13	6	A380	Titchfield, UK	K2523	-100 and -101 parts deleted - Rev 1

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
568-1-30751-105	--	28-26-03	CMM	CANISTER TYPE 20125 (FEED)	31-Jan-05	03-Dec-13	6	A380	Titchfield, UK	K2523	-100 and -101 parts deleted - Rev 1
568-1-30751-106	--	20125-28-002	SB	FUEL-FEED PUMP-INTRODUCTION OF NEW CANISTER	10-Apr-14	--	0	A380	Titchfield, UK	K2523	--
568-1-30751-106	--	28-26-03	CMM	CANISTER TYPE 20125 (FEED)	31-Jan-05	03-Dec-13	6	A380	Titchfield, UK	K2523	-100 and -101 parts deleted - Rev 1
568-1-30760-100	--	MM28-26-04	MM	Fuel Pp Type 20126 & Canr Type 20127	10-Jun-04	08-Mar-05	1	A380	Titchfield, UK	K2523	--
568-1-30760-101	--	20126-28-001	SB	Introduction of MK 200 Transfer Pump	31-Oct-12	--	0	A380	Titchfield, UK	K2523	--
568-1-30760-101	--	28-26-04	CMM	TRANSFER PUMP TYPE 20126	26-Oct-07	19-Feb-15	5	A380	Titchfield, UK	K2523	MK100 didnae go into service, the noo
568-1-30760-101	--	MM28-26-04	MM	Fuel Pp Type 20126 & Canr Type 20127	10-Jun-04	08-Mar-05	1	A380	Titchfield, UK	K2523	--
568-1-30760-101	--	SIL-2007-06	SIL	CAPACITOR REFORMING FOR A380 PUMPS	12-Sep-11	--	0	A380	Titchfield, UK	K2523	--
568-1-30760-101	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A322, A323, MRTT, A340	Titchfield, UK	K2523	--
568-1-30760-101	--	SIL-2009-09	SIL	A380 Time Line	06-Nov-09	--	0	A380	Titchfield, UK	K2523	--
568-1-30760-101	--	SIL-2010-04	SIL	FUEL - INTRODUCTION OF IMPROVED PUMP	--	--	0	A380	Titchfield, UK	K2523	CANCELLED
568-1-30760-102	--	20126-28-001	SB	Introduction of MK 200 Transfer Pump	31-Oct-12	--	0	A380	Titchfield, UK	K2523	--
568-1-30760-102	--	28-26-04	CMM	TRANSFER PUMP TYPE 20126	26-Oct-07	19-Feb-15	5	A380	Titchfield, UK	K2523	MK100 didnae go into service, the noo
568-1-30760-102	--	MM28-26-04	MM	Fuel Pp Type 20126 & Canr Type 20127	10-Jun-04	08-Mar-05	1	A380	Titchfield, UK	K2523	--
568-1-30760-102	--	SIL-2009-09	SIL	A380 Time Line	06-Nov-09	--	0	A380	Titchfield, UK	K2523	--
568-1-30760-102	--	SIL-2010-04	SIL	FUEL - INTRODUCTION OF IMPROVED PUMP	--	--	0	A380	Titchfield, UK	K2523	CANCELLED
568-1-30760-200	--	20126-28-001	SB	Introduction of MK 200 Transfer Pump	31-Oct-12	--	0	A380	Titchfield, UK	K2523	--
568-1-30760-200	--	20126-28-02	SB	Introduction of MK201 Pump	15-Sep-14	--	0	A380	Titchfield, UK	K2523	--
568-1-30760-200	--	20126-28-03	SB	Introduction of Amendment 2 MK200 Pumps	16-Jun-14	--	0	A380	Titchfield, UK	K2523	--
568-1-30760-200	--	28-26-16	CMM	Transfer Pump Mk200	12-Jun-13	23-Apr-19	2	A380	Titchfield, UK	K2523	--
568-1-30760-200	--	K2523-28-007	SIL	Introduction of Amdmt 2 Transfer Pump	28-Apr-14	--	0	A380	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
568-1-30760-201	--	20126-28-02	SB	Introduction of MK201 Pump	15-Sep-14	--	0	A380	Titchfield, UK	K2523	--
568-1-30760-201	--	28-26-16	CMM	Transfer Pump Mk200	12-Jun-13	23-Apr-19	2	A380	Titchfield, UK	K2523	--
568-1-30761-100	--	20127-28-001	SB	FUEL-TRANSFER PUMP-INTRODUCTION OF NEW CANISTER	03-Mar-14	--	0	A380	Titchfield, UK	K2523	--
568-1-30761-100	--	28-26-05	CMM	CANISTER TYPE 20127	02-Dec-04	09-Dec-13	2	A380	Titchfield, UK	K2523	--
568-1-30761-100	--	MM28-26-04	MM	Fuel Pp Type 20126 & Canr Type 20127	10-Jun-04	08-Mar-05	1	A380	Titchfield, UK	K2523	--
568-1-30761-102	--	20127-28-001	SB	FUEL-TRANSFER PUMP-INTRODUCTION OF NEW CANISTER	03-Mar-14	--	0	A380	Titchfield, UK	K2523	--
568-1-30761-102	--	28-26-05	CMM	CANISTER TYPE 20127	02-Dec-04	09-Dec-13	2	A380	Titchfield, UK	K2523	--
568-1-30770-100	--	MM28-26-06	MM	Fuel Pp Type 20128 & Canr Type 20129	30-Apr-04	08-Mar-05	1	A380	Titchfield, UK	K2523	DRAFT ONLY
568-1-30770-101	--	28-26-06	CMM	Trim Pump Type 20128	27-Jan-05	26-Jan-17	7	A380	Titchfield, UK	K2523	--
568-1-30770-101	--	SIL-2007-06	SIL	CAPACITOR REFORMING FOR A380 PUMPS	12-Sep-11	--	0	A380	Titchfield, UK	K2523	--
568-1-30770-101	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A340	Titchfield, UK	K2523	--
568-1-30770-102	--	28-26-06	CMM	Trim Pump Type 20128	27-Jan-05	26-Jan-17	7	A380	Titchfield, UK	K2523	--
568-1-30771-100	--	28-26-07	CMM	CANISTER TYPE 20129	29-Apr-05	24-Oct-07	1	A380	Titchfield, UK	K2523	--
568-1-30771-100	--	MM28-26-06	MM	Fuel Pp Type 20128 & Canr Type 20129	30-Apr-04	08-Mar-05	1	A380	Titchfield, UK	K2523	DRAFT ONLY
568-1-30780-100	--	28-26-08	CMM	PUMP TYPE 20026 (APU)	30-Sep-04	01-Dec-16	6	A380	Titchfield, UK	K2523	--
568-1-30780-100	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A340	Titchfield, UK	K2523	--
568-1-30780-100	--	SIL-2009-05	SIL	FUEL, APU PUMP, LIFE LIMITATION	17-Jul-09	--	0	A380	Titchfield, UK	K2523	--
568-1-30781-100	--	20027-28-01	SB	Introduction of New APU Canister	15-May-12	--	0	A380	Titchfield, UK	K2523	--
568-1-30781-100	--	28-26-09	CMM	APU PUMP CANISTER TYPE 20027	30-Sep-04	02-Mar-15	3	A380	Titchfield, UK	K2523	--
568-1-30781-101	--	20027-28-01	SB	Introduction of New APU Canister	15-May-12	--	0	A380	Titchfield, UK	K2523	--
568-1-30781-101	--	28-26-09	CMM	APU PUMP CANISTER TYPE 20027	30-Sep-04	02-Mar-15	3	A380	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
568-1-30781-200	--	20027-28-01	SB	Introduction of New APU Canister	15-May-12	--	0	A380	Titchfield, UK	K2523	--
568-1-30781-200	--	28-26-09	CMM	APU PUMP CANISTER TYPE 20027	30-Sep-04	02-Mar-15	3	A380	Titchfield, UK	K2523	--
568-1-30781-201	--	20027-28-01	SB	Introduction of New APU Canister	15-May-12	--	0	A380	Titchfield, UK	K2523	--
568-1-30781-201	--	28-26-09	CMM	APU PUMP CANISTER TYPE 20027	30-Sep-04	02-Mar-15	3	A380	Titchfield, UK	K2523	--
568-1-31155-001	--	28-20-71	CMM	PUMP TYPE 9912	--	--	0	BOEING 777	Titchfield, UK	K2523	CANCELLED
568-1-31212-100	--	28-20-55	CMM	TRANSFER PUMP HOUSING 20136 Mk100	--	--	0	BOEING 777-200LR	Titchfield, UK	K2523	DRAFT ONLY
568-1-31286-100	--	28-21-46	CMM	CANISTER TYPE 20137	16-Feb-06	--	0	A340-600	Titchfield, UK	K2523	BASIC MANUAL
568-1-31509-000	--	28-20-43++	CMM	Housing Assembly Type 9107Mk1, 9109Mk2, 9206Mk1 & 9603Mk1	01-Feb-94	10-Dec-13	8	BOEING 777	Titchfield, UK	K2523	--
568-8-20401	--	28-20-20+	CMM	FUEL BOOSTER PUMP	01-Apr-65	01-Jan-70	3	VC10	Titchfield, UK	K2523	--
568-8-21028	--	28-20-07+	CMM	Fuel Booster Pump SPE6210 Mk1	13-Nov-71	12-Apr-92	2	HS 748	Titchfield, UK	K2523	--
568-8-21049	--	38-10-2++	CMM	ELECTRICALLY DRIVEN WATER PUMP	28-Mar-66	15-Jul-68	5	BAC 1-11	Titchfield, UK	K2523	--
568-8-21099	--	38-10-2++	CMM	ELECTRICALLY DRIVEN WATER PUMP	28-Mar-66	15-Jul-68	5	BAC 1-11	Titchfield, UK	K2523	--
568-8-23402	--	28-20-17++	CMM	FUEL BOOSTER PUMP	01-Apr-70	01-Jul-94	6	STRIKEMASTER	Titchfield, UK	K2523	--
568-8-24220	--	28-20-08++	CMM	FUEL PUMP TYPE 6903 MK 2	06-Jan-81	--	0	MATADOR	Titchfield, UK	K2523	--
57-0001	--	28-43-31	CMM	MFLI OUTER ASSEMBLIES	24-Feb-99	12-Jan-09	5	A320, A321	Titchfield, UK	K2523	--
57-0001	--	SIL-CS-4-05	SIL	NON-PROCURABLE MFLIS	18-Jul-05	19-Apr-12	2	A319, A320, A321	Titchfield, UK	K2523	--
57-0004-1100	--	28-40-91	CMM	Magnetic Fluid Level Indicator (MFLI) Component Maintenance Manual	--	--	0	A321XLR	Titchfield, UK	K2523	TO BE WRITTEN
57-0005-1100	--	28-40-91	CMM	Magnetic Fluid Level Indicator (MFLI) Component Maintenance Manual	--	--	0	A321XLR	Titchfield, UK	K2523	TO BE WRITTEN
570-1-21273	--	28-20-1++	OM	FUEL BOOSTER PUMP AND HOUSING PACKAGE	30-Jun-64	29-Nov-69	3	BAC 1-11	Titchfield, UK	K2523	DUPLICATE ATA NO.
570-1-23550	--	28-23-02	CMM	PUMP ELEMENT	01-Oct-73	01-Aug-75	1	CONCORDE	Titchfield, UK	K2523	--
570-1-23591	--	28-09-04	CMM	ISOLATING CHAMBER	01-Aug-73	01-Jul-75	1	CONCORDE	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
570-1-23637	--	28-09-03+	CMM	ISOLATING CHAMBER TYPE 6815	15-Aug-73	28-Jul-75	2	CONCORDE	Titchfield, UK	K2523	--
570-1-23770	--	28-23-03	CMM	ISOLATING CHAMBER	01-Aug-73	01-Jul-75	2	CONCORDE	Titchfield, UK	K2523	--
570-1-23780	--	28-09-02	CMM	PUMP ELEMENT, TYPE 7007 MK1	26-Nov-73	28-Aug-75	1	CONCORDE	Titchfield, UK	K2523	--
570-1-23790	--	28-09-08	CMM	ISOLATING CHAMBER TYPE 7012	13-Aug-73	28-Jul-75	2	CONCORDE	Titchfield, UK	K2523	--
570-1-23820	--	28-09-07	CMM	ISOLATING CHAMBER	01-Aug-73	01-Jul-75	2	CONCORDE	Titchfield, UK	K2523	--
570-1-23840	--	28-09-05	CMM	MOUNTING PLATE	31-Aug-73	28-Jul-75	1	CONCORDE	Titchfield, UK	K2523	--
570-1-23870	--	28-23-04	CMM	ISOLATING CHAMBER	01-Aug-73	28-Jul-75	1	CONCORDE	Titchfield, UK	K2523	--
570-1-23893	--	28-09-01	CMM	PUMP ELEMENT	01-Sep-73	01-Mar-77	2	CONCORDE	Titchfield, UK	K2523	--
570-1-23893-000	--	28-09-01	CMM	PUMP ELEMENT	01-Sep-73	01-Mar-77	2	CONCORDE	Titchfield, UK	K2523	--
570-1-23898	--	28-23-01	CMM	PUMP ELEMENT	01-Oct-73	01-Mar-77	2	CONCORDE	Titchfield, UK	K2523	--
570-1-23900	--	28-09-06	CMM	MOUNTING PLATE TYPE 6823 MK2	28-Aug-73	28-Jul-75	1	CONCORDE	Titchfield, UK	K2523	--
570-1-24047	--	28-23-03	CMM	ISOLATING CHAMBER	01-Aug-73	01-Jul-75	2	CONCORDE	Titchfield, UK	K2523	--
570-8-21655	--	MM123	MM	--	--	--	0	CONCORDE	Titchfield, UK	K2523	--
570-8-21660	--	MM124	MM	--	--	--	0	CONCORDE	Titchfield, UK	K2523	--
570-8-21665	--	MM125	MM	--	--	--	0	CONCORDE	Titchfield, UK	K2523	--
570-8-21670	--	MM126	MM	--	--	--	0	CONCORDE	Titchfield, UK	K2523	--
570-8-21700	--	MM121	MM	--	--	--	0	CONCORDE	Titchfield, UK	K2523	--
570-8-21701	--	MM122	MM	--	--	--	0	CONCORDE	Titchfield, UK	K2523	--
570-8-23454	--	28-20-1++	OM	FUEL BOOSTER PUMP AND HOUSING PACKAGE	30-Jun-64	29-Nov-69	3	BAC 1-11	Titchfield, UK	K2523	DUPLICATE ATA NO.
570-8-23456	--	28-20-1++	OM	FUEL BOOSTER PUMP AND HOUSING PACKAGE	30-Jun-64	29-Nov-69	3	BAC 1-11	Titchfield, UK	K2523	DUPLICATE ATA NO.
5920262	--	28-13-05	OM	FLUID COOLER	01-Feb-71	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
6010002	--	52-60-14	CMM	AIRSTAIR ASSEMBLY (ELECTRIC)	29-May-92	20-Jul-95	2	F100	Titchfield, UK	K2523	--
6010002	--	6010002-52-1	SB	AIRSTAIR INSTALLATION-INTRO OF GEN. IMPROVMT PKGE	04-May-94	--	0	F100	Titchfield, UK	K2523	--
6010003	--	52-60-13	CMM	CARRIAGE ASSEMBLY	17-Jun-92	10-Jan-96	2	F100	Titchfield, UK	K2523	--
6010003	--	6010002-52-1	SB	AIRSTAIR INSTALLATION-INTRO OF GEN. IMPROVMT PKGE	04-May-94	--	0	F100	Titchfield, UK	K2523	--
6010006	--	52-60-16	CMM	AIRSCALATOR ASSEMBLIES	29-Jul-94	03-Jun-11	3	BAe ATP, JS61	Titchfield, UK	K2523	--
6010010	--	52-60-20	CMM	AIRSCALATOR ASSEMBLIES	01-Mar-92	03-Jun-11	8	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
6010010	--	D14624-52-1	SB	AIRSCALATOR - CRACKED TREAD SUPPORTS	02-Feb-95	--	0	BAE 146	Titchfield, UK	K2523	--
6010010	--	D14624-52-2	SB	AIRSCALATOR - WORN PIVOT BOLTS AND RELATED PARTS	16-May-95	21-Jul-97	1	BAE 146	Titchfield, UK	K2523	--
6010011	--	52-60-20	CMM	AIRSCALATOR ASSEMBLIES	01-Mar-92	03-Jun-11	8	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
6010011	--	D14624-52-1	SB	AIRSCALATOR - CRACKED TREAD SUPPORTS	02-Feb-95	--	0	BAE 146	Titchfield, UK	K2523	--
6010011	--	D14624-52-2	SB	AIRSCALATOR - WORN PIVOT BOLTS AND RELATED PARTS	16-May-95	21-Jul-97	1	BAE 146	Titchfield, UK	K2523	--
6010012	--	52-60-17	CMM	CARRIAGE ASSEMBLY	10-Nov-94	--	0	JS61	Titchfield, UK	K2523	--
6010017	--	52-60-16	CMM	AIRSCALATOR ASSEMBLIES	29-Jul-94	03-Jun-11	3	BAe ATP, JS61	Titchfield, UK	K2523	--
6010032	--	52-60-20	CMM	AIRSCALATOR ASSEMBLIES	01-Mar-92	03-Jun-11	8	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
6010032	--	6010032-52-1	SB	AIRSCALATOR - REPLACEMENT OF ELECTRICAL LINK	20-Jan-99	--	0	BAE 146	Titchfield, UK	K2523	--
6010032-1	--	52-60-20	CMM	AIRSCALATOR ASSEMBLIES	01-Mar-92	03-Jun-11	8	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
6010032-1	--	6010032-52-1	SB	AIRSCALATOR - REPLACEMENT OF ELECTRICAL LINK	20-Jan-99	--	0	BAE 146	Titchfield, UK	K2523	--
6010204	--	52-60-21	CMM	CARRIAGE ASSEMBLIES	01-Mar-92	20-Sep-18	11	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
6010204	--	D14624-52-2	SB	AIRSCALATOR - WORN PIVOT BOLTS AND RELATED PARTS	16-May-95	21-Jul-97	1	BAE 146	Titchfield, UK	K2523	--
6010204	--	SIL-PS-4-96	SIL	AIRSCALATOR CARRIAGE ASSY BANJO UNIONS - O-RING	06-Jun-96	--	0	Not Known	Titchfield, UK	K2523	--
6010626	--	24-09-53	CMM	ACTUATOR ASSEMBLY	31-Mar-93	--	0	F100	Titchfield, UK	K2523	EATON MANUAL (F100 A/STR)

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
6010905	--	52-60-24	CMM	OPERATING STRUT DAMPER ASSEMBLIES	01-Mar-92	03-Jun-11	7	BAE 146, BAe ATP, F100, JS61	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
60160	--	28-20-05++	CMM	Pressure Fuelling Shutoff Valve	28-Sep-11	18-Nov-16	1	BOEING 737	Titchfield, UK	K2523	--
6020203	--	52-60-12	CMM	PASSENGER DOOR HANDRAIL	01-Nov-91	03-Jun-11	2	JS41	Titchfield, UK	K2523	Supersedes PN 6020301
6020203	--	6020303-52-1	SB	PASSENGER DOOR HAND RAIL - INTERIM REINFORCEMENT	10-Jun-94	10-Jun-94	1	Not Known	Titchfield, UK	K2523	--
6020203	--	6020303-52-2	SB	PASSENGER DOOR HANDRAIL ASSEMBLY - NEW DESIGN	11-Oct-93	10-Dec-93	1	Not Known	Titchfield, UK	K2523	--
6020205	--	52-60-15	CMM	HANDRAIL ASSEMBLY	10-Feb-94	03-Jun-11	4	JS41	Titchfield, UK	K2523	--
6020205	--	6020205-52-1	SB	HANDRAIL ASSEMBLY - INCREASED GAS STRUT PRESSURE	30-Jan-96	28-Mar-96	1	Not Known	Titchfield, UK	K2523	--
6020207	--	52-60-19	CMM	HANDRAIL ASSEMBLY	07-May-96	03-Jun-11	1	JS41	Titchfield, UK	K2523	--
603AA01	--	38-20-1	OM	WATER TAP	01-Jun-60	--	0	Not Known	Titchfield, UK	K2523	--
603AA07	--	38-2-1	OM	URN TAP	01-Jul-59	--	0	Not Known	Titchfield, UK	K2523	SEE 38-2-1* FOR 502CB80
603AA08	--	25-30-01	OM	URN TAP	01-Aug-68	01-Jan-84	2	BAE 125, HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
603AA08	--	38-3-1	OM	URN TAP	01-Jun-59	01-Mar-62	3	Not Known	Titchfield, UK	K2523	--
603AA10	--	38-20-11	OM	WATER TAP	01-Jun-62	01-May-67	3	BAC 1-11	Titchfield, UK	K2523	--
603AA10-1	--	38-20-11	OM	WATER TAP	01-Jun-62	01-May-67	3	BAC 1-11	Titchfield, UK	K2523	--
603AA10-1A	--	38-20-11	OM	WATER TAP	01-Jun-62	01-May-67	3	BAC 1-11	Titchfield, UK	K2523	--
603AA10A	--	38-20-11	OM	WATER TAP	01-Jun-62	01-May-67	3	BAC 1-11	Titchfield, UK	K2523	--
603AB05	--	38-3-1	OM	URN TAP	01-Jun-59	01-Mar-62	3	Not Known	Titchfield, UK	K2523	--
603AB07	--	38-2-1	OM	URN TAP	01-Jul-59	--	0	Not Known	Titchfield, UK	K2523	SEE 38-2-1* FOR 502CB80
603AB08	--	38-4-1	OM	URN TAP	01-Jan-61	01-Nov-63	1	F27	Titchfield, UK	K2523	--
603AC01	--	38-3-1+	OM	URN TAP	01-Aug-59	01-Nov-63	1	F27	Titchfield, UK	K2523	--
603AD01	--	38-3-1+	OM	URN TAP	01-Aug-59	01-Nov-63	1	F27	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
603AF01	--	38-20-1	OM	WATER TAP	01-Jun-60	--	0	Not Known	Titchfield, UK	K2523	--
603AG01	--	38-20-51	CMM	SC DIAPHRAGM WATER TAPS	01-Mar-66	01-Sep-85	1	Not Known	Titchfield, UK	K2523	--
603CG01	--	38-20-51	CMM	SC DIAPHRAGM WATER TAPS	01-Mar-66	01-Sep-85	1	Not Known	Titchfield, UK	K2523	--
6040528	--	52-60-19	CMM	HANDRAIL ASSEMBLY	07-May-96	03-Jun-11	1	JS41	Titchfield, UK	K2523	--
6040529	--	52-60-19	CMM	HANDRAIL ASSEMBLY	07-May-96	03-Jun-11	1	JS41	Titchfield, UK	K2523	--
604AC09	--	79-10-21	OM	SOLENOID VALVE	20-Dec-66	--	0	TRIDENT	Titchfield, UK	K2523	--
604AD09	--	79-20-1	OM	SOLENOID VALVE	01-Nov-69	--	0	Not Known	Titchfield, UK	K2523	--
604BA07	--	38-4-1+	OM	WATER TAP	01-May-59	01-Mar-62	3	Not Known	Titchfield, UK	K2523	--
604BA11	--	38-10-2	OM	MW SPV	01-Dec-60	13-May-11	3	BAe 748	Titchfield, UK	K2523	for 208AA92 see 38-10-2+
604BB07	--	38-4-1+	OM	WATER TAP	01-May-59	01-Mar-62	3	Not Known	Titchfield, UK	K2523	--
604BB11	--	38-10-2	OM	MW SPV	01-Dec-60	13-May-11	3	BAe 748	Titchfield, UK	K2523	for 208AA92 see 38-10-2+
604CA12	--	38-10-24	OM	MANUALLY OPERATED M/WAY SPV	01-Nov-71	--	0	Not Known	Titchfield, UK	K2523	--
604CA12	--	38-10-24+	OM	WATER VALVE	01-Feb-67	01-Sep-71	1	Not Known	Titchfield, UK	K2523	*EX-SAUNDERS
605CR07	--	38-09-41	OM	WATER VALVE	21-Jan-65	13-May-11	1	BAe 748	Titchfield, UK	K2523	--
606BA52	--	38-10-58	OM	WATER VALVE	01-Apr-64	01-Mar-68	2	BAC 1-11	Titchfield, UK	K2523	--
606BR01	--	38-10-7	OM	WATER VALVE	01-Jun-62	--	0	Not Known	Titchfield, UK	K2523	--
606CA52	--	38-10-58	OM	WATER VALVE	01-Apr-64	01-Mar-68	2	BAC 1-11	Titchfield, UK	K2523	--
60B12	--	28-22-82	OM	SPV	29-Mar-99	27-Jul-05	1	AV8A	Titchfield, UK	K2523	--
612-1-39290	--	77-30-06	CMM	ENGINE ALARM AMPLIFIER	01-Oct-70	01-Mar-77	0	--	Titchfield, UK	K2523	--
612-1-39401-002	--	77-12-01	CMM	SPEED PROBE	01-Jun-70	05-May-79	4	RB211-22B, RB211-524	Titchfield, UK	K2523	--
614-1-03460	--	L33-1-846	SB	Improved insulation of battery stowage.	29-Mar-71	--	0	BAC 1-11, F27, F28, HERALD, HS 748	Titchfield, UK	K2523	--

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
614-1-03460-001	--	33-50-02	CMM	EMERGENCY LIGHTING UNIT MK2	--	21-Sep-73	1	HS 748	Titchfield, UK	K2523	--
614-1-03470	--	33-50-01	CMM	EXIT LIGHT UNIT MK1	--	21-Sep-73	1	ARGOSY, HS 748	Titchfield, UK	K2523	--
614-1-03470	--	L33-1-846	SB	Improved insulation of battery stowage.	29-Mar-71	--	0	BAC 1-11, F27, F28, HERALD, HS 748	Titchfield, UK	K2523	--
614-1-03470-001	--	33-50-01	CMM	EXIT LIGHT UNIT MK1	--	21-Sep-73	1	ARGOSY, HS 748	Titchfield, UK	K2523	--
6210C	--	28-22-60	OM	MW FUEL VALVE	01-Feb-74	--	0	Not Known	Titchfield, UK	K2523	--
6320786	--	24-13-01	OM	MK20 POD EQUIPMENT	01-Jun-70	--	0	Not Known	Titchfield, UK	K2523	--
64-1085-2	--	73-1-1	OM	--	15-Sep-59	--	0	DOUGLAS DC8	Titchfield, UK	K2523	BASIC MANUAL
64-1119-2	--	73-10-3	OM	ENG MOUNTED FUEL BOOST PUMP	15-Apr-66	28-May-99	5	DOUGLAS DC10, DOUGLAS DC8	Titchfield, UK	K2523	Nash Pump
64-1119-2	--	73-2	SB	ENGINE FUEL AND CONTROL - FUEL BOOST PUMP INSTALL RESTRICTION PLUGS	15-Mar-62	--	0	DOUGLAS DC8, DOUGLAS DC9	Titchfield, UK	K2523	--
64-1119-2	--	73-3	SB	ENGINE FUEL AND CONTROL - FUEL BOOST PUMP INSTALL BRACKET BEARING ASSEMBLY SPACER AND/OR SUMAC	01-Oct-64	--	0	DOUGLAS DC8, DOUGLAS DC9	Titchfield, UK	K2523	--
64-1119-2	--	73-4	SB	ENGINE FUEL AND CONTROL - FUEL BOOST PUMP ENLARGE RESTRICTION HOLES OR REMOVE RESTRICTION PLUGS	15-Nov-67	--	0	DOUGLAS DC8, DOUGLAS DC9	Titchfield, UK	K2523	--
64-1119-2	--	73-5	SB	ENGINE FUEL AND CONTROL - FUEL BOOST PUMP INSTALL IMPROVED COUPLING	15-Jan-77	--	0	DOUGLAS DC8, DOUGLAS DC9	Titchfield, UK	K2523	--
64-1119-3	--	73-10-3	OM	ENG MOUNTED FUEL BOOST PUMP	15-Apr-66	28-May-99	5	DOUGLAS DC10, DOUGLAS DC8	Titchfield, UK	K2523	Nash Pump
64-1119-3	--	73-2	SB	ENGINE FUEL AND CONTROL - FUEL BOOST PUMP INSTALL RESTRICTION PLUGS	15-Mar-62	--	0	DOUGLAS DC8, DOUGLAS DC9	Titchfield, UK	K2523	--
64-1119-3	--	73-3	SB	ENGINE FUEL AND CONTROL - FUEL BOOST PUMP INSTALL BRACKET BEARING ASSEMBLY SPACER AND/OR SUMAC	01-Oct-64	--	0	DOUGLAS DC8, DOUGLAS DC9	Titchfield, UK	K2523	--
64-1119-3	--	73-4	SB	ENGINE FUEL AND CONTROL - FUEL BOOST PUMP ENLARGE RESTRICTION HOLES OR REMOVE RESTRICTION PLUGS	15-Nov-67	--	0	DOUGLAS DC8, DOUGLAS DC9	Titchfield, UK	K2523	--
64-1119-3	--	73-5	SB	ENGINE FUEL AND CONTROL - FUEL BOOST PUMP INSTALL IMPROVED COUPLING	15-Jan-77	--	0	DOUGLAS DC8, DOUGLAS DC9	Titchfield, UK	K2523	--
64-1119-4	--	73-10-3	OM	ENG MOUNTED FUEL BOOST PUMP	15-Apr-66	28-May-99	5	DOUGLAS DC10, DOUGLAS DC8	Titchfield, UK	K2523	Nash Pump
64-1119-4	--	73-2	SB	ENGINE FUEL AND CONTROL - FUEL BOOST PUMP INSTALL RESTRICTION PLUGS	15-Mar-62	--	0	DOUGLAS DC8, DOUGLAS DC9	Titchfield, UK	K2523	--
64-1119-4	--	73-3	SB	ENGINE FUEL AND CONTROL - FUEL BOOST PUMP INSTALL BRACKET BEARING ASSEMBLY SPACER AND/OR SUMAC	01-Oct-64	--	0	DOUGLAS DC8, DOUGLAS DC9	Titchfield, UK	K2523	--
64-1119-4	--	73-4	SB	ENGINE FUEL AND CONTROL - FUEL BOOST PUMP ENLARGE RESTRICTION HOLES OR REMOVE RESTRICTION PLUGS	15-Nov-67	--	0	DOUGLAS DC8, DOUGLAS DC9	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
64-1119-4	--	73-5	SB	ENGINE FUEL AND CONTROL - FUEL BOOST PUMP INSTALL IMPROVED COUPLING	15-Jan-77	--	0	DOUGLAS DC8, DOUGLAS DC9	Titchfield, UK	K2523	--
64-1119-5	--	73-10-3	OM	ENG MOUNTED FUEL BOOST PUMP	15-Apr-66	28-May-99	5	DOUGLAS DC10, DOUGLAS DC8	Titchfield, UK	K2523	Nash Pump
64-1119-5	--	73-2	SB	ENGINE FUEL AND CONTROL - FUEL BOOST PUMP INSTALL RESTRICTION PLUGS	15-Mar-62	--	0	DOUGLAS DC8, DOUGLAS DC9	Titchfield, UK	K2523	--
64-1119-5	--	73-3	SB	ENGINE FUEL AND CONTROL - FUEL BOOST PUMP INSTALL BRACKET BEARING ASSEMBLY SPACER AND/OR WASHER	01-Oct-64	--	0	DOUGLAS DC8, DOUGLAS DC9	Titchfield, UK	K2523	--
64-1119-5	--	73-4	SB	ENGINE FUEL AND CONTROL - FUEL BOOST PUMP ENLARGE RESTRICTION HOLES OR REMOVE RESTRICTION PLUGS	15-Nov-67	--	0	DOUGLAS DC8, DOUGLAS DC9	Titchfield, UK	K2523	--
64-1119-5	--	73-5	SB	ENGINE FUEL AND CONTROL - FUEL BOOST PUMP INSTALL IMPROVED COUPLING	15-Jan-77	--	0	DOUGLAS DC8, DOUGLAS DC9	Titchfield, UK	K2523	--
6508295	--	28-13-04	OM	MK20 POD HOSEASSY,RECEP CPLG&DROG	01-Jun-70	--	0	Not Known	Titchfield, UK	K2523	--
6508390	--	28-13-04	OM	MK20 POD HOSEASSY,RECEP CPLG&DROG	01-Jun-70	--	0	Not Known	Titchfield, UK	K2523	--
6508391	--	28-13-04	OM	MK20 POD HOSEASSY,RECEP CPLG&DROG	01-Jun-70	--	0	Not Known	Titchfield, UK	K2523	--
6508541	--	28-87-73	CMM	DROGUE ASSY	01-Nov-88	--	0	Not Known	Titchfield, UK	K2523	MIL SYSTEMS DIV
65-5085-2	--	03-10EN-20(D)	OM	FUEL SYSTEM BOOST PUMP	20-Sep-66	--	0	CHEVALINE	Titchfield, UK	K2523	--
65-5093	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A320	Titchfield, UK	K2523	--
65-5093-4	--	28-20-1+	CMM	NASH FUEL PUMP & VOLUTE ASSY	01-Sep-68	27-Nov-06	6	BOEING 717, DOUGLAS DC9, MD-80, MD-90	Titchfield, UK	K2523	TR2 issued 12/01/2001
65-5093-4	--	K2523-28-001	SIL	PREMATURE RELEASE OF CMM	21-Feb-11	--	0	DOUGLAS DC9, MD-80, MD-90	Titchfield, UK	K2523	--
65-5094-1	--	28-20-1+	CMM	NASH FUEL PUMP & VOLUTE ASSY	01-Sep-68	27-Nov-06	6	BOEING 717, DOUGLAS DC9, MD-80, MD-90	Titchfield, UK	K2523	TR2 issued 12/01/2001
65-5094-1	--	K2523-28-001	SIL	PREMATURE RELEASE OF CMM	21-Feb-11	--	0	DOUGLAS DC9, MD-80, MD-90	Titchfield, UK	K2523	--
65-5094-2	--	28-20-1+	CMM	NASH FUEL PUMP & VOLUTE ASSY	01-Sep-68	27-Nov-06	6	BOEING 717, DOUGLAS DC9, MD-80, MD-90	Titchfield, UK	K2523	TR2 issued 12/01/2001
65-5094-2	--	K2523-28-001	SIL	PREMATURE RELEASE OF CMM	21-Feb-11	--	0	DOUGLAS DC9, MD-80, MD-90	Titchfield, UK	K2523	--
65-5094-3	--	28-20-1+	CMM	NASH FUEL PUMP & VOLUTE ASSY	01-Sep-68	27-Nov-06	6	BOEING 717, DOUGLAS DC9, MD-80, MD-90	Titchfield, UK	K2523	TR2 issued 12/01/2001
65-5094-3	--	K2523-28-001	SIL	PREMATURE RELEASE OF CMM	21-Feb-11	--	0	DOUGLAS DC9, MD-80, MD-90	Titchfield, UK	K2523	--
65-5094-3	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A320	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
65-5095-1	--	28-20-1+	CMM	NASH FUEL PUMP & VOLUTE ASSY	01-Sep-68	27-Nov-06	6	BOEING 717, DOUGLAS DC9, MD-80, MD-90	Titchfield, UK	K2523	TR2 issued 12/01/2001
65-5095-1	--	K2523-28-001	SIL	PREMATURE RELEASE OF CMM	21-Feb-11	--	0	DOUGLAS DC9, MD-80, MD-90	Titchfield, UK	K2523	--
65-5095-2	--	28-20-3	CMM	NASH SERIES VOLUTE ASSY	15-Dec-78	30-Nov-06	2	BOEING 717, DOUGLAS DC9, MD-80	Titchfield, UK	K2523	--
65-5095-2	--	28-20-3	CMM	NASH SERIES VOLUTE ASSY	15-Dec-78	30-Nov-06	2	BOEING 717, DOUGLAS DC9, MD-80	Titchfield, UK	K2523	--
65-5095-2	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A340	Titchfield, UK	K2523	--
65-5095-3	--	28-20-1+	CMM	NASH FUEL PUMP & VOLUTE ASSY	01-Sep-68	27-Nov-06	6	BOEING 717, DOUGLAS DC9, MD-80, MD-90	Titchfield, UK	K2523	TR2 issued 12/01/2001
65-5095-3	--	K2523-28-001	SIL	PREMATURE RELEASE OF CMM	21-Feb-11	--	0	DOUGLAS DC9, MD-80, MD-90	Titchfield, UK	K2523	--
65-5095-4	--	28-20-3	CMM	NASH SERIES VOLUTE ASSY	15-Dec-78	30-Nov-06	2	BOEING 717, DOUGLAS DC9, MD-80	Titchfield, UK	K2523	--
65-5095-4	--	28-20-3	CMM	NASH SERIES VOLUTE ASSY	15-Dec-78	30-Nov-06	2	BOEING 717, DOUGLAS DC9, MD-80	Titchfield, UK	K2523	--
65-5106-4	--	28-20-1+	CMM	NASH FUEL PUMP & VOLUTE ASSY	01-Sep-68	27-Nov-06	6	BOEING 717, DOUGLAS DC9, MD-80, MD-90	Titchfield, UK	K2523	TR2 issued 12/01/2001
65-5107-1	--	28-20-2+++	CMM	VOLUTE SERIES	15-Sep-67	30-Nov-06	3	BOEING 717, MD-80	Titchfield, UK	K2523	--
65-5107-1	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A340	Titchfield, UK	K2523	--
65-5107-2	--	28-20-2+++	CMM	VOLUTE SERIES	15-Sep-67	30-Nov-06	3	BOEING 717, MD-80	Titchfield, UK	K2523	--
67-0001	--	28-40-52	CMM	MK 15 FLOAT SWITCH	07-Feb-08	07-Feb-08	0	US101	Titchfield, UK	K2523	--
67-0002	--	28-40-52	CMM	MK 15 FLOAT SWITCH	07-Feb-08	07-Feb-08	0	US101	Titchfield, UK	K2523	--
67-0003	--	28-40-35	CMM	MK15 FLOAT SWITCH	12-Jan-99	04-Mar-09	4	EH101	Titchfield, UK	K2523	--
68-0001	--	28-42-01	ACMM	SWITCH-PRESSURE	05-Dec-07	12-Jun-15	4	Boeing 777X, BOEING 787	Titchfield, UK	K2523	--
68-0001	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320-MRTT, A340	Titchfield, UK	K2523	--
68-0002	--	28-42-01	ACMM	SWITCH-PRESSURE	05-Dec-07	12-Jun-15	4	Boeing 777X, BOEING 787	Titchfield, UK	K2523	--
68-0004	--	28-46-15	CMM	LEVEL AND TEMPERATURE SENSORS	01-Apr-86	20-Feb-12	9	A319, A320, A321, A330, A340, N250	Titchfield, UK	K2523	--
68-0004	--	SIL-2009-01	SIL	TEMPERATURE SENSOR, REPLACEMENT	12-Mar-09	--	0	A319, A320, A321, A330, A340	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
68-0005	--	28-46-15	CMM	LEVEL AND TEMPERATURE SENSORS	01-Apr-86	20-Feb-12	9	A319, A320, A321, A330, A340, N250	Titchfield, UK	K2523	--
68-0005	--	SIL-2009-01	SIL	TEMPERATURE SENSOR, REPLACEMENT	12-Mar-09	--	0	A319, A320, A321, A330, A340	Titchfield, UK	K2523	--
68-0008	--	28-46-15	CMM	LEVEL AND TEMPERATURE SENSORS	01-Apr-86	20-Feb-12	9	A319, A320, A321, A330, A340, N250	Titchfield, UK	K2523	--
68-0008	--	K2523-28-002	SIL	New Level Sensor	05-Mar-12	--	0	A318, A319, A320, A321	Titchfield, UK	K2523	--
6805011	--	FR18-87	TDS	NOZZLE ADAPTOR	01-May-87	02-Sep-03	1	NIMROD MRA4, TORNADO	Titchfield, UK	K2523	--
6805615	--	FR-ACD-7	TDS	NOZZLE TESTER	01-Apr-90	--	0	TORNADO	Titchfield, UK	K2523	--
700-1-12170	--	OSM707	CMM	Control Unit Mk 8	--	01-Jul-73	1	CANBERRA, HUNTER, LIGHTNING, SABRE	Titchfield, UK	K2523	*OUT OF PRINT
700-1-12200	--	OSM248	CMM	OVERVOLTAGE PROTECTION UNIT	17-Oct-68	--	0	JETSTREAM	Titchfield, UK	K2523	BASIC MANUAL
700-1-12260	--	OSM249	CMM	POWER FAILURE WARNING UNIT	31-Oct-68	--	0	JETSTREAM	Titchfield, UK	K2523	BASIC MANUAL
700-1-12620	--	OSM242	CMM	VOLTAGE REGULATOR	20-Jun-69	--	0	JETSTREAM	Titchfield, UK	K2523	BASIC MANUAL
700-1-12630	--	OSM244	CMM	UNDER VOLTAGE PROTECTION UNIT	24-Oct-68	22-Dec-14	1	JETSTREAM	Titchfield, UK	K2523	BASIC MANUAL
700-1-12650	--	OSM250	CMM	BUSBAR DIODE UNIT	22-Oct-68	--	0	JETSTREAM	Titchfield, UK	K2523	--
700-1-12680	--	24-20-13	OM	PROTECTION UNITS	24-May-74	--	0	JETSTREAM	Titchfield, UK	K2523	2ND EDITION
700-1-12801	--	24-40-01	CMM	OVERVOLTAGE UNIT	26-Mar-68	18-Apr-74	1	BAC 1-11	Titchfield, UK	K2523	--
700-1-12953	--	24-20-14	CMM	ADAPTOR UNIT	30-Apr-74	--	0	JETSTREAM	Titchfield, UK	K2523	BASIC MANUAL
700-1-12970	--	24-30-02	CMM	VOLTAGE REGULATOR	13-Mar-74	09-Jul-15	1	JETSTREAM	Titchfield, UK	K2523	BASIC MANUAL
700-1-12980	--	24-53-01	CMM	U/VOLTAGE UNIT	--	14-Jun-78	1	BAC 1-11	Titchfield, UK	K2523	--
700-1-15670	--	24-20-13	OM	PROTECTION UNITS	24-May-74	--	0	JETSTREAM	Titchfield, UK	K2523	2ND EDITION
700-1-18912-000	--	24-22-22	CMM	ENGINE SPEED UNIT	27-Nov-72	15-May-78	3	CONCORDE	Titchfield, UK	K2523	--
700-1-19030-000	--	24-30-02	CMM	VOLTAGE REGULATOR	13-Mar-74	09-Jul-15	1	JETSTREAM	Titchfield, UK	K2523	BASIC MANUAL
700-1-19101-000	--	24-40-02	CMM	GROUND POWER PROTECTION UNIT	10-Oct-73	12-Sep-77	2	CONCORDE	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
710BA12	--	28-09-22	OM	RELIEF VALVE	01-Dec-62	--	0	Not Known	Titchfield, UK	K2523	--
710CA12	--	28-09-57	OM	PRV	01-Dec-69	--	0	Not Known	Titchfield, UK	K2523	--
710CA17	--	28-20-75	OM	PRV	01-Apr-66	01-Apr-68	2	Not Known	Titchfield, UK	K2523	--
710CA28-1	--	28-20-78	OM	FLAPTYPE NRV	--	01-Jun-87	2	F100, F28, F70	Titchfield, UK	K2523	--
710GA10	--	28-20-73+	OM	NRV	--	01-Jan-71	2	Not Known	Titchfield, UK	K2523	*EX-SAUNDERS
712BA16-2	--	28-22-24	OM	NRV PR	01-Jul-62	01-Apr-63	1	Not Known	Titchfield, UK	K2523	SEE 28-22-24* FOR 508A*
712FA10	--	28-09-21	OM	NRV	01-Jul-62	01-Jan-65	1	Not Known	Titchfield, UK	K2523	--
712FA10-1	--	28-09-21	OM	NRV	01-Jul-62	01-Jan-65	1	Not Known	Titchfield, UK	K2523	--
712FA21	--	28-21-23	OM	NRV,PR	01-Jul-67	01-Sep-71	1	Not Known	Titchfield, UK	K2523	--
714BA01	--	28-21-21	OM	RELIEF VALVE	01-May-64	--	0	Not Known	Titchfield, UK	K2523	--
716BA11	--	28-2-1	OM	NRV	01-Jun-60	01-Jul-62	1	Not Known	Titchfield, UK	K2523	SEE 28-2-1** FOR NS1205
716BA11-1	--	28-2-1	OM	NRV	01-Jun-60	01-Jul-62	1	Not Known	Titchfield, UK	K2523	SEE 28-2-1** FOR NS1205
716CA20	--	28-20-68+	OM	FLOW-CONTROL VALVE	01-Feb-68	01-May-68	1	Not Known	Titchfield, UK	K2523	*EX-SAUNDERS
716CA21	--	28-21-67	OM	FLOW-CONTROL VALVE	01-Jul-68	--	0	Not Known	Titchfield, UK	K2523	--
716CA22	--	28-21-68	OM	FLOW-CONTROL VALVE	01-Jul-68	--	0	Not Known	Titchfield, UK	K2523	--
716GA10	--	28-21-22	CMM	BY-PASS VALVE	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
7202040	--	28-09-52	CMM	PIPE CONNECTOR	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
720PM05-1DA	--	28-10-12	OM	MOTORISED FUEL TRANSFER VALVE	01-May-63	17-Nov-08	5	BAC 1-11	Titchfield, UK	K2523	--
720SM05-1DA	--	28-10-12	OM	MOTORISED FUEL TRANSFER VALVE	01-May-63	17-Nov-08	5	BAC 1-11	Titchfield, UK	K2523	--
7214170	--	28-30-39	CMM	HTP ADAPTOR & SEALING COVER	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
7214175	--	28-30-39	CMM	HTP ADAPTOR & SEALING COVER	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
7401075	--	28-20-40	CMM	HTP PRV	--	--	0	Not Known	Titchfield, UK	K2523	--
75-0001-1100	--	28-22-99	CMM	CONTROLLER, OVERRIDE/JETTISON PUMP	08-May-08	29-Oct-18	9	BOEING 787	Titchfield, UK	K2523	Turbo Power Systems: was 24-20-01
75-0001-1200	--	28-22-99	CMM	CONTROLLER, OVERRIDE/JETTISON PUMP	08-May-08	29-Oct-18	9	BOEING 787	Titchfield, UK	K2523	Turbo Power Systems: was 24-20-01
75-0001-1300	--	28-22-99	CMM	CONTROLLER, OVERRIDE/JETTISON PUMP	08-May-08	29-Oct-18	9	BOEING 787	Titchfield, UK	K2523	Turbo Power Systems: was 24-20-01
75-0001-1400	--	28-22-99	CMM	CONTROLLER, OVERRIDE/JETTISON PUMP	08-May-08	29-Oct-18	9	BOEING 787	Titchfield, UK	K2523	Turbo Power Systems: was 24-20-01
75-0001-1400	--	75-0001-28-001	SB	Introduction of New Motor Controller	17-Dec-15	--	0	BOEING 787	Titchfield, UK	K2523	--
75-0001-1500	--	28-22-99	CMM	CONTROLLER, OVERRIDE/JETTISON PUMP	08-May-08	29-Oct-18	9	BOEING 787	Titchfield, UK	K2523	Turbo Power Systems: was 24-20-01
75-0001-1500	--	75-0001-28-001	SB	Introduction of New Motor Controller	17-Dec-15	--	0	BOEING 787	Titchfield, UK	K2523	--
75-0026	--	PSD-365	CMM	Firmware reprogramming	03-Feb-21	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
75-0026	--	PSD-368	CMM	FIRMWARE REPROGRAM	21-Apr-21	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
754-1-	--	75-31-08	CMM	BLEED CONTROL VALVE	--	--	0	LYNX	Titchfield, UK	K2523	--
754-1-15910	--	78-30-11	CMM	SELECTOR SEQUENCE VALVE	01-Apr-65	24-Jan-00	10	BAC 1-11, NIMROD, SPEY	Titchfield, UK	K2523	--
754-1-15910	--	RT78-18-2887	SB	Selector Valve - Increased selector piston locking load.	16-Oct-98	24-May-99	1	SPEY	Titchfield, UK	K2523	--
754-1-15910-001	--	78-30-11	CMM	SELECTOR SEQUENCE VALVE	01-Apr-65	24-Jan-00	10	BAC 1-11, NIMROD, SPEY	Titchfield, UK	K2523	--
754-1-16048	--	78-30-1	CMM	REVERSE THRUST, TWIN RAM	01-Apr-65	18-Aug-98	13	BAC 1-11, NIMROD, SPEY	Titchfield, UK	K2523	--
754-1-20021-000	--	36-20-01	CMM	PRESSURE SWITCH	09-Jun-70	--	0	BAC 1-11	Titchfield, UK	K2523	--
754-1-24171	--	83-20-01	CMM	AUXILIARY GEARBOX	01-Jun-81	--	0	AV8A, HARRIER, MATADOR	Titchfield, UK	K2523	Internal Issue
754-1-24172	--	83-20-02	CMM	BEVEL GEARBOX	03-Jun-81	12-Jul-12	1	AV8A, HARRIER, MATADOR	Titchfield, UK	K2523	Internal Issue
754-1-24517	--	21-30-02++	CMM	PRV	01-May-81	--	0	MATADOR	Titchfield, UK	K2523	--
754-1-27129	--	24-10-00	CMM	STARTER	01-May-64	01-May-08	52	BAC 1-11	Titchfield, UK	K2523	--
754-1-27130	--	24-10-00	CMM	STARTER	01-May-64	01-May-08	52	BAC 1-11	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
754-1-28826	--	75-31-02	CMM	INLET GUIDE VANE CONTROL RAM	01-Aug-70	30-May-86	16	RB211-22B	Titchfield, UK	K2523	RB211-22B RR support withdrawn
754-1-29412	--	78-31-00	CMM	PNEUMATIC DRIVE UNIT	01-Sep-74	30-Dec-82	14	BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	--
754-1-29412	--	PD78-18-2421	SB	Bulkhead Mounted Vent Valve - Introduction of improved operating lever assembly.	01-Aug-78	--	0	BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-1-29412	--	PD78-19-2499	SB	Bulkhead Mounted Vent Valve - Introduction of centralising shims at operating lever assembly.	19-Nov-79	--	0	BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-1-30071	--	75-31-01	CMM	INLET GUIDE VANE CONTROL RAM	01-Aug-70	01-Nov-89	19	RB211-22B	Titchfield, UK	K2523	RB211-22B - not supported by RR
754-1-30071	--	IGV75-001-2145	SB	Master Ram and Control - Introduction of improved connecting rod	25-Apr-72	22-May-72	1	LOCKHEED L1011, RB211, TRISTAR L1011	Titchfield, UK	K2523	--
754-1-30071	--	IGV75-010-2119	SB	Master Ram and Control - Introduction of MR 102 Mk 2 featuring a strengthened front casing	20-Dec-72	--	0	LOCKHEED L1011, RB211	Titchfield, UK	K2523	--
754-1-30071-003	--	75-31-05	CMM	INLET GUIDE VANE CONTROL RAM	01-Nov-76	30-Nov-89	9	RB211-22B	Titchfield, UK	K2523	*RB211-22B not supported by RR
754-1-30175	--	75-31-04	CMM	INLET GUIDE VANE CONTROL RAM	01-Feb-73	18-Jun-97	15	RB211-22B	Titchfield, UK	K2523	Rolls Royce support withdrawn
754-1-30176	--	75-31-03	CMM	INLET GUIDE VANE CONTROL RAM	01-Feb-73	30-Nov-89	15	RB211-22B	Titchfield, UK	K2523	--
754-1-30176-004	--	75-31-06	CMM	INLET GUIDE VANE CONTROL RAM	01-Nov-76	10-Jul-97	11	RB211-22B	Titchfield, UK	K2523	*RB211-22B not supported by RR
754-1-30176-005	--	75-31-01	CMM	INLET GUIDE VANE CONTROL RAM	01-Aug-70	01-Nov-89	19	RB211-22B	Titchfield, UK	K2523	RB211-22B - not supported by RR
754-1-30176-008	--	75-31-06	CMM	INLET GUIDE VANE CONTROL RAM	01-Nov-76	10-Jul-97	11	RB211-22B	Titchfield, UK	K2523	*RB211-22B not supported by RR
754-1-30307-002	--	73-21-14	CMM	P4/PF PRESSURE RATIO SWITCHES	01-Feb-73	30-Nov-89	13	RB211-22B	Titchfield, UK	K2523	*RB211-22B not supported by RR
754-1-30307-003	--	73-21-14	CMM	P4/PF PRESSURE RATIO SWITCHES	01-Feb-73	30-Nov-89	13	RB211-22B	Titchfield, UK	K2523	*RB211-22B not supported by RR
754-1-30574-005	--	PD78-31	SB	Pneumatic Drive Unit - Minor design changes.	14-Jul-86	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-1-30903-005	--	78-31-00	CMM	PNEUMATIC DRIVE UNIT	01-Sep-74	30-Dec-82	14	BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	--
754-1-30903-005	--	PD78-26-2591	SB	Air Motor Servo Unit - Introduction of new seals and revised output shaft seal arrangement.	01-Feb-82	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-1-30912-002	--	78-31-00	CMM	PNEUMATIC DRIVE UNIT	01-Sep-74	30-Dec-82	14	BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	--
754-1-30912-002	--	PD78-23-2502	SB	PR & SOV - Introduction of changes to simplify and improve reliability of indicator.	26-Jan-82	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-1-30912-002	--	PD78-24-2583	SB	PR & SOV - Introduction of corrosion resistant solenoid.	22-Jan-82	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
754-1-30912-002	--	PD78-25-2584	SB	PR & SOV - Introduction of changes to overcome unit instability.	22-Jan-82	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-1-30912-002	--	PD78-27-2599	SB	PR & SOV - Introduction of changes to overcome possibility of valve opening at take off power.	02-Feb-82	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-1-30912-002	--	PD78-29-2618	SB	PRV & SOV - Introduction of new piston ring configuration.	10-Feb-82	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-1-30912-003	--	78-31-00	CMM	PNEUMATIC DRIVE UNIT	01-Sep-74	30-Dec-82	14	BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	--
754-1-30912-003	--	PD78-23-2502	SB	PR & SOV - Introduction of changes to simplify and improve reliability of indicator.	26-Jan-82	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-1-30912-004	--	PD78-23-2502	SB	PR & SOV - Introduction of changes to simplify and improve reliability of indicator.	26-Jan-82	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-1-30912-004	--	PD78-24-2583	SB	PR & SOV - Introduction of corrosion resistant solenoid.	22-Jan-82	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-1-30912-004	--	PD78-25-2584	SB	PR & SOV - Introduction of changes to overcome unit instability.	22-Jan-82	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-1-30912-004	--	PD78-27-2599	SB	PR & SOV - Introduction of changes to overcome possibility of valve opening at take off power.	02-Feb-82	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-1-30912-004	--	PD78-29-2618	SB	PRV & SOV - Introduction of new piston ring configuration.	10-Feb-82	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-1-31699	--	OSM488S	CMM	ACTUATOR	01-Jul-81	--	0	MATADOR	Titchfield, UK	K2523	NOT ISSUED
754-1-32148	--	75-33-02	CMM	AIRFLOW CONTROL UNIT TYPE A001	01-Jun-76	01-Nov-94	17	RB211-524	Titchfield, UK	K2523	--
754-1-32148	--	75-33-08	CMM	AIRFLOW CONTROL UNIT	01-Sep-81	01-Nov-94	8	RB211-524	Titchfield, UK	K2523	--
754-1-32148-000	--	IGV75-030-2355	SB	Airflow Control Unit - Introduction of new bleed valve control unit with strengthened mounting lug	17-Nov-76	17-Jun-77	1	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-000	--	IGV75-034-2382	SB	Airflow Control Unit - Introduction of manifold and fluidic element assembly using silver copper bra	17-Nov-76	17-Jun-77	1	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-000	--	IGV75-042-2414	SB	Airflow Control Unit - Introduction of manifold and fluidic element assembly incorporating a stellit	12-May-78	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-000	--	IGV75-047-2436	SB	Airflow Control Unit - Introduction of airflow control unit AC 101 Mk 8 with revised calibration	28-Oct-77	06-Jul-78	2	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-008	--	75-33-02	CMM	AIRFLOW CONTROL UNIT TYPE A001	01-Jun-76	01-Nov-94	17	RB211-524	Titchfield, UK	K2523	--
754-1-32148-008	--	IGV75-042-2414	SB	Airflow Control Unit - Introduction of manifold and fluidic element assembly incorporating a stellit	12-May-78	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-008	--	IGV75-057-2472	SB	Airflow Control Unit - Introduction of "Cal V" with revised limits	12-Jan-79	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-008	--	IGV75-061-2482	SB	Airflow Control Unit - Introduction of self lubricating spheric bearings in lever and push rod assem	25-Mar-80	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
754-1-32148-008	--	IGV75-067-2568	SB	Airflow Control Unit - Introduction of alternative remote capacitor bleed orifice plug to improve st	09-Mar-81	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-008	--	IGV75-068-2473	SB	Airflow Control Unit - Introduction of external P4 temperature stabilising pipe assembly with a stre	15-Aug-80	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-008	--	IGV75-069-2474	SB	Airflow Control Unit - Introduction of seal at capacitor port transfer position on interface between	15-Aug-80	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-008	--	IGV75-072-2571	SB	Minor Design Changes	09-Mar-81	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-008	--	IGV75-077-2587	SB	Airflow Control Unit - Introduction of airflow control unit AC 101 Mk 17 with revised calibration to	09-Jun-82	29-Nov-85	1	BOEING 747	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-008	--	IGV75-079-2612	SB	Airflow Control Unit - Introduction of range of vent adjusters to improve control of unit gain	04-May-82	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-008	--	IGV75-080-2601	SB	Airflow Control Unit - Introduction of separate carbon thrust bearing assembly with increased surfac	01-Oct-82	01-Jun-84	1	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-008	--	IGV75-081-2600	SB	Airflow Control Unit - Introduction of an increased diameter feedback cam	22-Oct-82	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-008	--	IGV75-085-2641	SB	Airflow Control Unit - Introduction of redesigned "Trim A" orifice with contamination inhibiting fea	19-Apr-83	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-013	--	75-33-02	CMM	AIRFLOW CONTROL UNIT TYPE A001	01-Jun-76	01-Nov-94	17	RB211-524	Titchfield, UK	K2523	--
754-1-32148-013	--	IGV75-066-2543	SB	Airflow Control Unit - Introduction of increased slope datum adjustment	17-Jul-80	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-013	--	IGV75-068-2473	SB	Airflow Control Unit - Introduction of external P4 temperature stabilising pipe assembly with a stre	15-Aug-80	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-013	--	IGV75-069-2474	SB	Airflow Control Unit - Introduction of seal at capacitor port transfer position on interface between	15-Aug-80	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-013	--	IGV75-077-2587	SB	Airflow Control Unit - Introduction of airflow control unit AC 101 Mk 17 with revised calibration to	09-Jun-82	29-Nov-85	1	BOEING 747	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-013	--	IGV75-079-2612	SB	Airflow Control Unit - Introduction of range of vent adjusters to improve control of unit gain	04-May-82	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-013	--	IGV75-080-2601	SB	Airflow Control Unit - Introduction of separate carbon thrust bearing assembly with increased surfac	01-Oct-82	01-Jun-84	1	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-013	--	IGV75-081-2600	SB	Airflow Control Unit - Introduction of an increased diameter feedback cam	22-Oct-82	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-013	--	IGV75-082-2625	SB	Airflow Control Unit - Introduction of range of vent adjusters to improve control of unit gain	24-May-82	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-013	--	IGV75-084-2639	SB	Airflow Control Unit - Introduction of manifold and fluidic element assembly incorporating vent adju	10-Mar-83	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-013	--	IGV75-085-2641	SB	Airflow Control Unit - Introduction of redesigned "Trim A" orifice with contamination inhibiting fea	19-Apr-83	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-013	--	IGV75-086-2657	SB	Minor Design Changes	28-Aug-86	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
754-1-32148-013	--	IGV75-091-2690	SB	Airflow Control Unit - Introduction of range of vent adjusters to improve control over unit gain	18-Jul-84	04-Dec-84	1	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-013	--	IGV75-092-2727	SB	Airflow Control Unit - Introduction of manifold and fluidic element assembly incorporating fluidic e	09-Jul-86	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-013	--	IGV75-111-2806	SB	Airflow Control Unit - Introduction of improved feedback driveshaft bearings of stainless steel in I	21-Mar-90	--	0	BOEING 747, BOEING 767, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-013	--	IGV75-121-2832	SB	Airflow Control Unit - Introduction of manifold and element assembly with element assembled by elect	19-Feb-92	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-013	--	IGV75-122-2833	SB	Airflow Control Unit - Deletion of silver plating	02-Mar-92	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-019	--	75-33-08	CMM	AIRFLOW CONTROL UNIT	01-Sep-81	01-Nov-94	8	RB211-524	Titchfield, UK	K2523	--
754-1-32148-019	--	IGV75-080-2601	SB	Airflow Control Unit - Introduction of separate carbon thrust bearing assembly with increased surfac	01-Oct-82	01-Jun-84	1	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-019	--	IGV75-081-2600	SB	Airflow Control Unit - Introduction of an increased diameter feedback cam	22-Oct-82	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-019	--	IGV75-084-2639	SB	Airflow Control Unit - Introduction of manifold and fluidic element assembly incorporating vent adju	10-Mar-83	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-019	--	IGV75-085-2641	SB	Airflow Control Unit - Introduction of redesigned "Trim A" orifice with contamination inhibiting fea	19-Apr-83	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-019	--	IGV75-086-2657	SB	Minor Design Changes	28-Aug-86	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-019	--	IGV75-091-2690	SB	Airflow Control Unit - Introduction of range of vent adjusters to improve control over unit gain	18-Jul-84	04-Dec-84	1	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-019	--	IGV75-092-2727	SB	Airflow Control Unit - Introduction of manifold and fluidic element assembly incorporating fluidic e	09-Jul-86	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-019	--	IGV75-111-2806	SB	Airflow Control Unit - Introduction of improved feedback driveshaft bearings of stainless steel in I	21-Mar-90	--	0	BOEING 747, BOEING 767, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-019	--	IGV75-118-2836	SB	Airflow Control Unit - Introduction of airflow control unit Type AC103 Mk 50 with fixed datum contro	15-Nov-91	--	0	BOEING 747	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-019	--	IGV75-121-2832	SB	Airflow Control Unit - Introduction of manifold and element assembly with element assembled by elect	19-Feb-92	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32148-019	--	IGV75-122-2833	SB	Airflow Control Unit - Deletion of silver plating	02-Mar-92	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32149-002	--	MM252	MM	--	--	--	0	RB211-524	Titchfield, UK	K2523	--
754-1-32156-002	--	75-33-03	CMM	RAM ASSEMBLY	01-Apr-76	07-Jun-17	9	RB211-524	Titchfield, UK	K2523	--
754-1-32156-002	--	IGV75-056-2480	SB	Actuating Ram Assembly - Introduction of actuating ram assembly AR 101 Mk 3 with reduced ram volume	19-Mar-79	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32156-003	--	75-33-03	CMM	RAM ASSEMBLY	01-Apr-76	07-Jun-17	9	RB211-524	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
754-1-32156-003	--	SIL-CS-5-05	SIL	Alternative Union on AR101 Mk 300	--	--	0	--	Titchfield, UK	K2523	--
754-1-32322-001	--	75-33-04	CMM	P4: PF PRESSURE RATIO SWITCH	01-Apr-76	02-Jun-00	10	RB211-524	Titchfield, UK	K2523	--
754-1-32322-001	--	PRS73-2-2422	SB	Introduction of improved sealing at switch housing and fluidic element interface.	21-Nov-77	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32762-001	--	MM255	MM	--	--	--	0	RB211-524	Titchfield, UK	K2523	--
754-1-32762-002	--	75-33-01	CMM	CONTROL UNIT BLEED VALVE	01-May-76	08-May-99	11	RB211-524	Titchfield, UK	K2523	--
754-1-32762-002	--	IGV75-036-2435	SB	Bleed Valve Control Unit - Introduction of bleed valve control unit AV 101 Mk 4 with revised operati	15-Jun-77	--	0	BOEING 747	Titchfield, UK	K2523	BASIC MANUAL
754-1-32762-002	--	IGV75-051-2392	SB	Bleed Valve Control Unit - Introduction of bleed control valve assembly with re-designed bearing arr	21-Apr-78	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	--
754-1-32762-002	--	IGV75-076-2576	SB	Bleed Valve Control Unit - Introduction of bleed valve control unit AV 101 Mk 8 with revised calibra	08-Jan-82	--	0	BOEING 747	Titchfield, UK	K2523	--
754-1-32762-004	--	75-33-01	CMM	CONTROL UNIT BLEED VALVE	01-May-76	08-May-99	11	RB211-524	Titchfield, UK	K2523	--
754-1-32762-004	--	IGV75-051-2392	SB	Bleed Valve Control Unit - Introduction of bleed control valve assembly with re-designed bearing arr	21-Apr-78	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	--
754-1-32762-004	--	IGV75-054-2457	SB	Bleed Valve Control Unit - Introduction of bleed valve control unit AV 101 Mk 4 (Cal G) and identifi	11-Jul-79	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-32762-004	--	IGV75-058-2407	SB	Bleed Valve Control Unit - Conversion of AV 101 Mk 4 "Cal G" units to AV 101 Mk 2 "Cal E" units and	11-Jun-79	--	0	LOCKHEED L1011	Titchfield, UK	K2523	--
754-1-32762-010	--	75-33-07	CMM	BLEED VALVE CONTROL UNIT	01-Sep-81	15-Sep-05	7	RB211-524	Titchfield, UK	K2523	--
754-1-32808-000	--	75-33-06	CMM	BLEED VALVE CONTROL UNIT	01-Aug-89	17-May-99	3	RB211-524	Titchfield, UK	K2523	--
754-1-34600-001	--	75-31-07	CMM	BLEED CONTROL VALVE	01-Mar-82	01-Nov-84	1	LYNX	Titchfield, UK	K2523	--
754-1-34600-003	--	75-31-07	CMM	BLEED CONTROL VALVE	01-Mar-82	01-Nov-84	1	LYNX	Titchfield, UK	K2523	--
754-1-35045-000	--	24-10-00	CMM	STARTER	01-May-64	01-May-08	52	BAC 1-11	Titchfield, UK	K2523	--
754-1-37662-002	--	52-20-01	CMM	MOTOR PRV ASSY TYPE AM600	--	25-Feb-05	3	BOEING 747	Titchfield, UK	K2523	--
754-1-38545-000	--	IGV75-096-2723	SB	P4 Air Filter - Introduction of Type AF210 Mk 2 incorporating o25 micron filter element assembly	17-Jun-86	--	0	BOEING 747, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-38545-002	--	IGV75-097-2722	SB	P4 Air Filter - Introduction of Type AF200 Mk 3 incorporating 25 micron filter element assembly	17-Jun-86	--	0	BOEING 747, BOEING 757, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-38545-002	--	IGV75-102-2767	SB	P4 Air Filter - Introduction of Type AF210 Mk 3 incorporating 7 micron filter element assembly	17-Nov-87	--	0	BOEING 747, LOCKHEED L1011, RB211	Titchfield, UK	K2523	BASIC MANUAL

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
754-1-38545-002	--	IGV75-119-2829	SB	Minor Design Changes	24-Jul-92	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
754-1-38545-002	--	IGV75-120-2837	SB	P4 Air Filter - Introduction of Type AF210 Mk 4 with filter element assembly deleted	02-Dec-92	27-Oct-95	2	BOEING 747, BOEING 767, LOCKHEED L1011	Titchfield, UK	K2523	--
754-1-38545-003	--	75-33-10	CMM	AIR FILTER ASSEMBLY	01-Aug-89	19-Jun-00	2	RB211-524, SPEY, TAY ENGINE	Titchfield, UK	K2523	--
754-1-38545-003	--	IGV75-119-2829	SB	Minor Design Changes	24-Jul-92	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
754-1-38545-003	--	IGV75-120-2837	SB	P4 Air Filter - Introduction of Type AF210 Mk 4 with filter element assembly deleted	02-Dec-92	27-Oct-95	2	BOEING 747, BOEING 767, LOCKHEED L1011	Titchfield, UK	K2523	--
754-1-38545-004	--	75-33-10	CMM	AIR FILTER ASSEMBLY	01-Aug-89	19-Jun-00	2	RB211-524, SPEY, TAY ENGINE	Titchfield, UK	K2523	--
754-1-39405-001	--	MM293	MM	HP & LP Reg Vve & Shut Off Vve	30-May-90	30-May-90	0	C17A	Titchfield, UK	K2523	MK 1 VALVES **ONLY**
754-1-39406-001	--	MM293	MM	HP & LP Reg Vve & Shut Off Vve	30-May-90	30-May-90	0	C17A	Titchfield, UK	K2523	MK 1 VALVES **ONLY**
754-1-39406-002	--	MM293	MM	HP & LP Reg Vve & Shut Off Vve	30-May-90	30-May-90	0	C17A	Titchfield, UK	K2523	MK 1 VALVES **ONLY**
754-1-39743-002	--	IGV75-105-2801	SB	Actuating Ram Assembly - Introduction of Vespel components between position indicator operating mechanism	28-Aug-89	--	0	BOEING 747, RB211	Titchfield, UK	K2523	--
754-1-39743-002	--	IGV75-126-2863	SB	Actuating Ram Assy - Deletion of position indicator	30-Sep-96	--	0	BOEING 747, BOEING 767	Titchfield, UK	K2523	BASIC MANUAL
754-1-39743-003	--	75-33-16	CMM	RAM ASSEMBLY TYPE AR103	01-Oct-89	23-Jan-17	5	RB211-524	Titchfield, UK	K2523	--
754-1-39743-003	--	IGV75-116-2827	SB	Actuating Ram Assembly - Introduction of Type 103 Mk 3 incorporating improved standard position indicator	13-Jun-91	--	0	BOEING 747, BOEING 767	Titchfield, UK	K2523	BASIC MANUAL
754-1-39743-003	--	IGV75-126-2863	SB	Actuating Ram Assy - Deletion of position indicator	30-Sep-96	--	0	BOEING 747, BOEING 767	Titchfield, UK	K2523	BASIC MANUAL
754-1-39743-004	--	75-33-16	CMM	RAM ASSEMBLY TYPE AR103	01-Oct-89	23-Jan-17	5	RB211-524	Titchfield, UK	K2523	--
754-1-39744-001	--	75-33-06	CMM	BLEED VALVE CONTROL UNIT	01-Aug-89	17-May-99	3	RB211-524	Titchfield, UK	K2523	--
754-1-39744-001	--	IGV75-109-2795	SB	Bleed valve control unit - Introduction of bleed valve control unit Type AV103 Mk 2 with extended life	22-Dec-89	22-Dec-89	0	BOEING 747	Titchfield, UK	K2523	--
754-1-39744-002	--	75-33-06	CMM	BLEED VALVE CONTROL UNIT	01-Aug-89	17-May-99	3	RB211-524	Titchfield, UK	K2523	--
754-1-39744-002	--	IGV75-109-2795	SB	Bleed valve control unit - Introduction of bleed valve control unit Type AV103 Mk 2 with extended life	22-Dec-89	22-Dec-89	0	BOEING 747	Titchfield, UK	K2523	--
754-1-39785-000	--	IGV75-111-2806	SB	Airflow Control Unit - Introduction of improved feedback driveshaft bearings of stainless steel in I	21-Mar-90	--	0	BOEING 747, BOEING 767, LOCKHEED L1011	Titchfield, UK	K2523	BASIC MANUAL
754-1-39785-000	--	IGV75-118-2836	SB	Airflow Control Unit - Introduction of airflow control unit Type AC103 Mk 50 with fixed datum contro	15-Nov-91	--	0	BOEING 747	Titchfield, UK	K2523	BASIC MANUAL

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
754-1-39785-001	--	75-33-05	CMM	Airflow Control Unit, Type AC103	30-Jun-89	04-Oct-12	7	RB211-524	Titchfield, UK	K2523	--
754-1-39785-001	--	IGV75-104-2789	SB	Introduction of calibrated AJ	10-Jan-89	--	0	BOEING 747, RB211	Titchfield, UK	K2523	--
754-1-39785-001	--	IGV75-108-2794	SB	Airflow Control Unit - Introduction of airflow control unit Type AC103 Mk 3 with extended PF and sta	22-Dec-89	--	0	BOEING 747	Titchfield, UK	K2523	BASIC MANUAL
754-1-39785-001	--	IGV75-110-2805	SB	Airflow Control Unit - Introduction of orifice "B" with extended thread form	22-Dec-89	--	0	BOEING 747, BOEING 767	Titchfield, UK	K2523	--
754-1-39785-001	--	IGV75-112-2811	SB	Airflow Control Unit - Introduction of machined "A" and "B" orifices in stainless steel in lieu of n	27-Feb-90	--	0	BOEING 747, BOEING 767	Titchfield, UK	K2523	--
754-1-39785-001	--	IGV75-114-2816	SB	Airflow Control Unit - Deletion of silver plating	10-May-90	--	0	BOEING 747, BOEING 767	Titchfield, UK	K2523	--
754-1-39785-001	--	IGV75-115-2817	SB	Airflow Control Unit - Introduction of manifold and element assembled by electroless nickel plating	31-May-90	--	0	BOEING 747, BOEING 767	Titchfield, UK	K2523	--
754-1-39785-003	--	75-33-05	CMM	Airflow Control Unit, Type AC103	30-Jun-89	04-Oct-12	7	RB211-524	Titchfield, UK	K2523	--
754-1-39785-003	--	IGV75-110-2805	SB	Airflow Control Unit - Introduction of orifice "B" with extended thread form	22-Dec-89	--	0	BOEING 747, BOEING 767	Titchfield, UK	K2523	--
754-1-39785-003	--	IGV75-112-2811	SB	Airflow Control Unit - Introduction of machined "A" and "B" orifices in stainless steel in lieu of n	27-Feb-90	--	0	BOEING 747, BOEING 767	Titchfield, UK	K2523	--
754-1-39785-003	--	IGV75-114-2816	SB	Airflow Control Unit - Deletion of silver plating	10-May-90	--	0	BOEING 747, BOEING 767	Titchfield, UK	K2523	--
754-1-39785-003	--	IGV75-115-2817	SB	Airflow Control Unit - Introduction of manifold and element assembled by electroless nickel plating	31-May-90	--	0	BOEING 747, BOEING 767	Titchfield, UK	K2523	--
754-1-39785-003	--	IGV75-116-G720	SB	Introduction of New Airflow Control Unit	20-Jul-11	10-Nov-11	1	RB211-524	Titchfield, UK	K2523	--
754-1-39785-004	--	75-33-05	CMM	Airflow Control Unit, Type AC103	30-Jun-89	04-Oct-12	7	RB211-524	Titchfield, UK	K2523	--
754-1-39785-004	--	IGV75-116-G720	SB	Introduction of New Airflow Control Unit	20-Jul-11	10-Nov-11	1	RB211-524	Titchfield, UK	K2523	--
754-1-39785-050	--	75-33-09	CMM	AIRFLOW CONTROL UNIT TYPE AC103 MK50	01-Sep-91	31-Jan-03	3	RB211-524	Titchfield, UK	K2523	--
754-1-40126-000	--	75-33-02	CMM	AIRFLOW CONTROL UNIT TYPE A001	01-Jun-76	01-Nov-94	17	RB211-524	Titchfield, UK	K2523	--
754-1-40126-000	--	75-33-05	CMM	Airflow Control Unit, Type AC103	30-Jun-89	04-Oct-12	7	RB211-524	Titchfield, UK	K2523	--
754-1-40126-000	--	75-33-08	CMM	AIRFLOW CONTROL UNIT	01-Sep-81	01-Nov-94	8	RB211-524	Titchfield, UK	K2523	--
754-1-40126-000	--	75-33-09	CMM	AIRFLOW CONTROL UNIT TYPE AC103 MK50	01-Sep-91	31-Jan-03	3	RB211-524	Titchfield, UK	K2523	--
754-1-40129-000	--	75-33-06	CMM	BLEED VALVE CONTROL UNIT	01-Aug-89	17-May-99	3	RB211-524	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
754-1-40480-002	--	75-24-12	CMM	ACTUATING RAM TYPE AR210 MK2	30-Mar-94	06-Nov-08	1	TRENT	Titchfield, UK	K2523	--
754-1-40530-000	--	75-33-05	CMM	Airflow Control Unit, Type AC103	30-Jun-89	04-Oct-12	7	RB211-524	Titchfield, UK	K2523	--
754-1-40530-002	--	75-33-05	CMM	Airflow Control Unit, Type AC103	30-Jun-89	04-Oct-12	7	RB211-524	Titchfield, UK	K2523	--
754-1-40725-001	--	MM305-1	MM	THRUST REVERSER SYSTEM	01-Mar-97	--	0	DOUGLAS DC8	Titchfield, UK	K2523	--
754-1-40726-001	--	MM305	MM	ACTUATOR AND THRUST REVERSER SYSTEM	01-Mar-97	--	0	DOUGLAS DC8	Titchfield, UK	K2523	--
754-1-40740-001	--	MM305	MM	ACTUATOR AND THRUST REVERSER SYSTEM	01-Mar-97	--	0	DOUGLAS DC8	Titchfield, UK	K2523	--
754-1-41087-001	--	78-33-21	CMM	DEPLOY-ENABLE VALVE TYPE MV500 MK1	18-Apr-96	--	0	DOUGLAS DC8	Titchfield, UK	K2523	--
754-8-30574-000	--	PD78-22-2588	SB	Air Motor Servo Unit - Introduction of revised installation assembly at control rod eye ends.	16-Mar-81	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	--
754-8-30574-000	--	PD78-28-2606	SB	Input Control Ram - Introduction of changes to improve operation and prevent bearing wear.	15-Feb-82	28-May-86	1	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-8-30574-005	--	78-31-04	CMM	PNEUMATIC DRIVE UNIT	01-Sep-74	19-Dec-06	12	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	NO LONGER SUPPORTED
754-8-30574-005	--	PD78-20	SB	Pneumatic Drive Unit - Minor design changes.	25-Feb-88	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	--
754-8-30574-005	--	PD78-30-2624	SB	Input Control Ram - Introduction of improved piston sealing rings.	22-Apr-82	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-8-30574-005	--	PD78-32-2653	SB	INPut Control Ram - Introduction of changes to improve unit operation and avoid latch hunt.	25-Feb-88	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-8-30574-005	--	PD78-33-2689	SB	Air Motor Unit - Introduction of improved piston support bearing in latch operating air cylinder.	25-Feb-88	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-8-30574-005	--	PD78-34-2943	SB	Introduction of new harness assembly	23-Oct-01	--	0	A300	Titchfield, UK	K2523	--
754-8-30574-006	--	78-31-00	CMM	PNEUMATIC DRIVE UNIT	01-Sep-74	30-Dec-82	14	BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	--
754-8-30574-006	--	PD78-20	SB	Pneumatic Drive Unit - Minor design changes.	25-Feb-88	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	--
754-8-30574-006	--	PD78-30-2624	SB	Input Control Ram - Introduction of improved piston sealing rings.	22-Apr-82	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-8-30574-006	--	PD78-32-2653	SB	INPut Control Ram - Introduction of changes to improve unit operation and avoid latch hunt.	25-Feb-88	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-8-30574-006	--	PD78-33-2689	SB	Air Motor Unit - Introduction of improved piston support bearing in latch operating air cylinder.	25-Feb-88	--	0	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	BASIC MANUAL
754-8-30574-007	--	78-31-04	CMM	PNEUMATIC DRIVE UNIT	01-Sep-74	19-Dec-06	12	A300, BOEING 747, DOUGLAS DC10	Titchfield, UK	K2523	NO LONGER SUPPORTED

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
755-1-06883	--	73-20-12	CMM	FUEL SYSTEM, TYPE PGA 303/6	01-Jul-74	01-Nov-76	1	--	Titchfield, UK	K2523	--
755-1-08049	--	MM245	MM	--	--	--	0	LYNX	Titchfield, UK	K2523	--
755-1-08358	--	MM245	MM	--	--	--	0	LYNX	Titchfield, UK	K2523	--
755-1-08690-006	--	73-10-09 TO -15	CMM	FUEL FLOW CONTROL UNIT	01-Mar-81	01-Dec-84	1	Not Known	Titchfield, UK	K2523	--
755-1-08691-001	--	73-20-41	CMM	FREE PWR TURBINE GOVERNOR	24-Feb-81	30-Nov-84	1	Not Known	Titchfield, UK	K2523	--
755-1-10808-104	--	73-10-20	CMM	FUEL PUMP TYPE8405	01-May-94	22-Dec-14	4	MD-900 Explorer, PW206A	Titchfield, UK	K2523	--
755-1-10808-105	--	73-10-20	CMM	FUEL PUMP TYPE8405	01-May-94	22-Dec-14	4	MD-900 Explorer, PW206A	Titchfield, UK	K2523	--
77-897	--	28-10-09	MM	FLAME ARRESTOR	06-Jul-94	--	0	KT-1	Titchfield, UK	K2523	SHAW (DRAFT FOR INFO ONLY)
78-0104-1300	--	PSD-347	CMM	Firmware upgrade	--	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
78-0104-1300	--	PSD-389	CMM	Firmware upgrade	12-Jan-22	13-Jan-22	1	--	Titchfield, UK	K2523	BASIC MANUAL
78F0055	--	28-21-90	CMM	Thermal Relief Valve	06-May-09	05-Nov-15	4	BOEING 787	Titchfield, UK	K2523	--
7901014E	--	28-20-80	CMM	SPV	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
7901039F	--	28-21-98	OM	SPV	01-Oct-73	01-Sep-84	1	Not Known	Titchfield, UK	K2523	--
7901040B	--	28-22-08	OM	SPV	01-Aug-73	01-Oct-84	2	CASA 212	Titchfield, UK	K2523	--
7901053J	--	28-23-24	OM	SPV	29-Nov-78	06-May-11	1	BAe 748	Titchfield, UK	K2523	--
7901055B	--	28-22-95	OM	SPV	01-Sep-75	22-Aug-84	2	SD-330, SD-360	Titchfield, UK	K2523	--
7901067F	--	28-21-94	CMM	3/4 INCH SPV	10-Apr-98	--	0	CASA 101	Titchfield, UK	K2523	--
7901067F	--	7901067F-28-1	SB	SPV - INTRO OF FOULING PIN	01-Mar-85	--	0	Not Known	Titchfield, UK	K2523	--
7901220F	--	28-20-68	CMM	MOTORISED SPV	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
7901222E	--	28-20-68	CMM	MOTORISED SPV	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
7902223H	--	28-23-25	OM	MOT SPV	01-Feb-79	06-May-11	2	BAe 748	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
7903004D	--	28-22-37	OM	MOTORISED SPV	01-Jun-74	01-Aug-78	1	CONCORDE	Titchfield, UK	K2523	--
7903034R	--	28-22-31	CMM	MOT SPV	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
7903042M	--	28-09-03	OM	SPV	01-Sep-72	10-Jan-94	3	A300, A300-600	Titchfield, UK	K2523	--
7903043F	--	28-24-12	OM	SPV	01-Sep-72	01-May-79	1	A300	Titchfield, UK	K2523	--
7903049M	--	28-23-31	OM	SPV	01-Apr-81	11-Jan-94	3	CASA 212	Titchfield, UK	K2523	--
7903203D	--	28-22-37	OM	MOTORISED SPV	01-Jun-74	01-Aug-78	1	CONCORDE	Titchfield, UK	K2523	--
7903205M	--	28-30-10	CMM	MOT SPV	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
7903208H	--	28-10-25	OM	MOT SPV	01-Jan-70	--	0	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
7903221F	--	28-20-73	OM	MOT SPV	01-Dec-69	10-Feb-98	1	BAC 1-11	Titchfield, UK	K2523	--
7903224K	--	28-20-67	OM	MOTORISED SP PRV	01-Dec-69	01-May-71	1	Not Known	Titchfield, UK	K2523	--
7903231D	--	28-21-83	OM	MOTORISED SPV WITH MANUAL OVERRIDE	01-Mar-71	10-Apr-08	3	BAE 125	Titchfield, UK	K2523	--
7903279H	--	28-22-33	OM	1 IN PLUG-IN SPV	01-Jun-74	--	0	Not Known	Titchfield, UK	K2523	--
7903280M	--	28-22-39	OM	PLUG-IN MOTORISED SPV	01-Jul-74	11-Mar-94	1	CONCORDE	Titchfield, UK	K2523	--
7903281M	--	28-22-38	OM	TWIN MOTORISED (PLUG-IN) SPV	01-May-74	11-Mar-94	1	CONCORDE	Titchfield, UK	K2523	--
7903282R	--	28-22-40	OM	MOT SPV	01-May-74	01-Nov-90	1	Not Known	Titchfield, UK	K2523	--
7907015E	--	29-10-73	CMM	HIGH PRESSURE MULTIWAY VALVE	18-Oct-82	19-May-87	1	BAE 125	Titchfield, UK	K2523	--
7909301H	--	28-21-60	CMM	1in MOTORISED SHUT-OFF VALVE	01-Nov-92	09-Jan-17	4	SAAB 2000	Titchfield, UK	K2523	--
7913001F	--	28-22-72	OM	MANUALLY OPERATED SPV	01-Apr-75	24-Aug-84	2	SD-330, SD-360	Titchfield, UK	K2523	--
7913003K	--	28-23-15	CMM	SPV	25-Apr-80	06-May-11	5	BAE 125, BAE 146	Titchfield, UK	K2523	--
7913032H	--	28-20-50	CMM	1' SPV	01-Aug-84	20-Sep-16	4	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	BAE to approve
7913079F	--	28-23-38	CMM	SPV	01-Aug-82	06-May-11	2	JS31, JS32	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
7913209M	--	28-30-10+	MM	Maintenance Manual for 2-inch Motorised Spherical Plug Valve	01-May-75	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
7913209M	--	28-30-12	OM	SPHERICAL PLUG VALVES	30-Jun-77	11-Mar-94	2	CONCORDE	Titchfield, UK	K2523	--
7913209M	--	28-30-12-9092	SB	MOTOR WIRING CHANGE	01-Oct-76	--	0	Not Known	Titchfield, UK	K2523	--
7913239M	--	28-30-12	OM	SPHERICAL PLUG VALVES	30-Jun-77	11-Mar-94	2	CONCORDE	Titchfield, UK	K2523	--
7913241R	--	28-30-15	CMM	3' TWIN-MOT SP VALVE	01-Jul-84	01-Nov-90	1	S-61N HELICOPTER	Titchfield, UK	K2523	--
7913291D	--	28-08-08	CMM	VALVE WITH TELEFLEX CONTROL BOX	01-Jul-84	01-Apr-87	2	Not Known	Titchfield, UK	K2523	--
7923023H	--	28-20-49	CMM	MOTORISED SPV	01-Sep-84	02-Mar-01	4	HAWK	Titchfield, UK	K2523	DO NOT USE - OBSOLETE SWISS VERSION
7923023H	--	28-20-49+	CMM	MOTORISED SPV	01-Sep-84	18-Nov-11	5	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	BAE to approve
7923028M	--	28-10-63+	MM	Maintenance Manual 2-inch Motorised Spherical Plug Valve	15-Jun-83	15-Jun-83	1	--	Titchfield, UK	K2523	BASIC MANUAL
7923061M	--	28-10-89	CMM	1 1/4 IN SP/NRV	01-Nov-86	27-Oct-93	2	F100, F28	Titchfield, UK	K2523	--
7923076D	--	28-88-36	CMM	SPILL VALVE ASSY	01-Aug-88	04-Mar-14	3	MK 32 POD	Titchfield, UK	K2523	EX FRL MIL SYS
7923213K	--	9406556-28-01	SB	CLAMP RING ASSY INCONSISTENT TORQUE	--	--	0	AV8B, HAWK, MK 32 POD, T45, TORNADO	Titchfield, UK	K2523	TO BE WRITTEN
7923214K	--	9406556-28-01	SB	CLAMP RING ASSY INCONSISTENT TORQUE	--	--	0	AV8B, HAWK, MK 32 POD, T45, TORNADO	Titchfield, UK	K2523	TO BE WRITTEN
7923223H	--	28-20-49+	CMM	MOTORISED SPV	01-Sep-84	18-Nov-11	5	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	BAE to approve
7923223H	--	9406556-28-01	SB	CLAMP RING ASSY INCONSISTENT TORQUE	--	--	0	AV8B, HAWK, MK 32 POD, T45, TORNADO	Titchfield, UK	K2523	TO BE WRITTEN
7923225F	--	9406556-28-01	SB	CLAMP RING ASSY INCONSISTENT TORQUE	--	--	0	AV8B, HAWK, MK 32 POD, T45, TORNADO	Titchfield, UK	K2523	TO BE WRITTEN
7923227F	--	28-20-81	CMM	3/4' MOT SP PRV	01-Jun-84	13-Jul-18	3	CASA 235	Titchfield, UK	K2523	--
7923228M	--	28-10-63+	MM	Maintenance Manual 2-inch Motorised Spherical Plug Valve	15-Jun-83	15-Jun-83	1	--	Titchfield, UK	K2523	BASIC MANUAL
7923245M	--	28-10-63	CMM	2 IN MOTORISED SPV	01-May-84	01-Dec-16	5	CASA 235	Titchfield, UK	K2523	--
7923245M	--	SIL-2009-04	SIL	CDCCL Component Returns Policy	18-Jun-09	18-Oct-12	1	A300, A300-400, A300-600, A300-600 - PLESSEY, A310, A310-300, A310-MRTT, A318, A319, A320, A321, A320, A320 MRTT, A320	Titchfield, UK	K2523	--
7923261M	--	28-10-89	CMM	1 1/4 IN SP/NRV	01-Nov-86	27-Oct-93	2	F100, F28	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
7923267J	--	28-10-90	CMM	1 1/4IN PR/SPV	01-Jan-87	17-Oct-14	5	F100, F28, F50, F70	Titchfield, UK	K2523	--
7923267J	--	7923267J-28-1	SB	INTRO OF A NEW ACTUATOR TO MOT.PR/SPV PN 7923267J	17-Dec-92	--	0	F100, F70	Titchfield, UK	K2523	--
7923268L	--	28-10-91	CMM	1 3/4IN SPV	01-Jan-87	20-Feb-96	3	F100, F28	Titchfield, UK	K2523	--
7923270F	--	9406556-28-01	SB	CLAMP RING ASSY INCONSISTENT TORQUE	--	--	0	AV8B, HAWK, MK 32 POD, T45, TORNADO	Titchfield, UK	K2523	TO BE WRITTEN
7923276D	--	28-88-36	CMM	SPILL VALVE ASSY	01-Aug-88	04-Mar-14	3	MK 32 POD	Titchfield, UK	K2523	EX FRL MIL SYS
7923278F	--	9406556-28-01	SB	CLAMP RING ASSY INCONSISTENT TORQUE	--	--	0	AV8B, HAWK, MK 32 POD, T45, TORNADO	Titchfield, UK	K2523	TO BE WRITTEN
7933122C	--	34-10-01	CMM	SPHERICAL PLUG VALVE	01-Aug-90	22-Apr-11	3	BAE 146	Titchfield, UK	K2523	--
7933135C	--	28-21-59+	MM	Maintenance Manual for Manual Shut-Off Valve	17-Jun-91	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
7933140M	--	28-10-98	CMM	2IN SPHERICAL PLUG VALVE	01-Mar-92	14-Jul-93	1	F100, F70	Titchfield, UK	K2523	--
7933141J	--	28-10-97	CMM	1 1/4IN SPHERICAL PLUG VALVE	01-Mar-92	14-Mar-94	1	F100, F70	Titchfield, UK	K2523	--
7933150F	--	28-21-16	CMM	FUEL CROSSFEED VALVE ASSY	01-Feb-93	17-Jun-11	2	JS41	Titchfield, UK	K2523	RPLCS ISS DTD 10/91
7933156J	--	28-10-96	CMM	1 1/4IN SPHERICAL PLUG VALVE	01-Mar-92	11-Nov-98	2	F100, F70	Titchfield, UK	K2523	--
7933343F	--	28-21-16+	CMM	Maintenance Manual for Fuel Crossfeed Valve	09-Aug-91	13-Jan-92	1	--	Titchfield, UK	K2523	BASIC MANUAL
7933350F	--	28-21-16	CMM	FUEL CROSSFEED VALVE ASSY	01-Feb-93	17-Jun-11	2	JS41	Titchfield, UK	K2523	RPLCS ISS DTD 10/91
7933362M	--	28-21-61	CMM	MOTOR ACTUATED SHUT-OFF VALVE	18-Jun-93	20-Oct-94	1	SAAB 2000	Titchfield, UK	K2523	--
7933364H	--	28-22-18	CMM	FIREWALL SHUT-OFF VALVE	20-Apr-95	--	0	N250	Titchfield, UK	K2523	--
7933365H	--	28-22-20	CMM	CROSSFEED AND DEFUELLING VALVE	10-May-95	--	0	N250	Titchfield, UK	K2523	--
7933367D	--	28-23-41+	CMM	APU SHUT-OFF VALVE	16-May-95	--	0	N250	Titchfield, UK	K2523	--
7940002C	--	25-30-51	CMM	SPV	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
7940005H	--	38-09-22	CMM	SPHERICAL PLUG VALVE	01-May-80	13-May-11	4	BAE 146	Titchfield, UK	K2523	--
7940005H	--	38-09-22+	OM	SPHERICAL PLUG VALVE	01-Nov-69	01-Aug-81	1	A300	Titchfield, UK	K2523	* SEE CMM 38-09-22

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
7940008F	--	38-09-22+	OM	SPHERICAL PLUG VALVE	01-Nov-69	01-Aug-81	1	A300	Titchfield, UK	K2523	* SEE CMM 38-09-22
7940012D	--	38-10-23	OM	SPV	01-Nov-71	--	0	Not Known	Titchfield, UK	K2523	--
7940013D	--	38-10-22	OM	SPV	01-Nov-71	--	0	Not Known	Titchfield, UK	K2523	--
7940015B	--	73-11-02	OM	1/4' DIA SP DRAIN VALVE	01-Nov-82	01-Nov-82	1	RB211-22B, RB211-524	Titchfield, UK	K2523	COMPLETELY REVISED
7940023F	--	38-09-23	CMM	SPV	01-Jun-80	13-May-11	6	BAE 146	Titchfield, UK	K2523	--
7940023F	--	7940023F-38-10-1	SB	POT. WATER SYSTEM - CHARGING VALVE REMOVAL OF PTS	01-May-89	--	0	Not Known	Titchfield, UK	K2523	--
7940052D	--	38-10-67	CMM	SHUT OFF VALVE	01-Oct-82	13-May-11	3	A300, A300-400, A300-600, A310, JS31	Titchfield, UK	K2523	--
7940061D	--	38-10-46	CMM	SHUT-OFF VALVE	01-Aug-86	21-Mar-03	4	A319, A320, A321	Titchfield, UK	K2523	--
7940063C	--	38-10-17	CMM	WATER SHUT-OFF VALVE	01-Nov-86	13-May-11	3	BAe ATP, JS61	Titchfield, UK	K2523	--
7940066F	--	38-09-24	CMM	3/4IN DIA SPHERICAL PLUG VALVE	01-Jun-89	13-May-11	3	BAE 146	Titchfield, UK	K2523	--
7940167F	--	38-09-24	CMM	3/4IN DIA SPHERICAL PLUG VALVE	01-Jun-89	13-May-11	3	BAE 146	Titchfield, UK	K2523	--
7940168F	--	38-09-24	CMM	3/4IN DIA SPHERICAL PLUG VALVE	01-Jun-89	13-May-11	3	BAE 146	Titchfield, UK	K2523	--
7945001D	--	38-10-27+	MM	Maintenance Manual for Spherical Plug Water Valves	01-May-72	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
7945003F	--	38-10-27+	MM	Maintenance Manual for Spherical Plug Water Valves	01-May-72	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
7945005F	--	38-10-27+	MM	Maintenance Manual for Spherical Plug Water Valves	01-May-72	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
7945006F	--	38-10-27+	MM	Maintenance Manual for Spherical Plug Water Valves	01-May-72	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
7945007H	--	38-10-33	OM	SPV	01-Mar-73	17-Dec-96	2	A300, A300-600, A310	Titchfield, UK	K2523	--
7945008F	--	38-10-32	OM	SPV	01-Mar-73	30-Jul-84	1	A300, A310	Titchfield, UK	K2523	--
7945009F	--	38-10-32	OM	SPV	01-Mar-73	30-Jul-84	1	A300, A310	Titchfield, UK	K2523	--
7945010D	--	38-10-31	OM	SPV	01-Mar-73	12-Apr-89	2	A300	Titchfield, UK	K2523	--
7945011H	--	38-10-33	OM	SPV	01-Mar-73	17-Dec-96	2	A300, A300-600, A310	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
7945016H	--	38-10-62	CMM	SPV	01-Nov-80	01-Jul-84	1	A300	Titchfield, UK	K2523	--
7945017F	--	38-10-43	CMM	MOT WATER VALVE	01-Jun-81	16-Jan-19	5	A300, A300-400, A300-600, A310	Titchfield, UK	K2523	--
7945201H	--	38-10-41	OM	MOTORISED WATER VALVES	01-Jul-77	15-Dec-10	7	A300, A300-600, A310	Titchfield, UK	K2523	--
7945201H	--	7945201H-38-1	SB	MOT. VALVES - ALTVE MOTORS	01-Apr-77	01-Mar-81	1	A300, A310	Titchfield, UK	K2523	--
7945201H	--	SIL-CS-9-06	SIL	V Band 9406556 Vband Assy	29-Oct-06	--	0	A300, A300-600, A310, A320	Titchfield, UK	K2523	--
7945202H	--	38-10-41	OM	MOTORISED WATER VALVES	01-Jul-77	15-Dec-10	7	A300, A300-600, A310	Titchfield, UK	K2523	--
7945202H	--	7945201H-38-1	SB	MOT. VALVES - ALTVE MOTORS	01-Apr-77	01-Mar-81	1	A300, A310	Titchfield, UK	K2523	--
7945202H	--	SIL-CS-9-06	SIL	V Band 9406556 Vband Assy	29-Oct-06	--	0	A300, A300-600, A310, A320	Titchfield, UK	K2523	--
7945217F	--	38-10-43	CMM	MOT WATER VALVE	01-Jun-81	16-Jan-19	5	A300, A300-400, A300-600, A310	Titchfield, UK	K2523	--
7945217F	--	SIL-CS-9-06	SIL	V Band 9406556 Vband Assy	29-Oct-06	--	0	A300, A300-600, A310, A320	Titchfield, UK	K2523	--
7960002H	--	21-40-73	OM	FUEL THROTTLE VALVE(WITH CANISTER)	01-Feb-75	--	0	Not Known	Titchfield, UK	K2523	--
7960002H	--	21-40-78	OM	CANISTER	01-Apr-73	--	0	Not Known	Titchfield, UK	K2523	--
7960006M	--	28-22-36	MM	Maintenance Manual for CANISTER ASSY	01-Feb-74	--	0	Not Known	Titchfield, UK	K2523	BASIC MANUAL
7960007H	--	28-22-34	OM	VALVE CANISTER ASSY	01-Jul-74	--	0	Not Known	Titchfield, UK	K2523	--
7960007H	--	28-22-34+	MM	Maintenance Manual for Canister Assembly	22-Jan-73	--	0	--	Titchfield, UK	K2523	DRAFT ONLY
7990001R	--	75-20-01	CMM	BUTTERFLY VALVE	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
7CZ105648	--	24-09-204	CMM	not known	01-Dec-68	29-Jan-80	4	--	Titchfield, UK	K2523	*OUT OF PRINT
7CZ105648-2	--	24-09-39+	OM	S-TYPE SEALED RELAYS	28-Jan-71	--	0	--	Titchfield, UK	K2523	--
7CZ105649-2	--	24-09-39+	OM	S-TYPE SEALED RELAYS	28-Jan-71	--	0	--	Titchfield, UK	K2523	--
7CZ105834	--	24-09-206	OM	Relay	07-Jan-66	--	0	--	Titchfield, UK	K2523	--
7CZ105834-4	--	MM171	MM	--	--	--	0	HS 748	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
7CZ106201	--	OSM707	CMM	Control Unit Mk 8	--	01-Jul-73	1	CANBERRA, HUNTER, LIGHTNING, SABRE	Titchfield, UK	K2523	*OUT OF PRINT
7CZ106517	--	24-09-207	CMM	RELAYS	19-Oct-65	--	0	BAC 1-11	Titchfield, UK	K2523	--
7CZ106577	--	24-09-43+	CMM	MAGNETIC INDICATOR	27-Apr-71	--	0	BAC 1-11, SD-330	Titchfield, UK	K2523	--
7CZ106664	--	24-09-401	OM	TRIP FREE CIRCUIT BREAKERS	09-Oct-63	23-Jul-73	3	BAC 1-11, HS 748	Titchfield, UK	K2523	--
7CZ106800/9	--	30-40-40	CMM	CONTROLLER	05-Jan-65	05-Nov-69	8	ARGOSY, HS 748, JETSTREAM	Titchfield, UK	K2523	--
7CZ106800-11	--	30-40-40	CMM	CONTROLLER	05-Jan-65	05-Nov-69	8	ARGOSY, HS 748, JETSTREAM	Titchfield, UK	K2523	--
7CZ106800-19	--	30-40-40	CMM	CONTROLLER	05-Jan-65	05-Nov-69	8	ARGOSY, HS 748, JETSTREAM	Titchfield, UK	K2523	--
7CZ106800-8	--	30-40-40	CMM	CONTROLLER	05-Jan-65	05-Nov-69	8	ARGOSY, HS 748, JETSTREAM	Titchfield, UK	K2523	--
7CZ106800-9	--	30-40-40	CMM	CONTROLLER	05-Jan-65	05-Nov-69	8	ARGOSY, HS 748, JETSTREAM	Titchfield, UK	K2523	--
7CZ106805-1	--	30-40-05	CMM	CONTROLLER TYPE 4 Mk6	01-Aug-60	01-Jan-66	0	Not Known	Titchfield, UK	K2523	--
7CZ107151-2	--	24-09-39+	OM	S-TYPE SEALED RELAYS	28-Jan-71	--	0	--	Titchfield, UK	K2523	--
7CZ107152-2	--	24-09-39+	OM	S-TYPE SEALED RELAYS	28-Jan-71	--	0	--	Titchfield, UK	K2523	--
7CZ107352	--	24-09-201	CMM	RELAYS	--	19-Aug-65	1	BAC 1-11, VC10	Titchfield, UK	K2523	--
7CZ107902-2	--	24-09-39+	OM	S-TYPE SEALED RELAYS	28-Jan-71	--	0	--	Titchfield, UK	K2523	--
7CZ107903-2	--	24-09-39+	OM	S-TYPE SEALED RELAYS	28-Jan-71	--	0	--	Titchfield, UK	K2523	--
7CZ143667	--	24-09-201	CMM	RELAYS	--	19-Aug-65	1	BAC 1-11, VC10	Titchfield, UK	K2523	--
7CZ143684	--	24-09-43+	CMM	MAGNETIC INDICATOR	27-Apr-71	--	0	BAC 1-11, SD-330	Titchfield, UK	K2523	--
7CZ143982-1	--	24-09-351	CMM	THREE-PHASE AUTO TRANSFORMER	05-Nov-66	07-Apr-11	1	BAe ATP, HS 748	Titchfield, UK	K2523	--
7CZ75700	--	OSM706	CMM	HIGH ENERGY IGNITION UNIT	01-May-72	01-Oct-72	1	HUNTER, LIGHTNING, SABRE	Titchfield, UK	K2523	--
7CZ97508-1	--	24-09-201	CMM	RELAYS	--	19-Aug-65	1	BAC 1-11, VC10	Titchfield, UK	K2523	--
8000318C	--	28-10-72+	MM	Maintenance Manual fo 3/8-inch Motorised Shut-Off Valve	05-Jun-91	--	0	--	Titchfield, UK	K2523	BASIC MANUAL

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
8000320C	--	28-21-18	CMM	3/8IN DIA MOTORISED SHUT-OFF VALVE	01-Nov-91	19-Dec-14	3	JS41	Titchfield, UK	K2523	--
8000321F	--	28-21-17+	MM	3/4-inch LP Shut-Off Valve	09-Aug-91	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
8000322F	--	28-21-17	CMM	3/4IN LP MOTORISED SHUT-OFF VALVE	01-Jan-93	06-May-11	3	JS41	Titchfield, UK	K2523	REPL'S ISS DTD 1191
8070002H	--	28-21-84	OM	MULTIWAY SP VALVE	01-Mar-71	24-Aug-07	2	BAE 125	Titchfield, UK	K2523	--
8080013F	--	28-22-04	OM	MULTIWAY SPV	01-Jun-73	01-Jan-85	2	CASA 212	Titchfield, UK	K2523	--
8080033K	--	28-20-82	CMM	SP MULTIWAY VALVE	01-Mar-85	29-Nov-91	4	A300	Titchfield, UK	K2523	--
8084001F	--	38-10-26	CMM	MULTIWAY SPV	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
8084015F	--	38-10-37	OM	MULTIWAY SPV	01-Apr-73	10-Jun-99	1	A300	Titchfield, UK	K2523	--
8084017C	--	38-10-34	OM	MULTIWAY SPV	01-Apr-73	30-Jul-87	1	A300	Titchfield, UK	K2523	--
8084018D	--	38-10-36	OM	MULTIWAY SPV	01-Apr-73	25-Oct-01	2	A300	Titchfield, UK	K2523	--
8084019D	--	38-10-36	OM	MULTIWAY SPV	01-Apr-73	25-Oct-01	2	A300	Titchfield, UK	K2523	--
8084020C	--	38-10-34	OM	MULTIWAY SPV	01-Apr-73	30-Jul-87	1	A300	Titchfield, UK	K2523	--
8084021C	--	38-10-34	OM	MULTIWAY SPV	01-Apr-73	30-Jul-87	1	A300	Titchfield, UK	K2523	--
8084022C	--	38-10-35	OM	MULTIWAY SPV	28-Mar-73	--	0	A300	Titchfield, UK	K2523	--
8084023D	--	38-10-36	OM	MULTIWAY SPV	01-Apr-73	25-Oct-01	2	A300	Titchfield, UK	K2523	--
8084024D	--	38-10-36	OM	MULTIWAY SPV	01-Apr-73	25-Oct-01	2	A300	Titchfield, UK	K2523	--
8084032C	--	38-10-42	OM	MULTIWAY SPV	11-Aug-76	20-Jun-14	2	A300	Titchfield, UK	K2523	--
8084036H	--	38-10-64	CMM	MULTIWAY SPV	30-Oct-87	15-Dec-10	5	A300, A300-400, A300-600, A310	Titchfield, UK	K2523	--
8084036H	--	SIL-CS-9-06	SIL	V Band 9406556 Vband Assy	29-Oct-06	--	0	A300, A300-600, A310, A320	Titchfield, UK	K2523	--
8084037F	--	38-30-53	CMM	MULTIWAY FLUSHING VALVE	01-Aug-80	--	0	A300	Titchfield, UK	K2523	--
8084038F	--	38-30-52	CMM	MULTIWAY SPV	15-Aug-80	--	0	A300	Titchfield, UK	K2523	--

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
8084040H	--	38-10-65	CMM	MULTIWAY SPV	01-Sep-81	04-Aug-00	5	A300, A300-600, A310	Titchfield, UK	K2523	--
8084041E	--	82-10-02	CMM	3 WAY MANUAL SPV	01-Oct-83	08-Jul-11	2	JS31, JS32	Titchfield, UK	K2523	--
8084042H	--	38-10-47	CMM	FILL OVERFLOW DRAIN VALVE - MANUAL	01-Apr-87	--	0	Not Known	Titchfield, UK	K2523	--
8084044H	--	38-10-49	CMM	FILL/OVERFLOW DRAIN VALVE	01-Feb-88	30-Mar-90	3	A320	Titchfield, UK	K2523	--
8084240H	--	38-10-63	CMM	MOTORISED SPV	01-Oct-81	30-Oct-87	3	A300, A300-400, A300-600, A310	Titchfield, UK	K2523	--
8084240H	--	SIL-CS-9-06	SIL	V Band 9406556 Vband Assy	29-Oct-06	--	0	A300, A300-600, A310, A320	Titchfield, UK	K2523	--
8084245H	--	38-10-48	CMM	FILL/OVERFLOW DRAIN VALVE	01-Jan-88	14-Mar-03	6	A320	Titchfield, UK	K2523	--
8084246H	--	38-10-48	CMM	FILL/OVERFLOW DRAIN VALVE	01-Jan-88	14-Mar-03	6	A320	Titchfield, UK	K2523	--
8084246H	--	SIL-CS-9-06	SIL	V Band 9406556 Vband Assy	29-Oct-06	--	0	A300, A300-600, A310, A320	Titchfield, UK	K2523	--
8090010C	--	38-10-24++	OM	Manually Operated 10mm Multiway SP Valve	01-Nov-71	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
8090011C	--	38-10-25	OM	MANUALLY OPERATED MULTIWAY SPV	01-Nov-71	--	0	Not Known	Titchfield, UK	K2523	--
8090211M	--	38-10-27	CMM	Motorised Fail/Safe Spherical Plug Valve	01-Jul-80	--	0	--	Titchfield, UK	K2523	DRAFT ONLY
8090212M	--	38-10-27	CMM	Motorised Fail/Safe Spherical Plug Valve	01-Jul-80	--	0	--	Titchfield, UK	K2523	DRAFT ONLY
8090333F	--	fr/acd/11	MM	Pressure Vent Valve	--	--	0	--	Titchfield, UK	K2523	TO BE WRITTEN
812BR04	--	28-22-81	OM	1 1/2' GATE VALVE	18-Feb-99	--	0	Not Known	Titchfield, UK	K2523	--
816BR02	--	28-3-1	CMM	GATE VALVE	--	--	3	NIMROD / COMET	Titchfield, UK	K2523	OUT OF PRINT
816BR02-1	--	28-3-1	CMM	GATE VALVE	--	--	3	NIMROD / COMET	Titchfield, UK	K2523	OUT OF PRINT
816BR02-2	--	28-3-1	CMM	GATE VALVE	--	--	3	NIMROD / COMET	Titchfield, UK	K2523	OUT OF PRINT
824DB01R26	--	28-4-1	CMM	GATE VALVE	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
824FB01R24	--	28-4-1	CMM	GATE VALVE	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
824FB01R26	--	28-4-1	CMM	GATE VALVE	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
824FB01R36	--	28-4-1	CMM	GATE VALVE	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
824FB01R36A	--	28-4-1	CMM	GATE VALVE	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
824FB01R36B	--	28-4-1	CMM	GATE VALVE	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
8902000	--	79-20-02	OM	SCAVENGE OIL FILTER	01-Feb-79	29-Nov-99	7	RB211-22B, RB211-524	Titchfield, UK	K2523	--
8902075	--	79-20-02	OM	SCAVENGE OIL FILTER	01-Feb-79	29-Nov-99	7	RB211-22B, RB211-524	Titchfield, UK	K2523	--
8903000-2	--	28-10-40	OM	DE-AERATION FILTER ASSY	01-Jan-74	--	0	Not Known	Titchfield, UK	K2523	--
8903000-4	--	28-10-41	OM	DE-AERATION FILTER ASSY	01-Jan-74	--	0	Not Known	Titchfield, UK	K2523	--
8903000-5	--	28-20-09	CMM	FILTER BYPASS VALVE ASSY	01-Dec-87	14-Jun-99	3	F100, F70	Titchfield, UK	K2523	--
8903000-5	--	8903000-5-28-1	SB	FILTER/BY-PASS NRV ASSY	15-Oct-96	--	0	F100, F70	Titchfield, UK	K2523	--
8903100-6	--	28-13-06	CMM	FILTER (WITHOUT RELIEF)	12-Jun-95	--	0	N250	Titchfield, UK	K2523	--
9101000-25	--	28-22-56	OM	BURSTING DISC ASSY'S	01-May-74	--	0	Not Known	Titchfield, UK	K2523	--
9101000-26	--	28-22-56	OM	BURSTING DISC ASSY'S	01-May-74	--	0	Not Known	Titchfield, UK	K2523	--
9101000-55	--	82-20-09	CMM	METERING VALVE	01-Jul-83	03-Jun-11	3	JS31, JS32	Titchfield, UK	K2523	--
9201000-1	--	28-Q1-3	OM	FUEL CONTENTS UNIT MK1	01-Jan-64	--	0	Not Known	Titchfield, UK	K2523	--
9201000-100	--	49-70-1	OM	CONTENTS TRANSMITTER	01-Oct-69	--	0	Not Known	Titchfield, UK	K2523	--
9201000-113	--	79-30-11	OM	CONTENTS TRANSMITTER	01-Oct-69	--	0	Not Known	Titchfield, UK	K2523	--
9201000-12	--	38-09-1	OM	CONTENTS TRANSMITTER	03-Jun-66	--	0	Not Known	Titchfield, UK	K2523	--
9201000-123	--	79-30-15	OM	CONTENTS TRANSMITTER	01-Mar-73	--	0	Not Known	Titchfield, UK	K2523	--
9201000-124	--	28-40-99	OM	CONT TRANS/FLUID LEVEL IND UNIT	01-Sep-70	01-Nov-84	3	F27	Titchfield, UK	K2523	--
9201000-124	--	9201000-28-1	SB	INTRO OF NEW FLOAT ASSY	01-Jun-77	--	0	Not Known	Titchfield, UK	K2523	--
9201000-124	--	9201000-28-2	SB	CONTENTS TX - ALTVE SPRING IN RELIEF VALVE	01-Nov-77	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9201000-13	--	38-10-3++	OM	VARIABLE LEVEL FLOAT SWITCH	20-Sep-68	31-Mar-87	3	BAC 1-11	Titchfield, UK	K2523	--
9201000-13	--	9201000-13-38-1	SB	FLOAT SW - INTRO OF NEW REED SW'S & FLOAT ASSY	01-Jul-85	--	0	Not Known	Titchfield, UK	K2523	--
9201000-13	--	9201000-13-38-2	SB	FLOAT SW - INTRO OF NEW IMPROVED FLOAT ASSY	01-Jul-85	--	0	Not Known	Titchfield, UK	K2523	--
9201000-131	--	49-70-02	OM	CONTENTS TRANSMITTER	01-Sep-71	--	0	Not Known	Titchfield, UK	K2523	--
9201000-132	--	79-31-02	OM	CONTENTS TRANSMITTER	01-Oct-77	01-Jul-87	2	CONCORDE	Titchfield, UK	K2523	--
9201000-134	--	82-40-09	OM	CONTENTS TX	01-Oct-75	--	0	Not Known	Titchfield, UK	K2523	--
9201000-137	--	28-41-31	OM	CONTENTS TRANSMITTER	01-May-73	17-Jan-95	1	MB326	Titchfield, UK	K2523	--
9201000-14	--	28-Q1-7	OM	CONTENTS UNIT MK1	01-Oct-64	--	0	Not Known	Titchfield, UK	K2523	--
9201000-145	--	79-30-17	OM	CONTENTS TRANSMITTER	01-Aug-76	--	0	Not Known	Titchfield, UK	K2523	--
9201000-15	--	28-Q1-7	OM	CONTENTS UNIT MK1	01-Oct-64	--	0	Not Known	Titchfield, UK	K2523	--
9201000-152	--	82-40-08	CMM	CONTENTS TRANSMITTER	12-May-99	--	0	Not Known	Titchfield, UK	K2523	--
9201000-155	--	28-41-26	OM	CONTENTS TRANSMITTER	05-Nov-74	16-Oct-14	4	CASA 212	Titchfield, UK	K2523	--
9201000-16	--	28-Q1-7	OM	CONTENTS UNIT MK1	01-Oct-64	--	0	Not Known	Titchfield, UK	K2523	--
9201000-161	--	28-41-26	OM	CONTENTS TRANSMITTER	05-Nov-74	16-Oct-14	4	CASA 212	Titchfield, UK	K2523	--
9201000-162	--	28-41-26	OM	CONTENTS TRANSMITTER	05-Nov-74	16-Oct-14	4	CASA 212	Titchfield, UK	K2523	--
9201000-17	--	28-Q1-7	OM	CONTENTS UNIT MK1	01-Oct-64	--	0	Not Known	Titchfield, UK	K2523	--
9201000-170	--	28-41-53	OM	CONT TRANS & FLUID LEVEL INDICATOR	01-May-76	01-Apr-83	1	Not Known	Titchfield, UK	K2523	--
9201000-170	--	9201000-28-1	SB	INTRO OF NEW FLOAT ASSY	01-Jun-77	--	0	Not Known	Titchfield, UK	K2523	--
9201000-170	--	9201000-28-2	SB	CONTENTS TX - ALTVE SPRING IN RELIEF VALVE	01-Nov-77	--	0	Not Known	Titchfield, UK	K2523	--
9201000-171	--	82-40-07	OM	CONTENTS TRANSMITTER	01-Jul-75	--	0	SD-330	Titchfield, UK	K2523	--
9201000-174	--	28-41-45	OM	CONT TRANS & FLUID LEVEL INDICATOR	01-Sep-75	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9201000-174	--	9201000-28-1	SB	INTRO OF NEW FLOAT ASSY	01-Jun-77	--	0	Not Known	Titchfield, UK	K2523	--
9201000-174	--	9201000-28-2	SB	CONTENTS TX - ALTVE SPRING IN RELIEF VALVE	01-Nov-77	--	0	Not Known	Titchfield, UK	K2523	--
9201000-176	--	28-41-53	OM	CONT TRANS & FLUID LEVEL INDICATOR	01-May-76	01-Apr-83	1	Not Known	Titchfield, UK	K2523	--
9201000-176	--	9201000-28-1	SB	INTRO OF NEW FLOAT ASSY	01-Jun-77	--	0	Not Known	Titchfield, UK	K2523	--
9201000-176	--	9201000-28-2	SB	CONTENTS TX - ALTVE SPRING IN RELIEF VALVE	01-Nov-77	--	0	Not Known	Titchfield, UK	K2523	--
9201000-198	--	28-41-66	OM	CONTENTS TRANSMITTER	01-Feb-78	30-Mar-01	3	F28	Titchfield, UK	K2523	--
9201000-198	--	9201000-28-3	SB	PREVENTION OF NOISE AROUND OUTLET	01-May-78	--	0	Not Known	Titchfield, UK	K2523	--
9201000-198	--	SIL-TP-1-88	SIL	--	01-Nov-88	--	0	--	Titchfield, UK	K2523	*OUT OF PRINT
9201000-199	--	28-41-66	OM	CONTENTS TRANSMITTER	01-Feb-78	30-Mar-01	3	F28	Titchfield, UK	K2523	--
9201000-199	--	9201000-28-3	SB	PREVENTION OF NOISE AROUND OUTLET	01-May-78	--	0	Not Known	Titchfield, UK	K2523	--
9201000-199	--	SIL-TP-1-88	SIL	--	01-Nov-88	--	0	--	Titchfield, UK	K2523	*OUT OF PRINT
9201000-2	--	28-Q1-3	OM	FUEL CONTENTS UNIT MK1	01-Jan-64	--	0	Not Known	Titchfield, UK	K2523	--
9201000-20	--	28-Q1-7	OM	CONTENTS UNIT MK1	01-Oct-64	--	0	Not Known	Titchfield, UK	K2523	--
9201000-200	--	28-41-66	OM	CONTENTS TRANSMITTER	01-Feb-78	30-Mar-01	3	F28	Titchfield, UK	K2523	--
9201000-200	--	9201000-28-3	SB	PREVENTION OF NOISE AROUND OUTLET	01-May-78	--	0	Not Known	Titchfield, UK	K2523	--
9201000-201	--	28-41-66	OM	CONTENTS TRANSMITTER	01-Feb-78	30-Mar-01	3	F28	Titchfield, UK	K2523	--
9201000-201	--	9201000-28-3	SB	PREVENTION OF NOISE AROUND OUTLET	01-May-78	--	0	Not Known	Titchfield, UK	K2523	--
9201000-202	--	28-41-66	OM	CONTENTS TRANSMITTER	01-Feb-78	30-Mar-01	3	F28	Titchfield, UK	K2523	--
9201000-202	--	9201000-28-3	SB	PREVENTION OF NOISE AROUND OUTLET	01-May-78	--	0	Not Known	Titchfield, UK	K2523	--
9201000-206	--	28-41-69	OM	CONT TRANS FLUID LEVEL INDICATOR	01-Oct-78	11-May-01	2	F27	Titchfield, UK	K2523	--
9201000-206	--	9201000-28-3	SB	PREVENTION OF NOISE AROUND OUTLET	01-May-78	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9201000-21	--	28-Q1-8	OM	CONTENTS UNIT MK1	01-Oct-64	--	0	Not Known	Titchfield, UK	K2523	--
9201000-219	--	28-41-83	CMM	CONTENTS TRANSISTER	01-Feb-84	--	0	Not Known	Titchfield, UK	K2523	--
9201000-219	--	9201000-28-4	SB	CONTENTS TX - ENLARGEMENT OF HOLES IN MTG FLANGE	01-Jul-84	--	0	Not Known	Titchfield, UK	K2523	--
9201000-220	--	C.O.R.A. No.106	OM	Contents Transmitter	--	--	0	SEA HARRIER	Titchfield, UK	K2523	TO BE WRITTEN
9201000-221	--	29-30-08	CMM	CONTENTS TRANSMITTER	01-Mar-83	22-Apr-11	3	BAE 146	Titchfield, UK	K2523	--
9201000-226	--	79-01-03	CMM	CONTENTS TRANSMITTER	01-Mar-83	23-Dec-14	9	BAE 146	Titchfield, UK	K2523	--
9201000-235	--	38-10-05	CMM	CONTENTS TRANSMITTER	01-May-85	26-May-05	3	VARIOUS	Titchfield, UK	K2523	--
9201000-238	--	82-40-11	CMM	CONTENTS TX.	01-Sep-83	03-Jun-11	2	JS31, JS32	Titchfield, UK	K2523	--
9201000-243	--	29-30-09	CMM	CONTENTS TRANSMITTER	01-Nov-84	22-Dec-14	6	BAE 146	Titchfield, UK	K2523	--
9201000-244	--	29-30-10	CMM	CONTENTS TRANSMITTER	01-Dec-86	20-Jan-16	4	F50	Titchfield, UK	K2523	--
9201000-245	--	30-10-11	CMM	CONTENTS TX SERIES 245	11-Nov-85	13-Dec-14	6	BAE 125	Titchfield, UK	K2523	--
9201000-260	--	38-10-08	CMM	WATER CONTENTS TRANSMITTER	31-Aug-85	31-Mar-11	2	BAE 146	Titchfield, UK	K2523	--
9201000-263	--	38-10-18	CMM	CONTENTS TX	01-Dec-86	15-Jul-04	3	BAE 146, BAe ATP, JS61	Titchfield, UK	K2523	--
9201000-264	--	82-40-14	CMM	CONTENTS TRANSMITTER	01-Jun-86	03-Jun-11	5	JS31, JS32	Titchfield, UK	K2523	--
9201000-265	--	77-47-03	CMM	CONTENTS TRANSMITTER	01-Jul-86	14-Dec-07	7	TAY ENGINE (F100 AC)	Titchfield, UK	K2523	--
9201000-266	--	38-10-05	CMM	CONTENTS TRANSMITTER	01-May-85	26-May-05	3	VARIOUS	Titchfield, UK	K2523	--
9201000-27	--	79-30-8	OM	OIL CONTENTS TRANSMITTER UNIT	01-Aug-65	--	0	Not Known	Titchfield, UK	K2523	--
9201000-272	--	77-47-03	CMM	CONTENTS TRANSMITTER	01-Jul-86	14-Dec-07	7	TAY ENGINE (F100 AC)	Titchfield, UK	K2523	--
9201000-273	--	30-10-12	CMM	CONTENTS TRANSMITTER	01-Nov-90	01-Apr-98	2	Not Known	Titchfield, UK	K2523	--
9201000-277	--	29-31-05	CMM	CONTENTS TRANSMITTER	01-Nov-91	18-Mar-15	3	JS41	Titchfield, UK	K2523	--
9201000-3	--	28-Q1-3	OM	FUEL CONTENTS UNIT MK1	01-Jan-64	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9201000-4	--	28-Q1-3	OM	FUEL CONTENTS UNIT MK1	01-Jan-64	--	0	Not Known	Titchfield, UK	K2523	--
9201000-47	--	79-30-1	OM	OIL CONTENTS TRANSMITTER UNIT	01-May-67	01-Oct-69	2	Not Known	Titchfield, UK	K2523	--
9201000-48	--	79-30-1	OM	OIL CONTENTS TRANSMITTER UNIT	01-May-67	01-Oct-69	2	Not Known	Titchfield, UK	K2523	--
9201000-5	--	28-Q1-3	OM	FUEL CONTENTS UNIT MK1	01-Jan-64	--	0	Not Known	Titchfield, UK	K2523	--
9201000-50	--	28-40-67	OM	FLUID LEVEL TRANSMITTER	01-Apr-66	01-Sep-69	2	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
9201000-51	--	28-40-67	OM	FLUID LEVEL TRANSMITTER	01-Apr-66	01-Sep-69	2	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
9201000-52	--	28-40-67	OM	FLUID LEVEL TRANSMITTER	01-Apr-66	01-Sep-69	2	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
9201000-53	--	28-40-67	OM	FLUID LEVEL TRANSMITTER	01-Apr-66	01-Sep-69	2	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
9201000-54	--	28-40-67	OM	FLUID LEVEL TRANSMITTER	01-Apr-66	01-Sep-69	2	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
9201000-55	--	28-40-67	OM	FLUID LEVEL TRANSMITTER	01-Apr-66	01-Sep-69	2	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
9201000-56	--	28-40-67	OM	FLUID LEVEL TRANSMITTER	01-Apr-66	01-Sep-69	2	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
9201000-57	--	28-40-67	OM	FLUID LEVEL TRANSMITTER	01-Apr-66	01-Sep-69	2	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
9201000-58	--	28-40-67	OM	FLUID LEVEL TRANSMITTER	01-Apr-66	01-Sep-69	2	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
9201000-66	--	29-11-18791	SB	CONTENTS TX - INTRO HIGH TEMP RANGE RUBBER PARTS	31-Oct-67	--	0	Not Known	Titchfield, UK	K2523	--
9201000-66	--	29-19-9065	SB	CONTENTS TX - INTRO OF SKYDROL RESISTANT COVER	05-Dec-68	18-Jun-69	1	Not Known	Titchfield, UK	K2523	--
9201000-66	--	29-30-06	OM	CONTENTS TRANSMITTER	01-Jan-75	01-Jan-75	5	Not Known	Titchfield, UK	K2523	--
9201000-75	--	29-30-4	OM	CONTENTS TRANSMITTER	01-Nov-66	01-Sep-69	2	Not Known	Titchfield, UK	K2523	--
9201000-76	--	79-30-9	OM	OIL TANK CONTENTS TRANSMITTER	01-Nov-66	--	0	Not Known	Titchfield, UK	K2523	--
9201000-76	--	SIL-TP-1-88	SIL	--	01-Nov-88	--	0	--	Titchfield, UK	K2523	*OUT OF PRINT
9201000-78	--	29-30-5	OM	CONTENTS TRANSMITTER	01-Apr-67	30-Sep-04	6	F100, F28, F70	Titchfield, UK	K2523	--
9201000-78	--	SIL-TP-1-88	SIL	--	01-Nov-88	--	0	--	Titchfield, UK	K2523	*OUT OF PRINT

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9201000-79	--	29-30-5	OM	CONTENTS TRANSMITTER	01-Apr-67	30-Sep-04	6	F100, F28, F70	Titchfield, UK	K2523	--
9201000-79	--	SIL-TP-1-88	SIL	--	01-Nov-88	--	0	--	Titchfield, UK	K2523	*OUT OF PRINT
9201000-83	--	82-40-3	OM	CONTENTS TRANSMITTER	01-Mar-68	01-Oct-69	1	Not Known	Titchfield, UK	K2523	--
9201000-83	--	SIL-TP-1-88	SIL	--	01-Nov-88	--	0	--	Titchfield, UK	K2523	*OUT OF PRINT
9201000-85	--	28-40-99	OM	CONT TRANS/FLUID LEVEL IND UNIT	01-Sep-70	01-Nov-84	3	F27	Titchfield, UK	K2523	--
9201000-85	--	9201000-28-1	SB	INTRO OF NEW FLOAT ASSY	01-Jun-77	--	0	Not Known	Titchfield, UK	K2523	--
9201000-85	--	9201000-28-2	SB	CONTENTS TX - ALTYE SPRING IN RELIEF VALVE	01-Nov-77	--	0	Not Known	Titchfield, UK	K2523	--
9201000-9	--	82-40-1	OM	CONTENTS TRANSMITTER	01-Sep-64	--	0	BAC 1-11	Titchfield, UK	K2523	--
9201000-95	--	30-10-10	OM	CONTENTS TRANSMITTER	01-Jan-70	30-Oct-07	5	BAE 125	Titchfield, UK	K2523	--
9201000-98	--	28-40-88	OM	CONTENTS TRANSMITTER	01-Apr-68	--	0	Not Known	Titchfield, UK	K2523	--
9201137	--	38-09-1	OM	CONTENTS TRANSMITTER	03-Jun-66	--	0	Not Known	Titchfield, UK	K2523	--
9201843	--	28-41-70	OM	GRADUATED TUBE ASSY'S	01-Nov-78	--	0	F27	Titchfield, UK	K2523	--
9202255	--	28-41-70	OM	GRADUATED TUBE ASSY'S	01-Nov-78	--	0	F27	Titchfield, UK	K2523	--
9202595	--	28-41-70	OM	GRADUATED TUBE ASSY'S	01-Nov-78	--	0	F27	Titchfield, UK	K2523	--
9202631	--	28-41-70	OM	GRADUATED TUBE ASSY'S	01-Nov-78	--	0	F27	Titchfield, UK	K2523	--
9202716	--	28-41-70	OM	GRADUATED TUBE ASSY'S	01-Nov-78	--	0	F27	Titchfield, UK	K2523	--
9300020	--	28-20-51	CMM	1IN SPV WITH NRV	01-Aug-84	25-Nov-11	3	HAWK, Hawk 132 (HAL), Hawk T-165 (SAUDI)	Titchfield, UK	K2523	BAE to approve
9300020	--	HW5B-41-13	CMM	1in Spherical Plug Valve with Non-Return Flap (Finnish AF)	01-Aug-84	12-Apr-99	2	HAWK	Titchfield, UK	K2523	BASIC MANUAL
9300026	--	28-20-43	CMM	BOOSTER PUMP BY-PASS VALVE	01-Jun-84	28-Oct-05	5	HAWK	Titchfield, UK	K2523	(5copies) AQ version - Finnish
9300026	--	28-20-43+	CMM	swiss BOOSTER PUMP BY-PASS VALVE	01-Jun-84	28-Oct-05	5	HAWK	Titchfield, UK	K2523	D NOT USE - OBSOLETE SWISS VERSION
9300036	--	29-11-06	CMM	COUPLED MOTORISED VALVE	01-Aug-86	10-Dec-93	4	F100, F70	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9300141	--	29-11-07	CMM	COUPLED 1IN & 5/8IN SPV	01-Apr-92	14-Jul-98	1	F100, F70	Titchfield, UK	K2523	--
9300141	--	9300141-29-1	SB	COUPLED 1IN AND 5/8IN SPV - LEAKAGE PROBLEM	08-Jul-98	--	0	F100, F70	Titchfield, UK	K2523	--
9300143	--	29-11-08	CMM	1IN-5/8IN COUPLED SP VALVE	20-Dec-93	--	0	F100	Titchfield, UK	K2523	--
9300210	--	29-10-01	OM	MOTORISED HP/LP HYDRAULIC SPV	01-Feb-74	01-Aug-84	1	BAe 748	Titchfield, UK	K2523	--
9300210	--	29-11-9399-038	SB	HP/LP VALVE - MOD NO 9399-038	--	--	0	Not Known	Titchfield, UK	K2523	--
9300213	--	110M21-28-1	SB	MOT. VALVES - ALTVE ELECTRIC MOTORS	01-Apr-77	01-Mar-81	1	Not Known	Titchfield, UK	K2523	--
9300213	--	29-11-03	OM	COUPLED MOTORISED VALVE	01-Apr-75	22-Feb-00	2	F28	Titchfield, UK	K2523	--
9300216	--	29-11-06	CMM	COUPLED MOTORISED VALVE	01-Aug-86	10-Dec-93	4	F100, F70	Titchfield, UK	K2523	--
9300216	--	9300216-29-1	SB	INTRO OF A NEW ACTUATOR AND COUPLED VALVE	29-Nov-93	07-Jan-04	1	F100	Titchfield, UK	K2523	--
9300227	--	29-10-04	CMM	MOTORISED HP/LP HYDRAULIC SPV	18-Feb-85	18-Mar-11	2	BAe 748	Titchfield, UK	K2523	--
9300237	--	28-88-48	CMM	2 1/2 / 3 1/2 IN MOTORISED VALVE	01-Feb-88	21-Jan-97	2	MK 32 POD	Titchfield, UK	K2523	EX MIL SYS DIV
9300244	--	28-26-22	CMM	Booster Pump By-Pass Valve	06-Aug-12	--	0	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	TCH (pub NOT PN)=HAL, BAE for info only
9300618	--	24-09-48	CMM	MOTOR UNIT	01-Feb-88	01-Dec-99	4	MK 32 POD	Titchfield, UK	K2523	MIL SYSTEMS DIV
9301206	--	21-40-01	OM	SPV (PLUG-IN TYPE WITH A.C. MOTOR)	01-Nov-70	--	0	Not Known	Titchfield, UK	K2523	--
9301209	--	21-40-73	OM	FUEL THROTTLE VALVE(WITH CANISTER)	01-Feb-75	--	0	Not Known	Titchfield, UK	K2523	--
9301209	--	9301209-21-1	SB	FUEL THROTTLE VALVE - CHANGE OF GREASE	01-Mar-77	--	0	Not Known	Titchfield, UK	K2523	--
9350021	--	38-30-25	CMM	DRAIN VALVE	29-Oct-82	14-Oct-14	9	A300, A300-400, A300-600, A310, A319, A320, A321, A330, A340, F100, F50, F70	Titchfield, UK	K2523	--
9350021	--	SIL-PS-5-96	SIL	WASTE WATER DRAIN VALVE-BIOLOGICAL CONTAMINATION	25-Apr-97	23-Apr-13	4	A310, A319, A319CJ, A320, A321, A330, A340, A340-500, A340-600, F100, F70	Titchfield, UK	K2523	--
9350022	--	38-30-25	CMM	DRAIN VALVE	29-Oct-82	14-Oct-14	9	A300, A300-400, A300-600, A310, A319, A320, A321, A330, A340, F100, F50, F70	Titchfield, UK	K2523	--
9350022	--	SIL-PS-5-96	SIL	WASTE WATER DRAIN VALVE-BIOLOGICAL CONTAMINATION	25-Apr-97	23-Apr-13	4	A310, A319, A319CJ, A320, A321, A330, A340, A340-500, A340-600, F100, F70	Titchfield, UK	K2523	--
9350024	--	38-30-27	CMM	DRAIN VALVE	01-Nov-87	20-Sep-91	2	A300-600, A310, A320, F100, MD11	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9350024	--	SIL-PS-5-96	SIL	WASTE WATER DRAIN VALVE-BIOLOGICAL CONTAMINATION	25-Apr-97	23-Apr-13	4	A310, A319, A319CJ, A320, A321, A330, A340, A340-500, A340-600, F100, F70	Titchfield, UK	K2523	--
9350024	--	SIL-TP-2-91	SIL	--	20-Jun-91	--	0	--	Titchfield, UK	K2523	*OUT OF PRINT
9350025	--	38-30-28	CMM	DRAIN VALVE	01-Nov-87	01-Jul-88	1	F100	Titchfield, UK	K2523	--
9350025	--	SIL-PS-5-96	SIL	WASTE WATER DRAIN VALVE-BIOLOGICAL CONTAMINATION	25-Apr-97	23-Apr-13	4	A310, A319, A319CJ, A320, A321, A330, A340, A340-500, A340-600, F100, F70	Titchfield, UK	K2523	--
9350028	--	38-32-42	CMM	WASTE WATER DRAIN VALVE	01-Jul-91	01-Dec-91	1	A321	Titchfield, UK	K2523	--
9350028	--	SIL-PS-5-96	SIL	WASTE WATER DRAIN VALVE-BIOLOGICAL CONTAMINATION	25-Apr-97	23-Apr-13	4	A310, A319, A319CJ, A320, A321, A330, A340, A340-500, A340-600, F100, F70	Titchfield, UK	K2523	--
9350127	--	25-53-02	CMM	DRAIN VALVE (CARGO HOLD)	01-Feb-90	11-Feb-19	5	A319, A320, A321	Titchfield, UK	K2523	--
9350140	--	38-30-29	CMM	WATER WASTE DRAIN VALVE WITH NRV	21-Feb-97	15-Jun-04	1	A330, A340	Titchfield, UK	K2523	--
9350140	--	SIL-PS-5-96	SIL	WASTE WATER DRAIN VALVE-BIOLOGICAL CONTAMINATION	25-Apr-97	23-Apr-13	4	A310, A319, A319CJ, A320, A321, A330, A340, A340-500, A340-600, F100, F70	Titchfield, UK	K2523	--
9401011	--	24-09-13	OM	LIGHTWEIGHT MOTOR UNIT	01-Aug-70	01-May-71	1	Not Known	Titchfield, UK	K2523	--
9401011	--	28-33-8882	SB	LW MOTOR UNITS - IMPROVED TAB WASHER	01-Feb-71	01-Apr-71	1	Not Known	Titchfield, UK	K2523	--
9401015	--	24-09-36	OM	LIGHTWEIGHT MOTOR UNIT	01-Jan-75	15-Nov-04	1	CONCORDE	Titchfield, UK	K2523	--
9401019	--	24-09-15	OM	LIGHTWEIGHT MOTOR UNIT	01-Sep-70	--	0	Not Known	Titchfield, UK	K2523	--
9401019	--	28-26-9072	SB	LW MOT VALVES - TO IMPROVE O/HAUL LIFE	17-Jun-70	--	0	Not Known	Titchfield, UK	K2523	--
9401022	--	24-09-16	CMM	LIGHTWEIGHT MOTOR UNITS	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
9401023	--	24-09-16	CMM	LIGHTWEIGHT MOTOR UNITS	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
9401037	--	24-09-46	CMM	LIGHT WEIGHT MOTOR UNIT	01-Feb-87	01-Nov-13	6	F100, F50	Titchfield, UK	K2523	--
9402001	--	24-09-24	CMM	MOTOR UNIT	15-Oct-76	--	0	Not Known	Titchfield, UK	K2523	--
9402003	--	24-09-32	OM	MOTOR UNIT & GEARBOX	01-Jul-73	--	0	Not Known	Titchfield, UK	K2523	--
9402005	--	24-09-31	OM	MOTOR UNIT	01-Jul-73	30-Apr-08	1	Not Known	Titchfield, UK	K2523	--
9402006	--	24-09-19	OM	MOTOR UNIT	01-Jun-73	14-Apr-99	1	A300	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9402007	--	24-09-23	CMM	GEARBOX AND ACTUATOR	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
9402008	--	24-09-23	CMM	GEARBOX AND ACTUATOR	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
9402011	--	24-09-30	OM	MOTOR UNIT	01-Jun-74	--	0	Not Known	Titchfield, UK	K2523	--
9402012	--	24-09-28	OM	MOTOR UNIT	01-Jun-74	--	0	Not Known	Titchfield, UK	K2523	--
9402017	--	24-09-35	OM	MOTOR UNITS	01-Jun-77	01-Jun-77	1	Not Known	Titchfield, UK	K2523	--
9402017	--	28-30-12-9092	SB	MOTOR WIRING CHANGE	01-Oct-76	--	0	Not Known	Titchfield, UK	K2523	--
9402020	--	24-09-38	OM	MOTOR UNIT	01-Jul-76	--	0	Not Known	Titchfield, UK	K2523	--
9402021	--	24-09-37	OM	MOTOR UNIT & GEARBOX	01-Jul-76	--	0	Not Known	Titchfield, UK	K2523	--
9402022	--	24-09-35	OM	MOTOR UNITS	01-Jun-77	01-Jun-77	1	Not Known	Titchfield, UK	K2523	--
9404003	--	24-09-20	OM	TWIN MOTOR UNIT	01-Sep-73	16-Feb-04	5	A300	Titchfield, UK	K2523	--
9404011	--	24-09-26	OM	TWIN MOTOR UNIT	01-May-74	--	0	CONCORDE	Titchfield, UK	K2523	--
9406021	--	24-09-40	OM	FLAT ACTUATOR WITH OVERRIDE 0-90DEG	09-Sep-77	13-Oct-14	7	A300, A300-600, A310	Titchfield, UK	K2523	--
9406038	--	24-09-44	CMM	FLAT ACTUATOR	01-Oct-81	18-Apr-16	8	A300, A300-600, A310	Titchfield, UK	K2523	--
9406045	--	24-09-45	CMM	FAILSAFE ACTUATOR	30-Oct-84	22-Jul-11	7	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	BAE to approve as TCH
9406045	--	K2523-24-002	SIL	Introduction of New Motor	--	08-Oct-21	0	Hawk 132 (HAL), MK 32 POD	Titchfield, UK	K2523	TO BE WRITTEN
9406054	--	24-09-47	CMM	ACTUATOR	01-Feb-88	03-Oct-14	4	A320	Titchfield, UK	K2523	--
9406056	--	K2523-24-002	SIL	Introduction of New Motor	--	08-Oct-21	0	Hawk 132 (HAL), MK 32 POD	Titchfield, UK	K2523	TO BE WRITTEN
9406056	--	SIL-2007-04	SIL	SPILL VALVE ASSY CHECK	01-May-07	--	0	MK 32 POD	Titchfield, UK	K2523	REPLACES SIL-CS-11-06
9406056	--	SIL-CS-11-06	SIL	SPILL VALVE ASSY CHECK	--	--	0	MK 32 POD	Titchfield, UK	K2523	*OUT OF PRINT
9406057	--	24-09-47	CMM	ACTUATOR	01-Feb-88	03-Oct-14	4	A320	Titchfield, UK	K2523	--
9406556	--	28-23-05	ACMM	VEE-BAND CLAMP	25-Sep-12	25-Sep-12	0	A310, A310-MK11, A319, A320, A321, A330, A340, A340-500, A340-600, BAE 125, BAE 146, F100-IBATC/EMBANGER	Titchfield, UK	K2523	Re-issued (orig. iss.16-07-91),

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9407001	--	24-09-27	OM	GEARED MOTOR	01-Aug-73	06-Nov-01	1	A300	Titchfield, UK	K2523	--
9407002	--	24-09-34	OM	GEARED MOTOR	01-Aug-73	15-Nov-02	1	A300	Titchfield, UK	K2523	--
9407012	--	24-09-41	OM	MOTOR UNIT	01-Jan-80	18-Mar-11	3	BAe 748	Titchfield, UK	K2523	--
9409019	--	24-09-51	CMM	FLAT ACTUATOR	01-Nov-91	13-Nov-14	5	JS41	Titchfield, UK	K2523	--
9409020	--	24-09-50	CMM	FLAT ACTUATOR	30-Nov-92	05-Dec-14	3	SAAB 2000	Titchfield, UK	K2523	--
9409122	--	24-09-52	CMM	FLAT ACTUATOR	31-Jul-92	13-Dec-14	5	F100, F70	Titchfield, UK	K2523	--
9409122	--	9409122-24-1	SB	ACTUATOR MANUAL CONTROL KNOB - INCREASED TORQUE	29-Oct-98	--	0	F100, F70	Titchfield, UK	K2523	--
9409123	--	24-09-55	CMM	FLAT ACTUATOR	30-Jun-95	--	0	N250	Titchfield, UK	K2523	--
9409124	--	24-09-54	CMM	FLAT ACTUATOR	23-Apr-93	13-Dec-14	4	JS41	Titchfield, UK	K2523	--
9501235	--	28-E1-1	OM	VENT VALVES	01-Mar-63	--	0	Not Known	Titchfield, UK	K2523	--
9501430	--	28-E1-1	OM	VENT VALVES	01-Mar-63	--	0	Not Known	Titchfield, UK	K2523	--
9502135	--	28-10-17	OM	VENT VALVE	01-Jul-68	--	0	Not Known	Titchfield, UK	K2523	--
9502155	--	28-E9-1	OM	VENT VALVES	01-Oct-64	01-Oct-64	1	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
9502165	--	28-E9-1	OM	VENT VALVES	01-Oct-64	01-Oct-64	1	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
9502175	--	28-E9-1	OM	VENT VALVES	01-Oct-64	01-Oct-64	1	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
9502185	--	28-E9-1	OM	VENT VALVES	01-Oct-64	01-Oct-64	1	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
9502200	--	28-E10-1	OM	CUT-OFF VALVE	01-Nov-63	--	0	Not Known	Titchfield, UK	K2523	--
9502215	--	28-E9-1	OM	VENT VALVES	01-Oct-64	01-Oct-64	1	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
9502220	--	28-20-44	OM	CUT-OFF VALVE	01-Oct-64	--	0	Not Known	Titchfield, UK	K2523	--
9502221	--	28-20-44	OM	CUT-OFF VALVE	01-Oct-64	--	0	Not Known	Titchfield, UK	K2523	--
9505000	--	28-10-19	OM	FLOAT DRAIN VALVE	01-Jun-68	01-Aug-82	1	CASA 212, F100, F28, HFB 320 (HANSA JET), SD-330, SD-360	Titchfield, UK	K2523	--

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9505070	--	28-10-22	OM	FLOAT DRAIN VALVE & VENT VALVES	01-Jul-69	--	0	Not Known	Titchfield, UK	K2523	--
9505100	--	28-20-13	CMM	FLOAT DRAIN VALVE	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
9505110	--	28-22-25	TDS	VENT & DRAIN VALVE ASSYS	01-Apr-83	30-Sep-02	2	A300, A300-400, A300-600, A310, A318, A319, A320, A321, A330, A340, A340-500, A340-600, A380	Titchfield, UK	K2523	--
9505195	--	28-10-48	OM	VENT VALVE	01-Sep-76	--	0	Not Known	Titchfield, UK	K2523	--
9505200	--	28-10-48	OM	VENT VALVE	01-Sep-76	--	0	Not Known	Titchfield, UK	K2523	--
9505265	--	28-10-92	CMM	FLOAT DRAIN VALVE	01-Dec-87	01-May-88	1	F100	Titchfield, UK	K2523	--
9505285	--	28-10-94	CMM	DRAIN VALVE	01-Jun-90	01-Jul-91	1	F100	Titchfield, UK	K2523	--
9507080	--	28-10-4271-169	SB	FLOAT VENT VALVE REDUCTION OF FLOAT WEIGHT	23-Apr-67	--	0	Not Known	Titchfield, UK	K2523	--
9507080	--	28-10-7	OM	VENT FLOAT VALVE	01-May-67	01-Feb-89	4	F28	Titchfield, UK	K2523	--
9507080	--	28-37-22785	SB	VENT FLOAT VALVE - NEW FLOAT	01-Dec-72	--	0	Not Known	Titchfield, UK	K2523	--
9507080	--	9507305-28-1	SB	VENT FLOAT VALVE - INTRO OF NEW FLOAT ASSY	01-Jun-84	01-Dec-84	1	Not Known	Titchfield, UK	K2523	THIS SB WAS CANCELLED
9507100	--	28-10-38	OM	AIR NO FUEL VALVE ASSY	01-Jan-74	--	0	Not Known	Titchfield, UK	K2523	--
9507180	--	28-10-22	OM	FLOAT DRAIN VALVE & VENT VALVES	01-Jul-69	--	0	Not Known	Titchfield, UK	K2523	--
9507181	--	28-10-22	OM	FLOAT DRAIN VALVE & VENT VALVES	01-Jul-69	--	0	Not Known	Titchfield, UK	K2523	--
9507230	--	28-10-22	OM	FLOAT DRAIN VALVE & VENT VALVES	01-Jul-69	--	0	Not Known	Titchfield, UK	K2523	--
9507231	--	28-10-22	OM	FLOAT DRAIN VALVE & VENT VALVES	01-Jul-69	--	0	Not Known	Titchfield, UK	K2523	--
9507305	--	28-10-46	OM	VENT FLOAT VALVE	01-Aug-75	22-Feb-89	4	F28	Titchfield, UK	K2523	--
9507305	--	9507305-28-1	SB	VENT FLOAT VALVE - INTRO OF NEW FLOAT ASSY	01-Jun-84	01-Dec-84	1	Not Known	Titchfield, UK	K2523	THIS SB WAS CANCELLED
9507320	--	28-10-42	OM	AIR NO FUEL VALVE ASSY	01-Sep-74	--	0	Not Known	Titchfield, UK	K2523	--
9507320	--	28-10-42-9088	SB	AIR NO FUEL VALVE - IMPROVED ATTACHMENTS	01-Jan-77	--	0	Not Known	Titchfield, UK	K2523	--
9507425	--	28-10-62	CMM	VAPOUR RELEASE VALVE	01-May-91	03-Oct-12	3	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	B Ae to approve

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9507445	--	28-10-93	CMM	VENT VALVE	01-Feb-88	25-Sep-08	5	F100, F70	Titchfield, UK	K2523	--
9508000	--	28-10-3	OM	VENT VALVE	01-Feb-65	--	0	Not Known	Titchfield, UK	K2523	--
9508025	--	28-10-6	OM	VENT VALVE	01-Dec-65	01-Oct-69	1	Not Known	Titchfield, UK	K2523	--
9508069	--	28-10-23	OM	FLOAT VENT VALVE&THERM EXP VENT VA	01-Nov-69	--	0	Not Known	Titchfield, UK	K2523	--
9508070	--	28-10-23	OM	FLOAT VENT VALVE&THERM EXP VENT VA	01-Nov-69	--	0	Not Known	Titchfield, UK	K2523	--
9508090	--	28-10-32	OM	VENT VALVE	01-Mar-72	--	0	Not Known	Titchfield, UK	K2523	--
9508115	--	28-10-74	CMM	AIR NO FUEL VENT VALVE	01-Mar-83	30-Jul-84	1	A300-600, A310	Titchfield, UK	K2523	--
9508155	--	28-10-81	CMM	AIR/NOFUEL VENT VALVE	01-Oct-83	--	0	A310	Titchfield, UK	K2523	S/SEDED BY 9508170
9508170	--	28-10-87	CMM	AIR/NO FUEL VENT VALVE	01-Dec-83	04-Feb-02	4	A300, A300-400, A300-600, A310	Titchfield, UK	K2523	--
9508175	--	28-12-43	CMM	FLOAT VENT VALVE	01-Apr-87	06-Oct-14	5	A319, A320, A321, A330, A340	Titchfield, UK	K2523	--
9509180	--	28-10-39	OM	RELIEF VALVE (TANK)	01-Aug-74	30-Jun-98	1	Not Known	Titchfield, UK	K2523	--
9510045	--	28-10-23	OM	FLOAT VENT VALVE&THERM EXP VENT VA	01-Nov-69	--	0	Not Known	Titchfield, UK	K2523	--
9516000-4	--	28-21-13	CMM	RELIEF VALVE	01-May-87	06-May-11	2	BAe ATP, JS61	Titchfield, UK	K2523	--
9807100	--	28-F98-3	OM	NRV	01-Aug-70	26-May-05	3	BAC 1-11, HFB 320 (HANSA JET), MB326, YS11	Titchfield, UK	K2523	--
9807103	--	28-09-41	OM	NON RETURN VALVE	01-Apr-65	--	0	Not Known	Titchfield, UK	K2523	--
9807103	--	28-09-41-9818	SB	NRV - INTRO OF NEW SPRING	01-Jan-76	--	0	Not Known	Titchfield, UK	K2523	--
9807105	--	28-F98-3	OM	NRV	01-Aug-70	26-May-05	3	BAC 1-11, HFB 320 (HANSA JET), MB326, YS11	Titchfield, UK	K2523	--
9807115	--	28-09-36	OM	NRV	01-Feb-65	--	0	Not Known	Titchfield, UK	K2523	--
9807118	--	28-F98-3	OM	NRV	01-Aug-70	26-May-05	3	BAC 1-11, HFB 320 (HANSA JET), MB326, YS11	Titchfield, UK	K2523	--
9807120	--	28-F98-3	OM	NRV	01-Aug-70	26-May-05	3	BAC 1-11, HFB 320 (HANSA JET), MB326, YS11	Titchfield, UK	K2523	--
9807135	--	28-F98-8	OM	1 1/4" NRV	01-Nov-60	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9807170F	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9807170G	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9807170H	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9807170I	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9807170J	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9807170K	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9807170L	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9807170M	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9807170N	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9807170O	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9807170P	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9807170Q	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9807170R	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9807170S	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9807170T	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9807170U	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9807170V	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9807175	--	28-F98-3	OM	NRV	01-Aug-70	26-May-05	3	BAC 1-11, HFB 320 (HANSA JET), MB326, YS11	Titchfield, UK	K2523	--
9807180	--	28-F98-3	OM	NRV	01-Aug-70	26-May-05	3	BAC 1-11, HFB 320 (HANSA JET), MB326, YS11	Titchfield, UK	K2523	--
9807200	--	28-F98-12	OM	NRV 1 1/2 IN	01-Jan-63	--	0	Not Known	Titchfield, UK	K2523	--
9807210F	--	28-09-83	OM	NRV	01-Mar-74	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9807210H	--	28-09-83	OM	NRV	01-Mar-74	--	0	Not Known	Titchfield, UK	K2523	--
9807235	--	28-F98-5	OM	NRV 4 IN	01-May-62	--	0	Not Known	Titchfield, UK	K2523	--
9807285-1	--	28-09-53	OM	RESTRICTOR VARIABLE	01-Sep-68	--	0	Not Known	Titchfield, UK	K2523	--
9807285-2	--	28-09-53	OM	RESTRICTOR VARIABLE	01-Sep-68	--	0	Not Known	Titchfield, UK	K2523	--
9807285-3	--	28-09-53	OM	RESTRICTOR VARIABLE	01-Sep-68	--	0	Not Known	Titchfield, UK	K2523	--
9807285-4	--	28-09-53	OM	RESTRICTOR VARIABLE	01-Sep-68	--	0	Not Known	Titchfield, UK	K2523	--
9807295M	--	28-F98-17	OM	NRV 2IN	01-Jan-63	--	0	BAC 1-11	Titchfield, UK	K2523	--
9807310	--	28-F98-21	OM	NRV 1 IN	01-Nov-63	--	0	Not Known	Titchfield, UK	K2523	--
9807320J	--	28-08-01	CMM	NRV 1 1/4 IN	10-Feb-83	--	0	BAE 125	Titchfield, UK	K2523	--
9807325	--	28-09-50	OM	NRV 1 1/2 IN	01-Jul-68	--	0	Not Known	Titchfield, UK	K2523	--
9807330	--	28-F98-20	OM	1 1/2' NRV	01-Nov-63	01-Feb-85	1	BAC 1-11	Titchfield, UK	K2523	--
9807335	--	28-F98-20	OM	1 1/2' NRV	01-Nov-63	01-Feb-85	1	BAC 1-11	Titchfield, UK	K2523	--
9807350	--	28-09-84	OM	NRV	01-Mar-74	--	0	Not Known	Titchfield, UK	K2523	--
9807360	--	28-09-84	OM	NRV	01-Mar-74	--	0	Not Known	Titchfield, UK	K2523	--
9807365	--	28-09-64	OM	1 1/2 IN (40MM) NRV'S	01-May-71	02-May-95	1	BAC 1-11, VC10	Titchfield, UK	K2523	--
9807370	--	28-10-69	CMM	IRREVERSIBLE NRV'S (ANTI-ICING)	01-May-85	18-Mar-11	1	BAe 748	Titchfield, UK	K2523	--
9807380	--	28-10-69	CMM	IRREVERSIBLE NRV'S (ANTI-ICING)	01-May-85	18-Mar-11	1	BAe 748	Titchfield, UK	K2523	--
9807385	--	28-F98-20	OM	1 1/2' NRV	01-Nov-63	01-Feb-85	1	BAC 1-11	Titchfield, UK	K2523	--
9807440	--	28-F98-29	OM	NRV	01-Jun-64	--	0	BAC 1-11	Titchfield, UK	K2523	--
9807455	--	28-09-82	OM	NRV	18-Feb-74	--	0	Not Known	Titchfield, UK	K2523	--
9807460	--	28-09-38	OM	NRV	01-Nov-64	--	0	BAC 1-11	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9807480M	--	28-09-40	OM	NRV'S	01-Feb-65	--	0	BAC 1-11	Titchfield, UK	K2523	--
9807485L	--	28-09-40	OM	NRV'S	01-Feb-65	--	0	BAC 1-11	Titchfield, UK	K2523	--
9807490	--	28-09-38	OM	NRV	01-Nov-64	--	0	BAC 1-11	Titchfield, UK	K2523	--
9807520	--	28-09-43	OM	NRV	01-Sep-65	--	0	Not Known	Titchfield, UK	K2523	--
9807535	--	28-09-42	OM	NRV	01-Apr-69	01-Apr-69	1	BAC 1-11	Titchfield, UK	K2523	--
9807540	--	28-09-42	OM	NRV	01-Apr-69	01-Apr-69	1	BAC 1-11	Titchfield, UK	K2523	--
9807580	--	28-09-44	OM	NRV	01-May-66	--	0	A310, BAC 1-11	Titchfield, UK	K2523	BASIC MANUAL
9807660	--	28-09-67	OM	25.4MM (1 IN) NRV	01-Mar-72	--	0	Not Known, VFW 614	Titchfield, UK	K2523	--
9807700	--	28-09-64	OM	1 1/2 IN (40MM) NRV'S	01-May-71	02-May-95	1	BAC 1-11, VC10	Titchfield, UK	K2523	--
9807735	--	28-09-66	OM	NRV	01-Feb-71	30-Sep-04	3	F28	Titchfield, UK	K2523	--
9807735	--	28-35-22485	SB	NRV - NEW VALVE HEAD ASSY	01-Feb-72	--	0	Not Known	Titchfield, UK	K2523	--
9807740	--	28-09-65	OM	NRV'S	01-Jan-71	--	0	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
9807765	--	28-41-95	OM	NRV	01-Sep-78	--	0	VANGUARD	Titchfield, UK	K2523	--
9807835	--	28-10-49	OM	25MM (1 IN) NRV	01-Dec-77	01-Oct-88	2	Not Known	Titchfield, UK	K2523	--
9807870	--	28-09-96	OM	1.25 IN NRV	01-May-77	01-Nov-84	2	HS 125	Titchfield, UK	K2523	--
9809040	--	28-F98-22	OM	NRV	01-Nov-63	--	0	Not Known	Titchfield, UK	K2523	--
9809060	--	28-09-83	OM	NRV	01-Mar-74	--	0	Not Known	Titchfield, UK	K2523	--
9809075	--	28-09-37	OM	NRV'S	01-Nov-65	01-Aug-69	2	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
9809090	--	28-09-46	OM	NRV	01-Oct-66	--	0	Not Known	Titchfield, UK	K2523	--
9810020	--	28-F98-7	OM	NRV'S	01-Oct-60	--	0	Not Known	Titchfield, UK	K2523	--
9810110	--	28-F98-6	OM	NRV	01-Jul-60	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9810160	--	28-F98-7	OM	NRV'S	01-Oct-60	--	0	Not Known	Titchfield, UK	K2523	--
9810169	--	28-F98-7	OM	NRV'S	01-Oct-60	--	0	Not Known	Titchfield, UK	K2523	--
9810234J	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9810235J	--	28-F98-9	OM	NRV	01-Oct-60	01-Aug-64	1	BAC 1-11, BAE 125	Titchfield, UK	K2523	--
9810260	--	28-09-39	OM	NRV	01-Jan-65	--	0	Not Known	Titchfield, UK	K2523	--
9810265	--	28-F98-27	OM	NRV 2 IN	01-Mar-64	--	0	Not Known	Titchfield, UK	K2523	--
9810296	--	28-21-15	CMM	NRV MANIFOLD	28-Oct-91	06-May-11	1	JS41	Titchfield, UK	K2523	--
9811000	--	28-F98-4	OM	NRV (WITH SCREWED ENDS)	01-Sep-60	01-Aug-68	1	BAC 1-11	Titchfield, UK	K2523	--
9811070	--	F98-11-070	SL	NRV 1 IN	01-Jul-58	--	0	Not Known	Titchfield, UK	K2523	--
98111025	--	38-31-12	CMM	3/4in NON RETURN VALVE	30-Nov-93	05-Mar-14	2	A320, A321, A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
98111035	--	28-22-17	CMM	NON-RETURN VALVE	10-Apr-95	29-Jul-97	1	N250	Titchfield, UK	K2523	--
9811105	--	28-F98-13	OM	NRV 1 1/4 IN	01-Jan-61	--	0	Not Known	Titchfield, UK	K2523	--
98111085	--	28-23-48	CMM	1/2 INCH NON-RETURN VALVE	21-Mar-97	--	0	N250	Titchfield, UK	K2523	--
98111130	--	28-23-43+	CMM	1/2IN NON-RETURN VALVE ASSEMBLY	26-Mar-96	--	0	N250	Titchfield, UK	K2523	DUPLICATE ATA NO
9811116	--	28-F98-4	OM	NRV (WITH SCREWED ENDS)	01-Sep-60	01-Aug-68	1	BAC 1-11	Titchfield, UK	K2523	--
9811172	--	28-F98-11	OM	1/2 IN NRV	01-Nov-60	--	0	Not Known	Titchfield, UK	K2523	--
9811176	--	28-F98-4	OM	NRV (WITH SCREWED ENDS)	01-Sep-60	01-Aug-68	1	BAC 1-11	Titchfield, UK	K2523	--
9811215	--	28-F98-10	OM	NRV'S	01-Oct-60	01-Jul-84	2	Not Known	Titchfield, UK	K2523	--
9811220	--	28-F98-10	OM	NRV'S	01-Oct-60	01-Jul-84	2	Not Known	Titchfield, UK	K2523	--
9811240	--	28-F98-4	OM	NRV (WITH SCREWED ENDS)	01-Sep-60	01-Aug-68	1	BAC 1-11	Titchfield, UK	K2523	--
9811245	--	28-F98-10	OM	NRV'S	01-Oct-60	01-Jul-84	2	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9811246	--	28-09-86	OM	NRV (LEAK BACK)	01-Feb-74	--	0	Not Known	Titchfield, UK	K2523	--
9811290	--	70-09-5	CMM	NRV	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
9811305	--	70-09-5	CMM	NRV	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
9811395	--	28-F98-26	OM	NRV	01-Feb-64	--	0	BAC 1-11	Titchfield, UK	K2523	--
9811420	--	28-F98-24	OM	NRV 3/4 IN	01-Jan-63	01-May-64	1	Not Known	Titchfield, UK	K2523	--
9811475	--	28-09-49	OM	NRV	16-Jun-67	01-Oct-83	1	BAE 125	Titchfield, UK	K2523	--
9811485	--	28-09-60	OM	NRV	01-Jan-70	--	0	Not Known	Titchfield, UK	K2523	--
9811495	--	28-22-01	OM	NRV	01-Oct-73	02-Aug-07	2	AVIOKA (C.212), CASA 212	Titchfield, UK	K2523	--
9811505	--	28-22-02	OM	NRV	12-Oct-73	25-Mar-13	4	CASA 212	Titchfield, UK	K2523	--
9811530	--	28-09-65	OM	NRV'S	01-Jan-71	--	0	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
9811550	--	28-09-89	OM	NRV	01-Mar-75	14-Aug-08	3	EH101, LYNX	Titchfield, UK	K2523	WTP106D-003
9811560	--	38-10-30	OM	NRV	04-May-73	--	0	A300, A310	Titchfield, UK	K2523	--
9811585	--	38-10-30	OM	NRV	04-May-73	--	0	A300, A310	Titchfield, UK	K2523	--
9811625	--	28-09-94	CMM	NRV	--	--	0	Not Known	Titchfield, UK	K2523	BASIC MANUAL
9811630	--	28-09-94	CMM	NRV	--	--	0	Not Known	Titchfield, UK	K2523	BASIC MANUAL
9811635	--	28-09-94	CMM	NRV	--	--	0	Not Known	Titchfield, UK	K2523	BASIC MANUAL
9811640	--	28-09-94	CMM	NRV	--	--	0	Not Known	Titchfield, UK	K2523	BASIC MANUAL
9811690	--	28-23-37	CMM	NRV	15-Jul-82	06-May-11	1	JS31, JS32	Titchfield, UK	K2523	--
9811705	--	28-23-33	CMM	AUTO PURGE VALVE	01-Dec-82	01-Jan-84	1	SD-360	Titchfield, UK	K2523	--
9811715	--	28-23-32	CMM	PRESSURE MAINTAINING VALVE	31-Oct-82	06-May-11	1	BAe 748	Titchfield, UK	K2523	--
9811760	--	28-21-43	CMM	VALVE NR	01-Mar-87	01-Jun-92	2	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9811778	--	9811778-38-1	SB	POTABLE WATER SYSTEM - AIR RELIEF VALVE	01-Nov-88	--	0	Not Known	Titchfield, UK	K2523	Date was 01-03-90
9811784	--	28-20-08	CMM	NRV	01-Jun-86	22-Apr-11	3	BAE 146	Titchfield, UK	K2523	--
9811820	--	28-16-42	CMM	CHECK VALVE	01-Jun-87	12-Apr-07	6	A318, A319, A320, A321, A340	Titchfield, UK	K2523	--
9811820	--	9811820-28-1	SB	CHECK VALVE - NEW SPECIFICATION FOR O-RING	20-Oct-95	--	0	A319, A319CJ, A320, A321, A340	Titchfield, UK	K2523	--
9811825	--	28-21-43	CMM	VALVE NR	01-Mar-87	01-Jun-92	2	Not Known	Titchfield, UK	K2523	--
9811827	--	28-21-43	CMM	VALVE NR	01-Mar-87	01-Jun-92	2	Not Known	Titchfield, UK	K2523	--
9811839	--	28-21-44	CMM	1/2IN NON-RETURN VALVE	01-Sep-87	23-Apr-04	3	A319, A320, A321	Titchfield, UK	K2523	--
9811880	--	38-10-19	CMM	AIR RELIEF VALVE	01-Sep-86	13-May-11	4	BAe ATP, JS61	Titchfield, UK	K2523	S/SDS BY 9811778
9811880	--	9811778-38-1	SB	POTABLE WATER SYSTEM - AIR RELIEF VALVE	01-Nov-88	--	0	Not Known	Titchfield, UK	K2523	Date was 01-03-90
9811916	--	28-21-55	CMM	SUCTION INLET VALVE	30-Nov-92	--	0	SAAB 2000	Titchfield, UK	K2523	--
9811920	--	28-21-19	CMM	3/8IN NON-RETURN VALVE	12-Nov-91	06-May-11	1	JS41	Titchfield, UK	K2523	--
9811935	--	28-21-56	CMM	NON-RETURN (POPPET) VALVE	01-Nov-92	15-Apr-99	1	JSF, SAAB 2000	Titchfield, UK	K2523	--
9811950	--	38-31-11	CMM	3/4IN NON-RETURN VALVE	12-Dec-91	18-Jan-11	2	A330, A340	Titchfield, UK	K2523	--
9812050	--	28-E3-1	OM	WATER VENT VALVE	01-Nov-60	--	0	Not Known	Titchfield, UK	K2523	--
9812065	--	38-E1-1	OM	WATER VENT VALVE	01-Nov-62	--	0	Not Known	Titchfield, UK	K2523	--
9812120	--	38-30-54	CMM	AIR/NOWATER VENT VALVE	14-Jan-81	--	0	A310	Titchfield, UK	K2523	--
9813014	--	28-09-85	OM	NON-RETURN VALVE	01-Feb-74	--	0	Not Known	Titchfield, UK	K2523	--
9813170	--	28-22-68	OM	SHUTTLE VALVE	01-Feb-74	--	0	Not Known	Titchfield, UK	K2523	--
9813195	--	28-22-07	OM	SHUTTLE VALVE	01-Oct-71	--	0	MB326	Titchfield, UK	K2523	--
9813200	--	38-10-38	OM	SHUTTLE VALVE	01-May-73	--	0	Not Known	Titchfield, UK	K2523	--
9813215	--	38-10-39	OM	SHUTTLE VALVE	01-Mar-75	21-Jun-89	3	A300, A300-400, A300-600, A310	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
 techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9813275	--	28-21-06	CMM	SHUTTLE VALVE	01-Feb-84	--	0	Not Known	Titchfield, UK	K2523	--
9813285	--	82-20-08	CMM	PRES.MAINT VALVE	01-Sep-83	03-Jun-11	2	JS31, JS32	Titchfield, UK	K2523	--
9813395	--	28-21-41	CMM	AIR RELEASE VALVE	01-Aug-87	05-Nov-15	12	A318, A319, A320, A321, A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
9813395	--	9813365-28-1	SB	AIR RELEASE VALVE - MODIFIED VALVE TO MEET SPEC	01-Apr-88	01-Apr-88	2	A320	Titchfield, UK	K2523	--
9813395	--	9813395-28-1	SB	AIR RELEASE VALVE-MODIFICATION TO UPPER BODY ASSY	03-Jan-96	--	0	A320	Titchfield, UK	K2523	--
9813395	--	9813445-28-2	SB	FLOAT ASSY SPECIFIC GRAVITY	30-Mar-04	--	0	A319, A320, A321	Titchfield, UK	K2523	--
9813405	--	28-25-72	CMM	CHECK VALVE, RESTRICTOR ASSEMBLY	01-Mar-91	11-Aug-97	2	A300-600, A310, A321, A330, A340	Titchfield, UK	K2523	--
9813445	--	28-21-41	CMM	AIR RELEASE VALVE	01-Aug-87	05-Nov-15	12	A318, A319, A320, A321, A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
9813445	--	9813395-28-1	SB	AIR RELEASE VALVE-MODIFICATION TO UPPER BODY ASSY	03-Jan-96	--	0	A320	Titchfield, UK	K2523	--
9813445	--	9813445-28-1	SB	AIR RELEASE VALVE-FLOAT ASSY SPECIFIC GRAVITY	25-Nov-96	--	0	A320, A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
9813445	--	9813445-28-2	SB	FLOAT ASSY SPECIFIC GRAVITY	30-Mar-04	--	0	A319, A320, A321	Titchfield, UK	K2523	--
9815000	--	28-E2-1	OM	OUTWARD VENT VALVE	01-Apr-61	--	0	Not Known	Titchfield, UK	K2523	--
9815056	--	28-20-14	OM	TRANSFER RATE CONTROL VALVES	01-Jan-67	01-Feb-84	1	BAC 1-11	Titchfield, UK	K2523	--
9815145	--	28-20-37	CMM	OUTWARD VENT VALVE	01-Sep-68	--	0	A340	Titchfield, UK	K2523	--
9815150	--	28-20-14	OM	TRANSFER RATE CONTROL VALVES	01-Jan-67	01-Feb-84	1	BAC 1-11	Titchfield, UK	K2523	--
9815150	--	28-8-4271-171	SB	TRNSFR RATE CONTROL VALVE - NEW RELIEF SPRING	25-Oct-67	--	1	Not Known	Titchfield, UK	K2523	--
9815155	--	28-20-17	OM	PRES MAINT VALVE	01-Jan-65	--	0	BAC 1-11	Titchfield, UK	K2523	--
9815160	--	28-20-38	OM	VENT VALVE	01-Sep-68	--	0	ISLANDER/TRISLANDER	Titchfield, UK	K2523	--
9815200	--	28-20-38	OM	VENT VALVE	01-Sep-68	--	0	ISLANDER/TRISLANDER	Titchfield, UK	K2523	--
9815245	--	28-20-59	OM	RELIEF VALVE	01-Aug-68	--	0	Not Known	Titchfield, UK	K2523	--
9815260	--	28-12-04	OM	PRV	01-Feb-70	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9815275	--	28-20-38	OM	VENT VALVE	01-Sep-68	--	0	ISLANDER/TRISLANDER	Titchfield, UK	K2523	--
9815350	--	28-20-27	OM	TRANSFER RATE CONTROL VALVE	01-Oct-67	--	0	BAC 1-11	Titchfield, UK	K2523	--
9815350	--	28-8-4271-171	SB	TRNSFR RATE CONTROL VALVE - NEW RELIEF SPRING	25-Oct-67	--	1	Not Known	Titchfield, UK	K2523	--
9815490	--	28-22-96	OM	VENT VALVE	01-Apr-76	--	0	SHORTS SC7 SKYVAN	Titchfield, UK	K2523	--
9815500	--	28-09-90	OM	NRV (PRESSURE MAINTAINING)	01-Jan-75	20-Dec-96	1	CONCORDE	Titchfield, UK	K2523	--
9815500	--	9815500-28-1	SB	NRV - PREVENTION OF SPIDER ROTATION	01-Sep-77	--	0	CONCORDE	Titchfield, UK	K2523	--
9815630	--	28-10-84	CMM	VENT VALVE	01-Apr-84	--	0	HAWK	Titchfield, UK	K2523	--
9815675	--	28-10-85	CMM	INWARD/OUTWARD VALVE	01-Nov-83	--	0	Not Known	Titchfield, UK	K2523	--
9815690	--	79-10-23	CMM	INWARD/OUTWARD RELIEF VALVE	01-Dec-83	--	0	Not Known	Titchfield, UK	K2523	--
9815715	--	28-25-45	CMM	PRESSURE RELIEF VALVE	01-Jan-87	28-Oct-88	1	A319, A320, A321	Titchfield, UK	K2523	--
9815740	--	28-10-68	CMM	INWARD RELIEF VALVE	01-Mar-85	01-Oct-90	5	A310, A319CJ, A321, A340	Titchfield, UK	K2523	--
9815823	--	28-26-23	CMM	Outward Relief Valve	06-Aug-12	--	0	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	TCH (pub NOT PN)=HAL, BAE for info only
9815900	--	28-10-51	CMM	INWARD/OUTWARD VENT VALVE	30-Mar-94	30-Sep-04	3	F100, F28, F70	Titchfield, UK	K2523	--
9816040	--	28-E5-1	OM	RESTRICTOR VALVE	01-Feb-64	--	0	Not Known	Titchfield, UK	K2523	--
9817060	--	28-26-24	CMM	Restrictor Valve	06-Aug-12	--	0	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	TCH (pub NOT PN)=HAL, BAE for info only
9840000J	--	28-09-58	OM	NRV	14-Jan-70	12-Mar-04	2	BAE 125	Titchfield, UK	K2523	--
9840006F	--	28-09-71	OM	NRV	01-Feb-74	--	0	Not Known	Titchfield, UK	K2523	--
9840008E	--	28-09-70	CMM	NRV	--	--	0	CONCORDE	Titchfield, UK	K2523	OUT OF PRINT
9840009H	--	28-08-06	CMM	NRV	01-May-84	12-Aug-11	2	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	BAE to approve
9840027E	--	28-09-62	OM	NRV	01-Mar-71	01-Jul-85	2	Not Known	Titchfield, UK	K2523	--
9840034E	--	28-22-03	OM	NRV	01-Oct-73	01-Jul-85	2	AVIOKA (C.212), CASA 212	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9840042D	--	28-22-42	OM	NRV (FLAP TYPE)	01-Jun-74	01-Jul-85	1	F100	Titchfield, UK	K2523	--
9840044H	--	28-21-80	OM	NRV	01-Feb-71	27-Aug-97	2	F100, F28	Titchfield, UK	K2523	--
9840061M	--	28-08-05	CMM	NRV(50MM)	01-Jul-84	05-Aug-11	3	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	BAE to approve
9840064H	--	28-09-87	OM	NRV FLAP TYPE	01-Sep-74	--	0	Not Known	Titchfield, UK	K2523	--
9840065D	--	28-22-64	OM	NRV	01-Feb-74	--	0	HPT32	Titchfield, UK	K2523	--
9840069D	--	28-22-64	OM	NRV	01-Feb-74	--	0	HPT32	Titchfield, UK	K2523	--
9840070M	--	28-09-93	OM	NON RETURN VALVE	01-Oct-76	18-Aug-11	2	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	BAE to approve
9840074K	--	28-10-61	CMM	NRV	01-Sep-80	18-Mar-11	7	BAE 146, G222	Titchfield, UK	K2523	--
9840078J	--	28-09-95	OM	NRV	08-Jul-77	20-Sep-12	2	HS 125	Titchfield, UK	K2523	--
9840094H	--	38-10-66	CMM	NRV	02-Nov-81	24-Sep-12	1	A300, A300-400, A300-600, A310	Titchfield, UK	K2523	--
9840098H	--	38-10-44	CMM	NRV	24-Jul-80	--	0	A300	Titchfield, UK	K2523	--
9841013D	--	28-08-03	CMM	10MM NRV	01-Jun-84	05-Aug-11	1	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	BAE to approve
9841019F	--	28-09-97	OM	NRV	01-Mar-77	03-Jan-87	1	SD-330, SD-360	Titchfield, UK	K2523	--
9841022F	--	28-10-76	CMM	TWIN NRV	01-Jun-83	25-May-04	2	SD-360	Titchfield, UK	K2523	--
9841138	--	28-88-37	ACMM	Thermal Pressure Relief Valve	01-Aug-91	01-Apr-00	1	MK 32 POD	Titchfield, UK	K2523	EX FRL
9843001H	--	28-23-28	OM	PR/NRV	01-Nov-80	06-May-11	2	BAe 748	Titchfield, UK	K2523	--
9843015D	--	28-08-07	CMM	NRV	01-Jan-84	--	0	Not Known	Titchfield, UK	K2523	--
9843034F	--	SIL-2008-07	SIL	FUEL - TRIM TANK - INTRODUCE NEW CHECK VALVE	20-May-08	--	0	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
9843041H	--	38-10-45	CMM	1/2 IN NRV	01-Aug-84	12-Feb-85	1	A310	Titchfield, UK	K2523	--
9843042M	--	28-20-42	CMM	2IN FLAPTYPE NRV	01-Mar-86	29-Mar-99	1	A300-600 - PLESSEY	Titchfield, UK	K2523	Plessey Pump Mtg Plate
9843043H	--	28-10-61	CMM	NRV	01-Sep-80	18-Mar-11	7	BAE 146, G222	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9843144M	--	28-27-41	CMM	CHECK VALVE	01-Aug-90	08-Oct-14	4	A321, A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
9843153F	--	28-22-46	CMM	NRV ASSY	01-Nov-90	14-Apr-93	1	A330, A340	Titchfield, UK	K2523	--
9843169L	--	28-21-42	CMM	CHECK VALVE	01-May-91	02-Apr-04	2	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	WAS 9843150L-REISS'D
9843169L	--	K2523-28-003	SIL	JET PUMP CHECK VALVE	24-Jun-13	--	0	A330, A340	Titchfield, UK	K2523	--
9843181F	--	28-26-21	MM	CHECK VALVE	--	--	0	A380	Titchfield, UK	K2523	TO BE WRITTEN
9855005H	--	28-22-41	CMM	NRV	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
9855010D	--	28-23-35	CMM	1/2' X 5/8' NRV WITH PR	01-Sep-82	06-May-11	1	JS31, JS32	Titchfield, UK	K2523	--
9865204K	--	28-22-35	OM	SP/NR MOTORIZED (PLUG IN VALVE)	01-Sep-74	02-Aug-99	3	CONCORDE	Titchfield, UK	K2523	--
9865222K	--	9406556-28-01	SB	CLAMP RING ASSY INCONSISTENT TORQUE	--	--	0	AV8B, HAWK, MK 32 POD, T45, TORNADO	Titchfield, UK	K2523	TO BE WRITTEN
9865222K	--	SIL-CS-9-06	SIL	V Band 9406556 Vband Assy	29-Oct-06	--	0	A300, A300-600, A310, A320	Titchfield, UK	K2523	--
9870003H	--	28-22-43	OM	RELIEF VALVE	01-Apr-74	--	0	Not Known	Titchfield, UK	K2523	--
9870008M	--	21-40-75	OM	VALVE BODY ASSY	01-Feb-74	01-Aug-76	1	Not Known	Titchfield, UK	K2523	--
9870014H	--	28-22-44	OM	VALVE CANISTER ASSY	01-Apr-74	25-May-05	1	VARIOUS	Titchfield, UK	K2523	--
9870015M	--	21-30-03	CMM	RELIEF VALVE	01-Nov-85	01-Sep-86	1	Not Known	Titchfield, UK	K2523	--
9870035B	--	28-10-50	CMM	RELIEF UNIT	01-Oct-80	18-Mar-11	1	BAE 146	Titchfield, UK	K2523	--
9870038B	--	28-23-39	CMM	RELIEF VALVE	30-Apr-82	06-May-11	1	JS31, JS32	Titchfield, UK	K2523	--
9870040H	--	28-21-12	CMM	PR/NR VALVE 1 IN DIA	01-Apr-86	06-May-11	1	BAe ATP, JS61	Titchfield, UK	K2523	--
9870201M	--	21-40-02	OM	HEAT EXCH BY-PASS VALVE	01-Jul-73	01-Nov-74	1	Not Known	Titchfield, UK	K2523	--
9870201M	--	21-40-02-9089	SB	BY-PASS VALVE - NEW ELECTRIC MOTOR	01-Oct-76	--	0	Not Known	Titchfield, UK	K2523	--
9870204M	--	21-40-82	OM	HEAT EXCHANGER BY-PASS VALVE	01-Jul-76	--	0	Not Known	Titchfield, UK	K2523	--
9890011K	--	28-08-04	CMM	40MM PRV	01-Jun-84	01-Mar-85	1	HAWK	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
9890015K	--	28-26-25	CMM	Relief Valve	06-Aug-12	--	0	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	TCH (pub NOT PN)=HAL, BAE for info only
9895007F	--	38-30-55	CMM	NRV	01-Jan-81	31-Jul-85	1	A310	Titchfield, UK	K2523	--
9895011C	--	38-10-68	CMM	NRV	01-Sep-82	19-Dec-06	2	A300-600, A310	Titchfield, UK	K2523	--
9895013E	--	82-20-07	CMM	NRV	01-Sep-83	03-Jun-11	2	JS31, JS32	Titchfield, UK	K2523	--
99-0057	--	PSD-365	CMM	Firmware reprogramming	03-Feb-21	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
9901026	--	28-20-29	CMM	FUEL FLOW PROPORTIONER	01-May-89	--	0	TORNADO	Titchfield, UK	K2523	2250 LITRE TANKS
9901026	--	SIL-CS-2-03	SIL	FUEL FLOW PROPORTIONER - DRYING PROCEDURE	27-Mar-03	--	0	TORNADO	Titchfield, UK	K2523	--
9901030	--	28-20-16	CMM	FUEL FLOW PROPORTIONER	01-Aug-88	15-Jan-96	1	AM-X	Titchfield, UK	K2523	--
A1001	--	24-09-42	OM	MOTOR	01-Feb-80	18-Mar-11	1	BAe 748, F100	Titchfield, UK	K2523	--
A1001	--	24-09-42+	CMM	MOTOR	01-Feb-88	--	0	MK 32 POD	Titchfield, UK	K2523	*SEE ALSO OM
A1002	--	24-09-25	OM	MOTOR	01-Jul-73	--	0	A310	Titchfield, UK	K2523	--
A1003	--	24-09-25	OM	MOTOR	01-Jul-73	--	0	A310	Titchfield, UK	K2523	--
A1004	--	24-09-39	OM	MOTOR	01-Jul-76	--	0	CONCORDE	Titchfield, UK	K2523	--
A102-17	--	28-08-02	TDS	HANDLE ASSY	01-Sep-83	16-Mar-11	1	BAE 146	Titchfield, UK	K2523	--
A1201	--	24-09-29	CMM	MOTOR	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
A14631	--	56-10-34	CMM	OIL DASHPOT	01-Jul-82	03-Jul-15	4	BAE 146	Titchfield, UK	K2523	--
A500-10	--	24-09-1	OM	MOTOR UNITS	01-Mar-60	06-Jun-08	6	BAC 1-11	Titchfield, UK	K2523	--
A500-10	--	24-09-4-321	SB	MOTOR UNIT - IDENT OF ELECT WIRES	01-Jul-76	--	0	Not Known	Titchfield, UK	K2523	--
A500-16	--	24-09-1	OM	MOTOR UNITS	01-Mar-60	06-Jun-08	6	BAC 1-11	Titchfield, UK	K2523	--
A500-16	--	24-09-4-321	SB	MOTOR UNIT - IDENT OF ELECT WIRES	01-Jul-76	--	0	Not Known	Titchfield, UK	K2523	--
A701	--	24-09-2	OM	MOTOR UNITS	09-Jun-66	18-Dec-14	7	BAC 1-11, BAe 748	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
A701AA	--	24-09-2	OM	MOTOR UNITS	09-Jun-66	18-Dec-14	7	BAC 1-11, BAe 748	Titchfield, UK	K2523	--
A702	--	24-09-2	OM	MOTOR UNITS	09-Jun-66	18-Dec-14	7	BAC 1-11, BAe 748	Titchfield, UK	K2523	--
AE4707502	--	24-08-01	CMM	ROTARY ACTUATOR	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
AETL31115	--	28-26-26	CMM	Transfer Pump	--	--	0	A380	Titchfield, UK	K2523	TO BE WRITTEN
AETL31324	--	28-26-26	CMM	Transfer Pump	--	--	0	A380	Titchfield, UK	K2523	TO BE WRITTEN
AETL40411	--	28-26-26	CMM	Transfer Pump	--	--	0	A380	Titchfield, UK	K2523	TO BE WRITTEN
AL01401	--	24-08-54	CMM	LINEAR ACTUATOR	01-Mar-89	--	0	Not Known	Titchfield, UK	K2523	MIL SYSTEMS DIV
B11500	--	B11500-52-1	SB	PX DOOR CABLE ASSYS - REPAIR TO OUTER SLEEVES	28-Sep-98	23-Mar-99	1	Not Known	Titchfield, UK	K2523	--
B11501	--	B11500-52-1	SB	PX DOOR CABLE ASSYS - REPAIR TO OUTER SLEEVES	28-Sep-98	23-Mar-99	1	Not Known	Titchfield, UK	K2523	--
B12	--	24-09-17	OM	AC ROTARY ACTUATOR	01-Oct-70	--	0	Not Known	Titchfield, UK	K2523	--
B14700	--	52-60-23	CMM	HYDRAULIC JACK ASSEMBLIES	01-Mar-92	03-Jun-11	4	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
B14766	--	52-60-24	CMM	OPERATING STRUT DAMPER ASSEMBLIES	01-Mar-92	03-Jun-11	7	BAE 146, BAe ATP, F100, JS61	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
B14767	--	52-60-24	CMM	OPERATING STRUT DAMPER ASSEMBLIES	01-Mar-92	03-Jun-11	7	BAE 146, BAe ATP, F100, JS61	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
B14768	--	52-60-24	CMM	OPERATING STRUT DAMPER ASSEMBLIES	01-Mar-92	03-Jun-11	7	BAE 146, BAe ATP, F100, JS61	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
B14862	--	52-60-23	CMM	HYDRAULIC JACK ASSEMBLIES	01-Mar-92	03-Jun-11	4	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
B31009	--	52-60-10	CMM	MK J31 HANDRAIL MECHANISM	01-Jan-87	03-Jun-11	5	JS31, JS32	Titchfield, UK	K2523	--
B31010	--	52-60-10	CMM	MK J31 HANDRAIL MECHANISM	01-Jan-87	03-Jun-11	5	JS31, JS32	Titchfield, UK	K2523	--
B7774	--	52-60-18	CMM	HYDRAULIC JACK ASSEMBLY	17-Nov-94	03-Jun-11	3	BAe ATP, JS61	Titchfield, UK	K2523	--
B7797	--	52-60-24	CMM	OPERATING STRUT DAMPER ASSEMBLIES	01-Mar-92	03-Jun-11	7	BAE 146, BAe ATP, F100, JS61	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
C107T1	--	28-22-86	OM	SPV	01-Jul-75	--	0	Not Known	Titchfield, UK	K2523	--
C113M-EC	--	28-10-11	OM	COUPLED MOTORISED MULTIWAY SPV	01-May-62	01-Aug-66	1	BAC 1-11	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
C114M1-EC	--	28-20-11+	OM	PR/SP/MW MOT	13-Apr-93	01-Dec-66	2	BAC 1-11	Titchfield, UK	K2523	*EX-SAUNDERS
C115M1-EC	--	28-20-11+	OM	PR/SP/MW MOT	13-Apr-93	01-Dec-66	2	BAC 1-11	Titchfield, UK	K2523	*EX-SAUNDERS
C122-M	--	SL65	OM	SPV MOT	01-Nov-65	--	0	Not Known	Titchfield, UK	K2523	--
C125	--	34-10-31	OM	COUPLED SPV	01-Jan-65	23-Sep-83	2	BAE 125	Titchfield, UK	K2523	--
C126-M	--	SL65	OM	SPV MOT	01-Nov-65	--	0	Not Known	Titchfield, UK	K2523	--
C130M2-JB	--	28-20-87	CMM	PLUG IN SPV	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
C131M2-GA	--	28-20-87	CMM	PLUG IN SPV	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
C135	--	34-10-34	OM	COUPLED SPV	01-Dec-67	--	0	Not Known	Titchfield, UK	K2523	--
C137M1	--	28-09-9075-19776	SB	LW MOTOR UNITS - IMPROVED SEALING	01-Jun-70	09-Oct-70	1	F27, F28	Titchfield, UK	K2523	--
C137M1	--	29-10-72	OM	COUPLED MOTORIZED SPV'S	14-Mar-69	18-Apr-16	3	F28	Titchfield, UK	K2523	--
C137M11	--	28-09-9075-19776	SB	LW MOTOR UNITS - IMPROVED SEALING	01-Jun-70	09-Oct-70	1	F27, F28	Titchfield, UK	K2523	--
C137M11	--	29-10-72	OM	COUPLED MOTORIZED SPV'S	14-Mar-69	18-Apr-16	3	F28	Titchfield, UK	K2523	--
C14810	--	52-60-22	CMM	OIL RESERVOIR	01-Mar-92	29-Jan-14	7	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
C14810	--	C14810-52-1	SB	OIL RESERVOIR - IMPROVED PISTON	07-Jul-94	27-Oct-94	1	BAE 146	Titchfield, UK	K2523	--
C14810	--	SIL-TP-1-90	SIL	REWRITE AND REISSUE OF MK 146 AIRSCALATOR MANUALS	07-Dec-90	--	0	Not Known	Titchfield, UK	K2523	--
C6416	--	28-13-05	OM	FLUID COOLER	01-Feb-71	--	0	Not Known	Titchfield, UK	K2523	--
C7679	--	52-60-11	CMM	ATP AIRSCALATOR INSTN	01-Oct-87	03-Jun-11	11	BAe ATP	Titchfield, UK	K2523	--
C7682	--	52-60-11	CMM	ATP AIRSCALATOR INSTN	01-Oct-87	03-Jun-11	11	BAe ATP	Titchfield, UK	K2523	--
C7683	--	52-60-11	CMM	ATP AIRSCALATOR INSTN	01-Oct-87	03-Jun-11	11	BAe ATP	Titchfield, UK	K2523	--
CA2060	--	72-19-01	CMM	GOVERNOR PUMP	01-Jun-66	01-Nov-68	10	AVON 520	Titchfield, UK	K2523	--
CA3853	--	73-10-02	CMM	LP FUEL BACKING PUMP	01-Apr-65	17-Dec-02	17	ATLANTIC, BELFAST EQUIPMENTS, Not Known, TYNE 21/22, VANGUARD	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
CA57160-1	--	SIL-2008-02	SIL	TF-57160-1 - FILTER - Change of PN	--	--	0	HS 125	Titchfield, UK	K2523	TO BE WRITTEN
CK11804	--	OSM705	CMM	LP IGNITION SWITCH MK 6	01-Dec-71	01-Oct-72	1	HUNTER	Titchfield, UK	K2523	*OUT OF PRINT"
CK12422R	--	OSM704	CMM	HP SWITCH & SOLENOID VALVE	01-Jan-72	01-Jun-82	2	HUNTER	Titchfield, UK	K2523	--
CK12423	--	OSM703	CMM	FUEL PUMP, AIR BLOWER & MOTOR UNIT	01-Sep-72	01-Jun-82	2	HUNTER, SAAB 2000	Titchfield, UK	K2523	--
CZ26817	--	24-09-02	CMM	ELECTRIC MOTOR TYPE A-DC-A	01-Jul-63	10-Aug-77	2	AZOR, BRISTOL FREIGHTER, SHACKLETON, TWIN PIONEER, VIKING	Titchfield, UK	K2523	--
CZ54249	--	24-11-09	CMM	MOTOR PLESSEY TYPE C1606H/1&8	01-May-66	15-May-72	3	HUNTER, ISLANDER/TRISLANDER	Titchfield, UK	K2523	--
CZ55457	--	OSM392	CMM	MOTOR TYPE C1606B-1	21-Apr-72	--	0	BRITANNIA, HERALD, HS 748	Titchfield, UK	K2523	BASIC MANUAL
CZ77917	--	24-09-107	CMM	JAGUAR ACTUATORS	27-Sep-68	15-May-05	5	DART ENGINE	Titchfield, UK	K2523	--
CZ77917F	--	24-09-107	CMM	JAGUAR ACTUATORS	27-Sep-68	15-May-05	5	DART ENGINE	Titchfield, UK	K2523	--
CZ78311	--	OSM 384	CMM	DC Motor	13-Apr-65	--	0	PUMA	Titchfield, UK	K2523	--
D11342	--	125-SB-1010	SB	Introduction of Rigid Handrail	01-Sep-67	--	0	HS 125	Titchfield, UK	K2523	--
D11342	--	52-60-01	OM	MK 125 AIRSCALATOR	01-Apr-65	--	0	HS 125	Titchfield, UK	K2523	--
D11441	--	52-60-05	OM	AIRSCALATOR WITH RIGID HANDRAIL	01-Jul-78	--	0	BAE 125	Titchfield, UK	K2523	BAE 125
D14624	--	52-60-20	CMM	AIRSCALATOR ASSEMBLIES	01-Mar-92	03-Jun-11	8	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
D14624	--	D14624-52-1	SB	AIRSCALATOR - CRACKED TREAD SUPPORTS	02-Feb-95	--	0	BAE 146	Titchfield, UK	K2523	--
D14624	--	D14624-52-2	SB	AIRSCALATOR - WORN PIVOT BOLTS AND RELATED PARTS	16-May-95	21-Jul-97	1	BAE 146	Titchfield, UK	K2523	--
D14625	--	52-60-06	CMM	MK 146 AIRSCALATOR-REAR DR/AFT STW	01-Feb-83	01-May-89	1	--	Titchfield, UK	K2523	S/S BY 52-60-20 to24
D14625	--	52-60-20	CMM	AIRSCALATOR ASSEMBLIES	01-Mar-92	03-Jun-11	8	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
D14625	--	D14624-52-1	SB	AIRSCALATOR - CRACKED TREAD SUPPORTS	02-Feb-95	--	0	BAE 146	Titchfield, UK	K2523	--
D14625	--	D14624-52-2	SB	AIRSCALATOR - WORN PIVOT BOLTS AND RELATED PARTS	16-May-95	21-Jul-97	1	BAE 146	Titchfield, UK	K2523	--
D14652	--	52-60-21	CMM	CARRIAGE ASSEMBLIES	01-Mar-92	20-Sep-18	11	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
D14652	--	D14624-52-2	SB	AIRSCALATOR - WORN PIVOT BOLTS AND RELATED PARTS	16-May-95	21-Jul-97	1	BAE 146	Titchfield, UK	K2523	--
D14652	--	SIL-PS-4-96	SIL	AIRSCALATOR CARRIAGE ASSY BANJO UNIONS - O-RING	06-Jun-96	--	0	Not Known	Titchfield, UK	K2523	--
D14664	--	52-60-21	CMM	CARRIAGE ASSEMBLIES	01-Mar-92	20-Sep-18	11	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
D14664	--	D14624-52-2	SB	AIRSCALATOR - WORN PIVOT BOLTS AND RELATED PARTS	16-May-95	21-Jul-97	1	BAE 146	Titchfield, UK	K2523	--
D14664	--	SIL-PS-4-96	SIL	AIRSCALATOR CARRIAGE ASSY BANJO UNIONS - O-RING	06-Jun-96	--	0	Not Known	Titchfield, UK	K2523	--
D14741	--	52-60-20	CMM	AIRSCALATOR ASSEMBLIES	01-Mar-92	03-Jun-11	8	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
D14741	--	D14624-52-1	SB	AIRSCALATOR - CRACKED TREAD SUPPORTS	02-Feb-95	--	0	BAE 146	Titchfield, UK	K2523	--
D14741	--	D14624-52-2	SB	AIRSCALATOR - WORN PIVOT BOLTS AND RELATED PARTS	16-May-95	21-Jul-97	1	BAE 146	Titchfield, UK	K2523	--
D14742	--	52-60-21	CMM	CARRIAGE ASSEMBLIES	01-Mar-92	20-Sep-18	11	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
D14742	--	D14624-52-2	SB	AIRSCALATOR - WORN PIVOT BOLTS AND RELATED PARTS	16-May-95	21-Jul-97	1	BAE 146	Titchfield, UK	K2523	--
D14742	--	SIL-PS-4-96	SIL	AIRSCALATOR CARRIAGE ASSY BANJO UNIONS - O-RING	06-Jun-96	--	0	Not Known	Titchfield, UK	K2523	--
D14848	--	52-60-07	CMM	MK 146 ARSCLTR-REAR DR/AFT STW-LPT	01-Oct-83	--	0	--	Titchfield, UK	K2523	S/S BY 52-60-20 to24
D14848	--	52-60-20	CMM	AIRSCALATOR ASSEMBLIES	01-Mar-92	03-Jun-11	8	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
D14848	--	D14624-52-1	SB	AIRSCALATOR - CRACKED TREAD SUPPORTS	02-Feb-95	--	0	BAE 146	Titchfield, UK	K2523	--
D14848	--	D14624-52-2	SB	AIRSCALATOR - WORN PIVOT BOLTS AND RELATED PARTS	16-May-95	21-Jul-97	1	BAE 146	Titchfield, UK	K2523	--
D14849	--	52-60-08	CMM	MK 146 ARSCLTR-FWD DR/AFT STWG-LPT	01-Oct-83	--	0	--	Titchfield, UK	K2523	S/S BY 52-60-20 to24
D14849	--	52-60-20	CMM	AIRSCALATOR ASSEMBLIES	01-Mar-92	03-Jun-11	8	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
D14849	--	D14624-52-1	SB	AIRSCALATOR - CRACKED TREAD SUPPORTS	02-Feb-95	--	0	BAE 146	Titchfield, UK	K2523	--
D14849	--	D14624-52-2	SB	AIRSCALATOR - WORN PIVOT BOLTS AND RELATED PARTS	16-May-95	21-Jul-97	1	BAE 146	Titchfield, UK	K2523	--
D14850	--	52-60-09	CMM	MK 146 ARSCLTR-AFT DR/FWD STWG-LPT	01-Oct-83	--	0	--	Titchfield, UK	K2523	S/S BY 52-60-20 to24
D14850	--	52-60-20	CMM	AIRSCALATOR ASSEMBLIES	01-Mar-92	03-Jun-11	8	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
D14850	--	D14624-52-1	SB	AIRSCALATOR - CRACKED TREAD SUPPORTS	02-Feb-95	--	0	BAE 146	Titchfield, UK	K2523	--
D14850	--	D14624-52-2	SB	AIRSCALATOR - WORN PIVOT BOLTS AND RELATED PARTS	16-May-95	21-Jul-97	1	BAE 146	Titchfield, UK	K2523	--
D14868	--	52-60-21	CMM	CARRIAGE ASSEMBLIES	01-Mar-92	20-Sep-18	11	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
D14868	--	D14624-52-2	SB	AIRSCALATOR - WORN PIVOT BOLTS AND RELATED PARTS	16-May-95	21-Jul-97	1	BAE 146	Titchfield, UK	K2523	--
D14868	--	SIL-PS-4-96	SIL	AIRSCALATOR CARRIAGE ASSY BANJO UNIONS - O-RING	06-Jun-96	--	0	Not Known	Titchfield, UK	K2523	--
D14869	--	52-60-21	CMM	CARRIAGE ASSEMBLIES	01-Mar-92	20-Sep-18	11	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
D14869	--	SIL-PS-4-96	SIL	AIRSCALATOR CARRIAGE ASSY BANJO UNIONS - O-RING	06-Jun-96	--	0	Not Known	Titchfield, UK	K2523	--
D14870	--	52-60-21	CMM	CARRIAGE ASSEMBLIES	01-Mar-92	20-Sep-18	11	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
D14870	--	D14624-52-2	SB	AIRSCALATOR - WORN PIVOT BOLTS AND RELATED PARTS	16-May-95	21-Jul-97	1	BAE 146	Titchfield, UK	K2523	--
D14870	--	SIL-PS-4-96	SIL	AIRSCALATOR CARRIAGE ASSY BANJO UNIONS - O-RING	06-Jun-96	--	0	Not Known	Titchfield, UK	K2523	--
D14888	--	52-60-20	CMM	AIRSCALATOR ASSEMBLIES	01-Mar-92	03-Jun-11	8	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
D14888	--	D14624-52-1	SB	AIRSCALATOR - CRACKED TREAD SUPPORTS	02-Feb-95	--	0	BAE 146	Titchfield, UK	K2523	--
D14888	--	D14624-52-2	SB	AIRSCALATOR - WORN PIVOT BOLTS AND RELATED PARTS	16-May-95	21-Jul-97	1	BAE 146	Titchfield, UK	K2523	--
D14888	--	D14888-52-1	SB	AIRSCALATOR - INTRODUCTION OF POLISHED HANDRAILS	22-Apr-96	--	0	Not Known	Titchfield, UK	K2523	--
D14929	--	52-60-21	CMM	CARRIAGE ASSEMBLIES	01-Mar-92	20-Sep-18	11	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
D14929	--	D14624-52-2	SB	AIRSCALATOR - WORN PIVOT BOLTS AND RELATED PARTS	16-May-95	21-Jul-97	1	BAE 146	Titchfield, UK	K2523	--
D14929	--	SIL-PS-4-96	SIL	AIRSCALATOR CARRIAGE ASSY BANJO UNIONS - O-RING	06-Jun-96	--	0	Not Known	Titchfield, UK	K2523	--
D14930	--	52-60-21	CMM	CARRIAGE ASSEMBLIES	01-Mar-92	20-Sep-18	11	BAE 146	Titchfield, UK	K2523	S/SDS 52-60-04 to 09
D14930	--	SIL-PS-4-96	SIL	AIRSCALATOR CARRIAGE ASSY BANJO UNIONS - O-RING	06-Jun-96	--	0	Not Known	Titchfield, UK	K2523	--
D31005	--	52-60-10	CMM	MK J31 HANDRAIL MECHANISM	01-Jan-87	03-Jun-11	5	JS31, JS32	Titchfield, UK	K2523	--
D31005	--	D31005-52-1	SB	INTRODUCTION OF RIVETED JOINTS IN PLACE OF WELDED JOINTS	30-Sep-91	--	0	JS31, JS32	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
D31005	--	D31005-52-2	SB	INTRODUCTION OF AN ALUMINIUM ALLOY END PIECE IN PLACE OF A PLASTIC END PIECE	18-Oct-91	29-Jun-92	1	JS31, JS32	Titchfield, UK	K2523	--
D31005	--	D31005-52-3	SB	INTRODUCTION OF A NEW SHEAR PIN	30-Jul-92	--	0	JS31, JS32	Titchfield, UK	K2523	--
D33126	--	52-60-04	OM	MK 330 AIRSCALATOR	01-Sep-76	19-Aug-97	2	SD-330	Titchfield, UK	K2523	--
D7158	--	52-60-02	OM	MK 748 AIRSCALATOR (Scissor Type)	01-Jan-67	03-Jun-11	5	BAe 748	Titchfield, UK	K2523	Ex Strabor manual
D7365	--	52-60-03	OM	MK 748.S. AIRSCALATOR (STANDRD.DR)	01-Oct-74	03-Jun-11	6	BAe 748	Titchfield, UK	K2523	--
D7482	--	52-60-03	OM	MK 748.S. AIRSCALATOR (STANDRD.DR)	01-Oct-74	03-Jun-11	6	BAe 748	Titchfield, UK	K2523	--
D7680	--	52-60-11	CMM	ATP AIRSCALATOR INSTN	01-Oct-87	03-Jun-11	11	BAe ATP	Titchfield, UK	K2523	--
D7680	--	D7680-52-1	SB	INTRODUCTION OF LIGHTWEIGHT COMPOSITE TREADS	30-Apr-91	--	0	Not Known	Titchfield, UK	K2523	--
D7681	--	52-60-11	CMM	ATP AIRSCALATOR INSTN	01-Oct-87	03-Jun-11	11	BAe ATP	Titchfield, UK	K2523	--
D7819	--	52-60-11	CMM	ATP AIRSCALATOR INSTN	01-Oct-87	03-Jun-11	11	BAe ATP	Titchfield, UK	K2523	--
D7819	--	D7680-52-1	SB	INTRODUCTION OF LIGHTWEIGHT COMPOSITE TREADS	30-Apr-91	--	0	Not Known	Titchfield, UK	K2523	--
DUMMY	--	SIL-TP-1-92	SIL	STANDARD PART NO CROSS REFERENCE CHART	16-Jul-93	16-Dec-98	3	A300-600, A310, A319, A319CJ, A320, A321, A330, A340, VARIOUS	Titchfield, UK	K2523	--
E42F10	--	28-20-94	OM	ELECT OP SPV	01-Jul-70	--	0	Not Known	Titchfield, UK	K2523	--
FC441	--	E2-159B	OM	AIRCRAFT UNIT SEALING CAPS	08-Mar-72	16-Mar-92	1	BAE 125, BAE 146, NIMROD	Titchfield, UK	K2523	MEGGIT PN DON'T UPDATE OR DISTRIBUTE
FCMX109/A	--	E2-159B	OM	AIRCRAFT UNIT SEALING CAPS	08-Mar-72	16-Mar-92	1	BAE 125, BAE 146, NIMROD	Titchfield, UK	K2523	MEGGIT PN DON'T UPDATE OR DISTRIBUTE
FCMX113MK2	--	E1-158B	OM	AIRCRAFT UNIT 2 1/2 IN	16-May-61	12-Mar-92	2	BAE 125, BAE 146, HAWK	Titchfield, UK	K2523	MEGGIT IP- DON'T UPDATE/DISTRIBUTE
FCMX129M2	--	E1-158B	OM	AIRCRAFT UNIT 2 1/2 IN	16-May-61	12-Mar-92	2	BAE 125, BAE 146, HAWK	Titchfield, UK	K2523	MEGGIT IP- DON'T UPDATE/DISTRIBUTE
FRH010004	--	24-09-56	CMM	ROTARY ACTUATOR	16-Nov-94	12-Apr-07	2	AOA GTG - TOILET SYS	Titchfield, UK	K2523	Paper and disk format.
FRH010012	--	21-31-06_K2523	CMP	(KSA Program Only) Flat Actuator MK 9 Component Maintenance Manual	--	--	0	EFA	Titchfield, UK	K2523	TO BE WRITTEN
FRH010012	--	PSD-054	MM	MK 9 FLAT ACTUATOR	10-Sep-98	--	0	JSF	Titchfield, UK	K2523	--
FRH010014	--	24-09-63	CMM	ACTUATOR	15-May-00	04-Sep-07	2	EH101	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRH010030	--	PSD-060	MM	MODULATING ACTUATOR	21-Nov-98	--	0	JSF	Titchfield, UK	K2523	--
FRH010034	--	24-09-62	CMM	TWIN MOTOR ACTUATOR	02-Feb-01	04-Jan-17	5	A319, A319CJ	Titchfield, UK	K2523	--
FRH010034	--	28-87-40	CMM	KC46A - Twin Motor Actuator	--	31-May-16	0	KC46A	Titchfield, UK	K2523	*** COBHAM USE ONLY ***
FRH010038	--	21-22-03_K2523	CMP	(KSA Programs Only) Actuator Assembly Component Maintenance Publication	--	--	0	EFA	Titchfield, UK	K2523	TO BE WRITTEN
FRH010041	--	24-09-65	CMM	TWIN MOTOR ACTUATOR	28-Feb-01	16-Jul-18	7	A310-MRTT, A320, A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
FRH010041	--	HTE190026-24-1	SB	NEW TWIN MOTOR ACTUATOR PN FRH010041	26-Oct-00	--	0	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
FRH010041	--	K2523-24-001	SIL	Obsolete Actuator	03-Oct-16	--	0	A330, A340	Titchfield, UK	K2523	--
FRH010041	--	SIL-2009-07	SIL	INTRODUCTION OF IMPROVED TWIN MOTOR ACTUATOR	11-Nov-09	--	0	A319, A330, A340	Titchfield, UK	K2523	--
FRH010041	--	SIL-CS-08-06	SIL	TWIN MOTOR ACTUATOR IMPROVEMENT	08-Aug-06	--	0	A330	Titchfield, UK	K2523	--
FRH010041	--	SIL-CS-2-05	SIL	ACTUATOR IMPROVEMENT TRIAL	09-Feb-05	--	0	A330	Titchfield, UK	K2523	TAIL No. A6-EKX ONLY
FRH010045	--	24-09-66	CMM	TWIN MOTOR ACTUATOR	--	--	0	Not Known	Titchfield, UK	K2523	CANCELLED
FRH010046	--	52-60-36	CMM	LINEAR ACTUATOR	--	--	0	DORNIER 728JET	Titchfield, UK	K2523	TO BE WRITTEN
FRH010058	--	28-21-27_K2523	CMP	(KSA Program Only) Flat Actuator MK 9 Component Maintenance Manual	--	--	0	EFA	Titchfield, UK	K2523	TO BE WRITTEN
FRH011004	--	28-87-54+	CMM	LINEAR ACTUATOR	--	03-May-05	0	MK 32 POD	Titchfield, UK	K2523	--
FRH021004	--	27-10-01	CMM	AILERON DISCONNECT UNIT	22-Apr-98	18-Mar-11	3	BAE 146	Titchfield, UK	K2523	--
FRH050001-1	--	28-43-29	CMM	MFLI OUTER ASSEMBLY (UPPER & LOWER)	23-Feb-99	23-Feb-15	3	A319, A320	Titchfield, UK	K2523	--
FRH050001-1	--	3508802-29-28-1	SB	MFLI - NEW DESIGN MOD No. FRCA9328	14-Oct-98	--	0	A319, A320	Titchfield, UK	K2523	--
FRH050001-2	--	28-43-29	CMM	MFLI OUTER ASSEMBLY (UPPER & LOWER)	23-Feb-99	23-Feb-15	3	A319, A320	Titchfield, UK	K2523	--
FRH050001-2	--	3508802-29-28-1	SB	MFLI - NEW DESIGN MOD No. FRCA9328	14-Oct-98	--	0	A319, A320	Titchfield, UK	K2523	--
FRH050001C/9C	--	28-43-26	ACMM	INNER ASSEMBLY - MFLI	01-Feb-88	20-Aug-12	4	A319, A320, A321	Titchfield, UK	K2523	Original Scanned
FRH050002	--	28-43-30	CMM	MFLI OUTER ASSEMBLIES	24-Feb-99	05-Apr-07	3	A319, A320, A321	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRH050002	--	3508802-29-28-1	SB	MFLI - NEW DESIGN MOD No. FRCA9328	14-Oct-98	--	0	A319, A320	Titchfield, UK	K2523	--
FRH050002	--	FRH050002-28-1	SB	FUEL SYSTEM-MFLI INSPECTION FOR INCORRECT ASSY	15-Dec-03	12-Jul-12	1	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH050002	--	FRH050002-28-2	SB	Top Stop Retention	06-Feb-06	--	0	A319, A320, A321	Titchfield, UK	K2523	--
FRH050002	--	FRH050002-28-3	SB	Inspection for incorrect assembly	--	--	0	A319, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN
FRH050002	--	SIL-CS-4-03	SIL	ATA 28 - MFLI (OIT 999.0064/03)	21-Jul-03	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH050003	--	28-43-30	CMM	MFLI OUTER ASSEMBLIES	24-Feb-99	05-Apr-07	3	A319, A320, A321	Titchfield, UK	K2523	--
FRH050003	--	3508802-29-28-1	SB	MFLI - NEW DESIGN MOD No. FRCA9328	14-Oct-98	--	0	A319, A320	Titchfield, UK	K2523	--
FRH050003	--	FRH050002-28-1	SB	FUEL SYSTEM-MFLI INSPECTION FOR INCORRECT ASSY	15-Dec-03	12-Jul-12	1	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH050003	--	FRH050002-28-2	SB	Top Stop Retention	06-Feb-06	--	0	A319, A320, A321	Titchfield, UK	K2523	--
FRH050003	--	FRH050002-28-3	SB	Inspection for incorrect assembly	--	--	0	A319, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN
FRH050003	--	SIL-CS-4-03	SIL	ATA 28 - MFLI (OIT 999.0064/03)	21-Jul-03	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH050004	--	28-43-30	CMM	MFLI OUTER ASSEMBLIES	24-Feb-99	05-Apr-07	3	A319, A320, A321	Titchfield, UK	K2523	--
FRH050004	--	3508802-29-28-1	SB	MFLI - NEW DESIGN MOD No. FRCA9328	14-Oct-98	--	0	A319, A320	Titchfield, UK	K2523	--
FRH050004	--	FRH050002-28-1	SB	FUEL SYSTEM-MFLI INSPECTION FOR INCORRECT ASSY	15-Dec-03	12-Jul-12	1	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH050004	--	FRH050002-28-2	SB	Top Stop Retention	06-Feb-06	--	0	A319, A320, A321	Titchfield, UK	K2523	--
FRH050004	--	FRH050002-28-3	SB	Inspection for incorrect assembly	--	--	0	A319, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN
FRH050004	--	SIL-CS-4-03	SIL	ATA 28 - MFLI (OIT 999.0064/03)	21-Jul-03	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH050005	--	28-43-30	CMM	MFLI OUTER ASSEMBLIES	24-Feb-99	05-Apr-07	3	A319, A320, A321	Titchfield, UK	K2523	--
FRH050005	--	3508802-29-28-1	SB	MFLI - NEW DESIGN MOD No. FRCA9328	14-Oct-98	--	0	A319, A320	Titchfield, UK	K2523	--
FRH050005	--	FRH050002-28-1	SB	FUEL SYSTEM-MFLI INSPECTION FOR INCORRECT ASSY	15-Dec-03	12-Jul-12	1	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH050005	--	FRH050002-28-2	SB	Top Stop Retention	06-Feb-06	--	0	A319, A320, A321	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRH050005	--	FRH050002-28-3	SB	Inspection for incorrect assembly	--	--	0	A319, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN
FRH050005	--	SIL-CS-4-03	SIL	ATA 28 - MFLI (OIT 999.0064/03)	21-Jul-03	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH050006	--	28-43-30	CMM	MFLI OUTER ASSEMBLIES	24-Feb-99	05-Apr-07	3	A319, A320, A321	Titchfield, UK	K2523	--
FRH050006	--	3508802-29-28-1	SB	MFLI - NEW DESIGN MOD No. FRCA9328	14-Oct-98	--	0	A319, A320	Titchfield, UK	K2523	--
FRH050006	--	FRH050002-28-1	SB	FUEL SYSTEM-MFLI INSPECTION FOR INCORRECT ASSY	15-Dec-03	12-Jul-12	1	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH050006	--	FRH050002-28-2	SB	Top Stop Retention	06-Feb-06	--	0	A319, A320, A321	Titchfield, UK	K2523	--
FRH050006	--	FRH050002-28-3	SB	Inspection for incorrect assembly	--	--	0	A319, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN
FRH050006	--	SIL-CS-4-03	SIL	ATA 28 - MFLI (OIT 999.0064/03)	21-Jul-03	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH050007	--	28-43-31	CMM	MFLI OUTER ASSEMBLIES	24-Feb-99	12-Jan-09	5	A320, A321	Titchfield, UK	K2523	--
FRH050007	--	3508802-29-28-1	SB	MFLI - NEW DESIGN MOD No. FRCA9328	14-Oct-98	--	0	A319, A320	Titchfield, UK	K2523	--
FRH050007	--	FRH050002-28-1	SB	FUEL SYSTEM-MFLI INSPECTION FOR INCORRECT ASSY	15-Dec-03	12-Jul-12	1	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH050007	--	FRH050002-28-2	SB	Top Stop Retention	06-Feb-06	--	0	A319, A320, A321	Titchfield, UK	K2523	--
FRH050007	--	FRH050002-28-3	SB	Inspection for incorrect assembly	--	--	0	A319, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN
FRH050007	--	SIL-CS-4-03	SIL	ATA 28 - MFLI (OIT 999.0064/03)	21-Jul-03	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH050008	--	28-43-31	CMM	MFLI OUTER ASSEMBLIES	24-Feb-99	12-Jan-09	5	A320, A321	Titchfield, UK	K2523	--
FRH050008	--	3508802-29-28-1	SB	MFLI - NEW DESIGN MOD No. FRCA9328	14-Oct-98	--	0	A319, A320	Titchfield, UK	K2523	--
FRH050008	--	FRH050002-28-1	SB	FUEL SYSTEM-MFLI INSPECTION FOR INCORRECT ASSY	15-Dec-03	12-Jul-12	1	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH050008	--	FRH050002-28-2	SB	Top Stop Retention	06-Feb-06	--	0	A319, A320, A321	Titchfield, UK	K2523	--
FRH050008	--	FRH050002-28-3	SB	Inspection for incorrect assembly	--	--	0	A319, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN
FRH050008	--	SIL-CS-4-03	SIL	ATA 28 - MFLI (OIT 999.0064/03)	21-Jul-03	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH050009	--	28-43-31	CMM	MFLI OUTER ASSEMBLIES	24-Feb-99	12-Jan-09	5	A320, A321	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRH050009	--	3508802-29-28-1	SB	MFLI - NEW DESIGN MOD No. FRCA9328	14-Oct-98	--	0	A319, A320	Titchfield, UK	K2523	--
FRH050009	--	FRH050002-28-1	SB	FUEL SYSTEM-MFLI INSPECTION FOR INCORRECT ASSY	15-Dec-03	12-Jul-12	1	A318, A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH050009	--	FRH050002-28-2	SB	Top Stop Retention	06-Feb-06	--	0	A319, A320, A321	Titchfield, UK	K2523	--
FRH050009	--	FRH050002-28-3	SB	Inspection for incorrect assembly	--	--	0	A319, A320, A321	Titchfield, UK	K2523	TO BE WRITTEN
FRH050009	--	SIL-CS-4-03	SIL	ATA 28 - MFLI (OIT 999.0064/03)	21-Jul-03	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH050010-1	--	28-43-32	CMM	MFLI OUTER ASSEMBLY, CENTRE UNIT	01-May-01	--	0	A340-600	Titchfield, UK	K2523	--
FRH050010-2	--	28-43-32	CMM	MFLI OUTER ASSEMBLY, CENTRE UNIT	01-May-01	--	0	A340-600	Titchfield, UK	K2523	--
FRH050010C	--	28-43-53	ACMM	MFLI INNER ASSY	01-Mar-92	17-Aug-12	3	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
FRH050011	--	28-43-33	CMM	MFLI'S - OUTER ASSEMBLIES	25-Jun-01	11-Apr-12	5	A340-500, A340-600	Titchfield, UK	K2523	--
FRH050011C	--	28-43-53	ACMM	MFLI INNER ASSY	01-Mar-92	17-Aug-12	3	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
FRH050012	--	28-43-33	CMM	MFLI'S - OUTER ASSEMBLIES	25-Jun-01	11-Apr-12	5	A340-500, A340-600	Titchfield, UK	K2523	--
FRH050012C	--	28-43-53	ACMM	MFLI INNER ASSY	01-Mar-92	17-Aug-12	3	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
FRH050013	--	28-43-33	CMM	MFLI'S - OUTER ASSEMBLIES	25-Jun-01	11-Apr-12	5	A340-500, A340-600	Titchfield, UK	K2523	--
FRH050014	--	28-43-33	CMM	MFLI'S - OUTER ASSEMBLIES	25-Jun-01	11-Apr-12	5	A340-500, A340-600	Titchfield, UK	K2523	--
FRH050015	--	28-43-33	CMM	MFLI'S - OUTER ASSEMBLIES	25-Jun-01	11-Apr-12	5	A340-500, A340-600	Titchfield, UK	K2523	--
FRH050015C	--	28-43-53	ACMM	MFLI INNER ASSY	01-Mar-92	17-Aug-12	3	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
FRH050016	--	28-43-33	CMM	MFLI'S - OUTER ASSEMBLIES	25-Jun-01	11-Apr-12	5	A340-500, A340-600	Titchfield, UK	K2523	--
FRH050016C	--	28-43-53	ACMM	MFLI INNER ASSY	01-Mar-92	17-Aug-12	3	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
FRH050017	--	28-43-33	CMM	MFLI'S - OUTER ASSEMBLIES	25-Jun-01	11-Apr-12	5	A340-500, A340-600	Titchfield, UK	K2523	--
FRH050017C	--	28-43-53	ACMM	MFLI INNER ASSY	01-Mar-92	17-Aug-12	3	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
FRH050018C	--	28-43-53	ACMM	MFLI INNER ASSY	01-Mar-92	17-Aug-12	3	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRH050020	--	28-43-33	CMM	MFLI'S - OUTER ASSEMBLIES	25-Jun-01	11-Apr-12	5	A340-500, A340-600	Titchfield, UK	K2523	--
FRH050021	--	28-43-33	CMM	MFLI'S - OUTER ASSEMBLIES	25-Jun-01	11-Apr-12	5	A340-500, A340-600	Titchfield, UK	K2523	--
FRH050022	--	28-43-33	CMM	MFLI'S - OUTER ASSEMBLIES	25-Jun-01	11-Apr-12	5	A340-500, A340-600	Titchfield, UK	K2523	--
FRH050048	--	28-43-33	CMM	MFLI'S - OUTER ASSEMBLIES	25-Jun-01	11-Apr-12	5	A340-500, A340-600	Titchfield, UK	K2523	--
FRH050049	--	28-43-33	CMM	MFLI'S - OUTER ASSEMBLIES	25-Jun-01	11-Apr-12	5	A340-500, A340-600	Titchfield, UK	K2523	--
FRH060002	--	28-40-02	CMM	MK 15 FLOAT SWITCH	10-Oct-94	25-Sep-14	5	EH101	Titchfield, UK	K2523	S/SEDES PN 3515000-252
FRH060004	--	28-40-36	CMM	MK15 FLOAT SWITCH	18-May-00	04-Aug-08	1	EH101	Titchfield, UK	K2523	CANADIAN CORMORANT VERS.
FRH060007	--	PSD-133	SL	Maintenance Service Leaflet	18-Jun-04	--	0	HAWK	Titchfield, UK	K2523	De-burring instructions
FRH060007	--	SIL-CS-4-04	SIL	FLOAT SWITCH - DEFECTIVE MAGNET CHECK	22-Nov-04	04-Jan-05	1	HAWK	Titchfield, UK	K2523	--
FRH090001	--	PSD-066	MM	TEMPERATURE SENSOR	02-Oct-98	--	0	JSF	Titchfield, UK	K2523	--
FRH090004	--	PSD-065	MM	FUEL TEMPERATURE SENSOR	02-Dec-98	--	0	JSF	Titchfield, UK	K2523	--
FRH10002A	--	28-40-06	ACMM	PRESSURE SWITCH	12-Aug-96	07-Feb-08	3	A300, A300-600, A310, A330	Titchfield, UK	K2523	--
FRH10002A	--	SIL-2009-02	SIL	FUEL, OPTIONAL PRESSURE SWITCH	16-Mar-09	07-Jul-09	1	A330, A340	Titchfield, UK	K2523	--
FRH10004A	--	28-40-08	ACMM	PRESSURE SWITCH	27-Sep-96	25-May-99	1	A330, A340	Titchfield, UK	K2523	--
FRH100013A	--	28-22-61	ACMM	APU PRESSURE SWITCH	15-Apr-98	30-Apr-02	2	A319, A320, A321, A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
FRH100014A	--	28-22-62	ACMM	APU FUEL LOW PRESSURE SWITCH	15-Apr-98	12-Jun-18	6	A319, A320, A321	Titchfield, UK	K2523	--
FRH100021A	--	28-40-09	ACMM	PRESSURE SWITCH	29-Sep-98	25-May-99	1	A330, A340	Titchfield, UK	K2523	--
FRH100028A	--	28-40-10	ACMM	Pressure Switch	30-Oct-00	01-May-03	2	A310-MRRT, A330, A340, A340-600	Titchfield, UK	K2523	Re-written - re-issued
FRH120044H	--	PSD-053	MM	APU/FADEC ISOLATION VALVE	09-Sep-98	01-Mar-99	1	JSF	Titchfield, UK	K2523	--
FRH120049R	--	PSD-052	MM	ENGINE ISOLATION VALVE	08-Sep-98	01-Mar-99	1	JSF	Titchfield, UK	K2523	--
FRH120050F	--	28-25-30	CMM	MAINTENANCE SHUT OFF VALVE	30-Apr-98	--	0	KT-1	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRH120060M	--	PSD-388	CMM	Locking wire rework	03-Dec-21	--	0	--	Titchfield, UK	K2523	BASIC MANUAL
FRH120061F	--	28-25-31	CMM	EMERGENCY SHUT OFF VALVE	30-Apr-98	--	0	KT-1	Titchfield, UK	K2523	--
FRH120066P	--	28-88-48+	CMM	2.5"/0.375" Motorised Valve	01-Dec-99	01-Aug-13	1	MK 32 POD	Titchfield, UK	K2523	--
FRH120078K	--	PSD-055	MM	TRANSFER/REFUEL SHUT-OFF VALVE	10-Sep-98	01-Mar-99	1	JSF	Titchfield, UK	K2523	--
FRH120092M	--	PSD-069	MM	GROUND REFUEL/DEFUEL SHUT OFF VALVE	17-Sep-98	01-Mar-99	1	JSF	Titchfield, UK	K2523	--
FRH120094H	--	PSD-059	MM	TEMPERATURE CONTROL VALVE	21-Sep-98	--	0	JSF	Titchfield, UK	K2523	--
FRH120099M	--	28-25-46	CMM	FUEL VENT VALVE	13-Feb-01	18-May-05	2	A319CJ, A321XLR	Titchfield, UK	K2523	--
FRH120099M	--	FRH120099M-28-001	SB	Requalification of Fuel Vent Valve for A321XLR	--	--	0	A321XLR	Titchfield, UK	K2523	TO BE WRITTEN
FRH120099M	--	SIL-2007-03	SIL	CONVERTED TO SB FRH120125-28-01/2/3	--	--	0	A310-MRTT, A319CJ, A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120106M	--	28-24-42	CMM	FUEL CROSSFEED VALVE	23-Aug-99	--	0	A340	Titchfield, UK	K2523	--
FRH120107M	--	28-25-46	CMM	FUEL VENT VALVE	13-Feb-01	18-May-05	2	A319CJ, A321XLR	Titchfield, UK	K2523	--
FRH120112P	--	PSD-056	MM	REMOTELY OPERATED 3-WAY VALVE	21-Dec-98	21-Feb-00	1	JSF	Titchfield, UK	K2523	--
FRH120114P	--	PSD-056	MM	REMOTELY OPERATED 3-WAY VALVE	21-Dec-98	21-Feb-00	1	JSF	Titchfield, UK	K2523	--
FRH120125M	--	28-24-03	CMM	DEFUEL VALVE	20-Jul-01	15-Dec-10	5	A340-600	Titchfield, UK	K2523	--
FRH120126M	--	28-24-03	CMM	DEFUEL VALVE	20-Jul-01	15-Dec-10	5	A340-600	Titchfield, UK	K2523	--
FRH120126M	--	FRH120125-28-02	SB	Unswaged Universal Joints	--	--	0	A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120126M	--	SIL-2007-03	SIL	CONVERTED TO SB FRH120125-28-01/2/3	--	--	0	A310-MRTT, A319CJ, A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120127	--	28-24-03	CMM	DEFUEL VALVE	20-Jul-01	15-Dec-10	5	A340-600	Titchfield, UK	K2523	--
FRH120128	--	28-25-46	CMM	FUEL VENT VALVE	13-Feb-01	18-May-05	2	A319CJ, A321XLR	Titchfield, UK	K2523	--
FRH120133	--	28-24-05	CMM	LP VALVE	15-Nov-01	09-Sep-13	2	A340-500, A340-600	Titchfield, UK	K2523	--
FRH120137R	--	28-30-18	CMM	JETTISON VALVE	02-Jul-01	30-May-05	2	A340-500, A340-600	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRH120138R	--	28-30-18	CMM	JETTISON VALVE	02-Jul-01	30-May-05	2	A340-500, A340-600	Titchfield, UK	K2523	--
FRH120152K	--	28-23-50	CMM	1.5 INCH L.P COCK VALVE	19-Mar-01	17-Jun-11	1	BAE 146	Titchfield, UK	K2523	--
FRH120154K	--	28-23-50	CMM	1.5 INCH L.P COCK VALVE	19-Mar-01	17-Jun-11	1	BAE 146	Titchfield, UK	K2523	--
FRH120196M	--	28-24-05	CMM	LP VALVE	15-Nov-01	09-Sep-13	2	A340-500, A340-600	Titchfield, UK	K2523	--
FRH120197M	--	28-24-05	CMM	LP VALVE	15-Nov-01	09-Sep-13	2	A340-500, A340-600	Titchfield, UK	K2523	--
FRH120197M	--	FRH120197-28-01	SB	FUEL – LP VALVE – MODIFY VALVE TO INCLUDE SECONDARY LOCKING	09-Nov-12	--	0	A340, A340-500, A340-600	Titchfield, UK	K2523	--
FRH120199M	--	28-24-06	CMM	2IN LP ENGINE VALVE (I/B)	07-Dec-01	04-Sep-15	6	A340-500, A340-600	Titchfield, UK	K2523	--
FRH120199M	--	FRH120125-28-02	SB	Unswaged Universal Joints	--	--	0	A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120199M	--	FRH120199-28-01	SB	Replacement LP Inboard Valve	05-Nov-12	--	0	A340-500, A340-600	Titchfield, UK	K2523	--
FRH120199M	--	SIL-2007-03	SIL	CONVERTED TO SB FRH120125-28-01/2/3	--	--	0	A310-MRTT, A319CJ, A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120200M	--	28-24-06	CMM	2IN LP ENGINE VALVE (I/B)	07-Dec-01	04-Sep-15	6	A340-500, A340-600	Titchfield, UK	K2523	--
FRH120201	--	28-24-06	CMM	2IN LP ENGINE VALVE (I/B)	07-Dec-01	04-Sep-15	6	A340-500, A340-600	Titchfield, UK	K2523	--
FRH120202P	--	28-24-04	CMM	CROSSFEED VALVE	01-Oct-01	25-Jan-08	1	A340, A340-600	Titchfield, UK	K2523	--
FRH120202P	--	FRH120125-28-02	SB	Unswaged Universal Joints	--	--	0	A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120202P	--	SIL-2007-03	SIL	CONVERTED TO SB FRH120125-28-01/2/3	--	--	0	A310-MRTT, A319CJ, A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120205P	--	28-24-04	CMM	CROSSFEED VALVE	01-Oct-01	25-Jan-08	1	A340, A340-600	Titchfield, UK	K2523	--
FRH120205P	--	FRH120125-28-02	SB	Unswaged Universal Joints	--	--	0	A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120205P	--	SIL-2007-03	SIL	CONVERTED TO SB FRH120125-28-01/2/3	--	--	0	A310-MRTT, A319CJ, A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120207T	--	28-24-02	CMM	TRANSFER CONTROL VALVE	24-Jul-01	27-Aug-13	1	A340-600	Titchfield, UK	K2523	--
FRH120207T	--	FRH120125-28-02	SB	Unswaged Universal Joints	--	--	0	A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120207T	--	FRH120-28-01	SB	Retaining Ring Check	--	--	0	A340	Titchfield, UK	K2523	TO BE WRITTEN

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRH120207T	--	SIL-2007-03	SIL	CONVERTED TO SB FRH120125-28-01/2/3	--	--	0	A310-MRTT, A319CJ, A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120209T	--	28-24-02	CMM	TRANSFER CONTROL VALVE	24-Jul-01	27-Aug-13	1	A340-600	Titchfield, UK	K2523	--
FRH120209T	--	FRH120125-28-02	SB	Unswaged Universal Joints	--	--	0	A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120209T	--	SIL-2007-03	SIL	CONVERTED TO SB FRH120125-28-01/2/3	--	--	0	A310-MRTT, A319CJ, A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120222P	--	28-20-95	CMM	FUEL VALVE & DRIVE ASSEMBLIES	01-Nov-02	30-Jan-08	1	A310-MRTT	Titchfield, UK	K2523	--
FRH120222P	--	FRH120125-28-03	SB	Unswaged Universal Joints	--	--	0	A310-MRTT	Titchfield, UK	K2523	TO BE WRITTEN
FRH120222P	--	SIL-2007-03	SIL	CONVERTED TO SB FRH120125-28-01/2/3	--	--	0	A310-MRTT, A319CJ, A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120225P	--	28-20-95	CMM	FUEL VALVE & DRIVE ASSEMBLIES	01-Nov-02	30-Jan-08	1	A310-MRTT	Titchfield, UK	K2523	--
FRH120225P	--	FRH120125-28-03	SB	Unswaged Universal Joints	--	--	0	A310-MRTT	Titchfield, UK	K2523	TO BE WRITTEN
FRH120225P	--	SIL-2007-03	SIL	CONVERTED TO SB FRH120125-28-01/2/3	--	--	0	A310-MRTT, A319CJ, A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120228P	--	28-20-95	CMM	FUEL VALVE & DRIVE ASSEMBLIES	01-Nov-02	30-Jan-08	1	A310-MRTT	Titchfield, UK	K2523	--
FRH120228P	--	FRH120125-28-03	SB	Unswaged Universal Joints	--	--	0	A310-MRTT	Titchfield, UK	K2523	TO BE WRITTEN
FRH120228P	--	SIL-2007-03	SIL	CONVERTED TO SB FRH120125-28-01/2/3	--	--	0	A310-MRTT, A319CJ, A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120230P	--	28-20-96	CMM	FUEL VALVE AND DRIVE ASSEMBLY	15-Dec-02	--	0	A310-MRTT	Titchfield, UK	K2523	--
FRH120233P	--	28-20-95	CMM	FUEL VALVE & DRIVE ASSEMBLIES	01-Nov-02	30-Jan-08	1	A310-MRTT	Titchfield, UK	K2523	--
FRH120233P	--	FRH120125-28-03	SB	Unswaged Universal Joints	--	--	0	A310-MRTT	Titchfield, UK	K2523	TO BE WRITTEN
FRH120233P	--	SIL-2007-03	SIL	CONVERTED TO SB FRH120125-28-01/2/3	--	--	0	A310-MRTT, A319CJ, A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120235P	--	28-20-95	CMM	FUEL VALVE & DRIVE ASSEMBLIES	01-Nov-02	30-Jan-08	1	A310-MRTT	Titchfield, UK	K2523	--
FRH120235P	--	FRH120125-28-03	SB	Unswaged Universal Joints	--	--	0	A310-MRTT	Titchfield, UK	K2523	TO BE WRITTEN
FRH120235P	--	SIL-2007-03	SIL	CONVERTED TO SB FRH120125-28-01/2/3	--	--	0	A310-MRTT, A319CJ, A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120258M	--	28-24-03	CMM	DEFUEL VALVE	20-Jul-01	15-Dec-10	5	A340-600	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRH120258M	--	FRH120125-28-02	SB	Unswaged Universal Joints	--	--	0	A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120258M	--	SIL-2007-03	SIL	CONVERTED TO SB FRH120125-28-01/2/3	--	--	0	A310-MRTT, A319CJ, A340-500, A340-600, A340-600 WV101	Titchfield, UK	K2523	TO BE WRITTEN
FRH120259	--	28-24-03	CMM	DEFUEL VALVE	20-Jul-01	15-Dec-10	5	A340-600	Titchfield, UK	K2523	--
FRH120266M	--	28-24-05	CMM	LP VALVE	15-Nov-01	09-Sep-13	2	A340-500, A340-600	Titchfield, UK	K2523	--
FRH120266M	--	FRH120197-28-01	SB	FUEL – LP VALVE – MODIFY VALVE TO INCLUDE SECONDARY LOCKING	09-Nov-12	--	0	A340, A340-500, A340-600	Titchfield, UK	K2523	--
FRH120282M	--	28-24-05	CMM	LP VALVE	15-Nov-01	09-Sep-13	2	A340-500, A340-600	Titchfield, UK	K2523	--
FRH150006P	--	21-51-15_K2523	CMP	(KSA Program Only) Air Conditioning Shut-Off Valve Component Maintenance Publication	--	--	0	EFA	Titchfield, UK	K2523	TO BE WRITTEN
FRH160006M	--	21-40-76	CMM	2in ACTUATED BUTTERFLY VALVE	28-Jun-96	07-Apr-11	6	BAE 146, HAWKER800XP, HS 125	Titchfield, UK	K2523	--
FRH160006M	--	HTE250072-21-1	SB	Modify HTE250072 to HTE250072-1	30-Sep-05	--	0	HAWKER800XP	Titchfield, UK	K2523	--
FRH160024M	--	21-50-22	CMM	2 IN ACTUATED BUTTERFLY VALVE	27-Jan-98	22-Oct-04	1	BAE 125	Titchfield, UK	K2523	--
FRH180013K	--	28-21-26_K2523	CMP	(KSA Program Only) Refuel Shut-Off Valve Component Maintenance Publication	--	--	0	EFA	Titchfield, UK	K2523	TO BE WRITTEN
FRH180014K	--	28-21-28_K2523_1	CMP	(KSA Program Only) Refuel Shut-Off Valve Type II Component Maintenance Publication	--	--	0	EFA	Titchfield, UK	K2523	TO BE WRITTEN
FRH200002H	--	28-22-17	CMM	NON-RETURN VALVE	10-Apr-95	29-Jul-97	1	N250	Titchfield, UK	K2523	--
FRH200011D	--	28-23-49	CMM	1/2 INCH NON RETURN VALVE	24-Nov-97	--	0	N250	Titchfield, UK	K2523	--
FRH200016H	--	PSD-061	MM	HOT FUEL RETURN CHECK VALVE	02-Oct-98	--	0	JSF	Titchfield, UK	K2523	--
FRH200017K	--	PSD-057	MM	TRANSFER PUMP CHECK VALVE	02-Dec-98	--	0	JSF	Titchfield, UK	K2523	--
FRH200021F	--	PSD-083	MM	SCAVENGE PUMP CHECK VALVE	02-Dec-98	--	0	JSF	Titchfield, UK	K2523	--
FRH200058C	--	38-10-16	CMM	Valve Vent	19-Nov-07	--	0	A321, A330, A380	Titchfield, UK	K2523	--
FRH200063P	--	28-26-11	CMM	PRESSURE HOLDING VALVE	31-May-04	10-Jan-15	2	A380	Titchfield, UK	K2523	--
FRH200068M	--	28-26-05	CMM	CANISTER TYPE 20127	02-Dec-04	09-Dec-13	2	A380	Titchfield, UK	K2523	--
FRH210008M	--	28-25-75	CMM	CHECK VALVE, RESTRICTOR	31-May-96	02-Jan-19	4	A330, A340	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRH220008X	--	75-00-05	CMM	4.875 INCH DOUBLE FLAP NRV	29-Mar-93	25-Sep-08	5	RB211-524	Titchfield, UK	K2523	--
FRH220015V	--	36-15-03	CMM	DUCT & NON-RETURN VALVE	28-Sep-01	08-Jan-19	3	A319, A320, A321	Titchfield, UK	K2523	--
FRH220015V	--	HTE460009-36-002	SB	INTRODUCTION OF ST. ST. NRV ASSY	31-May-01	22-Oct-04	2	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH220015V	--	HTE460009-36-003	SB	Intro of New NRV Assy	--	--	0	--	Titchfield, UK	K2523	TO BE WRITTEN
FRH220017V	--	36-15-03	CMM	DUCT & NON-RETURN VALVE	28-Sep-01	08-Jan-19	3	A319, A320, A321	Titchfield, UK	K2523	--
FRH220033V	--	36-15-03	CMM	DUCT & NON-RETURN VALVE	28-Sep-01	08-Jan-19	3	A319, A320, A321	Titchfield, UK	K2523	--
FRH220033V	--	K2523-36-001	SIL	SIL New NRV in Duct	05-Apr-11	--	0	A319, A320, A321	Titchfield, UK	K2523	--
FRH220034V	--	36-15-03	CMM	DUCT & NON-RETURN VALVE	28-Sep-01	08-Jan-19	3	A319, A320, A321	Titchfield, UK	K2523	--
FRH220034V	--	FRH220034V-36-001	SB	DUCT AND NON-RETURN VALVE - VALVE FLAP CRACKING	--	--	0	A319, A320, A321	Titchfield, UK	K2523	CANCELLED
FRH220034V	--	HTE460009-36-002	SB	INTRODUCTION OF ST. ST. NRV ASSY	31-May-01	22-Oct-04	2	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH220034V	--	HTE460009-36-003	SB	Intro of New NRV Assy	--	--	0	--	Titchfield, UK	K2523	TO BE WRITTEN
FRH220034V	--	K2523-36-001	SIL	SIL New NRV in Duct	05-Apr-11	--	0	A319, A320, A321	Titchfield, UK	K2523	--
FRH220034V	--	SIL-CS-1-04	SIL	HTE460009-1 DUCT AND NRV ASSEMBLY - PRODUCTION CANCELLED	19-May-04	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH220034V	--	SIL-CS-3-04	SIL	APU DUCT AND NRV OVERLENGTH SPRINGS	08-Nov-04	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
FRH220036H	--	36-11-99	CMM	SERVICE AIR CHECK VALVE	30-Sep-05	--	0	A380	Titchfield, UK	K2523	--
FRH220055V	--	HTE460009-36-003	SB	Intro of New NRV Assy	--	--	0	--	Titchfield, UK	K2523	TO BE WRITTEN
FRH221007H	--	47-21-14	ACMM	1 INCH CHECK VALVE	09-Dec-15	--	0	C17A	Titchfield, UK	K2523	Changes funded by HS (UTC)
FRH221008X	--	21-52-29	CMM	5IN CHECK VALVE	15-Dec-04	--	0	A380	Titchfield, UK	K2523	HAMILTON SUNDSTRAND
FRH221009T	--	21-63-20	CMM	3.5 IN CHECK VALVE	15-Dec-04	30-Aug-08	2	A380	Titchfield, UK	K2523	HAMILTON SUNDSTRAND
FRH230002R	--	PSD-051	MM	HEAT EXCHANGER BY-PASS VALVE	27-Aug-98	--	0	JSF	Titchfield, UK	K2523	--
FRH230003C	--	38-40-12	CMM	PRESSURE REDUCING AND RELIEF VALVE	27-Feb-01	24-Feb-15	7	A319, A320, A321, A330, A340	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRH230003C	--	SIL-PS-01-00	SIL	ALTERNATIVE PRESSURE REDUCING AND RELIEF VALVE	27-Jan-00	--	0	A319, A320, A321, A330, A340	Titchfield, UK	K2523	--
FRH230014C	--	28-20-98	CMM	THERMAL RELIEF VALVE	20-Dec-02	--	0	A310-MRTT	Titchfield, UK	K2523	--
FRH250007P	--	PSD-067	MM	GROUND REFUEL RECEPTACLE	17-Sep-98	--	0	JSF	Titchfield, UK	K2523	--
FRH280002	--	28-21-41	CMM	AIR RELEASE VALVE	01-Aug-87	05-Nov-15	12	A318, A319, A320, A321, A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
FRH280002	--	9813445-28-1	SB	AIR RELEASE VALVE-FLOAT ASSY SPECIFIC GRAVITY	25-Nov-96	--	0	A320, A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
FRH280002	--	9813445-28-2	SB	FLOAT ASSY SPECIFIC GRAVITY	30-Mar-04	--	0	A319, A320, A321	Titchfield, UK	K2523	--
FRH280005H	--	PSD-063	MM	AIR/NO FUEL VALVE	16-Sep-98	--	0	JSF	Titchfield, UK	K2523	--
FRH280006	--	PSD-064	MM	VENT DRAIN VALVE	02-Oct-98	--	0	JSF	Titchfield, UK	K2523	--
FRH290020	--	28-14-06_K2523	CMP	(KSA Program Only) Fuel Vent Package Component Maintenance Publication	--	--	0	EFA	Titchfield, UK	K2523	TO BE WRITTEN
FRH320002N	--	28-12-09	CMM	REFUEL VENT VALVE	28-Mar-97	--	0	N250	Titchfield, UK	K2523	--
FRH330002C	--	38-41-15	CMM	AIR/NO WATER FLOAT VALVE	01-Aug-02	01-Sep-03	1	A340-500, A340-600	Titchfield, UK	K2523	--
FRH340002B	--	28-25-74	CMM	WATER DRAIN VALVE	24-Aug-95	28-Oct-02	1	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
FRH340003H	--	38-30-30	CMM	WASTE WATER DRAIN VALVE	21-Feb-98	11-May-17	8	A319, A319CJ, A320, A321, A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
FRH340003H	--	SIL-PS-5-96	SIL	WASTE WATER DRAIN VALVE-BIOLOGICAL CONTAMINATION	25-Apr-97	23-Apr-13	4	A310, A319, A319CJ, A320, A321, A330, A340, A340-500, A340-600, F100, F70	Titchfield, UK	K2523	--
FRH340004	--	28-11-44	CMM	WATER DRAIN VALVE (INDIRECT)	16-Feb-96	--	0	A330, A340	Titchfield, UK	K2523	--
FRH340004	--	SIL-PS-5-96	SIL	WASTE WATER DRAIN VALVE-BIOLOGICAL CONTAMINATION	25-Apr-97	23-Apr-13	4	A310, A319, A319CJ, A320, A321, A330, A340, A340-500, A340-600, F100, F70	Titchfield, UK	K2523	--
FRH340005	--	28-11-45	CMM	WATER DRAIN VALVE (DIRECT)	16-Feb-96	18-Feb-00	1	A330, A340, A340-600	Titchfield, UK	K2523	--
FRH340005	--	SIL-PS-5-96	SIL	WASTE WATER DRAIN VALVE-BIOLOGICAL CONTAMINATION	25-Apr-97	23-Apr-13	4	A310, A319, A319CJ, A320, A321, A330, A340, A340-500, A340-600, F100, F70	Titchfield, UK	K2523	--
FRH340008F	--	38-30-30	CMM	WASTE WATER DRAIN VALVE	21-Feb-98	11-May-17	8	A319, A319CJ, A320, A321, A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
FRH340009	--	PSD-070	MM	DRAIN VALVE, DIRECT	02-Oct-98	--	0	JSF	Titchfield, UK	K2523	--
FRH340009	--	SIL-PS-5-96	SIL	WASTE WATER DRAIN VALVE-BIOLOGICAL CONTAMINATION	25-Apr-97	23-Apr-13	4	A310, A319, A319CJ, A320, A321, A330, A340, A340-500, A340-600, F100, F70	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRH340010	--	PSD-071	MM	DRAIN VALVE, REMOTE	02-Oct-98	--	0	JSF	Titchfield, UK	K2523	--
FRH340010	--	SIL-PS-5-96	SIL	WASTE WATER DRAIN VALVE-BIOLOGICAL CONTAMINATION	25-Apr-97	23-Apr-13	4	A310, A319, A319CJ, A320, A321, A330, A340, A340-500, A340-600, F100, F70	Titchfield, UK	K2523	--
FRH340014E	--	38-42-05	CMM	TOILET FLUSH VALVE	11-Jan-91	10-Jun-11	7	BAE 146, BAe ATP	Titchfield, UK	K2523	--
FRH340014E	--	HTE530004-38-002	SB	LEAKAGE FROM PUSH BUTTON	09-Aug-02	12-Sep-02	1	BAE 146	Titchfield, UK	K2523	--
FRH340017	--	28-11-46	CMM	TRIM TANK DRAIN VALVE (INDIRECT)	01-Jun-01	--	0	A340-600	Titchfield, UK	K2523	--
FRH340021H	--	38-30-31	CMM	WASTE WATER DRAIN VALVE	26-Jan-00	18-Jan-11	4	EMBRAER 170, EMBRAER 190, FALCON	Titchfield, UK	K2523	--
FRH340021H	--	SIL-PS-5-96	SIL	WASTE WATER DRAIN VALVE-BIOLOGICAL CONTAMINATION	25-Apr-97	23-Apr-13	4	A310, A319, A319CJ, A320, A321, A330, A340, A340-500, A340-600, F100, F70	Titchfield, UK	K2523	--
FRH340031F	--	SIL-PS-5-96	SIL	WASTE WATER DRAIN VALVE-BIOLOGICAL CONTAMINATION	25-Apr-97	23-Apr-13	4	A310, A319, A319CJ, A320, A321, A330, A340, A340-500, A340-600, F100, F70	Titchfield, UK	K2523	--
FRH340038D	--	38-10-15	CMM	WATER/WASTE NON-RETURN VALVE	08-Mar-93	21-Mar-06	1	A330, A340, A380	Titchfield, UK	K2523	--
FRH380001	--	28-13-08	CMM	JET PUMP	29-Sep-95	--	0	N250	Titchfield, UK	K2523	--
FRH380008	--	PSD-058	MM	SCAVENGE PUMP	21-Nov-98	--	0	JSF	Titchfield, UK	K2523	--
FRH380009	--	28-21-33	CMM	SCAVENGE PUMP	14-Jun-99	--	0	Not Known	Titchfield, UK	K2523	--
FRH380016	--	28-26-10	CMM	JET PUMP	31-May-04	18-Nov-13	3	A380	Titchfield, UK	K2523	--
FRH380020	--	28-24-07	CMM	JET PUMP	11-Aug-03	26-Mar-04	1	A340-500	Titchfield, UK	K2523	--
FRH380031	--	28-26-10	CMM	JET PUMP	31-May-04	18-Nov-13	3	A380	Titchfield, UK	K2523	--
FRH410004P	--	PSD-068	MM	GROUND REFUEL CAP	21-Dec-98	06-Jan-00	1	JSF	Titchfield, UK	K2523	--
FRH430019	--	28-11-09	CMM	FUEL/AIR CONNECTION (PYLON)	14-Feb-01	--	0	KT-1	Titchfield, UK	K2523	--
FRH430020	--	28-11-10	CMM	FUEL/AIR CONNECTION (TANK)	14-Feb-01	10-Apr-08	1	KT-1	Titchfield, UK	K2523	--
FRH430021	--	28-11-12	CMM	FUEL/AIR CONNECTION (WING)	14-Feb-01	10-Apr-08	1	KT-1	Titchfield, UK	K2523	--
FRH430022P	--	28-20-99	CMM	ACT INTERFACE/INTERCONNECTOR	28-Nov-03	10-Oct-14	1	A310-MRTT	Titchfield, UK	K2523	--
FRH461112	--	29-10-25	CMM	SLIDING UNION TYPE 2 (SIZE 24)	09-Jan-06	14-Apr-17	3	A380	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRH461113	--	29-10-26	CMM	SLIDING UNION TYPE 3 (SIZE 32)	10-Jan-06	09-Jun-14	1	A380	Titchfield, UK	K2523	--
FRH461113	--	FRH46111N-29-01	SB	Introduction of New LP Sliding Unions	08-Jan-15	--	0	A380	Titchfield, UK	K2523	--
FRH461114	--	29-10-27	CMM	SLIDING UNION TYPE 4 (SIZE 20)	10-Jan-06	22-Nov-07	1	A380	Titchfield, UK	K2523	--
FRH461115	--	29-10-24	CMM	SLIDING UNION TYPE 1 (SIZE 16)	06-Jan-06	11-Jun-18	3	A380	Titchfield, UK	K2523	--
FRH461115	--	FRH46111N-29-01	SB	Introduction of New LP Sliding Unions	08-Jan-15	--	0	A380	Titchfield, UK	K2523	--
FRH461116	--	29-10-25	CMM	SLIDING UNION TYPE 2 (SIZE 24)	09-Jan-06	14-Apr-17	3	A380	Titchfield, UK	K2523	--
FRH461116	--	FRH46111N-29-01	SB	Introduction of New LP Sliding Unions	08-Jan-15	--	0	A380	Titchfield, UK	K2523	--
FRH461117	--	29-10-26	CMM	SLIDING UNION TYPE 3 (SIZE 32)	10-Jan-06	09-Jun-14	1	A380	Titchfield, UK	K2523	--
FRH461117	--	FRH46111N-29-01	SB	Introduction of New LP Sliding Unions	08-Jan-15	--	0	A380	Titchfield, UK	K2523	--
FRH461118	--	29-10-27	CMM	SLIDING UNION TYPE 4 (SIZE 20)	10-Jan-06	22-Nov-07	1	A380	Titchfield, UK	K2523	--
FRH461119	--	29-10-27	CMM	SLIDING UNION TYPE 4 (SIZE 20)	10-Jan-06	22-Nov-07	1	A380	Titchfield, UK	K2523	--
FRH530004H	--	28-20-09	CMM	FILTER BYPASS VALVE ASSY	01-Dec-87	14-Jun-99	3	F100, F70	Titchfield, UK	K2523	--
FRH530014D	--	32-31-31	CMM	DOOR BYPASS VALVE	26-May-99	15-Oct-14	8	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
FRH530014D	--	FRH530014D-32-1	SB	DOOR BY-PASS VALVE - BROKEN BOLTS.	03-Apr-07	12-Sep-07	1	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
FRH530014D	--	HTE960023-32-1	SB	DOOR BY-PASS VALVE - LEAKAGE AT END CONNECTIONS	01-Feb-99	--	0	A330, A340	Titchfield, UK	K2523	--
FRH530014D	--	SIL-CS-2-04	SIL	DOOR BY-PASS VALVE	20-Aug-04	10-Oct-05	1	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	cancelled
FRH530014D	--	SIL-CS-5-06	SIL	Bolt Tightening Procedure	--	--	0	--	Titchfield, UK	K2523	TO BE WRITTEN
FRH530017C	--	29-20-01+	CMM	GAS CHARGING VALVE	14-Mar-96	13-Mar-19	9	A319, A320, A321, A330, A340, A340-500, A340-600	Titchfield, UK	K2523	DUPLICATE ATA NO.
FRH550007	--	28-50-01	CMM	MK8 NOZZLE AND EMERGENCY NRV	23-Jun-98	15-Dec-98	1	EH101	Titchfield, UK	K2523	--
FRH580011	--	52-60-30	CMM	AIRSTAIR ASSEMBLIES	--	--	0	DORNIER 728JET	Titchfield, UK	K2523	TO BE WRITTEN
FRH580012	--	52-60-40	CMM	RAILS - AIRSTAIR INSTN	--	--	0	DORNIER 728JET	Titchfield, UK	K2523	TO BE WRITTEN

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRH580014	--	52-60-31	CMM	CARRIAGE ASSY - MANUAL	--	--	0	DORNIER 728JET	Titchfield, UK	K2523	TO BE WRITTEN
FRH580016	--	52-60-38	CMM	TRAILING LOOM - MANUAL AIRSTAIR	--	--	0	DORNIER 728JET	Titchfield, UK	K2523	TO BE WRITTEN
FRH580021	--	52-60-30	CMM	AIRSTAIR ASSEMBLIES	--	--	0	DORNIER 728JET	Titchfield, UK	K2523	TO BE WRITTEN
FRH580022	--	52-60-40	CMM	RAILS - AIRSTAIR INSTN	--	--	0	DORNIER 728JET	Titchfield, UK	K2523	TO BE WRITTEN
FRH580023	--	52-60-40	CMM	RAILS - AIRSTAIR INSTN	--	--	0	DORNIER 728JET	Titchfield, UK	K2523	TO BE WRITTEN
FRH580024	--	52-60-32	CMM	CARRIAGE ASSY - ELECTRIC	--	--	0	Not Known	Titchfield, UK	K2523	TO BE WRITTEN
FRH580024-138	--	52-60-34	CMM	CONTROLLER - ELECT. AIRSTAIR	--	--	0	Not Known	Titchfield, UK	K2523	TO BE WRITTEN
FRH580025	--	52-60-40	CMM	RAILS - AIRSTAIR INSTN	--	--	0	DORNIER 728JET	Titchfield, UK	K2523	TO BE WRITTEN
FRH580026	--	52-60-39	CMM	TRAILING LOOM - ELECTRIC AIRSTAIR	--	--	0	Not Known	Titchfield, UK	K2523	TO BE WRITTEN
FRH951001	--	36-13-01	CMM	HP GROUND CONNECTOR & NRV	30-Sep-05	--	0	A380	Titchfield, UK	K2523	--
FRS1005	--	28-09-55	OM	FR PIPE CONNECTORS	01-Jan-69	--	0	Not Known	Titchfield, UK	K2523	--
FRS1075	--	28-09-55	OM	FR PIPE CONNECTORS	01-Jan-69	--	0	Not Known	Titchfield, UK	K2523	--
FRS1091	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS1095	--	28-09-55	OM	FR PIPE CONNECTORS	01-Jan-69	--	0	Not Known	Titchfield, UK	K2523	--
FRS1096	--	28-09-54	OM	FR TERMINATION PIPE CONNECTORS	01-Jan-69	--	0	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
FRS1097	--	28-09-54	OM	FR TERMINATION PIPE CONNECTORS	01-Jan-69	--	0	HFB 320 (HANSA JET)	Titchfield, UK	K2523	--
FRS110	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS110	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS VC10	Titchfield, UK	K2523	--
FRS110	--	28-7-3989	SB	PIPE CONNECTORS - IMPROVED LOCKING CIRCLIP	22-Mar-67	--	0	Not Known	Titchfield, UK	K2523	--
FRS110	--	SIL-2010-01	SIL	Installation of FRS Couplings	14-Jun-10	--	0	NIMROD, VC10	Titchfield, UK	K2523	--
FRS110	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRS1100	--	28-09-55	OM	FR PIPE CONNECTORS	01-Jan-69	--	0	Not Known	Titchfield, UK	K2523	--
FRS1141	--	28-09-3	OM	FR PIPE CONNECTOR	01-Mar-69	--	0	Not Known	Titchfield, UK	K2523	--
FRS1141	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS1143	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS1145	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS122	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS122	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS122	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS132	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS132	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS132	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS150	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS150	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS150	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS175	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS175	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS175	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS185	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS192	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS192	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS192	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRS206	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS230	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS230	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS230	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS246	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS246	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS246	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS295	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS325	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS325	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS325	--	28-4-3512	SB	PIPE CONNECTORS - IMPROVED LOCKING CIRCLIP	31-Mar-66	--	0	Not Known	Titchfield, UK	K2523	--
FRS325	--	28-7-3989	SB	PIPE CONNECTORS - IMPROVED LOCKING CIRCLIP	22-Mar-67	--	0	Not Known	Titchfield, UK	K2523	--
FRS325	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS350	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS355	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS355	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS355	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS370	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS380	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS380	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS395	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
FRS395	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS395	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS400	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS400	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS400	--	SIL-CS-1-03	SIL	FR-PIPE CONCTRS - NON-AV OF THIOKOL	04-Mar-03	21-Sep-07	3	A300, BAe 748, BAe ATP, F27, F28, HAWK, TRISTAR SUP TANKER, VARIOUS, VC10	Titchfield, UK	K2523	--
FRS460	--	28-09-2	OM	HEAT SHIELDS AND DRIP SHIELDS	01-Mar-69	18-Mar-11	5	BAC 1-11, BAe 748, BAe ATP, JS61, YS11	Titchfield, UK	K2523	--
FRS480	--	26-09-1-4628	SB	PIPE CONNECTOR SEAL IDENTIFICATION	01-Dec-75	--	0	Not Known	Titchfield, UK	K2523	--
FRS480	--	28-09-1	OM	FR PIPE CONNECTORS	01-Sep-67	15-Aug-11	8	A300, BAC 1-11, BAe 748, BAe ATP, F28, HFB 320 (HANSA JET), JS61, NIMROD, SD-330, SEA KING, VARIOUS, VC10	Titchfield, UK	K2523	--
HTE440029	--	36-10-11	CMM	DOUBLE FLAP NRV	04-Jul-91	13-May-11	1	BAE 146	Titchfield, UK	K2523	--
HTE4407	--	21-61-20	CMM	NRV	31-Jan-77	--	0	BOEING	Titchfield, UK	K2523	--
HTE4418	--	36-11-02	CMM	3 1/2 NRV	28-Jan-89	18-Apr-16	5	F100, F70, TAY ENGINE (F100 AC)	Titchfield, UK	K2523	--
HTE4431	--	21-00-01	CMM	DOUBLE FLAP NRV	01-Nov-82	--	0	SEA KING, WG30	Titchfield, UK	K2523	--
HTE450001-2	--	HTE450001-3-75-001	SB	MODIFICATION OF 6 IN DOUBLE FLAP NRV	10-Dec-90	--	0	RB211	Titchfield, UK	K2523	--
HTE450001-3	--	HTE450001-3-75-001	SB	MODIFICATION OF 6 IN DOUBLE FLAP NRV	10-Dec-90	--	0	RB211	Titchfield, UK	K2523	--
HTE450001-3	--	HTE450001-75-2	SB	6 IN DOUBLE FLAP NRV - INTRODUCTION OF STELLITE BUSHES	14-Nov-96	--	0	RB211	Titchfield, UK	K2523	--
HTE450001-4	--	75-00-06	CMM	6 INCH DOUBLE FLAP NRV	29-Nov-91	13-Sep-05	5	RB211-524	Titchfield, UK	K2523	--
HTE450001-4	--	HTE450001-75-2	SB	6 IN DOUBLE FLAP NRV - INTRODUCTION OF STELLITE BUSHES	14-Nov-96	--	0	RB211	Titchfield, UK	K2523	--
HTE450001-5	--	75-00-06	CMM	6 INCH DOUBLE FLAP NRV	29-Nov-91	13-Sep-05	5	RB211-524	Titchfield, UK	K2523	--
HTE450001-5	--	HTE450001-75-2	SB	6 IN DOUBLE FLAP NRV - INTRODUCTION OF STELLITE BUSHES	14-Nov-96	--	0	RB211	Titchfield, UK	K2523	--
HTE450001-7	--	75-00-06	CMM	6 INCH DOUBLE FLAP NRV	29-Nov-91	13-Sep-05	5	RB211-524	Titchfield, UK	K2523	--
HTE450001-7	--	HTE450001-75-2	SB	6 IN DOUBLE FLAP NRV - INTRODUCTION OF STELLITE BUSHES	14-Nov-96	--	0	RB211	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE450001-8	--	75-00-06	CMM	6 INCH DOUBLE FLAP NRV	29-Nov-91	13-Sep-05	5	RB211-524	Titchfield, UK	K2523	--
HTE450001-9	--	75-00-06	CMM	6 INCH DOUBLE FLAP NRV	29-Nov-91	13-Sep-05	5	RB211-524	Titchfield, UK	K2523	--
HTE4579	--	29-10-22	CMM	NRV	--	01-Apr-84	1	SD-330, SD-360	Titchfield, UK	K2523	--
HTE4584	--	80-20-03	CMM	NRV	29-Aug-75	--	0	SD-330	Titchfield, UK	K2523	--
HTE460002	--	21-30-04	CMM	NON-RETURN VALVE	19-Mar-86	--	0	JAS 39	Titchfield, UK	K2523	--
HTE460004	--	21-30-06	CMM	DOUBLE FLAP NRV	09-Jul-90	07-Apr-11	1	JS31, JS32	Titchfield, UK	K2523	--
HTE460005	--	21-30-07	CMM	DOUBLE FLAP NRV	09-Jul-90	07-Apr-11	1	JS31	Titchfield, UK	K2523	--
HTE460009	--	36-15-01	CMM	DUCT AND NON-RETURN VALVE	20-Jul-87	30-Sep-02	3	A319, A320, A321	Titchfield, UK	K2523	--
HTE460009	--	HTE460009-36-001	SB	DUCT AND NRV MODIFICATION	10-May-94	19-Jan-95	1	A319, A320, A321	Titchfield, UK	K2523	--
HTE460009	--	HTE460009-36-002	SB	INTRODUCTION OF ST. ST. NRV ASSY	31-May-01	22-Oct-04	2	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
HTE460009	--	SIL-CS-1-04	SIL	HTE460009-1 DUCT AND NRV ASSEMBLY - PRODUCTION CANCELLED	19-May-04	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
HTE460009-1	--	36-15-01	CMM	DUCT AND NON-RETURN VALVE	20-Jul-87	30-Sep-02	3	A319, A320, A321	Titchfield, UK	K2523	--
HTE460009-1	--	HTE460009-36-001	SB	DUCT AND NRV MODIFICATION	10-May-94	19-Jan-95	1	A319, A320, A321	Titchfield, UK	K2523	--
HTE460009-1	--	HTE460009-36-002	SB	INTRODUCTION OF ST. ST. NRV ASSY	31-May-01	22-Oct-04	2	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
HTE460009-1	--	HTE460009-36-003	SB	Intro of New NRV Assy	--	--	0	--	Titchfield, UK	K2523	TO BE WRITTEN
HTE460009-1	--	SIL-CS-1-04	SIL	HTE460009-1 DUCT AND NRV ASSEMBLY - PRODUCTION CANCELLED	19-May-04	--	0	A319, A319CJ, A320, A321	Titchfield, UK	K2523	--
HTE460018	--	21-30-08	CMM	DOUBLE FLAP NRV	09-Jul-90	07-Apr-11	1	JS31	Titchfield, UK	K2523	--
HTE460024	--	21-30-18	cmm	2 IN DOUBLE FLAP NRV	09-Jul-90	--	0	Not Known	Titchfield, UK	K2523	--
HTE460025	--	21-30-19	CMM	4 IN DOUBLE FLAP NRV	09-Jul-90	--	0	BAE 125	Titchfield, UK	K2523	--
HTE460071	--	28-23-58	CMM	1 INCH CHECK VALVE	20-Dec-96	30-Mar-01	1	LEARJET 45	Titchfield, UK	K2523	--
HTE460072	--	28-23-59	CMM	1« INCH CHECK VALVE	20-Dec-96	--	0	LEARJET 45	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE460073-1	--	28-23-60	CMM	2 INCH CHECK VALVE	20-Dec-96	--	0	LEARJET 45	Titchfield, UK	K2523	--
HTE460074	--	38-31-46	CMM	2 1/4IN CHECK VALVE	28-Oct-94	--	0	AOA GTG - TOILET SYS	Titchfield, UK	K2523	Paper and disk format.
HTE460075	--	21-20-14	CMM	50MM NRV	21-Mar-95	--	0	JAS 39	Titchfield, UK	K2523	--
HTE460076	--	21-20-15	CMM	3IN NRV	27-Mar-95	--	0	JAS 39	Titchfield, UK	K2523	--
HTE460078	--	21-00-02	CMM	4 INCH DOUBLE FLAP NON-RETURN VALVE	25-Jul-97	02-Oct-12	1	EH101	Titchfield, UK	K2523	--
HTE4715	--	29-10-07	CMS	FLOW REGULATOR	22-Feb-93	--	0	LYNX	Titchfield, UK	K2523	--
HTE4804	--	28-20-01+	CMM	NRV'S	01-Apr-76	--	0	SD-330	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE4805	--	28-20-01+	CMM	NRV'S	01-Apr-76	--	0	SD-330	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE4820	--	29-10-06+	CMM	NRV	01-Oct-82	--	0	C-23A (MILITARY 330), C-23B (MILITARY 360), SD-360	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE4853	--	28-23-62	ACMM	1/4 INCH SINGLE FLAP NRV	30-Jun-07	--	0	BAE 125, HAWKER800XP, HS 125	Titchfield, UK	K2523	--
HTE4855	--	28-22-24++	CMM	NRV	01-Feb-83	06-May-11	3	BAE 146	Titchfield, UK	K2523	**EX-HTE
HTE4855-1	--	28-22-24++	CMM	NRV	01-Feb-83	06-May-11	3	BAE 146	Titchfield, UK	K2523	**EX-HTE
HTE4874	--	29-20-01	CMM	PRESSURE RELIEF VALVE	01-May-88	--	0	AM-X	Titchfield, UK	K2523	--
HTE4876-1	--	21-00-05	CMM	MANUAL BALL VALVE	09-Jul-90	07-Apr-11	2	JS31, JS32	Titchfield, UK	K2523	--
HTE4878	--	29-00-10	CMM	IN/OUT VENT VALVE	09-Jul-90	06-May-11	1	JS31, JS32	Titchfield, UK	K2523	--
HTE4889	--	28-20-15	CMM	1/4 NRV	--	22-Apr-11	1	BAe ATP	Titchfield, UK	K2523	--
HTE490004	--	75-00-01	TDS	NRV	01-Dec-86	07-Feb-08	1	A310, A319CJ, A320, A321, A340	Titchfield, UK	K2523	--
HTE490005	--	75-00-02	TDS	LINE NRV	01-Dec-86	01-Feb-08	4	A310, A310-MRTT, A319CJ, A320, A321, A340	Titchfield, UK	K2523	--
HTE4912	--	38-41-31	OM	TWIN NON-RETURN VALVE	27-Jun-74	22-Apr-76	1	CONCORDE	Titchfield, UK	K2523	--
HTE4918	--	38-40-05	CMM	NRV	--	15-Oct-97	4	A300, A300-400, A300-600, A310, A319, A320, A321	Titchfield, UK	K2523	--
HTE4918	--	HTE4918-38-2	SB	NON-RETURN VALVE HTE 4918	12-Mar-87	--	0	A300, A300-400, A300-600, A310, A319, A320, A321	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE4925-1	--	28-20-17+	CMM	1 IN ACT BALL VALVE	02-Sep-97	22-Apr-11	3	JS31, JS32, JS41	Titchfield, UK	K2523	*EX-HTE
HTE4925-1	--	HTE4925-1-SB-1	SB	REPLACE VALVE SPINDLE	23-Sep-85	--	0	Not Known	Titchfield, UK	K2523	--
HTE4925-1	--	HTE4925-29-2	SB	INTRO OF PORT & STBD VALVES WITH THERMAL RELIEF	12-Mar-97	--	0	Not Known	Titchfield, UK	K2523	--
HTE4928	--	29-10-31+	CMM	1 IN ACT BALL VALVE	27-Jun-86	22-Apr-11	2	BAe ATP	Titchfield, UK	K2523	*EX-HTE
HTE4934	--	29-20-24+	CMM	1/2 NRV	01-Aug-86	22-Apr-11	1	BAe ATP	Titchfield, UK	K2523	*EX-HTE
HTE510005	--	38-40-10	CMM	PRESSURE REDUCING AND RELIEF VALVE	--	12-Oct-12	7	A300, A300-400, A300-600, A310, A319, A320, A321	Titchfield, UK	K2523	--
HTE510005	--	HTE510005-38-002	SB	MODIFICATION OF PRESSURE REDUCING AND RELIEF VALVE	31-Mar-92	06-Jul-93	2	A320	Titchfield, UK	K2523	--
HTE510005	--	HTE510010-38-001	SB	PRESSURE REDUCING AND RELIEF VALVE	05-Dec-89	--	0	A300-600, A310, A319, A320, A321	Titchfield, UK	K2523	--
HTE510005-1	--	38-40-10	CMM	PRESSURE REDUCING AND RELIEF VALVE	--	12-Oct-12	7	A300, A300-400, A300-600, A310, A319, A320, A321	Titchfield, UK	K2523	--
HTE510005-1	--	HTE510010-38-001	SB	PRESSURE REDUCING AND RELIEF VALVE	05-Dec-89	--	0	A300-600, A310, A319, A320, A321	Titchfield, UK	K2523	--
HTE510005-1	--	SIL-PS-01-00	SIL	ALTERNATIVE PRESSURE REDUCING AND RELIEF VALVE	27-Jan-00	--	0	A319, A320, A321, A330, A340	Titchfield, UK	K2523	--
HTE510010	--	38-40-10	CMM	PRESSURE REDUCING AND RELIEF VALVE	--	12-Oct-12	7	A300, A300-400, A300-600, A310, A319, A320, A321	Titchfield, UK	K2523	--
HTE510010	--	HTE510005-38-002	SB	MODIFICATION OF PRESSURE REDUCING AND RELIEF VALVE	31-Mar-92	06-Jul-93	2	A320	Titchfield, UK	K2523	--
HTE510010	--	HTE510010-38-001	SB	PRESSURE REDUCING AND RELIEF VALVE	05-Dec-89	--	0	A300-600, A310, A319, A320, A321	Titchfield, UK	K2523	--
HTE510010-1	--	38-40-10	CMM	PRESSURE REDUCING AND RELIEF VALVE	--	12-Oct-12	7	A300, A300-400, A300-600, A310, A319, A320, A321	Titchfield, UK	K2523	--
HTE510010-1	--	HTE510005-38-002	SB	MODIFICATION OF PRESSURE REDUCING AND RELIEF VALVE	31-Mar-92	06-Jul-93	2	A320	Titchfield, UK	K2523	--
HTE510010-1	--	HTE510010-38-001	SB	PRESSURE REDUCING AND RELIEF VALVE	05-Dec-89	--	0	A300-600, A310, A319, A320, A321	Titchfield, UK	K2523	--
HTE510013-1	--	29-30-01	CMM	CHECK VALVE	20-Mar-89	22-Apr-11	1	BAe ATP	Titchfield, UK	K2523	--
HTE510016	--	29-20-01+	CMM	GAS CHARGING VALVE	14-Mar-96	13-Mar-19	9	A319, A320, A321, A330, A340, A340-500, A340-600	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE510016	--	HTE510016-29-1	SB	GAS CHNG VLVE PREVENTION OF CONXN OF HP TO LP SPLY	03-Dec-98	--	0	A330, A340	Titchfield, UK	K2523	--
HTE510027-1	--	38-40-01	CMM	PRESSURE REDUCING AND RELIEF VALVE	11-Feb-91	08-Aug-08	3	A330, A340	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE510027-1	--	SIL-PS-01-00	SIL	ALTERNATIVE PRESSURE REDUCING AND RELIEF VALVE	27-Jan-00	--	0	A319, A320, A321, A330, A340	Titchfield, UK	K2523	--
HTE510031	--	36-10-14	CMM	PRESSURE REDUCING AND RELIEF VALVE	01-Dec-95	17-Feb-00	2	--	Titchfield, UK	K2523	--
HTE510032	--	36-10-14	CMM	PRESSURE REDUCING AND RELIEF VALVE	01-Dec-95	17-Feb-00	2	--	Titchfield, UK	K2523	--
HTE510035-1	--	38-40-04	CMM	PRESSURE REGULATING VALVE	18-Mar-92	10-Jun-11	5	BAE 146	Titchfield, UK	K2523	--
HTE510035-1	--	HTE510035-38-1	SB	PRESSURE REGULATING VALVE - CHANGE OF SPRING	23-Oct-97	14-Feb-98	1	BAE 146	Titchfield, UK	K2523	--
HTE510035-2	--	38-40-04	CMM	PRESSURE REGULATING VALVE	18-Mar-92	10-Jun-11	5	BAE 146	Titchfield, UK	K2523	--
HTE510035-2	--	HTE510035-38-1	SB	PRESSURE REGULATING VALVE - CHANGE OF SPRING	23-Oct-97	14-Feb-98	1	BAE 146	Titchfield, UK	K2523	--
HTE520011	--	28-21-20	CMM	DRAIN VALVE	28-Jun-95	06-May-11	1	BAe ATP	Titchfield, UK	K2523	--
HTE520028	--	28-11-07	CMM	DRAIN VALVE	20-Dec-96	--	0	LEARJET 45	Titchfield, UK	K2523	--
HTE520031	--	28-25-20	CMM	FUEL DRAIN VALVE - SELF LOCKING	09-Sep-94	15-Nov-04	1	KT-1	Titchfield, UK	K2523	--
HTE530002	--	41-40-60	CMM	FUSELAGE TANK FLOAT VALVE	01-Oct-88	--	0	AM-X	Titchfield, UK	K2523	--
HTE530003	--	41-30-16	CMM	VENT VALVE ASSEMBLY	01-Oct-88	01-Jul-98	1	AM-X	Titchfield, UK	K2523	--
HTE530004	--	38-42-05	CMM	TOILET FLUSH VALVE	11-Jan-91	10-Jun-11	7	BAE 146, BAe ATP	Titchfield, UK	K2523	--
HTE530004	--	HTE530004-38-001	SB	MODIFICATION OF TOILET FLUSHING VALVE	07-Dec-90	--	0	BAE 146	Titchfield, UK	K2523	--
HTE530004-1	--	38-42-05	CMM	TOILET FLUSH VALVE	11-Jan-91	10-Jun-11	7	BAE 146, BAe ATP	Titchfield, UK	K2523	--
HTE530004-1	--	HTE530004-38-001	SB	MODIFICATION OF TOILET FLUSHING VALVE	07-Dec-90	--	0	BAE 146	Titchfield, UK	K2523	--
HTE530004-1	--	HTE530004-38-002	SB	LEAKAGE FROM PUSH BUTTON	09-Aug-02	12-Sep-02	1	BAE 146	Titchfield, UK	K2523	--
HTE530004-2	--	38-42-05	CMM	TOILET FLUSH VALVE	11-Jan-91	10-Jun-11	7	BAE 146, BAe ATP	Titchfield, UK	K2523	--
HTE530004-2	--	HTE530004-38-002	SB	LEAKAGE FROM PUSH BUTTON	09-Aug-02	12-Sep-02	1	BAE 146	Titchfield, UK	K2523	--
HTE530039-2	--	28-11-08	CMM	FLOAT OPERATED VENT VALVE	03-Nov-97	--	0	LEARJET 45	Titchfield, UK	K2523	--
HTE530042	--	28-25-21	CMM	AIR NO FUEL VALVE WITH THERMAL RELF	02-Sep-94	15-Jul-04	2	KT-1	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE530045	--	28-10-55	CMM	AIR NO FUEL VALVE	10-Apr-95	--	0	EH101	Titchfield, UK	K2523	--
HTE540007	--	28-25-22	CMM	21MM AND 55MM FLAP VALVE	12-Sep-94	--	0	KT-1	Titchfield, UK	K2523	--
HTE540010	--	28-25-22	CMM	21MM AND 55MM FLAP VALVE	12-Sep-94	--	0	KT-1	Titchfield, UK	K2523	--
HTE540-2A	--	29-10-05	CMM	NRV	10-May-76	03-Sep-96	2	C-23A (MILITARY 330), C-23B (MILITARY 360), SD-330, SD-360, SHERPA/UTT	Titchfield, UK	K2523	--
HTE550019	--	28-00-08+	CMM	ADAPTOR	15-May-90	--	0	BAE 125, JS32	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE550020	--	28-00-10+	CMM	FLEXIBLE DRIVE ASSEMBLY	18-May-90	--	0	BAE 125	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE550023	--	28-00-09+	CMM	ADAPTOR	16-May-90	--	0	Not Known	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE550031	--	28-24-04	CMM	CROSSFEED VALVE	01-Oct-01	25-Jan-08	1	A340, A340-600	Titchfield, UK	K2523	--
HTE550031	--	28-24-05	CMM	LP VALVE	15-Nov-01	09-Sep-13	2	A340-500, A340-600	Titchfield, UK	K2523	--
HTE550031	--	28-24-06	CMM	2IN LP ENGINE VALVE (I/B)	07-Dec-01	04-Sep-15	6	A340-500, A340-600	Titchfield, UK	K2523	--
HTE550031	--	28-25-46	CMM	FUEL VENT VALVE	13-Feb-01	18-May-05	2	A319CJ, A321XLR	Titchfield, UK	K2523	--
HTE550031	--	28-30-18	CMM	JETTISON VALVE	02-Jul-01	30-May-05	2	A340-500, A340-600	Titchfield, UK	K2523	--
HTE570064	--	28-25-23	CMM	FLOP TUBE	12-Sep-94	--	0	KT-1	Titchfield, UK	K2523	--
HTE605	--	28-12-62	OM	DRAIN VALVE	21-Sep-74	--	0	CONCORDE	Titchfield, UK	K2523	--
HTE6137	--	27-60-01	CMM	SLIDE AND SWIVEL JOINT	01-Feb-84	05-Aug-11	4	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	BAE to approve
HTE6148	--	32-40-01	CMM	BRAKE SLIDE AND SWIVEL JOINT	01-Feb-84	20-Jan-12	3	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	BAE to approve
HTE6168	--	27-22-04	CMM	RUDDER SWIVEL JOINT	01-Apr-77	--	0	VFW 614	Titchfield, UK	K2523	--
HTE620069	--	29-00-13	CMM	360 DEGREES SWIVEL JOINT	05-Feb-92	--	0	SD-330	Titchfield, UK	K2523	--
HTE620071-1	--	29-10-02	CMM	1 INCH SLIDING UNION	18-Mar-91	15-Dec-10	3	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
HTE620071-1	--	HTE620071-1-29-1	SB	NEW SLIDING UNIONS	15-Mar-04	--	0	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
HTE620072-1	--	29-10-03	CMM	1.5 INCH SLIDING UNION	19-Feb-91	29-Mar-02	2	A330, A340	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE620072-1	--	HTE620071-1-29-1	SB	NEW SLIDING UNIONS	15-Mar-04	--	0	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
HTE620196	--	29-10-14	CMM	1 INCH SLIDING UNION	30-Apr-02	28-Aug-12	4	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
HTE620196	--	HTE620071-1-29-1	SB	NEW SLIDING UNIONS	15-Mar-04	--	0	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
HTE620197	--	29-10-15	CMM	1.5 INCH SLIDING UNION	30-Apr-02	20-Nov-06	2	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
HTE620197	--	HTE620071-1-29-1	SB	NEW SLIDING UNIONS	15-Mar-04	--	0	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
HTE623	--	28-10-04+	CMM	DRAIN VALVE	31-Jan-83	--	0	JAGUAR	Titchfield, UK	K2523	*EX-HTE
HTE625E	--	36-10-42	MM	PRESSURE VENT VALVE	02-Jun-66	23-Oct-67	1	BAC 1-11	Titchfield, UK	K2523	--
HTE6303	--	52-30-10	CMM	SWIVEL PIPE ASSY	01-Dec-84	25-Sep-14	3	A310	Titchfield, UK	K2523	--
HTE6363-1	--	28-00-07	CMM	FLOAT OPERATED VENT VALVE	28-Nov-90	--	0	TRISTAR TANKER	Titchfield, UK	K2523	--
HTE6376	--	28-20-05	CMM	4 INCH RAFLEX COUPLING AND NRV	29-Aug-86	--	0	TRISTAR TANKER	Titchfield, UK	K2523	--
HTE6381	--	28-20-07	CMM	4 INCH ACTUATED BALL VALVE	01-Aug-86	--	0	TRISTAR TANKER	Titchfield, UK	K2523	--
HTE6394	--	28-20-11++	CMM	CROSS AND TRANS VALVES	12-Jan-88	26-Oct-15	9	A319, A320, A321	Titchfield, UK	K2523	--
HTE6395	--	28-20-11++	CMM	CROSS AND TRANS VALVES	12-Jan-88	26-Oct-15	9	A319, A320, A321	Titchfield, UK	K2523	--
HTE640020	--	29-00-12	CMM	3/8 INCH BANJO SWIVEL	29-Jan-92	--	0	SD-330	Titchfield, UK	K2523	--
HTE640024	--	29-30-12	CMM	Hydraulic Swivel	06-Aug-12	--	0	HAWK, Hawk 132 (HAL)	Titchfield, UK	K2523	TCH (pub NOT PN)=HAL, BAE for info only
HTE660020	--	29-11-53	CMM	COMPENSATED SLIDE	20-Jul-87	12-Oct-12	3	A319, A320, A321	Titchfield, UK	K2523	--
HTE69000	--	28-22-52	CMM	PRESSURE SWITCH	12-Jan-84	21-Jan-15	4	A300-600, A310	Titchfield, UK	K2523	Changed from 28-21-52
HTE69000	--	HTE69000-28-001	SB	PRESSURE SWITCH HTE 69000	27-Nov-86	11-Apr-88	1	A319, A320, A321, A330, A340	Titchfield, UK	K2523	--
HTE69000-1	--	28-21-53+	CMM	PRESSURE SWITCH	01-Dec-86	02-Oct-19	6	A300, A300-400, A300-600, A310, A319, A320, A321, A330, A340, A340-500, A340-600	Titchfield, UK	K2523	*EX-HTE
HTE69000-1	--	SIL-2009-02	SIL	FUEL, OPTIONAL PRESSURE SWITCH	16-Mar-09	07-Jul-09	1	A330, A340	Titchfield, UK	K2523	--
HTE690012	--	69-00-12	TDS	PRESSURE SWITCH	05-Apr-87	25-May-99	1	BAE 125	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE690033	--	63-20-01	CMM	PRESSURE SWITCH	28-May-87	28-Jun-99	1	SEA KING	Titchfield, UK	K2523	--
HTE690035	--	29-31-01	TDS	PRESSURE SWITCH	--	28-Jun-99	2	A319, A320, A321	Titchfield, UK	K2523	--
HTE690035	--	HTE690035-29-001	SB	MODIFICATION OF PRESSURE SWITCH	30-Jul-90	--	0	A319, A320, A321	Titchfield, UK	K2523	--
HTE690035-1	--	29-31-01	TDS	PRESSURE SWITCH	--	28-Jun-99	2	A319, A320, A321	Titchfield, UK	K2523	--
HTE690035-1	--	HTE690035-29-001	SB	MODIFICATION OF PRESSURE SWITCH	30-Jul-90	--	0	A319, A320, A321	Titchfield, UK	K2523	--
HTE690040	--	29-30-01+	CMM	PRESSURE SWITCH	01-Aug-87	22-Apr-11	2	BAE 146	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE690041	--	21-30-06+	CMS	PRESSURE SWITCH	23-Sep-91	07-Apr-11	3	BAE 146	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE690042	--	21-30-07+	CMS	PRESSURE SWITCH	23-Sep-91	30-May-03	2	BAE 146	Titchfield, UK	K2523	--
HTE690045	--	28-40-01	TDS	PRESSURE SWITCH	05-Nov-90	03-Dec-18	3	A310, A321, A340	Titchfield, UK	K2523	--
HTE690046	--	28-40-03	CMS	PRESSURE SWITCH	20-Sep-91	06-May-11	4	BAE 146	Titchfield, UK	K2523	--
HTE690047	--	21-20-07	ACMM	PRESSURE SWITCH	20-Aug-87	23-Aug-19	5	A319, A320, A321, A330, A340, A340-500, A340-600	Titchfield, UK	K2523	--
HTE690090	--	21-30-06++	TDS	PRESSURE SWITCH	20-Mar-90	03-Nov-08	2	BAE 125	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE690097	--	21-30-04+	CMM	PRESSURE SWITCH	07-Jan-91	25-May-99	1	BAE 125	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE690108	--	28-40-04	CMS	PRESSURE SWITCH	05-Apr-94	08-Oct-12	3	EH101	Titchfield, UK	K2523	--
HTE690109	--	28-40-05	CMS	PRESSURE SWITCH	05-Apr-94	09-Oct-12	3	EH101	Titchfield, UK	K2523	--
HTE690112	--	29-30-11	ACMM	PRESSURE SWITCH	21-Feb-97	--	0	A319, A320, A321	Titchfield, UK	K2523	--
HTE691002-1	--	21-30-21	ACMM	PRESSURE SWITCH & MOUNTING BRACKET	15-Mar-96	25-May-99	1	BAE 125	Titchfield, UK	K2523	--
HTE692005	--	21-30-05	CMM	PRESSURE SWITCH	08-Jan-91	02-Nov-07	2	BAE 125	Titchfield, UK	K2523	--
HTE6943	--	38-41-13	MM	AIR SUPPLY FILTER	25-Feb-74	--	0	Not Known	Titchfield, UK	K2523	--
HTE711-103F	--	711-103F	TDS	NIPPLE ASSY	01-Nov-82	--	0	SD-330, SD-360	Titchfield, UK	K2523	--
HTE711-115F	--	28-10-06	CMM	GROUND AIR PRESSURE FITTING	01-Jan-88	--	0	AM-X	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE711-18E	--	29-10-02+	CMM	MINILOCK S-S QUICK RELEASE COUPLING	21-Mar-75	--	0	VFW 614	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE711-18F	--	29-10-02+	CMM	MINILOCK S-S QUICK RELEASE COUPLING	21-Mar-75	--	0	VFW 614	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE711-62D	--	29-10-10	CMM	MINILOCK NIPPLE	15-Sep-75	--	0	SD-330, SD-360	Titchfield, UK	K2523	--
HTE711-75B	--	29-10-10	CMM	MINILOCK NIPPLE	15-Sep-75	--	0	SD-330, SD-360	Titchfield, UK	K2523	--
HTE712-11J	--	29-10-02+	CMM	MINILOCK S-S QUICK RELEASE COUPLING	21-Mar-75	--	0	VFW 614	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE712-11K	--	29-10-02+	CMM	MINILOCK S-S QUICK RELEASE COUPLING	21-Mar-75	--	0	VFW 614	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE712-14V	--	38-41-14	MM	AIR CHARGING VALVE	01-Oct-73	--	0	CONCORDE	Titchfield, UK	K2523	--
HTE712-27C	--	29-10-02+	CMM	MINILOCK S-S QUICK RELEASE COUPLING	21-Mar-75	--	0	VFW 614	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE712-27D	--	29-10-02+	CMM	MINILOCK S-S QUICK RELEASE COUPLING	21-Mar-75	--	0	VFW 614	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE714-10-RV	--	49-00-02	CMM	HTP OVERFLOW CONNECTION NIPPLE ASSY	01-Jun-70	--	0	Not Known	Titchfield, UK	K2523	--
HTE714-74K	--	28-25-24	CMM	3/4 IN MINILOCK NIPPLE	13-Sep-94	--	0	KT-1	Titchfield, UK	K2523	--
HTE8001	--	28-23-05	ACMM	VEE-BAND CLAMP	25-Sep-12	25-Sep-12	0	A310, A310-MK11, A319, A320, A321, A330, A340, A340-500, A340-600, BAE 125, BAE 146, A310, A310-MK11, A319, A320, A321, A330, A340, A340-500, A340-600, BAE 125, BAE 146, E100, BAE 146/CLAMP	Titchfield, UK	K2523	Re-issued (orig. iss.16-07-91),
HTE8002	--	28-23-05	ACMM	VEE-BAND CLAMP	25-Sep-12	25-Sep-12	0	A310, A310-MK11, A319, A320, A321, A330, A340, A340-500, A340-600, BAE 125, BAE 146, E100, BAE 146/CLAMP	Titchfield, UK	K2523	Re-issued (orig. iss.16-07-91),
HTE820155	--	28-25-25	CMM	3/4 IN FLEXIBLE COUPLING	12-Sep-94	--	0	KT-1	Titchfield, UK	K2523	--
HTE8204-1C	--	29-09-45	CMM	STARLOCK SOCKETS	26-Nov-75	--	0	CONCORDE	Titchfield, UK	K2523	--
HTE8204-1D	--	29-09-07	CMM	STARLOCK NIPPLES	26-Nov-75	--	0	Not Known	Titchfield, UK	K2523	--
HTE8204-1J	--	29-09-45	CMM	STARLOCK SOCKETS	26-Nov-75	--	0	CONCORDE	Titchfield, UK	K2523	--
HTE8204-1K	--	29-09-07	CMM	STARLOCK NIPPLES	26-Nov-75	--	0	Not Known	Titchfield, UK	K2523	--
HTE8204-1N	--	29-09-45	CMM	STARLOCK SOCKETS	26-Nov-75	--	0	CONCORDE	Titchfield, UK	K2523	--
HTE8204-1Z	--	29-09-07	CMM	STARLOCK NIPPLES	26-Nov-75	--	0	Not Known	Titchfield, UK	K2523	--
HTE8204-2K	--	29-09-07	CMM	STARLOCK NIPPLES	26-Nov-75	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE8404-1-J	--	29-09-46	OM	STARLOCK PRESSURE CAPS	26-Nov-75	--	0	CONCORDE	Titchfield, UK	K2523	--
HTE8404-1-N	--	29-09-46	OM	STARLOCK PRESSURE CAPS	26-Nov-75	--	0	CONCORDE	Titchfield, UK	K2523	--
HTE860001	--	36-10-09	CMM	OUTLET FLAP ACT	15-Sep-88	13-May-11	2	JS31, JS32	Titchfield, UK	K2523	--
HTE860028	--	36-10-10+	CMM	OUTLET DUCT FLAP ACTUATOR	27-Nov-89	06-Jan-15	8	JS31, JS32	Titchfield, UK	K2523	INCL.ACTUATOR HTE200024
HTE860046	--	28-20-97	CMM	MANUAL OVERRIDE	15-Nov-02	--	0	A310-MRTT	Titchfield, UK	K2523	--
HTE880011-1	--	28-00-10++	TDS	1/2 NRV	09-Jul-90	22-Apr-11	1	JS31, JS32	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE880012	--	28-20-29+	CMM	FUEL SELECTOR MANIFOLD	27-Nov-90	03-Jan-08	2	BAE 125	Titchfield, UK	K2523	*EX-HTE
HTE880016	--	28-30-16	CMM	FUEL SELECTOR MANIFOLD	10-Oct-94	10-Dec-14	5	EH101	Titchfield, UK	K2523	--
HTE880016-029	--	28-30-16	CMM	FUEL SELECTOR MANIFOLD	10-Oct-94	10-Dec-14	5	EH101	Titchfield, UK	K2523	--
HTE880016-1	--	28-30-16	CMM	FUEL SELECTOR MANIFOLD	10-Oct-94	10-Dec-14	5	EH101	Titchfield, UK	K2523	--
HTE880017-1	--	28-30-17	CMM	JETTISON/TRANSFER VALVE	24-Sep-95	29-Nov-99	2	EH101	Titchfield, UK	K2523	--
HTE880020	--	32-30-10	CMM	HYDRAULIC CONTROL MANIFOLD	01-Dec-95	13-Jul-15	2	BAE 125	Titchfield, UK	K2523	BASIC MANUAL
HTE8803	--	21-60-09	CMM	ACTUATOR, SINGLE MOTOR	25-Feb-92	15-Jan-15	5	ATR42, ATR42-300, ATR72	Titchfield, UK	K2523	--
HTE8811	--	24-09-15+	CMM	ACTUATOR, SINGLE MOTOR	15-May-82	10-Jun-99	1	Not Known	Titchfield, UK	K2523	*EX-HTE
HTE8813	--	28-20-04	CMM	ACTUATOR TWIN MOTOR	03-May-84	03-Jan-14	6	CASA 235	Titchfield, UK	K2523	'HTE MANUAL'
HTE8815	--	28-20-16+	CMM	ACTUATOR, SINGLE MOTOR	15-Sep-88	19-Dec-14	4	JS31, JS32, JS41	Titchfield, UK	K2523	--
HTE8816	--	24-09-17+	CMM	ACTUATOR SINGLE MOTOR	09-Jul-98	17-Jan-05	3	CASA 235	Titchfield, UK	K2523	*HTE MANUALsee 28-10-63
HTE8818	--	21-60-07	CMM	ACTUATOR, SINGLE MOTOR	07-May-08	03-Mar-14	2	JAS 39	Titchfield, UK	K2523	--
HTE8819	--	24-00-01	CMM	Modulating Actuator	--	--	0	CASA 212	Titchfield, UK	K2523	TO BE WRITTEN
HTE8822	--	28-20-06	CMM	ACTUATOR, TWIN MOTOR	29-Aug-86	05-Jun-08	2	TRISTAR TANKER	Titchfield, UK	K2523	--
HTE8826	--	28-01-12	CMM	ACTUATOR, SINGLE MOTOR	20-Oct-85	30-Sep-04	2	F50	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE8920-J	--	29-09-20	CMM	SCREWED MINLOCK COUPLING	01-Jul-84	--	0	Not Known	Titchfield, UK	K2523	--
HTE8921-K	--	29-09-20	CMM	SCREWED MINLOCK COUPLING	01-Jul-84	--	0	Not Known	Titchfield, UK	K2523	--
HTE900001	--	28-20-10	CMM	LP VALVE	20-May-88	30-Jul-19	10	A319, A320, A321	Titchfield, UK	K2523	--
HTE900001	--	HTE900001-28-001	SB	CONVERSION OF HTE900001-001 TO HTE900118-001	31-Mar-88	--	0	Not Known	Titchfield, UK	K2523	--
HTE900028	--	49-00-03	CMM	1/2 ACT BALL VALVE	30-Jun-86	03-Jun-11	2	BAe ATP	Titchfield, UK	K2523	--
HTE900033	--	28-00-01	CMM	FUEL VALVE	19-Dec-86	31-Oct-18	6	A310, A319, A320, A321, A340	Titchfield, UK	K2523	--
HTE900034	--	28-20-11++	CMM	CROSS AND TRANS VALVES	12-Jan-88	26-Oct-15	9	A319, A320, A321	Titchfield, UK	K2523	--
HTE900034	--	HTE900034-35-28-001	SB	MOD OF FUEL CROSSFEED & FUEL TRANSFER VALVES	01-Aug-90	--	0	A320	Titchfield, UK	K2523	--
HTE900035	--	28-20-11++	CMM	CROSS AND TRANS VALVES	12-Jan-88	26-Oct-15	9	A319, A320, A321	Titchfield, UK	K2523	--
HTE900035	--	HTE900034-35-28-001	SB	MOD OF FUEL CROSSFEED & FUEL TRANSFER VALVES	01-Aug-90	--	0	A320	Titchfield, UK	K2523	--
HTE900044-1	--	28-30-02	CMM	ELECT. ACTUATED FUEL JETTISON VALVE	22-Jun-94	20-Jan-07	3	EH101	Titchfield, UK	K2523	--
HTE900054	--	41-10-03	CMM	GAS PRODUCER SHUT OFF VALVE	01-Oct-88	--	0	AM-X	Titchfield, UK	K2523	--
HTE900056	--	28-20-12++	CMM	INTERCELL TRANS VALVE	01-May-86	19-Dec-14	11	A319, A320	Titchfield, UK	K2523	--
HTE900057	--	28-20-12++	CMM	INTERCELL TRANS VALVE	01-May-86	19-Dec-14	11	A319, A320	Titchfield, UK	K2523	--
HTE900059	--	41-40-18	CMM	EXTERNAL REFUEL/TRANSFER VALVE	01-Oct-88	01-Dec-92	1	AM-X	Titchfield, UK	K2523	--
HTE900060	--	41-20-10	CMM	ENGINE SHUT OFF VALVE	01-Oct-88	01-Dec-92	1	AM-X	Titchfield, UK	K2523	--
HTE900061	--	41-60-04	CMM	DEFUEL VALVE	01-Oct-88	01-Dec-92	1	AM-X	Titchfield, UK	K2523	--
HTE900087	--	28-20-12++	CMM	INTERCELL TRANS VALVE	01-May-86	19-Dec-14	11	A319, A320	Titchfield, UK	K2523	--
HTE900087	--	HTE900087-28-001	SB	FUEL-TRANSFER VALVE-INCORRECT PART MARKING	09-Apr-13	--	0	A318, A319, A320	Titchfield, UK	K2523	--
HTE900087-001	--	28-20-12++	CMM	INTERCELL TRANS VALVE	01-May-86	19-Dec-14	11	A319, A320	Titchfield, UK	K2523	--
HTE900088	--	28-20-12++	CMM	INTERCELL TRANS VALVE	01-May-86	19-Dec-14	11	A319, A320	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE900090	--	28-20-18+	CMM	FUEL SOV	15-Sep-88	22-Apr-11	2	JS31, JS32	Titchfield, UK	K2523	*EX-HTE
HTE900091	--	28-20-19++	CMM	FUEL SOV	15-Sep-88	22-Apr-11	2	JS31, JS32	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE900092	--	29-01-01	CMM	HYDRAULIC SOV	15-Sep-88	18-Mar-11	2	JS31, JS32	Titchfield, UK	K2523	--
HTE900095	--	28-20-12++	CMM	INTERCELL TRANS VALVE	01-May-86	19-Dec-14	11	A319, A320	Titchfield, UK	K2523	--
HTE900096	--	28-20-12++	CMM	INTERCELL TRANS VALVE	01-May-86	19-Dec-14	11	A319, A320	Titchfield, UK	K2523	--
HTE900098	--	28-20-16++	CMM	3 INCH ACTUATED BALL VALVE	14-Apr-88	--	0	IAI VARIOUS AIRCRAFT	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE900100	--	29-01-02	CMM	HYDRAULIC SOV	15-Sep-88	02-Oct-17	4	JS31, JS32	Titchfield, UK	K2523	--
HTE900100-1	--	29-01-02	CMM	HYDRAULIC SOV	15-Sep-88	02-Oct-17	4	JS31, JS32	Titchfield, UK	K2523	--
HTE900118	--	28-20-10	CMM	LP VALVE	20-May-88	30-Jul-19	10	A319, A320, A321	Titchfield, UK	K2523	--
HTE900118-001	--	28-20-10	CMM	LP VALVE	20-May-88	30-Jul-19	10	A319, A320, A321	Titchfield, UK	K2523	--
HTE900118-001	--	HTE900118-28-01	SB	Introduce new TRV	27-Jun-17	27-Jun-17	0	A320	Titchfield, UK	K2523	--
HTE900130-1	--	29-20-01++	CMM	MOTORISED FIRE SOV	09-Jul-90	--	0	BAE 125	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE900132	--	28-20-11++	CMM	CROSS AND TRANS VALVES	12-Jan-88	26-Oct-15	9	A319, A320, A321	Titchfield, UK	K2523	--
HTE900133	--	28-20-11++	CMM	CROSS AND TRANS VALVES	12-Jan-88	26-Oct-15	9	A319, A320, A321	Titchfield, UK	K2523	--
HTE900134	--	28-20-11++	CMM	CROSS AND TRANS VALVES	12-Jan-88	26-Oct-15	9	A319, A320, A321	Titchfield, UK	K2523	--
HTE900134	--	HTE900034-35-28-001	SB	MOD OF FUEL CROSSFEED & FUEL TRANSFER VALVES	01-Aug-90	--	0	A320	Titchfield, UK	K2523	--
HTE900135	--	28-20-11++	CMM	CROSS AND TRANS VALVES	12-Jan-88	26-Oct-15	9	A319, A320, A321	Titchfield, UK	K2523	--
HTE900135	--	HTE900034-35-28-001	SB	MOD OF FUEL CROSSFEED & FUEL TRANSFER VALVES	01-Aug-90	--	0	A320	Titchfield, UK	K2523	--
HTE900156	--	28-20-90	CMM	ACTUATED FUEL SOV & 40MM FUEL VALVE	17-Oct-94	--	0	BOEING 707 TANKER	Titchfield, UK	K2523	--
HTE900156-001	--	28-20-08+	CMM	FUEL SHUT OFF VALVE	24-Feb-93	--	0	Not Known	Titchfield, UK	K2523	*EX-HTE
HTE900157	--	28-20-90	CMM	ACTUATED FUEL SOV & 40MM FUEL VALVE	17-Oct-94	--	0	BOEING 707 TANKER	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE900157-001	--	28-20-09+	CMM	40 MM FUEL VALVE	24-Feb-93	20-Jan-07	1	Not Known	Titchfield, UK	K2523	--
HTE900158	--	29-10-20	CMM	ACT HYDRAULIC SOV	23-Mar-90	21-Mar-00	2	F100	Titchfield, UK	K2523	--
HTE900158	--	HTE900158-29-001	SB	ELEC ACT HYD SOV - MOD OF HTE900158 TO HTE900195	12-Mar-97	--	0	F100	Titchfield, UK	K2523	--
HTE900162	--	28-23-41	CMM	FUEL CROSSFEED VALVE	30-Jan-91	10-May-16	8	A330, A330 NEO, A340	Titchfield, UK	K2523	--
HTE900162	--	HTE900162-28-1	SB	AIRBUS VALVE - PRODUCT IMPROVEMENT	14-Oct-98	14-Oct-98	0	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
HTE900162	--	HTE900212-28-01	SB	FUEL VALVE DRIVE ASSEMBLY INSPECTION PROCEDURE	28-Jul-00	02-Feb-15	1	A330, A340	Titchfield, UK	K2523	--
HTE900162	--	HTE900212-28-01	SB	FUEL VALVE DRIVE ASSEMBLY INSPECTION PROCEDURE	28-Jul-00	02-Feb-15	1	A330, A340	Titchfield, UK	K2523	--
HTE900169	--	28-23-43	CMM	JETTISON FUEL VALVE	30-Jan-91	23-Dec-14	7	A330, A340	Titchfield, UK	K2523	--
HTE900169	--	HTE900162-28-1	SB	AIRBUS VALVE - PRODUCT IMPROVEMENT	14-Oct-98	14-Oct-98	0	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
HTE900169	--	HTE900169-28-2	SB	Fuel System-Jettison Valve-Check	--	--	0	A330, A340	Titchfield, UK	K2523	REPLACED BY REVISED HTE900169-28-1
HTE900170	--	28-00-04	CMM	3 INCH ACTUATED BALL VALVE	--	15-Nov-04	3	VARIOUS	Titchfield, UK	K2523	--
HTE900189	--	28-20-37+	CMM	25MM FUEL VALVE	09-Nov-92	15-Dec-15	6	A321	Titchfield, UK	K2523	*EX-HTE
HTE900193	--	28-20-35+	CMM	50 MM FUEL VALVE	11-Jul-91	02-Oct-12	3	A310, A340	Titchfield, UK	K2523	*EX-HTE
HTE900195	--	29-10-23	CMM	ACTUATED SHUT OFF VALVE	19-Jun-91	04-Aug-00	2	F100, F70	Titchfield, UK	K2523	--
HTE900195	--	HTE900158-29-001	SB	ELEC ACT HYD SOV - MOD OF HTE900158 TO HTE900195	12-Mar-97	--	0	F100	Titchfield, UK	K2523	--
HTE900195-001	--	29-10-23	CMM	ACTUATED SHUT OFF VALVE	19-Jun-91	04-Aug-00	2	F100, F70	Titchfield, UK	K2523	--
HTE900196	--	28-20-33+	CMM	FUEL SHUT OFF VALVE	29-Apr-91	24-Sep-08	2	F50	Titchfield, UK	K2523	--
HTE9002-001	--	24-09-12+	CMM	ACTUATOR, SINGLE MOTOR	15-May-82	07-Apr-08	4	JAGUAR, S-61N HELICOPTER	Titchfield, UK	K2523	*EX-HTE
HTE900205-1	--	28-21-32	CMM	TRANSFER VALVE	20-Oct-98	--	0	EH101	Titchfield, UK	K2523	--
HTE900206-001	--	28-23-44	CMM	CROSSFEED VALVE ASSEMBLY	13-Jul-92	29-Aug-19	6	A340	Titchfield, UK	K2523	--
HTE900206-001	--	HTE900162-28-1	SB	AIRBUS VALVE - PRODUCT IMPROVEMENT	14-Oct-98	14-Oct-98	0	A330, A340	Titchfield, UK	K2523	BASIC MANUAL

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE900206-001	--	HTE900212-28-01	SB	FUEL VALVE DRIVE ASSEMBLY INSPECTION PROCEDURE	28-Jul-00	02-Feb-15	1	A330, A340	Titchfield, UK	K2523	--
HTE900208-001	--	28-23-46	CMM	EMERGENCY ISOLATION VALVE ASSEMBLY	13-Jul-92	09-Dec-15	4	A340	Titchfield, UK	K2523	--
HTE900208-001	--	HTE900162-28-1	SB	AIRBUS VALVE - PRODUCT IMPROVEMENT	14-Oct-98	14-Oct-98	0	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
HTE900208-001	--	HTE900212-28-01	SB	FUEL VALVE DRIVE ASSEMBLY INSPECTION PROCEDURE	28-Jul-00	02-Feb-15	1	A330, A340	Titchfield, UK	K2523	--
HTE900209-001	--	28-23-45	CMM	TANK ISOLATION VALVE ASSEMBLY	13-Jul-92	26-Feb-19	3	A330	Titchfield, UK	K2523	--
HTE900209-001	--	HTE900212-28-01	SB	FUEL VALVE DRIVE ASSEMBLY INSPECTION PROCEDURE	28-Jul-00	02-Feb-15	1	A330, A340	Titchfield, UK	K2523	--
HTE900211	--	28-23-42	CMM	FUEL CROSSFEED VALVE	11-May-92	05-Dec-14	4	A340	Titchfield, UK	K2523	--
HTE900211	--	HTE900162-28-1	SB	AIRBUS VALVE - PRODUCT IMPROVEMENT	14-Oct-98	14-Oct-98	0	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
HTE900211	--	HTE900211-28-1	SB	ACTUATOR FAILURE DUE TO ICE IN FUEL XFEED VALVE	06-Sep-99	--	0	A340	Titchfield, UK	K2523	--
HTE900211	--	HTE900212-28-01	SB	FUEL VALVE DRIVE ASSEMBLY INSPECTION PROCEDURE	28-Jul-00	02-Feb-15	1	A330, A340	Titchfield, UK	K2523	--
HTE900212	--	28-24-41	CMM	LOW PRESSURE FUEL VALVE	11-May-92	01-Nov-18	6	A330, A330 NEO, A340	Titchfield, UK	K2523	--
HTE900212	--	HTE900162-28-1	SB	AIRBUS VALVE - PRODUCT IMPROVEMENT	14-Oct-98	14-Oct-98	0	A330, A340	Titchfield, UK	K2523	BASIC MANUAL
HTE900212	--	HTE900212-28-01	SB	FUEL VALVE DRIVE ASSEMBLY INSPECTION PROCEDURE	28-Jul-00	02-Feb-15	1	A330, A340	Titchfield, UK	K2523	--
HTE900214-001	--	28-23-47	CMM	TANK ISOLATION VALVE ASSEMBLY	13-Jul-92	03-Dec-18	6	A320, A330	Titchfield, UK	K2523	--
HTE900214-001	--	HTE900212-28-01	SB	FUEL VALVE DRIVE ASSEMBLY INSPECTION PROCEDURE	28-Jul-00	02-Feb-15	1	A330, A340	Titchfield, UK	K2523	--
HTE9003-001C	--	WTP113E-013	CMM	ROTARY ACTUATOR	08-Sep-82	01-Apr-08	4	LYNX	Titchfield, UK	K2523	EDITION 2 whatever the revision is
HTE9005-001	--	WTP113E-012	CMM	ROTARY ACTUATOR	01-Aug-78	01-Sep-07	7	LYNX	Titchfield, UK	K2523	WHL MANUAL
HTE9014-1	--	24-09-10+	CMM	ACTUATOR, SINGLE MOTOR	15-May-82	24-Feb-06	1	Not Known	Titchfield, UK	K2523	*EX-HTE
HTE9025-001	--	24-09-01	OM	ROTARY ACTUATOR	27-Jun-75	18-Jan-06	1	VARIOUS	Titchfield, UK	K2523	BASIC MANUAL
HTE9035	--	24-09-04	CMM	ACTUATOR, SINGLE MOTOR	01-May-82	19-Jan-07	9	SD-330, SD-360	Titchfield, UK	K2523	--
HTE9037	--	24-09-05	CMM	ACTUATOR, SINGLE MOTOR	13-Feb-09	05-Feb-09	9	SD-360	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE9037	--	HTE9037-24-001	SB	SINGLE MOTOR ACTUATOR-MOD	30-Aug-90	01-Jun-98	1	SD-330	Titchfield, UK	K2523	--
HTE9037-1	--	24-09-05	CMM	ACTUATOR, SINGLE MOTOR	13-Feb-09	05-Feb-09	9	SD-360	Titchfield, UK	K2523	--
HTE9039	--	28-00-10	CMM	ACTUATOR, SINGLE MOTOR	01-Oct-88	24-Dec-14	6	AM-X	Titchfield, UK	K2523	--
HTE9039	--	41-40-19	CMM	QD COUPLING PYLON TANK	01-Nov-87	--	0	AM-X	Titchfield, UK	K2523	--
HTE9044-001	--	24-09-18	CMM	ACTUATOR, SINGLE MOTOR	20-Mar-90	28-Oct-14	4	BAE 125	Titchfield, UK	K2523	--
HTE9052	--	28-00-10	CMM	ACTUATOR, SINGLE MOTOR	01-Oct-88	24-Dec-14	6	AM-X	Titchfield, UK	K2523	--
HTE9060	--	24-09-06	CMM	ACTUATOR, SINGLE MOTOR	15-May-82	30-Jul-04	3	Not Known	Titchfield, UK	K2523	--
HTE9061	--	24-09-13+	CMM	ACTUATOR, SINGLE MOTOR	15-May-82	09-May-08	4	IAI VARIOUS AIRCRAFT, MBB HELICOPTER	Titchfield, UK	K2523	*EX-HTE
HTE9074	--	36-10-06	CMM	ACTUATOR, SINGLE MOTOR	20-Mar-86	24-Feb-06	1	VFW 614	Titchfield, UK	K2523	BASIC MANUAL
HTE9082-1	--	28-20-01++	CMM	ACTUATOR, SINGLE MOTOR	08-Oct-81	26-Apr-22	14	BAE 146	Titchfield, UK	K2523	--
HTE9082-1	--	HTE9082-32-001	SB	ELECTRICAL ACTUATOR	08-Jun-87	--	0	BAE 146	Titchfield, UK	K2523	--
HTE9082-1	--	HTE9479-29-002	SB	ELECTRICALLY ACTUATED BALL VALVE	27-Nov-86	27-Jan-87	2	BAE 146	Titchfield, UK	K2523	--
HTE9082-1	--	HTE9490-32-002	SB	ELECTRICALLY ACTUATED BALL VALVE	27-Nov-86	04-Mar-87	3	BAE 146	Titchfield, UK	K2523	--
HTE9082-1	--	HTE9531-29-003	SB	HYDRAULIC PUMP ISOLATION VALVE	27-Nov-86	27-Jan-87	2	BAE 146	Titchfield, UK	K2523	--
HTE9082-1	--	HTE9635-29-001	SB	ELECTRICALLY ACTUATED BALL VALVE	27-Nov-86	27-Jan-87	2	BAE 146	Titchfield, UK	K2523	--
HTE9083	--	24-09-04	CMM	ACTUATOR, SINGLE MOTOR	01-May-82	19-Jan-07	9	SD-330, SD-360	Titchfield, UK	K2523	--
HTE9084	--	28-20-01++	CMM	ACTUATOR, SINGLE MOTOR	08-Oct-81	26-Apr-22	14	BAE 146	Titchfield, UK	K2523	--
HTE9093	--	28-01-14	CMM	ACTUATOR, SINGLE MOTOR	30-Oct-85	03-Dec-14	5	VARIOUS	Titchfield, UK	K2523	--
HTE9099	--	24-09-09	CMM	ACTUATOR, SINGLE MOTOR	15-May-82	09-May-08	3	Not Known	Titchfield, UK	K2523	--
HTE9119	--	21-00-12	CMM	2 In Actuated Butterfly Valve	24-Mar-11	--	0	EH101	Titchfield, UK	K2523	--
HTE9140	--	21-60-08	CMM	ACTUATED 40 MM BUTTERFLY VAVLE	25-Feb-92	27-Mar-15	1	ATR42, ATR42-300, ATR72	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE9178	--	21-20-03	CMM	2 IN BUTTERFLY VALVE	29-Jul-81	16-Feb-04	3	BAE 125, SD-360	Titchfield, UK	K2523	--
HTE9181	--	21-20-04	CMM	ON/OFF VALVE	14-Jan-82	07-Apr-11	3	BAE 146, TRISTAR TANKER	Titchfield, UK	K2523	--
HTE9181-1	--	21-20-04	CMM	ON/OFF VALVE	14-Jan-82	07-Apr-11	3	BAE 146, TRISTAR TANKER	Titchfield, UK	K2523	--
HTE920007	--	21-20-03+	CMM	ACTUATED AIR VALVE	19-Feb-87	12-Apr-16	3	A300-600, A310, A319CJ, A321, A340	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE920007-001	--	21-20-03+	CMM	ACTUATED AIR VALVE	19-Feb-87	12-Apr-16	3	A300-600, A310, A319CJ, A321, A340	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE920012	--	29-00-07+	CMM	ACTUATED BALL VALVE	04-Feb-91	--	0	Not Known	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE920021	--	29-00-01+	CMM	ACTUATED BALL VALE	28-Jun-89	--	0	Not Known	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE920026	--	29-10-03+	CMM	ACT. BALL VALVE	04-Feb-88	22-Apr-11	10	BAE 146	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE920039-101	--	29-00-10+	CMM	1 INCH ACTUATED TOMER 270 VALVE	17-Jan-92	--	0	Not Known	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE920040-2	--	38-10-14	CMM	ACTUATED SHUT OFF VALVE	15-Jul-91	17-Jun-11	6	BAE 146	Titchfield, UK	K2523	--
HTE920051	--	28-20-17+	CMM	1 IN ACT BALL VALVE	02-Sep-97	22-Apr-11	3	JS31, JS32, JS41	Titchfield, UK	K2523	*EX-HTE
HTE920052	--	28-20-17+	CMM	1 IN ACT BALL VALVE	02-Sep-97	22-Apr-11	3	JS31, JS32, JS41	Titchfield, UK	K2523	*EX-HTE
HTE920053	--	38-10-14	CMM	ACTUATED SHUT OFF VALVE	15-Jul-91	17-Jun-11	6	BAE 146	Titchfield, UK	K2523	--
HTE920055	--	38-10-14	CMM	ACTUATED SHUT OFF VALVE	15-Jul-91	17-Jun-11	6	BAE 146	Titchfield, UK	K2523	--
HTE920056	--	82-20-10	CMM	WATER METHS SHUT OFF VALVE	23-Aug-96	03-Jun-11	1	JS41	Titchfield, UK	K2523	--
HTE9206	--	28-22-01+	CMM	DEFUELLING GATE-VALVE	12-May-76	--	0	Not Known	Titchfield, UK	K2523	*EX-HTE
HTE9210	--	21-60-10	CMM	38MM MANUAL BUTTERFLY VALVE	05-May-92	--	0	Not Known	Titchfield, UK	K2523	--
HTE9215	--	21-60-01	CMM	HOT AIR BUTTERFLY VALVE	--	07-Mar-00	4	SD-360	Titchfield, UK	K2523	--
HTE9215	--	HTE9215-21-001	SB	1.5 INCH HOT AIR BUTTERFLY VALVE	08-Feb-90	--	0	SD-360	Titchfield, UK	K2523	--
HTE9215-1	--	21-60-01	CMM	HOT AIR BUTTERFLY VALVE	--	07-Mar-00	4	SD-360	Titchfield, UK	K2523	--
HTE9215-1	--	HTE9215-21-001	SB	1.5 INCH HOT AIR BUTTERFLY VALVE	08-Feb-90	--	0	SD-360	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE9232-2	--	21-60-02	CMM	MODULATING TEMP CONTROL VALVE	28-Feb-91	23-Mar-18	6	JAS 39	Titchfield, UK	K2523	--
HTE9232-3	--	21-60-02	CMM	MODULATING TEMP CONTROL VALVE	28-Feb-91	23-Mar-18	6	JAS 39	Titchfield, UK	K2523	--
HTE9232-4	--	21-60-02	CMM	MODULATING TEMP CONTROL VALVE	28-Feb-91	23-Mar-18	6	JAS 39	Titchfield, UK	K2523	--
HTE9232-5	--	21-60-02	CMM	MODULATING TEMP CONTROL VALVE	28-Feb-91	23-Mar-18	6	JAS 39	Titchfield, UK	K2523	--
HTE9232-6	--	21-60-02	CMM	MODULATING TEMP CONTROL VALVE	28-Feb-91	23-Mar-18	6	JAS 39	Titchfield, UK	K2523	--
HTE9232-6	--	HTE9232-6-21-1	SB	TEMPERATURE CONTROL VALVE - NEW V-BAND CLAMP	05-Jun-97	--	0	Not Known	Titchfield, UK	K2523	--
HTE9316	--	HTE9316-24-001	SB	ACTUATOR - MICROSWITCH ASSEMBLY - CRACKED PLAIN LEVER ARM	20-Mar-08	--	0	JAGUAR, S-61N HELICOPTER	Titchfield, UK	K2523	--
HTE9330	--	28-25-02	CMM	0.5 INCH BALL VALVE	02-May-77	--	0	VFW 614	Titchfield, UK	K2523	--
HTE9331	--	30-10-06	CMM	ACTUATED CROSSFEED BALL VALVE	30-Apr-75	18-Mar-11	1	BAE 146	Titchfield, UK	K2523	--
HTE9332-001	--	WAP106C-W001	CMM	ACTUATED ON/OFF VALVE	01-Nov-71	20-Mar-74	1	LYNX	Titchfield, UK	K2523	--
HTE9360	--	29-11-02	CMM	ACTUATED BALL VALVE	28-Mar-78	--	0	VFW 614	Titchfield, UK	K2523	--
HTE9360	--	HTE.SB.29.10	SB	ACTUATED 2 WAY HYD VALVE, INTRO OF MOTOR SEAL CAP	15-Mar-78	--	0	Not Known	Titchfield, UK	K2523	--
HTE940007	--	28-00-07+	CMM	MANUAL BALL VALVE	09-Jul-90	22-Apr-11	1	JS31, JS32, JS41	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE940018	--	28-01-18	CMM	1.5 IN MANUAL SOV	--	10-Jun-11	3	JS31, JS32	Titchfield, UK	K2523	--
HTE940018-1	--	28-01-18	CMM	1.5 IN MANUAL SOV	--	10-Jun-11	3	JS31, JS32	Titchfield, UK	K2523	--
HTE940020	--	28-00-10+++	CMM	1.5 INCH MANUAL SOV	06-Feb-92	--	0	Not Known	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE940025	--	28-00-06+	CMM	MANUAL BALL VALVE	28-Nov-90	--	0	Not Known	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE940032-1	--	28-23-54	CMM	¼ INCH PRE-CHECK VALVE	20-Dec-96	15-Nov-04	1	LEARJET 45	Titchfield, UK	K2523	--
HTE940040	--	28-25-26	CMM	MAINTENANCE SOV	31-Aug-94	--	0	KT-1	Titchfield, UK	K2523	--
HTE940041	--	28-25-27	CMM	MECHANICAL SOV	06-Sep-94	--	0	KT-1	Titchfield, UK	K2523	--
HTE9436	--	28-12-78	CMM	ACTUATED PRESSURISATION VALVE	28-Oct-78	--	0	Not Known	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE9464	--	29-10-11+	CMM	1/2 BALL VALVE	30-Aug-75	30-May-13	3	SD-330, SD-360	Titchfield, UK	K2523	*EX-HTE
HTE9476	--	29-10-12+	OM	14MM ACTUATED BALL VALVE	15-May-82	18-Mar-96	1	Not Known	Titchfield, UK	K2523	--
HTE9479-2	--	29-10-03+	CMM	ACT. BALL VALVE	04-Feb-88	22-Apr-11	10	BAE 146	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE9479-2	--	HTE9479-29-002	SB	ELECTRICALLY ACTUATED BALL VALVE	27-Nov-86	27-Jan-87	2	BAE 146	Titchfield, UK	K2523	--
HTE9479-3	--	29-10-03+	CMM	ACT. BALL VALVE	04-Feb-88	22-Apr-11	10	BAE 146	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE9479-3	--	HTE9479-29-002	SB	ELECTRICALLY ACTUATED BALL VALVE	27-Nov-86	27-Jan-87	2	BAE 146	Titchfield, UK	K2523	--
HTE9479-3	--	HTE9479-3-29-1	SB	HYDRAULIC BALL VALVES - SURFACE FINISH OF BALL	12-Feb-99	--	0	BAE 146	Titchfield, UK	K2523	--
HTE9482	--	28-20-56	OM	ACTUATED BALL VALVE	12-Jul-77	07-Mar-14	1	MBB HELICOPTER	Titchfield, UK	K2523	--
HTE9490-2	--	32-30-02	CMM	ACT FOUR PORT VALVE	01-Apr-85	29-Mar-17	10	BAE 146	Titchfield, UK	K2523	--
HTE9490-2	--	HTE9490-32-001	SB	ELECTRICALLY ACTUATED FOUR PORT BALL VALVE	20-Nov-86	20-Jan-87	1	BAE 146	Titchfield, UK	K2523	--
HTE9490-2	--	HTE9490-32-002	SB	ELECTRICALLY ACTUATED BALL VALVE	27-Nov-86	04-Mar-87	3	BAE 146	Titchfield, UK	K2523	--
HTE9490-3	--	32-30-02	CMM	ACT FOUR PORT VALVE	01-Apr-85	29-Mar-17	10	BAE 146	Titchfield, UK	K2523	--
HTE9490-3	--	HTE9490-32-001	SB	ELECTRICALLY ACTUATED FOUR PORT BALL VALVE	20-Nov-86	20-Jan-87	1	BAE 146	Titchfield, UK	K2523	--
HTE9490-3	--	HTE9490-32-002	SB	ELECTRICALLY ACTUATED BALL VALVE	27-Nov-86	04-Mar-87	3	BAE 146	Titchfield, UK	K2523	--
HTE9490-4	--	32-30-02	CMM	ACT FOUR PORT VALVE	01-Apr-85	29-Mar-17	10	BAE 146	Titchfield, UK	K2523	--
HTE9490-4	--	HTE9490-32-003	SB	Introduction of Improved LGSV Valve	02-Sep-08	--	0	BAE 146	Titchfield, UK	K2523	--
HTE9490-4	--	SIL-CS-3-05	SIL	ELECTRICALLY ACTUATED FOUR PORT VALVE (LANDING GEAR SELECTOR VALVE) IMPROVEMENT TRIAL	10-May-05	10-May-05	0	BAE 146	Titchfield, UK	K2523	Rev 1 was deleted and reverted back to original
HTE9490-4	--	SIL-CS-6-05	SIL	Electrically Actuated 4 Port Valve (LGS) Improvement Trial	19-Aug-05	16-Nov-05	2	BAE 146	Titchfield, UK	K2523	--
HTE9490-5	--	32-30-02	CMM	ACT FOUR PORT VALVE	01-Apr-85	29-Mar-17	10	BAE 146	Titchfield, UK	K2523	--
HTE9490-5	--	HTE9490-32-003	SB	Introduction of Improved LGSV Valve	02-Sep-08	--	0	BAE 146	Titchfield, UK	K2523	--
HTE9499	--	28-20-14+	CMM	FUEL SHUT OFF VAVLE	25-Mar-86	--	0	JPATS/FANRANGER	Titchfield, UK	K2523	*EX-HTE

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE95004	--	29-20-31	CMM	1/4 ACT BALL VALVE	01-Aug-86	22-Apr-11	3	BAe ATP	Titchfield, UK	K2523	--
HTE9510	--	38-12-15	OM	LINE DRAIN VALVE 1/2 IN ELEC. ACT.	23-Oct-74	--	0	Not Known	Titchfield, UK	K2523	--
HTE9526	--	36-10-04	CMM	PRV	23-Apr-82	22-Apr-11	6	BAE 146	Titchfield, UK	K2523	--
HTE9531-2	--	29-10-04+	CMM	HYD PUMP ISOL VALVE	--	18-Mar-11	11	BAE 146	Titchfield, UK	K2523	*EX-HTE
HTE9531-2	--	HTE9531-29-003	SB	HYDRAULIC PUMP ISOLATION VALVE	27-Nov-86	27-Jan-87	2	BAE 146	Titchfield, UK	K2523	--
HTE9531-3	--	29-10-04+	CMM	HYD PUMP ISOL VALVE	--	18-Mar-11	11	BAE 146	Titchfield, UK	K2523	*EX-HTE
HTE9531-3	--	HTE9479-3-29-1	SB	HYDRAULIC BALL VALVES - SURFACE FINISH OF BALL	12-Feb-99	--	0	BAE 146	Titchfield, UK	K2523	--
HTE9531-3	--	HTE9531-29-003	SB	HYDRAULIC PUMP ISOLATION VALVE	27-Nov-86	27-Jan-87	2	BAE 146	Titchfield, UK	K2523	--
HTE9549	--	28-24-01	CMM	ACTUATED SHUT OFF BALL VALVE	18-Aug-75	--	0	VFW 614	Titchfield, UK	K2523	--
HTE9575	--	41-30-05	CMM	PRESSURE VENT VALVE	01-Sep-88	--	0	AM-X	Titchfield, UK	K2523	--
HTE9580	--	28-10-02	CMM	FUEL CONTROL VALVE	--	16-Apr-84	1	SD-330, SD-360	Titchfield, UK	K2523	--
HTE960000	--	29-20-03	CMM	3/8 INCH MANUAL BALL VALVE	21-Jun-93	22-Apr-11	1	BAE 146	Titchfield, UK	K2523	--
HTE960005	--	38-10-11	CMM	DUAL WATER VALVE	15-May-87	13-Nov-11	3	BAe ATP	Titchfield, UK	K2523	--
HTE960023	--	32-31-30	CMM	DOOR BY-PASS VALVE	14-Mar-91	11-Mar-16	9	A330, A340	Titchfield, UK	K2523	--
HTE960023	--	HTE960023-32-1	SB	DOOR BY-PASS VALVE - LEAKAGE AT END CONNECTIONS	01-Feb-99	--	0	A330, A340	Titchfield, UK	K2523	--
HTE960023	--	SIL-CS-2-04	SIL	DOOR BY-PASS VALVE	20-Aug-04	10-Oct-05	1	A330, A340, A340-500, A340-600	Titchfield, UK	K2523	cancelled
HTE960023	--	SIL-CS-5-06	SIL	Bolt Tightening Procedure	--	--	0	--	Titchfield, UK	K2523	TO BE WRITTEN
HTE960029-1	--	29-00-14	CMM	3/8 INCH BALL VALVE	12-Feb-92	06-May-11	2	BAE 125, BAE 146	Titchfield, UK	K2523	--
HTE960034	--	38-10-09	CMM	1/2IN MANUAL BALL VALVE	14-Jul-95	31-Aug-02	1	F100, F70	Titchfield, UK	K2523	--
HTE960035	--	38-10-10	CMM	1/2IN MANUAL BALL VALVE	18-Jul-95	03-Oct-12	2	F100, F70	Titchfield, UK	K2523	--
HTE9621	--	30-10-08	CMM	ACT 3-WAY BALL VALVE	29-Jun-78	18-Mar-11	1	BAE 146, VFW 614	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE9635-2	--	29-10-03+	CMM	ACT. BALL VALVE	04-Feb-88	22-Apr-11	10	BAE 146	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE9635-2	--	HTE9635-29-001	SB	ELECTRICALLY ACTUATED BALL VALVE	27-Nov-86	27-Jan-87	2	BAE 146	Titchfield, UK	K2523	--
HTE9635-3	--	29-10-03+	CMM	ACT. BALL VALVE	04-Feb-88	22-Apr-11	10	BAE 146	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE9635-3	--	HTE9479-3-29-1	SB	HYDRAULIC BALL VALVES - SURFACE FINISH OF BALL	12-Feb-99	--	0	BAE 146	Titchfield, UK	K2523	--
HTE9635-3	--	HTE9635-29-001	SB	ELECTRICALLY ACTUATED BALL VALVE	27-Nov-86	27-Jan-87	2	BAE 146	Titchfield, UK	K2523	--
HTE9681	--	32-30-02	CMM	ACT FOUR PORT VALVE	01-Apr-85	29-Mar-17	10	BAE 146	Titchfield, UK	K2523	--
HTE9681-1	--	32-30-02	CMM	ACT FOUR PORT VALVE	01-Apr-85	29-Mar-17	10	BAE 146	Titchfield, UK	K2523	--
HTE9681-2	--	32-30-02	CMM	ACT FOUR PORT VALVE	01-Apr-85	29-Mar-17	10	BAE 146	Titchfield, UK	K2523	--
HTE9682	--	29-10-03+	CMM	ACT. BALL VALVE	04-Feb-88	22-Apr-11	10	BAE 146	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE9683	--	29-10-03+	CMM	ACT. BALL VALVE	04-Feb-88	22-Apr-11	10	BAE 146	Titchfield, UK	K2523	DUPLICATE ATA NO.
HTE9690	--	28-30-01	CMM	ACTUATED FUEL JETTISON VALVE	19-Jul-82	--	0	WG30	Titchfield, UK	K2523	--
HTE9726-001	--	28-21-42+	OM	DRAIN VALVE	01-Oct-74	01-May-97	0	CONCORDE	Titchfield, UK	K2523	NOT SIGNED, NO ILLUSTRTN
HTE9783	--	38-42-01	CMM	PRV	24-May-82	13-May-11	1	BAE 146	Titchfield, UK	K2523	--
HTE9783-1	--	38-42-04	CMM	PRV	24-May-83	10-Jun-11	4	BAE 146	Titchfield, UK	K2523	--
HTE9783-2	--	38-42-04	CMM	PRV	24-May-83	10-Jun-11	4	BAE 146	Titchfield, UK	K2523	--
HTE9799-1	--	38-42-02	CMM	PRV	19-Nov-82	10-Jun-11	1	BAE 146	Titchfield, UK	K2523	--
HTE980025	--	21-30-03+	CMM	FOXER UNIT SOLENOID VALVE	21-Jun-93	13-Nov-14	3	BAe ATP	Titchfield, UK	K2523	--
HTE980056-2	--	28-23-52	CMM	REFUEL SHUT OFF VALVE	20-Dec-96	--	0	LEARJET 45	Titchfield, UK	K2523	--
HTE980065	--	27-30-01	CMM	STICK PUSH CONTROL VALVE	17-Jul-97	07-Apr-11	2	BAE 146	Titchfield, UK	K2523	--
HTE9812	--	32-40-04	CMM	0.25 INCH NRV	01-Jan-84	--	0	WG30	Titchfield, UK	K2523	--
HTE9817	--	28-10-16+	CMM	MANUAL OVERRIDE	20-May-87	22-Apr-11	2	BAE 146	Titchfield, UK	K2523	*EX-HTE

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
HTE991	--	991	TDS	BANJO SWIVEL	01-Nov-82	--	0	SD-360	Titchfield, UK	K2523	--
HTE9921	--	27-50-10	CMM	SOLENOID OP SOV	01-Feb-77	14-Nov-03	4	SD-330, SD-360	Titchfield, UK	K2523	--
HTE9923	--	32-30-01	CMM	RESTRICTOR VALVES	01-May-82	--	0	SD-330, SD-360	Titchfield, UK	K2523	--
HTE9925	--	32-30-01	CMM	RESTRICTOR VALVES	01-May-82	--	0	SD-330, SD-360	Titchfield, UK	K2523	--
HTE9927	--	32-30-01	CMM	RESTRICTOR VALVES	01-May-82	--	0	SD-330, SD-360	Titchfield, UK	K2523	--
HTE9930	--	32-30-01	CMM	RESTRICTOR VALVES	01-May-82	--	0	SD-330, SD-360	Titchfield, UK	K2523	--
HTE9936	--	32-30-01	CMM	RESTRICTOR VALVES	01-May-82	--	0	SD-330, SD-360	Titchfield, UK	K2523	--
HTE994	--	32-40-02	CMM	5MM BANJO SWIVEL JOINT	01-Feb-84	23-Sep-97	1	HAWK, HAWK (T-45)	Titchfield, UK	K2523	--
HTE9948	--	32-30-03	CMM	RESTRICTOR VALVES	01-Oct-82	--	0	SD-330, SD-360	Titchfield, UK	K2523	--
HTE995	--	32-40-02	CMM	5MM BANJO SWIVEL JOINT	01-Feb-84	23-Sep-97	1	HAWK, HAWK (T-45)	Titchfield, UK	K2523	--
HTE9950	--	32-30-03	CMM	RESTRICTOR VALVES	01-Oct-82	--	0	SD-330, SD-360	Titchfield, UK	K2523	--
HTE9952	--	32-30-01	CMM	RESTRICTOR VALVES	01-May-82	--	0	SD-330, SD-360	Titchfield, UK	K2523	--
HTE9999	--	29-11-05+	CMM	AIR SOV	15-Mar-85	--	0	LYNX	Titchfield, UK	K2523	--
ICZ80360-B13	--	24-09-115	CMM	CUB JAGUAR ACTUATOR	10-Sep-71	--	0	HS 748	Titchfield, UK	K2523	BASIC MANUAL
L20A04	--	28-09-61	OM	SPV	01-Sep-65	--	0	SHORTS SC7 SKYVAN	Titchfield, UK	K2523	--
LJ42376	--	LJ42376-80-01	SB	DUCT, UPPER STARTER AIR, BEARING REPLACEMENT	24-Feb-10	--	0	TRENT	Titchfield, UK	K2523	--
LR54170E	--	28-22-14	CMM	FUEL TRANSFER PUMP	20-Jul-96	--	0	N250	Titchfield, UK	K2523	--
M096249	--	28-25-28	CMM	FUEL FILTER ASSEMBLY	31-Mar-95	--	0	KT-1	Titchfield, UK	K2523	FAIREY MANUAL FOR KTX-1
N30A03	--	SL64	OM	PRV	01-Oct-65	01-Jan-67	1	Not Known	Titchfield, UK	K2523	--
N31A05	--	28-22-25+	OM	NRV	01-May-65	--	0	Not Known	Titchfield, UK	K2523	*EX-SAUNDERS
NFR07102	--	28-11-04	ACMM	ADAPTER AND CAP ASSEMBLY	12-Jun-95	--	0	N250	Titchfield, UK	K2523	SHAW AERO DEVICES MANUAL

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
NFR39107	--	28-22-12	ACMM	MANIFOLD	30-May-95	--	0	N250	Titchfield, UK	K2523	GEC-MARCONI MANUAL
NFR39112	--	28-22-11	CMM	FUEL PUMP ASSEMBLY	31-May-95	--	0	N250	Titchfield, UK	K2523	GEC-MARCONI MANUAL
NFR91110	--	28-42-24	CMM	SIGNAL CONDITIONER	15-Dec-95	--	0	N250	Titchfield, UK	K2523	--
NFR91111	--	28-42-20	CMM	FUELLING PANEL	15-Dec-95	--	0	N250	Titchfield, UK	K2523	--
NFR99107	--	28-12-10	ACMM	FLAME ARRESTOR	12-Jun-95	--	0	N250	Titchfield, UK	K2523	SHAW AERO DEVICES MANUAL
NS1002	--	28-20-2++	OM	NRV	18-Sep-62	15-Jun-66	1	HERALD	Titchfield, UK	K2523	--
NS1205	--	28-2-1++	OM	NRV	01-Jun-60	05-Dec-61	1	Not Known	Titchfield, UK	K2523	SEE 28-2-1 FOR 716BA11,-1
P8F42B10	--	28-23-17	CMM	SPV MOT	--	--	0	Not Known	Titchfield, UK	K2523	OUT OF PRINT
R14F20A04	--	SL70	OM	SPV MOT	01-Dec-66	--	0	Not Known	Titchfield, UK	K2523	--
R4159	--	MM301	MM	--	--	--	0	EFA	Titchfield, UK	K2523	--
R4199	--	MM306	MM	--	--	--	0	EFA	Titchfield, UK	K2523	--
RG9570M1	--	MISC 2	CMM	POWER DRIVEN ROTARY PUMP	15-Nov-85	20-Dec-91	3	PILATUS	Titchfield, UK	K2523	CRANE LEAR ROMAC MANUAL
RG9570R1	--	MISC 2	CMM	POWER DRIVEN ROTARY PUMP	15-Nov-85	20-Dec-91	3	PILATUS	Titchfield, UK	K2523	CRANE LEAR ROMAC MANUAL
RR53710A	--	MISC 1	CMM	CENTRIFUGAL FUEL BOOST PUMP	18-Oct-85	26-Jun-92	1	CESSNA, DORNIER, PILATUS	Titchfield, UK	K2523	CRANE LEAR ROMAC MANUAL
RR53710B	--	MISC 1	CMM	CENTRIFUGAL FUEL BOOST PUMP	18-Oct-85	26-Jun-92	1	CESSNA, DORNIER, PILATUS	Titchfield, UK	K2523	CRANE LEAR ROMAC MANUAL
RR53710D	--	MISC 1	CMM	CENTRIFUGAL FUEL BOOST PUMP	18-Oct-85	26-Jun-92	1	CESSNA, DORNIER, PILATUS	Titchfield, UK	K2523	CRANE LEAR ROMAC MANUAL
RR53710F	--	MISC 1	CMM	CENTRIFUGAL FUEL BOOST PUMP	18-Oct-85	26-Jun-92	1	CESSNA, DORNIER, PILATUS	Titchfield, UK	K2523	CRANE LEAR ROMAC MANUAL
RR53710H	--	MISC 1	CMM	CENTRIFUGAL FUEL BOOST PUMP	18-Oct-85	26-Jun-92	1	CESSNA, DORNIER, PILATUS	Titchfield, UK	K2523	CRANE LEAR ROMAC MANUAL
RR53710J	--	MISC 1	CMM	CENTRIFUGAL FUEL BOOST PUMP	18-Oct-85	26-Jun-92	1	CESSNA, DORNIER, PILATUS	Titchfield, UK	K2523	CRANE LEAR ROMAC MANUAL
SFR45134	--	28-11-04	ACMM	ADAPTER AND CAP ASSEMBLY	12-Jun-95	--	0	N250	Titchfield, UK	K2523	SHAW AERO DEVICES MANUAL
SFR92014	--	77-40-01	CMM	Contents Transmitter	12-Jul-02	--	0	EMBRAER 120	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
SFR92014	--	PSD-129	CMM	Contents Transmitter	--	--	0	EMBRAER 120	Titchfield, UK	K2523	TO BE WRITTEN
SFR92015-1	--	77-40-02	CMM	Contents Transmitter	14-Aug-03	--	0	SAAB 2000	Titchfield, UK	K2523	--
SFR92015-1	--	92015-77-01	SIL	Conformal Coating Check	06-Apr-10	06-Apr-10	0	SAAB 2000	Titchfield, UK	K2523	--
SFR92015-1	--	PSD-129	CMM	Contents Transmitter	--	--	0	EMBRAER 120	Titchfield, UK	K2523	TO BE WRITTEN
SFR92016	--	77-40-03	CMM	Contents Transmitter	07-Jan-04	--	0	V-22 OSPREY	Titchfield, UK	K2523	--
SFR92016	--	PSD-129	CMM	Contents Transmitter	--	--	0	EMBRAER 120	Titchfield, UK	K2523	TO BE WRITTEN
SPE16195	--	28-20-16+++	CMM	SUBMERGED FUEL PUMP	01-Nov-68	--	0	VC10	Titchfield, UK	K2523	--
SPE16505	--	82-20-2+	CMM	WATER METHS INJECTION PUMP	30-Jun-66	13-Aug-04	4	HS 748	Titchfield, UK	K2523	--
SPE17025	--	82-20-04	CMM	PUMP	01-Nov-65	01-Sep-69	3	GULFSTREAM I, YS11	Titchfield, UK	K2523	--
SPE17186	--	OSM498	CMM	PUMP & INV. FLT VALVE	01-Apr-75	01-Apr-92	1	HS 748	Titchfield, UK	K2523	--
SPE17681	--	28-20-22+	CMM	FUEL PUMP	01-May-75	01-Oct-70	1	Not Known	Titchfield, UK	K2523	--
SPE19838	--	28-20-27++	CMM	ELECTRICALLY DRIVEN SUBMERGED FUEL PUMP	27-Jun-66	01-Aug-76	5	HS 748	Titchfield, UK	K2523	+ TR2 & TR3
SPE19838	--	Pu28-14	SB	BP1/RS Mk 6. SPE 19838. Introduction of improved sealing to the motor shaft.	17-Nov-71	--	0	HS 748	Titchfield, UK	K2523	--
SPE20399	--	28-20-36++	CMM	ELECTRICALLY DRIVEN FUEL PUMP	01-Jun-67	28-Feb-68	2	JETSTREAM	Titchfield, UK	K2523	--
SPE20726	--	OSM592	CMM	FUEL RECUPERATOR	01-Mar-70	--	0	Not Known	Titchfield, UK	K2523	--
SPE21041	--	OSM510	CMM	MK 4 PUMP	01-Nov-69	01-Apr-71	?	FRL Equip	Titchfield, UK	K2523	--
SPE6210F	--	OSM498	CMM	PUMP & INV. FLT VALVE	01-Apr-75	01-Apr-92	1	HS 748	Titchfield, UK	K2523	--
SPM20-00-01	--	20-00-01	CMM	Standard Practices Manual	30-Sep-04	29-Nov-12	1	A380	Titchfield, UK	K2523	--
ST3262	--	21-14-11	OM	3IN COMPENSATING SLIDE&GIMBAL JOINT	12-Nov-74	--	0	CONCORDE	Titchfield, UK	K2523	--
TF-157160-1	--	SIL-2008-02	SIL	TF-57160-1 - FILTER - Change of PN	--	--	0	HS 125	Titchfield, UK	K2523	TO BE WRITTEN
TSK2545-5	--	28-21-49	CMM	CANISTER TYPE 8811	01-Jul-91	27-Jul-18	9	A330, A340	Titchfield, UK	K2523	--

For all index queries please contact Robert Lamb, Supportability Manager, Aerospace Group:
techdocenquiry@eaton.com

PART NUMBER	MODEL NUMBER	ATA NUMBER	DOCUMENT TYPE	DOCUMENT TITLE	ISSUE DATE	REVISION DATE	REVISION NUMBER	AIRCRAFT PLATFORM/S	SITE OF MANUFACTURE	CAGE CODE	REMARKS
V2500-A1	--	THDV2500-1IA	CMM	TUBES HOSES AND DUCTS	01-Oct-98	01-Nov-03	53	A319, A320, A321	Titchfield, UK	K2523	Intl.Aero Eng. 3 Volumes
V2500-A5	--	THDV2500-1IA	CMM	TUBES HOSES AND DUCTS	01-Oct-98	01-Nov-03	53	A319, A320, A321	Titchfield, UK	K2523	Intl.Aero Eng. 3 Volumes
HTE200043	--	21-20-11	CMM	ACTUATOR, SINGLE MOTOR	08-Sep-93	13-Feb-15	5	A319, A320, A321	South Molton, UK	U9084	--
HTE200066	--	24-09-64	CMM	SINGLE MOTOR ACTUATOR	22-Dec-99	11-Feb-19	4	A321	South Molton, UK	U9084	--
HTE370001	--	36-15-02	CMM	HP GROUND CON. & NRV	20-Jul-87	20-Apr-16	6	A319, A320, A321, A330, A340, A340-500, A340-600	South Molton, UK	U9084	--
21-0037-1100	--	28-20-36+	CMM	PUMP OUTLET NON-RETURN VALVE	09-Nov-92	27-Oct-15	1	A321	South Molton, UK	U9084	*EX-HTE
23C0002	--	38-40-13	CMM	Pressure Reducing and Relief Valve	--	--	0	A319, A320, A321, A330, A340	South Molton, UK	U9084	TO BE WRITTEN
9406012	--	24-09-43	CMM	FLAT ACTUATOR	01-Oct-81	07-Nov-18	13	A300, A300-600, A310	South Molton, UK	U9084	--
9406056	--	24-09-49	CMM	FLAT ACTUATOR	21-Oct-88	27-Oct-14	5	MK 32 POD	South Molton, UK	U9084	--
9811795	--	38-30-26	CMM	NRV	01-Aug-86	16-Aug-17	7	A300, A300-400, A300-600, A310, A319, A320, A321	South Molton, UK	U9084	--
HTE490012	--	28-20-36+	CMM	PUMP OUTLET NON-RETURN VALVE	09-Nov-92	27-Oct-15	1	A321	South Molton, UK	U9084	*EX-HTE