

P.O. Box 14460
St. Louis, MO 63178-4460

114 Old State Road
Ellisville, MO 63021-5942
(636) 394-2877



Date: June 18, 2013
To: Cooper Bussmann ABU, BAN, FNW, KTQ Midget Fuse Customers
Subject: End-of-Life Notice

To improve product availability and lead times, Bussmann will discontinue the ABU, BAN, FNW and KTQ Series of 13/32" diameter "Midget" fuses effective July 31, 2013, and replace their availability with the BAF, KTK, FNM and BBS midget fuse equivalents.

Orders for the discontinued fuses will be accepted until inventory is exhausted. Once exhausted, the functional equivalent in the recommended replacements listed on page 2 of this notice will be substituted, with the exception of the ABU-60 for which there will be no replacement.

All current stocks of these fuses are viable products and should not be returned.

Important points to remember about this End-of-Life notice:

- Effective October 31, 2013, all orders should be placed using the recommended replacement fuse part numbers.
- Once the inventory for the discontinued Midget fuse part numbers is depleted, the recommended replacement Cooper Bussmann part numbers (in the table on page 2) will be automatically substituted at the same price.
- The recommended replacement part numbers will deliver the same form, fit, function and electrical performance as provided by the part numbers they replace.
- The stock of these Midget fuse series you may have in inventory are still saleable and should not be returned.

Thank you for your continued support of Cooper Bussmann. We are here to help make this product End-of-Life as seamless as possible and to avoid any disruption in your business. Should you have any questions about this notification, please contact your local Bussmann representative or the Bussmann Customer Satisfaction Team toll free at 1-855-BUSSMANN (287-7626).

Cordially,

Cooper Bussmann
Product Management

Discontinued Part #	Discontinued Part # UPC Code	Replacement Part #	Replacement Part # UPC Code
ABU-1	051712700603	BAF-1	051712320016
ABU-2	051712700610	BAF-2	051712320023
ABU-5	051712700634	BAF-5	051712320054
ABU-10	051712700641	BAF-10	051712320108
ABU-20	051712700665	BAF-20	051712320207
ABU-25	051712700672	BAF-25	051712320252
ABU-30	051712700689	BAF-30	051712320306
ABU-40	051712700702	KTK-40	051712420327
ABU-50	051712700719	KTK-50	051712420341
ABU-60	051712700726	no replacement	no replacement
BAN-1	051712707015	BAF-1	051712320016
BAN-2	051712707022	BAF-2	051712320023
BAN-3	051712707039	BAF-3	051712320030
BAN-4	051712707046	BAF-4	051712320047
BAN-5	051712707053	BAF-5	051712320054
BAN-6	051712707060	BAF-6	051712320061
BAN-8	051712707084	BAF-8	051712320092
BAN-10	051712707107	BAF-10	051712320108
BAN-12	051712707121	BAF-12	051712320115
BAN-15	051712707152	BAF-15	051712320153
BAN-20	051712707206	BAF-20	051712320207
BAN-25	051712707251	BAF-25	051712320252
BAN-30	051712707305	BAF-30	051712320306
FNW-12	051712523127	FNM-12	051712521208
FNW-15	051712523134	FNM-15	051712521505
FNW-20	051712523141	FNM-20	051712522007
FNW-25	051712523158	FNM-25	051712522250
FNW-30	051712523165	FNM-30	051712523004
KTQ-1	051712720816	BBS-1	051712707435
KTQ-2	051712720823	BBS-2	051712707442
KTQ-3	051712720830	BBS-3	051712707459
KTQ-4	051712720847	BBS-4	051712707466
KTQ-5	051712720854	BBS-5	051712707473
KTQ-6	051712179225	BBS-6	051712707510