





Power Defense™

Circuit Breaker Accessory

For PDG3 Frame

IL012262EN H02

PDG3 - Screw Terminal/End Cap 400 amps, 3 Poles  
Cat. No. PDG3X3TS400  
Quantity - 1



INSTALL END CAP PRIOR TO BREAKER INSTALLATION.

**Instructions For Assembly:**

- Place End Cap on Breaker.
- Install Breaker.
- Fasten Conductors (Install Bolted Connections).
- Torque Terminal Screws to 120-144 in-lb (14-16 N·m).




Power Defense™

Circuit Breaker Accessory

For PDG3 Frame

IL012262EN H02

PDG3 - Screw Terminal/End Cap 400 amps, 3 Poles  
Cat. No. PDG3X3TS400  
Quantity - 1



INSTALL END CAP PRIOR TO BREAKER INSTALLATION.

**Instructions For Assembly:**

- Place End Cap on Breaker.
- Install Breaker.
- Fasten Conductors (Install Bolted Connections).
- Torque Terminal Screws to 120-144 in-lb (14-16 N·m).





Power Defense™

Circuit Breaker Accessory

For PDG2 Frame

IL012262EN H02

PDG3 - Screw Terminal/End Cap 400 amps, 3 Poles  
Cat. No. PDG3X3TS400  
Quantity - 1



INSTALL END CAP PRIOR TO BREAKER INSTALLATION.

**Instructions For Assembly:**

- Place End Cap on Breaker.
- Install Breaker.
- Fasten Conductors (Install Bolted Connections).
- Torque Terminal Screws to 120-144 in-lb (14-16 N·m).





Power Defense™

Circuit Breaker Accessory

For PDG3 Frame

IL012262EN H02

PDG3 - Screw Terminal/End Cap 400 amps, 3 Poles  
Cat. No. PDG3X3TS400  
Quantity - 1



INSTALL END CAP PRIOR TO BREAKER INSTALLATION.

**Instructions For Assembly:**

- Place End Cap on Breaker.
- Install Breaker.
- Fasten Conductors (Install Bolted Connections).
- Torque Terminal Screws to 120-144 in-lb (14-16 N·m).