



Instructions For Assembly:

Install Screw.

IL012246EN H04

Assemble Wire Clamp to Bottom of Conductor as Shown.

poles

PDG2 Clamp Terminal (Steel) 20 amps, AWG 14-20, 4

595

8668924

6689245955

FAT-N PDG2 Clamp Terminal (Steel) 20 amps, AWG 14-20, 4 poles Cat. No. PDG2X4T20 Power Style No. 624B100G76 Defense™ Quantity - 4 Circuit Breaker Accessory 59 Conductor For PDG2 4 **Frame** Ö 998 Wire Clamp Instructions For Assembly: Assemble Wire Clamp to Bottom of Conductor as Shown. Install Screw. IL012246EN H04