



Eaton
Electronics Division
5735 W. Las Positas Blvd #100
Pleasanton, CA 94588
www.eaton.com/electronics

Product Change Notice

PCN#: EE-PCN16037

10/31/2016

CLASSIFICATION OF CHANGE:

End of Life (EOL)

DESCRIPTION OF CHANGE:

ABC non-RoHS compliant color coded fuses plus various additional fuses have reached EOL

REASON FOR CHANGE:

Product has reached end of life.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

Not applicable

PARTS FAMILIES AFFECTED:

Please see tables on next page.

TIME SCHEDULE:

Last Time Buy Date: November 30, 2016

Last Time Shipment Date: November 30, 2016

Existing inventory is saleable and should not be returned

ISSUED BY:

Global Product Manager:

CONTACT INFORMATION:

For questions or comments, please contact your local [Eaton sales representative](#).

EOL Part Number	Recommended Replacement
135637P4	No Replacement
ABC-10-G	No Replacement
ABC-V-1	ABC-V-1-R
BK-ABC-10DX	No Replacement
BK-ABC-10EE	No Replacement
BK-ABC-10NB	No Replacement
BK-ABC-10NX	No Replacement
BK-ABC-10RR	No Replacement
BK-ABC-1BX	No Replacement
BK-ABC-2EE	No Replacement
BK-ABC-4RX	No Replacement
BK-ABC-4YX	No Replacement
BK-ABC-5DD	No Replacement
BK-ABC-5DX	No Replacement
BK-ABC-5LX	No Replacement
BK-ABC-5RX	No Replacement
BK-ABC-6EX	No Replacement
BK-ABC-6KX	No Replacement
BK-ABC-8YV	No Replacement
BK-ABC-B-10	No Replacement
BK-ABC-V-1-1-2	BK-ABC-V-1-1-2R
BK-S500-2A	BK-S500-2-R