

P.O. Box 14460  
St. Louis, MO 63178-4460  
114 Old State Road  
Ellisville, MO 63021  
Phone: (636) 527-1270



**Date: July 20, 2013**  
**To: Cooper Bussmann Circuit Protection Customers**  
**Subject: End-of-Life Notice for S451 End Cap**

Dear Valued Customer:

Effective immediately, Bussmann has discontinued the S451 axial leaded end cap for retrofitting 5mm diameter fuses.

There is no recommended replacement for this part.

If you need assistance in determining if there is another Bussmann product that can help you meet your application's need, contact our Application Engineers by e-mail at [FuseTech@cooperindustries.com](mailto:FuseTech@cooperindustries.com)

If further information is required regarding this End-of-Life Notice, please contact your Bussmann representative.

We thank you for your continued support of the Cooper Bussmann brand of circuit protection products.

Regards,

Matt Chamberlain  
Global Product Manager  
Electronic Circuit Protection  
Cooper Bussmann  
[matt.chamberlain@cooperindustries.com](mailto:matt.chamberlain@cooperindustries.com)