

Eaton

5735 W. Las Positas Blvd #100 Pleasanton, CA 94588 www.eaton.com/electronics

Product Change Notice

PCN#: EE-PCN15017 November 23, 2015

CLASSIFICATION OF CHANGE:

Datasheet reference specification change

DESCRIPTION OF CHANGE:

Recommended PCB layout dimension update

REASON FOR CHANGE:

Increase manufacturability for different pick and place systems

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices.

PARTS FAMILIES AFFECTED:

FP2-S047-R	FP2-V050-R	FP2-D082-R
FP2-S068-R	FP2-V100-R	FP2-D100-R
FP2-S082-R	FP2-V120-R	FP2-D120-R
FP2-S100-R	FP2-V150-R	
FP2-S120-R	FP2-D047-R	
FP2-S200-R	FP2-D068-R	

ISSUED BY:

Paul Wiener, Global Product Manager - Magnetics

CONTACT INFORMATION:

For questions or comments, please contact your local **Eaton sales representative**.