

Eaton Electronics Division 5735 W. Las Positas Blvd #100 Pleasanton, CA 94588 www.eaton.com/electronics

# **Product Change Notice**

PCN#: EE-PCN17028 06/01/2017

### **CLASSIFICATION OF CHANGE:**

Specification improvement of 1025HC surface mount fuses

## **DESCRIPTION OF CHANGE:**

	Voltage Rating		Interrupting Rating at rated voltage (Vac)	
Part Number	Old	New	Old	New
1025HC40-R	250Vac/72Vdc	250Vac/72Vdc	100A	300A
1025HC50-R	60Vdc	250Vac/60Vdc	N/A	300A

### **REASON FOR CHANGE:**

Due to our continuous improvement efforts, Eaton has achieved a higher interrupting rating at 250Vac for the 40A and a 250Vac rating on the 50A products within the 1025HC product family. The 1025HC family can now be applied in more applications due to these increase in ratings.

## **EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:**

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices.

## **PARTS FAMILIES AFFECTED:**

See table above

## TIME SCHEDULE:

Start Shipment Date: Immediate

### **SAMPLE AVAILABILITY:**

Available upon request

### **QUALIFICATION DATA:**

Available upon request

#### **ISSUED BY:**

Nick Stone: Product Manager – Circuit Protection

## **CONTACT INFORMATION:**

For questions or comments, please contact your local Eaton sales representative.