

Product Change Notice

March 24, 2015

CLASSIFICATION OF CHANGE:


Appearance change.

DESCRIPTION OF CHANGE:

The Eaton PowerStor XB and XV Series supercapacitors are receiving a visible change. This change involves adding a groove around the circumference at the center of the length, as shown in the illustration below.



Current Cell Shape



New Cell Shape

REASON FOR CHANGE:

This groove enhances mechanical stability to the electrode structure inside the can and is part of our continuous improvement efforts.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, PERFORMANCE:

There is no change to the form, fit, electrical properties, or function of these supercapacitors.

PARTS NUMBERS/SERIES/FAMILIES AFFECTED:

XB3550-2R5307-R

XB3560-2R5407-R

XB3585-2R5607-R

XV3550-2R7307-R

XV3560-2R7407-R

XV3585-2R7607-R

TIME SCHEDULE:

Start Shipment Date: October 1, 2014 (date code X40). Existing inventory is saleable and should not be returned.

Last Time Buy Date: n/a

Last Time Shipment Date: n/a

SAMPLE AVAILABILITY:

n/a

QUALIFICATION DATA:

n/a

ISSUED BY:



Jason Lee, Global Product Manager - Supercapacitors

If you have any question about this product change, please contact your local Eaton representative.