

Product Change Notice

PCN#: EE-PCN24006

1/18/2024

CLASSIFICATION OF CHANGE:

Product Transition and End of Life

DESCRIPTION OF CHANGE:

Select Eaton fuse accessories HTC have reached end of life and are being discontinued. Suggested alternates, where applicable, have been suggested.

REASON FOR CHANGE:

To streamline fuse accessories product category, package quantities of select HTC fuse accessories are being replaced by bulk package quantities with “BK1” PN prefix.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

There will be no effect on the quality, reliability, or performance. There are no changes to form, fit, and function of the devices.

PARTS FAMILIES AFFECTED:

Product Series	FG P/N	Part Status	Replacement PN
HTC	BK-HTC-100M	End of Life	BK1-HTC-100M
HTC	BK-HTC-140M	End of Life	BK1-HTC-140M
HTC	BK-HTC-150M	End of Life	BK1-HTC-150M
HTC	BK-HTC-15M	End of Life	BK1-HTC-15M
HTC	BK-HTC-30M	End of Life	BK1-HTC-30M
HTC	BK-HTC-45M	End of Life	BK1-HTC-45M
HTC	BK-HTC-50M	End of Life	BK1-HTC-50M
HTC	HTC-15M	End of Life	BK1-HTC-15M
HTC	HTC-30M	End of Life	BK1-HTC-30M

TIME SCHEDULE:

The replacement parts are available now.

Last Time Buy Date for end-of-life parts: Not Available

SAMPLE AVAILABILITY:

Available upon request

ISSUED BY:

Elon Brown
 Global Product Manager – Circuit Protection

CONTACT INFORMATION:

For questions or comments, please [Contact us](#)