

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
MS24-3906-30BC-4	170043	Vickers	Bent Axis Motors	DHC-7
MF30-3913-30ZE-5	170998	Vickers	Bent Axis Motors	Lockheed 382, 382B, E, F, G
MF36-3907-30Z	174883	Vickers	Inline Piston Motor	YS-11, -11A (Series 200 & 300)
PF90-3911-30ZE-3	181094	Vickers	Bent Axis Pump	CL44D4; CL44J
AA-60321-R	182044	Vickers	Bent Axis ACMP	Bell 204B
MS9-3911-30ZE	188911	Vickers	Bent Axis Motors	B707
AA-19020A	201779	Vickers	Bent Axis ACMP	YS-11, 11A (Series 200 & 300)
AS-19058	202897	Vickers	Bent Axis ACMP	B707
MF9-3911-30Z-S481	230550	Vickers	Inline Piston Motor	C130
AA-19071	237210	Vickers	Bent Axis ACMP	CL44D4; CL44J
AA-19072	237211	Vickers	Bent Axis ACMP	CL44D4; CL44J
PF17L-3911-25ZE-4C	240486	Vickers	Bent Axis Pump	YS-11, -11A (S/N's 2 thru 49)
MS9-3911-30ZE-4C	240863	Vickers	Bent Axis Motors	B707, B727
MF016B0011A	247492	Vickers	Bent Axis Motors	YS-11A (200 & 300 Series)
AS-63664-LE	248262	Vickers	Bent Axis Pump	D-8 (Series 30)
MS9-3911-30-S431-4C	248508	Vickers	Bent Axis Motors	DC-8 (Series 10, 20, 30, 40, 50)
AS-63665-LE	249849	Vickers	Bent Axis Pump	D-8 (Series 50, 60, 61, 62, 63)
MF110B008A	253478	Vickers	Bent Axis Motors	707-100, -100B, -200, -300, -300B, -300C, -400, 720 & 720B
A-0643-089-A	265567	Vickers	Bent Axis PTU	727 (Series 100 & 200)
AS-19570-B-GB1	268737	Vickers	Bent Axis ACMP	BAC-1-11, 400 Series
AS-19570-B	279952	Vickers	Bent Axis ACMP	B727
MS24-3906-30-S589-4	281533	Vickers	Bent Axis Motors	GULF STREAM
AS-19088	283554	Vickers	Bent Axis ACMP	DC-8F, DC-10 (Series 10CF, 30CF, 40 CF)
MF36-3909-20Z-S595-3	283689	Vickers	Inline Piston Motor	L1011
AS-19593	287358	Vickers	Bent Axis ACMP	DC9
AS-66698-L8A	291086	Vickers	Bent Axis Pump	BAC-1-11 (200 & 400 Series)
MF36-3909-11Z-	293843	Vickers	Inline Piston Motor	Lockheed 1329, 1329-25

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
S595-3				
A-0643-089-C	298113	Vickers	Bent Axis PTU	DC9
4V146R002	303925	Vickers	Vane Fuel Pump	
MF36-3909-20Z-S658-3	309742	Vickers	Inline Piston Motor	YS-11
AS-66411-L-S666	314195	Vickers	Bent Axis Pump	DC9, MD80
PVB-022-2	314470	Vickers	Variable Inline Piston Pump	Falcon 10, Falcon 50
AS-66651-L8A	316842	Vickers	Bent Axis Pump	707-100, -100B, -300B, -300C,
PV3-044-8	320598	Vickers	Variable Inline Piston Pump	Bell 205/205A
EA-1045-037-2B	323576	Vickers	Bent Axis ACMP	Lockheed 382, 382B, E, F, G
AS-19570-C	323636	Vickers	Bent Axis ACMP	B727
PV3-075-4	326544	Vickers	Variable Inline Piston Pump	C130
MPEV3-022-5	327784	Vickers	Variable AC Motorpump	DC8
MPEV3-022-3A	328759	Vickers	Variable AC Motorpump	BAC-1-11
PV3-075-5	328837	Vickers	Variable Inline Piston Pump	YS-11
PV3-044-16B	333861	Vickers	Variable Inline Piston Pump	YS-11
MS30-3913-25Z-S656-5A	334359	Vickers	Bent Axis Motors	DC-8
<b>MF1-095-6</b>	<b>342381</b>	<b>Vickers</b>	<b>Bent Axis Motors</b>	<b>747-100, -200B, -400; 777 - 200</b>
PV3-022-18	351290	Vickers	Variable Inline Piston Pump	SA-226
4V146R101	352325	Vickers	Vane Fuel Pump	
AA-19089	354744	Vickers	Bent Axis ACMP	
A-0643-089-D	369724	Vickers	Bent Axis PTU	
<b>PV3-160-4</b>	<b>371380</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>B707/B727/B737, DC9, MD88</b>
PF4-094-2B	377305	Vickers	Vane Fuel Pump	JT15D
MPEV1-060-2	378001	Vickers	Fixed AC Motorpump	727-100, -200; 737-100, -200
PF4-024-5	381194	Vickers	Vane Fuel Pump	PT6A
PV3-044-26	384925	Vickers	Variable Inline Piston Pump	SA-226, Jetstream 31
MF3-044-3	385840	Vickers	Inline Piston Motor	L1011

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
PV3-075-10	388222	Vickers	Variable Inline Piston Pump	L1011
<b>PV3-075-12</b>	<b>390060</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>A300, A310</b>
MF3-075-4B	391357	Vickers	Inline Piston Motor	
PPF4-094-3A	395575	Vickers	Vane Fuel Pump	TFE-731
MPHF1-152-2B	395812	Vickers	Fixed Bent Axis PTU	L1011
MPEV3-032-2	396370	Vickers	Variable AC Motorpump	Lockheed 382
PV3-022-25	402431	Vickers	Variable Inline Piston Pump	MU-300
MPEV3-022-14D	403756	Vickers	Variable AC Motorpump	L1011
<b>MPHF1-152-3</b>	<b>404250</b>	<b>Vickers</b>	<b>Fixed Bent Axis PTU</b>	<b>A300, A310</b>
A-0643-089-E	405016	Vickers	Bent Axis PTU	DC-9
MPEV3-032-1D	405893	Vickers	Variable AC Motorpump	DC-10, -10, -30, -40, MD-10-10F, MD-10-30F
MPEV3-032-1E	414470	Vickers	Variable AC Motorpump	DC-9, DC-10, A300, A310, MD-10
AS-19593-B	414770	Vickers	Bent Axis ACMP	
PPF4-094-1J	417219	Vickers	Vane Fuel Pump	TFE-731
PPF4-094-2G	417221	Vickers	Vane Fuel Pump	TFE-731
PV3-044-30A	418397	Vickers	Variable Inline Piston Pump	Lockheed 1329, 1329-25
<b>CMV3-075-1D</b>	<b>418575</b>	<b>Vickers</b>	<b>Servo Control Motor</b>	<b>DC-10, MD11</b>
<b>PV3-160-4A</b>	<b>424244</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>B707/B727/B737</b>
AS-19593-C	428117	Vickers	Bent Axis ACMP	
PV3-044-33	428131	Vickers	Variable Inline Piston Pump	CL-600
MPEV3-022-14E	428153	Vickers	Variable AC Motorpump	L1011
PPF4-094-19	428199	Vickers	Vane Fuel Pump	TFE-731
<b>MPEV3-032-10A</b>	<b>518150</b>	<b>Vickers</b>	<b>Variable AC Motorpump</b>	<b>A320</b>
<b>A-0643-089-F</b>	<b>518735</b>	<b>Vickers</b>	<b>Bent Axis PTU</b>	
PPF4-094-18	569072	Vickers	Vane Fuel Pump	TFE-731
PPF4-094-13	569196	Vickers	Vane Fuel Pump	TFE-731
PPF4-094-14	569260	Vickers	Vane Fuel Pump	TFE-731

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
PPF4-094-15	569262	Vickers	Vane Fuel Pump	TFE-731
PPF4-094-16	569264	Vickers	Vane Fuel Pump	TFE-731
PV3-160-8	569653	Vickers	Variable Inline Piston Pump	DC-8
<b>MF1-019-1</b>	<b>569668</b>	<b>Vickers</b>	<b>Bent Axis Motors</b>	<b>757</b>
<b>MF1-060-18</b>	<b>569670</b>	<b>Vickers</b>	<b>Bent Axis Motors</b>	<b>757; 737-300, -400</b>
<b>MF1-152-9</b>	<b>569672</b>	<b>Vickers</b>	<b>Bent Axis Motors</b>	<b>757</b>
<b>PV3-032-3</b>	<b>570347</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>DHC-8</b>
PV3-044-38A	570527	Vickers	Variable Inline Piston Pump	CL-600
<b>PV3-022-29</b>	<b>570796</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>EMB-120</b>
<b>MPHF1-152-3A</b>	<b>571191</b>	<b>Vickers</b>	<b>Fixed Bent Axis PTU</b>	<b>A300, A310</b>
AA-34563-A	601729	Vickers	Bent Axis ACMP	
<b>MPHF3-160-8C</b>	<b>622362</b>	<b>Vickers</b>	<b>Fixed Inline PTU</b>	<b>B757</b>
<b>MPHF3-160-8D</b>	<b>622532</b>	<b>Vickers</b>	<b>Fixed Inline PTU</b>	<b>B757</b>
<b>MF1-019-3</b>	<b>622634</b>	<b>Vickers</b>	<b>Bent Axis Motors</b>	<b>757/767</b>
PV3-044-41	622738	Vickers	Variable Inline Piston Pump	CL-600
<b>PV3-240-2H</b>	<b>623272</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>A300/310</b>
<b>MPEV3-056-6F</b>	<b>623303</b>	<b>Vickers</b>	<b>Variable AC Motorpump</b>	<b>B747/B757/B767</b>
<b>PV3-160-4B</b>	<b>623337</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>B707/B727/B737</b>
<b>PV3-160-4C</b>	<b>623339</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>B707/B727/B737</b>
<b>MPEV3-008-2B</b>	<b>623859</b>	<b>Vickers</b>	<b>Variable DC Motorpump</b>	<b>EMB120</b>
<b>PV3-240-10</b>	<b>623977</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>B747/767, A320, MD-11, MD-10</b>
MPEV3-056-7	624206	Vickers	Variable AC Motorpump	B727/B737
MPEV3-011-25B	624345	Vickers	Variable AC Motorpump	DHC-8
MPEV3-032-1F	624372	Vickers	Variable AC Motorpump	MD-80, DC-10, MD11
<b>MPEV3-032-10B</b>	<b>693335</b>	<b>Vickers</b>	<b>Variable AC Motorpump</b>	<b>A320</b>
PV3-011-8GB1	715640	Vickers	Variable Inline Piston Pump	SD3-30
EA-50057-GB3	715745	Vickers	Bent Axis ACMP	BAE-146

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
MPEV3-011-13GB1	715750	Vickers	Variable AC Motorpump	BAE-146
MPEV3-032-GB1	715776	Vickers	Variable AC Motorpump	BAE-146
MPHF1-037-UK2	716853	Vickers	Fixed Bent Axis PTU	BAE-146
HR6B9-002-UK2	716884	Vickers	Brake Metering Valve	BAE-146
PV3-075-9UK2	716958	Vickers	Variable Inline Piston Pump	BAE-146
PV3-075-9UK2A	716988	Vickers	Variable Inline Piston Pump	BAE-146
PV3-044-41A	731334	Vickers	Variable Inline Piston Pump	CL-600
MPEV3-056-9	731428	Vickers	Variable AC Motorpump	B727/B737
MPEV3-056-10	731430	Vickers	Variable AC Motorpump	B727/B737
PV3-044-38B	731515	Vickers	Variable Inline Piston Pump	CL-600
PV3-044-8A	731633	Vickers	Variable Inline Piston Pump	Bell 205/205A
MPEV3-011-25C	731840	Vickers	Variable AC Motorpump	DHC-8
<b>MPEV3-056-6H</b>	<b>731966</b>	<b>Vickers</b>	<b>Variable AC Motorpump</b>	<b>B747/B757/B767/B777</b>
PV3-160-4GB1	776932	Vickers	Variable Inline Piston Pump	BAC 1-11
<b>PV3-300-13C</b>	<b>848354</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>A330/A340</b>
PV3-019-1A	848846	Vickers	Variable Inline Piston Pump	Falcon 2000
<b>MPEV3-012-2B</b>	<b>848847</b>	<b>Vickers</b>	<b>Variable AC Motorpump</b>	<b>CL600-2B19, CRJ</b>
PF4-038-11D	848882	Vickers	Vane Fuel Pump	PW306
MPHV3-115-1	848907	Vickers	Variable Inline PTU	A320
MPEV3-011-25D	849557	Vickers	Variable AC Motorpump	DHC-8
<b>PV3-240-18</b>	<b>849589</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>B737NG</b>
MPEV3-032-2A	861195	Vickers	Variable AC Motorpump	Lockheed 382
<b>MPEV3-032-1G</b>	<b>861555</b>	<b>Vickers</b>	<b>Variable AC Motorpump</b>	<b>DC-10, MD11, A300, A310,</b>
MPEV3-032-1H	861686	Vickers	Variable AC Motorpump	A300, A310
PV3-115-EA5	862536	Vickers	Variable Inline Piston Pump	F-100
MPEV3-011-30	887030	Vickers	Variable AC Motorpump	F-100
PV3-032-9	887031	Vickers	Variable Inline Piston Pump	F-100

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
<b>PV3-044-48</b>	<b>887055</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>CL-600, CRJ</b>
<b>MF1-019-3A</b>	<b>887087</b>	<b>Vickers</b>	<b>Bent Axis Motors</b>	<b>757-200</b>
PV3-240-10A	887111	Vickers	Variable Inline Piston Pump	B747/767
<b>MPEV3-008-2C</b>	<b>887173</b>	<b>Vickers</b>	<b>Variable DC Motorpump</b>	<b>EMB120</b>
PF4-038-11C	887182	Vickers	Vane Fuel Pump	PW305
<b>MPEV3-056-7A</b>	<b>887477</b>	<b>Vickers</b>	<b>Variable AC Motorpump</b>	<b>B727/B737/B737NG</b>
MPEV3-056-10A	887478	Vickers	Variable AC Motorpump	B727/B737
MPEV3-056-9A	887479	Vickers	Variable AC Motorpump	B727/B737
<b>PV3-240-10C</b>	<b>887673</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>B747/757/767, L1011, MD11, MD-10, A320</b>
65WE09004	937980	Stratopower	Variable Check Valve Pump	
64WE20004	938052	Stratopower	Variable Piston Pump	
65WE01036-2	938090	Stratopower	Variable Check Valve Pump	
53WK16011	938097	Stratopower	Hydraulic Starter	
53FE010160	938797	Stratopower	Hydraulic Starter	
66WAN200-10	938822	Stratopower	Variable Check Valve Pump	
66WAP200-10	938823	Stratopower	Variable Check Valve Pump	
65WE01046	938951	Stratopower	Variable Check Valve Pump	
53WE05001	939202	Stratopower	Hydraulic Starter	
130WE00501	939548	Stratopower	Hydraulic Pump Package	
165WE0026	939603	Stratopower	AC Motorpump	
64WE01011-2	939685	Stratopower	Variable Piston Pump	
64WE07507	939734	Stratopower	Variable Piston Pump	
65WE00241	939758	Stratopower	Variable Check Valve Pump	
165FE00503	939788	Stratopower	AC Motorpump	
75FE01201	939822	Stratopower	Fixed Piston Motor	
64WE07501-1	939849	Stratopower	Variable Piston Pump	
64WE07507-1	939852	Stratopower	Variable Piston Pump	

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
165F300503-1	940070	Stratopower	AC Motorpump	
<b>165W01022</b>	<b>940732</b>	<b>Stratopower</b>	<b>AC Motorpump</b>	
66WA400	960403	Stratopower	Variable Check Valve Pump	
65W01008	960865	Stratopower	Variable Check Valve Pump	
66WAP200	960949	Stratopower	Variable Check Valve Pump	
165W01007-3	961284	Stratopower	AC Motorpump	
66WA200-2	961350	Stratopower	Variable Check Valve Pump	
165W01010-3	961357	Stratopower	AC Motorpump	
65W01025	961375	Stratopower	Variable Check Valve Pump	
165WE01003-1	961386	Stratopower	AC Motorpump	
66WBG300-4	961422	Stratopower	Variable Check Valve Pump	
66WBD300-4	961423	Stratopower	Variable Check Valve Pump	
66WAN200-1	961460	Stratopower	Variable Check Valve Pump	
66WAP200-1	961461	Stratopower	Variable Check Valve Pump	
66WU400-1	961464	Stratopower	Variable Check Valve Pump	
66WBQ200	961497	Stratopower	Variable Check Valve Pump	
66WBL200	961503	Stratopower	Variable Check Valve Pump	
65WE01004	961514	Stratopower	Variable Check Valve Pump	
53WK16005-1	961521	Stratopower	Hydraulic Starter	
65WE01035	961540	Stratopower	Variable Check Valve Pump	
65WE01031-1	961541	Stratopower	Variable Check Valve Pump	
53WK16008	961555	Stratopower	Hydraulic Starter	
65WE01036	961564	Stratopower	Variable Check Valve Pump	
67U100-1	961574	Stratopower	Variable Check Valve Pump	
65WE00527-1	961582	Stratopower	Variable Check Valve Pump	
64WE07501	961596	Stratopower	Variable Piston Pump	
65WE01030-3	961598	Stratopower	Variable Check Valve Pump	

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
53WK20002	961602	Stratopower	Hydraulic Starter	
53WK20002	961602	Stratopower	Hydraulic Starter	
65WE01042	961612	Stratopower	Variable Check Valve Pump	
165W01020	961627	Stratopower	AC Motorpump	
<b>MPEV3-008-6</b>	<b>971533</b>	<b>Vickers</b>	<b>Variable DC Motorpump</b>	<b>EMB135/145</b>
<b>MPHV3-115-1C</b>	<b>971600</b>	<b>Vickers</b>	<b>Variable Inline PTU</b>	<b>A320</b>
<b>PV3-032-11</b>	<b>971808</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>EMB-135/145</b>
<b>PV3-300-13E</b>	<b>971844</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>A330/A340</b>
<b>PV3-300-16C</b>	<b>972424</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>B777</b>
<b>PV3-300-13F</b>	<b>972630</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>A330/A340</b>
MPEV3-040-10B	972687	Vickers	Variable AC Motorpump	B777
<b>PV3-300-16D</b>	<b>972952</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>B777 &amp; B747-8F</b>
MPEV3-040-10C	973122	Vickers	Variable AC Motorpump	B777
<b>MF1-152-13</b>	<b>973600</b>	<b>Vickers</b>	<b>Bent Axis Motors</b>	<b>737-700</b>
<b>PV3-115-34F</b>	<b>973930</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>B777</b>
<b>MPHV3-115-1B</b>	<b>974014</b>	<b>Vickers</b>	<b>Variable Inline PTU</b>	<b>A320</b>
<b>MPEV3-032-15</b>	<b>974540</b>	<b>Vickers</b>	<b>Variable AC Motorpump</b>	<b>A320/330/340</b>
<b>PV3-300-13L</b>	<b>974800</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>A330/A340</b>
MPEV3-040-10D	997635	Vickers	Variable AC Motorpump	B777
PF4-038-11F	3029309-001	Vickers	Vane Fuel Pump	PW306
<b>PV3-240-2F</b>	<b>350880-6</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>DC-10, MD-11, A300, A310, B747, 757,767</b>
<b>PV3-240-2G</b>	<b>350880-7</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>L1011, A300, A310, B747, 757,767</b>
64WE07504	64WE07504	Stratopower	Variable Piston Pump	
65WE01019	65WE01019	Stratopower	Variable Check Valve Pump	
65WE01036-1	65WE01036-1	Stratopower	Variable Check Valve Pump	
	AS66411LS666	Vickers	Bent Axis Pump	DC9, MD80
MC14549-5	MC14549-5	MC Aerospace	Fixed Piston Pump	Cessna

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
SV3-150-6	420078	Vickers	Variable Inline Starter Motor	CH-47
PF4-038-17B	972716	Vickers	Vane Fuel Pump	Cessna Citation X
Rudder Isolation Valve	997305	Vickers	Hydraulic Valve	DASH-8
RMV3-011-1A	3029134-001	Vickers	Servo Control Motor	Hawker Horizon 4000
RMV3-011-1B	3029134-002	Vickers	Servo Control Motor	Hawker Horizon 4000
RMV3-011-1C	3029134-003	Vickers	Servo Control Motor	Hawker Horizon 4000
RMV3-011-1D	3029134-004	Vickers	Servo Control Motor	Hawker Horizon 4000
RMV3-011-2A	3029136-001	Vickers	Servo Control Motor	Hawker Horizon 4000
RMV3-011-2B	3029136-002	Vickers	Servo Control Motor	Hawker Horizon 4000
RMV3-011-2C	3029136-003	Vickers	Servo Control Motor	Hawker Horizon 4000
RMV3-011-2D	3029136-004	Vickers	Servo Control Motor	Hawker Horizon 4000
MPHF3-160-9	3029686-001	Vickers	Fixed Inline PTU	GV
MPEV3-012-4	3029807-001	Vickers	Variable AC Motorpump	
AS-66411-L-S666B	3029981-001	Vickers	Bent Axis Pump	DC9, MD80
RRP-640-1	3030218-001	Vickers	Reservoir	RAH-66
PV3-008-1A	3030244-001	Vickers	Variable Inline Piston Pump	SJ-30 Bizjet
PPEV3-011-15C	3030359-002	Vickers	Variable Inline Pump Package	Hawker Horizon 4000
PPEV3-011-15D	3030359-003	Vickers	Variable Inline Pump Package	Hawker Horizon 4000
MPHF1-037-5B	3030536-002	Vickers	Fixed Bent Axis PTU	Hawker Horizon 4000
RMV3-011-3A	3031031-001	Vickers	Servo Control Motor	Challenger 300
RMV3-011-3B	3031031-002	Vickers	Servo Control Motor	Challenger 300
RMV3-011-3C	3031031-003	Vickers	Servo Control Motor	Challenger 300
MF1-095-25	3031075-001	Vickers	Bent Axis Motors	
PPV3-045-1A	3031096-001	Vickers	Variable Inline Pump Package	S-92
PV3-056-3A	3031317-001	Vickers	Variable Inline Piston Pump	B609
PV3-300-31A	3031450-001	Vickers	Variable Inline Piston Pump	A380
PV3-300-31B	3031523-001	Vickers	Variable Inline Piston Pump	A380

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
PV3-300-31C	3031575-001	Vickers	Variable Inline Piston Pump	A380
PV3-300-31D	3031611-001	Vickers	Variable Inline Piston Pump	A380
PV3-300-31E	3031615-001	Vickers	Variable Inline Piston Pump	A380
PV3-011-24	3031629-001	Vickers	Variable Inline Piston Pump	
PV3-056-5A	3031642-001	Vickers	Variable Inline Piston Pump	Hawker Horizon 4000
PV3-300-31F	3031683-001	Vickers	Variable Inline Piston Pump	A380
MFPF3-005-6B	3031713-001	Vickers	Inline Piston Motor	B-609 Tiltrotor
PV3-300-31G	3031733-001	Vickers	Variable Inline Piston Pump	A380
MF2-019-8	3031737-001	Vickers	Bent Axis Motors	EC225 Super Puma
PV3-019-1B	3031749-001	Vickers	Variable Inline Piston Pump	Falcon 2000
<b>PV3-240-10D</b>	<b>3031863-001</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>A320, B747, B757 &amp; B767</b>
MS9-3911-30-S431	206040	Vickers	Bent Axis Motors	DC-8
PV3-022-8A	351285	Vickers	Variable Inline Piston Pump	DC-8
MF1-009-2B	357745	Vickers	Bent Axis Motors	
MF3-044-4A	373364	Vickers	Inline Piston Motor	
MF3-044-2A	381923	Vickers	Inline Piston Motor	L1011
MPHF1-152-2A	382927	Vickers	Fixed Bent Axis PTU	L1011
MF3-044-2B	385840	Vickers	Inline Piston Motor	L1011
<b>CMV3-075-1C</b>	<b>390017</b>	<b>Vickers</b>	<b>Servo Control Motor</b>	<b>DC-10, MD11</b>
PF4-057-6A	406138	Vickers	Vane Fuel Pump	TPE 331
PF4-057-6B	414199	Vickers	Vane Fuel Pump	TPE-331
PF4-057-6C	428337	Vickers	Vane Fuel Pump	TPE-331
PF4-057-6D	429969	Vickers	Vane Fuel Pump	TPE-331
MPEV3-008-8UK2B	453665	Vickers	Variable DC Motorpump	
HR6B9-002-EA2	453740	Vickers	Brake Metering Valve	
PV3-032-EA1A	454108	Vickers	Variable Inline Piston Pump	
PPEV3-008-EA2A	454481	Vickers	Variable Inline Pump Package	P-180

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
PPEV3-008-1A	518450	Vickers	Variable Inline Pump Package	STARTSHIP I, MODEL 2000
PV3-115-EA1C	520550	Vickers	Variable Inline Piston Pump	A320
CMV3-022-EA3	520567	Vickers	Servo Control Motor	A320
MPHF1-037-EA1A	520696	Vickers	Fixed Bent Axis PTU	BAE-146
MF3-032-EA3C	520805	Vickers	Inline Piston Motor	
MPEV3-032-EA1	520831	Vickers	Variable AC Motorpump	BAE-146
PV3-115-EA3C	521449	Vickers	Variable Inline Piston Pump	BAE-146
PV3-022-28	569105	Vickers	Variable Inline Piston Pump	Bell 214
PPEV3-011-12A	570500	Vickers	Variable Inline Pump Package	Beech 1900
PPEV3-011-13	571641	Vickers	Variable Inline Pump Package	Beech 1900
EA-1010-119	603265	Vickers	Bent Axis ACMP	
EA-50182-7	610353	Vickers	Bent Axis ACMP	
EA-50182-8	612457	Vickers	Bent Axis ACMP	
<b>MPEV3-056-6D</b>	<b>622199</b>	<b>Vickers</b>	<b>Variable AC Motorpump</b>	<b>B747/B757/B767</b>
PPEV3-011-12B	624494	Vickers	Variable Inline Pump Package	Beech 1900
PPEV3-011-13A	624499	Vickers	Variable Inline Pump Package	Beech 200/300
MPEV3-022-14F	693980	Vickers	Variable AC Motorpump	L1011
HR6B9-002-GB3	715418	Vickers	Brake Metering Valve	
HR6B9-310-GB1A	715439	Vickers	Brake Metering Valve	
HR6B9-002-GB1A	715445	Vickers	Brake Metering Valve	
PV3-075-9UK1A	717091	Vickers	Variable Inline Piston Pump	BAE-146
PV3-115-EA1D	933260	Vickers	Variable Inline Piston Pump	A320
PPEV3-011-13C	971518	Vickers	Variable Inline Pump Package	Beech 200/300
PPEV3-011-12D	971652	Vickers	Variable Inline Pump Package	Beech 1900
<b>PV3-115-34E</b>	<b>971910</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>B777</b>
Reservoir Level Switch	974641	Vickers	Electrical Switch	DASH-8
<b>PV3-300-EA2</b>	<b>3022053-000</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>A330/340</b>

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
MK 8	501-1-13775-008	FR-HiTEMP	Motor, Starter	146/RJ
TYPE 3616	501-1-14561-003	FR-HiTEMP	Motor, Starter	A320
TYPE C3616	501-1-14561-004	FR-HiTEMP	Motor, Starter	A320 (4952164)
	0725145	FR-HiTEMP	ELEMENT ASSEMBLY	A318, A319, A320, A321
	0725185	FR-HiTEMP	REFUEL COUPLING ASSY	A320, A340
	0727540	FR-HiTEMP	FLUSH COVER AND CABLE	A319, A321
	103BA09	FR-HiTEMP	3/8" SP AERO VALVE	Bae 146
	110DB28	FR-HiTEMP	1 1/4" SP AERO VALVE	F28
	110M21	FR-HiTEMP	1 1/4" MOTORIZED VALVE	F28
	114DA30	FR-HiTEMP	1 3/4" SP AERO VALVE	F100
HR6B9-002- EA5A	3022016-000	Vickers	Park Brake Relief Valve	A320
	3508802-10	FR-HiTEMP	LOWER ASSEMBLY	A319, A320
	3508802-24	FR-HiTEMP	LOWER ASSEMBLY	A319, A320
	3508802-28	FR-HiTEMP	LOWER ASSEMBLY	A319, A320
	3508802-29	FR-HiTEMP	LOWER ASSEMBLY	A319, A320
	3508802-30	FR-HiTEMP	OUTER ASSEMBLY	F70, F100
	3508802-32	FR-HiTEMP	OUTER ASSEMBLY	F70, F100
	3508802-35	FR-HiTEMP	OUTER ASSEMBLY	A319, A320, A321
	3508802-36	FR-HiTEMP	OUTER ASSEMBLY	A319, A320, A321
	3508802-37	FR-HiTEMP	OUTER ASSEMBLY (SEE FRH050004)	A319, A320, A321
	3508802-38	FR-HiTEMP	OUTER ASSEMBLY	A319, A320, A321
	3508802-39	FR-HiTEMP	OUTER ASSEMBLY	A319, A320
	3508802-40	FR-HiTEMP	UPPER ASSEMBLY	A319, A320
	3508803-493	FR-HiTEMP	UPPER ASSEMBLY	F70, F100
	3514100-262	FR-HiTEMP	FLOAT SWITCH MK14	BAe 125
	3515000-103	FR-HiTEMP	FLOAT SWITCH SERIES 103.	BAe 125
	3515000-105	FR-HiTEMP	GA MK15-105 FLOAT SWITCH	BAe 125

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
	3515000-106	FR-HiTEMP	GA MK15-106 FLOAT SWITCH	BAe 125
	3515000-107	FR-HiTEMP	GA MK15-107 FLOAT SWITCH	BAe 125
	3515000-135	FR-HiTEMP	GA MK15-107 FLOAT SWITCH	F50, F70, F100
	3515000-149	FR-HiTEMP	GA MK15-149 FLOAT SWITCH	BAe 125
	3515000-164	FR-HiTEMP	GA MK15-164 FLOAT SWITCH	BAe 125
	3515000-165	FR-HiTEMP	GA MK15-165 FLOAT SWITCH	BAe 125
	3515000-171	FR-HiTEMP	FLOAT SW.ASSY,MK15 SERIES171.	BAe 125
	3515000-238	FR-HiTEMP	MK15-238 FLOAT SWITCH	CASA 212
	3515000-240	FR-HiTEMP	MK15-240 FLOAT SWITCH	BAe 146
	3515000-241	FR-HiTEMP	GA MK15-241 FLOAT SWITCH	BAe 146
	3515000-268	FR-HiTEMP	GA MK15-268 FLOAT SWITCH	BAe 125
	3515000-269	FR-HiTEMP	MK15-269 FLOAT SWITCH	BAe 125
	3515000-270	FR-HiTEMP	GA MK15-270 FLOAT SWITCH	BAe 125
	3515000-76	FR-HiTEMP	GA MK15-76 FLOAT SWITCH	BAe 125
	3530000-1	FR-HiTEMP	GA OF LEVEL SENSOR	A319, A320, A321, A330, A340
	3530000-3	FR-HiTEMP	GA OF LEVEL SENSOR	A330, A340
	3540000-1	FR-HiTEMP	TEMPERATURE SENSOR	A319, A320, A321
	3540000-3	FR-HiTEMP	TEMPERATURE SENSOR	A330, A340
	3540000-4	FR-HiTEMP	DUAL TEMPERATURE SENSOR	A330, A340
	3706270	FR-HiTEMP	SOLENOID VALVE ASSY	BAe 146, JS61
	3802045	FR-HiTEMP	SOLENOID VALVE ASSEMBLY	A320
	3901035	FR-HiTEMP	Part Not Recognised UK	F27, F28
	3901395	FR-HiTEMP	JET PUMP ASSEMBLY	A319, A320
	3901515	FR-HiTEMP	JET PUMP ASSY	A321
	708CA29	FR-HiTEMP	1" VENT VALVE	F28, F70, F100
	7903231D	FR-HiTEMP	1/2" MOTD. MAN O/RIDE SP.VALVE	BAe 125
	7907015E	FR-HiTEMP	5/8 3/8 BSP HP VALVE	BAe 125

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
	7913001F	FR-HiTEMP	3/4" MAN.VALVE	SD330, SD360
	7913003K	FR-HiTEMP	1.50" DIAMETER SP VALVE	BAe 125, BAe 146
	7923061M	FR-HiTEMP	1.25" MOTORISED SP/NR VALVE	F50, F70, F100
	7923227F	FR-HiTEMP	MOT VALVE	CASA 235
	7923245M	FR-HiTEMP	2" DIAMETER MOTORISED SP VALVE	
	7923267J	FR-HiTEMP	1.25" MOTORISED SP/NR VALVE	F50, F70, F100
	7923268L	FR-HiTEMP	1.75" DIAMETER SP VALVE	F28, F70, F100
	7940005H	FR-HiTEMP	1" S.S SP WATER VALVE	BAe 146
	7940023F	FR-HiTEMP	3/4" DIA. S.P. AERO. VALVE	BAe 146
	7940052D	FR-HiTEMP	1/2" DIA. SHUT OFF VALVE	JS31
	7940066F	FR-HiTEMP	3/4" DIA. SP. VALVE	BAe 146
	7945017F	FR-HiTEMP	S.P. WATER VALVE	A300, A310
	7945217F	FR-HiTEMP	MOTORISED SP. VALVE	A300, A310
	8000320C	FR-HiTEMP	3/8" MOT. SHUT-OFF VALVE	JS41
	8000322F	FR-HiTEMP	3/4"DIA. MOT L.P. SHUT OFF VALVE	JS41
	8084036H	FR-HiTEMP	DRAIN VALVE	A300
	8084040H	FR-HiTEMP	4 WAY SP VALVE	A300, A310
	8084044H	FR-HiTEMP	DRAIN VALVE	A320
	8084240H	FR-HiTEMP	S P VALVE	A300, A310
	8903000-5	FR-HiTEMP	FILTER/BYPASS NRV VALVE	F70, F100
	9201000-226	FR-HiTEMP	CONTENTS TRANSMITTER	BAe 146
	9201000-238	FR-HiTEMP	238 CONTENTS TRANSMITTER	
	9201000-245	FR-HiTEMP	CONTENTS TRANSMITTER	BAe 125
	9201000-263	FR-HiTEMP	GA SER's 263 CONTENTS Tx	JS61
	9201000-265	FR-HiTEMP	CONTENTS TRANSMITTER	F100
	9201000-272	FR-HiTEMP	CONTENTS TRANSMITTER	F100
	9201000-78	FR-HiTEMP	CONTENTS TRANSMITTER.	F28, F70, F100

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
	9201000-79	FR-HiTEMP	CONTENTS TRANSMITTER.	F28, F70, F100
	9201000-95	FR-HiTEMP	CONTENTS TRANSMITTER	BAe 125
	9300213	FR-HiTEMP	1" & 1.625" DIA. MOT SP VALVE	F28, F50
	9350022	FR-HiTEMP	WATER DRAIN VALVE	A300, A310, A320, F50, F70, F100
	9350024	FR-HiTEMP	DRAIN VALVE	A300, A310, A320, F100
	9406021	FR-HiTEMP	GA FLAT ACTUATOR	
	9406038	FR-HiTEMP	FLAT ACTUATOR (0 DEGREE 90 DEGRE	A300, A310
	9409019	FR-HiTEMP	GA FLAT ACTUATOR	JS41
	9409122	FR-HiTEMP	FLAT ACTUATOR WITH OVERRIDE	F70, F100
	9409124	FR-HiTEMP	FLAT ACTUATOR	JS41
	9507445	FR-HiTEMP	VENT FLOAT VALVE	F70, F100
	9508175	FR-HiTEMP	VENT VALVE	A319, A320, A321, A330, A340
	9811505	FR-HiTEMP	3/8" DIA. N.R.V. 75 PSI	CASA 212
	9811705	FR-HiTEMP	AUTOMATIC PURGE VALVE ASSEMBLY	SD360
	9811795	FR-HiTEMP	N R VALVE	A300, A319, A321
	9811820	FR-HiTEMP	CHECK VALVE	A319, A320, A321, A340
	9811839	FR-HiTEMP	0.50" NON RETURN VALVE	A319, A320, A321
	9813215	FR-HiTEMP	WATER TANK VENT SHUTTLE VALVE	A300, A310
	9813395	FR-HiTEMP	AIR RELEASE VALVE	A319, A320, A321
	9813445	FR-HiTEMP	REL/VALVE REPLACED BY FRH280002	A330, A340
	9815900	FR-HiTEMP	1" INWARD/OUTWARD VENT VALVE	F70, F100
	9840044H	FR-HiTEMP	NRV VALVE	F28, F100
	9840094H	FR-HiTEMP	NRV VALVE	A300, A310
	9841019F	FR-HiTEMP	VALVE, NON RETURN	SD330, SD360
	9841022F	FR-HiTEMP	TWIN NON-RETURN VALVE	SD360
	9843043H	FR-HiTEMP	G.A. 1.0" DIAMETER FLAP N.R.V.	BAe 146

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
	9870019B	FR-HiTEMP	RELIEF UNIT	BAe 125
	FRH010041	FR-HiTEMP	ACTUATOR	
	FRH021001	FR-HiTEMP	SOLENOID ASSEMBLY	
	FRH050001-1	FR-HiTEMP	MFLI OUTER, UPPER	A319
	FRH050002	FR-HiTEMP	M.F.L.I. OUTER UNIT 1.	A319
	FRH050003	FR-HiTEMP	MFLI OUTER UNIT 2	A319
	FRH050004	FR-HiTEMP	MFLI OUTER UNIT 3.	A319
	FRH050005	FR-HiTEMP	MFLI OUTER UNIT 4	A319
	FRH050006	FR-HiTEMP	M.F.L.I. OUTER UNIT 5.	A319
	FRH050007	FR-HiTEMP	MFLI OUTER UNIT 7	A321
	FRH070001	FR-HiTEMP	GA OF CONTENTENTS TRANSMITTER	
	FRH10002A	FR-HiTEMP	PRESSURE SWITCH	A300-600
	FRH100013A	FR-HiTEMP	PRESSURE SWITCH	A319, A320, A321, A330, A340
	FRH100014A	FR-HiTEMP	PRESSURE SWITCH	A319, A320, A321
	FRH100028A	FR-HiTEMP	PRESSURE SWITCH	A340
	FRH130004H	FR-HiTEMP	1" DIAMETER MOT. S.P. VALVE	B767
	FRH160006M	FR-HiTEMP	2" ACT. BUTTERFLY VALVE	
	FRH220015V	FR-HiTEMP	NON-RETURN VALVE (REPLACED BY FRH220034V)	
	FRH220017V	FR-HiTEMP	4" DOUBLE FLAP NRV (REPLACED BY FRH220033V) (REPLACED BY FRH220033V)	AIRBUS
	FRH220033V	FR-HiTEMP	NON RETURN VALVE	
	FRH220034V	FR-HiTEMP	NON RETURN VALVE	A320
	FRH230003C	FR-HiTEMP	VALVE,PRESSURE REDUCING &RELIEFRELIEF	AIRBUS
	FRH241001	FR-HiTEMP	VALVE, SOLENOID	
	FRH280002	FR-HiTEMP	AIR RELEASE VALVE	A319, A320, A321, A330, A340
	FRH340002B	FR-HiTEMP	WASTE WATER DRAIN VALVE	A330, A340
	FRH340003H	FR-HiTEMP	WASTE WATER DRAIN VALVE	A321

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
	FRH340014E	FR-HiTEMP	VALVE, TOILET FLUSHING	
	FRH530014D	FR-HiTEMP	VALVE , DOOR BYPASS	A330, A340
	HTE190001-1	FR-HiTEMP	TWIN MOTOR ACTUATOR	A319, A320, A321
	HTE190001-2	FR-HiTEMP	ACTUATOR ASSEMBLY	A319, A320, A321
	HTE190026	FR-HiTEMP	ACTUATOR VALVE FUEL	A330, A340
	HTE1984-1	FR-HiTEMP	ASSY MANUAL FUEL VALVE HTE	BAe 125
	HTE200002	FR-HiTEMP	ASSY ACTUATOR	A300, A310, A319, A321
	HTE200002-1	FR-HiTEMP	90 DEG ACTUATOR	A319, A320, A321
	HTE200016	FR-HiTEMP	ASSY ACTUATOR	
	HTE200024	FR-HiTEMP	ASSY ACTUATOR	JS31
	HTE200032	FR-HiTEMP	ASSY ACTUATOR	JS41
	HTE200066	FR-HiTEMP	90 DEG ACTUATOR	A321
	HTE210014	FR-HiTEMP	ACTUATOR	BAe 146
	HTE250035-1	FR-HiTEMP	BALL VALVE	BAe 125
	HTE250072	FR-HiTEMP	2.0 ACTUATED BUTTERFLY VALVE	BAe 146
	HTE250072-001	FR-HiTEMP	ASSY BUTTERFLY VALVE HTE	BAe 146
	HTE250072-1	FR-HiTEMP	2" ACT BUTTERFLY PLATE	BAe 146
	HTE250076-1	FR-HiTEMP	2 1/2" DIA MOT. BUTTERFLYVALVE	BAe 146
	HTE250088	FR-HiTEMP	ASSY 2" ACT B/FLY VALVE HTE	BAe 125
	HTE250113-1	FR-HiTEMP	ISOLATION VALVE HTE	A310
	HTE250113-2	FR-HiTEMP	ISOLATION VALVE	A300, A310
	HTE250138-1	FR-HiTEMP	63MM AIR SHUT OFF VALVE	Toilet System
	HTE310021	FR-HiTEMP	ASSY REFUL GALL AIR INLET VAL	A319, A321
	HTE310021-1	FR-HiTEMP	ASSY FUEL GALRY AIR INLET VAL	A319, A320
	HTE310028	FR-HiTEMP	FUEL DRAIN VALVE	A300, A310, A319, A320, A321
	HTE330114	FR-HiTEMP	4.875" GIMBAL JOINT	A319, A320, A321, A330, A340
	HTE365-4	FR-HiTEMP	3"DOUBLE FLAP NRV HTE	BAe 146

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
	HTE370001	FR-HiTEMP	ASSY H.P. GROUND CONNECTOR NR	A319, A320, A321, A330, A340
	HTE400064	FR-HiTEMP	'T' + N.R.V.	JS31
	HTE400071	FR-HiTEMP	ICE PROTECTION SYSTEM N.R.V	JS31
	HTE400115	FR-HiTEMP	VALVE CHECK	A330, A340
	HTE400130	FR-HiTEMP	ASSY VENT MANIFOLD	JS41
	HTE400200	FR-HiTEMP	IN-LINE PNEUMATIC N.R.V	BAe 146
	HTE4168	FR-HiTEMP	ASSY 63MM DOUBLE FLAP N.R.V.	BAe 125
	HTE420043	FR-HiTEMP	SYSTEM RETURN P.R.V.	BAe 146
	HTE420044	FR-HiTEMP	SYSTEM RETURN P.R.V THE	A319, A320
	HTE420079	FR-HiTEMP	RELIEF VALVE	BAe 146
	HTE4344-1	FR-HiTEMP	ASSY 3/8" NRV	BAe 146
	HTE4345-2	FR-HiTEMP	ASSY NON-RETURN VALVE	BAe 146
	HTE4350	FR-HiTEMP	ASSY 1/4IN SINGLE FLAP N.R.V.	BAe 125
	HTE4373-1	FR-HiTEMP	ASSY 2 1/2 DOUBLE FLAP NRV	BAe 146
	HTE4373-2	FR-HiTEMP	2.1/2" DOUBLE FLAP VALVE	BAe 146
	HTE440007	FR-HiTEMP	4" DOUBLE FLAP NON-RETURN VALVE	F70, F100
	HTE4405	FR-HiTEMP	G/ASSY 1" DOUBLE FLAP NRV	BAe 125
	HTE4418	FR-HiTEMP	ASSY 3-1/2 NRV	F70, F100
	HTE450001-9	FR-HiTEMP	ASSEMBLY NON RETURN VALVE	RB211
	HTE460009	FR-HiTEMP	ASSY 4" NRV	A319, A320, A321
	HTE460009-001	FR-HiTEMP	ASSY 4" NRV	A319, A320, A321
	HTE460009-009	FR-HiTEMP	ASSY 4" NRV (NEW STD IS FRH220033V)	A319, A320, A321
	HTE460009-1	FR-HiTEMP	ASSY 4IN N.R.V. (NEW STD IS FRH220034V)	A319, A320, A321
	HTE4853	FR-HiTEMP	ASSY SINGLE FLAP N.R.V. 1/4IN	BAe 125
	HTE4853	FR-HiTEMP	SINGLE FLAP NON RETURN VALVE	BAe 125
	HTE490005	FR-HiTEMP	ASSY LINE NON-RETURN VALVE	A310, A321, A340

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
	HTE510005	FR-HiTEMP	PRESS REDUCING & RELIEF VALVE	A319, A320, A321
	HTE510005-1	FR-HiTEMP	PRESS REDUCING & RELIEF VALVE (DO NOT RE-ORDER)	A319, A320, A321
	HTE510010	FR-HiTEMP	ASSY PRESSURE REDUCING VALVE	A300
	HTE510010-1	FR-HiTEMP	PRESS REDUCING & RELIEF VALVE	A300, A310
	HTE510016	FR-HiTEMP	GAS CHARGING/BLEED VALVE	A319, A320, A321, A330, A340
	HTE510035-1	FR-HiTEMP	PRESSURE REGULATING VALVE	BAe 146
	HTE510035-2	FR-HiTEMP	PRESSURE REGULATING VALVE	BAe 146
	HTE530004	FR-HiTEMP	SUPERSEDED BY 530004-1	BAe 146
	HTE530004-1	FR-HiTEMP	TOILET FLUSHING VALVE ASSY	BAe 146, JS61
	HTE540-2A	FR-HiTEMP	ASSY 1/4IN NON RETURN VALVE	SD330, SD360
	HTE620071-1	FR-HiTEMP	1" SLIDING UNION	A330, A340
	HTE6303	FR-HiTEMP	FREIGHT DOOR SWIVEL	A310
	HTE660020	FR-HiTEMP	ASSY 1 1/2" COMPENSATED SLIDEHTE	A319, A320, A321
	HTE69000	FR-HiTEMP	PRESSURE SWITCH HTE	A300, A310
	HTE69000-1	FR-HiTEMP	PRESSURE SWITCH	A300, A310, A319, A320, A321, A330, 340
	HTE690011	FR-HiTEMP	PRESSURE SWITCH HTE	BAe 125
	HTE690012	FR-HiTEMP	PRESSURE SWITCH HTE	BAe 125
	HTE690014-1	FR-HiTEMP	PRESSURE SWITCH HTE	BAe 125
	HTE690035-1	FR-HiTEMP	PRESSURE SWITCH ASSEMBLY HTE	A319, A320, A321
	HTE690041	FR-HiTEMP	PRESSURE SWITCH ASSEMBLY HTE	BAe 146
	HTE690042	FR-HiTEMP	PRESSURE SWITCH ASSEMBLY HTE	BAe 146
	HTE690046	FR-HiTEMP	PRESSURE SWITCH ASSEMBLY HTE	BAe 146
	HTE690047	FR-HiTEMP	PRESSURE SWITCH HTE	A319, A320, A321, A330, A340
	HTE690070-001	FR-HiTEMP	PRESSURE SWITCH HTE	
	HTE690097	FR-HiTEMP	PRESSURE SWITCH HTE	BAe 125

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
	HTE690112	FR-HiTEMP	PRESSURE SWITCH ASSY HTE	A320
	HTE711-62C	FR-HiTEMP	MINILOCK SOCKET ASSY- 3/8IN HTE	SD360
	HTE860028	FR-HiTEMP	ACT OUTLET DUCT FLAP HTE	JS31
	HTE880012-003	FR-HiTEMP	VALVE S/ASSY HTE	BAe 125
	HTE880012-005	FR-HiTEMP	VALVE S/ASSY HTE	BAe 125
	HTE880012-007	FR-HiTEMP	VALVE S/ASSY HTE	BAe 125
	HTE8815	FR-HiTEMP	SEAT DIAPHRAGM	BAe 125
	HTE900033	FR-HiTEMP	ASSY VALVE HTE	A310, A321, A340
	HTE900087-001	FR-HiTEMP	VALVE ASSEMBLY HTE	A319, A320
	HTE900092	FR-HiTEMP	ASSY HYD.SHUT OFF VALVE L/H HTE	JS31
	HTE900095	FR-HiTEMP	S/ASSY DRIVE SPINDLE HTE	A319, A320
	HTE900096	FR-HiTEMP	S/ASSY DRIVE SPINDLE HTE	A319, A320
	HTE900100	FR-HiTEMP	ASSY HYD.SHUT OFF VALVE R/HHTE.(SUPERSEDED BY 900100-1)	JS31
	HTE900100-1	FR-HiTEMP	ASSY HYD.SHUT OFF VALVE R/HHTE.(SUPERSEDED BY 900100-1)	JS31
	HTE900118	FR-HiTEMP	1 1/2" L.P VALVE ASSY HTE	A319, A320, A321
	HTE900118-001	FR-HiTEMP	1 1/2" L.P VALVE ASSY HTE	A319, A320, A321
	HTE900130-1	FR-HiTEMP	MOTORISED FIRE S/O VALVE.HTE	BAe 125
	HTE900133	FR-HiTEMP	ASSY 1 1/2" BALL VALVE HTE	A319, A320, A321
	HTE900135	FR-HiTEMP	ASSY 1 1/2" BALL VALVE HTE	A319, A320, A321
	HTE900162	FR-HiTEMP	FUEL VALVE - CROSSFEED	A330
	HTE900169	FR-HiTEMP	FUEL VALVE JETTISON ASSY	A340
	HTE900169-001	FR-HiTEMP	VALVE S/ASSY HTE	A340
	HTE900189	FR-HiTEMP	ASSY 25MM FUEL VALVE HTE	A321
	HTE900212	FR-HiTEMP	VALVE-FUEL-L.P. ASSY HTE	A330, A340
	HTE9037	FR-HiTEMP	ASSY ACTUATOR HTE	SD360

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
	HTE9044-001	FR-HiTEMP	ASSY ACTUATOR	BAe 146
	HTE9082-1	FR-HiTEMP	ASSY ACTUATOR	BAe 146
	HTE9084	FR-HiTEMP	ASSY ACTUATOR	BAe 146
	HTE9178	FR-HiTEMP	ASSY 2IN BUTTERFLY VALVE ACT.HTE	BAe 125
	HTE9196	FR-HiTEMP	STOP PLATE	
	HTE920007	FR-HiTEMP	ASSY ACT.AIR VALVE HTE	A300, A310, A321, A340
	HTE920010	FR-HiTEMP	ACTUATED HOT AIR BALL VALVE HTE	CASA 212
	HTE920018	FR-HiTEMP	BALL VALVE HTE	MBB HELICOPTER
	HTE920036	FR-HiTEMP	ACTUATED HOT AIR BALL VALVE HTE	MBB HELICOPTER
	HTE920042	FR-HiTEMP	16MM HOT AIR ACT.BALL VALVE HTE	
	HTE9215	FR-HiTEMP	ASSY ACT'D. BUTTERFLY VALVE HTE	SD360
	HTE9215-001	FR-HiTEMP	ASSY 1-1/2" BUTTERFLY VALVE HTE	SD360
	HTE940008	FR-HiTEMP	ASSY MANUAL BALL VALVE 1/4IN HTE	BAe 125
	HTE9401037	FR-HiTEMP	LIGHT WT. MOTOR UNIT	F50, F100
	HTE9406012	FR-HiTEMP	FLAT ACTUATOR 0-90 DEGREES	A300, A310
	HTE9464	FR-HiTEMP	ASSY BALL VALVE 1/2IN ACTHTE	SD330, SD360
	HTE9479-3	FR-HiTEMP	ACTUATED BALL VALVE HTE	BAe 146
	HTE9482	FR-HiTEMP	ASSY 14MM ACT BALL VALVE HTE	MBB HELICOPTER
	HTE9490-4	FR-HiTEMP	LANDING GEAR SELECTOR VALVE HTE	BAe 146
	HTE9526	FR-HiTEMP	ASSY RELIEF VALVE HTE	BAe 146
	HTE9531-101	FR-HiTEMP	ASSY BALL VALVE HTE	BAe 146
	HTE9531-3	FR-HiTEMP	HYDRAULIC PUMP ISOLATION VALVHTE	BAe 146
	HTE9596-001	FR-HiTEMP	ASSY 3 PORT FUEL VALVE HTE	BAe 125
	HTE9596-1	FR-HiTEMP	ASSY 3 PORT FUEL VALVE HTE	BAe 125
	HTE9635-3	FR-HiTEMP	ASSY ACTUATED 3/8" BALL VALVEHTE	BAe 146

**EATON AEROSPACE, LLC**  
**REPAIR STATION – COMPONENT CAPABILITIES LIST**  
**FAA APPROVED REPAIR STATION NUMBER EF4R152M**  
(Additions indicated with bold type on the last page)

<b>MODEL</b>	<b>P/N</b>	<b>MFG</b>	<b>DESCRIPTION</b>	<b>AIRCRAFT</b>
	HTE9681	FR-HiTEMP	ASSY SELECTOR VALVE HTE	BAe 146
	HTE9681-1	FR-HiTEMP	ASSY SELECTOR VALVE HTE	BAe 146
	HTE9683	FR-HiTEMP	ASSY SELECTOR VALVE HTE	BAe 146
	HTE9783-1	FR-HiTEMP	ASSY PRESSURE RELIEF VALVE HTE VALVE HTE	BAe 146
	HTE980065	FR-HiTEMP	STICK PUSH CONTROL VALVE	BAe 146
	HTE9921	FR-HiTEMP	ASSY SOLENOID SHUT OFF VALVE HTE	SD330, SD360
	SFR92015-1	FR-HiTEMP	CONTENTS TRANSMITTER	SAAB 2000
	SFR92016	FR-HiTEMP	CONTENTS TRANSMITTER	
	FRH340021H	FR-HiTEMP	WATER DRAIN VALVE	
	HTE711-Series	FR-HiTEMP	MINILOCK SOCKET ASSY- 3/8IN HTE	Multiple
	1608565	FR-HiTEMP	OVERFLOW VALVE	A319/320/321, F100
	9508175	FR-HiTEMP	VENT VALVE	A319/320/321, A300
	9507445	FR-HiTEMP	VENT FLOAT VALVE	F100
	1159000-1	FR-HiTEMP	PRESSURE CONTROL VALVE	BAe 125, BAe 146
MK 57	1157060	FR-HiTEMP	MK 57 VALVE ELEMENT ASSY	A300/310/319/320/321/330/340
	1158000-21	FR-HiTEMP	ELEMENT ASSEMBLY	A319/320/321
MK 54	1154035	FR-HiTEMP	DEFUEL VALVE (MK54 REFUEL)	SD 330/360
	1158000-15	FR-HiTEMP	CANISTER & CHECK VALVE ASSY	A319/320/321
MK 2	568-1-27171-002	FR-HiTEMP	MOUNTING PLATE,TYPE:8414,Mk2	AIRBUS
	1157020	FR-HiTEMP	MK57 CANNISTER ASSEMBLY	A300/319/320/321
MK 1	568-1-25663-001	FR-HiTEMP	PUMP,TYPE:7814,Mk.1	BAe 146
MK 2	568-1-27863-002	FR-HiTEMP	PUMP,REFUELING,TYPE:8712,Mk2	Unknown(0)
MK 2	568-1-29117-002	FR-HiTEMP	PUMP,TYPE:9108,Mk2	Boeing 777
MK 57	568-1-27202-005	FR-HiTEMP	PUMP,FUEL,TYPE:8410,Mk5	A319/320/321/330/340
MK 2	568-1-27202-002	FR-HiTEMP	PUMP,FUEL,TYPE:8410,Mk2	A319/320/321, B737
	568-1-30522-001	FR-HiTEMP	GA OF O/J PUMP TYPE 20002	Boeing 747

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
MK 2	568-1-27170-002	FR-HiTEMP	PUMP,FUEL TRANSFER, TYPE:8413,Mk2	A319/320/321/330/340
MK 4	568-1-28300-004	FR-HiTEMP	BOOST PUMP,TYPE:8810,Mk4	A319/320/321/330/340
MK 2	568-1-28300-002	FR-HiTEMP	BOOST PUMP,TYPE:8810,Mk2	A319/320/321/330/340
MK 5	568-1-26713-005	FR-HiTEMP	PUMP,FUEL,TYPE:8240,Mk5	Boeing 737
MK 4	568-1-26713-004	FR-HiTEMP	PUMP,FUEL,TYPE:8240,Mk4	Boeing 737
MK 2	568-1-27967-002	FR-HiTEMP	PUMP TYPE 8801 Mk2 G.A.	C17
MK 1	568-1-30685-001	FR-HiTEMP	GA BOOST PUMP 20004 MK 1	Boeing 747
MK 4	568-1-29115-004	FR-HiTEMP	PUMP,BOOST,TYPE:9106,Mk4	Boeing 777
MK 2	568-1-29115-002	FR-HiTEMP	PUMP,BOOST,TYPE:9106,Mk2	Boeing 777
	568-1-29684-001	FR-HiTEMP	MOUNTING PLATE,TYPE:9209	A319/320/321
	568-1-29447-000	FR-HiTEMP	OUTLET FLAP VALVE ASSY	Boeing 777
MK 2	568-1-29116-002	FR-HiTEMP	CANISTER,TYPE:9107,Mk2	Boeing 777
MK 1	568-1-29116-001	FR-HiTEMP	CANISTER,TYPE:9107,Mk1	Boeing 777
MK 3	568-1-28301-003	FR-HiTEMP	CANISTER,TYPE:8811,Mk3	A319/320/321
	568-1-27761-000	FR-HiTEMP	OUTLET VALVE ASSY	A319/320/321
MK 2	568-1-27244-002	FR-HiTEMP	CANISTER,TYPE:8411,MK2, CONFIG.2	A319/320/321
MK 2	568-1-27203-002	FR-HiTEMP	CANISTER,TYPE:8411,MK2, CONFIG.1	A319/320/321
	457-825	FR-HiTEMP	SHAW CAP	A319/320/321
	568-1-27202-05R	FR-HiTEMP	568-1-272202-005	A319/320/321
	D31005	FR-HiTEMP	HANDRAIL ASSY	Jetstream
	6020207	FR-HiTEMP	HANDRAIL ASSEMBLY	Jetstream, BAe 146
	6020205	FR-HiTEMP	HANDRAIL ASSEMBLY	BAe 146
	B31010	FR-HiTEMP	GAS SPRING STRUT ASSY	Jetstream
	B31009	FR-HiTEMP	GAS SPRING STRUT ASSY	Jetstream, A319/320/321, BAe 146
	568-1-30073-001	FR-HiTEMP	CANISTER	
Pump Upgrade PV3-240-10C	887673DER001	Eaton	Variable Inline Piston Pump	B747/757/767, L1011, MD11, MD-10, A320

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
Adapter repair	624022R	Eaton	Adapter	B747/757/767, L1011, MD11, MD-10, A320
Pump Upgrade PV3-044-48	887055DER003	Eaton	Variable Inline Piston Pump	CRJ 100/200
MPEV3-012-5	3030288-001	Eaton	AC Motorpump Assembly	Sikorsky (S-92A)
PPV3-045-1A	3031096-001	Eaton	Hydraulic Pump Package	Sikorsky (S-92A)
PV3-090-1	973748	Eaton	Hydraulic Pump Assembly	Sikorsky (S-92A)
MF1-019-7	848537	Eaton	Hydraulic Motor	F100 and F70
MK4	1604270	FR-HiTEMP	Pressure Relief Valve	
65WE00201-1	DS-960914	Stratopower	Variable Check Valve Pump	
MF1-009-12	416570	Eaton	Hydraulic Motor Assembly	Rescue Hoist
MPEV3-008-4A	973541	Eaton	DC Motorpump Assembly	Gulfstream V
MPEV3-008-10	3029043-001	Eaton	DC Motorpump Assembly	Ilyushin 114
MPEV3-008-9	997749	Eaton	DC Motorpump Assembly	Hawker Horizon 4000
PV3-008-1B	3030244-002	Eaton	Hydraulic Pump Assembly	SJ-30 Bizjet
	FRH050001-2	FR-HiTEMP	MFLI OUTER, UPPER	A319
	8813	FR-HiTEMP	Actuator	CASA 235
	9201000-244	FR-HiTEMP	Contents Transmitter	BAe125
	HTE900087	FR-HiTEMP	VALVE ASSEMBLY HTE	A319, A320
	HTE210033	FR-HiTEMP	ASSY ACTUATOR	JS41
	FRH050008	FR-HiTEMP	MFLI OUTER UNIT 8	A321
	HTE900158	FR-HiTEMP	Actuator Shut Off Valve	F100
	HTE900158-001	FR-HiTEMP	Actuator Shut Off Valve	F100
	HTE900195	FR-HiTEMP	Actuator Shut Off Valve	F70, F100
	HTE900195-001	FR-HiTEMP	Actuator Shut Off Valve	F70, F100
	HTE900214-001	FR-HiTEMP	Fuel Valve Drive Assembly	A330
	HTE200043	FR-HiTEMP	Rotary Actuator	A321

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
<b>PV3-300-EA2A</b>	<b>3022053-001</b>	<b>Eaton</b>	<b>Hydraulic Pump</b>	<b>A330/340</b>
Pump Upgrade PV3-044-48	887055DER009	Eaton	Variable Inline Piston Pump	CRJ 100/200
PV3-300-31J	3032374-001	Eaton	Variable Inline Piston Pump	A380
PV3-300-31K	3032782-000	Eaton	Variable Inline Piston Pump	A380
PV3-044-53	3032467-001	Eaton	Variable Inline Piston Pump	CRJ 100/200
Type 8410	568-1-27202-006	Eaton	Fuel Pump	A320, A321
PV3-056-5C	303 2438-001	Eaton	Hydraulic Pump	Hawker 4000
PV3-300-31G	3031733-001	Eaton	Variable Inline Piston Pump	A380
Type 8810	568-1-28300-101	Eaton	Fuel Pump	A340
PV3-240-10D Housing	971699	Eaton	Pump Housing	B737 new generation
MK 57	1157060	Eaton	Valve Element	A300, A310
9602	568-1-30080-001/2	Eaton	Fuel Pump	B777
12D0024	FRH530014D-32-1	Eaton	Door Bypass Valve	A330/340
PPEF4-004-1C	3032683-100	Eaton	Hydraulic Power Pack	EMB500
HR6B9-002- EA5	00-920635	Eaton	Brake Metering Valve	A320
<b>PV3-300-13K</b>	<b>00-974976</b>	<b>Eaton</b>	<b>Hydraulic Pump</b>	<b>A330/340</b>
Type9107 Mk1	568-1-29118	Eaton	Housing Assembly	B777
PV3-075-49	3031917 ref: 5914548 5915277-1 5915388-1 5915664-1	Eaton	RAT Pump	B787
165W01020	940732	Eaton	A/C Motorpump	B727, B737
<b>165W01022</b>	<b>961627</b>	<b>Eaton</b>	<b>A/C Motorpump</b>	<b>B727, B737</b>
MF 044L008C	278032	Eaton	Hydraulic Motor	Columbia Helicopter 234
PV3-300-31L PV3-300-31M PV3-300-31N	3032793-000 3032793-001 3032793-002	Eaton	Hydraulic Pump	A380

EATON AEROSPACE, LLC  
REPAIR STATION – COMPONENT CAPABILITIES LIST  
FAA APPROVED REPAIR STATION NUMBER EF4R152M  
(Additions indicated with bold type on the last page)

MODEL	P/N	MFG	DESCRIPTION	AIRCRAFT
MK 2	568-1-29117-003	FR-HiTEMP	PUMP,TYPE:9108,Mk2	Boeing 777
PV3-075-49D	5916669-1	Eaton	RAT Pump	Boeing 787
	960023 / FRH530014D	FR-HiTemp	Bypass Valve	A330 / A340
PPEF4-004-1E	3032683-002	Eaton	Hydraulic Power Pack	EMB500
PPEF4-004-1F	3032683-003	Eaton	Hydraulic Power Pack	EMB500
<b>PV3-022-36</b>	<b>00 - 847705</b>	<b>Vickers</b>	<b>Variable Inline Piston Pump</b>	<b>Y7 – 200A</b>
<b>MPEV3-011-33</b>	<b>00 - 847711</b>	<b>Vickers</b>	<b>Variable AC Motorpump</b>	<b>Y7 – 200A</b>
RRS-306-2B	3032763-002	Eaton	Reservoir	EMB500
1158000-21R	1158000-21R	FR-HiTEMP	ELEMENT ASSEMBLY	A319/320/321
1158000-45	1158000-45	FR-HiTEMP	ELEMENT ASSEMBLY	A319/320/321
PPEF4-004-2x	3032988-001, -002	Eaton	Hydraulic Pump Package	Embraer VLJ
<b>HD5E9-020-1</b>	<b>00-887692</b>	<b>Eaton</b>	<b>Valve</b>	<b>B737-300</b>