




BM-009

Maintenance Capability List for CAAC

Approval No F04400442

Uncontrolled Copy Printed From the Intranet

Function	Title	Name	Signature	Date
Prepared by (Subject Matter Expert)	Senior Quality Engineer	Tyler Sitch		Jul 17
Approved by (Process Owner)	Accountable Manager	Ben Bryson		Jul 17
Approved by (Process Owner)	Quality Manager	Ian Dickson		Jul 17
Issuing Authority (Document Controller)	Senior Secretary, Quality – Titchfield	Carol Lock		Jul 17

Revision		Reason for change + Revision summary
Number	Date	
1	Apr 2015	Procedure Format Change renumbering the original BM-108 and Full Review of Capability List to ensure full compliance with the MOM Scope of Work. 787 Parts that do not have a Boeing / FAA approved CMM removed from the list. Added CAAC Capability List Amendment Form BM-F-009-1.
2	Jul 2017	Subject matter expert changed from Owen Case to Tyler Sitch. Full Review of Capability list carried out and harmonised with EASA/FAA Capability List BM-004. Airbus, Boeing and RR parts added at request of Chinese operators, Airbus and RR. Form BM-F-009-1 deleted. Additions to CAAC Cap List to be made via BM-F-004-1. Ratings added to reflect Chinese Customers Requests. ATA Chapters 21, 24, 25, 26, 32, 38, 47, 49, 52, 73, 75 and 77. ATA Chapter 39 removed as Eaton have no products within this rating.

* It is the responsibility of the Process Owner to ensure this document is reviewed within a 2 year period. Note: all updates require communication and training with records to be maintained.

Table of Contents

1.	Purpose:.....	3
2.	Scope:.....	3
3.	Related Documents.....	3
4.	RESPONSIBILITIES	3
4.1	Quality Manager	3
4.2	Plant Manager Aftermarket.....	4
5.	DOCUMENT MAINTENANCE	4
5.1	Requirements for additions	4
5.2	Incorporation of Amendment.....	4
6.	APPENDIX A - CAPABILITY LIST – TITCHFIELD.....	5

1. Purpose:

The purpose of this document is to detail the components on which the Maintenance Organisation, Eaton Limited at Titchfield has capability to perform repair and overhaul activities and thereby defines the scope of approval granted to the company by the CAAC.

Components itemised in these lists (Appendix A) are complete assemblies, however, the individual piece parts and sub-assemblies of these are also considered to be covered by the entry in the list of the complete assembly.

2. Scope:

The Approved Maintenance Organisation at the Titchfield Plant of Eaton Limited.

3. Related Documents

BM-005 Maintenance Management Manual for the CAAC Approved Maintenance Organisation/Repair Station.

4. RESPONSIBILITIES

4.1 Quality Manager

The Quality Manager is responsible for the following:

- Ensuring that this document is maintained in accordance with the requirements specified by the CAAC.
- Incorporation of all amendments to this document.
- Verification of the company's capability to Repair/Overhaul a component prior to submission for additional capability.
- Authorisation, on behalf of the company, of the submission to the CAAC for additions to the Capability List.
- Maintain data base recording date BM-009 was sent to the CAAC and date approval was granted.
- Validation of the ratings specified in the company's scope of approval.

4.2 Plant Manager Aftermarket

The Plant Manager Aftermarket is responsible for the following:

- Ensuring that the company maintains the capability for all the components detailed in the Capability List.
- Identifying to the Quality Manager any required changes to the Capability List.
- Initial verification of the company's capability to Repair/Overhaul a component prior to submission for additional capability.

5. DOCUMENT MAINTENANCE

5.1 Requirements for additions

The company will not undertake the Repair or Overhaul of any component unless that component is detailed in the Capability List or a revision to the Capability List on Form BM-F-004-1 has been verified and accepted by the Quality Department on behalf of the CAAC.

Prior to verification and acceptance of an addition to BM-009 the company will ensure that the that the following are available:

- Relevant technical data, such as Component Maintenance Manuals, Overhaul Manuals etc., issued through the appropriate control systems.
- Sufficient qualified personnel capable of performing the maintenance activities on the subject components.
- All the tools, materials and test equipment as required by the relevant technical data.
- Suitable facilities, e.g. benches, plant and machinery, etc.

If the additional component is not covered by the company's scope of approval from the CAAC then a request for the relevant scope of work to be added will be made as part of the submission for additional capability.

5.2 Incorporation of Amendment

Once the requirements of para 5.1 have been met, the completed form BM-F-009-1 will be accepted. Each form will be numbered uniquely and sequentially.

Details of the changes along with copies of completed BM-F-004-1 forms will be retained as history within the Quality Department.

A monthly review of the Capability list will be conducted by the Quality Department with the aim of a formal reissue six monthly or more frequently if the need arises. All amendments to BM-009 Capability List will be incorporated at the 6 monthly review and sent to the CAAC for acceptance.

6. APPENDIX A - CAPABILITY LIST – TITCHFIELD

Item No	Part Number	Description	ATA Chapter No	Manufacturer	Maintenance Function	Technical Data	Major Equipment	Remarks
1	0725145	ELEMENT ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A318 A319 A320 A321
2	0725185	REFUEL COUPLING	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A320 A321
3	0727540	FLUSH COVER AND CABLE ASSEMBLY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321
4	0733220	WATER DRAIN VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
5	1157020	CANISTER MK 57 VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A310 A300
6	1157060	MK 57 VALVE ELEMENT	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A310 A300
7	1158000-SERIES	REFUEL VALVE ELEMENT	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321
8	3802045	VALVE ASSY SOLENOID	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A318 A319 A320 A321
9	3901340	JET PUMP	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300 A310 A330 A340
10	3901395	SCAVENGE JET PUMP	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320
11	3901515	JET PUMP	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A321
12	4127360	Vent and drain valve	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300 A310 A319 A320 A321 A330 A340
13	9350022	DRAIN VALVE	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A310 A320 F50 F70 F100
14	9350127	DRAIN VALVE (CARGO HOLD)	25	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A320 A319 A321
15	9350140	WATER WASTE DRAIN VALVE WITH N	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
16	9406012	FLAT ACTUATOR	24	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300 A310
17	9406038	FLAT ACTUATOR	24	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300 A310
18	9508170	AIR/NO FUEL VENT VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300 A310
19	9508175	FLOAT VENT VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A320 A319 A321 A330 A340
20	9811795	NRV	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300 A319 A321

Item No	Part Number	Description	ATA Chapter No	Manufacturer	Maintenance Function	Technical Data	Major Equipment	Remarks
21	9811820	CHECK VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321 A340
22	9811839	1/2IN NON-RETURN VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321
23	9811950	3/4" NRV VALVE	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330
24	9813395	AIR RELEASE VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330
25	9813405	CHECK VALVE, RESTRICTOR ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A321 A340
26	9813445	RELIEF VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
27	98111025	0.75" NRV	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
28	12-0065	DRIVESHAFT-VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
29	12-0066	DRIVESHAFT-VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
30	12-0067	DRIVESHAFT-VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
31	12-0084	DRIVESHAFT-VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
32	12D0024	DOOR BYPASS VALVE	32	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
33	12F0069	VALVE-3/4IN REMOTE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
34	12F0074	VALVE-3/4IN REMOTE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
35	12H0035	VALVE-1IN REMOTE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
36	12H0058	CENTRE TANK EJECTOR PUMP	47	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
37	12H0068	VALVE-1IN PEDESTAL	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
38	12H0077	Valve in Remote Drive	47	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
39	12K0036	VALVE	47	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
40	12K0063	1.5 INCH PEDESTAL BALL VALVE	47	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
41	12M0033	VALVE 2" REMOTE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
42	12M0034	VALVE-2IN REMOTE (DEFUEL)	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787

Item No	Part Number	Description	ATA Chapter No	Manufacturer	Maintenance Function	Technical Data	Major Equipment	Remarks
43	12M0037	VALVE BODY - 2IN (JTSN)	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
44	12M0075	VALVE 2" REMOTE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
45	12M0076	VALVE-2IN REMOTE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
46	12M0090	LP VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
47	20-0034	VALVE-PRESSURE RELIEF (7012069H05)	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
48	20C0003	VALVE-DRAIN	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
49	20K0032	CHECK VALVE 1 3/4"	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
50	20P0023	DRIVESHAFT-VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
51	20R0016	Valve 3" Check	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
52	21-0007	VALVE-DRAIN	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
53	21-0013	VALVE DRAIN	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
54	21-0037-1100	PUMP OUTLET NON-RETURN VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A320
55	21F0010	VALVE-3/4IN CHECK	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
56	21F0015	CHECK VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
57	21H0005	1 1/4" CHECK VALVE	47	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
58	21K0003	VALVE 1 1/2" CHECK	47	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
59	21M0017	Valve 2" Check Arrest	47	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
60	21M0018	VALVE-2IN CHECK	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
61	21V0020	NON RETURN VALVE	36	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A320
62	23-0001-1100	VALVE-PRESS RELIEF	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
63	25-0007	MK 57 VALVE ELEMENT	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300 A310
64	25P0001	ADAPTER REFUEL	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787

Item No	Part Number	Description	ATA Chapter No	Manufacturer	Maintenance Function	Technical Data	Major Equipment	Remarks
65	25R0017	ELEMENT ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A318 A319 A320 A321
66	28-0017	Vent Float Valve (HS P/N 7012066H03)	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
67	28-0018	VALVE-VENT FLOAT (HS PN: 7012079H04)	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
68	34-0001	VALVE BODY-TELL-TALE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
69	34-0005	VALVE (AND ACTUATION MECHANISM)	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
70	34-0012	VALVE BODY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
71	3508802-1	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320
72	3508802-10	MAGNETIC FUEL LEVEL INDICATOR UPPER OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A320
73	3508802-2	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320
74	3508802-20	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320
75	3508802-29	MAGNETIC FUEL LEVEL INDICATOR LOWER OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320
76	3508802-3	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320
77	3508802-35	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321
78	3508802-36	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321
79	3508802-37	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321
80	3508802-38	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321
81	3508802-4	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320
82	3508802-40	MAGNETIC FUEL LEVEL INDICATOR UPPER OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320
83	3508802-47	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
84	3508802-52	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
85	3508802-57	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
86	3508802-58	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340

Item No	Part Number	Description	ATA Chapter No	Manufacturer	Maintenance Function	Technical Data	Major Equipment	Remarks
87	3508802-59	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
88	3508802-70	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A321
89	3508802-71	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A321
90	3508802-78	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
91	3508802-79	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
92	3508802-84	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
93	3530000-SERIES	LEVEL & TEMPERATURE SENSORS	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321 A330 A340
94	3540000-SERIES	LEVEL & TEMPERATURE SENSORS	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321
95	38-0002	JET PUMP-WATER SCAVENGE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
96	38-0008	JET PUMP	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
97	38-0009	JET PUMP INBOARD	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
98	38-0011	PUMP-FUEL TRANSFER SCAV	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
99	38-0014	PUMP, EJECTOR	47	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
100	39-0001-SERIES	PUMP, BOOST	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
101	39-0002-1100	PUMP, OVRD/JTSN	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
102	39-0003-SERIES	HOUSING, OVERRIDE/JETTISON PUMP	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
103	39-0004-1100	HOUSING, BOOST PUMP	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
104	39-0005-SERIES	PUMP APU TYPE 390005	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
105	39-0006-1100	HOUSING-DC PUMP APU	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
106	46H0009	SLIDING UNION ASSY, - SIZE 16	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
107	46K0010	SLIDING UNION ASSY - SIZE 24	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
108	46M0011	SLIDING UNION AND COVERS (SIZE 32)	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380

Item No	Part Number	Description	ATA Chapter No	Manufacturer	Maintenance Function	Technical Data	Major Equipment	Remarks
109	46M0015	SLIDING UNION ASSY - SIZE 32	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
110	506-1-04040-002	SOLENOID VALVE SOV110 Mk 2	75	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR TRENT
111	53-0002	ADAPTOR ACTUATOR	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
112	53-0005	ADAPTOR ACTUATOR	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
113	53-0014	TWIN MOTOR ACTUATOR	24	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
114	53-0037	ACTUATOR VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
115	53-0038	ACTUATOR, VALVE	47	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
116	53-0041	ADAPTOR, ACTUATOR	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
117	53-0049	VALVE ACTUATOR	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
118	550-1-00236	LOW PRESSURE FUEL (BACKING PUMP)	73	Eaton Ltd	repair, modification, overhaul, inspection		According CMM	RR TAY RR SPEY
119	568-1-26713-005	FUEL PUMP TYPE 8420 MK 4	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 737
120	568-1-27170-SERIES	FUEL PUMP TYPE 8413	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321
121	568-1-27171-002	MOUNTING PLATE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300, A319, A321, A340
122	568-1-27202-SERIES	PUMP 8410 MK1, 2, 5, 6 & 7	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A320
123	568-1-27203-SERIES	CANISTER TYPE 8411 MK 3	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321
124	568-1-27244-SERIES	CANISTER TYPE 8411	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A320
125	568-1-28300-SERIES	BOOST PUMP TYPE 8810	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
126	568-1-28301-SERIES	CANISTER TYPE 8811	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
127	568-1-28405-001	PUMP JET 8814 MK 1	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
128	568-1-29115-SERIES	FUEL BOOST PUMP TYPE 9106	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 777
129	568-1-29116-SERIES	HOUSING ASSY, FUEL BOOST OJ PUMP	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 777
130	568-1-29117-SERIES	FUEL PUMP OVERRIDE/JETTISON	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 777

Item No	Part Number	Description	ATA Chapter No	Manufacturer	Maintenance Function	Technical Data	Major Equipment	Remarks
131	568-1-29118-SERIES	HOUSING ASSEMBLIES, FUEL BOOST, JETTISON AND OVERRIDE PUMPS	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 777
132	568-1-29407-002	APU PUMP 9121Mk 2 (60B92403-23)	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 777
133	568-1-29408-SERIES	HOUSING Mk100 TYPE 9122	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 777
134	568-1-29447-000	OUTLET FLAP VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 777
135	568-1-29507-SERIES	CANISTER, TYPE 9206	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 777
136	568-1-29684-SERIES	PLATE MOUNTING 9209	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
137	568-1-30073-SERIES	HOUSING ASSY, TYPE 9603	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 777
138	568-1-30080-SERIES	FUEL BOOST PUMP TYPE 9602	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 777
139	568-1-30522-001	PUMP TYPE 20002 Mk 1	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 747
140	568-1-30666-SERIES	HOUSING ASSY JETTISON TYPE 20107	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 777
141	568-1-30685-001	PUMP TYPE 20004 Mk 1	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 747
142	568-1-30750-SERIES	FEED PUMP TYPE 20124 MKs101, 103, 105, AND 151	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
143	568-1-30751-SERIES	CANISTER TYPE 20125	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
144	568-1-30760-101	TRANSFER PUMP TYPE 20126 MK 101	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
145	568-1-30760-102	TRANSFER PUMP TYPE 20126 MK 102	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
146	568-1-30760-200	TRANSFER PUMP MK 200	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
147	568-1-30760-201	TRANSFER PUMP Mk 201	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
148	568-1-30761-100	CANISTER TYPE 20127 Mk 100	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
149	568-1-30761-102	CANISTER TYPE 20127 Mk 102	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
150	568-1-30770-SERIES	A380 TRIM PUMP	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
151	568-1-30780-100	APU PUMP TYPE 20026 MK.100	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
152	568-1-30781-SERIES	CANISTER MK 201	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380

Item No	Part Number	Description	ATA Chapter No	Manufacturer	Maintenance Function	Technical Data	Major Equipment	Remarks
153	568-1-31509-000	VALVE FLAP OUTLET	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 777
154	68-0002	PRESSURE SWITCH	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
155	68-0004	SENSOR	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
156	68-0005	TEMPERATURE SENSOR	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330
157	68-0008	TEMPERATURE SENSOR	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A318 A319 A320 A321
158	7012060H02	VALVE	47	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
159	7012060H03	VALVE 1 INCH REMOTE DRIVE	47	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
160	7012061H01	1 ½" CHECK VALVE	47	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
161	7012062H01	1 1/4 INCH CHECK VALVE	47	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
162	7012063H02	CHECK ARRESTOR VALVE 2 INCH	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
163	7012064H01	VALVE BODY-TELL-TALE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
164	7012067H02	VALVE-VENT DRAIN	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
165	7012070H03	ACTUATOR VALVE	47	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
166	7012073H01	VALVE BODY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
167	7012075H01	PUMP-EJECTOR	47	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
168	7012079H04	VALVE-VENT FLOAT	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
169	7012080H02	1.5 INCH REMOTE VALVE	47	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
170	7013072H01	DRIVESHAFT-VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
171	7112060H01	CENTRE TANK EJECTOR PUMP	47	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
172	7112074H01	ANTI CROOS FLOW CHECK VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
173	7112080H01	1.5 INCH PEDESTAL VALVE	47	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
174	75-0001-SERIES	CONTROLLER-OVRD/JSTN PUMP	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787

Item No	Part Number	Description	ATA Chapter No	Manufacturer	Maintenance Function	Technical Data	Major Equipment	Remarks
175	754-1-32148-SERIES	CONTROL UNIT AIRFLOW AC101 SER	75	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR RB211
176	754-1-32156-003	RAM ASSY, TYPE AR101 MK 3	75	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR RB211
177	754-1-32322-001	SWITCH PRESSURE RATIO PRS104	75	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR RB211
178	754-1-32762-002	AV101 MK2 CONTROL UNIT	75	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR RB211
179	754-1-32762-010	Control Unit Bleed Valve AV101	75	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR RB211
180	754-1-37662-002	MOTOR PRV ASSEMBLY AM600 MK 2	52	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 747 767
181	754-1-39743-SERIES	RAM ASSY AR 103 (-003 / -004)	75	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR RB211
182	754-1-39744-002	CONTROL UNIT BLEED VALVE AV103	75	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR RB211
183	754-1-39785-SERIES	AIRFLOW CONTROL UNIT	75	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR RB211
184	754-1-40126-000	BODY ASSY	75	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR RB211
185	754-1-40129-000	MANIFOLD AND ELEMENT ASSEMBLY	75	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR RB211
186	754-1-40480-002	ACTUATING RAM AR210 SERIES	75	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR TRENT
187	754-1-40530-SERIES	MANIFOLD AND ELEMENT ASSEMBLY	75	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR RB211
188	78F0055	VALVE THERMAL RELIEF	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 787
189	7940061D	SHUT-OFF VALVE	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A320
190	7945202H	VALVE	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300 A310
191	7945217F	MOTORISED WATER VALVE	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300 A310
192	8084015F	MULTIWAY SPV	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300
193	8084032C	MULTIWAY SPV	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300
194	8084036H	MULTIWAY SPV	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300 A310
195	8084240H	MOTORISED SPV	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300 A310
196	9201000-265	CONTENTS TRANSMITTER	77	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR TAY

Item No	Part Number	Description	ATA Chapter No	Manufacturer	Maintenance Function	Technical Data	Major Equipment	Remarks
197	9201000-272	CONTENTS TRANSMITTER	77	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR TAY
198	9840094H	NON-RETURN VALVE	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300 A310
199	9843144M	CHECK VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
200	9843153F	NRV ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
201	9843169L	CHECK VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
202	9843181F	CHECK VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A321 A380
203	FRH010034	TWIN MOTOR ACTUATOR	24	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 BAE 146
204	FRH010041	TWIN MOTOR ACTUATOR	24	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
205	FRH050001-SERIES	MFLI OUTER ASSEMBLY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A318 A319 A320
206	FRH050002	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSEMBLY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A318 A319 A320 A321
207	FRH050003	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSEMBLY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A318 A319 A320 A321
208	FRH050004	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSEMBLY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A318 A319 A320 A321
209	FRH050005	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSEMBLY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A318 A319 A320 A321
210	FRH050006	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSEMBLY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A318 A319 A320 A321
211	FRH050007	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSEMBLY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A321
212	FRH050008	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSEMBLY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A321
213	FRH050009	MAGNETIC FUEL LEVEL INDICATOR OUTER ASSEMBLY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A321
214	FRH100002A	PRESSURE SWITCH	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300 A310 A330
215	FRH100013A	PRESSURE SWITCH	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A321 A330 A340
216	FRH100014A	PRESSURE SWITCH	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321
217	FRH100021A	PRESSURE SWITCH	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
218	FRH100028A	PRESSURE SWITCH	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340

Item No	Part Number	Description	ATA Chapter No	Manufacturer	Maintenance Function	Technical Data	Major Equipment	Remarks
219	FRH120137R	JETTISON VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
220	FRH120196M	2 IN OUTBOARD LP VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
221	FRH120197M	LP VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
222	FRH120199M	ACTUATED SHUT-OFF BALL VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
223	FRH120200M	2 INCH LP ENGINE VALVE (INBOARD)	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
224	FRH120207T	TRANSFER CONTROL VALVE (PORT)	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
225	FRH120209T	TRANSFER CONTROL VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
226	FRH120221P	2.5" SP VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 MRTT
227	FRH120231	DRIVE AAR ISOLATION UNIT	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 MRTT
228	FRH120233P	AAR ISOLATION VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 MRTT
229	FRH120266M	VALVE LP OUTBOARD	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
230	FRH200045M	PRESSURE HOLDING VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
231	FRH200058C	VALVE	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
232	FRH200063P	VALVE PRESSURE HOLDING	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
233	FRH200068M	VALVE PRESSURE HOLDING	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
234	FRH210008M	CHECK VALVE RESTRICTOR	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
235	FRH220008X	4.875 IN DOUBLE FLAP NRV	75	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR RB211
236	FRH220033V	NON RETURN VALVE	36	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A318 A319 A320 A321
237	FRH220034V	DUCT AND NON-RETURN VALVE	36	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A320
238	FRH230003C	PRESSURE REDUCING AND RELIEF V	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321 A330
239	FRH230014C	THERMAL RELIEF VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 MRTT
240	FRH280002	AIR RELEASE VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321 A330

Item No	Part Number	Description	ATA Chapter No	Manufacturer	Maintenance Function	Technical Data	Major Equipment	Remarks
241	FRH340002B	WATER DRAIN VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
242	FRH340003H	WASTE WATER DRAIN VALVE	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321 A330 A340
243	FRH340004	WATER DRAIN VALVE (INDIRECT)	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
244	FRH340005	WATER DRAIN VALVE (DIRECT)	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
245	FRH340017	WATER DRAIN VALVE - INDIRECT	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
246	FRH461111	UNION-SLIDING	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
247	FRH461112	UNION-SLIDING	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
248	FRH461113	UNION SLIDING TYPE 3 - SIZE 32	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
249	FRH461114	UNION SLIDING	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
250	FRH461115	UNION-SLIDING	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
251	FRH461116	UNION-SLIDING	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
252	FRH461117	UNION SLIDING TYPE 3 - SIZE 32	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
253	FRH461118	SLIDING UNION TYPE 4 (SIZE 20) - WING	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
254	FRH461119	UNION-SLIDING	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A380
255	FRH530014D	DOOR BYPASS VALVE	32	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
256	HTE190001-SERIES	TWIN MOTOR ACTUATOR	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321
257	HTE190021	Twin Motor Actuator	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
258	HTE190026	ACTUATOR TWIN MOTOR	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
259	HTE200002-SERIES	ACTUATOR, SINGLE MOTOR	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A321
260	HTE200066	SINGLE MOTOR ACTUATOR	24	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A320
261	HTE250113-2	ELECTRIC ACTUATED ISOLATION VALVE	21	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300 A310
262	HTE310020	DEPRESSURISING VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340

Item No	Part Number	Description	ATA Chapter No	Manufacturer	Maintenance Function	Technical Data	Major Equipment	Remarks
263	HTE310021-SERIES	REFUEL GALLERY AIR INLET VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A318 A319 A320
264	HTE310028	FUEL DRAIN VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300 A310 A319 A320 A321
265	HTE370001	HP GROUND CON. & NRV	36	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321 A330 A340
266	HTE400115	CHECK VALVE	26	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A330 A340
267	HTE400127	3/8 INCH NRV	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
268	HTE400207	3/8 INCH NRV	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
269	HTE420044	PRESS HOLDING VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320
270	HTE420080	PRESSURE HOLDING VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
271	HTE420086	PRESSURE HOLDING VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A321
272	HTE4418	NRV	36	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR TAY
273	HTE450001-9	6 INCH DOUBLE FLAP NRV	75	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR RB211
274	HTE450001-SERIES	6 INCH DOUBLE FLAP NRV	75	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	RR RB211
275	HTE490012	PUMP OUTLET NON-RETURN VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A321
276	HTE4918	NRV	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300 A310 A319 A320 A321
277	HTE510005-SERIES	PRESSURE REDUCING AND RELIEF VALVE	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321
278	HTE510010-SERIES	PRESSURE REDUCING AND RELIEF VALVE	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300 A310
279	HTE510016	GAS CHARGING VALVE	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321 A330 A340
280	HTE510027-1	PRESSURE REDUCING AND RELIEF VALVE	38	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
281	HTE550031	DRIVE ASSEMBLY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A320 A330 A340
282	HTE620071-1	1 INCH SLIDING UNION	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
283	HTE620072-1	1.5 INCH SLIDING UNION	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
284	HTE620196	1 INCH SLIDING UNION	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340

Item No	Part Number	Description	ATA Chapter No	Manufacturer	Maintenance Function	Technical Data	Major Equipment	Remarks
285	HTE620197	1.5 INCH SLIDING UNION	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
286	HTE6303	SWIVEL PIPE ASSY	52	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A310
287	HTE660020	COMPENSATED SLIDE	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321
288	HTE69000-1	PRESSURE SWITCH	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A300 A310 A319 A320 A321 A330 A340
289	HTE690035-1	PRESSURE SWITCH	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321
290	HTE690047	PRESSURE SWITCH	21	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A319 A320 A321 A330 A340
291	HTE690112	PRESSURE SWITCH	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A320
292	HTE900033	FUEL VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A310 A320 A321 A330 A340
293	HTE900087-SERIES	INTERCELL TRANS VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A318 A319 A320
294	HTE900095	DRIVE SPINDLE ASSEMBLY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A318 A319 A320
295	HTE900096	DRIVE SPINDLE ASSEMBLY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A318 A319 A320
296	HTE900118-SERIES	LP VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A318 A319 A320 A321
297	HTE900133	VALVE ASSEMBLY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A318 A319 A320 A321
298	HTE900135	VALVE ASSEMBLY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A318 A319 A320 A321
299	HTE900162	FUEL CROSSFEED VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
300	HTE900169	JETTISON FUEL VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A321 A330 A340
301	HTE900189	25MM FUEL VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A321
302	HTE900193	50mm FUEL VALVE ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A310 A330 A340
303	HTE900206-001	CROSSFEED VALVE ASSEMBLY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
304	HTE900208-001	EMERGENCY ISOLATION VALVE ASSE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
305	HTE900208-003	VALVE SUB ASSY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340



PROCEDURE
Maintenance Capability List for CAAC

No: **BM-009**
Page 19 of 19
Revision: **02**

Item No	Part Number	Description	ATA Chapter No	Manufacturer	Maintenance Function	Technical Data	Major Equipment	Remarks
306	HTE900209-001	TANK ISOLATION VALVE ASSEMBLY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
307	HTE900211	FUEL CROSSFEED VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A340
308	HTE900212	LOW PRESSURE FUEL VALVE	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340
309	HTE900214-001	TANK ISOLATION VALVE ASSEMBLY	28	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330
310	HTE920007-001	ACTUATED AIR VALVE	21	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A310 A319
311	HTE920012	ELECTRICALLY ACTUATED BALL VALVE	29	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	BOEING 707
312	HTE960023	DOOR BY-PASS VALVE	32	Eaton Ltd	repair, modification, overhaul, inspection	CMM / IPL	According CMM	A330 A340