

Burton-on-the-Wolds, 13<sup>th</sup> September 2021

**Product Change Notification PCN\_BUR\_00172**

**Subject: Eaton's Bussmann series High speed fuse link 170M6286 label updated with correct rated current**

Dear Customer,


Following a review of Eaton's Bussmann series high speed fuse technical data, a correction has been made to the labelling of the 170M6286 current rating which was made as a result of a system error. The formally labelled 1600 A rating has been changed to 1500 A as per the controlling datasheet rating and subsequent test report. The change will include the product label as well as packaging label accompanying the product. This change will be made with immediate effect.

Part number	Previous description printed on label	Correct description printed on label
170M6286	1600 A 690V IEC aR 3KW/110	1500A 690V IEC aR 3KW/110

Please note, no changes have been made to the fuse design as a result of the correction. The change only corrects the text on the label to represent the current rating originally intended by its design.

If you have any queries or require any additional technical support on this change, please contact our Field Application Engineers at [bulehighspeedtechnical@eaton.com](mailto:bulehighspeedtechnical@eaton.com).

Yours sincerely



Ryan Patterson  
Product Manager & Field Applications Manager, High Speed Fuses  
Bussmann series products, Industrial Control & Protection Division  
[ryanjpatterson@eaton.com](mailto:ryanjpatterson@eaton.com)