

Important note

Room Controller Touch lux sensor

Subject: The lux sensor on the Room Controller Touch is no longer supported.

Background:

Since the launch of the Room Controller Touch contains a lux-sensor, which hasn't been documented due to very situational application possibilities. The function was only available if used with the xComfort Smart Home Controller where it is presented as an independent device, however the measured data is unpredictable and outputs a lesser value.

Decision:

Due to the shortage of the electronic components for the lux-sensor combined with the internal programming memory limitations we were compelled to no longer support the lux-sensor function in the Room Controller Touch.

Consequences:

The Room Controller Software version 3 and higher doesn't support the lux sensor anymore. This is applicable for both the **Universal** and the **Legacy** version of the Room Controller Touch software.

Room controller Touch that has the last 5 digits of the bar-code BK77C up to BK92C or BLxxC do not contain the lux sensor hardware.

Older Room Controller Touch

A Room Controller Touch that has the lux sensor hardware can continue to use the lux information in the xComfort Smart Home Controller. These Room Controller should not be upgraded to version 3L but should stay programmed with version 2 or lower.

These Room Controllers can be identified by the last 5 digits of the bar-code: AxxxC, BTxxC or BK41C up to BK77C.