

Product Change Notice

PCN#: EE-PCN16031

09/06/2016

Update on 08/15/2017

CLASSIFICATION OF CHANGE:

End of Life Notification (EOL)

DESCRIPTION OF CHANGE:

End of Life Notification (EOL) for MPI2520 Product Family

REASON FOR CHANGE:

Discontinuation of MPI25200 product family, MPI25-V2 as replacement product

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

Not applicable

PARTS FAMILIES AFFECTED:

MPI2520R0		MPI2510V2	
EATON PN (EOL)	Height	EATON PN (Eaton PN Recommend Replacement)	Height
MPI2520R0-R47-R	1.0 mm	MPI2510V2-R47-R	1.0 mm
MPI2520R0-1R0-R	1.0 mm	MPI2510V2-1R0-R	1.0 mm
MPI2520R0-1R5-R	1.0 mm	MPI2510V2-1R5-R	1.0 mm
MPI2520R0-2R2-R	1.0 mm	MPI2510V2-2R2-R	1.0 mm
MPI2520R0-3R3-R	1.0 mm	MPI2510V2-3R3-R	1.0 mm
MPI2520R0-4R7-R	1.0 mm	MPI2510V2-4R7-R	1.0 mm
MPI2520R1		MPI2512V2	
EATON PN (EOL)	Height	EATON PN (Eaton PN Recommend Replacement)	Height
MPI2520R1-R47-R	1.2 mm	MPI2512V2-R47-R	1.2 mm
MPI2520R1-1R0-R	1.2 mm	MPI2512V2-1R0-R	1.2 mm
MPI2520R1-1R5-R	1.2 mm	MPI2512V2-1R5-R	1.2 mm
MPI2520R1-2R2-R	1.2 mm	MPI2512V2-2R2-R	1.2 mm
MPI2520R1-4R7-R	1.2 mm	MPI2512V2-4R7-R	1.2 mm

TIME SCHEDULE:

Last Time Buy Date: September 15th, 2016

Last Time Shipment Date: March 1th, 2017

REPLACEMENT SAMPLE AVAILABILITY:

Replacement sample availability will be announced through EOL-inductors@eaton.com. Customers are encouraged to email their contact information to receive up-to-date EOL notifications.

REPLACEMENT PRODUCT DOCUMENTATION:

Please request replacement product documentation through EOL-inductors@eaton.com , also by contacting your local Eaton sales representative or distributors.

ISSUED BY:

Steve Subiry - Global Product Manager

CONTACT INFORMATION: For questions or comments, please contact your local [Eaton sales representative](#).