

P.O. Box 14460
St. Louis, MO 63178-4460
114 Old State Road
Ellisville, MO 63021
Phone: (636) 527-3877

Date: **April 03, 2007**
To: PC04F / PC06F fuse customers
Subject: **PC04F / PC06F Fuse END of LIFE NOTICE**

Cooper Bussmann is discontinuing the PC04F and PC06F fuse Series.

The recommended replacement for the PC06F is the RoHS compliant 0603FA-R Series CHIP™ Fuse.

The 0603FA-R Series is immediately available and its data sheet is on our website
(www.cooperbussmann.com).
