

P.O. Box 14460  
St. Louis, MO 63178-4460  
114 Old State Road  
Ellisville, MO 63021  
Phone: (636) 527-1270



## End-of-Life Notice

**July 1, 2010**

**To: Cooper Bussmann® Circuit Protection Customers**

**Subject: SR-5 40mA-80mA End-of-Life Notice**

The Cooper Bussmann® SR-5 40mA-80mA subminiature time-delay fuses have reached their end-of-life and will be discontinued effective September, 2010. You can find the data sheet for the affected part number(s) at [www.cooperbussmann.com/datasheets/elx](http://www.cooperbussmann.com/datasheets/elx) under data sheet number 4347. A last time buy to order these part numbers is available through August 31, 2010.

Obsolete Part Number	Replacement Part Number
SR-5-40mA-AP	No direct replacement
SR-5-40mA-BK	No direct replacement
SR-5-50mA-AP	No direct replacement
SR-5-50mA-BK	No direct replacement
SR-5-63mA-AP	No direct replacement
SR-5-63mA-BK	No direct replacement
SR-5-80mA-AP	No direct replacement
SR-5-80mA-BK	No direct replacement

If you have any questions or concerns about the end of life date or suggested replacement(s), please contact your local Cooper Bussmann Sales Representative or Applications Engineering ([FuseTech@CooperIndustries.com](mailto:FuseTech@CooperIndustries.com)).

Thank you for your business and cooperation during this upcoming transition.

Best Regards,

Jacquelyn Dickerson  
Associate Product Manager