

Product Change Notice

PCN#: EE-PCN19004
Mar 20th, 2019

CLASSIFICATION OF CHANGE:

Winding process expansion for MPI(A)4020V2

DESCRIPTION OF CHANGE:

Expand internal winding process capability for MPI(A)4020V2

REASON FOR CHANGE:

Winding process capability expansion needed to maintain short lead-times, and high level of customer service

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

It is running change. There is no impact to form-fit- function and no effect on the quality, reliability, or performance.

PARTS FAMILIES AFFECTED:

MPI(A)4020V2-R33-R

MPI(A)4020V2-1R0-R

MPI(A)4020V2-2R2-R

TIME SCHEDULE:

Start Shipment Date: Jun 1st, 2020

Last Time Buy Date: N/A

Last Time Shipment Date: N/A

SAMPLE AVAILABILITY:

Available upon request

QUALIFICATION DATA:

Available upon request

ISSUED BY:

Product Manager: Steve Subiry

CONTACT INFORMATION:

For questions or comments, please link this url: <https://www.eaton.com/content/eaton/us/en-us/products/electronic-components/contact-us>