114 Old State Road Ellisville, MO 63021 Phone: (636) 527-1270



## Dear Valued Customer:

Effective February 2013, Cooper Bussmann implemented a marking change to the FP3 Series of High Current Inductors comprised of the following part numbers.

FP3-R10-R	FP3-R68-R	FP3-2R0-R	FP3-8R2-R
FP3-R20-R	FP3-1R0-R	FP3-3R3-R	FP3-100-R
FP3-R47-R	FP3-1R5-R	FP3-4R7-R	FP3-150-R

This marking change added a manufacturing location identifier for traceability.

Part marking for the FP3 Series now consists of the following:


Y= last digit of the year

**WW** = week of year

**L** = manufacturing location

This part marking change does not affect the FP3 Series part numbers, the ordering process or orientation.

See below for examples of the old and new part markings.



Cooper Bussmann is committed to providing all customers with high quality products and services. If further information is required regarding this Product Change Notification, please contact your Cooper Bussmann representative or <a href="mailto:lnductorTech@cooperindustries.com">lnductorTech@cooperindustries.com</a>. We thank you for your continued support of Cooper Bussmann and the Coiltronics brand of magnetics.

## Regards,

Jenny Li Sr. Product Manager - Magnetics Cooper Bussmann Jenny.Li@cooperindustries.com