



Eaton
Electronics Division
5735 W. Las Positas Blvd #100
Pleasanton, CA 94588
www.eaton.com/electronics

Product Change Notice

PCN#: EE-PCN20013
10/7/2020

CLASSIFICATION OF CHANGE:

End of life

DESCRIPTION OF CHANGE:

Rationalization of HTB part numbers

REASON FOR CHANGE:

As part of the product life cycle management process, these part numbers do not meet the criteria for historical unit shipment volume and product revenue performance. Recommended replacement parts are listed below.

PARTS FAMILIES AFFECTED

Please refer to the table on the last page for EOL parts and recommended replacements.

TIME SCHEDULE:

Effective immediately

ISSUED BY:

Jenan Krouchick
Product Manager – Circuit Protection

CONTACT INFORMATION:

For questions or comments, please contact <https://www.eaton.com/content/eaton/us/en-us/products/electronic-components/contact-us.html/>

Item	EOL Part Number	Recommended Replacement Part Number
1	BK-HTB-1K0801	BK-HTB-32I-R
2	BK-HTB-1K0802	BK-HTB-28M-R
3	BK-HTB-26IAGC-1	BK-HTB-26I-R
4	BK-HTB-36I	BK-HTB-36I-R
5	BK-HTB-48I	BK-HTB-48I-R
6	BK-HTB-54M	BK-HTB-54M-R
7	BK-HTB-56I-RCEL	BK-HTB-56I-R
8	BK-HTB-94M	BK-HTB-94M-R
9	BK-HTB-96I	BK-HTB-96I-R
10	HTB-26M	HTB-26M-R
11	HTB-38I	HTB-38I-R
12	HTB-44I	HTB-44I-R
13	HTB-44I-SP-L	HTB-44I-R
14	HTB-52M	BK-HTB-52M-R
15	HTB-68M	BK-HTB-58M-R
16	HTB-84I	BK-HTB-84I-R
17	HTB-86M	BK-HTB-86M-R
18	HTB-92I	HTB-92I-R
19	HTB-96M	HTB-96M-R
20	HTB-98M	BK-HTB-98M-R