

Eaton Electronics Division 5735 W. Las Positas Blvd #100 Pleasanton, CA 94588 www.eaton.com/electronics

Product Change Notice

PCN#: EE-PCN21023 10/27/2021

CLASSIFICATION OF CHANGE:

End of Life Notification

DESCRIPTION OF CHANGE:

The gold plated 1384x Edge Connectors have reached end of life. The recommended replacement parts are the tin over copper plated 1384x parts listed below.

REASON FOR CHANGE:

This change has been implemented in order to rationalize low demand configurations.

EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

The gold plated 1384x edge connector (1384X-XXG) parts are end of life. The tin over copper (1384X-XXT) recommended replacements are listed below.

PARTS AFFECTED:

| Material Number | Recommended Replacement |
|-----------------|----------------------------|
| 13847-10G02B | 13847-10T02B |
| 13847-14G02B | 13847-14T02B |
| 13847-14G02G | 13847-14T02B |
| 13847-16G02B | 13847-16T02B |
| 13848-05G02B | 13848-05T02B |
| 13848-08G02B | 13848-08T02B |
| 13848-08G02B-M | 13848-08T02B-M |
| 13848-14G02B | 13848-14T02B |
| 13848-18G02B | 13848-18T02B |

TIME SCHEDULE:

Last time buy – November 30, 2021 Last time shipment date – December 31, 2021

ISSUED BY:

Jenan Krouchick Product Manager – Circuit Protection

CONTACT INFORMATION:

For questions or comments, please contact https://www.eaton.com/content/eaton/us/en-us/products/electronic-components/contact-us.html