

## Product Change Notice

PCN#: EE-PCN23019

7/25/2023

### CLASSIFICATION OF CHANGE:

VDE certification change

### DESCRIPTION OF CHANGE:

Fuse holder H15 series has no VDE certification. Suggested alternates, where applicable, have been suggested.

### REASON FOR CHANGE:

Fuse holder H15 does not comply with VDE requirements, H15 is only available with UL certification.

### EXPECTED INFLUENCE ON QUALITY, RELIABILITY, AND PERFORMANCE:

Fuse holder H15 has no change on the quality, reliability, and performance.

### PARTS FAMILIES AFFECTED:

PN's affected and suggested replacements with VDE certification are listed below.

Product Series	FG P/N	Replacement PN
H15	BK-H15-V-1	BK1-HTC-45M
H15	BK1-H15-V-1	BK1-HTC-45M
H15	BK-H15-H-1	BK1-HTC-50M
H15	BK1-H15-H-1	BK1-HTC-50M
H15	BK-H15-V-1-K	BK1-HTC-45M
H15	BK-H15-H-1-B	BK1-HTC-50M

### TIME SCHEDULE:

Immediately

### SAMPLE AVAILABILITY:

Available upon request

### ISSUED BY:

Roald Bai  
Product Manager – Circuit Protection

### CONTACT INFORMATION:

For questions or comments, please [Contact us](#)