

FLEXTITE™ HAZARDOUS LOCATION PENDANT PUSHBUTTON STATIONS

Installation & Maintenance Addendum

 **COOPER** Crouse-Hinds

IF 1327 A

SAVE THESE INSTRUCTIONS FOR FUTURE REFERENCE

 **WARNING**

Explosion Hazard - Do not disconnect equipment unless power has been switched off or the area is known to be non-hazardous.

 **WARNING**

Explosion Hazard - Substitution of components may impair suitability for Class I, Division 2.

All statements, technical information and recommendations contained herein are based on information and tests we believe to be reliable. The accuracy or completeness thereof are not guaranteed. In accordance with Cooper Crouse-Hinds "Terms and Conditions of Sale", and since conditions of use are outside our control, the purchaser should determine the suitability of the product for his intended use and assumes all risk and liability whatsoever in connection therewith.

 **COOPER** Crouse-Hinds

Cooper Industries Inc.
Crouse-Hinds Division
PO Box 4999, Syracuse, New York 13221 • U.S.A.
Copyright© 2003, Cooper Industries, Inc.

IF 1327 A
Revision 1
New 11/03

FLEXTITE™ HAZARDOUS LOCATION PENDANT PUSHBUTTON STATIONS

Installation & Maintenance Addendum

 **COOPER** Crouse-Hinds

IF 1327 A

SAVE THESE INSTRUCTIONS FOR FUTURE REFERENCE

 **WARNING**

Explosion Hazard - Do not disconnect equipment unless power has been switched off or the area is known to be non-hazardous.

 **WARNING**

Explosion Hazard - Substitution of components may impair suitability for Class I, Division 2.

All statements, technical information and recommendations contained herein are based on information and tests we believe to be reliable. The accuracy or completeness thereof are not guaranteed. In accordance with Cooper Crouse-Hinds "Terms and Conditions of Sale", and since conditions of use are outside our control, the purchaser should determine the suitability of the product for his intended use and assumes all risk and liability whatsoever in connection therewith.

 **COOPER** Crouse-Hinds

Cooper Industries Inc.
Crouse-Hinds Division
PO Box 4999, Syracuse, New York 13221 • U.S.A.
Copyright© 2003, Cooper Industries, Inc.

IF 1327 A
Revision 1
New 11/03